10201160 2017 FORD ESCAPE Suv, Mid Size

	1611071 1061 - Pre Deli	Meter: very Insp	924 ection			In Date:	10/26/2016	Closed:	10/26/20	016
- Pre Delivery I	Inspection									
- Travel time					04000	5 .		-		
	Hours :	3.50		Labor:	210.00	Parts:	0.00	l otal:	210.00	
	1700229 Right front tire ç	Meter: going flat	3176			In Date:	01/09/2017	Closed:	01/12/20	017
- Repair and ba	alance right fror	nt tire.			Parts Li	ist				Qty
- Shop Supplie	- Shop Supplies					Shop Supplies				
	Hours	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
	1701484 P.M. Service.	Meter:	6453			In Date:	02/13/2017	Closed:	02/28/20	017
- P.m. Service.					Parts Li	ist				Qty
- Rotate and ba	alance tires.				Napagold Oil Filter					
- Shop Supplie	s				5w20 Engine Oil 6.0					
					Washer	Fluid Conce	entr			1.00
					Used Fi	re X Refurbi	shed			1.00
					Shop Su	upplies				1.00
	Hours :	3.00		Labor:	180.00	Parts:	35.47	Total:	215.47	
	1702289 Right rear tire g	Meter: joing flat.	8395			In Date:	03/07/2017	Closed:	03/28/20	017
- Repair and ba	alance right rea	r tire.			Parts Li	ist				Qty
- Replace and	balance damag	jed left re	ar tire.		Tire Mic	235/55/17				1.00
- Shop Supplie	s				Shop Su	upplies				1.00
					Tire Dis	posal Fee				1.00
	Hours	1.50		Labor:	90.00	Parts:	197.28	Total:	287.28	
	1704418 DRIVERS SIDE	Meter: REAR 1	11083 FIRE IS LEAK	ING.		In Date:	05/02/2017	Closed:	05/08/20	017
- C/c driver side to bring vehicle	e rear tire.verify to vista to repla		to repair.instal	l spare						
·	Hours	0.25		Labor:	15.00	Parts:	0.00	Total:	15.00	

Workorder: Problem:	1704419 P.M. service		10871 on left rear.		I ı	n Date:	05/02/2017	Closed:	05/05/20	17
- P.m. service	Э.				Parts List					Qty
- Replace left	rear tire for si	dewall dama	age.rotate and	ı	5w20 Engine Oil					6.00
balance four t	ires .nitrofill tire	∋s.			Napagold			1.00		
- Shop Suppli	ies				Tire Mic 2	35/55/17			1.00	
					Shop Supp	plies				1.00
					Tire Dispo	sal Fee				1.00
	Hou :	rs 3.50		Labor:	210.00	Parts:	213.34	Total:	423.34	
Workorder: Problem:	1706722 P.M. service.	Meter:	16349		I	n Date:	07/10/2017	Closed:	07/20/20	17
- P.m. service	€.				Parts List					Qty
- Rotate and	high speed bal	lance all fou	r wheels.nitro	fill all.	5w20 Eng	ine Oil				6.00
- Repair right	front tire and b	alance .nitr	ogen fill tires.		Napagold	Oil Filter				1.00
- Shop Suppli	ies				Accufit Be	am				2.00
					Wpr/blde					1.00
					Washer Fl	uid Conc	entr			1.00
					Shop Supp	plies				1.00
	Hou :	rs 4.00		Labor:	240.00	Parts:	63.55	Total:	303.55	
Workorder: Problem:	1708165 Dash cluster	Meter: goes black	18443 at times.		Īı	n Date:	08/18/2017	Closed:	08/23/20	17
- Transport to	and from dea	ler for cluste	er going		Parts List					Qty
	am cluster and				Shop Supp	plies				1.00
G. ISP Gupp.		ırs 2.00		Lahor:	120.00	Parts:	2.00	Total:	122.00	
				Labor.	120.00					
Workorder:	1709890		21636		lı	n Date:	10/10/2017	Closed:	10/17/20	17
	: 1709890 P.M. service				lı		10/10/2017	Closed:		17
	P.M. service				lı	n Date:	10/10/2017	Closed:		17 Qty
Problem: - P.m. service - Repair right	P.M. service e. rear tire .rotate	and wire ligl	ht bar to stay o		lı ut key on.	n Date:	10/10/2017	Closed:		
Problem: - P.m. service - Repair right tires.nitrogen	P.M. service e. rear tire .rotate fill tires.	and wire ligl	ht bar to stay o		lı ut key on. Parts List	n Date:	10/10/2017	Closed:		Qty
Problem: - P.m. service - Repair right tires.nitrogen - Rewire light	P.M. service e. rear tire .rotate fill tires. bar to work wi	and wire ligl	ht bar to stay o		ut key on. Parts List Napagold	n Date: Oil Filter		Closed:		Qty 1.00
Problem: - P.m. service - Repair right tires.nitrogen	P.M. service e. rear tire .rotate fill tires. bar to work wi	and wire ligl	ht bar to stay o		ut key on. Parts List Napagold 5w20 Eng	n Date: Oil Filter ine Oil in Air Filte		Closed:		Qty 1.00 6.00 1.00
Problem: - P.m. service - Repair right tires.nitrogen - Rewire light	P.M. service e. rear tire .rotate fill tires. bar to work wi	and wire ligl	ht bar to stay o		ut key on. Parts List Napagold 5w20 Engi Napa Cab Wiper Blac	n Date: Oil Filter ine Oil in Air Filte		Closed:		Qty 1.00 6.00 1.00
Problem: - P.m. service - Repair right tires.nitrogen - Rewire light	P.M. service e. rear tire .rotate fill tires. bar to work wi	and wire ligl	ht bar to stay o		ut key on. Parts List Napagold 5w20 Engi Napa Cab Wiper Blace Wiper Blace Blade	n Date: Oil Filter ine Oil in Air Filte de	€ſ	Closed:		Qty 1.00 6.00 1.00 1.00 1.00
Problem: - P.m. service - Repair right tires.nitrogen - Rewire light	P.M. service e. rear tire .rotate fill tires. bar to work wi	and wire ligl	ht bar to stay o		ut key on. Parts List Napagold 5w20 Engi Napa Cab Wiper Blac Wiper Blac Blade Washer Fl	n Date: Oil Filter ine Oil in Air Filte de de	€ſ	Closed:		Qty 1.00 6.00 1.00 1.00 1.00 1.00
Problem: - P.m. service - Repair right tires.nitrogen - Rewire light	P.M. service e. rear tire .rotate fill tires. bar to work wi ies	and wire ligl	ht bar to stay o	on witho	ut key on. Parts List Napagold 5w20 Engi Napa Cab Wiper Blace Wiper Blace Blade	n Date: Oil Filter ine Oil in Air Filte de de uid Conce	€ſ			Qty 1.00 6.00 1.00 1.00 1.00

Workorder: Problem:	1711158 Left front tire	Meter: has nail.	23662			In Date:	11/13/2017	Closed:	11/16/20)17
- Replace two	worn front tir	es with new	.balance and	d reset	Parts Li	st				Qty
tire sensors.					P235 55	r17 Fuel M	ax			2.00
- Shop Supplie	es				Shop Su	pplies				1.00
					Tire Disp	osal Fee				2.00
	Hou :	urs 1.00		Labor:			345.45	Total:	405.45	
	1800254 P.M. Service	Meter:	26744			In Date:	01/08/2018	Closed:	01/16/20)18
- P.m. service.					Parts Li	st				Qty
- Replaced two front tires.rotate and balanced all four tires						gine Oil				6.00
.nitrogen fill tire						d Oil Filter				1.00
- Removed an		ft side outer	tie rod end.c	due to	Used Fir		1.00			
excessive play		oont.			Washer		1.00			
- Perform four	•	nent.			P235 55		2.00			
- Shop Supplie	; 5				Tie Rod					1.00
					Lug Nut					1.00
					Shop Su	pplies				1.00
					Tire Disp	osal Fee				2.00
	Hou :	urs 7.40		Labor:	444.00	Parts:	410.42	Total:	854.42	
	1803439 P.M. service	Meter:	31684			In Date:	04/02/2018	Closed:	04/04/20)18
- P.m. service.					Parts Li	st				Qty
- Load test bat test.replace ba				l	5w20 En	_				6.00
- Rotate and b	-		, 3.GIII.			d Oil Filter				1.00
- Shop Supplie		ui iiies.			_	Fluid Conc	entr			1.00
- Shop Supplie	75				Battery					1.00
					Shop Su	pplies				1.00

Labor: 240.00 Parts: 186.35

Total: 426.35

Hours 4.00

Workorder: 180829 Problem: P.M. Se		er: 36382			In Date:	08/13/2018	Closed:	08/20/2018	;
- P.m. service.				Parts Lis	st			Q	Qty
- Replace two tires . E	Balance and r	otate all fou	ır tires. Nitrofill.	Napagol	1.	.00			
- Shop Supplies				5w20 En		6.	.00		
				Wiper				1.	.00
				20" Wipe	er Blade			1.	.00
				Wiper Bl	ades 24"			1.	.00
				Used Fire	e X Refurb	ished		1.	.00
				235/55r1	7 Assuran	ce		2.	.00
				Blade				1.	.00
				Wiper Bl	ade			1.	.00
				Wiper Bl	ade			1.	.00
				Shop Su	pplies			1.	.00
				Tire Disp	osal Fee			2.	.00
	Hours 4.00		Labor:	240.00	Parts:	420.05	Total:	660.05	
Workorder: 181051 Problem: Splash - Reinstall right splach	shield hangi	ng down .	Labor:	13.40	In Date: Parts:	0.00	Closed: Total:	10/17/2018 13.40	
Workorder: 190005 Problem: P.M. se		er: 41708	<u> </u>		In Date:	01/02/2019	Closed:	01/10/2019)
- P.m. service.	ervice.			Parts Lis	et.			0	Qty
- Replace both rear le	akina shocks								.00
- Resurface both rear	•		ers Renlace	Napagold Oil Filter Napa Quart 5w20					
brake pads and flush a				Washer Fluid Concentr					.00
- Rotate and high spe	ed balance a	II four tires.	Nitrofill all.	Blade	i idid Oolio	Onti			.00
- Shop Supplies				Wiper Bl	ade				.00
				Wiper Bl					.00
				Napa Air					.00
				-	bin Air Filte	er			.00
				Shock Al		= -			.00
				Brake Pa					.00
				Shop Su					.00
	Hours 7.60		l ahor	509.20		389.18	Total:	898.38	

Workorder: Problem:	1905147 P.M. service	Meter:	46566		ln	Date:	05/13/2019	Closed:	05/16/2019	
- P.m. service).				Parts List				Q	
- Replace and	d balance all fo	our tires . N	itrofill all.		Napagold C	il Filter			1.0	
- Inspect brak	es . Resurfac	e both front	brake rotors an	nd	5w20 Engin	e Oil			6.0	
service caliper	rs . Replace b		Flush and bleed		Blade	1.0				
system . Road		Donal-Cl-	C - Left for a co	1.	Wiper Blade	Э			1.0	
- Diagnose no Retest .	oise on turns .	R&r defded	tive left front ax	de.	Wiper Blade	Э			1.0 1.0	
	nolete four wh	eel alignme	nt and road tes	t	Washer Flu	id Conc	entr			
- Shop Suppli	-	oo. ang		• •	Mac Wite Li	ithium G	res		1.0	
3ap 3.app					Lug Nut				1.0	
					Tire235/55/	17 Mic			4.0	
					Non-chlor B	rake Cli	nr		1.0	
					brake fluid				1.0	
					Brake Pad				1.0	
					Left Front A	xle			1.0	
					Shop Suppl	ies			1.0	
					Tire Dispos	al Fee			4.0	
	Hou	ırs 12.50		Labor:	837.50	Parts:	1,100.36	Total:	1,937.86	
FIUDIEIII:	Front passer	nger headlig	ht & license pla	ite bulbs	s out.					
- Replace left defective tag li	low beam hea		ht & license pla		Parts List Blister Pack	c Capsul	es		Q 1.0	
- Replace left	low beam hea		·		Parts List Blister Pack Bulbs	·	es		1.0 1.0	
- Replace left defective tag li	low beam hea ight bulb. es	adlight bulb	. Test and repla	ace	Parts List Blister Pack Bulbs Shop Suppl	ies		Total	1.0 1.0 1.0	
- Replace left defective tag li	low beam hea ight bulb. es		. Test and repla		Parts List Blister Pack Bulbs Shop Suppl	ies	es 18.17	Total:	1.0 1.0	
- Replace left defective tag li - Shop Suppli	low beam hea ight bulb. es	adlight bulburs 0.80	. Test and repla	ace	Parts List Blister Pack Bulbs Shop Suppl 53.60	ies		Total:	1.0 1.0 1.0	
- Replace left defective tag li - Shop Suppli	low beam hea ight bulb. es Hou : 1910642 P.M. service	adlight bulburs 0.80	. Test and repla	ace	Parts List Blister Pack Bulbs Shop Suppl 53.60	ies Parts:	18.17		1.0 1.0 1.0 71.77	
- Replace left defective tag li - Shop Suppli Workorder: Problem:	low beam heatight bulb. es Hou : 1910642 P.M. service.	adlight bulburs 0.80 Meter:	. Test and repla	ace	Parts List Blister Pack Bulbs Shop Suppl 53.60	ies Parts: Date:	18.17		1.0 1.0 1.0 71.77	
- Replace left defective tag li - Shop Supplie Workorder: Problem: - P.m. service - Test and rep - Charge batte	low beam heatight bulb. es Hou : 1910642 P.M. service. e. blace right rea	adlight bulb urs 0.80 Meter: r marker light battery and	. Test and replace 51498 ht bulb .	ace Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List	ies Parts: Date:	18.17		1.0 1.0 71.77 10/24/2019	
- Replace left defective tag li - Shop Supplie - Shop Supplie - P.m. service - Test and reproblem: - Charge battery failed I	low beam heatight bulb. es Hou : 1910642 P.M. service. clace right reacery fully . Testload test . R&I	adlight bulb urs 0.80 Meter: r marker light battery and r defective battery	. Test and replace 51498 ht bulb . d charging systemattery .replace	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C	ies Parts: Date:	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - P.m. service - Test and reproduced - Charge battery failed I corroded positions - Reproduced - Controded - Con	low beam heatight bulb. es Hou : 1910642 P.M. service. c) c) blace right rea ery fully . Test load test . R&i cive battery ca	adlight bulb urs 0.80 Meter: r marker light battery and r defective battery	. Test and replace 51498 ht bulb .	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin	ies Parts: Date: Dil Filter Dil Oil	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - Problem: - P.m. service - Test and rep - Charge batter gailed I corroded posit monitoring sys	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem .	marker light battery and right defective below to be a Hook to be a defective below to be a defective	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold Co 5w20 Engin Blade	Date:	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - P.m. service - Test and reproduced - Charge battery failed I corroded posit monitoring systems - Remove left	low beam heatight bulb. es Hou : 1910642 P.M. service. clace right reacery fully . Test load test . R&itive battery castem . front seat for	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin Blade Wiper Blade	ies Parts: Date: Dil Filter ie Oil	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - Problem: - P.m. service - Test and rep - Charge batter failed I corroded posit monitoring sys - Remove left - Rotate and h	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem . front seat for high speed ba	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin Blade Wiper Blade Wiper Blade	Date: Date: Oil Filter Die Oil Die Coll Die Col	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - P.m. service - Test and reproduced - Charge battery failed I corroded posit monitoring systems.	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem . front seat for high speed ba	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin Blade Wiper Blade Wiper Blade Used Fire X	ies Parts: Date: Dil Filter ie Oil Refurb atures	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - Problem: - P.m. service - Test and rep - Charge batter failed I corroded posit monitoring sys - Remove left - Rotate and h	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem . front seat for high speed ba	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin Blade Wiper Blade Wiper Blade Used Fire X Boxed Minia	ies Parts: Date: Dil Filter ie Oil Refurb atures	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0 1.0 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - Problem: - P.m. service - Test and rep - Charge batter failed I corroded posit monitoring sys - Remove left - Rotate and h	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem . front seat for high speed ba	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold C 5w20 Engin Blade Wiper Blade Wiper Blade Used Fire X Boxed Minia Battery Cab	Date: Date: Oil Filter Die Oil Die Control Control Control Control Die Control Control Control Die Control Control Die Control Control Die Control Di	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0 1.0 1.0	
- Replace left defective tag li - Shop Supplie - Shop Supplie - Problem: - P.m. service - Test and rep - Charge batter failed I corroded posit monitoring sys - Remove left - Rotate and h	low beam heatight bulb. es Hou : 1910642 P.M. service. e. clace right reatery fully . Test load test . R&itive battery castem . front seat for high speed ba	marker light battery and refective below the repair and	. Test and replace to the state of the state	Labor:	Parts List Blister Pack Bulbs Shop Suppl 53.60 In Parts List Napagold Co 5w20 Engin Blade Wiper Blade Wiper Blade Used Fire X Boxed Minia Battery Cab Battery	Date: Date: Oil Filter Die Oil Die Control Die Contro	18.17		1.0 1.0 71.77 10/24/2019 Q 1.0 6.0 1.0 1.0 1.0 1.0	

Workorder: Problem:	2000393 Overhead	Meter: lights inop and	54425 d left low bear	m inop .		In Date:	01/13/2020	Closed:	04/02/2020
- Test and rep	olace left lo	w beam head	ight bulb .		Parts L	Qty			
- Test and dis	sassemble l	ight bar to ren	nove and sen	d out	Blister F		1.00		
control circuit	nd test oper		mble light ba	r	Shop Su			1.00	
- Shop Suppli		lours 1.50		Labor:	109.50	Parts:	17.86	Total:	127.36
Workorder: Problem:	2003436 P.M . serv	Meter:	54576			In Date:	04/06/2020	Closed:	04/09/2020
- P.m. service	e.				Parts L	ist			Qty
		ht assembly.	Replace cra	ck right	Permate	ex			1.00
tail lamp lens	and mount	strobe bulb .			Napago	1.00 6.00			
		four tires . Nit	rofill all.		5w20 E				
- Shop Suppli	ies				Blade				1.00
					Wiper B	lade			1.00
					Wiper B	lade			1.00
					Napa C	abin Air Filte	er		1.00
					Headlar	np Asy Drive	er		1.00
					L Amp A	Asy			1.00
					Shop St	upplies			1.00
	H :	lours 6.00		Labor:	438.00	Parts:	1,189.18	Total:	1,627.18
Workorder: Problem:	2009263 remove ex	Meter: ktra decals for	59147 surplus			In Date:	09/16/2020	Closed:	09/16/2020
- remove extr	a decals fo	r surplus			Parts L	ist			Qty
- Shop Suppli	ies				Shop St	upplies			1.00
	H :	lours 2.00		Labor:	146.00	Parts:	4.00	Total:	150.00
Workorder: Problem:	2009385 Transition	Meter: Prep Charge	59147			In Date:	09/17/2020	Closed:	09/17/2020
- Transition P	rep Charge)							
	H	lours 2.00		Labor:	146.00	Parts:	0.00	Total:	146.00
	:								