

6/6/2022
10:01:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10210053 2019 HONDA RANCHER 4X4 Atv, 4X4

Total Hours: 37.00 Labor: 2,665.00 Parts: 2,496.07 Comm: 0.00 Charged: 5161.06

Work Order: 1900339 **Meter:** 1 **In Date:** 01/09/2019 **Closed:** 01/10/2019
Problem: pre delivery inspection

Work Completed

Parts Issued

Quantity

- pre delivery inspection
- Shop Supplies

Shop Supplies 1.00

Hours: 2.00 Comm: 0.00 Labor: 134.00 Parts: 3.00 Total: 137.00

Work Order: 1907168 **Meter:** 25 **In Date:** 07/11/2019 **Closed:** 07/17/2019
Problem: pm service

Work Completed

Parts Issued

Quantity

- Pm Service
- Shop Supplies

10w30 4stroke Gn4 3.00

Oil Filter 1.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 268.00 Parts: 40.55 Total: 308.55

Work Order: 2001532 **Meter:** 54 **In Date:** 02/12/2020 **Closed:** 02/26/2020
Problem: pm service

Work Completed

Parts Issued

Quantity

- pm service
- Shop Supplies

Oil Filter 1.00

10w30 4stroke Gn4 4.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 53.22 Total: 345.22

Work Order: 2008613 **Meter:** 54 **In Date:** 08/27/2020 **Closed:** 09/04/2020
Problem: pm service

Work Completed

Parts Issued

Quantity

- pm service
- Shop Supplies

Oil Filter 1.00

10w30 4stroke Gn4 4.00

Shop Supplies 1.00

Hours: 4.00 Comm: 0.00 Labor: 292.00 Parts: 54.03 Total: 346.03

6/6/2022
10:01:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10210053 2019 HONDA RANCHER 4X4 Atv, 4X4

Work Order: 2105429 **Meter:** 131 **In Date:** 05/14/2021 **Closed:** 06/07/2021

Problem: PM Service. Front and rear cargo racks are rusted through, causing the roof rack to become detached. Need replacement ra

Work Completed

- Preventive Maint. Service
- Racks Were Rusted. Clean Atv, Replace Front & Rear Luggage Racks, Bumper Assembly, Apply Rust Remover, Undercoat All Metal, Paint, And Preventative Coating
- Replace Front & Rear Tires, Paint Wheels
- Shop Supplies

Parts Issued

Quantity

| | |
|----------------------------|-------|
| 24x8-12 | 2.00 |
| 24x10-11 Lr | 2.00 |
| Oil Filter | 1.00 |
| 10w30 4stroke Gn4 | 4.00 |
| Spark Plug | 1.00 |
| Non-chlor Brake Clnr | 1.00 |
| Corrosion-x Inhibitor 16oz | 1.00 |
| Raptor 2k Aero White | 3.00 |
| Rust Fix | 3.00 |
| Glos Blk | 5.00 |
| Raptor 2k Aero Black | 3.00 |
| Rear Carrier | 1.00 |
| Front Pipe | 1.00 |
| Front Carrier | 1.00 |
| Bolt Flange | 2.00 |
| Flange Nut 8mm | 2.00 |
| Pipe End Cap | 2.00 |
| Sc1 Clear Coat | 2.00 |
| Front Reflector | 2.00 |
| Rear Reflector | 4.00 |
| Nut 6mm | 6.00 |
| Flange Bolt | 12.00 |
| Mudguard Clip | 14.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |
| Freight Charge | 1.00 |

Hours: 21.00

Comm: 0.00

Labor: 1,533.00

Parts: 2,345.28

Total: 3,878.28

6/6/2022
10:01:39 AM

Palm Beach County Fleet Management Asset Maintenance History
10210053 2019 HONDA RANCHER 4X4 Atv, 4X4

Work Order: 2204379 **Meter:** 131 **In Date:** 04/26/2022 **Closed:** 04/26/2022
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 37.00

Total Labor: 2,665.00

Total Comm: 0.00

Total Parts: 2,496.07