

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Total Hours: 593.30	Labor: 41,111.90	Parts: 50,596.06	Comm: 67,322.09	Charged: 159030.06
----------------------------	-------------------------	-------------------------	------------------------	---------------------------

Work Order: 1502099	Meter: 1136	In Date: 02/26/2015	Closed: 02/27/2015
Problem: Check in			

Work Completed

- Check in equipment
- Shop Supplies

Parts Issued

Shop Supplies

Quantity

1.00

Hours: 5.00

Comm: 0.00

Labor: 300.00

Parts: 2.00

Total: 302.00

Work Order: 1502275	Meter: 1136	In Date: 03/03/2015	Closed: 03/10/2015
Problem: Move bucket mount			

Work Completed

- Move bucket mount

Hours: 0.00

Comm: 1,095.60

Labor: 0.00

Parts: 0.00

Total: 1,095.60

Work Order: 1502497	Meter: 1136	In Date: 03/10/2015	Closed: 03/10/2015
Problem: 1062 - Make & Apply Decals. Check Fluids, Belts and Operation			

Work Completed

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 1.00

Comm: 0.00

Labor: 60.00

Parts: 0.00

Total: 60.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1506748 **Meter:** 6590 **In Date:** 07/07/2015 **Closed:** 07/21/2015
Problem: PM

Work Completed

- pm
- pm upper
- computer diagnosis. replace Lf wheel speed sensor. clear codes
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Wiper Blade	2.00
Washer Fl	1.00
Speed Sensor	1.00
Brake Cleaner	2.00
Hydraulic Filter	1.00
Ptex Superbond Sm	1.00
Shop Supplies	1.00

Hours: 12.50 Comm: 0.00 Labor: 750.00 Parts: 426.28 Total: 1,176.28

Work Order: 1508005 **Meter:** 7076 **In Date:** 08/10/2015 **Closed:** 08/11/2015
Problem: Tire needed on Front Driver side

Work Completed

- Tire Service Mlk Blvd and Old Dixie Hwy - Tire needed on Front Driver side

Hours: 0.00 Comm: 484.31 Labor: 0.00 Parts: 0.00 Total: 484.31

Work Order: 1508006 **Meter:** 7076 **In Date:** 08/10/2015 **Closed:** 08/11/2015
Problem: Service

Work Completed

- Tire Service Mlk Blvd and Old Dixie Hwy - Service

Hours: 0.00 Comm: 46.40 Labor: 0.00 Parts: 0.00 Total: 46.40

Work Order: 1512705 **Meter:** 11431 **In Date:** 12/16/2015 **Closed:** 01/05/2016
Problem: Annual

Work Completed

- Annual
- dielectric test

Hours: 0.00 Comm: 780.00 Labor: 0.00 Parts: 0.00 Total: 780.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1512706 **Meter:** 11528 **In Date:** 12/16/2015 **Closed:** 01/13/2016
Problem: PM

Work Completed

- pm
- replace air drier
- pm upper
- road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Used Fire X Refurbished	1.00
Brake Cleaner	2.00
Ad Ip Dryer Cart	1.00
Hydraulic Filter	1.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 930.00

Parts: 549.17

Total: 1,479.17

Work Order: 1601029 **Meter:** 12989 **In Date:** 01/28/2016 **Closed:** 01/29/2016
Problem: winch out

Work Completed

- Tow From: lyons/palmetto park in the median

Hours: 0.00

Comm: 210.00

Labor: 0.00

Parts: 0.00

Total: 210.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1604345 **Meter:** 16655 **In Date:** 04/26/2016 **Closed:** 05/12/2016
Problem: PM

Work Completed

- Pm
- Bucket Pm
- Service Ac
- Replace blinker bulb
- Remove and reseal sencer at Pto
- Shop Supplies

Parts Issued

Quantity

Fuel Fil	1.00
15-40 Oil	30.00
Napagold Oil Filter	1.00
Grande Cab Shock	1.00
2602212c1 Air Filter	1.00
22" Wiper Blade	2.00
Hydraulic Filter	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Fuel Screen	1.00
Bulb	1.00
Shop Supplies	1.00

Hours: 14.50

Comm: 0.00

Labor: 870.00

Parts: 553.55

Total: 1,423.55

Work Order: 1607594 **Meter:** 21334 **In Date:** 07/26/2016 **Closed:** 08/08/2016
Problem: replace head light

Work Completed

- Lf headlight

Hours: 0.50

Comm: 0.00

Parts Issued

Quantity

Halogen Capsule	1.00
Labor: 30.00	Parts: 5.24
Total: 35.24	

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1609515 **Meter:** 23874 **In Date:** 09/13/2016 **Closed:** 09/30/2016
Problem: PM/ Coolent leak

Work Completed

Parts Issued

Quantity

- pm	Thermostat By Pass	1.00
- pm upper	15-40 Oil	30.00
- replace intercooler t-stat connecting hoses	Napagold Oil Filter	1.00
- scan codes	Fuel Fil	1.00
- road test	2602212c1 Air Filter	1.00
- Shop Supplies	Napa Cabin Air Filter	1.00
	Cabin Air Filter	1.00
	Wiper Blade	2.00
	Hydraulic Filter	1.00
	Shop Supplies	1.00

Hours: 13.50 Comm: 0.00 Labor: 810.00 Parts: 644.41 Total: 1,454.41

Work Order: 1609863 **Meter:** 23828 **In Date:** 09/21/2016 **Closed:** 09/27/2016
Problem: 3 Tires

Work Completed

- 3 Tires				
Hours: 0.00	Comm: 1,504.49	Labor: 0.00	Parts: 0.00	Total: 1,504.49

Work Order: 1610658 **Meter:** 24645 **In Date:** 10/17/2016 **Closed:** 11/02/2016
Problem: head light out

Work Completed

Parts Issued

Quantity

- replace passenger side headlight	Capsule	1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00 Parts: 3.20 Total: 33.20

Work Order: 1612035 **Meter:** 26768 **In Date:** 11/22/2016 **Closed:** 11/29/2016
Problem: Head Light

Work Completed

Parts Issued

Quantity

- head light replace	Capsule	1.00
Hours: 0.50	Comm: 0.00	Labor: 30.00 Parts: 3.20 Total: 33.20

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1702034 **Meter:** 29857 **In Date:** 02/28/2017 **Closed:** 05/05/2017
Problem: PM/ List

Work Completed

- Pm
- Pm Bucket
- Replace coolent pipe and hoses from water pump to oil cooler
- Replace batteries
- Road test
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
2602212c1 Air Filter	1.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Hydraulic Filter	1.00
Hose Clamp	2.00
Group 31 Stud Delco	2.00
tube assy	1.00
disf rotella	6.00
Shop Supplies	1.00

Hours: 15.50

Comm: 0.00

Labor: 930.00

Parts: 991.45

Total: 1,921.45

Work Order: 1702709 **Meter:** 29704 **In Date:** 03/16/2017 **Closed:** 03/17/2017
Problem: LF tire

Work Completed

- Lf tire

Hours: 0.00

Comm: 535.87

Labor: 0.00

Parts: 0.00

Total: 535.87

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1708680 **Meter:** 35124 **In Date:** 08/31/2017 **Closed:** 09/22/2017
Problem: pm/list

Work Completed

Parts Issued

Quantity

- pm
- pm upper
- replace bumper marker sticks
- Ac filter and refresh
- add coolant
- retape boom gaurd
- pintle pin
- road test
- Shop Supplies

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Air Filter	1.00
Used Fire X Refurbished	2.00
Non-chlor Brake Clnr	2.00
Wiper Blade	2.00
Hydraulic Filter	1.00
Blade Guide Org 3 4in	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
disf rotella	1.00
Boltron Tape	1.00
Pintle Pin W/clip	1.00
Shop Supplies	1.00

Hours: 15.00

Comm: 0.00

Labor: 900.00

Parts: 578.20

Total: 1,478.20

Work Order: 1711028 **Meter:** 38086 **In Date:** 11/07/2017 **Closed:** 11/16/2017
Problem: Head light

Work Completed

Parts Issued

Quantity

- R&r headlight bulb

Halogen Capsule	1.00
-----------------	------

Hours: 0.50

Comm: 0.00

Labor: 30.00

Parts: 5.24

Total: 35.24

Work Order: 1712729 **Meter:** 40210 **In Date:** 12/27/2017 **Closed:** 02/02/2018
Problem: RRIO tires

Work Completed

- Rrio tires

Hours: 0.00

Comm: 1,003.38

Labor: 0.00

Parts: 0.00

Total: 1,003.38

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1800850 **Meter:** 41353 **In Date:** 01/24/2018 **Closed:** 03/06/2018
Problem: PM

Work Completed

- Pm
- Bucket Pm
- Drained coolant and replaced Egr cooler hose
- Pulled codes Spn 2659, Fmi 21, Egr Low flow. R&r Egr valve and housing
- Service air dryer
- Service Ac
- Wash Vehical,and bay
- Test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Air Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	2.00
Hydraulic Filter	1.00
Hose	1.00
Rotell Elc Antifeerze	8.00
Egr Actuator	1.00
Intake Heater Duct	1.00
Ad Ip Dryer Cart	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Shop Supplies	1.00

Hours: 26.50

Comm: 0.00

Labor: 1,590.00

Parts: 2,506.97

Total: 4,096.97

Work Order: 1801571 **Meter:** 41138 **In Date:** 02/09/2018 **Closed:** 03/01/2018
Problem: Annual/ repairs

Work Completed

- Annual
- dielectric test
- r/r upper boom area, placards, clean lower boom r/r strobe, emergency stop switch,

Hours: 0.00

Comm: 3,069.98

Labor: 0.00

Parts: 0.00

Total: 3,069.98

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1803966 **Meter:** 42665 **In Date:** 04/17/2018 **Closed:** 04/25/2018
Problem: No start / AC

Work Completed

Parts Issued

Quantity

- Jump start, and replace batteries
- Ck A/c no problem found
- To Traffic
- Diagnosis pull codes and clear
- Test run
- Shop Supplies

Napa Battery	2.00
Shop Supplies	1.00

Hours: 6.50 Comm: 0.00 Labor: 390.00 Parts: 387.56 Total: 777.56

Work Order: 1806451 **Meter:** 44077 **In Date:** 06/25/2018 **Closed:** 07/10/2018
Problem: clicking noise in drive train

Work Completed

Parts Issued

Quantity

- remove metal from driveshaft
- road test
- Shop Supplies

Shop Supplies	1.00
---------------	------

Hours: 1.50 Comm: 0.00 Labor: 90.00 Parts: 2.00 Total: 92.00

Work Order: 1807313 **Meter:** 44077 **In Date:** 07/18/2018 **Closed:** 08/23/2018
Problem: Inspection

Work Completed

- Repairs by Altec

Hours: 0.00 Comm: 480.00 Labor: 0.00 Parts: 0.00 Total: 480.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1807316 **Meter:** 44281 **In Date:** 07/18/2018 **Closed:** 08/14/2018
Problem: Repair plug and hitch

Work Completed

- To Altec 2xs (accident Damage)
- Replace hitch, and rewire in a new plug
- Shop Supplies

Parts Issued

Quantity

Bulk Battery Cable	2.00
Bulk Trailer Wire	2.00
trailer plug	1.00
Pin Hook	1.00
Shop Supplies	1.00

Hours: 9.00

Comm: 0.00

Labor: 540.00

Parts: 134.12

Total: 674.12

Work Order: 1807426 **Meter:** 44077 **In Date:** 06/25/2018 **Closed:** 07/20/2018
Problem: : Damage to rear bumper, right rear bin, ladder & trailer plug

Work Completed

- : Damage to rear bumper, right rear bin, ladder & trailer plug

Hours: 0.00

Comm: 4,292.70

Labor: 0.00

Parts: 0.00

Total: 4,292.70

Work Order: 1808473 **Meter:** 44430 **In Date:** 08/16/2018 **Closed:** 08/24/2018
Problem: Accident Inspection

Work Completed

- Accident Inspection

Hours: 0.00

Comm: 2,389.06

Labor: 0.00

Parts: 0.00

Total: 2,389.06

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1809551 **Meter:** 45478 **In Date:** 09/17/2018 **Closed:** 10/03/2018
Problem: pm

Work Completed

- pm truck
- pm upper
- service ac system
- service transmission filters
- replace 2 bulbs
- rear brakes hardware and seals
- air dryer replace
- test run
- pintle pin
- Shop Supplies

Parts Issued

Quantity

Non-chlor Brake Clnr	4.00
15-40 Oil	31.00
Napagold Oil Filter	1.00
Air Filter	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Hydraulic Filter	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Syn-atf Trans Fluid S	20.00
Napa Trans Filter	1.00
Boxed Capsules	2.00
Non-chlor Brake Clnr	8.00
Rear Drums	2.00
Shoes	2.00
Ad Ip Dryer Cart	1.00
Tran Flu Qt Dexron3i	4.00
Shop Supplies	1.00

Hours: 28.00

Comm: 0.00

Labor: 1,876.00

Parts: 1,608.45

Total: 3,484.45

Work Order: 1810286 **Meter:** 45484 **In Date:** 10/03/2018 **Closed:** 10/03/2018
Problem: RF Tire

Work Completed

- Rf tire

Hours: 0.00

Comm: 535.76

Labor: 0.00

Parts: 0.00

Total: 535.76

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1811387 **Meter:** 46433 **In Date:** 11/05/2018 **Closed:** 11/08/2018
Problem: headlight

Work Completed

- Headlight
- Shop Supplies

Hours: 1.00

Comm: 0.00

Parts Issued

Boxed Capsules	1.00
----------------	------

Shop Supplies	1.00
---------------	------

Labor: 67.00	Parts: 11.72	Total: 78.72
--------------	--------------	--------------

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1903258 **Meter:** 50142 **In Date:** 03/26/2019 **Closed:** 04/26/2019
Problem: PM

Work Completed

- Pm
- Pm Bucket
- To Altec 2xs
- Service Ac
- Service Power steering
- Replace light assemblies
- Refinnish head light lenses
- Replace bumper markers
- Reinstall Lf wheel well
- Rd test
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
15-40 Oil	31.00
Air Filter	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	3.00
Hydraulic Filter	1.00
Air Freshener	1.00
Evap Odor Elinitator	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Psf Qt	2.00
Oil Fil	1.00
Hi Temp 9004 9007	1.00
Boxed Capsules	2.00
Power Steering Filter	1.00
Hdlght Clr Coat	1.00
3m Tm Headlight Lens	1.00
Led M C 12v Grommet	1.00
Blade Guide Org 3 4in	1.00
Shop Supplies	1.00

Hours: 26.50

Comm: 0.00

Labor: 1,775.50

Parts: 653.37

Total: 2,428.87

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1903576 **Meter:** 49910 **In Date:** 04/02/2019 **Closed:** 04/19/2019
Problem: Annual/ Repairs

Work Completed

- annual
- dielectric test
- r/r pto, quick disconnect caps, repair fiberglass on upper boom, platform, non-skid platform step

Hours: 0.00 Comm: 4,869.41 Labor: 0.00 Parts: 0.00 Total: 4,869.41

Work Order: 1906475 **Meter:** 52967 **In Date:** 06/20/2019 **Closed:** 08/01/2019
Problem: trailer brakes/ac/headlight/list

Work Completed

- replace both bulbs and pigtail
- replace trailer plug repair wiring
- replace clogged ac filters
- check engine light scan codes
- to rechtien 2xs
- Shop Supplies

Parts Issued

Quantity

Hi Temp 9004 9007	1.00
Headlight Connector	1.00
Boxed Capsules	1.00
trailer plug	1.00
Shop Supplies	1.00

Hours: 12.00 Comm: 0.00 Labor: 804.00 Parts: 41.24 Total: 845.24

Work Order: 1906932 **Meter:** 52898 **In Date:** 07/03/2019 **Closed:** 08/05/2019
Problem: Repairs by Rechtien

Work Completed

- repair by rechtien

Hours: 0.00 Comm: 1,505.44 Labor: 0.00 Parts: 0.00 Total: 1,505.44

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1910604 **Meter:** 56385 **In Date:** 10/15/2019 **Closed:** 11/18/2019
Problem: PM

Work Completed

- pm
- upper pm
- ac service
- test run
- replace headlight bulbs
- repair rear step
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Air Fltr	1.00
Used Fire X Refurbished	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Motor Treatment Gal	1.00
Non-chlor Brake Clnr	3.00
Hydraulic Filter	1.00
Evap Odor Elinitator	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Boxed Capsules	1.00
11r22.5fstone Fs561	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 17.00

Comm: 0.00

Labor: 1,241.00

Parts: 1,099.26

Total: 2,340.26

Work Order: 1911587 **Meter:** 56334 **In Date:** 11/04/2019 **Closed:** 11/07/2019
Problem: 5 tires

Work Completed

- Tire Service he shop - 5 tires

Hours: 0.00

Comm: 276.56

Labor: 0.00

Parts: 0.00

Total: 276.56

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 1912061 **Meter:** 56542 **In Date:** 11/20/2019 **Closed:** 11/26/2019
Problem: 4 Tires

Work Completed

- tires
- Shop Supplies

Parts Issued

Quantity

11r22.5fstone Fs561 Fgr	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 0.00	Comm: 0.00	Labor: 0.00	Parts: 2,099.16	Total: 2,099.16
-------------	------------	-------------	-----------------	-----------------

Work Order: 2000754 **Meter:** 59580 **In Date:** 01/23/2020 **Closed:** 02/12/2020
Problem: List

Work Completed

- R&r batteries
- Low voltage and trans. codes
- Ac not working low voltage codes, reset system
- Serviced over heated trans
- Multiple test runs
- Replace Rs head light
- Replace fuel water sensor
- Shop Supplies

Parts Issued

Quantity

Group 31 Stud Delco	2.00
Syn-atf Trans Fluid S	22.00
Napa Trans Filter	1.00
Boxed Capsules	1.00
Brush	1.00
Filter	1.00
sensor	1.00
Shop Supplies	1.00

Hours: 13.00	Comm: 0.00	Labor: 949.00	Parts: 690.61	Total: 1,639.61
--------------	------------	---------------	---------------	-----------------

Work Order: 2002161 **Meter:** 60624 **In Date:** 03/02/2020 **Closed:** 04/03/2020
Problem: boom issues

Work Completed

- To Altec 2xs
- Repair lights
- Shop Supplies

Parts Issued

Quantity

Hi Temp 9004 9007	1.00
Boxed Capsules	1.00
Shop Supplies	1.00

Hours: 5.50	Comm: 0.00	Labor: 401.50	Parts: 23.77	Total: 425.27
-------------	------------	---------------	--------------	---------------

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2004757 **Meter:** 62383 **In Date:** 05/12/2020 **Closed:** 06/15/2020
Problem: PM/ Annual

Work Completed

- pm
- bucket pm
- scan codes. diagnose electrical issue
- R&r wiring harness at battery to ecu
- ac service
- service dryer
- test run
- to altec 2xs
- Shop Supplies

Parts Issued

Quantity

Napagold Oil Filter	1.00
Air Fltr	1.00
Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Non-chlor Brake Clnr	2.00
Hydraulic Filter	1.00
Battery Harness	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Ad Ip Dryer Cart	1.00
15-40 Oil	30.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 20.50

Comm: 0.00

Labor: 1,496.50

Parts: 888.39

Total: 2,384.89

Work Order: 2005822 **Meter:** 62383 **In Date:** 06/11/2020 **Closed:** 06/15/2020
Problem: Annual/ Dielectric/ Repairs

Work Completed

- annual
- dielectric test
- repair gelcoat on platform,upper boom,adjust lower boom leveling rods,r/r
up boom c/screw,socket cvr,t/shot start-stop

Hours: 0.00

Comm: 5,633.60

Labor: 0.00

Parts: 0.00

Total: 5,633.60

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2011715 **Meter:** 69391 **In Date:** 11/24/2020 **Closed:** 12/15/2020
Problem: Do for PM check up

Work Completed

- Preventive Maint. Service
- Pm bucket
- Road test
- Service A/c
- Replace batterys
- service hydraulic system
- replace Rh spot light bulb
- Shop Supplies

Parts Issued

Quantity

Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
15-40 Oil	30.00
Filter	1.00
Air Fltr	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Hydraulic Filter	1.00
Group 31 Stud Delco	2.00
Halogen Sealed Beams	1.00
Shop Supplies	1.00

Hours: 16.50

Comm: 0.00

Labor: 1,204.50

Parts: 763.26

Total: 1,967.76

Work Order: 2100002 **Meter:** 69755 **In Date:** 01/04/2021 **Closed:** 01/05/2021
Problem: air tank leak

Work Completed

- found governor leaking as well as several fittings change and test ok now
- to traffic yard 1/4
- Shop Supplies

Parts Issued

Quantity

Governor	1.00
tee	1.00
Non-chlor Brake Clnr	1.00
Shop Supplies	1.00

Hours: 2.50

Comm: 0.00

Labor: 182.50

Parts: 80.79

Total: 263.29

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2100874 **Meter:** 70334 **In Date:** 01/26/2021 **Closed:** 02/03/2021
Problem: leaking hydraulic fluid underneath the boom tourniquet when the PTO is Engauge, left rear reverse light out, driver side

Work Completed

- Hydraulic & Pressure Sys
- To Altec 2xs
- rev. Lights
- Shop Supplies

Parts Issued

Quantity

Boxed Capsules	1.00
Led Back-up Lamp Sys	1.00
Shop Supplies	1.00

Hours: 6.00 Comm: 0.00 Labor: 438.00 Parts: 185.79 Total: 623.79

Work Order: 2101322 **Meter:** 70334 **In Date:** 02/04/2021 **Closed:** 02/11/2021
Problem: Replace rotary joint

Work Completed

- Hydraulic & Pressure Sys

Hours: 0.00 Comm: 2,648.12 Labor: 0.00 Parts: 0.00 Total: 2,648.12

Work Order: 2104822 **Meter:** 72924 **In Date:** 04/29/2021 **Closed:** 04/29/2021
Problem: 1 - Key(s) Issued

Work Completed

- 1 - Key(s) Issued

Parts Issued

Quantity

Duplicate Vehicle Keys	1.00
------------------------	------

Hours: 0.30 Comm: 0.00 Labor: 21.90 Parts: 3.00 Total: 24.90

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2107218 **Meter:** 74697 **In Date:** 07/01/2021 **Closed:** 07/26/2021
Problem: PM check up- Bucket controls sticks in operation - AC cut in and out please check

Work Completed

- Annual Bucket Inspection
- To and From altec
- pm
- dielectric test
- repairs by altec
- Service Ac system Rr filters clean evaporator, clear blockage on system.
- Replace air dryer
- Transmission service replace trans filters
- Found water trace on fuel filter add additive to rid of water on system.
- Replace driver seat cushion seat bottom would not pass Dot inspection.
- Clean and adjust front and rear brakes,...
- Test run X2
- Shop Supplies

Parts Issued

Quantity

Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Air Filter	1.00
Filter	1.00
15-40 Oil	30.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Motor Treatment Gal	1.00
Non-chlor Brake Clnr	4.00
Stiction Elimint 16oz	1.00
Air Freshener	1.00
Evap Odor Elinitator	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Reman Air Dryer	1.00
Syn-atf Trans Fluid S	22.00
Napa Trans Filter	1.00
Seat Cushion	1.00
Shop Supplies	1.00

Hours: 25.50

Comm: 2,804.05

Labor: 1,861.50

Parts: 985.57

Total: 5,651.12

Work Order: 2107787 **Meter:** 74697 **In Date:** 07/15/2021 **Closed:** 07/23/2021
Problem: Front tires

Work Completed

- Tire Service: He Problem: Front tires
-

Hours: 0.00

Comm: 811.34

Labor: 0.00

Parts: 0.00

Total: 811.34

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2107788 **Meter:** 74697 **In Date:** 07/16/2021 **Closed:** 07/23/2021
Problem: Front Tires Labor

Work Completed

- Tire Service: He Problem: Front Tires Labor

Hours: 0.00 Comm: 133.31 Labor: 0.00 Parts: 0.00 Total: 133.31

Work Order: 2200076 **Meter:** 79446 **In Date:** 01/04/2022 **Closed:** 04/04/2022
Problem: PM Service. Hydraulic leaks in lower boom base, driver side strobe is out, AC cuts in a7 out

Work Completed

- Preventive Maint. Service
- Front brakes below specs
- Rear brakes below specs
- Pm upper service
- Air brakes- dryer full of water, fix air leak air brakes
- Ac system service including cleaning evaporator core
- Transmission service
- Strobe light out Rr unit
- Service rear differential
- Change gear oil on both front hubs
- Left headlight out Rr headlight bulb
- to rechtin 2xs
- repairs by Rechtien. Belt,tensioner. lat
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Air Tool Lube 16oz	1.00
Stiction Elimint 16oz	1.00
Motor Treatment Gal	1.00
Non-chlor Brake Clnr	4.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Air Fltr	1.00
Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Hydraulic Filter	1.00
Ad Ip Dryer Cart	1.00
Air Valve	1.00
Air Freshener	1.00
Evap Odor Elinitator	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Syn-atf Trans Fluid S	22.00
Napa Trans Filter	1.00
Gear Oil	4.00
Brake Drum	2.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Parts Issued	Quantity
4702qp Brake Shoe	2.00
Fitting	1.00
Drum	2.00
Shoes	2.00
Tran Flu Qt Dexron3i	4.00
strobe light	1.00
85-140 Gear Oil Gear	25.00
Shop Supplies	1.00

Hours: 49.00 Comm: 1,501.77 Labor: 3,577.00 Parts: 2,644.54 Total: 7,723.31

Work Order: 2201863 **Meter:** 79446 **In Date:** 02/18/2022 **Closed:** 03/28/2022
Problem: Repair swivel & gear box

Work Completed

- Hydraulic & Pressure Sys replace gearbox motor, rotary joint and placards

Hours: 0.00 Comm: 6,384.26 Labor: 0.00 Parts: 0.00 Total: 6,384.26

Work Order: 2202038 **Meter:** 79446 **In Date:** 02/09/2022 **Closed:** 02/23/2022
Problem: Rear tires

Work Completed

- Tire Service: He Problem: Rear tires

Hours: 0.00 Comm: 1,401.20 Labor: 0.00 Parts: 0.00 Total: 1,401.20

Work Order: 2202039 **Meter:** 79446 **In Date:** 02/23/2022 **Closed:** 02/23/2022
Problem: Rear tires

Work Completed

- Tire Service: He Problem: Rear tires

Hours: 0.00 Comm: 389.62 Labor: 0.00 Parts: 0.00 Total: 389.62

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2205857 **Meter:** 81583 **In Date:** 06/02/2022 **Closed:** 07/27/2022
Problem: Hydraulic fluid leak leaks, Hoses broken bucket not working

Work Completed	Parts Issued	Quantity
- Hydraulic leak due to blown hoses. Bypass leaks and control valve in order to manually rotate boom and lower unit.	Shop Supplies	1.00
- To Palmetto Park Circle.		
- To Altec		
- Annual		
- Dielectric		
- Shop Supplies		
Hours: 8.00	Comm: 14,874.25 Labor: 584.00	Parts: 2.65 Total: 15,460.90

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2210290 **Meter:** 83803 **In Date:** 10/06/2022 **Closed:** 11/15/2022
Problem: PM Service, Driver side head light out, passenger side blinker bulb, horn not working and diver side the dash light

Work Completed

- Preventive Maint. Service
- Pm bucket
- Road test
- Service A/c system
- Replace Lh headlight bulb
- Replace Rh turn signal bulb
- Pm power steering pump
- Install Air horn valve
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Filter	1.00
Air Fltr	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Hydraulic Filter	1.00
Dielectric Oil Aw Hvi	8.00
Boxed Miniatures	1.00
Boxed Capsules	1.00
Psf Qt	1.00
Power Steering Filter Replace 7191	1.00
Air Valve	1.00
Shop Supplies	1.00

Hours: 20.50

Comm: 0.00

Labor: 1,496.50

Parts: 645.67

Total: 2,142.17

Work Order: 2212609 **Meter:** 84392 **In Date:** 12/15/2022 **Closed:** 02/24/2023

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Problem: There is a leak coming from the Radiator and have had to add water several times. Please check Thank you

Work Completed

- Operator states radiator is damaged did complete overhaul of cooling system. disassembled cooling pack removed and installed intercooler, removed and replaced fan clutch removed and replaced radiator remove and replaced expansion tank
- Drain and refill cooling system
- Replace Drive Belt and belt tensioner and idler pulley
- Replace Condensor And Drier Along With Seals
- Removed and installed hood and grille lights to gain access to coolers and to replace multiple other parts
- Drain and refill transmission due to removing trans cooler
- Replaced both bumper markers
- Removed and installed power steering reservoir. to remove coolers off front of truck
- To mako plus wait
- Extended test drive road test
- scanned vehicle for codes after repairs to ensure proper repairs completed.
- Found Marker light to be internally faulty removed and replaced marker cab light
- Upon inspection found driver headlight to be internally faulty upon repairs found headlight wiring to be burned and damaged removed burnt wiring harness and replaced with new aftermarket connector
- Shop Supplies

Parts Issued

Quantity

Radiator	1.00
Radiator Hose	1.00
Coolant Hose	1.00
Expansion Tank	1.00
Aux Radiator	1.00
Clamp	4.00
Hose	2.00
Coolant Hose	1.00
lpr	1.00
Thermostat	1.00
Rotell Elc Antifeerze	12.00
Tensioner	1.00
Belt	1.00
Idler Pulley	1.00
Fan Clutch Assembly	1.00
Cap	1.00
Clamp	2.00
Non-chlor Brake Clnr	12.00
A/c Seal Kit	1.00
Dryer	1.00
A/c Condenser	1.00
Dielect Silicone Comp	1.00
Socket	1.00
Boxed Capsules	1.00
Napa Trans Filter	1.00
Transynd 668 3x1g	6.00
Clearance Light	1.00
Shop Supplies	1.00

Hours: 56.00

Comm: 0.00

Labor: 4,088.00

Parts: 10,363.90

Total: 14,451.90

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2301024 **Meter:** 84463 **In Date:** 01/31/2023 **Closed:** 02/08/2023
Problem: Please check belts they are shredding. Thank you

Work Completed

Parts Issued

Quantity

- Replaced damaged drive belt
- Repaired Damaged pulley and cleaned / inspected threads proceeded to replace all hardware and torqued to spec aided with thread locker on hardware.
- Extended Test drive to ensure operators issue is repaired test drove vehicle 20+ miles
- Drained and refilled cooling system in order to properly do repairs.
- Shop Supplies

Drive Belt	1.00
Pulley	1.00
Bolt M6	4.00
bolt	1.00
Bolt	2.00
Bolt	1.00
Px Blue Threadlocker	1.00
Shop Supplies	1.00

Hours: 7.00

Comm: 0.00

Labor: 511.00

Parts: 199.69

Total: 710.69

Work Order: 2304984 **Meter:** 86400 **In Date:** 05/18/2023 **Closed:** 05/24/2023
Problem: AC

Work Completed

Parts Issued

Quantity

- a/c inop , check pressures , test high and low pressure switches found high pressure switch to be faulty. evac and recharge a/c system install new high pressure sensor
- test run
- Shop Supplies

Freon He Shop	10.00
Switch	1.00
Hand Wipes	1.00
Shop Supplies	1.00

Hours: 4.50

Comm: 0.00

Labor: 328.50

Parts: 369.27

Total: 697.77

Work Order: 2305868 **Meter:** 86982 **In Date:** 06/13/2023 **Closed:** 12/29/2023
Problem: PM Service

Work Completed

Parts Issued

Quantity

- Preventive Maint. Service
- To Altec 2xs
- annual
- dielectric test
- repairs by altec
- Pm Bucket
- Road test 2x

Tensioner	1.00
Drive Belt	1.00
Bushing	1.00
Dust Cover	1.00
Idler Pulley	1.00
Bolt	1.00
Electrical Tape	1.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

- Service A/c system, clean evaporator, change cab air filter
- Pm power steering pump, change filter, drain & refill
- to altec 2x
- Long road test to verify intermittent a/c inop. Diag inop condition. Found failed blend door actuator assy and sloppy recirc motor assy.
- R&r interior trim and dog house. Replace failed a/c blend door actuator and recirc motor assys.
- Operator states bin lights inop. Repair broken wiring in bins. Modify and replace all 8 bin light assys with new led units.
- Operator states passenger spot light loose. Repair loose spot light assy.
- Rattle and chirp noise from engine bay. Fan idler assy failed. R&r fan hub, shaft, clutch assys, drive belt, tensioner and idler assys.
- Air leak heard from engine bay. Trace and locate air leak. Found worn fitting and line. R&r fitting and renew air line end.
- Operator states bucket got stuck in air. Manually stow bucket and get operator down.
- Bucket will not fly. No Pto engagement. Perform diagnostics with scan tool, and wiring checks. Pto stays disabled. Unit to Altec for further repairs.
- To Altec
- To Boynton Beach blvd.
- to rechtien 2xs
- Air leak under cab. Replace leaking lines and fittings for cab air suspension.
- repairs by Rechtien
- Operator states play in steering. Inspect front end and found play in front wheel bearings. Service front hubs and adjust front wheel bearings.
- Operator states truck jumps left when brakes applied. Front drums out of round and cracked. R&r front shoes and drums. Found s cams endplay out of spec. Remove slack adjusters and Shim s cam endplay. Reinstall slack adjusters.
- Test Run
- Unit still pulls hard after alignment and bearing adjustments. Perform dial indicator inspection of front end components. Found faulty king pin thrust bearings.

Parts Issued	Quantity
hor99a4621	1.00
Pulley Fan Clutch	1.00
Mose From Mako	1.00
Hose Made Mako	1.00
Fittings From Mako	1.00
Lucas 85-140 Gear Oil	2.00
Hub Cap	2.00
4702qp Brake Shoe	2.00
Brake Drum	2.00
king pin	1.00
Tef Seal	2.00
Hub Cap Gasket	2.00
Delvac 15w40 1 Ga	8.00
13 Oz Aero Kroil	1.00
Used Fire X Refurbished	1.00
Napagold Oil Filter	1.00
Air Fltr	1.00
Filter	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Rotell Elc Antifeerze	1.00
Hydraulic Filter	1.00
Dielectric Oil Aw Hvi	12.00
Power Steering Filter	1.00
Blower Control	1.00
Actuator Door	2.00
Dome Light	8.00
Kp Tool	1.00

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

- Unit still pulls hard after alignment and bearing adjustments. Perform dial indicator inspection of front end components. Found faulty king pin thrust bearings. R&r king pins, bushings, and thrust bearings. Shim to spec.

- alignment

- Shop Supplies

Parts Issued	Quantity
--------------	----------

Bushing Driver	1.00
----------------	------

King Pin Kit	1.00
--------------	------

Onsite Alignment	1.00
------------------	------

Shop Supplies	1.00
---------------	------

Freight Charge	1.00
----------------	------

Hours: 94.50

Comm: 4,271.47

Labor: 6,898.50

Parts: 9,155.79

Total: 20,325.75

Work Order: 2400416

Meter: 87732

In Date: 01/11/2024 **Closed:** 01/30/2024

Problem: engine light/knocking/low on power/headlamps and LED head lights

Work Completed

- replace headlamp assemblies and install new headlight bulbs

- engine misfire , cylinder 3&1 injector open circuit. disassemble topside of engine replace all 6 injectors , rebuild oil rail & replace injector harness

- multiple test runs after repairs . data log high pressure oil and related injections sensors

- replace batteries

- repair ac by rechtien

- Shop Supplies

Parts Issued	Quantity
--------------	----------

9007 Led	1.00
----------	------

Head Light Assy	1.00
-----------------	------

head light	1.00
------------	------

Seal Kit	1.00
----------	------

Regulator	1.00
-----------	------

Sensor	1.00
--------	------

Gasket	1.00
--------	------

injector	6.00
----------	------

Brake Parts Cleaner	14.00
---------------------	-------

Vac Line Assy	1.00
---------------	------

vacuum harness assy	1.00
---------------------	------

Group 31 Stud Delco	3.00
---------------------	------

Rotell Elc Antifeerze	10.00
-----------------------	-------

Pigtail Harness	2.00
-----------------	------

Injector Drv Mod	1.00
------------------	------

Shop Supplies	1.00
---------------	------

Freight Charge	1.00
----------------	------

Hours: 27.00

Comm: 2,881.64

Labor: 1,971.00

Parts: 10,134.70

Total: 14,987.34

7/3/2024
2:39:02 PM

Palm Beach County Fleet Management Asset Maintenance History
10196235 2015 INTERNATIONAL 4300 Bucket Truck, 42 Ft. 33000 Gvwr, Utility Body

Work Order: 2401810 **Meter:** 88281 **In Date:** 02/16/2024 **Closed:** 03/04/2024
Problem: oil leak

Work Completed

- Operator states oil leak. Wash down unit and locate oil leak from valve cover gasket and harness. Replace gasket and harness. Refill and bleed cooling system.

- Test Run

- Shop Supplies

Parts Issued

Quantity

Gasket	1.00
Rotell Elc Antifeerze	10.00
Shop Supplies	1.00

Hours: 12.50

Comm: 0.00

Labor: 912.50

Parts: 1,150.30

Total: 2,062.80

Work Order: 2405199 **Meter:** 90957 **In Date:** 05/09/2024 **Closed:** 05/24/2024
Problem: Tires: LFS; Blowout. Replace Tire

Work Completed

- Tire Service: 2601 vista traffic lot Problem: Tires: Lfs; Blowout. Replace Tire

Hours: 0.00

Comm: 508.50

Labor: 0.00

Parts: 0.00

Total: 508.50

Work Order: 2406140 **Meter:** 91546 **In Date:** 06/25/2024 **Closed:** 06/27/2024
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

- Shop Supplies

Parts Issued

Quantity

Shop Supplies	1.00
---------------	------

Hours: 2.00

Comm: 0.00

Labor: 146.00

Parts: 2.65

Total: 148.65

Total Hours: 593.30

Total Labor: 41,111.90

Total Comm: 67,322.09

Total Parts: 50,596.06