

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Total Hours: 355.00 Labor: 24,361.00 Parts: 31,281.35 Comm: 34,890.04 Charged: 90532.39

Work Order: 1502535 **Meter:** 1161 **In Date:** 03/10/2015 **Closed:** 04/03/2015
Problem: Check in

Work Completed

- Check In
- Mount fire exstingusher plug tool box holes
- Make and apply decals
- To Rechten 2xs
- Rewire trailer plug brake wire
- Shop Supplies

Parts Issued

Quantity

3/4"plug Button	50.00
3/4" Plug Button	50.00
Shop Supplies	1.00
Freight Charge	1.00

Hours: 12.50 Comm: 0.00 Labor: 750.00 Parts: 86.55 Total: 836.55

Work Order: 1503428 **Meter:** 1161 **In Date:** 04/01/2015 **Closed:** 04/01/2015
Problem: 1062 - Make & Apply Decals. Check Fluids, Belts and Operation

Work Completed

- Make & Apply Decals. Check Fluids, Belts and Operation

Hours: 1.00 Comm: 0.00 Labor: 60.00 Parts: 0.00 Total: 60.00

Work Order: 1508676 **Meter:** 2576 **In Date:** 08/31/2015 **Closed:** 09/02/2015
Problem: pm

Work Completed

- pm
- aerial pm
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Wiper Blade	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
2602212c1 Air Filter	1.00
Napa Hydraulic Filtr	1.00
Shop Supplies	1.00

Hours: 12.50 Comm: 0.00 Labor: 750.00 Parts: 389.08 Total: 1,139.08

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 1610075 **Meter:** 8978 **In Date:** 09/26/2016 **Closed:** 11/23/2016
Problem: pm/engine light/ low on power

Work Completed

Parts Issued

Quantity

- pm	Napa Cabin Air Filter	1.00		
- pm upper	15-40 Oil	30.00		
- ac service	Napagold Oil Filter	1.00		
- to rechtien	Fuel Fil	1.00		
- scan engine light with laptop	2602212c1 Air Filter	1.00		
- road test	Wiper Blade	2.00		
- Shop Supplies	Washer Fluid Concentr	1.00		
	Non-chlor Brake Clnr	2.00		
	Used Fire X Refurbished	1.00		
	Napa Hydraulic Filtr	1.00		
	Cabin Air Filter	1.00		
	Shop Supplies	1.00		
Hours: 18.50	Comm: 0.00	Labor: 1,110.00	Parts: 395.06	Total: 1,505.06

Work Order: 1610181 **Meter:** 8929 **In Date:** 09/26/2016 **Closed:** 09/28/2016
Problem: low power, check engine light on

Work Completed

- Tow From: Jpp maint compound To: He shop

Hours: 0.00 Comm: 132.00 Labor: 0.00 Parts: 0.00 Total: 132.00

Work Order: 1611685 **Meter:** 8929 **In Date:** 11/14/2016 **Closed:** 12/02/2016
Problem: annual/repairs

Work Completed

- Annual
- r/r rusted line block,holding valves,bolton tape,tool boot, lower insert,
outrig, base, platform, placard, Sil-622
- dielectric test

Hours: 0.00 Comm: 2,793.01 Labor: 0.00 Parts: 0.00 Total: 2,793.01

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 1708872 **Meter:** 14307 **In Date:** 09/15/2017 **Closed:** 09/26/2017
Problem: PM/abs light

Work Completed

- pm
- pm upper
- service Ac system and change filters
- replace rear lights and wiring
- replace rf abs sensor
- pull abs codes. repair sensor and clear codes
- test run
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Fuel Fil	1.00
Air Filter	1.00
Wiper Blade	2.00
Washer Fluid Concentr	1.00
Non-chlor Brake Clnr	3.00
Used Fire X Refurbished	1.00
Napa Hydraulic Filtr	1.00
1cart Palladium 2 Grs	1.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Speed Sensor	1.00
Led M C Lamp	3.00
Grommet	3.00
Cable Tie	1.00
Shop Supplies	1.00

Hours: 19.00

Comm: 0.00

Labor: 1,140.00

Parts: 592.52

Total: 1,732.52

Work Order: 1710351 **Meter:** 15309 **In Date:** 10/20/2017 **Closed:** 12/20/2017
Problem: Bucket cover and outrigger pads

Work Completed

- outrigger pads and bucket cover
- Shop Supplies

Parts Issued

Quantity

outrigger pad	4.00
platform cover	1.00
Shop Supplies	1.00

Hours: 0.00

Comm: 0.00

Labor: 0.00

Parts: 383.03

Total: 383.03

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 2000273 **Meter:** 33098 **In Date:** 01/09/2020 **Closed:** 02/12/2020
Problem: PM/ List

Work Completed

- Pm
- Service Bucket
- To Altec
- To Rechten
- Service Ac
- Shop Supplies

Parts Issued

Quantity

Syn-atf Trans Fluid S	3.00
Dielectric Oil Aw Hvi	8.00
15-40 Oil	33.00
Air Fltr	1.00
Filter	1.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Napa Hydraulic Filtr	1.00
Penetrating Oil 12 Oz	1.00
L0152-063 Gear Shield	1.00
Led M C Lamp	1.00
Shop Supplies	1.00

Hours: 17.50

Comm: 0.00

Labor: 1,277.50

Parts: 474.70

Total: 1,752.20

Work Order: 2000623 **Meter:** 32987 **In Date:** 01/17/2020 **Closed:** 01/30/2020
Problem: Annual

Work Completed

- Annual
- dielectric test
- r/r start/stop switch, start/stop plunger, boom rests all at upper controls, adjust tool pressure
- r/r fuel filter, fuel pressure regulator

Hours: 0.00

Comm: 3,244.61

Labor: 0.00

Parts: 0.00

Total: 3,244.61

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

- Pm Bucket Performed
- Check Engine Light On Dpf Filter Light Flashing, Pulled Codes Found Many Codes For Dpf System, Fdp Below Min, Fuel Doser Valve, Trans Temp, Will Diag And Replace Parts Accordingly
- Performed Road Test
- Performed Transmission Service Filters Due Reset Filter Life
- A/c System Service Performed With Filters
- Performed Cooling System Service
- 3 Upper Red Marker Lights Broken On Cargo Box Replaced All 3 Lights And Gromets
- Air Brake Drier Due For Service Replaced Entire Drier Unit As Could Not Remove Old Filter Due To Being Seized
- During Inspection Found Dpf Filter Is Coming Apart Will Remove And Inspect Removed All Exhaust Parts And Replaced All Exhaust Filters And Exhaust System Parts Installed All New Temp Sensors And Pressure Sensor
- Driver States Trans Temp Fluctuating, Installed Scanner Pulled Codes Found Code For P0713 Tft Sensor Circuit High, Removed Trans Pan And Replace Tft Sensor And Wiring Harness.
- During Inspections Found 2 Fittings At Air Brake Governor Leaking Removed And Replaced Leaking Fittings
- During Diag Found Dosing Valve To Be Clogged With Carbon Causing Dpf Issues Removed Dog Box Cover Removed And Replaced Valve And Reinstalled All Removed Parts
- Travel To International
- Shop Supplies

Parts Issued	Quantity
hydrocarbon injector	1.00
Bolt	2.00
Motor Tune-up 16oz	1.00
Non-chlor Brake Clnr	2.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Napagold Oil Filter	1.00
Air Fltr	1.00
Filter	1.00
15-40 Oil	30.00
Napa Hydraulic Filtr	1.00
Napa Trans Filter	1.00
Syn-atf Trans Fluid S	20.00
Freon He Shop	2.00
Cabin Air Filter	1.00
Napa Cabin Air Filter	1.00
Rotell Elc Antifeerze	6.00
Led M C Grommet Kit	3.00
tee	1.00
Reman Air Dryer	1.00
Exhaust Temp Sensor	2.00
Dpf Filter	1.00
Purimufl	1.00
Gfil Gasket	1.00
Gfil Gasket	1.00
Band Clap	1.00
Exhaust Sensor	1.00
etg sensors	1.00
Pressure Tube	1.00
Pressure Tube	1.00

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 2202452
Problem: PM

Meter: 51381

In Date: 03/04/2022 **Closed:** 05/16/2022

Work Completed

- Preventive Maint. Service
- Bucket Pm
- Road test
- Service A/c system
- Red marker lights
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Led M C Lamp	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Non-chlor Brake Clnr	2.00
Penetrating Oil 12 Oz	1.00
Used Fire X Refurbished	1.00
Rotell Elc Antifeerze	3.00
Napa Hydraulic Filtr	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Filter	1.00
Air Fltr	1.00
Napagold Oil Filter	1.00
Shop Supplies	1.00

Hours: 13.50

Comm: 0.00

Labor: 985.50

Parts: 411.50

Total: 1,397.00

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 2300617 **Meter:** 55729 **In Date:** 01/23/2023 **Closed:** 03/31/2023
Problem: PM/annual/dielectric

Work Completed

- Preventive Maint. Service
- annual
- dielectric test
- to altec 2xs
- Repairs @ Altec
- Pm Bucket
- Road test
- Service A/c system
- Replace Red marker lamps
- power steering service
- Shop Supplies

Parts Issued

Quantity

15-40 Oil	30.00
Napagold Oil Filter	1.00
Filter	1.00
Air Fltr	1.00
Napa Hydraulic Filtr	1.00
Rotell Elc Antifeerze	1.00
Wiper Blade	2.00
Washer Fluid Concentr	2.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Non-chlor Brake Clnr	1.00
Used Fire X Refurbished	1.00
Dielectric Oil Aw Hvi	10.00
Power Steering Filter	1.00
Tran Flu Qt Dexron3i	2.00
Lamp	1.00
Led M C Grommet Kit	4.00
Shop Supplies	1.00

Hours: 19.00 Comm: 2,184.06 Labor: 1,387.00 Parts: 554.07 Total: 4,125.13

Work Order: 2304298 **Meter:** 56533 **In Date:** 04/06/2023 **Closed:** 04/28/2023
Problem: WINCH OUT OF MUD

Work Completed

- Tow From: 47225 N. Us Highway 27 (john Stretch memorial park To: Emergency Service

Hours: 0.00 Comm: 197.75 Labor: 0.00 Parts: 0.00 Total: 197.75

Work Order: 2403812 **Meter:** 64892 **In Date:** 04/17/2024 **Closed:** 05/12/2025
Problem: PM/LRO nail, front damage. Radiator line behind front bumper is leaking. Passenger bumper bracket broken., pm servic

Work Completed

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

- Preventive Maint. Service
- Recall: Altec Sil 785 - Pto Request Wire Inspection missing.
- Recall: Product Update Notice Pun2021e-upper Boom Drive System Walking Link Bearing Wear Gauge
- altec annual
- dielectric test
- to and from altec
- repairs by altec
- jump truck- replace batteys and check charging system
- complaint radiator leaking- found radiator drain leaking- replace radiator drain and check for leaks
- service cooling system
- service transmission- scrap old gaskets off filter cover
- service rear end
- service a/c system- clean cowl from excessive debris build up, clean A/c box from ants and debris, clean evap from ants and debris, and clean filters
- service power steering system
- service air dryer- replace air dryer and housing
- replace belt and tensioner and idler pulley
- service front brake system- shoes, drums, slack adjusters
- service rear brake system- shoes, drums, slack adjusters
- service aps system
- repair air leaks- repair air leaks under hood
- replace several cracking hyd lines- reline all hyd lines in terret, replace mutiple hoses for out riggers, and main hoses from tank
- replace foggy headlights
- test drive, and operate aps system 2x
- replace fuel filter housing- while changing filters found excessive debris in filter housing screen, while checking to make sure pressure relief wasn't clogged noticed the spring was miss as well, replace fuel filter housing
- to mako and wait 4x

Parts Issued	Quantity
Cable Tie Colors	1.00
Front Brake Drum	2.00
hardware kit	4.00
Rear Drum	2.00
Drive Belt	2.00
Tensioner	1.00
Idler Pulley	1.00
Used Fire X Refurbished	1.00
Filter	1.00
Napagold Oil Filter	1.00
Penetrating Oil 12 Oz	1.00
Non-chlor Brake Clnr	8.00
15-40 Oil	30.00
Washer Fluid Concentr	2.00
Wiper Blade	2.00
Air Fltr	1.00
Motor Tune-up 16oz	1.00
Napa Cabin Air Filter	1.00
Cabin Air Filter	1.00
Rotell Elc Antifeerze	8.00
Transynd 668 3x1g	6.00
Odor Eliminator	1.00
Napagold Oil Filter	1.00
Power Steering Fluid	2.00
air dryer housing	1.00
Brake Shoe	2.00
Front Slack Adjuster	2.00
Brake Chamber	4.00
Slack Adjuster	1.00
Slack Adjuster	1.00

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

- rusted Egr cooler lines- found excessive rust on Egr cooler lines, replace cooler lines, thermostat, and hoses
- power steering leak- replace both power steering lines- top off fluid and check for leaks
- onsite alignment
- replace rear brake chambers- rear brake chambers leaking, replace both rear brake chambers
- Shop Supplies

Parts Issued	Quantity	
Shoes	2.00	
L0152-063 Gear Shield	1.00	
Lucas Red-tacky Grs	2.00	
Napa Hydraulic Filtr	1.00	
Head Light Assy	1.00	
head light	1.00	
Coolent Pipe	1.00	
Coolent Pipe	1.00	
Heater Hose	6.00	
Hose	4.00	
Hose Made Mako	1.00	
Thermostat By Pass	1.00	
Center Support Bearing Asm	1.00	
Center Support Bearing	1.00	
Hose Made Mako	1.00	
Non-chlor Brake Clnr	12.00	
On Site Alignment Service	1.00	
Steering Hose	1.00	
G85w140p	1.00	
9007 Led	2.00	
Group 31 Stud Delco	2.00	
fuel pump with filter housing	1.00	
Hose	1.00	
Shop Supplies	1.00	
Freight Charge	1.00	
Freight Charge	1.00	
Labor: 6,679.50	Parts: 13,721.84	Total: 26,371.93

Hours: 91.50

Comm: 5,970.59

6/9/2025
5:17:45 PM

Palm Beach County Fleet Management Asset Maintenance History
10196237 2015 INTERNATIONAL 4300 Bucket Truck, 58 Ft. 33000 Gvwr

Work Order: 2503840 **Meter:** 64892 **In Date:** 04/17/2025 **Closed:** 04/25/2025
Problem: Tires: All Wear. Replace Tire

Work Completed

- Tire Service: he Problem: Tires: All Wear. Replace Tire

Hours: 0.00 Comm: 2,747.80 Labor: 0.00 Parts: 0.00 Total: 2,747.80

Work Order: 2504616 **Meter:** 64892 **In Date:** 05/16/2025 **Closed:** 05/22/2025
Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 2.00 Comm: 0.00 Labor: 146.00 Parts: 0.00 Total: 146.00

Total Hours: 355.00 Total Labor: 24,361.00 Total Comm: 34,890.04 Total Parts: 31,281.35