**Palm Beach County Fleet Management**
**Asset Maintenance History**

**10179594 2010 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane**

**Workorder:** 1006598 **Meter:** 338 **In Date:** 06/23/2010 **Closed:** 06/24/2010
**Problem:** flash canceiver & reprogram

- Reflashed and reprogrammed Canceiver drove 5 miles and tested ok
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |

Hours : 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

---

**Workorder:** 1007299 **Meter:** 338 **In Date:** 07/12/2010 **Closed:** 07/12/2010
**Problem:** Pre Delivery Inspection

- Pre Delivery Inspection

Hours : 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00

---

**Workorder:** 1008071 **Meter:** 679 **In Date:** 07/29/2010 **Closed:** 08/09/2010
**Problem:** Install ladder rack.

- Fabricate,drill and install new ladder rack asper request.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |
| Ladder Rack | 1.00 |

Hours : 3.00 Labor: 180.00 Parts: 480.50 Total: 660.50

---

**Workorder:** 1008762 **Meter:** 679 **In Date:** 08/02/2010 **Closed:** 08/13/2010
**Problem:** lr outer flat

- 8100 forrest hill

Hours : 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

---

**Workorder:** 1008763 **Meter:** 679 **In Date:** 08/03/2010 **Closed:** 08/13/2010
**Problem:** Tires

- 8100 forest hill

Hours : 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

---

**Workorder:** 1011781 **Meter:** 2413 **In Date:** 10/21/2010 **Closed:** 10/21/2010
**Problem:** Left rear outer tire flat.

- Repair flat left rear outer tire,nitrogen fill and balance same.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |

Hours : 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1013558 **Meter:** 3264 **In Date:** 12/09/2010 **Closed:** 12/16/2010
**Problem:** Pm service.

- P.m. Service.
- Inspect and service crane.
- Rotate and balance all six tires.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |
| 8c3z9a343a Seal Kit Fuel Filter (ford) | 1.00 |
| 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| 15/40 Oil | 15.00 |
| Used Firex Refurbed Fire Extingshers | 1.00 |
| 31-22 Wiper Blades 22" Wiper Blade | 2.00 |

Hours : 6.50 Labor: 390.00 Parts: 141.62 Total: 531.62

**Workorder:** 1100350 **Meter:** 3264 **In Date:** 12/17/2010 **Closed:** 01/10/2011
**Problem:** damage to rgt frt fender

- damage to rgt frt fender

Hours : 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

**Workorder:** 1104797 **Meter:** 5639 **In Date:** 05/04/2011 **Closed:** 05/17/2011
**Problem:** P.M. Service.

- P.m. Service.
- Replace pintle pin and chain.
- Inspect and service crane.
- Rotate and balance all six tires.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |
| 51551 Hydraulic Filter | 1.00 |
| 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| 15/40 Oil | 15.00 |
| 18410 Pintle Pin | 1.00 |

Hours : 6.75 Labor: 405.00 Parts: 129.66 Total: 534.66

**Workorder:** 1111858 **Meter:** 10719 **In Date:** 11/03/2011 **Closed:** 11/14/2011
**Problem:** P.M. service .

- P.m. Service.
- Replace broken pintle pin.
- Inspect and service crane.
- Rotate and balance all six tires.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Pm-22-a Additive Diesel Fuel (m/craft) | 1.00 |
| Shop Supplies | 1.00 |
| 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| 8c3z9a343a Seal Kit Fuel Filter (ford) | 1.00 |
| 51551 Hydraulic Filter | 1.00 |
| 15/40 Oil | 15.00 |
| 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| Used Firex Refurbed Fire Extingshers | 1.00 |
| 7090blk Frt Floor Mats (rubber Queen) | 1.00 |
| 18410 Pintle Pin | 1.00 |

Hours : 6.75 Labor: 405.00 Parts: 210.05 Total: 615.05

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1204935 **Meter:** 16077 **In Date:** 05/14/2012 **Closed:** 05/29/2012
**Problem:** rr flat

- Tire Service 8100 forrest hill/ croc - rr flat

Hours : 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

---

**Workorder:** 1204936 **Meter:** 16077 **In Date:** 05/22/2012 **Closed:** 05/29/2012
**Problem:** tires

- Tire Service 8100 forest hill blvd - tires

Hours : 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

---

**Workorder:** 1205817 **Meter:** 16736 **In Date:** 06/19/2012 **Closed:** 07/11/2012
**Problem:** P.M. service and rear light bar broken and raise outriggers.

- P.m. Service.
- Replace center rear marker light strip.
- Inspect and service crane.replace broken limit switch rod.raise both outrigger cylinders.clean rust on outrigger extension and lube.
- Replace five worn out tires and balance all.
- Complete wheel alignment.test drive.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |
| 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| 51551 Hydraulic Filter | 1.00 |
| L0135-063 Lubriplate Chain&cable Lube,03050crc | 1.00 |
| 15/40 Oil | 15.00 |
| 31-22 Wiper Blades 22" Wiper Blade | 2.00 |
| 15050r Id Bar Red Model 15 Led | 1.00 |
| 179636492 Lt245/75r17 Wrangler Sr-a E | 5.00 |
| Tr416 Valve Stem | 5.00 |
| Tire Disposal Fee | 5.00 |

Hours : 14.00 Labor: 840.00 Parts: 1,129.14 Total: 1,969.14

---

**Workorder:** 1206835 **Meter:** 17204 **In Date:** 07/23/2012 **Closed:** 07/24/2012
**Problem:** Canceiver

- check canceiver, install new style screws
- reprogram and flash canceiver
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |

Hours : 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00

---

**Workorder:** 1208210 **Meter:** 18311 **In Date:** 08/30/2012 **Closed:** 09/10/2012
**Problem:** Crane is inop.

- Diagnose crane inop complain.fault code P0730 present.replace defective brake pressure switch.clear code and retest operation.
- Diagnose electrical circuit to crane.repair wires and replace blown fuse.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |
| Brake Pressure Switch | 1.00 |
| 15319477 Fuse 30 Amp Gmc | 3.00 |

Hours : 3.50 Labor: 210.00 Parts: 45.95 Total: 255.95

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1209453 **Meter:** 19080 **In Date:** 09/14/2012 **Closed:** 10/02/2012
**Problem:** lf flat

- Tire Service croc - lf flat

Hours: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

---

**Workorder:** 1209666 **Meter:** 20059 **In Date:** 10/10/2012 **Closed:** 11/15/2012
**Problem:** Crane boom inop.

- Diagnose crane boom inop.test and replace failed boom load hydraulic pressure transducer switch with new and test all crane functions.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 33167 Pressure Switch | 1.00 |
| Shop Supplies | 1.00 |

Hours: 2.00 Labor: 120.00 Parts: 297.97 Total: 417.97

---

**Workorder:** 1301205 **Meter:** 22584 **In Date:** 02/01/2013 **Closed:** 02/27/2013
**Problem:** Pm service.

- P.m. Service.
- Inspect and service crane.repair right side out rigger.drill,re-tap and replace broken bolts in shim plate.lube slides.
- Replace right headlamp bulb.
- Replace one tire,rotate and balance all six.
- Transport vehicle to dealer for oil and coolant leak (warranty).
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Oil Filter | 1.00 |
| Napagold Fuel Filter | 1.00 |
| Used Firex Refurbed F | 1.00 |
| Stg Wheel Cov - Ford | 1.00 |
| Napa Hydraulic Filtr | 1.00 |
| Aw68 Hydro Fluid Hydr | 15.00 |
| Halogen Lamp | 1.00 |
| 179636492 Lt245-75r17 | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 1.00 |

Hours: 11.50 Labor: 690.00 Parts: 429.61 Total: 1,119.61

---

**Workorder:** 1303977 **Meter:** 24195 **In Date:** 04/23/2013 **Closed:** 04/25/2013
**Problem:** Has to jump start all the time.

- Test starting and charging system.both batteries failed loadtest after recharge.replace both failed batteries with new.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Battery 65 | 2.00 |
| Shop Supplies | 1.00 |

Hours: 2.00 Labor: 120.00 Parts: 289.22 Total: 409.22

---

**Workorder:** 1305050 **Meter:** 24692 **In Date:** 05/22/2013 **Closed:** 05/31/2013
**Problem:** Hydraulic hose under crane cracks

- Replace leaking crane hydraulic hose and clean fluid fron tool compartment.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Hose | 1.00 |
| Shop Supplies | 1.00 |

Hours: 1.50 Labor: 90.00 Parts: 56.09 Total: 146.09

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1309526 **Meter:** 28370 **In Date:** 09/20/2013 **Closed:** 11/04/2013

**Problem:** Pm service.Crane steel line broken and knob at boom missing.

- P.m. Service.
- Inspect and service crane.fabricate and install steel line to hydraulic motor.install boom lock knob..replace missing hitch pintle pin.
- Fabricate and reseal leftside back-up lamp,holding water.
- Replace one tire,rotate and balance all six.
- Replace broken cup holder.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Napagold Fuel Filter | 1.00 |
| Wiper Blade | 2.00 |
| Brake Cleaner | 1.00 |
| Washer Fl | 1.00 |
| Napa Hydraulic Filtr | 1.00 |
| Aw68 Hydro Fluid Hydr | 5.00 |
| Pintle Pin W/chain | 1.00 |
| Led Back-up Lamp Sys | 1.00 |
| Holder | 1.00 |
| 179636492 Lt245-75r17 | 1.00 |
| Hydraulic Tube | 1.00 |
| Knob | 1.00 |
| Cx05-0145 Hook Latch | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 1.00 |

Hours : 11.00 Labor: 660.00 Parts: 663.85 Total: 1,323.85

**Workorder:** 1402986 **Meter:** 31809 **In Date:** 03/27/2014 **Closed:** 03/28/2014

**Problem:** Right rear tire flat.

- Repair flat right rear outer tire.nitrogen fill and balance same.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |

Hours : 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1405298 **Meter:** 33582 **In Date:** 05/30/2014 **Closed:** 06/17/2014
**Problem:** P.M. service and check rear marker light.

- Perform pm service.
- Install four new tires.nitrogen fill and balance all six.
- Inspect and service hydraulic crane.
- Install new rear brake pads and resurface brake rotors..service calipers.flush brake fluid and automated bleed hydraulic system with scan tool.
- Inspect and replace missing tail gate light bar with new.test and replace failed bed lamp bulb with new.
- Perform wheel alignment comple.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Napagold Air Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| 179636492 Lt245-75r17 | 4.00 |
| Napagold Fuel Filter | 1.00 |
| Rear Pads | 1.00 |
| Brake Cleaner | 1.00 |
| Led M C Lamp | 1.00 |
| Aw68 Hydro Fluid Hydr | 6.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |

Hours: 17.25 Labor: 1,035.00 Parts: 1,287.21 Total: 2,322.21

**Workorder:** 1408159 **Meter:** 34880 **In Date:** 08/18/2014 **Closed:** 09/08/2014
**Problem:** Crane will not rotate left or right.

- Diagnose crane rotation inop.replace broken rotator pinion gear set and adjust bearing preload.retest.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Bearing Holder | 1.00 |
| Shop Supplies | 1.00 |
| Freight Charge | 1.00 |

Hours: 4.00 Labor: 240.00 Parts: 695.97 Total: 935.97

**Workorder:** 1410708 **Meter:** 36071 **In Date:** 10/27/2014 **Closed:** 10/31/2014
**Problem:** Crane intermittent and PTO on and off.

- Computer diagnose for Pto inop.and wrench light on.codes Po703 and P162e Perform pin point test and replace defective brake deactivation switch.also recalibrate Pcm with latest update.
- Replace missing Led light on clearance light bar in rear of truck.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Switch | 1.00 |
| Led M C Lamp | 1.00 |
| Shop Supplies | 1.00 |

Hours: 3.50 Labor: 210.00 Parts: 55.60 Total: 265.60

**Workorder:** 1411075 **Meter:** 36205 **In Date:** 11/05/2014 **Closed:** 11/06/2014
**Problem:** wont fuel

- Test Canceiver . repair electrical connections
- Shop Supplies

| Parts List | Qty |
|---|---|
| Shop Supplies | 1.00 |

Hours: 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1412217 **Meter:** 36803 **In Date:** 12/05/2014 **Closed:** 12/31/2014

**Problem:** Pm service.Left rear tire flat.Replace crane cable.

- Pm service.
- Inspect and service hydraulic crane.replace defective hoist cable.
- Replace one tire.rotate and balance all six.
- Replace defective left headlamp.
- Fabricate and replace broken vise on rear bumper.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Hd Workshop Vise | 1.00 |
| Aw68 Hydro Fluid Hydr | 7.00 |
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| Wiper Blade | 2.00 |
| Napagold Fuel Filter | 1.00 |
| 179636492 Lt245-75r17 | 1.00 |
| Tr416 Valve Stem | 1.00 |
| Halogen Lamp | 1.00 |
| Clr Rtv Silcn Sealant | 1.00 |
| Crane Cable Fabrication | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 1.00 |

Hours : 9.50 Labor: 570.00 Parts: 748.29 Total: 1,318.29

**Workorder:** 1505873 **Meter:** 40210 **In Date:** 06/12/2015 **Closed:** 08/18/2015

**Problem:** P.M. service and replace damaged utility door left center.

- P.m. Service.
- Replace both tail lamps.
- Inspect and service crane.
- Resurface front brake rotors,replace front pads.service and lube calipers,flush and bleed system.
- Replace left side center bin door with salvage parts.
- Pressure test and inspect cooling system.replace leaking upper radiator hose.flush and refill cooling system.
- Rotate and balance all six tires.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| Used Fire X Refurbished | 1.00 |
| Wiper Blade | 2.00 |
| M C Lamp | 2.00 |
| Napa Hydraulic Filtr | 1.00 |
| Brake Pads | 1.00 |
| Body Mount Kit | 2.00 |
| Curved Radiator Hose | 1.00 |
| Peak Global | 3.00 |
| Cx05-0145 Hook Latch | 1.00 |
| Shop Supplies | 1.00 |

Hours : 17.50 Labor: 1,050.00 Parts: 511.73 Total: 1,561.73

**Workorder:** 1510491 **Meter:** 42119 **In Date:** 10/16/2015 **Closed:** 10/27/2015

**Problem:** Hydraulic oil leak under bed of truck.Rear clearance light bar broken.

- Replace corroded leaking hydraulic oil filter due to chemical .in truck.also repair crane hydraulic oil line leaking degrease and clean both areas.
- Replace broken rear three Led light bar and rewire.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Napa Hydraulic Filtr | 1.00 |
| Led Id Bar 6 Ctrs | 1.00 |
| Aw68 Hydro Fluid Hydr | 10.00 |
| Shop Supplies | 1.00 |

Hours : 4.00 Labor: 240.00 Parts: 75.74 Total: 315.74

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1601219 **Meter:** 44160 **In Date:** 02/04/2016 **Closed:** 03/17/2016

**Problem:** Pm service.Left rear tire flat.Replace crane cable.Check batteries.

- Pm service.
- Check starting and charging system.both batteries failed loadtest after recharge.replace both defective batteries.
- Inspect and service crane.replace defective winch cable and pressure transducer switch.
- Dismantle light bar .test and replace four defective strobe light bulbs.
- Replace one tire.rotate and balance all six.
- Flush and replace transmission fluid.
- Replace defective Led clearance light bar above rear bumper.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| Battery | 2.00 |
| Napa Hydraulic Filtr | 1.00 |
| 179636492 Lt245-75r17 | 1.00 |
| Syn-atf Trans Fluid S | 12.00 |
| Led Back-up Lamp Sys | 1.00 |
| Aw68 Hydro Fluid Hydr | 5.00 |
| Lift Cable | 1.00 |
| Linear Strobe Module | 4.00 |
| Pressure Switch | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 1.00 |
| Freight Charge | 1.00 |

Hours : 16.00 Labor: 960.00 Parts: 2,042.92 Total: 3,002.92

**Workorder:** 1604224 **Meter:** 45838 **In Date:** 04/21/2016 **Closed:** 06/09/2016

**Problem:** Crane will not rotate.

- Diagnose crane inop.r&r crane assemble from truck.diss-assemble crane and replace pedestal and sheared off rotation gears.reinstall and adjust gear lash.replace defective cylinder holding valve.test crane operation.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Screw | 3.00 |
| washer | 3.00 |
| Dowel Pin | 3.00 |
| Wormgear | 1.00 |
| dust shield | 1.00 |
| Lock Nut | 1.00 |
| Bearing Cone | 1.00 |
| Bearing Cup | 1.00 |
| Bearing Holder Motor | 1.00 |
| Bearing Holder Adjuster | 1.00 |
| Weldment Base | 1.00 |
| Clr Rtv Silcn Sealant | 2.00 |
| Counter Balance Valve | 1.00 |
| Shop Supplies | 1.00 |
| Freight Charge | 1.00 |

Hours : 20.00 Labor: 1,200.00 Parts: 2,712.79 Total: 3,912.79

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1606740 **Meter:** 46416 **In Date:** 07/01/2016 **Closed:** 07/29/2016
**Problem:** Crane cable need replaced.Check fluid leak on cylinder.

- Replace leaking boom cylinder.replace damaged cable.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Lift Cable | 1.00 |
| Lift Clinder | 1.00 |
| Shop Supplies | 1.00 |
| Freight Charge | 1.00 |

Hours 5.00 Labor: 300.00 Parts: 1,233.54 Total: 1,533.54
:

**Workorder:** 1610233 **Meter:** 51984 **In Date:** 09/29/2016 **Closed:** 04/18/2017
**Problem:** P.M. Service.Right rear tire has nail.

- P.m. Service.
- Blower works only on high.replace blower resistor.
- Inspect and service crane.replace pressure switch.
- Replace four tires,rotate and balance all six.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Napagold Air Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| 22" Wiper Blade | 2.00 |
| Bulb | 1.00 |
| Free Replaces Pentron | 1.00 |
| Blower Resistor | 1.00 |
| Napa Hydraulic Filtr | 1.00 |
| 179636492 Lt245-75r17 | 4.00 |
| Tr416 Valve Stem | 4.00 |
| Seal Kit | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |

Hours 9.50 Labor: 570.00 Parts: 1,312.80 Total: 1,882.80
:

**Workorder:** 1704769 **Meter:** 52514 **In Date:** 05/12/2017 **Closed:** 05/22/2017
**Problem:** P.M. service and front fuel cap missing.

- P.m. service .install missing fuel cap.
- Replace two tires ,new on front.rotate and balance all six tires.nitro fill tires.
- Inspect and service crane .replace filter.
- Inspect and serviceemergency lighting bar.four lamps inop.install new lamps and test.check and repair trailer tail circuit inop.burnt fuse replaced.
- Perform complete front end alignment.install left front adjustable bushing.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| 22" Wiper Blade | 2.00 |
| Used Fire X Refurbished | 1.00 |
| Washer Fluid Concentr | 1.00 |
| 179636492 Lt245-75r17 | 2.00 |
| Napa Hydraulic Filtr | 1.00 |
| Whelen 500 6led Ctr Pod Amber | 4.00 |
| Fuel Cap | 1.00 |
| Fmx-30 Fuse | 1.00 |
| Caster-camber Bushing | 1.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 2.00 |

Hours 13.00 Labor: 780.00 Parts: 1,438.04 Total: 2,218.04
:

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1710801 **Meter:** 57100 **In Date:** 11/01/2017 **Closed:** 11/02/2017
**Problem:** RF Tire

- Rf tire

Hours: 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

**Workorder:** 1711663 **Meter:** 57508 **In Date:** 11/29/2017 **Closed:** 12/18/2017
**Problem:** P.M. service.

- P.m. service.
- Inspect all brakes .r&i new rear brakes.resurface both rear rotors.install calipers and service caliper pins.completely bleed and flush brake system .road test.
- Perform battery load test and charging analizing .both batteries failed .alt out put 180 amps.no drain .replace both batteries.
- Inspect and replace both rear broken bump stops.
- Inspect and service crane.r&i out riggers entension and pads .lube and rust and corrosion from slides.r&i Pto pressure switch,leaking.
- Inspect and test tail light circuit .r&i new lamp.
- Perform rotation and high speed balancing all six wheels.replace right front to match other tire.nitro fill all.
- Shop Supplies

| Parts List | Qty |
|---|---|
| 15-40 Oil | 15.00 |
| Napagold Oil Filter | 1.00 |
| Fuel Filter Ford Only | 1.00 |
| 22" Wiper Blade | 2.00 |
| Washer Fluid Concentr | 1.00 |
| Slip Plate Spray 12oz | 1.00 |
| Brake Pad | 1.00 |
| Reman Brake Caliper | 1.00 |
| Reman Brake Caliper | 1.00 |
| B Fluid Dot 3-32oz | 1.00 |
| Non-chlor Brake Clnr | 1.00 |
| Battery 65 | 2.00 |
| Bumper | 2.00 |
| Napa Hydraulic Filtr | 1.00 |
| Pressure Switch | 1.00 |
| Led Sup Mdl 44 42 Dio | 1.00 |
| Shop Supplies | 1.00 |
| Lt245/75r17 Tire | 1.00 |

Hours: 17.30 Labor: 1,038.00 Parts: 1,101.41 Total: 2,139.41

**Palm Beach County Fleet Management**
**Asset Maintenance History**

**Workorder:** 1807270 **Meter:** 60172 **In Date:** 07/17/2018 **Closed:** 07/24/2018
**Problem:** P.M. service and A/C not cold.

- P.m. service.
- Test and replace defective high mounted brake light assembly and right rear tail light assembly . Replace trailer plug connector and rewire as needed.
- A/c performance test . Leak test . Recover system and add R134 stop leak .complete recharge and retest.
- Inspect and service crane.
- Balance and rotate all six tires. Nitrofill.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Napagold Oil Filter | 1.00 |
| 15-40 Oil | 15.00 |
| Washer Nozzle | 2.00 |
| 20" Wiper Blade | 2.00 |
| Fuel Filter Ford Only | 1.00 |
| Seal Kit | 1.00 |
| Used Fire X Refurbished | 1.00 |
| Ford Triton Pvc Swc | 1.00 |
| Led Sup Mdl 44 42 Dio | 1.00 |
| trailer plug | 1.00 |
| Freon Lv Shop 2 | 2.00 |
| Red Angel Ac Stop Lk | 1.00 |
| Napa Hydraulic Filtr | 1.00 |
| Lamp Assy | 1.00 |
| Shop Supplies | 1.00 |

Hours : 10.90 Labor: 654.00 Parts: 467.72 Total: 1,121.72

**Workorder:** 1900655 **Meter:** 63618 **In Date:** 01/16/2019 **Closed:** 01/29/2019
**Problem:** P.M. service.

- P.m. service.
- Inspect and service crane . Replace failed eye hook for cable guild. Replace failed tank cap breather .
- Replace four tires . Rotate and high speed balance all six tires . Nitrofill all.
- Replace both defective front bump stops .
- Pressure test and inspect cooling system . Repair leak for loose clamp at cooler . Top off coolant and retest.
- Shop Supplies

| Parts List | Qty |
|---|---|
| Napagold Oil Filter | 1.00 |
| 15-40 Oil | 15.00 |
| Used Fire X Refurbished | 1.00 |
| Washer Fluid Concentr | 1.00 |
| 20" Wiper Blade | 2.00 |
| Fuel Filter Ford Only | 1.00 |
| Filler Breather | 1.00 |
| Aw68 Hydro Fluid Hydr | 12.00 |
| Eye Bolt | 1.00 |
| Napa Hydraulic Filtr | 1.00 |
| Tr416 Valve Stem | 4.00 |
| Lt245/75r17 Mich Defend Ltx | 4.00 |
| bumper | 2.00 |
| Shop Supplies | 1.00 |
| Tire Disposal Fee | 4.00 |

Hours : 10.50 Labor: 703.50 Parts: 1,391.02 Total: 2,094.52

**Workorder:** 1907472 **Meter:** 67104 **In Date:** 07/19/2019 **Closed:** 07/19/2019
**Problem:** Transition Prep Charge

- Transition Prep Charge

Hours : 2.00 Labor: 134.00 Parts: 0.00 Total: 134.00