Palm Beach County Fleet Management
Asset Maintenance History

10142515 2003 FORD CROWN VICTORIA Car, Standard, 4 Door

Workorder: 252081 **Meter:** 4511 **In Date:** 11/21/2002 **Closed:** 11/22/2002
Problem: P.M. SERVICE.

- P.m. Service.
- Service Brakes.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
L/f Ph820 Frm Ph2 Wix 51372 Oil Filter	1.00
5w20 Engine Oil	6.00

Hours 2.50 Labor: 125.00 Parts: 21.93 Total: 146.93
:

Workorder: 343867 **Meter:** 7887 **In Date:** 07/10/2003 **Closed:** 07/14/2003
Problem: P.M.SERVICE

- Pm Service
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
L/f Ph820 Frm Ph2 Wix 51372 Oil Filter	1.00
5w20 Engine Oil	5.00

Hours 2.00 Labor: 100.00 Parts: 19.15 Total: 119.15
:

Workorder: 441581 **Meter:** 12076 **In Date:** 04/16/2004 **Closed:** 04/20/2004
Problem: P.M. SERVICE.RECALL.

- Pm Service
- Transport & Pickup Vehicle At Dealer.(recall#02b02/03s05)
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
L/f Ph820 Frm Ph2 Wix 51372 Oil Filter	1.00
G8018 Fuel Filter Lbf G6593 Wix 33595	1.00
5w20 Engine Oil	5.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours 3.00 Labor: 150.00 Parts: 36.29 Total: 186.29
:

Workorder: 452750 **Meter:** 12800 **In Date:** 08/03/2004 **Closed:** 08/04/2004
Problem: P.M.SERVICE

- Pm Service
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours 2.00 Labor: 100.00 Parts: 36.00 Total: 136.00
:

Workorder: 541774 **Meter:** 15040 **In Date:** 04/13/2005 **Closed:** 04/15/2005
Problem: P.M.SERVICE,RECALL(WHEELS)

- Pm Service
- Balance 4 Tires
- Ck Charging Sys; Recharge Battery
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
46814 Air Filter Crown Vic Police Pkg	1.00
G8018 Fuel Filter Lbf G6593 Wix 33595	1.00
5w20 Engine Oil	7.00

Hours 3.50 Labor: 175.00 Parts: 40.34 Total: 215.34
:

Palm Beach County Fleet Management
Asset Maintenance History

Workorder: 551953 **Meter:** 16467 **In Date:** 08/02/2005 **Closed:** 08/03/2005
Problem: P.M.SERVICE

- Pm
- Rr 4 Tires
- Ck Charging Sys Rr Battery
- Complete Alignment And Test Drive
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	6.00
31-22 Wiper Blades 22" Wiper Blade	2.00
65-72 Battery Group Group 65	1.00
732354500 225/60r16 Eagle Rs-a 97v	4.00

Hours 6.75 Labor: 337.50 Parts: 383.90 Total: 721.40
:

Workorder: 557984 **Meter:** 0 **In Date:** 11/01/2005 **Closed:** 11/10/2005
Problem: 002 WASH TICKETS ISSUED OUT 11/01/05

- 002 Wash Tickets Issued Out 11/01/05

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 632998 **Meter:** 18039 **In Date:** 01/19/2006 **Closed:** 01/20/2006
Problem: P.M.SERVICE

- Pm Service
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
5w20 Engine Oil	7.00
31-22 Wiper Blades 22" Wiper Blade	2.00

Hours 2.00 Labor: 100.00 Parts: 42.99 Total: 142.99
:

Workorder: 647689 **Meter:** 21310 **In Date:** 10/24/2006 **Closed:** 10/31/2006
Problem: PM SERVICE-D/S WINDOW INOP

- Pm Service
- Ck Driver's Window Motor Inop.r&r Door Panel And Replace Lift Motor.replace Defective Power Mirror Switch.
- Replace Both Rear Shocks.(leaking)
- Nitrogen Fill All Tires.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00
1372 Oil Filter Frm Ph2 Wix 51372	1.00
46814 Air Filter Crown Vic Police Pkg	1.00
G8018 Fuel Filter Lbf G6593 Wix 33595	1.00
5w20 Engine Oil	7.00
Wd40 Spray Lube Stock# 405540002	1.00
31-22 Wiper Blades 22" Wiper Blade	2.00
1w7z5423394ba Driver Window Motor	1.00
F5tz17b676a Power Mirror Switch	1.00
3u2z18125af Rear Shock Absorbor	2.00

Hours 7.00 Labor: 385.00 Parts: 336.48 Total: 721.48
: