Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 55891008
Invoice No. 55345 - 55891008

Client Department:
Department: 55345M
Work Order Description
NO CRANK NO START-VEHICLE RETIRED
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 342,080 - DH

Chronology		
Reported	Aug 26, 2022 4:05:00 PM	Aug 26, 2022 4:05:00 PM
Started	Aug 29, 2022 4:10:00 PM	
Completed	Aug 29, 2022 11:57:00 PM	Aug 29, 2022 11:57:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle no crank.

Cause: Main fuse missing, alternator not charging sufficiently.

Correction: Replaced main fuse with good used unit. Remove and replaced alternator and 2 batteries (34AGM) not in inventory.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 29, 2022 7:32:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 55891008
Invoice No. 55345 - 55891008

Client Department:
Department: 55345M
Work Order Description
NO CRANK NO START-VEHICLE RETIRED
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 342,080 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL NO CRANK NO START-VHEICLE TOWED BY GARDENS
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 55891008
Invoice No. 55345 - 55891008

Client Department:
Department: 55345M
Work Order Description
NO CRANK NO START-VEHICLE RETIRED
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 342,080 - DH

Activity Header
Activity: 20 032 CRANKING
Activity Note: CHECK VEHICLE FOR NO CRANK CONDITION
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-22	Earl Johnson	1.18	0	0
29-Aug-22	Earl Johnson	0.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 55891008
Invoice No. 55345 - 55891008

Client Department:
Department: 55345M
Work Order Description
NO CRANK NO START-VEHICLE RETIRED
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 342,080 - DH

Activity Header
Activity: 30 031/001/001 ALTERNATOR
Activity Note: Install Alternator
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Aug-22	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	230	230

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-22	Earl Johnson	1.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	230.00
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.00**

Work Order Footer

Work Order 55891008 Total	
Parts:	230.00
Labor:	0.00
Labor Hours:	3.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**230.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55854142
Invoice No. 55345 - 55854142

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear AC malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	99 - Cancelled (99)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	340,442 - DH

Chronology		
Reported	Aug 14, 2022 7:26:43 PM	Aug 14, 2022 7:26:43 PM
Started	Aug 14, 2022 7:28:00 PM	
Completed	Aug 23, 2022 4:17:00 PM	Aug 23, 2022 4:17:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:***VOID***

Cause:

Correction:

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 23, 2022 4:15:40 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Aug 23, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				4:15:40 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 23, 2022 4:15:40 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 23, 2022 4:15:40 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 23, 2022 4:15:40 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 23, 2022 4:15:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55854142
Invoice No. 55345 - 55854142

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear AC malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	99 - Cancelled (99)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	340,442 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Aug-22	Earl Johnson	1.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55854142 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55844949
Invoice No. 55345 - 55844949

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Rear AC		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	340,174 - DH

Chronology		
Reported	Aug 10, 2022 3:50:00 PM	Aug 10, 2022 3:50:00 PM
Started	Aug 10, 2022 3:50:00 PM	
Completed	Aug 11, 2022 12:43:00 AM	Aug 11, 2022 12:43:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: System restriction.

Correction: Remove and replaced rear orifice tube. Vacuum, leak tested, added PAG oil and recharged to spec.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 10-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Aug 10, 2022 7:58:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55844949
Invoice No. 55345 - 55844949

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Rear AC		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	340,174 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear AC
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.77	0.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-22	Earl Johnson	3.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.77
Labor:	0.00
Labor Hours:	3.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.77**

Work Order Footer

Work Order 55844949 Total	
Parts:	0.77
Labor:	0.00
Labor Hours:	3.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55834639
Invoice No. 55345 - 55834639

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
A/C Not Working		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	339,786 - DH

Chronology		
Reported	Aug 7, 2022 1:53:54 PM	Aug 7, 2022 1:53:54 PM
Started	Aug 7, 2022 1:56:00 PM	
Completed	Aug 7, 2022 3:46:00 PM	Aug 7, 2022 3:46:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front A/C at 65MPH air Goes to defrost

Cause: Bad A/C Check Valve

Correction: Swap A/C Vacuum tank & Check Valve from adown bus & Replace Road test all is Ok At this time. no New Parts use.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 7, 2022 1:56:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55834639
Invoice No. 55345 - 55834639

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
A/C Not Working		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	339,786 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Aug-22	Arthurs,Durvin	1.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55834639 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55802429
Invoice No. 55345 - 55802429

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
check engine light on		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,718 - DH

Chronology		
Reported	Jul 25, 2022 8:09:00 PM	Jul 25, 2022 8:09:00 PM
Started	Jul 25, 2022 8:11:00 PM	
Completed	Aug 3, 2022 2:41:00 PM	Aug 3, 2022 2:41:00 PM
Down Time		

Work Order Notes

Line 10 VEHICLE CAME IN FOR MISFIRE ISSUE. ' i check and found the intake is leaking coolant Line 20 removed intake from engine and clean up black for replacement parts next day Line 30 I will issue parts next shift stop working on unit at 9 pm Line 40 removed and replace new intake malifold to unit part# 615-188. change spark plugs 8. PART number sp521. also 8. coil boot PART # 357006 and 16 injector seal part # FOPZ-9229-A. CHANGE ONE INJECTOR CABLE PART # 5U2Z-14S411-ZB. ROAD TEST VEHICLE FOR 10 MILES VEHICLE WORKING ASDESIGN RETURN VEHICLE BACK TO WORK Line 50 replaced five gallons coolant FXAB 51

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 3, 2022 2:38:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55802429
Invoice No. 55345 - 55802429

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
check engine light on		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,718 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55802429
Invoice No. 55345 - 55802429

Client Department:
Department: 55345M
Work Order Description
check engine light on
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 338,718 - DH

Activity Header
Activity: 30 020 GROUP, DRIVETRAIN
Activity Note: intake leaking coolant
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Aug-22	357006	BOOT, COIL-ON-PLUG, IGNITION	8	6.42	51.36
04-Aug-22	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	1	13.54	13.54
04-Aug-22	SP-521	PLUG, SPARK, 5.4L, FORD	6	4.84	29.04
03-Aug-22	SP-521	PLUG, SPARK, 5.4L, FORD	1	4.84	4.84
03-Aug-22	FXAB51	ANTIFREEZE, PREMIXED, TYPE-3, RED, EXTENDED-LIFE, OAT	5	0.72	3.6
03-Aug-22	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	1	13.54	13.54
04-Aug-22	SP521	PLUG, SPARK, 5.4L, FORD	1	3.54	3.54
03-Aug-22	615-188	MANIFOLD, INTAKE, DORMAN	1	191.03	191.03
03-Aug-22	5U2Z-14S411-ZB	PIGTAIL, WIRE, INJECTOR, FUEL SAME AS WPT1051	1	16.18	16.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-22	Junior Hurst	6.32	0	0
02-Aug-22	Junior Hurst	8.88	0	0
03-Aug-22	Junior Hurst	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	326.67
Labor:	0.00
Labor Hours:	17.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**326.67**

Work Order Footer

	Work Order 55802429 Total	
	Parts:	326.67
	Labor:	0.00
	Labor Hours:	17.32
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**326.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55794983
Invoice No. 55345 - 55794983

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 HEADLIGHTS		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,556 - DH

Chronology		
Reported	Jul 22, 2022 10:46:33 AM	Jul 22, 2022 10:46:33 AM
Started	Jul 22, 2022 12:00:00 AM	
Completed	Jul 22, 2022 10:50:00 AM	Jul 22, 2022 10:50:00 AM
Down Time		

Work Order Notes

Line 10 replaced driver side headlight bulb

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 22-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jul 22, 2022 10:48:05 AM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55794983
Invoice No. 55345 - 55794983

Client Department:
Department: 55345M
Work Order Description
55345 HEADLIGHTS
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 338,556 - DH

Activity Header
Activity: 20 034/001/000 HEADLAMP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-22	H13BP	BULB, HEADLAMP, HALOGEN	1	12.2	12.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-22	Rodriguez,Raul	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	12.20
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.20**

Work Order Footer

Work Order 55794983 Total	
Parts:	12.20
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55787156
Invoice No. 55345 - 55787156

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 338,052 - DH

Chronology		
Reported	Jul 19, 2022 10:26:12 PM	Jul 19, 2022 10:26:12 PM
Started	Jul 19, 2022 11:24:00 PM	
Completed	Jul 20, 2022 12:55:00 AM	Jul 20, 2022 12:55:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs front tires and AC filter

Cause: tires low spec ,AC filter bad

Correction:2 new tires mount and balance, replace AC filter
torque wheels 140 lbs second torque 140 lbs
part number 192659 qty2

Activity Header
Activity: 10 001/001 AIR CONDITIONING
Activity Note: needs AC filter
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	140.79	281.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-22	Gaspard,Ronald	0.42	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	281.58
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**281.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55787156
Invoice No. 55345 - 55787156

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,052 - DH

Activity Header
Activity: 20 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs front tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-22	Gaspard,Ronald	0.52	0	0
20-Jul-22	Gaspard,Ronald	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55787156 Total	
Parts:	281.58
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**281.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55630425
Invoice No. 55345 - 55630425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,052 - DH

Chronology		
Reported	Jul 11, 2022 12:00:00 AM	Jul 11, 2022 12:00:00 AM
Started	Jul 19, 2022 3:41:00 PM	
Completed	Jul 19, 2022 10:59:00 PM	Jul 19, 2022 10:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
check inflate tires to spec

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 19, 2022 8:46:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55630425
Invoice No. 55345 - 55630425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	338,052 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jul-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-22	Gaspard,Ronald	1.75	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 19-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jul 19, 2022 10:23:34 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jul 19, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				10:23:34 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done	needs AC filter	RGASPARD	Jul 19, 2022 10:23:34 PM	Yes	55787156
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	2 32nds of an inch	needs front tires	RGASPARD	Jul 19, 2022 10:23:34 PM	Yes	55787156
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jul 19, 2022 10:23:34 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	2.19
	Labor:	0.00
	Labor Hours:	1.75
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55630425
Invoice No. 55345 - 55630425

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 338,052 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-22	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 19-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 19, 2022 10:33:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 19, 2022 10:33:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 19, 2022 10:33:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 19, 2022 10:33:18 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 19, 2022 10:33:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 19, 2022 10:33:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 19, 2022 10:33:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 19, 2022 10:33:18 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.20
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55630425 Total	
Parts:	2.19
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54732649
Invoice No. 55345 - 54732649

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
QCC FLEET INSPECTION		Ford E350 Champion Crusaders	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	337,832 -

Chronology

Reported	Jul 13, 2022 12:41:11 PM	Jul 13, 2022 12:41:11 PM
Started	Jul 13, 2022 9:28:00 PM	
Completed	Jul 13, 2022 9:30:00 PM	Jul 13, 2022 9:30:00 PM
Down Time		

Work Order Notes

Line 10 PERFROM QCC INSPECTION

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 13-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 13, 2022 9:16:26 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54732649
Invoice No. 55345 - 54732649

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
QCC FLEET INSPECTION		Ford E350 Champion Crusaders	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	337,832 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54732649 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55771354
Invoice No. 55345 - 55771354

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check AC (Rear AC)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	337,832 - DH

Chronology		
Reported	Jul 13, 2022 5:03:00 PM	Jul 13, 2022 5:03:00 PM
Started	Jul 13, 2022 5:05:00 PM	
Completed	Jul 13, 2022 7:26:00 PM	Jul 13, 2022 7:26:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: RearcAC malfunction.

Cause: Faulty condenser fan.

Correction: Remove and replaced 1 condenser fan.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 13, 2022 6:43:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 13, 2022 6:43:08 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 13, 2022 6:43:08 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 13, 2022 6:43:08 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 13, 2022 6:43:08 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Jul 13, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:43:08 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55771354
Invoice No. 55345 - 55771354

Client Department:
Department: 55345M
Work Order Description
Check AC (Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 337,832 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear AC
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-22	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	1	64.51	64.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-22	Earl Johnson	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	64.51
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.51**

Work Order Footer

Work Order 55771354 Total	
Parts:	64.51
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**64.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55667053
Invoice No. 55345 - 55667053

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
HEAD LIGHT ASSY		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	334,321 - DH

Chronology		
Reported	Jun 6, 2022 9:03:00 AM	Jun 6, 2022 9:03:00 AM
Started	Jun 6, 2022 9:39:00 AM	
Completed	Jun 6, 2022 2:50:00 PM	Jun 6, 2022 2:50:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: head light assy bracket broken, (driver side)

Cause: unknow

Correction: removed and replaced head light with know used good part

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 06-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 6, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:49:38 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 6, 2022 2:49:38 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 6, 2022 2:49:38 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 6, 2022 2:49:38 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 6, 2022 2:49:38 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 6, 2022 2:49:38 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55667053
Invoice No. 55345 - 55667053

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
HEAD LIGHT ASSY		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	334,321 - DH

Activity Header
Activity: 20 034/001/000 HEADLAMP
Activity Note: check driver side head lamp assy
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jun-22	Rodriguez,Raul	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55667053 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55653008
Invoice No. 55345 - 55653008

Client Department:
Department: 55345M
Work Order Description
Road Call (Bus Hard To Stop) All Lights On Dash
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 333,932 - DH

Chronology		
Reported	May 31, 2022 4:26:00 PM	May 31, 2022 4:26:00 PM
Started	May 31, 2022 4:27:00 PM	
Completed	May 31, 2022 7:28:00 PM	May 31, 2022 7:28:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:bus has no power and over heat

Cause: belt broken

Correction: replace serpentine belt
part number 1360K6 qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 31, 2022 7:21:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55653008
Invoice No. 55345 - 55653008

Client Department:
Department: 55345M
Work Order Description
Road Call (Bus Hard To Stop) All Lights On Dash
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 333,932 - DH

Activity Header
Activity: 10 045/000 POWER PLANT
Activity Note: ROAD CALL (Hard To Stop)
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-May-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.32	21.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-May-22	Gaspard,Ronald	2.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.32
Labor:	0.00
Labor Hours:	2.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.32**

Work Order Footer

Work Order 55653008 Total	
Parts:	21.32
Labor:	0.00
Labor Hours:	2.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55648337
Invoice No. 55345 - 55648337

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Left headlight housing damaged.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	333,704 - DH

Chronology		
Reported	May 29, 2022 12:03:50 PM	May 29, 2022 12:03:50 PM
Started	May 29, 2022 12:06:00 PM	
Completed	May 29, 2022 6:09:00 PM	May 29, 2022 6:09:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Left headligut housing damage.

Cause: Damaged during operation.

Correction: Reattached headlight housing mounting bracket.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 29, 2022 6:08:00 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	May 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				6:08:00 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 29, 2022 6:08:00 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 29, 2022 6:08:00 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 29, 2022 6:08:00 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 29, 2022 6:08:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55648337
Invoice No. 55345 - 55648337

Client Department:
Department: 55345M
Work Order Description
Left headlight housing damaged.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 333,704 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Left headlight housing damaged.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-May-22	Earl Johnson	2.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55648337 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55634940
Invoice No. 55345 - 55634940

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Tire Rear)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 333,288 - DH

Chronology		
Reported	May 24, 2022 5:37:00 PM	May 24, 2022 5:37:00 PM
Started	May 24, 2022 5:39:00 PM	
Completed	May 24, 2022 7:34:00 PM	May 24, 2022 7:34:00 PM
Down Time		

Work Order Notes

Line 10 right rear outside tire flat puncture
dismount tire , patch , mount and balance
torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 24, 2022 7:24:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 24, 2022 7:24:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 24, 2022 7:24:06 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	May 24, 2022 7:24:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 24, 2022 7:24:06 PM	No	
11 - Have you successfully completed the Personal	Done		RGASPARD	May 24, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				7:24:06 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55634940
Invoice No. 55345 - 55634940

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Tire Rear)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 333,288 - DH

Activity Header
Activity:20 017/001/000 TIRE, PNEUMATIC
Activity Note: Check Rear Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-22	Gaspard,Ronald	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55634940 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55524489
Invoice No. 55345 - 55524489

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	333,288 - DH

Chronology		
Reported	May 19, 2022 12:00:00 AM	May 19, 2022 12:00:00 AM
Started	May 23, 2022 7:51:00 AM	
Completed	May 23, 2022 12:26:00 PM	May 23, 2022 12:26:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PMC Service

Cause: preventive maintenance

Correction: PMC Service and lube, transmission service, and rear end service, front tire rotation

lift ,batteries service

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55524489
Invoice No. 55345 - 55524489

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	333,288 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-22	NELSON PIERRE-LOUIS	2.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	May 23, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:26:21 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	May 23, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	12:26:21 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	21567 Cycles		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	May 23, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	12:26:21 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	May 23, 2022 12:26:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55524489
Invoice No. 55345 - 55524489

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 333,288 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-22	20021	FILTER, TRANSMISSION 20021	1	17.44	17.44
23-May-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.14	2.14
23-May-22	65266	PLUG, DRAIN, OIL, ENGINE	1	4.9	4.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-22	NELSON PIERRE-LOUIS	1.58	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	May 23, 2022 12:25:37 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.48
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.48**

Work Order Footer

Work Order 55524489 Total	
Parts:	24.48
Labor:	0.00
Labor Hours:	3.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55529512
Invoice No. 55345 - 55529512

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 REAR BRAKE		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,502 - DH

Chronology		
Reported	Apr 18, 2022 7:12:42 AM	Apr 18, 2022 7:12:42 AM
Started	Apr 18, 2022 7:23:00 AM	
Completed	Apr 18, 2022 9:16:00 AM	Apr 18, 2022 9:16:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: low rear brake pads

Cause: Wear, preventive maintenance

Correction: replaced rear brake pads and lube pins

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 18-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 18, 2022 9:15:16 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 18, 2022 9:15:16 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 18, 2022 9:15:16 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 18, 2022 9:15:16 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 18, 2022 9:15:16 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Apr 18, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	9:15:16 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55529512
Invoice No. 55345 - 55529512

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 REAR BRAKE		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,502 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note: REAR BRAKES
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Apr-22	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	52.26	52.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-22	NELSON PIERRE-LOUIS	1.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	52.26
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.26**

Work Order Footer

Work Order 55529512 Total	
Parts:	52.26
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55401308
Invoice No. 55345 - 55401308

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,502 - DH

Chronology		
Reported	Apr 12, 2022 12:00:00 AM	Apr 12, 2022 12:00:00 AM
Started	Apr 14, 2022 4:31:00 PM	
Completed	Apr 15, 2022 2:39:00 PM	Apr 15, 2022 2:39:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE:preventive maintenance

CORRECTION:performed PMA Service and lube all Pivoting Points

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	2.5	0	0
15-Apr-22	NELSON PIERRE-LOUIS	-2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:36:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55401308
Invoice No. 55345 - 55401308

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 328,502 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	1.75	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Apr 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	2:31:15 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.5 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,250 - INSPECT_Overhead Compartment for Water	Done		NPIERRE-	Apr 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks			LOUIS	2:31:15 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4.5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4.5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		NPIERRE-	Apr 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism			LOUIS	2:31:15 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55401308
Invoice No. 55345 - 55401308

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,502 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Apr-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
101,000 - FRA Change Oil Filters	No		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
102,000 - FRA Drain Engine Oil	No		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:48 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.99
	Labor:	0.00
	Labor Hours:	0.75
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.99**

Work Order Footer

Work Order 55401308 Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55522740
Invoice No. 55345 - 55522740

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REAR AC INOPERATIVE		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,296 - DH

Chronology		
Reported	Apr 15, 2022 7:06:33 AM	Apr 15, 2022 7:06:33 AM
Started	Apr 15, 2022 7:11:00 AM	
Completed	Apr 15, 2022 9:10:00 AM	Apr 15, 2022 9:10:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT. per driver, rear ac inoperative

Cause. Defective thermostat control

Correction. Removed and replaced thermostat control with known used good part.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 15-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Apr 15, 2022 7:11:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Apr 15, 2022 7:11:53 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Apr 15, 2022 7:11:53 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Apr 15, 2022 7:11:53 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Apr 15, 2022 7:11:53 AM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Apr 15, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				7:11:53 AM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55522740
Invoice No. 55345 - 55522740

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REAR AC INOPERATIVE		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	328,296 - DH

Activity Header
Activity: 20 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC DIAG
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-22	Rodriguez,Raul	1.97	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55522740 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55512735
Invoice No. 55345 - 55512735

Client Department:
Department: 55345M
Work Order Description
Road Call noise coming out the front end
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 99 - Cancelled (99)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 327,722 - DH

Chronology		
Reported	Apr 12, 2022 8:06:00 AM	Apr 12, 2022 8:06:00 AM
Started	Apr 12, 2022 8:13:00 AM	
Completed	Apr 12, 2022 8:35:14 AM	Apr 12, 2022 8:35:14 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55512735
Invoice No. 55345 - 55512735

Client Department:
Department: 55345M
Work Order Description
Road Call noise coming out the front end
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 99 - Cancelled (99)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 327,722 - DH

Activity Header
Activity: 20 018/001/000 AXLE, HUBS & BEARINGS, FRONT
Activity Note: INSPECT FRONT END
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-22	Pierre,Hubert J	0.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55512735 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55498577
Invoice No. 55345 - 55498577

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Engine Light On		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	327,226 - DH

Chronology		
Reported	Apr 6, 2022 3:57:00 PM	Apr 6, 2022 3:57:00 PM
Started	Apr 6, 2022 3:58:00 PM	
Completed	Apr 6, 2022 11:19:00 PM	Apr 6, 2022 11:19:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light illuminated.

Cause: Cyl. 7 misfire (ignition coil).

Correction: Remove and replaced cyl 7 spark plug and igntion coil.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 06-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 6, 2022 6:49:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55498577
Invoice No. 55345 - 55498577

Client Department:
Department: 55345M
Work Order Description
Check Engine Light On
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 327,226 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check Engine Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Apr-22	AP103	PLUG, SPARK	1	3.5	3.5
06-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	65.89	65.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Apr-22	Earl Johnson	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	69.39
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.39**

Work Order Footer

Work Order 55498577 Total	
Parts:	69.39
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**69.39**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55493983
Invoice No. 55345 - 55493983

Client Department:
Department: 55345M
Work Order Description
PER PTC RANDOM INSPECTION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 327,226 - DH

Chronology		
Reported	Apr 5, 2022 12:00:00 PM	Apr 5, 2022 12:00:00 PM
Started	Apr 5, 2022 4:44:00 PM	
Completed	Apr 5, 2022 11:20:00 PM	Apr 5, 2022 11:20:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Check AC blower.

Cause: Debris lodged in blower wheel.

Correction: Remove front AC blower. Removed debris from blower wheel and inspected for damage. Reinstalled blower, works properly.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 05-APR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 5, 2022 8:59:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55493983
Invoice No. 55345 - 55493983

Client Department:
Department: 55345M
Work Order Description
PER PTC RANDOM INSPECTION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 327,226 - DH

Activity Header
Activity: 20 001/001/082 MOTOR, BLOWER
Activity Note: CHECK BLOWER MOTOR
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Apr-22	Earl Johnson	2.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55493983 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55482393
Invoice No. 55345 - 55482393

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check PTC Camera)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 326,921 - DH

Chronology		
Reported	Mar 31, 2022 5:37:00 PM	Mar 31, 2022 5:37:00 PM
Started	Mar 31, 2022 5:38:00 PM	
Completed	Mar 31, 2022 11:57:00 PM	Mar 31, 2022 11:57:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: Rear facing PT camera damaged.

Cause: Damaged during operation.

Correction: Remove and replaced rear facing camera with god used unit.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 31-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 31, 2022 8:22:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 31, 2022 8:22:33 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 31, 2022 8:22:33 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 31, 2022 8:22:33 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 31, 2022 8:22:33 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Mar 31, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				8:22:33 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55482393
Invoice No. 55345 - 55482393

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check PTC Camera)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 326,921 - DH

Activity Header
Activity: 20 036/008/002 CAMERA, SYSTEM, SURVEILLANCE
Activity Note: VERIFY COMPLAINT (Check PTC Drive Camera)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-22	Earl Johnson	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55482393 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55472645
Invoice No. 55345 - 55472645

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WC lift malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	326,578 - DH

Chronology		
Reported	Mar 28, 2022 7:18:57 PM	Mar 28, 2022 7:18:57 PM
Started	Mar 28, 2022 7:20:00 PM	
Completed	Mar 29, 2022 10:02:00 PM	Mar 29, 2022 10:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift creeps down from floor level.

Cause: Faulty WC lift tower cylinders seals.

Correction: Noted for repair. Line 20 Remove and replaced 2 WC lift tower cylinders. Refilled fluid back to spec and ran lift thru 5 consecutive cycles without any issues. WC lift no longer creeps down. Line 30 W/C LIFT CYLINDERS REPLACED WITH KNOWN GOOD USED PARTS.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:59:37 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 29, 2022 9:59:37 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 29, 2022 9:59:37 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 29, 2022 9:59:37 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 29, 2022 9:59:37 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 29, 2022 9:59:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55472645
Invoice No. 55345 - 55472645

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WC lift malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	326,578 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-22	Earl Johnson	0.73	0	0
29-Mar-22	Delva,Terry	1.95	0	0
29-Mar-22	Perez,Javier	0.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55472645
Invoice No. 55345 - 55472645

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 326,578 - DH

Activity Header
Activity: 25 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Remove and replace WC lift cylinders.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Mar-22	Earl Johnson	2.8	0	0
29-Mar-22	Earl Johnson	1.53	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55472645 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55465227
Invoice No. 55345 - 55465227

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WHEEL CHAIR INSPECTION		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	326,496 - DH

Chronology		
Reported	Mar 25, 2022 2:56:00 PM	Mar 25, 2022 2:56:00 PM
Started	Mar 27, 2022 1:12:00 PM	
Completed	Mar 27, 2022 7:02:00 PM	Mar 27, 2022 7:02:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: WC lift malfunction.

Cause: Outboard rollstop not closing properly.

Correction: Remove and replaced 1 rollstop gas spring.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 27-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 27, 2022 6:58:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 27, 2022 6:58:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 27, 2022 6:58:06 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 27, 2022 6:58:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 27, 2022 6:58:06 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Mar 27, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:58:06 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55465227
Invoice No. 55345 - 55465227

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WHEEL CHAIR INSPECTION		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	326,496 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: PER DRIVER THE LIFT IS NOT WORKING (INTERMITENTLY)
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Mar-22	32831	SPRING, SHOCK, GAS, W/C	1	27.26	27.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-22	Earl Johnson	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	27.26
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.26**

Work Order Footer

Work Order 55465227 Total	
Parts:	27.26
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55426804
Invoice No. 55345 - 55426804

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Repair Light Signal)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 324,554 - DH

Chronology		
Reported	Mar 11, 2022 6:11:00 PM	Mar 11, 2022 6:11:00 PM
Started	Mar 11, 2022 6:12:00 PM	
Completed	Mar 15, 2022 8:50:00 AM	Mar 15, 2022 8:50:00 AM
Down Time		

Work Order Notes

Line 10 vehicle came in for left signal lamp not working. check and found plug loose FIX THE PROBLEM AND RETURN VEHICLE BACK TO WORK NO PARTS REPLACE

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 15-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 15, 2022 8:49:34 AM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55426804
Invoice No. 55345 - 55426804

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Repair Light Signal)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 324,554 - DH

Activity Header
Activity: 20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: VERIFY COMPLAINT (Left Turn Signal)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Mar-22	Junior Hurst	1.33	0	0
11-Mar-22	Junior Hurst	0.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55426804 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55426103
Invoice No. 55345 - 55426103

Client Department:
Department: 55345M
Work Order Description
PER DRIVER SLIGHT SMELL OF GAS IN THE VEHICLE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 324,554 - DH

Chronology		
Reported	Mar 11, 2022 2:10:00 PM	Mar 11, 2022 2:10:00 PM
Started		
Completed	Mar 11, 2022 9:10:00 PM	Mar 11, 2022 9:10:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle came in for signal lamp

Cause: loose plug

Correction: correct the problem by repairing the plug after return vehicle back to work

Line 20 Complaint: Gas smell inside vehicle.

Cause: Suspect fuel overfill.

Correction: Visually inspected vehicle for fuel leaks, found none. Could not verify Complaint. Will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 11, 2022 9:09:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55426103
Invoice No. 55345 - 55426103

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PER DRIVER SLIGHT SMELL OF GAS IN THE VEHICLE		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	324,554 - DH

Activity Header
Activity: 15 044/001/011 LINE, FUEL
Activity Note: INSPECT FUEL SYSTEM FOR LEAKS
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55426103 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55398988
Invoice No. 55345 - 55398988

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wheelchair Lift		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	323,562 - DH

Chronology		
Reported	Mar 3, 2022 7:35:00 AM	Mar 3, 2022 7:35:00 AM
Started	Mar 3, 2022 7:40:00 AM	
Completed	Mar 7, 2022 1:50:00 PM	Mar 7, 2022 1:50:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT. per driver, lift going down by itself

cause. no problem found

correction. tested for about 1 hour, performed maintenance.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 7, 2022 1:47:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 7, 2022 1:47:26 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 7, 2022 1:47:26 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 7, 2022 1:47:26 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 7, 2022 1:47:26 PM	No	
11 - Have you successfully completed the	Done		RAURODRIGUEZ	Mar 7, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:47:26 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55398988
Invoice No. 55345 - 55398988

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 323,562 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Mar-22	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	184.89	184.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-22	Rodriguez,Raul	2.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	184.89
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.89**

Work Order Footer

Work Order 55398988 Total	
Parts:	184.89
Labor:	0.00
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**184.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55266379
Invoice No. 55345 - 55266379

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	323,562 - DH

Chronology		
Reported	Mar 1, 2022 12:00:00 AM	Mar 1, 2022 12:00:00 AM
Started	Mar 3, 2022 12:47:00 PM	
Completed	Mar 3, 2022 3:35:00 PM	Mar 3, 2022 3:35:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: vehicle came in for service

CAUSE: service by miles

CORRECTION: job complete change oil filter part # B329 change rear A / C filter no part # return vehicle back to work

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 3, 2022 3:33:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55266379
Invoice No. 55345 - 55266379

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	323,562 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-22	Junior Hurst	1.08	0	0
03-Mar-22	Junior Hurst	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 03-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Mar 3, 2022 3:34:25 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	21119 Cycles		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Mar 3, 2022 3:34:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55266379
Invoice No. 55345 - 55266379

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 323,562 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Mar-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-22	Junior Hurst	0.53	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 03-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Mar 3, 2022 3:29:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Mar 3, 2022 3:29:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Mar 3, 2022 3:29:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Mar 3, 2022 3:29:59 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Mar 3, 2022 3:29:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Mar 3, 2022 3:29:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Mar 3, 2022 3:29:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Mar 3, 2022 3:29:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.99
	Labor:	0.00
	Labor Hours:	0.53
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.99**

Work Order Footer

Work Order 55266379 Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	2.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55398260
Invoice No. 55345 - 55398260

Client Department:
Department: 55345M
Work Order Description
Check Wheel Chair Lift
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 323,367 - DH

Chronology		
Reported	Mar 2, 2022 6:44:00 PM	Mar 2, 2022 6:44:00 PM
Started	Mar 2, 2022 6:45:00 PM	
Completed	Mar 2, 2022 9:10:00 PM	Mar 2, 2022 9:10:00 PM
Down Time		

Work Order Notes

Line 10 driver complaint about lift issue
not working well
check lift i found it's going slowly down by itself.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 2, 2022 8:28:49 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55398260
Invoice No. 55345 - 55398260

Client Department:
Department: 55345M
Work Order Description
Check Wheel Chair Lift
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 323,367 - DH

Activity Header
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: VERIFY COMPLAINT (Check Wheel Chair Lift)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-22	Gaspard,Ronald	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55398260 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55323580
Invoice No. 55345 - 55323580

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Emergency Brake Goes to Floor)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 320,389 - DH

Chronology		
Reported	Feb 4, 2022 8:52:00 PM	Feb 4, 2022 8:52:00 PM
Started	Feb 4, 2022 8:53:00 PM	
Completed	Feb 4, 2022 10:23:00 PM	Feb 4, 2022 10:23:00 PM
Down Time		

Work Order Notes

Line 10 Remove Wheel To adjust Emergency Brakes E brake Pedal Was Low.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-FEB-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 4, 2022 9:01:27 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55323580
Invoice No. 55345 - 55323580

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Emergency Brake Goes to Floor)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 320,389 - DH

Activity Header
Activity:20 013/002/000 REAR BRAKES & DRUMS
Activity Note: VERIFY COMPLAINT (Emergency Brake Goes to Floor)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Feb-22	Arthurs,Durvin	1.38	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55323580 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55120849
Invoice No. 55345 - 55120849

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	318,797 - DH

Chronology		
Reported	Jan 10, 2022 12:00:00 AM	Jan 10, 2022 12:00:00 AM
Started	Jan 17, 2022 1:01:00 PM	
Completed	Jan 17, 2022 4:01:00 PM	Jan 17, 2022 4:01:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: service by miles

CORRECTION: job cmplete new oil filter replace part # B329 aiso replace two wiper blade Part # 40520
Replace rear A/C filter road test unit working asdesign. Unit back to work

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-22	Junior Hurst	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 17-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 17, 2022 1:03:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55120849
Invoice No. 55345 - 55120849

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 318,797 - DH

Activity Header
Activity: 10 011RTD SUSPENSION
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jan-22	40520	BLADE, WIPER, WINDSHIELD, 20"	1	4.4	4.4
17-Jan-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99
19-Jan-22	40520	BLADE, WIPER, WINDSHIELD, 20"	1	4.4	4.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-22	Junior Hurst	0.68	0	0
17-Jan-22	Junior Hurst	1.82	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 17-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Jan 17, 2022 2:52:21 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.16 Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.16 Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.18 Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.18 Inch		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	20886 Cycles		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jan 17, 2022 2:52:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	10.79
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55120849
Invoice No. 55345 - 55120849

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	318,797 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jan-22	Junior Hurst	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: JUHURST Performed on: 17-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jan 17, 2022 3:19:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jan 17, 2022 3:19:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Jan 17, 2022 3:19:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	
201,000 - Service Crankcase Breather	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		JUHURST	Jan 17, 2022 3:19:20 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		JUHURST	Jan 17, 2022 3:19:20 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Jan 17, 2022 3:19:20 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55120849 Total	
Parts:	10.79
Labor:	0.00
Labor Hours:	2.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54887282
Invoice No. 55345 - 54887282

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	313,973 - DH

Chronology		
Reported	Nov 23, 2021 12:00:00 AM	Nov 23, 2021 12:00:00 AM
Started	Nov 24, 2021 7:38:00 AM	
Completed	Nov 24, 2021 1:48:00 PM	Nov 24, 2021 1:48:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 24-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 24, 2021 1:39:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 24, 2021 1:39:41 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 24, 2021 1:39:41 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 24, 2021 1:39:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 24, 2021 1:39:41 PM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Nov 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:39:41 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54887282
Invoice No. 55345 - 54887282

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 313,973 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Nov-21	NELSON PIERRE-LOUIS	3.42	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 24-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Nov 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:47:22 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.2 Volt*		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.1 Volt*		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Nov 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	1:47:22 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	69 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	29.5 Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	29.5 Inch		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Nov 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	1:47:22 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Nov 24, 2021 1:47:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54887282
Invoice No. 55345 - 54887282

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 313,973 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Nov-21	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 24-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Nov 24, 2021 1:40:10 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	1.99
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.99**

Work Order Footer

Work Order 54887282 Total	
Parts:	1.99
Labor:	0.00
Labor Hours:	3.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55086007
Invoice No. 55345 - 55086007

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front Brakes noise		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	313,160 - DH

Chronology		
Reported	Nov 12, 2021 7:38:51 PM	Nov 12, 2021 7:38:51 PM
Started	Nov 12, 2021 7:41:00 PM	
Completed	Nov 12, 2021 9:01:00 PM	Nov 12, 2021 9:01:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Brake noise.

Cause: Front Pad Low & Front Rotor Glaze.

Correction:Remove &Replace Front Pads& scuff Both Rotor.
Parts # 8C2Z-2V001-D Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 12, 2021 8:57:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55086007
Invoice No. 55345 - 55086007

Client Department:
Department: 55345M
Work Order Description
Front Brakes noise
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 313,160 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Front Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Nov-21	ES801219	TIE-ROD, OUTER, FORD	2	14.86	29.72
12-Nov-21	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	51.88	51.88
16-Nov-21	EV801332	TIE-ROD, INNER, FORD	2	26.1	52.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-21	Arthurs,Durvin	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	133.80
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.80**

Work Order Footer

Work Order 55086007 Total	
Parts:	133.80
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55056414
Invoice No. 55345 - 55056414

Client Department:
Department: 55345M
Work Order Description
CHECK ENGINE LIGHT FLASHING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 312,223 - DH

Chronology		
Reported	Nov 3, 2021 10:49:00 AM	Nov 3, 2021 10:49:00 AM
Started	Nov 3, 2021 11:35:00 AM	
Completed	Nov 3, 2021 3:30:00 PM	Nov 3, 2021 3:30:00 PM
Down Time		

Work Order Notes

Line 10 C: Check engine light on

C: Check computer system found code for engine misfire on cylinder 1

C: replaced ignition coil retest and road test vehicle ok at this time

Part:
1 new ignition coil 26326

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 03-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Nov 3, 2021 2:23:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55056414
Invoice No. 55345 - 55056414

Client Department:
Department: 55345M
Work Order Description
CHECK ENGINE LIGHT FLASHING
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 312,223 - DH

Activity Header
Activity: 20 033 IGNITION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Nov-21	26326	PLUG, COIL, IGNITION	1	29.72	29.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Nov-21	Perez,Javier	3.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	29.72
Labor:	0.00
Labor Hours:	3.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.72**

Work Order Footer

Work Order 55056414 Total	
Parts:	29.72
Labor:	0.00
Labor Hours:	3.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**29.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54931396
Invoice No. 55345 - 54931396

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replace Leaking Drain Plug		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,702 - DH

Chronology		
Reported	Sep 24, 2021 5:39:00 PM	Sep 24, 2021 5:39:00 PM
Started		
Completed	Oct 19, 2021 12:22:33 PM	Oct 19, 2021 12:22:33 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 24-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Sep 24, 2021 6:21:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		AOWENS	Sep 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				6:21:04 PM		
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Sep 24, 2021 6:21:04 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Sep 24, 2021 6:21:04 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Sep 24, 2021 6:21:04 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Sep 24, 2021 6:21:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54931396
Invoice No. 55345 - 54931396

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replace Leaking Drain Plug		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,702 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Drain Plug
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54931396 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54920128
Invoice No. 55345 - 54920128

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle towing for repair		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,513 - DH

Chronology		
Reported	Sep 21, 2021 3:11:58 PM	Sep 21, 2021 3:11:58 PM
Started	Sep 21, 2021 3:19:00 PM	
Completed	Sep 21, 2021 8:02:00 PM	Sep 21, 2021 8:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle leaking coolant

Cause: Broken radiator

Correction: Removed and replaced new radiator part # G1000382282CSF After five gallons of Coolant to unit part # FXAB51 return Vehicle to work after please charge out the part for me can¿t fine

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 21, 2021 8:01:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54920128
Invoice No. 55345 - 54920128

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle towing for repair		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	310,513 - DH

Activity Header
Activity: 15 020 GROUP, DRIVETRAIN
Activity Note: Vehicle towing for repair
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-21	G1000382282CSF	RADIATOR, E450	1	205.18	205.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Sep-21	Junior Hurst	4.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	205.18
Labor:	0.00
Labor Hours:	4.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**205.18**

Work Order Footer

Work Order 54920128 Total	
Parts:	205.18
Labor:	0.00
Labor Hours:	4.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**205.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54887280
Invoice No. 55345 - 54887280

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	309,490 - DH

Chronology		
Reported	Sep 10, 2021 12:45:40 PM	Sep 10, 2021 12:45:40 PM
Started	Sep 10, 2021 12:00:00 AM	
Completed	Sep 10, 2021 12:49:00 PM	Sep 10, 2021 12:49:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54887280
Invoice No. 55345 - 54887280

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	309,490 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Sep-21	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	50.03	50.03

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-21	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.03
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.03**

Work Order Footer

Work Order 54887280 Total	
Parts:	50.03
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54785064
Invoice No. 55345 - 54785064

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	309,490 - DH

Chronology		
Reported	Sep 9, 2021 12:00:00 AM	Sep 9, 2021 12:00:00 AM
Started		
Completed	Sep 10, 2021 12:46:00 PM	Sep 10, 2021 12:46:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 10-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Sep 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	12:35:18 PM		
20 - Miles			NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	
40 - Hours			NPIERRE-LOUIS	Sep 10, 2021 12:35:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54785064
Invoice No. 55345 - 54785064

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	309,490 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 10-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-	Sep 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:45:51 PM		
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.2 Volt*		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.1 Volt*		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		NPIERRE-	Sep 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038			LOUIS	12:45:51 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	Yes	54887280
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Sep 10, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	12:45:51 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Sep 10, 2021 12:45:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54785064
Invoice No. 55345 - 54785064

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 309,490 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Sep-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 10-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Sep 10, 2021 12:34:47 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 3.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.96**

Work Order Footer

Work Order 54785064 Total	
Parts:	3.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54877710
Invoice No. 55345 - 54877710

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
RFtire low.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	308,851 - DH

Chronology		
Reported	Sep 7, 2021 8:28:26 PM	Sep 7, 2021 8:28:26 PM
Started	Sep 7, 2021 8:29:00 PM	
Completed	Sep 7, 2021 11:38:00 PM	Sep 7, 2021 11:38:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: RF tire pressure low.

Cause: Tire Punctured.

Correction: Remove and replaced RF tire.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 07-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Sep 7, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				10:00:12 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
20 - Miles			EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
30 - Kilometers			EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	
40 - Hours			EARJOHNSON	Sep 7, 2021 10:00:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54877710
Invoice No. 55345 - 54877710

Client Department:
Department: 55345M
Work Order Description
RFtire low.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 308,851 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: RF tire low.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Sep-21	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	128.26	128.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Sep-21	Earl Johnson	1.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	128.26
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.26**

Work Order Footer

Work Order 54877710 Total	
Parts:	128.26
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54860389
Invoice No. 55345 - 54860389

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WC lift malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	307,938 - DH

Chronology		
Reported	Aug 31, 2021 11:32:34 PM	Aug 31, 2021 11:32:34 PM
Started	Sep 1, 2021 12:00:00 AM	
Completed	Sep 1, 2021 12:25:00 AM	Sep 1, 2021 12:25:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction.

Cause: Joints binding.

Correction: Lubricated all pivot points and ran thru 5 consecutive cycles without any issues.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Sep 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:04:47 AM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
20 - Miles			EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
30 - Kilometers			EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	
40 - Hours			EARJOHNSON	Sep 1, 2021 12:04:47 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54860389
Invoice No. 55345 - 54860389

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 307,938 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-21	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	-1	104.55	-104.55
14-Sep-21	9C2Z-1520125-B	DOOR, FRONT, LH, E450	1	402.38	402.38
14-Sep-21	004708	TIRE, 195/75R16C, BSW, D/8-PLY, CV, TRANSFORCE, FIRESTONE	1	104.55	104.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Sep-21	Earl Johnson	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	402.38
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**402.38**

Work Order Footer

Work Order 54860389 Total	
Parts:	402.38
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**402.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54666818
Invoice No. 55345 - 54666818

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	305,020 - DH

Chronology		
Reported	Aug 4, 2021 12:00:00 AM	Aug 4, 2021 12:00:00 AM
Started	Aug 4, 2021 7:29:00 PM	
Completed	Aug 5, 2021 12:15:00 AM	Aug 5, 2021 12:15:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC Service
Oil filter B329 qty1
Engine oil 10w30 qty 7qts
Air filter PA4075 qty1
Fixed washer fluid hose

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 4, 2021 7:29:18 PM	No	
20 - Miles			RGASPARD	Aug 4, 2021 7:29:18 PM	No	
30 - Kilometers			RGASPARD	Aug 4, 2021 7:29:18 PM	No	
40 - Hours			RGASPARD	Aug 4, 2021 7:29:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54666818
Invoice No. 55345 - 54666818

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	305,020 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-21	Gaspard,Ronald	0.65	0	0
04-Aug-21	Gaspard,Ronald	1.48	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 04-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Aug 4, 2021 9:56:56 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Aug 4, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:56:56 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,400 - LUBE_All Chassis Components	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19796 Cycles		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Aug 4, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				9:56:56 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Aug 4, 2021 9:56:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54666818
Invoice No. 55345 - 54666818

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 305,020 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98
04-Aug-21	PA4075	FILTER, AIR SEE P546597	1	5.32	5.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-21	Gaspard,Ronald	0.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 04-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 4, 2021 10:26:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Aug 4, 2021 10:26:26 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Aug 4, 2021 10:26:26 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Aug 4, 2021 10:26:26 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Aug 4, 2021 10:26:26 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Aug 4, 2021 10:26:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order Footer

Work Order 54666818 Total	
Parts:	7.30
Labor:	0.00
Labor Hours:	2.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54751715
Invoice No. 55345 - 54751715

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear A/C Not Blowing		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,681 - DH

Chronology		
Reported	Jul 22, 2021 9:04:00 PM	Jul 22, 2021 9:04:00 PM
Started	Jul 22, 2021 9:26:00 PM	
Completed	Jul 22, 2021 11:17:00 PM	Jul 22, 2021 11:17:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Blower Motor.

Cause: Bad Blower Motor.

Correction: Remove&Replace Rear Blower Motor & Replace Rear A/C Vent.
Parts #1456500C Qty (1)
Parts #8010002 Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:16:58 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 22, 2021 11:16:58 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 22, 2021 11:16:58 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 22, 2021 11:16:58 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 22, 2021 11:16:58 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 22, 2021 11:16:58 PM	No	
20 - Miles			DARTHURS	Jul 22, 2021 11:16:58 PM	No	
30 - Kilometers			DARTHURS	Jul 22, 2021 11:16:58 PM	No	
40 - Hours			DARTHURS	Jul 22, 2021 11:16:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54751715
Invoice No. 55345 - 54751715

Client Department:
Department: 55345M
Work Order Description
Rear A/C Not Blowing
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 303,681 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Not Blowing
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-21	8010002	MOTOR, BLOWER, HVAC SAME AS BLW-206P	1	117.25	117.25
22-Jul-21	14565100C	COVER, LOUVER, EVAPORATOR, A/C	1	15.38	15.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-21	Arthurs,Durvin	1.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	132.63
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**132.63**

Work Order Footer

Work Order 54751715 Total	
Parts:	132.63
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**132.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54745556
Invoice No. 55345 - 54745556

Client Department:
Department: 55345M
Work Order Description
Engine light is on
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 303,681 - DH

Chronology		
Reported	Jul 21, 2021 8:21:38 AM	Jul 21, 2021 8:21:38 AM
Started	Jul 21, 2021 8:26:00 AM	
Completed	Jul 21, 2021 1:21:00 PM	Jul 21, 2021 1:21:00 PM
Down Time		

Work Order Notes

Line 10 Engine light is on

Bad fuel pump

Replace fuel pump completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-21	AC2Z-9H307-D	PUMP, FUEL, E350	1	248	248

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-21	Pierre,Hubert J	4.88	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 21-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
20 - Miles			HPIERRE	Jul 21, 2021 11:21:13 AM	No	
30 - Kilometers	2		HPIERRE	Jul 21, 2021 11:21:13 AM	No	
40 - Hours	2		HPIERRE	Jul 21, 2021 11:21:13 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	248.00
Labor:	0.00
Labor Hours:	4.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**248.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54745556
Invoice No. 55345 - 54745556

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Engine light is on		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,681 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: D PM Level D
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54745556 Total	
Parts:	248.00
Labor:	0.00
Labor Hours:	4.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**248.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54729758
Invoice No. 55345 - 54729758

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle vibration.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	303,059 - DH

Chronology		
Reported	Jul 14, 2021 7:13:04 PM	Jul 14, 2021 7:13:04 PM
Started	Jul 14, 2021 7:14:00 PM	
Completed	Jul 14, 2021 9:05:00 PM	Jul 14, 2021 9:05:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle vibration.

Cause: Worn transmission mount.

Correction: Remove and replaced transmission mount.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jul 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				8:59:29 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
20 - Miles			EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
30 - Kilometers			EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	
40 - Hours			EARJOHNSON	Jul 14, 2021 8:59:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54729758
Invoice No. 55345 - 54729758

Client Department:
Department: 55345M
Work Order Description
Vehicle vibration.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 303,059 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Vehicle vibrating.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-21	F81Z-6068-DA	MOUNT, TRANSMISSION, E450	1	15.12	15.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-21	Earl Johnson	1.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	15.12
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.12**

Work Order Footer

Work Order 54729758 Total	
Parts:	15.12
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54669425
Invoice No. 55345 - 54669425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wiper blade		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,754 - DH

Chronology		
Reported	Jun 21, 2021 7:38:16 PM	Jun 21, 2021 7:38:16 PM
Started	Jun 21, 2021 7:45:00 PM	
Completed	Jun 21, 2021 8:30:00 PM	Jun 21, 2021 8:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for wiper issue

Cause: one broken and out of place

Correction: removed and replaced properly whit blade part # 40520 after check unit complete and return back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jun 21, 2021 7:58:34 PM	No	
20 - Miles			JUHURST	Jun 21, 2021 7:58:34 PM	No	
30 - Kilometers			JUHURST	Jun 21, 2021 7:58:34 PM	No	
40 - Hours			JUHURST	Jun 21, 2021 7:58:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54669425
Invoice No. 55345 - 54669425

Client Department:
Department: 55345M
Work Order Description
Wiper blade
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 300,754 - DH

Activity Header
Activity: 15 R053 Safety Equipment
Activity Note: Wiperblade
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-21	40520	BLADE, WIPER, WINDSHIELD, 20"	1	4.4	4.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-21	Junior Hurst	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	4.40
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.40**

Work Order Footer

Work Order 54669425 Total	
Parts:	4.40
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546685
Invoice No. 55345 - 54546685

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 296,229 - DH

Chronology		
Reported	May 11, 2021 2:28:02 PM	May 11, 2021 2:28:02 PM
Started		
Completed	Jun 21, 2021 4:28:00 PM	Jun 21, 2021 4:28:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 21, 2021 4:26:44 PM	No	
20 - Miles			AOWENS	Jun 21, 2021 4:26:44 PM	No	
30 - Kilometers			AOWENS	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:26:44 PM		
40 - Hours			AOWENS	Jun 21, 2021 4:26:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546685
Invoice No. 55345 - 54546685

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 296,229 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: AOWENS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:	FTTG		AOWENS	Jun 21, 2021 4:27:29 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546685 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558203
Invoice No. 55345 - 53558203

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-A/C INSPECTION		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,754 -

Chronology		
Reported	Jun 18, 2021 11:19:35 AM	Jun 18, 2021 11:19:35 AM
Started	Jun 21, 2021 12:00:00 AM	
Completed	Jun 21, 2021 12:03:00 PM	Jun 21, 2021 12:03:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: A/C inspection

Cause: preventive maintenance

Correction: Front and rear A/C inspection was completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:58:24 AM		
20 - Miles			NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 21, 2021 11:58:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558203
Invoice No. 55345 - 53558203

Client Department:
Department: 55345M
Work Order Description
55345-A/C INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 300,754 -

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: ANNUAL A/C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-21	NELSON PIERRE-LOUIS	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558203 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557845
Invoice No. 55345 - 53557845

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-PTC INSPECTION		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,754 -

Chronology		
Reported	Jun 18, 2021 11:19:36 AM	Jun 18, 2021 11:19:36 AM
Started	Jun 21, 2021 12:00:00 AM	
Completed	Jun 21, 2021 11:56:00 AM	Jun 21, 2021 11:56:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PTC inspection

Cause: preventive maintenance

Correction: perform PTC inspection check for safety all over the vehicle

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:54:07 AM		
20 - Miles			NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 21, 2021 11:54:07 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557845
Invoice No. 55345 - 53557845

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-PTC INSPECTION		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,754 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: PTC INSPECTION
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-21	NELSON PIERRE-LOUIS	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557845 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54557747
Invoice No. 55345 - 54557747

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	300,754 - DH

Chronology		
Reported	Jun 18, 2021 11:19:35 AM	Jun 18, 2021 11:19:35 AM
Started	Jun 21, 2021 7:54:00 AM	
Completed	Jun 21, 2021 11:52:00 AM	Jun 21, 2021 11:52:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	10:56:31 AM		
20 - Miles			NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 21, 2021 10:56:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54557747
Invoice No. 55345 - 54557747

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 300,754 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-21	NELSON PIERRE-LOUIS	3.97	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:56:03 AM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.3 Volt*		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.2 Volt*		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	10:56:03 AM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Jun 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	10:56:03 AM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Jun 21, 2021 10:56:03 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54557747
Invoice No. 55345 - 54557747

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 300,754 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 21-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jun 21, 2021 10:57:09 AM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.98

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.98**

Work Order Footer

Work Order 54557747 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	3.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558019
Invoice No. 55345 - 53558019

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 300,615 -

Chronology		
Reported	Jun 18, 2021 11:19:35 AM	Jun 18, 2021 11:19:35 AM
Started		
Completed	Jun 20, 2021 3:56:00 PM	Jun 20, 2021 3:56:00 PM
Down Time		

Work Order Notes

Line 10 Performed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 20, 2021 3:16:06 PM	No	
20 - Miles			TDELVA	Jun 20, 2021 3:16:06 PM	No	
30 - Kilometers			TDELVA	Jun 20, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:16:06 PM		
40 - Hours			TDELVA	Jun 20, 2021 3:16:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558019
Invoice No. 55345 - 53558019

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 300,615 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: ANNUAL FIRE SAFETY INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558019 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54569209
Invoice No. 55345 - 54569209

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wipers not working.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	296,647 - DH

Chronology		
Reported	May 16, 2021 6:45:07 PM	May 16, 2021 6:45:07 PM
Started	May 16, 2021 6:46:00 PM	
Completed	May 16, 2021 9:18:00 PM	May 16, 2021 9:18:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Wipers not working.

Cause: Wiper linkage Damaged.

Correction: Remove and replaced wiper linkage. Line 20 Part#: 1C2Z-17566-AA Qty.(1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-May-21	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:17:07 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 16, 2021 9:17:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 16, 2021 9:17:07 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 16, 2021 9:17:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 16, 2021 9:17:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 16, 2021 9:17:07 PM	No	
20 - Miles			EARJOHNSON	May 16, 2021 9:17:07 PM	No	
30 - Kilometers			EARJOHNSON	May 16, 2021 9:17:07 PM	No	
40 - Hours			EARJOHNSON	May 16, 2021 9:17:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54569209
Invoice No. 55345 - 54569209

Client Department:
Department: 55345M
Work Order Description
Wipers not working.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 296,647 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Wipers not working.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-May-21	1C2Z-17566-AA	LINKAGE, WIPER, WINDSHIELD	1	31.29	31.29

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-May-21	Earl Johnson	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	31.29
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.29**

Work Order Footer

Work Order 54569209 Total	
Parts:	31.29
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**31.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54433352
Invoice No. 55345 - 54433352

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	296,372 - DH

Chronology		
Reported	May 11, 2021 11:45:56 AM	May 11, 2021 11:45:56 AM
Started	May 11, 2021 3:45:00 PM	
Completed	May 12, 2021 9:36:24 AM	May 12, 2021 9:36:24 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: Service

CORRECTION: perform PmA Service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 11, 2021 8:01:07 PM	No	
20 - Miles			RGASPARD	May 11, 2021 8:01:07 PM	No	
30 - Kilometers			RGASPARD	May 11, 2021 8:01:07 PM	No	
40 - Hours			RGASPARD	May 11, 2021 8:01:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54433352
Invoice No. 55345 - 54433352

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 296,372 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-21	Gaspard,Ronald	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 11-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	May 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:03:06 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	May 11, 2021 9:03:06 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	May 11, 2021 9:03:06 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	May 11, 2021 9:03:06 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	May 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:03:06 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	May 11, 2021 9:03:06 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	17543 Cycles		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	May 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				9:03:06 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	May 11, 2021 9:03:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54433352
Invoice No. 55345 - 54433352

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 296,372 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-May-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-21	Gaspard,Ronald	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 11-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 11, 2021 9:27:48 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 11, 2021 9:27:48 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 11, 2021 9:27:48 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 11, 2021 9:27:48 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 11, 2021 9:27:48 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 11, 2021 9:27:48 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 11, 2021 9:27:48 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 11, 2021 9:27:48 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order Footer

Work Order 54433352 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	1.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54479104
Invoice No. 55345 - 54479104

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear A/C Circuit Board		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	293,725 - DH

Chronology		
Reported	Apr 18, 2021 7:15:22 PM	Apr 18, 2021 7:15:22 PM
Started	Apr 18, 2021 7:41:00 PM	
Completed	Apr 18, 2021 8:30:00 PM	Apr 18, 2021 8:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Condenser Fan Stay On when ignition off

Cause: Bad rear circuit board.

Correction: Remove & Replace Rear circuit board.
Parts #04278801A Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 18, 2021 7:42:07 PM	No	
20 - Miles			DARTHURS	Apr 18, 2021 7:42:07 PM	No	
30 - Kilometers			DARTHURS	Apr 18, 2021 7:42:07 PM	No	
40 - Hours			DARTHURS	Apr 18, 2021 7:42:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54479104
Invoice No. 55345 - 54479104

Client Department:
Department: 55345M
Work Order Description
Rear A/C Circuit Board
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,725 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Rear A/C Circuit Board
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Apr-21	04278801A	BOARD, RELAY, A/C	1	153.43	153.43

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-21	Arthurs,Durvin	0.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	153.43
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**153.43**

Work Order Footer

Work Order 54479104 Total	
Parts:	153.43
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**153.43**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54477964
Invoice No. 55345 - 54477964

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear Condenser fan Stays On		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	293,725 - DH

Chronology		
Reported	Apr 18, 2021 1:29:56 PM	Apr 18, 2021 1:29:56 PM
Started	Apr 18, 2021 1:32:00 PM	
Completed	Apr 18, 2021 7:15:00 PM	Apr 18, 2021 7:15:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Condenser Fan Stays On / Rear Blower Motor. High Pressure Service port leaking

Cause: High Pressure Service Valve Bad / Right Side Rear Blower Motor Bad/ Rear Condenser Fan relay stuck.

Correction: Evacuate Freon from Rear A/ C Replace Service Valve . Recharge found Compressor no Suction.Evacuate & Remove& Replace Compressor. Replace Orifice tube / Replace Rear Blower Motor. Replace Driver Sun Visor.
Parts #3411885 Qty (1)
Parts #8025005 Qty (1)
Parts #8010002 Qty (1)
Freon Qty (6.5) Lbs
Oil Charge (12) Ozs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 18, 2021 1:32:45 PM	No	
20 - Miles			DARTHURS	Apr 18, 2021 1:32:45 PM	No	
30 - Kilometers			DARTHURS	Apr 18, 2021 1:32:45 PM	No	
40 - Hours			DARTHURS	Apr 18, 2021 1:32:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54477964
Invoice No. 55345 - 54477964

Client Department:
Department: 55345M
Work Order Description
Rear Condenser fan Stays On
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,725 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear A/C Condenser fan stays on.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Apr-21	3411885	TUBE, ORIFICE, A/C, FORD	1	0.74	0.74
18-Apr-21	8025005	COMPRESSOR, A/C, TM21	1	279.73	279.73
18-Apr-21	8010002	MOTOR, BLOWER, HVAC SAME AS BLW-206P	1	117.25	117.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-21	Arthurs,Durvin	5.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	397.72
Labor:	0.00
Labor Hours:	5.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**397.72**

Work Order Footer

Work Order 54477964 Total	
Parts:	397.72
Labor:	0.00
Labor Hours:	5.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**397.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54469819
Invoice No. 55345 - 54469819

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light illuminated.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	293,388 - DH

Chronology		
Reported	Apr 14, 2021 7:05:38 PM	Apr 14, 2021 7:05:38 PM
Started		
Completed	Apr 15, 2021 12:12:00 AM	Apr 15, 2021 12:12:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check engine light Illuminated.

Cause: Cyl 5 Misfire.

Correction: Remove and replaced Cyl 5 ignition coil and spark plug.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Apr 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				8:35:35 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
20 - Miles			EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
30 - Kilometers			EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	
40 - Hours			EARJOHNSON	Apr 14, 2021 8:35:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54469819
Invoice No. 55345 - 54469819

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 293,388 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Apr-21	AP103	PLUG, SPARK	1	3.35	3.35
14-Apr-21	26326	PLUG, COIL, IGNITION	1	28.89	28.89

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	32.24
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.24**

Work Order Footer

Work Order 54469819 Total	
Parts:	32.24
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54312892
Invoice No. 55345 - 54312892

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,093 - DH

Chronology		
Reported	Apr 1, 2021 12:00:00 AM	Apr 1, 2021 12:00:00 AM
Started	Apr 1, 2021 7:40:00 PM	
Completed	Apr 2, 2021 12:13:00 AM	Apr 2, 2021 12:13:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE: Service

CORRECTION: perform pmB Service
Oil filter B329 Qty1
Engine oil 10w30 qty 7 qts
Drain plug oil 65266 Qty1
Fixed rear AC high side hose ;leaking from the valve .charge System to spec

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 1, 2021 7:40:33 PM	No	
20 - Miles			RGASPARD	Apr 1, 2021 7:40:33 PM	No	
30 - Kilometers			RGASPARD	Apr 1, 2021 7:40:33 PM	No	
40 - Hours			RGASPARD	Apr 1, 2021 7:40:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54312892
Invoice No. 55345 - 54312892

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	292,093 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Gaspard,Ronald	2.18	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:15:18 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.24 Volt*		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Apr 1, 2021 9:15:18 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:15:18 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	13645 Cycles		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				9:15:18 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Apr 1, 2021 9:15:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54312892
Invoice No. 55345 - 54312892

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 292,093 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Apr-21	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Gaspard,Ronald	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Apr 1, 2021 9:52:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Apr 1, 2021 9:52:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Apr 1, 2021 9:52:52 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Apr 1, 2021 9:52:52 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order Footer

Work Order 54312892 Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	2.66
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54403500
Invoice No. 55345 - 54403500

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Lift not working		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	290,952 - DH

Chronology

Reported	Mar 23, 2021 7:01:42 AM	Mar 23, 2021 7:01:42 AM
Started	Mar 23, 2021 7:04:00 AM	
Completed	Mar 23, 2021 10:13:00 AM	Mar 23, 2021 10:13:00 AM
Down Time		

Work Order Notes

Line 10 Need comments and/or Parts

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 23, 2021 10:11:06 AM	No	
20 - Miles			HPIERRE	Mar 23, 2021 10:11:06 AM	No	
30 - Kilometers	1		HPIERRE	Mar 23, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:11:06 AM		
40 - Hours	2		HPIERRE	Mar 23, 2021 10:11:06 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54403500
Invoice No. 55345 - 54403500

Client Department:
Department: 55345M
Work Order Description
Lift not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 290,952 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-21	Pierre,Hubert J	3.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54403500 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54341593
Invoice No. 55345 - 54341593

Client Department:
Department: 55345M
Work Order Description
PER DRIVER BUS HESITATES UNDER ACELERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 288,808 - DH

Chronology		
Reported	Mar 2, 2021 7:08:00 AM	Mar 2, 2021 7:08:00 AM
Started	Mar 2, 2021 8:37:00 AM	
Completed	Mar 2, 2021 11:25:00 AM	Mar 2, 2021 11:25:00 AM
Down Time		

Work Order Notes

Line 10 Driver complained

Bad fuel pump

Replaced fuel pump text drive bus completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 02-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Mar 2, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				11:23:23 AM		
20 - Miles			HPIERRE	Mar 2, 2021 11:23:23 AM	No	
30 - Kilometers	2		HPIERRE	Mar 2, 2021 11:23:23 AM	No	
40 - Hours	6		HPIERRE	Mar 2, 2021 11:23:23 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54341593
Invoice No. 55345 - 54341593

Client Department:
Department: 55345M
Work Order Description
PER DRIVER BUS HESITATES UNDER ACELERATION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 288,808 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-21	Pierre,Hubert J	2.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54341593 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54328363
Invoice No. 55345 - 54328363

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Lights		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,297 - DH

Chronology		
Reported	Feb 25, 2021 7:30:04 AM	Feb 25, 2021 7:30:04 AM
Started	Feb 25, 2021 7:31:00 AM	
Completed	Feb 25, 2021 8:49:00 AM	Feb 25, 2021 8:49:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: tag light out

Cause: preventive maintenance

Correction: replaced tag light

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Feb 25, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	8:44:25 AM		
20 - Miles			NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	
40 - Hours			NPIERRE-LOUIS	Feb 25, 2021 8:44:25 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54328363
Invoice No. 55345 - 54328363

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Lights		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	288,297 - DH

Activity Header
Activity: 20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Tag light
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-21	3975927	LAMP, PLATE, LICENSE	1	11.96	11.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-21	NELSON PIERRE-LOUIS	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	11.96
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.96**

Work Order Footer

Work Order 54328363 Total	
Parts:	11.96
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54312876
Invoice No. 55345 - 54312876

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,823 - DH

Chronology		
Reported	Feb 19, 2021 12:20:05 PM	Feb 19, 2021 12:20:05 PM
Started	Feb 19, 2021 12:22:00 PM	
Completed	Feb 19, 2021 1:38:00 PM	Feb 19, 2021 1:38:00 PM
Down Time		

Work Order Notes

Line 10 PMA follow up need rear brakes pads

Preventive maintenance

Replaced rear brakes pads completed

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Feb-21	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	37.06	37.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Feb-21	Pierre,Hubert J	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	37.06
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.06**

Work Order Footer

Work Order 54312876 Total	
Parts:	37.06

	Labor:	0.00
	Labor Hours:	1.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**37.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54198859
Invoice No. 55345 - 54198859

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,823 - DH

Chronology		
Reported	Feb 19, 2021 7:22:43 AM	Feb 19, 2021 7:22:43 AM
Started	Feb 19, 2021 7:41:00 AM	
Completed	Feb 19, 2021 12:22:00 PM	Feb 19, 2021 12:22:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: Performed service lube all pivoting point cross tires completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Feb 19, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				12:04:56 PM		
20 - Miles			HPIERRE	Feb 19, 2021 12:04:56 PM	No	
30 - Kilometers	12		HPIERRE	Feb 19, 2021 12:04:56 PM	No	
40 - Hours	4		HPIERRE	Feb 19, 2021 12:04:56 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54198859
Invoice No. 55345 - 54198859

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 287,823 - DH

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Feb-21	Pierre,Hubert J	4.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 19-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Feb 19, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:20:03 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,000 - Engine Inspection	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit	N/A	HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		HPIERRE	Feb 19, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				12:20:03 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.6 Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.6 Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	3 32nds of an inch		HPIERRE	Feb 19, 2021 12:20:03 PM	Yes	54312876
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	22331 Cycles		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		HPIERRE	Feb 19, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				12:20:03 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Feb 19, 2021 12:20:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54198859
Invoice No. 55345 - 54198859

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	287,823 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Feb-21	P7398	FILTER, OIL	1	1.41	1.41

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 19-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 19, 2021 12:05:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 19, 2021 12:05:46 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 19, 2021 12:05:46 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.41
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.41**

Work Order Footer

Work Order 54198859 Total	
Parts:	1.41
Labor:	0.00
Labor Hours:	4.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 54198843
Invoice No. 55345 - 54198843

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Chronology		
Reported	Jan 11, 2021 8:04:00 PM	Jan 11, 2021 8:04:00 PM
Started	Jan 11, 2021 8:18:00 PM	
Completed	Jan 11, 2021 10:35:00 PM	Jan 11, 2021 10:35:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: 2 front clearance lights out.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jan-21	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.57	235.14
11-Jan-21	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	1	9.49	9.49
11-Jan-21	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	43.07	43.07
11-Jan-21	3974688	LAMP, LED, AMBER	2	8.8	17.6
11-Jan-21	141096	BRACKET, CALIPER, BRAKE, DISC, FRONT, LH, FORD	1	34.44	34.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	339.74
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**339.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 54198843
Invoice No. 55345 - 54198843

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity:20 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: Near out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	1.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 54198843
Invoice No. 55345 - 54198843

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity: 30 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: Near out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 54198843
Invoice No. 55345 - 54198843

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity: 40 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 54198843
Invoice No. 55345 - 54198843

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity: 50 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Near out of spec.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54198843 Total	
Parts:	339.74
Labor:	0.00
Labor Hours:	2.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**339.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54088547
Invoice No. 55345 - 54088547

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Chronology		
Reported	Jan 11, 2021 12:00:00 AM	Jan 11, 2021 12:00:00 AM
Started	Jan 11, 2021 5:45:00 PM	
Completed	Jan 11, 2021 8:17:00 PM	Jan 11, 2021 8:17:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM A service

CAUSE: Due by Mileage.

CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 11-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
20 - Miles			EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
30 - Kilometers			EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	
40 - Hours			EARJOHNSON	Jan 11, 2021 8:13:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54088547
Invoice No. 55345 - 54088547

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	2.37	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: EARJOHNSON Performed on: 11-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	-	2 front clearance lights out.	EARJOHNSON	Jan 11, 2021 8:04:16 PM	Yes	54198843
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,800 - INSPECT_High Idle Control	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
31,000 - SSF (Street Side Front)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,000 - Engine Inspection	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,100 - INSPECT_Intake System	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*	NA	EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,010 - CSF (Curb Side Front)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.6 Volt*		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.7 Volt*		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,100 - *RPT*INSPECT_Steering components- Drag Link, Tie Rods ends and Steering Damper	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,400 - LUBE_All Chassis Components	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,700 - INSPECT_Tire Condition	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch	Near out of spec.	EARJOHNSON	Jan 11, 2021 8:04:16 PM	Yes	54198843
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch	Near out of spec.	EARJOHNSON	Jan 11, 2021 8:04:16 PM	Yes	54198843
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	Out of spec.	EARJOHNSON	Jan 11, 2021 8:04:16 PM	Yes	54198843
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	Near out of spec.	EARJOHNSON	Jan 11, 2021 8:04:16 PM	Yes	54198843
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.51 Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.505 Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,100 - INSPECT_Vibration Damper	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,600 - INSPECT_Tire Condition	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	5 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.5 Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.5 Inch		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	15782 Cycles		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,400 - INSPECT_All Pivot Points	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,500 - INSPECT_Cams and Slots	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,600 - INSPECT_Rollers	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
62,700 - INSPECT_All Linkages	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		EARJOHNSON	Jan 11, 2021 8:04:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54088547
Invoice No. 55345 - 54088547

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	283,604 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jan-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-21	Earl Johnson	0.07	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: EARJOHNSON Performed on: 11-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
104,000 - Lubricate Chassis	Done		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Jan 11, 2021 8:08:36 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 54088547 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.49
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54168353
Invoice No. 55345 - 54168353

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 282,343 - DH

Chronology		
Reported	Dec 29, 2020 6:55:07 PM	Dec 29, 2020 6:55:07 PM
Started	Dec 29, 2020 6:57:00 PM	
Completed	Dec 29, 2020 8:53:00 PM	Dec 29, 2020 8:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine light illuminated.

Cause:

Correction: Remove and replaced Cyl. 3 spark plug and ignition coil.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 29, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:50:47 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
20 - Miles			EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
30 - Kilometers			EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	
40 - Hours			EARJOHNSON	Dec 29, 2020 8:50:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54168353
Invoice No. 55345 - 54168353

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 282,343 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-20	26326	PLUG, COIL, IGNITION	1	25.01	25.01

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-20	Earl Johnson	1.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	25.01
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.01**

Work Order Footer

Work Order 54168353 Total	
Parts:	25.01
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54043358
Invoice No. 55345 - 54043358

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Batteries		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	277,205 - DH

Chronology		
Reported	Nov 10, 2020 6:38:00 PM	Nov 10, 2020 6:38:00 PM
Started	Nov 10, 2020 6:43:00 PM	
Completed	Dec 1, 2020 4:22:00 PM	Dec 1, 2020 4:22:00 PM
Down Time		

Work Order Notes

Line 10 Poor cranking
Test batteries; results ;batteries bad.
2 new batteries .
Part number:34 FT qty2 Line 20 2 BATTERIES UNDER WARRANTY

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 10, 2020 6:43:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			RGASPARD	Nov 10, 2020 6:43:42 PM	No	
30 - Kilometers			RGASPARD	Nov 10, 2020 6:43:42 PM	No	
40 - Hours			RGASPARD	Nov 10, 2020 6:43:42 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54043358
Invoice No. 55345 - 54043358

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Batteries		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	277,205 - DH

Activity Header
Activity: 10 032/001/001 BATTERY
Activity Note: BATTER REPLACEMENT DIAGNOSTIC CHECK
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 08 Improper Electrical Value
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Nov-20	Gaspard,Ronald	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: BATTER REPLACEMENT DIAGNOSTIC CHECK
Task: BATTERY REPLACEMENT DIAGNOSTIC Performed by: RGASPARD Performed on: 01-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000,000 - LOAD TEST PERFORMANCE RESULTS	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,100,000 - 1. RECORD THE CCA FOR EACH BATTERY:	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,101,000 - BATTERY ONE	9 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,102,000 - BATTERY TWO	10 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,103,000 - BATTERY THREE	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,104,000 - BATTERY FOUR	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,105,000 - **NOTE** ANY VARIATION IN CCA RATINGS IS UNACCEPTABLE AND MUST BE CORRECTED	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,200,000 - 2. RECORD THE RESERVE CAPACITY FOR EACH BATTERY	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,201,000 - BATTERY ONE	2 Minute*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,202,000 - BATTERY TWO	2 Minute*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,203,000 - BATTERY THREE	0 Minute*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,204,000 - BATTERY FOUR	Minute*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,205,000 - **NOTE** ANYVARIATION IN RC RATINGS IS UNACCEPABLE AND MUST BE CORRECTED	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,300,000 - 3. RECORD THE OPEN CIRCUIT VOLTAGE FOR EACH BATTERY PRIOR TO LOAD TESTING	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,301,000 - BATTERY ONE	142 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,302,000 - BATTERY TWO	14.2 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,303,000 - BATTERY THREE	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,304,000 - BATTERY FOUR	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,400,000 - 5. RECORD THE END OF LOAD TEST VOLTAGE FOR EACH BATTERY	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,401,000 - BATTERY ONE	13.9 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,402,000 - BATTERY TWO	13.9 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,403,000 - BATTERY THREE	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,404,000 - BATTERY FOUR	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,500,000 - DYNAMIC VOLTAGE TESTS OF INTEREST-RECORD AT 1200-1250RPM	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,501,000 - 1. RECORD VOLTAGE AT ALT TERMINAL OUTPUT POST (MIN 27.6V)	20 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,502,000 - 2. RECORD VOLTAGE ACROSS ALL BATTERIES (MIN 27.4)	14 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,503,000 - 3. DETERMINE THE DIFFERENCE IN STEP ONE AND TWO (MAX IS 0.5V)	.4 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,504,000 - 4. RECORD VOLTAGE ACROSS BATTERIES IN 12V SYSTEM (MIN 13.6V)	13.5 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,505,000 - 5. RECORD THE VOLTAGE ACROSS BATTERIES IN 24V SYSTEM (MIN 13.6V)	13.5 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,506,000 - 6. DETERMINE THE DIFFERENCE IN STEP FOUR AND FIVE (MAX 0.7V)	.5 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,000 - 7. RECORD VOLTAGE ACROSS THE TERMINALS OF EACH BATTERY (REFER TO DOCUMENT)	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,100 - SET 1- BATTERY ONE	13.9 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,200 - SET 1- BATTERY TWO	13.9 Volt*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,300 - SET 2- BATTERY THREE	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,400 - SET 2- BATTERY FOUR	0 Volt*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,500 - MAX VARIATION NOT TO EXCEED 0.70V	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,600 - NO VARIATION IN A GIVEN BATTERY SET IS ACCEPTABLE	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,507,700 - **NOTE** ALL BATTERIES MUST BE THE SAME CCA AND RESERVE CAPACITY RATING	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,600,000 - DYNAMIC CURRENT FLOW READING OF INTEREST	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,601,000 - 1. ALTERNATOR OUTPUT (SEE DOCUMENT FOR INSTRUCTIONS AND MIN LIMITS)	10 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,601,100 - **NOTE** CURRENT FLOW MEASURED CAN BE NEGATIVE, THIS INDICATES A BAD ALTERNATOR	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,602,000 - 2. RECORD TOTAL CHARGING CURRENT FLOW TO/FROM BATTERIES (SEE DOC FOR INSTRUCT)	10 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,602,100 - A POSITIVE FLOW IS REQUIRED	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,602,200 - **NOTE** VALUE MAY BE NEGATIVE, RECORD AS NEGATIVE NUMBER	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,602,300 - IF FLOW IS NEGATIVE, DO NOT REPLACE BATTERIES UNTIL POSITIVE FLOW IS ATTAINED	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,603,000 - 3a. CURRENT FLOW OF TWO BATTERY CONFIGURATION (MEASURE EACH)	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,100 - BATTERY 1 AMP FLOW	9 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,200 - BATTERY 2 AMP FLOW	9 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,300 - 3b. CURRENT FLOW OF FOUR BATTERY CONFIGURATION (MEASURE SET)	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,400 - BATTERY SET 1 AMP FLOW	9 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,500 - BATTERY SET 2 AMP FLOW	9 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,603,600 - THE CURRENT FLOW MEASURED IN BATTERY 2 OR SET 2 CANNOT BE NEGATIVE	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,000 - RECORD CURRENT FLOW THROUGH EACH BATTERY IN EACH SET	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,100 - SET 1 BATTERY 1	10 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,200 - SET 1 BATTERY 2	10 Ampere*		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,300 - SET 2 BATTERY 3	0 Ampere*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,400 - SET 2 BATTERY 4	0 Ampere*	na	RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,500 - MAX VARIATION OF FLOW BETWEEN BATTERIES IS 10% OF THE TOTAL FLOW THRU SET	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	
1,604,600 - **NOTE** SEE DOCUMENT FOR THE DIFFERENCE BETWEEN THE PRIMARY AND SECONDARY SETS	Done		RGASPARD	Dec 1, 2020 4:22:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54043358 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54088397
Invoice No. 55345 - 54088397

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 WATER PUMP		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	279,246 - DH

Chronology		
Reported	Nov 27, 2020 10:20:38 AM	Nov 27, 2020 10:20:38 AM
Started	Nov 27, 2020 10:21:00 AM	
Completed	Nov 27, 2020 1:30:00 PM	Nov 27, 2020 1:30:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: water pump was leaking

Cause: preventive maintenance

Correction: replaced the water pump and 2 gallons coolant

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 27-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Nov 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	12:02:05 PM		
20 - Miles			NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	
40 - Hours			NPIERRE-LOUIS	Nov 27, 2020 12:02:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54088397
Invoice No. 55345 - 54088397

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 WATER PUMP		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	279,246 - DH

Activity Header
Activity: 20 042/004/000 PUMP, WATER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Nov-20	T4196	PUMP, WATER, CQWPS	1	34.98	34.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-20	NELSON PIERRE-LOUIS	3.13	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	34.98
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.98**

Work Order Footer

Work Order 54088397 Total	
Parts:	34.98
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53973572
Invoice No. 55345 - 53973572

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	279,246 - DH

Chronology		
Reported	Nov 26, 2020 12:00:00 AM	Nov 26, 2020 12:00:00 AM
Started	Nov 27, 2020 7:07:00 AM	
Completed	Nov 27, 2020 12:36:00 PM	Nov 27, 2020 12:36:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: PMC service

Cause: preventive maintenance

Correction: perform PMC service and Lube all Pivoting Points,Service rear end

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Nov-20	40520	BLADE, WIPER, WINDSHIELD, 20"	1	4.11	4.11

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 27-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
20 - Miles			NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	
40 - Hours			NPIERRE-LOUIS	Nov 27, 2020 12:05:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	4.11
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53973572
Invoice No. 55345 - 53973572

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMC		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	279,246 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-20	NELSON PIERRE-LOUIS	3.22	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 27-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Nov 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:28:17 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13 Volt*		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13 Volt*		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Nov 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	12:28:17 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Nov 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	12:28:17 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Nov 27, 2020 12:28:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53973572
Invoice No. 55345 - 53973572

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 279,246 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Nov-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
27-Nov-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 27-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		NPIERRE-	Nov 27, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)			LOUIS	12:08:04 PM		
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Nov 27, 2020 12:08:04 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order Footer

Work Order 53973572 Total	
Parts:	11.35
Labor:	0.00
Labor Hours:	3.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**11.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54022476
Invoice No. 55345 - 54022476

Client Department:
Department: 55345M
Work Order Description
Bad Wheel Vibration at 40 MPH, Check Engine Light, Rough Idle
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 276,692 - DH

Chronology		
Reported	Nov 3, 2020 11:22:00 PM	Nov 3, 2020 11:22:00 PM
Started	Nov 4, 2020 7:45:00 AM	
Completed	Nov 4, 2020 10:23:00 AM	Nov 4, 2020 10:23:00 AM
Down Time		

Work Order Notes

Line 10 C: Check engine light on

C: Check computer system found code for engine misfire on cylinder 3

C: Replaced ignition coil retest system and road test vehicle, no vibration ok at this time

Part:
1 ignition coil 26326

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 04-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Nov 4, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:22:12 AM		
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
20 - Miles			JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
30 - Kilometers			JAPEREZ	Nov 4, 2020 10:22:12 AM	No	
40 - Hours			JAPEREZ	Nov 4, 2020 10:22:12 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54022476
Invoice No. 55345 - 54022476

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Bad Wheel Vibration at 40 MPH, Check Engine Light, Rough Idle		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	276,692 - DH

Activity Header
Activity: 20 033 IGNITION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54022476
Invoice No. 55345 - 54022476

Client Department:
Department: 55345M
Work Order Description
Bad Wheel Vibration at 40 MPH, Check Engine Light, Rough Idle
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 276,692 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light on
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Nov-20	26326	PLUG, COIL, IGNITION	1	25.11	25.11

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Nov-20	Perez,Javier	2.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	25.11
Labor:	0.00
Labor Hours:	2.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.11**

Work Order Footer

Work Order 54022476 Total	
Parts:	25.11
Labor:	0.00
Labor Hours:	2.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53972170
Invoice No. 55345 - 53972170

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: SHARRINGTON
Created By: SHARRINGTON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 274,820 - DH

Chronology		
Reported	Oct 18, 2020 5:04:30 PM	Oct 18, 2020 5:04:30 PM
Started	Oct 18, 2020 5:05:00 PM	
Completed	Oct 22, 2020 1:47:00 PM	Oct 22, 2020 1:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: no start

Cause: Starter had a internal short

Correction: Replaced Starter dl3z-11002-a

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 22-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		SHARRINGTON	Oct 22, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				1:47:11 PM		
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
20 - Miles			SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
30 - Kilometers			SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	
40 - Hours			SHARRINGTON	Oct 22, 2020 1:47:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53972170
Invoice No. 55345 - 53972170

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: SHARRINGTON
Created By: SHARRINGTON
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 274,820 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Oct-20	DL3Z-11002-A	STARTER, E350, '14	1	142.88	142.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-20	Stephen Harrington	2.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	142.88
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**142.88**

Work Order Footer

Work Order 53972170 Total	
Parts:	142.88
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**142.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53969906
Invoice No. 55345 - 53969906

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP--> Replace Rear Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 274,820 - DH

Chronology		
Reported	Oct 16, 2020 7:35:14 PM	Oct 16, 2020 7:35:14 PM
Started	Oct 16, 2020 7:58:00 PM	
Completed	Oct 19, 2020 10:59:00 PM	Oct 19, 2020 10:59:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear brakes and rotate tires

Cause: wear

Correction:Replaced rear brake pads and rotate tires
Part number 9C2Z-2V200-B qty1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Oct-20	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	37.44	37.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-20	Gaspard,Ronald	0.92	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	37.44
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.44**

Work Order Footer

Work Order 53969906 Total	
Parts:	37.44
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**37.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53826309
Invoice No. 55345 - 53826309

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	274,820 - DH

Chronology		
Reported	Oct 16, 2020 12:00:00 AM	Oct 16, 2020 12:00:00 AM
Started	Oct 16, 2020 5:59:00 PM	
Completed	Oct 19, 2020 9:51:00 AM	Oct 19, 2020 9:51:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 16, 2020 5:59:33 PM	No	
20 - Miles			RGASPARD	Oct 16, 2020 5:59:33 PM	No	
30 - Kilometers			RGASPARD	Oct 16, 2020 5:59:33 PM	No	
40 - Hours			RGASPARD	Oct 16, 2020 5:59:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53826309
Invoice No. 55345 - 53826309

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 274,820 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-20	Gaspard,Ronald	1.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53826309
Invoice No. 55345 - 53826309

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	274,820 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Oct-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-20	Gaspard,Ronald	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 16-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 16, 2020 7:44:06 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 16, 2020 7:44:06 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 16, 2020 7:44:06 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 16, 2020 7:44:06 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 16, 2020 7:44:06 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 16, 2020 7:44:06 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 16, 2020 7:44:06 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 16, 2020 7:44:06 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 53826309 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.96
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53958201
Invoice No. 55345 - 53958201

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (HydroBooster Leaking)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 274,514 - DH

Chronology		
Reported	Oct 13, 2020 11:57:00 PM	Oct 13, 2020 11:57:00 PM
Started	Oct 14, 2020 6:00:00 AM	
Completed	Oct 14, 2020 1:47:00 PM	Oct 14, 2020 1:47:00 PM
Down Time		

Work Order Notes

Line 10 TECH REPLACED HYDROBOOSTER

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
20 - Miles			HPIERRE	Oct 14, 2020 1:36:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers	1		HPIERRE	Oct 14, 2020 1:36:28 PM	No	
40 - Hours	4		HPIERRE	Oct 14, 2020 1:36:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53958201
Invoice No. 55345 - 53958201

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 PER DVIR (HydroBooster Leaking)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	274,514 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53958201
Invoice No. 55345 - 53958201

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (HydroBooster Leaking)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 274,514 - DH

Activity Header
Activity: 30 013 BRAKES
Activity Note: Replace HydroBooster
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Oct-20	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	187.03	187.03

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Oct-20	Pierre,Hubert J	6	0	0
14-Oct-20	Pierre,Hubert J	0.53	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	187.03
Labor:	0.00
Labor Hours:	6.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.03**

Work Order Footer

Work Order 53958201 Total	
Parts:	187.03
Labor:	0.00
Labor Hours:	6.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53925789
Invoice No. 55345 - 53925789

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wheelchair Lift		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	273,366 - DH

Chronology		
Reported	Oct 2, 2020 9:52:54 AM	Oct 2, 2020 9:52:54 AM
Started	Oct 2, 2020 9:53:00 AM	
Completed	Oct 2, 2020 12:50:00 PM	Oct 2, 2020 12:50:00 PM
Down Time		

Work Order Notes

Line 10 Complaint. W/C lift not working

Cause. Found bad control

Correction. Replaced control, all okay at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 02-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Oct 2, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:49:39 PM		
20 - Miles			RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
30 - Kilometers			RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	
40 - Hours			RAURODRIGUEZ	Oct 2, 2020 12:49:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53925789
Invoice No. 55345 - 53925789

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 273,366 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Oct-20	33659KS	PENDANT, CONTROL, W/C, BRAUN	1	187.94	187.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Oct-20	Rodriguez,Raul	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	187.94
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.94**

Work Order Footer

Work Order 53925789 Total	
Parts:	187.94
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53917778
Invoice No. 55345 - 53917778

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 273,152 - DH

Chronology		
Reported	Sep 30, 2020 6:37:24 AM	Sep 30, 2020 6:37:24 AM
Started	Sep 30, 2020 6:38:00 AM	
Completed	Sep 30, 2020 2:47:00 PM	Sep 30, 2020 2:47:00 PM
Down Time		

Work Order Notes

Line 10 PREPARE BUS FOR P.T.C ANNUAL INSPECTION.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Sep-20	Rodriguez,Raul	2.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53917778
Invoice No. 55345 - 53917778

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 273,152 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 30-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
20 - Miles			RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
30 - Kilometers			RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	
40 - Hours			RAURODRIGUEZ	Sep 30, 2020 2:46:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53917778 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53892627
Invoice No. 55345 - 53892627

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Front Tires)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 272,502 - DH

Chronology		
Reported	Sep 21, 2020 6:47:00 PM	Sep 21, 2020 6:47:00 PM
Started		
Completed	Sep 21, 2020 11:41:00 PM	Sep 21, 2020 11:41:00 PM
Down Time		

Work Order Notes

Line 10 Complaint tire on was low on left front

Cause no problem found

Correction put air to 70psi and checked for any objects in tire and nothing was found.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 21-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
10 - Have you successfully completed the	Done		SHARRINGTON	Sep 21, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				10:19:00 PM		
20 - Miles			SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
30 - Kilometers			SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	
40 - Hours			SHARRINGTON	Sep 21, 2020 10:19:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53892627
Invoice No. 55345 - 53892627

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 PER DVIR (Check Front Tires)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,502 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: VERIFY COMPLAINT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53892627
Invoice No. 55345 - 53892627

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 PER DVIR (Check Front Tires)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,502 - DH

Activity Header
Activity: 30 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Check Front Tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53892627 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53885391
Invoice No. 55345 - 53885391

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 Alternator		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,118 - DH

Chronology		
Reported	Sep 18, 2020 10:29:00 AM	Sep 18, 2020 10:29:00 AM
Started	Sep 21, 2020 3:29:00 PM	
Completed	Sep 21, 2020 3:34:00 PM	Sep 21, 2020 3:34:00 PM
Down Time		

Work Order Notes

Line 10 C: Vehicle die while driving

C: inspect electrical system found alternator pulley broke off causing the belt to came off and not to charge the batteries

C:Replaced alternator and belt retest system ok at this time

Parts:
1 new alternator
1 belt

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 21-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
20 - Miles			JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
30 - Kilometers			JAPEREZ	Sep 21, 2020 3:33:40 PM	No	
40 - Hours			JAPEREZ	Sep 21, 2020 3:33:40 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53885391
Invoice No. 55345 - 53885391

Client Department:
Department: 55345M
Work Order Description
55345 Alternator
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 272,118 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Sep-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21
21-Sep-20	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	242.66	242.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Sep-20	Perez,Javier	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	263.66
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**263.66**

Work Order Footer

Work Order 53885391 Total	
Parts:	263.66
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**263.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53883096
Invoice No. 55345 - 53883096

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Install Water Pump		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,118 - DH

Chronology		
Reported	Sep 17, 2020 4:29:00 PM	Sep 17, 2020 4:29:00 PM
Started	Sep 17, 2020 10:00:00 PM	
Completed	Sep 18, 2020 12:08:00 AM	Sep 18, 2020 12:08:00 AM
Down Time		

Work Order Notes

Line 10 Remove and replaced vehicles water pump.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Sep-20	Earl Johnson	0.0666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 17-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
20 - Miles			EARJOHNSON	Sep 17, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:25:11 PM		
30 - Kilometers			EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	
40 - Hours			EARJOHNSON	Sep 17, 2020 11:25:11 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53883096
Invoice No. 55345 - 53883096

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Install Water Pump		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	272,118 - DH

Activity Header
Activity: 20 042/004/000 PUMP, WATER
Activity Note: Install Water Pump
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Sep-20	3L3Z-8501-CA	PUMP, WATER, E450	1	36.96	36.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Sep-20	Earl Johnson	1.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	36.96
Labor:	0.00
Labor Hours:	1.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.96**

Work Order Footer

Work Order 53883096 Total	
Parts:	36.96
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53876752
Invoice No. 55345 - 53876752

Client Department:
Department: 55345M
Work Order Description
BUS DOES NOT CRANK NO START
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 271,897 - DH

Chronology		
Reported	Sep 16, 2020 7:29:00 AM	Sep 16, 2020 7:29:00 AM
Started	Sep 16, 2020 8:39:00 AM	
Completed	Sep 16, 2020 10:42:00 AM	Sep 16, 2020 10:42:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: No crank No start

Cause: loose terminal and blown 30am fuse for starter

Correction: Replaced under hood terminal (positive) and replaced blown 30am Fuse

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Sep 16, 2020 9:56:56 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Sep 16, 2020 9:56:56 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Sep 16, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:56:56 AM		
4 - Have you performed the proper LOTO?	Done		TDELVA	Sep 16, 2020 9:56:56 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Sep 16, 2020 9:56:56 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Sep 16, 2020 9:56:56 AM	No	
20 - Miles			TDELVA	Sep 16, 2020 9:56:56 AM	No	
30 - Kilometers			TDELVA	Sep 16, 2020 9:56:56 AM	No	
40 - Hours			TDELVA	Sep 16, 2020 9:56:56 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53876752
Invoice No. 55345 - 53876752

Client Department:
Department: 55345M
Work Order Description
BUS DOES NOT CRANK NO START
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 271,897 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-20	Delva,Terry	1.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53876752 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53670872
Invoice No. 55345 - 53670872

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,467 - DH

Chronology		
Reported	Aug 28, 2020 12:00:00 AM	Aug 28, 2020 12:00:00 AM
Started	Aug 28, 2020 10:10:00 PM	
Completed	Aug 29, 2020 12:28:00 AM	Aug 29, 2020 12:28:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: service

CORRECTION: Perform PMA service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 28-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 28, 2020 10:10:55 PM	No	
20 - Miles			RGASPARD	Aug 28, 2020 10:10:55 PM	No	
30 - Kilometers			RGASPARD	Aug 28, 2020 10:10:55 PM	No	
40 - Hours			RGASPARD	Aug 28, 2020 10:10:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53670872
Invoice No. 55345 - 53670872

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMA		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	270,467 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Aug-20	Gaspard,Ronald	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53670872
Invoice No. 55345 - 53670872

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 270,467 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Aug-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Aug-20	Gaspard,Ronald	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 28-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 28, 2020 11:42:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 28, 2020 11:42:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 28, 2020 11:42:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 28, 2020 11:42:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 28, 2020 11:42:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 28, 2020 11:42:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 28, 2020 11:42:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 28, 2020 11:42:31 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.28
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53670872
Invoice No. 55345 - 53670872

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 270,467 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-20	Gaspard,Ronald	0.45	0	0
28-Aug-20	Gaspard,Ronald	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 29-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	18357 Cycles		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Aug 29, 2020 12:00:23 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

	Work Order 53670872 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.28
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53747199
Invoice No. 55345 - 53747199

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Wheel Chair Lift)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,129 - DH

Chronology		
Reported	Jul 31, 2020 5:17:00 PM	Jul 31, 2020 5:17:00 PM
Started	Jul 31, 2020 6:06:00 PM	
Completed	Jul 31, 2020 8:22:00 PM	Jul 31, 2020 8:22:00 PM
Down Time		

Work Order Notes

Line 10 Complaint driver stated that Lift wouldn¿t come down

Cause switch for down and up was broken

Correction replace switch #32519ks
Sharrington

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 31-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
20 - Miles			SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
30 - Kilometers			SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	
40 - Hours			SHARRINGTON	Jul 31, 2020 8:21:48 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53747199
Invoice No. 55345 - 53747199

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 PER DVIR (Check Wheel Chair Lift)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	268,129 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53747199
Invoice No. 55345 - 53747199

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Wheel Chair Lift)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 268,129 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Check WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jul-20	32519KS	SWITCH, RAISED, W/C	1	27.98	27.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-20	Stephen Harrington	0.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	27.98
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.98**

Work Order Footer

Work Order 53747199 Total	
Parts:	27.98
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53729143
Invoice No. 55345 - 53729143

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (While Driving Hearing Humming Noise)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 267,799 - DH

Chronology		
Reported	Jul 24, 2020 10:42:00 PM	Jul 24, 2020 10:42:00 PM
Started	Jul 24, 2020 10:44:00 PM	
Completed	Jul 26, 2020 2:46:00 PM	Jul 26, 2020 2:46:00 PM
Down Time		

Work Order Notes

Line 10 Road Test to verify complaint . Found Steering Shaking at 65 MPH & humming sound at 40MPH. Balance & Repack Both Front Wheel bearing. Check driving seem Ok.Need Transmission Mount. None in stock.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 26, 2020 2:45:40 PM	No	
20 - Miles			DARTHURS	Jul 26, 2020 2:45:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			DARTHURS	Jul 26, 2020 2:45:40 PM	No	
40 - Hours			DARTHURS	Jul 26, 2020 2:45:40 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53729143
Invoice No. 55345 - 53729143

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (While Driving Hearing Humming Noise)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 267,799 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jul-20	Arthurs,Durvin	1.27	0	0
25-Jul-20	Arthurs,Durvin	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53729143
Invoice No. 55345 - 53729143

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (While Driving Hearing Humming Noise)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 267,799 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Humming Noise While Driving Highway Speed
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jul-20	Arthurs,Durvin	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53729143 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.99
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53716019
Invoice No. 55345 - 53716019

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 PER DVIR (Front A/C Not Working)		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	267,500 - DH

Chronology		
Reported	Jul 20, 2020 9:22:00 PM	Jul 20, 2020 9:22:00 PM
Started	Jul 20, 2020 9:23:00 PM	
Completed	Jul 20, 2020 9:41:00 PM	Jul 20, 2020 9:41:00 PM
Down Time		

Work Order Notes

Line 10

Complaint: Front a/c not working

Cause: Front a/c blower motor burned

Correction: Replace Front a/c blower motor and also fixed windshield washer hose

Parts: 4C2Z-19A706-AA QTY 1
XC2Z-19805-BA QTY 1
AC2Z-19834-A QTY 1

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA Task: PRA and Meter Readings Performed by: AOWENS Performed on: 20-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 20, 2020 9:33:13 PM	No	
20 - Miles			AOWENS	Jul 20, 2020 9:33:13 PM	No	
30 - Kilometers			AOWENS	Jul 20, 2020 9:33:13 PM	No	
40 - Hours			AOWENS	Jul 20, 2020 9:33:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53716019
Invoice No. 55345 - 53716019

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Front A/C Not Working)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 267,500 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-20	Owens,Arthur	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53716019
Invoice No. 55345 - 53716019

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Front A/C Not Working)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 267,500 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Replace Front A/C Blower Motor
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-20	AC2Z-19834-A	WHEEL, MOTOR, BLOWER	1	29.39	29.39
20-Jul-20	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	12.86	12.86
20-Jul-20	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	35.59	35.59

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-20	Owens,Arthur	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	77.84
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.84**

Work Order Footer

Work Order 53716019 Total	
Parts:	77.84
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53687767
Invoice No. 55345 - 53687767

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Coolant Tank Leaking		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,783 - DH

Chronology		
Reported	Jul 10, 2020 10:51:00 PM	Jul 10, 2020 10:51:00 PM
Started	Jul 12, 2020 12:39:00 PM	
Completed	Jul 12, 2020 2:47:00 PM	Jul 12, 2020 2:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Lost Coolant

Cause: Surge Tank leaking

Correction: Replaced coolant surge tank

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 12-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jul 12, 2020 2:47:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jul 12, 2020 2:47:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jul 12, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:47:35 PM		
4 - Have you performed the proper LOTO?	Done		TDELVA	Jul 12, 2020 2:47:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jul 12, 2020 2:47:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 12, 2020 2:47:35 PM	No	
20 - Miles			TDELVA	Jul 12, 2020 2:47:35 PM	No	
30 - Kilometers			TDELVA	Jul 12, 2020 2:47:35 PM	No	
40 - Hours			TDELVA	Jul 12, 2020 2:47:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53687767
Invoice No. 55345 - 53687767

Client Department:

Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Coolant Tank Leaking		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,783 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Coolant Tank Leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jul-20	8C2Z-8A080-C	TANK, SURGE, COOLANT	1	121.96	121.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-20	Delva,Terry	1.07	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	121.96
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**121.96**

Work Order Footer

Work Order 53687767 Total	
Parts:	121.96
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**121.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53558541
Invoice No. 55345 - 53558541

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,164 - DH

Chronology		
Reported	Jul 3, 2020 12:00:00 AM	Jul 3, 2020 12:00:00 AM
Started	Jul 3, 2020 9:43:00 PM	
Completed	Jul 4, 2020 12:30:00 AM	Jul 4, 2020 12:30:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: Service

CORRECTION: perform PMB Service
Oil filter B329 Qty1
Engine oil 10w30 Qty1
Replaced marker light Qty1
Replaced left Pigtail and head light bulb
Headlight bulb 9008 Qty1

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jul 3, 2020 9:43:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 3, 2020 9:43:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 3, 2020 9:43:38 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jul 3, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:43:38 PM		
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 3, 2020 9:43:38 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 3, 2020 9:43:38 PM	No	
20 - Miles			RGASPARD	Jul 3, 2020 9:43:38 PM	No	
30 - Kilometers			RGASPARD	Jul 3, 2020 9:43:38 PM	No	
40 - Hours			RGASPARD	Jul 3, 2020 9:43:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53558541
Invoice No. 55345 - 53558541

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,164 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-20	Gaspard,Ronald	1.67	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53558541
Invoice No. 55345 - 53558541

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 266,164 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jul-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-20	Gaspard,Ronald	0.58	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 03-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 3, 2020 11:55:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jul 3, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:55:27 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jul 3, 2020 11:55:27 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jul 3, 2020 11:55:27 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53558541
Invoice No. 55345 - 53558541

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345-LIGHT DUTY PMB		Ford E350 Champion Crusaders	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	266,164 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 04-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	18072 Cycles		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Jul 4, 2020 12:28:11 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558541 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.25

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53531322
Invoice No. 55345 - 53531322

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP----->Replace Moryde
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,828 - DH

Chronology		
Reported	May 6, 2020 11:50:50 PM	May 6, 2020 11:50:50 PM
Started	May 7, 2020 6:40:00 PM	
Completed	May 7, 2020 8:02:00 PM	May 7, 2020 8:02:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs moryde

Cause: Broken

Correction:Replaced moryde
Part number DSR108-075 qty1

Activity Header
Activity: 10 014/001 FRAME
Activity Note: needs motor ride
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-20	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	152.75	152.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-20	Gaspard,Ronald	1.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	152.75
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order Footer

Work Order 53531322 Total	
Parts:	152.75
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53328355
Invoice No. 55345 - 53328355

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,828 - DH

Chronology		
Reported	May 5, 2020 10:39:56 AM	May 5, 2020 10:39:56 AM
Started	May 5, 2020 10:19:00 PM	
Completed	May 7, 2020 10:19:56 AM	May 7, 2020 10:19:56 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service
Oil filter B329 qty1
Engine oil 10w30qty 7qts
Replaced AC filter

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-May-20	Gaspard,Ronald	0.72	0	0
06-May-20	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53328355
Invoice No. 55345 - 53328355

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,828 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-20	Gaspard,Ronald	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 06-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 6, 2020 9:39:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 6, 2020 9:39:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 6, 2020 9:39:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 6, 2020 9:39:40 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	May 6, 2020 9:39:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 6, 2020 9:39:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	May 6, 2020 9:39:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 6, 2020 9:39:40 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.43
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53328355
Invoice No. 55345 - 53328355

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,828 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 6, 2020 9:40:17 PM	No	
20 - Miles			RGASPARD	May 6, 2020 9:40:17 PM	No	
30 - Kilometers			RGASPARD	May 6, 2020 9:40:17 PM	No	
40 - Hours			RGASPARD	May 6, 2020 9:40:17 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53328355 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53530755
Invoice No. 55345 - 53530755

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front end service.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,828 - DH

Chronology		
Reported	May 6, 2020 4:44:20 PM	May 6, 2020 4:44:20 PM
Started	May 6, 2020 4:48:00 PM	
Completed	May 6, 2020 6:32:00 PM	May 6, 2020 6:32:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Alignment.

Cause: Wear and tear.

Correction: Remove and replaced drag link, inner tie rod and both outer tie rods.
Part# 8CZ-3304-C Qty.(1). MEOE165 Qty.(1). MEOE126 Qty.(2).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-20	Earl Johnson	0.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 06-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 6, 2020 6:15:38 PM	No	
20 - Miles			EARJOHNSON	May 6, 2020 6:15:38 PM	No	
30 - Kilometers			EARJOHNSON	May 6, 2020 6:15:38 PM	No	
40 - Hours			EARJOHNSON	May 6, 2020 6:15:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53530755
Invoice No. 55345 - 53530755

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front end service.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,828 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Front end service.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-May-20	8C2Z-3304-C	LINK, DRAG, STEERING	1	99.38	99.38
06-May-20	MEOE126	END, TIE-ROD, OUTER, RH, ECONOLINE	2	44.68	89.36
06-May-20	MEOE165	END, TIE-ROD	1	63.61	63.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-May-20	Earl Johnson	1.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	252.35
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**252.35**

Work Order Footer

Work Order 53530755 Total	
Parts:	252.35
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**252.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53524787
Invoice No. 55345 - 53524787

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front tires.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,669 - DH

Chronology		
Reported	May 4, 2020 6:42:33 PM	May 4, 2020 6:42:33 PM
Started	May 4, 2020 7:28:00 PM	
Completed	May 4, 2020 8:54:00 PM	May 4, 2020 8:54:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: RF tire worn.

Cause: wear and tear due to alignment issue.

Correction: Remove and replaced 2front tires. Recommend an alignment.
Part# 192659 Qty.(2).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-May-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 4, 2020 8:14:29 PM	No	
20 - Miles			EARJOHNSON	May 4, 2020 8:14:29 PM	No	
30 - Kilometers			EARJOHNSON	May 4, 2020 8:14:29 PM	No	
40 - Hours			EARJOHNSON	May 4, 2020 8:14:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53524787
Invoice No. 55345 - 53524787

Client Department:
Department: 55345M
Work Order Description
Front tires.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 261,669 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Front tires.
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-May-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-May-20	Earl Johnson	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order Footer

Work Order 53524787 Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53353338
Invoice No. 55345 - 53353338

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,519 - DH

Chronology		
Reported	Mar 5, 2020 8:26:32 AM	Mar 5, 2020 8:26:32 AM
Started	Mar 5, 2020 8:27:00 AM	
Completed	Mar 5, 2020 1:49:00 PM	Mar 5, 2020 1:49:00 PM
Down Time		

Work Order Notes

Line 10 Check engine light on

Bus need a TCM and transmission

Replaced transmission need TCM completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Mar 5, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:46:06 PM		
20 - Miles			HPIERRE	Mar 5, 2020 1:46:06 PM	No	
30 - Kilometers	12		HPIERRE	Mar 5, 2020 1:46:06 PM	No	
40 - Hours	6		HPIERRE	Mar 5, 2020 1:46:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53353338
Invoice No. 55345 - 53353338

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,519 - DH

Activity Header
Activity:20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Mar-20	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	21.63	21.63
11-Mar-20	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.09	9.09
05-Mar-20	19180251	TRANSMISSION, REMANUFACTURED	1	234.5	234.5
11-Mar-20	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Mar-20	Pierre,Hubert J	5.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: HPIERRE Performed on: 05-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		HPIERRE	Mar 5, 2020 1:45:30 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	388.74
Labor:	0.00
Labor Hours:	5.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**388.74**

Work Order Footer

Work Order 53353338 Total	
Parts:	388.74
Labor:	0.00
Labor Hours:	5.35

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**388.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53352371
Invoice No. 55345 - 53352371

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
WC lift malfunction.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,519 - DH

Chronology		
Reported	Mar 4, 2020 8:13:22 PM	Mar 4, 2020 8:13:22 PM
Started	Mar 4, 2020 8:14:00 PM	
Completed	Mar 4, 2020 11:34:00 PM	Mar 4, 2020 11:34:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC lift malfunction per PT.

Cause: Outboard gas shock faulty.

Correction: Remove and replaced 1 gas shock.
Part# 32831 Qty. (1).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-20	Earl Johnson	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
20 - Miles			EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
30 - Kilometers			EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	
40 - Hours			EARJOHNSON	Mar 4, 2020 8:37:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53352371
Invoice No. 55345 - 53352371

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 258,519 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Mar-20	32831	SPRING, SHOCK, GAS, W/C	2	26.73	53.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-20	Earl Johnson	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	53.46
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.46**

Work Order Footer

Work Order 53352371 Total	
Parts:	53.46
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**53.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53344657
Invoice No. 55345 - 53344657

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,281 - DH

Chronology		
Reported	Mar 3, 2020 7:41:47 AM	Mar 3, 2020 7:41:47 AM
Started	Mar 3, 2020 7:43:00 AM	
Completed	Mar 3, 2020 9:25:00 AM	Mar 3, 2020 9:25:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Engine Light On

Cause: Check computer system found codes P0763 and P0980 solenoid C circuit high

Correction:follow diagnostic test and road test vehicle can¿t duplicate concern at this time

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 03-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JAPEREZ	Mar 3, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				9:24:51 AM		
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
20 - Miles			JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
30 - Kilometers			JAPEREZ	Mar 3, 2020 9:24:51 AM	No	
40 - Hours			JAPEREZ	Mar 3, 2020 9:24:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53344657
Invoice No. 55345 - 53344657

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,281 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-20	Perez,Javier	1.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53344657 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53328266
Invoice No. 55345 - 53328266

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-->Repair Washer fluid bottle
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 99 - Cancelled (99)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 257,670 - DH

Chronology		
Reported	Feb 26, 2020 11:44:51 PM	Feb 26, 2020 11:44:51 PM
Started	Feb 27, 2020 12:27:00 AM	
Completed	Feb 27, 2020 8:25:00 PM	Feb 27, 2020 8:25:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:

Cause:

Correction:

Activity Header
Activity:10 002/035/059 HARDWARE, MOUNTING, ARM, WIPER, WINDSHIELD, APFI - 002-035-016
Activity Note: broken hose under reservoir washer fluid
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-20	Gaspard,Ronald	0.48	0	0
27-Feb-20	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53328266 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53211916
Invoice No. 55345 - 53211916

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	257,670 - DH

Chronology		
Reported	Feb 26, 2020 11:22:10 AM	Feb 26, 2020 11:22:10 AM
Started	Feb 26, 2020 9:29:00 PM	
Completed	Feb 27, 2020 12:48:00 AM	Feb 27, 2020 12:48:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service
Oil filter B329 qty1
Drain plug oil 65266 qty1
Engine oil 10w20 qty 7 Qts

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-20	Gaspard,Ronald	1.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53211916
Invoice No. 55345 - 53211916

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 257,670 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Feb-20	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25
26-Feb-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 26-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 26, 2020 11:12:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 26, 2020 11:12:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 26, 2020 11:12:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 26, 2020 11:12:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 26, 2020 11:12:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 26, 2020 11:12:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 26, 2020 11:12:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 26, 2020 11:12:31 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	6.21
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**6.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53211916
Invoice No. 55345 - 53211916

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	257,670 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 26-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 26, 2020 11:13:57 PM	No	
20 - Miles			RGASPARD	Feb 26, 2020 11:13:57 PM	No	
30 - Kilometers			RGASPARD	Feb 26, 2020 11:13:57 PM	No	
40 - Hours			RGASPARD	Feb 26, 2020 11:13:57 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53211916 Total	
Parts:	6.21
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53269978
Invoice No. 55345 - 53269978

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Driver side mirror broken		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	255,855 - DH

Chronology		
Reported	Feb 10, 2020 4:22:12 PM	Feb 10, 2020 4:22:12 PM
Started		
Completed	Feb 10, 2020 6:10:00 PM	Feb 10, 2020 6:10:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for driver side mirror broken

Cause: Unknown

Correction: Removed on replace new mirror to unit part # 709770 now working as design return vehicle back to work

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 10-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Feb 10, 2020 6:09:07 PM	No	
20 - Miles			JUHURST	Feb 10, 2020 6:09:07 PM	No	
30 - Kilometers			JUHURST	Feb 10, 2020 6:09:07 PM	No	
40 - Hours			JUHURST	Feb 10, 2020 6:09:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53269978
Invoice No. 55345 - 53269978

Client Department:
Department: 55345M
Work Order Description
Driver side mirror broken
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 255,855 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note: Driver mirror broken
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Feb-20	709770	PIVOT, HOUSING, GLASS, UPPER	1	28.6	28.6

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	28.60
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.60**

Work Order Footer

Work Order 53269978 Total	
Parts:	28.60
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53242388
Invoice No. 55345 - 53242388

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Right inner tire fiat		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,756 - DH

Chronology		
Reported	Feb 2, 2020 2:53:34 PM	Feb 2, 2020 2:53:34 PM
Started	Feb 2, 2020 5:46:00 PM	
Completed	Feb 2, 2020 7:02:00 PM	Feb 2, 2020 7:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for rear tire flat

Cause: Nail in tire also below specification

Correction: Removed on replace two new tires to Right rear of unit Bridge stone size LT225/75R16 after check vehicle complete on return vehicle back to working line

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 02-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Feb 2, 2020 6:32:46 PM	No	
20 - Miles			JUHURST	Feb 2, 2020 6:32:46 PM	No	
30 - Kilometers			JUHURST	Feb 2, 2020 6:32:46 PM	No	
40 - Hours			JUHURST	Feb 2, 2020 6:32:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53242388
Invoice No. 55345 - 53242388

Client Department:
Department: 55345M
Work Order Description
Right inner tire fiat
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 254,756 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Right inner tire flat
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Feb-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	132.06	264.12

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-20	Junior Hurst	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	264.12
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**264.12**

Work Order Footer

Work Order 53242388 Total	
Parts:	264.12
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**264.12**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53211849
Invoice No. 55345 - 53211849

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,581 - DH

Chronology		
Reported	Jan 24, 2020 9:39:50 AM	Jan 24, 2020 9:39:50 AM
Started	Jan 24, 2020 9:56:00 AM	
Completed	Jan 24, 2020 1:58:00 PM	Jan 24, 2020 1:58:00 PM
Down Time		

Work Order Notes

Line 10 Pm follow up

Preventing maintenance

Replace both motor mount completed

Activity Header
Activity: 10 014/001 FRAME
Activity Note: need front mount
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53211849
Invoice No. 55345 - 53211849

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 253,581 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-20	F7UZ-6038-DB	MOUNT, ENGINE	1	40.27	40.27
24-Jan-20	F7UZ-6038-DC	INSULATOR	1	31.55	31.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-20	Pierre,Hubert J	4.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	71.82
Labor:	0.00
Labor Hours:	4.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.82**

Work Order Footer

Work Order 53211849 Total	
Parts:	71.82
Labor:	0.00
Labor Hours:	4.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53119506
Invoice No. 55345 - 53119506

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,581 - DH

Chronology		
Reported	Jan 23, 2020 4:10:24 PM	Jan 23, 2020 4:10:24 PM
Started	Jan 24, 2020 6:07:00 AM	
Completed	Jan 24, 2020 9:55:00 AM	Jan 24, 2020 9:55:00 AM
Down Time		

Work Order Notes

Line 10 Pic

Preventing maintenance

Perform pm lube all pivoted point cross rotate tire completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53119506
Invoice No. 55345 - 53119506

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 253,581 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-20	Pierre,Hubert J	3.8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 24-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		HPIERRE	Jan 24, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				9:50:35 AM		
201,000 - Service Crankcase Breather	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Jan 24, 2020 9:50:35 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Jan 24, 2020 9:50:35 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Jan 24, 2020 9:50:35 AM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Jan 24, 2020 9:50:35 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53119506
Invoice No. 55345 - 53119506

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,581 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 24-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
20 - Miles			HPIERRE	Jan 24, 2020 9:51:27 AM	No	
30 - Kilometers	12		HPIERRE	Jan 24, 2020 9:51:27 AM	No	
40 - Hours			HPIERRE	Jan 24, 2020 9:51:27 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53119506 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53205212
Invoice No. 55345 - 53205212

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Fire detector		Ford E350 Champion Crusaders	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,233 - DH

Chronology		
Reported	Jan 22, 2020 2:21:51 PM	Jan 22, 2020 2:21:51 PM
Started	Jan 22, 2020 2:24:00 PM	
Completed	Jan 22, 2020 3:12:00 PM	Jan 22, 2020 3:12:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for fire detector

Cause: empty container

Correction: Removed on replace new fire bottle. To unit also change right side head lamp part# # H 13. Unit now working as design return vehicle back to work Please charge out this Part can¿t fine the #. H13 / 9008

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 22, 2020 3:11:32 PM	No	
20 - Miles			JUHURST	Jan 22, 2020 3:11:32 PM	No	
30 - Kilometers			JUHURST	Jan 22, 2020 3:11:32 PM	No	
40 - Hours			JUHURST	Jan 22, 2020 3:11:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53205212
Invoice No. 55345 - 53205212

Client Department:
Department: 55345M
Work Order Description
Fire detector
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 253,233 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Fire detector
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jan-20	Junior Hurst	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53205212 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53195254
Invoice No. 55345 - 53195254

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	252,591 - DH

Chronology		
Reported	Jan 20, 2020 7:59:51 AM	Jan 20, 2020 7:59:51 AM
Started	Jan 20, 2020 8:01:00 AM	
Completed	Jan 20, 2020 12:46:00 PM	Jan 20, 2020 12:46:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Check engine light on

Cause: Check computer system found code for cylinder #4 misfire perform diagnostic test found head gasket leaks coolant

Correction:install head gasket stop leak, retest system and road test vehicle ok at this time

Part:
1 head gasket sealer 38386

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 20-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
20 - Miles			JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
30 - Kilometers			JAPEREZ	Jan 20, 2020 12:46:11 PM	No	
40 - Hours			JAPEREZ	Jan 20, 2020 12:46:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53195254
Invoice No. 55345 - 53195254

Client Department:
Department: 55345M
Work Order Description
Check engine light on
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 252,591 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jan-20	38386	TREATMENT, SEALER, COOLANT	1	59.5	59.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jan-20	Perez,Javier	3.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	59.50
Labor:	0.00
Labor Hours:	3.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**59.50**

Work Order Footer

Work Order 53195254 Total	
Parts:	59.50
Labor:	0.00
Labor Hours:	3.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**59.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53133900
Invoice No. 55345 - 53133900

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light illuminated.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	250,196 - DH

Chronology		
Reported	Dec 29, 2019 1:53:14 PM	Dec 29, 2019 1:53:14 PM
Started	Dec 29, 2019 2:03:00 PM	
Completed	Jan 6, 2020 7:57:00 AM	Jan 6, 2020 7:57:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle running rough and stalling.

Cause: Cylinder #2 misfire.

Correction: Remove and replaced cylinder #2 ignition coil.
Part# 3W7Z-12029-AA Qty. (1).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-19	Earl Johnson	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
20 - Miles			EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
30 - Kilometers			EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	
40 - Hours			EARJOHNSON	Dec 29, 2019 4:08:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53133900
Invoice No. 55345 - 53133900

Client Department:
Department: 55345M
Work Order Description
Check engine light illuminated.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 250,196 - DH

Activity Header
Activity: 15 033 IGNITION
Activity Note: Check engine light illuminated.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-19	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	1	34.61	34.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-19	Earl Johnson	1.97	65	128.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	34.61
Labor:	128.05
Labor Hours:	1.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**162.66**

Work Order Footer

Work Order 53133900 Total	
Parts:	34.61
Labor:	133.47
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**168.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53014228
Invoice No. 55345 - 53014228

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Chronology		
Reported	Dec 20, 2019 8:59:44 AM	Dec 20, 2019 8:59:44 AM
Started	Dec 22, 2019 7:57:00 AM	
Completed	Dec 22, 2019 12:50:00 PM	Dec 22, 2019 12:50:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE
REPLACED AIR FILTER

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.85	65	55.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	55.25
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53014228
Invoice No. 55345 - 53014228

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 249,496 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
22-Dec-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.27	65	17.55

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 22-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:11 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	17.55
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53014228
Invoice No. 55345 - 53014228

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 22-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
20 - Miles			VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
30 - Kilometers			VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	
40 - Hours			VAMRITTEEMAL	Dec 22, 2019 12:50:39 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53014228 Total	
Parts:	7.24
Labor:	72.80
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**80.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 53119425
Invoice No. 55345 - 53119425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Chronology		
Reported	Dec 22, 2019 8:48:36 AM	Dec 22, 2019 8:48:36 AM
Started	Dec 22, 2019 9:05:00 AM	
Completed	Dec 22, 2019 12:46:00 PM	Dec 22, 2019 12:46:00 PM
Down Time		

Work Order Notes

Line 10 Coolant reservoir not leaking
Passed pressure test at 16 psi
Front brakes low
Seized slide pins caused uneven wear
Replaced pads and cleaned and lubricated slide pins
Rear brakes low
Normal wear
Replaced rear brakes
Right rear tire has nail
Repaired puncture
Torqued all wheels to 140ftlb test driven and retorqued Line 20 Coolant reservoir not leaking
Passed pressure test at 16 psi
Front brakes low
Seized slide pins caused uneven wear
Replaced pads and cleaned and lubricated slide pins
Rear brakes low
Normal wear
Replaced rear brakes
Right rear tire has nail
Repaired puncture
Torqued all wheels to 140ftlb test driven and retorqued Line 30 Coolant reservoir not cracked
Passed pressure test at 16 psi
Front brakes uneven wear
Slide pins seized
Replaced pads and cleaned and lubricated slide pins
Rear brakes low
Normal wear
Replaced rear brakes
Right rear tire has nail
Repaired puncture
Torqued wheels to 140ftlb test driven and retorqued Line 40 T

Activity Header
Activity: 10 042 COOLING SYSTEM
Activity Note: coolant reservoir cracked
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.7	65	45.5

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	45.50
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**45.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 53119425
Invoice No. 55345 - 53119425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Activity Header
Activity: 20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: front brakes low
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.38	65	24.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	48.87
Labor:	24.70
Labor Hours:	0.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**73.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 53119425
Invoice No. 55345 - 53119425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Activity Header
Activity: 30 013/000/000 BRAKES
Activity Note: rear brakes low
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Dec-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.85	65	55.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	46.22
Labor:	55.25
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 53119425
Invoice No. 55345 - 53119425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Activity Header
Activity: 40 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Right rear flat tire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.42	65	27.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	27.30
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 53119425
Invoice No. 55345 - 53119425

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOWUP-FT Light Duty		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,496 - DH

Activity Header
Activity: 50 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

50 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 22-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
20 - Miles			VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
30 - Kilometers			VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	
40 - Hours			VAMRITTEEMAL	Dec 22, 2019 12:30:14 PM	No	

Activity Sub Total

Activity 50 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53119425 Total	
Parts:	95.09
Labor:	152.75
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**247.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53068700
Invoice No. 55345 - 53068700

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replaced blower 3 speed resister		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,570 - DH

Chronology		
Reported	Dec 6, 2019 11:21:17 AM	Dec 6, 2019 11:21:17 AM
Started		
Completed	Dec 12, 2019 9:02:00 AM	Dec 12, 2019 9:02:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Rear AC work on medium only

Cause: 3-speed blower resistor went bad

Correction: replaced rear blower resistor

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 11-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
20 - Miles			NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	
40 - Hours			NPIERRE-LOUIS	Dec 11, 2019 11:58:28 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53068700
Invoice No. 55345 - 53068700

Client Department:
Department: 55345M
Work Order Description
Replaced blower 3 speed resister
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 247,570 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Dec-19	8165001	RESISTOR, BLOWER, 3-SPEED W/KIT	1	17.63	17.63

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: ELECTRICAL SYSTEM Performed by: NPIERRE-LOUIS Performed on: 06-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - A/C SYSTEM CHECK	Done		NPIERRE-LOUIS	Dec 6, 2019 12:46:00 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	17.63
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.63**

Work Order Footer

Work Order 53068700 Total	
Parts:	17.63
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53049687
Invoice No. 55345 - 53049687

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear ac not working.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	246,758 - DH

Chronology		
Reported	Dec 1, 2019 8:42:58 PM	Dec 1, 2019 8:42:58 PM
Started	Dec 1, 2019 12:00:00 AM	
Completed	Dec 2, 2019 10:15:47 AM	Dec 2, 2019 10:15:47 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear ac not working.

Cause: White multi wire connector for rear ac thermostat damaged.

Correction: Remove and replaced connector.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-19	Earl Johnson	0.1	65	6.5

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
20 - Miles			EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
30 - Kilometers			EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	
40 - Hours			EARJOHNSON	Dec 1, 2019 8:57:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	6.50
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53049687
Invoice No. 55345 - 53049687

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear ac not working.		Ford E350 Champion Crusaders	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	246,758 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear ac not working.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-19	Earl Johnson	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order Footer

Work Order 53049687 Total	
Parts:	0.00
Labor:	136.50
Labor Hours:	2.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**136.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53030833
Invoice No. 55345 - 53030833

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replaced floor mat		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,831 - DH

Chronology		
Reported	Nov 22, 2019 8:11:14 PM	Nov 22, 2019 8:11:14 PM
Started	Nov 22, 2019 12:00:00 AM	
Completed	Nov 22, 2019 8:15:00 PM	Nov 22, 2019 8:15:00 PM
Down Time		

Work Order Notes

Line 10 Replaced floor mat

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Nov-19	BC2Z-3513000-AA	MAT, FLOOR	1	307.01	307.01

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Nov-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 22-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
30 - Kilometers			VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	
40 - Hours			VAMRITTEEMAL	Nov 22, 2019 8:15:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	307.01
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**372.01**

Work Order Footer

Work Order 53030833 Total	
Parts:	307.01
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**372.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52898742
Invoice No. 55345 - 52898742

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,234 - DH

Chronology		
Reported	Nov 18, 2019 12:00:00 AM	Nov 18, 2019 12:00:00 AM
Started	Nov 18, 2019 12:00:00 AM	
Completed	Nov 19, 2019 12:04:00 AM	Nov 19, 2019 12:04:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Nov-19	Gaspard,Ronald	1.5833333	65	102.9166645

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Nov 18, 2019 11:37:02 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 18, 2019 11:37:02 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52898742
Invoice No. 55345 - 52898742

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 245,234 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Nov-19	Gaspard,Ronald	1.0833333	65	70.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 18, 2019 11:37:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 18, 2019 11:37:38 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 18, 2019 11:37:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 18, 2019 11:37:38 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 18, 2019 11:37:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 18, 2019 11:37:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Nov 18, 2019 11:37:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 18, 2019 11:37:38 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	70.42
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**72.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52898742
Invoice No. 55345 - 52898742

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,234 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Nov-19	Gaspard,Ronald	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 18, 2019 11:38:02 PM	No	
20 - Miles			RGASPARD	Nov 18, 2019 11:38:02 PM	No	
30 - Kilometers			RGASPARD	Nov 18, 2019 11:38:02 PM	No	
40 - Hours			RGASPARD	Nov 18, 2019 11:38:02 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	16.25
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**16.25**

Work Order Footer

Work Order 52898742 Total	
Parts:	1.96
Labor:	189.58
Labor Hours:	2.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**191.54**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52956310
Invoice No. 55345 - 52956310

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check engine light on		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	243,071 - DH

Chronology		
Reported	Nov 1, 2019 10:26:34 AM	Nov 1, 2019 10:26:34 AM
Started		
Completed	Nov 6, 2019 10:28:41 AM	Nov 6, 2019 10:28:41 AM
Down Time		

Work Order Notes

Line 10 Complaint: check engine light on

Cause: Misfire, Cylinder 1 and 4

Correction: replaced 2 spark plugs, the vehicle ok at this time

Parts: Ap103 , spark plug

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 01-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-	Nov 1, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:32:57 AM		
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
20 - Miles			NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	
40 - Hours			NPIERRE-LOUIS	Nov 1, 2019 10:32:57 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52956310
Invoice No. 55345 - 52956310

Client Department:
Department: 55345M
Work Order Description
Check engine light on
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 243,071 - DH

Activity Header
Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Nov-19	E262	COIL, IGNITION	2	42.58	85.16
01-Nov-19	AP103	PLUG, SPARK	2	3.11	6.22

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	91.38
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.38**

Work Order Footer

Work Order 52956310 Total	
Parts:	91.38
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52927752
Invoice No. 55345 - 52927752

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Interior light out		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,739 - DH

Chronology		
Reported	Oct 23, 2019 11:35:00 PM	Oct 23, 2019 11:35:00 PM
Started	Oct 23, 2019 12:00:00 AM	
Completed	Oct 24, 2019 11:06:09 AM	Oct 24, 2019 11:06:09 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Interior light is out

Cause: normal usage

Correction: replace L.E.D blub

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Owens,Arthur	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 23-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Oct 23, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:40:19 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Oct 23, 2019 11:40:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Oct 23, 2019 11:40:19 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Oct 23, 2019 11:40:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Oct 23, 2019 11:40:19 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Oct 23, 2019 11:40:19 PM	No	
20 - Miles			AOWENS	Oct 23, 2019 11:40:19 PM	No	
30 - Kilometers			AOWENS	Oct 23, 2019 11:40:19 PM	No	
40 - Hours			AOWENS	Oct 23, 2019 11:40:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52927752
Invoice No. 55345 - 52927752

Client Department:
Department: 55345M
Work Order Description
Interior light out
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 241,739 - DH

Activity Header
Activity: 15 034/000/000 LIGHTING SYSTEM
Activity Note: Replace Interior light
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-19	3976389	LAMP, INTERIOR, LED	1	26.71	26.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Owens,Arthur	0.8	65	52

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	26.71
Labor:	52.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.71**

Work Order Footer

Work Order 52927752 Total	
Parts:	26.71
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52905170
Invoice No. 55345 - 52905170

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Bus don¿t start		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,003 - DH

Chronology		
Reported	Oct 17, 2019 11:29:31 AM	Oct 17, 2019 11:29:31 AM
Started		
Completed	Oct 17, 2019 11:43:00 AM	Oct 17, 2019 11:43:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: bus won¿t starter

Cause: Bad Starter

Correction:replace starter check charging system completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 17-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
20 - Miles			HPIERRE	Oct 17, 2019 11:43:37 AM	No	
30 - Kilometers	12		HPIERRE	Oct 17, 2019 11:43:37 AM	No	
40 - Hours	1		HPIERRE	Oct 17, 2019 11:43:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52905170
Invoice No. 55345 - 52905170

Client Department:
Department: 55345M
Work Order Description
Bus don¿t start
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 241,003 - DH

Activity Header
Activity: 15 031/002/001 REGULATOR, VOLTAGE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Oct-19	DL3Z-11002-A-COR	CORE, STARTER, E350, '14	1	35	35
25-Oct-19	DL3Z-11002-A	STARTER, E350, '14	1	133.95	133.95
04-Nov-19	DL3Z-11002-A-COR	CORE, STARTER, E350, '14	-1	35	-35

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order Footer

Work Order 52905170 Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52787692
Invoice No. 55345 - 52787692

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,675 - DH

Chronology		
Reported	Oct 14, 2019 3:08:07 PM	Oct 14, 2019 3:08:07 PM
Started	Oct 15, 2019 12:00:00 AM	
Completed	Oct 15, 2019 3:26:07 PM	Oct 15, 2019 3:26:07 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMB SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 15-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,135 - Brake Rotor LF	39.86 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,136 - Brake Rotor RF	39.88 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,137 - Brake Rotor LR	35.9 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,138 - Brake Rotor RR	35.89 Inch		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Oct 15, 2019 12:53:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52787692
Invoice No. 55345 - 52787692

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,675 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: VAMRITTEEMAL Performed on: 15-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		VAMRITTEEMAL	Oct 15, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				12:54:59 PM		
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No	n/a	VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Oct 15, 2019 12:54:59 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52787692
Invoice No. 55345 - 52787692

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RRENE	**Status:**	40 - Closed (40)
Created By:	RRENE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,675 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 15-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
20 - Miles			VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 15, 2019 12:55:29 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52787692 Total	
Parts:	1.96
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**181.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52897950
Invoice No. 55345 - 52897950

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replaced 2 front tires		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	240,675 - DH

Chronology

Reported	Oct 15, 2019 12:57:31 PM	Oct 15, 2019 12:57:31 PM
Started	Oct 15, 2019 12:00:00 AM	
Completed	Oct 15, 2019 1:59:00 PM	Oct 15, 2019 1:59:00 PM
Down Time		

Work Order Notes

Line 10 Front tires worn
Mount and balanced 2 front tires
Torqued wheels to 140ftlb test driven and retorqued

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 15-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Oct 15, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:01:13 PM		
20 - Miles			VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 15, 2019 1:01:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52897950
Invoice No. 55345 - 52897950

Client Department:
Department: 55345M
Work Order Description
Replaced 2 front tires
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 240,675 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Oct-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	121.55	243.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	243.10
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**308.10**

Work Order Footer

Work Order 52897950 Total	
Parts:	243.10
Labor:	82.33
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**325.43**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52677776
Invoice No. 55345 - 52677776

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	236,237 - DH

Chronology		
Reported	Sep 12, 2019 2:41:04 PM	Sep 12, 2019 2:41:04 PM
Started	Sep 12, 2019 12:00:00 AM	
Completed	Sep 13, 2019 7:42:23 AM	Sep 13, 2019 7:42:23 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts
Replaced exhaust hanger

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Sep-19	Gaspard,Ronald	1.6	65	104

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 12-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Sep 12, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:56:56 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 12, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:56:56 PM		
20,260 - Check Stop Request System	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,442 - Freeze Point	Degree	NA	RGASPARD	Sep 12, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:56:56 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Sep 12, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:56:56 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Sep 12, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:56:56 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Sep 12, 2019 11:56:56 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 12, 2019 11:56:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	104.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52677776
Invoice No. 55345 - 52677776

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 236,237 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Sep-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Sep-19	Gaspard,Ronald	1.1	65	71.5

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 12-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 12, 2019 11:57:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 12, 2019 11:57:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 12, 2019 11:57:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 12, 2019 11:57:28 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 12, 2019 11:57:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 12, 2019 11:57:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Sep 12, 2019 11:57:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 12, 2019 11:57:28 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	71.50
	Labor Hours:	1.10
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**73.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52677776
Invoice No. 55345 - 52677776

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 236,237 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Sep-19	Gaspard,Ronald	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 12, 2019 11:57:52 PM	No	
20 - Miles			RGASPARD	Sep 12, 2019 11:57:52 PM	No	
30 - Kilometers			RGASPARD	Sep 12, 2019 11:57:52 PM	No	
40 - Hours			RGASPARD	Sep 12, 2019 11:57:52 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52677776 Total	
Parts:	1.96
Labor:	192.83
Labor Hours:	2.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**194.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 52677743
Invoice No. 55345 - 52677743

Client Department:
Department: 55345M
Work Order Description
Front brakes /interior Light / Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Chronology		
Reported	Aug 9, 2019 11:32:50 PM	Aug 9, 2019 11:32:50 PM
Started	Aug 9, 2019 12:00:00 AM	
Completed	Aug 10, 2019 12:09:00 AM	Aug 10, 2019 12:09:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Brakes / interior Light / Rear Tires / Serpentine belts

Cause: Front Brakes Low / one interior Light Out / Both R/R Tire Low. Belts cracks.

Correction: Remove and replace Front Brakes / Remove& Replace serpentine belts / Replace interior Light/ Mount & Balance Both R/R rear tire rotate new Tire To Front & Both Front To R/R,
Parts# 192569 Qty (2)
Parts #8C2Z-2V001-D Qty (1)
Parts# 1360K6 Qty (1)
Parts #3976389 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 9, 2019 11:35:06 PM	No	
20 - Miles			DARTHURS	Aug 9, 2019 11:35:06 PM	No	
30 - Kilometers			DARTHURS	Aug 9, 2019 11:35:06 PM	No	
40 - Hours			DARTHURS	Aug 9, 2019 11:35:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52591115
Invoice No. 55345 - 52591115

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Chronology		
Reported	Aug 9, 2019 4:25:26 PM	Aug 9, 2019 4:25:26 PM
Started	Aug 9, 2019 12:00:00 AM	
Completed	Aug 10, 2019 12:09:00 AM	Aug 10, 2019 12:09:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check Brakes. Clean batteries.replace A/C Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,420 - Check Hood	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,138 - Brake Rotor RR	1.416 Inch		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Aug 9, 2019 11:25:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Aug 9, 2019 11:25:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 52677743
Invoice No. 55345 - 52677743

Client Department:
Department: 55345M
Work Order Description
Front brakes /interior Light / Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	42.81	42.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	42.81
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**107.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52591115
Invoice No. 55345 - 52591115

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 09-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Aug 9, 2019 11:26:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Aug 9, 2019 11:26:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Aug 9, 2019 11:26:20 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 52677743
Invoice No. 55345 - 52677743

Client Department:
Department: 55345M
Work Order Description
Front brakes /interior Light / Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Activity Header
Activity:25 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-19	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.05	21.05

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	1	65	65
09-Aug-19	Arthurs,Durvin	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	21.05
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52591115
Invoice No. 55345 - 52591115

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,796 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 9, 2019 11:27:02 PM	No	
20 - Miles			DARTHURS	Aug 9, 2019 11:27:02 PM	No	
30 - Kilometers			DARTHURS	Aug 9, 2019 11:27:02 PM	No	
40 - Hours			DARTHURS	Aug 9, 2019 11:27:02 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52591115 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 52677743
Invoice No. 55345 - 52677743

Client Department:
Department: 55345M
Work Order Description
Front brakes /interior Light / Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Activity Header
Activity: 35 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.48	240.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	240.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**305.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 52677743
Invoice No. 55345 - 52677743

Client Department:
Department: 55345M
Work Order Description
Front brakes /interior Light / Rear tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 231,796 - DH

Activity Header
Activity: 45 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Aug-19	3976389	LAMP, INTERIOR, LED	1	26.71	26.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Aug-19	Arthurs,Durvin	0.25	65	16.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	26.71
Labor:	16.25
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**42.96**

Work Order Footer

Work Order 52677743 Total	
Parts:	331.53
Labor:	249.17
Labor Hours:	3.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**580.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52663831
Invoice No. 55345 - 52663831

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replaced condenser fan		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	231,238 - DH

Chronology		
Reported	Aug 5, 2019 9:16:11 PM	Aug 5, 2019 9:16:11 PM
Started	Aug 5, 2019 12:00:00 AM	
Completed	Aug 5, 2019 10:07:00 PM	Aug 5, 2019 10:07:00 PM
Down Time		

Work Order Notes

Line 10 Replaced 1 rear a/c condenser fan

Activity Header
Activity: 10 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-19	AMRIT TEEMAL,VISHNU	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52663831
Invoice No. 55345 - 52663831

Client Department:
Department: 55345M
Work Order Description
Replaced condenser fan
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 231,238 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Aug-19	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	1	101.17	101.17

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 05-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
20 - Miles			VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
30 - Kilometers			VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	
40 - Hours			VAMRITTEEMAL	Aug 5, 2019 9:19:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	101.17
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**118.50**

Work Order Footer

Work Order 52663831 Total	
Parts:	101.17
Labor:	49.83
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52591082
Invoice No. 55345 - 52591082

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear Brakes / L/R Lug Nut Strip.		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,611 - DH

Chronology		
Reported	Jul 10, 2019 11:33:24 PM	Jul 10, 2019 11:33:24 PM
Started	Jul 10, 2019 12:00:00 AM	
Completed	Jul 11, 2019 12:14:00 AM	Jul 11, 2019 12:14:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes Low / L/R Wheel Stud

Cause: Rear Brakes Low / L/R wheel Stud Strip.

Correction: Remove& Replace Rear Brakes. & Remove. L/R hub To Replace Strip Lug& Replace hub.
Parts#9C2Z-2V200-B Qty (1)
Parts#249 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 10, 2019 11:35:53 PM	No	
20 - Miles			DARTHURS	Jul 10, 2019 11:35:53 PM	No	
30 - Kilometers			DARTHURS	Jul 10, 2019 11:35:53 PM	No	
40 - Hours			DARTHURS	Jul 10, 2019 11:35:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52493509
Invoice No. 55345 - 52493509

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,611 - DH

Chronology		
Reported	Jul 10, 2019 9:11:44 AM	Jul 10, 2019 9:11:44 AM
Started	Jul 10, 2019 12:00:00 AM	
Completed	Jul 11, 2019 12:14:00 AM	Jul 11, 2019 12:14:00 AM
Down Time		

Work Order Notes

Line 10 Perform PMC Service. Change Oil & Filter. Lube all Pivoting Points. Check Brakes Clean batteries.Perform Transmission Service./ Perform Differential Service . drain& Fill Replace Air Filter.
Parts# B329 Qty (1)
Parts # PA4075 Qty (1)
Parts# 20021 Qty (1)
Oil 5W20 Qty (6.5) Qt
Gear Oil 80W90 Qty (3) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-19	Arthurs,Durvin	3.5	65	227.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 10-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,133 - Brake Pad Thickness LR	2 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,134 - Brake Pad Thickness RR	2 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,138 - Brake Rotor RR	1.415 Inch		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 10, 2019 11:22:35 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 10, 2019 11:22:35 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	227.50
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52591082
Invoice No. 55345 - 52591082

Client Department:
Department: 55345M
Work Order Description
Rear Brakes / L/R Lug Nut Strip.
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,611 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jul-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-19	Arthurs,Durvin	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.22
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**208.72**

Work Order Footer

Work Order 52591082 Total	
Parts:	46.22
Labor:	167.92
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52493509
Invoice No. 55345 - 52493509

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 227,611 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jul-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
10-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
10-Jul-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 10-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jul 10, 2019 11:24:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jul 10, 2019 11:24:09 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Jul 10, 2019 11:24:09 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jul 10, 2019 11:24:09 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jul 10, 2019 11:24:09 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Jul 10, 2019 11:24:09 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	24.51
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52493509
Invoice No. 55345 - 52493509

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,611 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 10, 2019 11:24:47 PM	No	
20 - Miles			DARTHURS	Jul 10, 2019 11:24:47 PM	No	
30 - Kilometers			DARTHURS	Jul 10, 2019 11:24:47 PM	No	
40 - Hours			DARTHURS	Jul 10, 2019 11:24:47 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52493509 Total	
Parts:	24.51
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**284.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52576440
Invoice No. 55345 - 52576440

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle smell coolant		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,038 - DH

Chronology		
Reported	Jul 5, 2019 10:00:04 AM	Jul 5, 2019 10:00:04 AM
Started	Jul 5, 2019 12:00:00 AM	
Completed	Jul 8, 2019 9:59:33 AM	Jul 8, 2019 9:59:33 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle smell coolant

Cause: check cooling system found heater hoses leaking

Correction:tech replaced both heater hoses and add coolant

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 05-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
20 - Miles			NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	
40 - Hours			NPIERRE-LOUIS	Jul 5, 2019 10:22:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52576440
Invoice No. 55345 - 52576440

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle smell coolant		Ford E350 Champion Crusaders	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,038 - DH

Activity Header
Activity: 15 042 COOLING SYSTEM
Activity Note: Driver complaint the vehicle was smell coolant
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.54	59.54

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-19	NELSON PIERRE-LOUIS	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	119.08
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**249.08**

Work Order Footer

Work Order 52576440 Total	
Parts:	119.08
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**249.08**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52562767
Invoice No. 55345 - 52562767

Client Department:
Department: 55345M
Work Order Description
Replaced radiator/front blower motor resistor/pigtail
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,395 - DH

Chronology

Reported	Jun 30, 2019 4:32:52 PM	Jun 30, 2019 4:32:52 PM
Started	Jun 30, 2019 12:00:00 AM	
Completed	Jul 1, 2019 8:56:20 AM	Jul 1, 2019 8:56:20 AM
Down Time		

Work Order Notes

Line 10 Replaced radiator
Replaced front blower motor resistor w/ pigtail

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 30-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	
40 - Hours			VAMRITTEEMAL	Jun 30, 2019 4:46:59 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52562767
Invoice No. 55345 - 52562767

Client Department:
Department: 55345M
Work Order Description
Replaced radiator/front blower motor resistor/pigtail
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,395 - DH

Activity Header
Activity: 20 042 COOLING SYSTEM
Activity Note:
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-19	G1000382282CSF	RADIATOR, E450	1	205.04	205.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	205.04
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**270.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52562767
Invoice No. 55345 - 52562767

Client Department:
Department: 55345M
Work Order Description
Replaced radiator/front blower motor resistor/pigtail
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,395 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-19	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	13.46	13.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	13.46
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.46**

Work Order Footer

Work Order 52562767 Total	
Parts:	218.50
Labor:	147.33
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**365.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52400877
Invoice No. 55345 - 52400877

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 223,455 - DH

Chronology		
Reported	Jun 5, 2019 11:59:27 AM	Jun 5, 2019 11:59:27 AM
Started	Jun 5, 2019 12:00:00 AM	
Completed	Jun 6, 2019 12:04:00 AM	Jun 6, 2019 12:04:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PmA

CAUSE: Service

CORRECTION:perform PmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Gaspard,Ronald	1.5833333	65	102.9166645

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 5, 2019 11:40:46 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 5, 2019 11:40:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52400877
Invoice No. 55345 - 52400877

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	223,455 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Gaspard,Ronald	1.1	65	71.5

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 5, 2019 11:41:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 5, 2019 11:41:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 5, 2019 11:41:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 5, 2019 11:41:27 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 5, 2019 11:41:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 5, 2019 11:41:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 5, 2019 11:41:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 5, 2019 11:41:27 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	71.50
	Labor Hours:	1.10
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**73.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52400877
Invoice No. 55345 - 52400877

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 223,455 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-19	Gaspard,Ronald	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 5, 2019 11:42:12 PM	No	
20 - Miles			RGASPARD	Jun 5, 2019 11:42:12 PM	No	
30 - Kilometers			RGASPARD	Jun 5, 2019 11:42:12 PM	No	
40 - Hours			RGASPARD	Jun 5, 2019 11:42:12 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52400877 Total	
Parts:	1.96
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52431058
Invoice No. 55345 - 52431058

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
INTERIOR LIGHT IS DIM		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	220,655 - DH

Chronology		
Reported	May 14, 2019 11:42:00 PM	May 14, 2019 11:42:00 PM
Started	May 14, 2019 12:00:00 AM	
Completed	May 14, 2019 11:53:00 PM	May 14, 2019 11:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: INTERIOR LIGHT IS DIM

Cause: L.E.D INTERIOR LIGHT IS NO GOOD DUE TO NORMAL USAGE

Correction: REMOVE AND REPLACE L.E.D. LIGHT
PART 3976389 QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-19	Owens,Arthur	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 14-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	May 14, 2019 11:52:39 PM	No	
20 - Miles			AOWENS	May 14, 2019 11:52:39 PM	No	
30 - Kilometers			AOWENS	May 14, 2019 11:52:39 PM	No	
40 - Hours			AOWENS	May 14, 2019 11:52:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52431058
Invoice No. 55345 - 52431058

Client Department:
Department: 55345M
Work Order Description
INTERIOR LIGHT IS DIM
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 220,655 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: INTERIOR LIGHT DIM
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-May-19	3974891	OUT OF SERVICE LAMP, INTERIOR, LED	1	21.6	21.6

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-19	Owens,Arthur	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	21.60
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**86.60**

Work Order Footer

Work Order 52431058 Total	
Parts:	21.60
Labor:	78.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**99.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52300269
Invoice No. 55345 - 52300269

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,224 - DH

Chronology		
Reported	May 3, 2019 11:03:27 AM	May 3, 2019 11:03:27 AM
Started	May 3, 2019 12:00:00 AM	
Completed	May 3, 2019 10:56:00 PM	May 3, 2019 10:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 03-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,631 - Tread Depth RF	4 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,135 - Brake Rotor LF	39.68 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,136 - Brake Rotor RF	39.71 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,137 - Brake Rotor LR	35.82 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,138 - Brake Rotor RR	35.87 Inch		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	May 3, 2019 10:34:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52400872
Invoice No. 55345 - 52400872

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replaced front tires		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,224 - DH

Chronology

Reported	May 3, 2019 10:47:15 PM	May 3, 2019 10:47:15 PM
Started	May 3, 2019 12:00:00 AM	
Completed	May 3, 2019 10:56:00 PM	May 3, 2019 10:56:00 PM
Down Time		

Work Order Notes

Line 10 Mount and balanced 2 front tires
Torqued wheels to 140ftlb test driven and retorqued

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 03-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
30 - Kilometers			VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	
40 - Hours			VAMRITTEEMAL	May 3, 2019 10:50:08 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52300269
Invoice No. 55345 - 52300269

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 219,224 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 03-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	May 3, 2019 10:34:46 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	97.50
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**99.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52400872
Invoice No. 55345 - 52400872

Client Department:
Department: 55345M
Work Order Description
Replaced front tires
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,224 - DH

Activity Header
Activity:20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-May-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.47	240.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	240.94
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**305.94**

Work Order Footer

Work Order 52400872 Total	
Parts:	240.94
Labor:	82.33
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**323.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52300269
Invoice No. 55345 - 52300269

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,224 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 03-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
20 - Miles			VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
30 - Kilometers			VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	
40 - Hours			VAMRITTEEMAL	May 3, 2019 10:22:35 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52300269 Total	
Parts:	1.96
Labor:	179.83
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**181.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52367888
Invoice No. 55345 - 52367888

Client Department:
Department: 55345M
Work Order Description
Replaced front a/c resistor
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,842 - DH

Chronology		
Reported	Apr 23, 2019 3:08:05 PM	Apr 23, 2019 3:08:05 PM
Started	Apr 23, 2019 12:00:00 AM	
Completed	Apr 23, 2019 10:58:00 PM	Apr 23, 2019 10:58:00 PM
Down Time		

Work Order Notes

Line 10 Driver stated a/c only blows on high
Replaced front a/c resistor

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 23-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
30 - Kilometers			VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	
40 - Hours			VAMRITTEEMAL	Apr 23, 2019 3:11:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52367888
Invoice No. 55345 - 52367888

Client Department:
Department: 55345M
Work Order Description
Replaced front a/c resistor
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,842 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Apr-19	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	17.83	17.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Apr-19	AMRIT TEEMAL,VISHNU	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	17.83
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.33**

Work Order Footer

Work Order 52367888 Total	
Parts:	17.83
Labor:	49.83
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52202373
Invoice No. 55345 - 52202373

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	214,836 - DH

Chronology		
Reported	Mar 29, 2019 12:30:44 PM	Mar 29, 2019 12:30:44 PM
Started	Mar 31, 2019 12:00:00 AM	
Completed	Mar 31, 2019 5:38:00 PM	Mar 31, 2019 5:38:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMB Service.

CAUSE: Service Due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries. Replace two front clearance light.
Parts #B329 Qty (1)
Oil 5W20QTY (6.5) Qt.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-19	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 31-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				5:30:33 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:30:33 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,420 - Check Hood	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			5:30:33 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			5:30:33 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				5:30:33 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,135 - Brake Rotor LF	1.555 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,138 - Brake Rotor RR	1.416 Inch		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Mar 31, 2019 5:30:33 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Mar 31, 2019 5:30:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52202373
Invoice No. 55345 - 52202373

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,836 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Mar-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 31-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 31, 2019 5:31:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Mar 31, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				5:31:56 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Mar 31, 2019 5:31:56 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Mar 31, 2019 5:31:56 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Mar 31, 2019 5:31:56 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52202373
Invoice No. 55345 - 52202373

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 214,836 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 31-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 31, 2019 5:32:51 PM	No	
20 - Miles			DARTHURS	Mar 31, 2019 5:32:51 PM	No	
30 - Kilometers			DARTHURS	Mar 31, 2019 5:32:51 PM	No	
40 - Hours			DARTHURS	Mar 31, 2019 5:32:51 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52202373 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52237366
Invoice No. 55345 - 52237366

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Heather hose		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,876 - DH

Chronology		
Reported	Mar 8, 2019 11:10:17 PM	Mar 8, 2019 11:10:17 PM
Started	Mar 8, 2019 12:00:00 AM	
Completed	Mar 8, 2019 11:57:00 PM	Mar 8, 2019 11:57:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: coolant leak

Cause: Heather hose leaking

Correction: Remove &Replace Heather hose. & Refill radiator
Parts# BC2Z-18472DA Qty (1)
Parts# BC2Z-18472-CA Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 8, 2019 11:46:39 PM	No	
20 - Miles			DARTHURS	Mar 8, 2019 11:46:39 PM	No	
30 - Kilometers			DARTHURS	Mar 8, 2019 11:46:39 PM	No	
40 - Hours			DARTHURS	Mar 8, 2019 11:46:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52237366
Invoice No. 55345 - 52237366

Client Department:
Department: 55345M
Work Order Description
Heather hose
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 211,876 - DH

Activity Header
Activity: 15 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.05	59.05
08-Mar-19	BC2Z-18472-DA	TUBE, HEATER, WATER	1	55.95	55.95
11-Mar-19	BC2Z-18472-DA	TUBE, HEATER, WATER	-1	55.95	-55.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-19	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	115.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.00**

Work Order Footer

Work Order 52237366 Total	
Parts:	115.00
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52221845
Invoice No. 55345 - 52221845

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs left front tire		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,254 - DH

Chronology		
Reported	Mar 4, 2019 11:56:42 PM	Mar 4, 2019 11:56:42 PM
Started	Mar 5, 2019 12:00:00 AM	
Completed	Mar 5, 2019 12:09:00 AM	Mar 5, 2019 12:09:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs left front tire

Cause: nail in side wall

Correction:replaced left front tire and balance
Torque wheel 140 lbs second torque 140 lbs
Part number 002760 Qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Mar-19	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 4, 2019 11:59:15 PM	No	
20 - Miles			RGASPARD	Mar 4, 2019 11:59:15 PM	No	
30 - Kilometers			RGASPARD	Mar 4, 2019 11:59:15 PM	No	
40 - Hours			RGASPARD	Mar 4, 2019 11:59:15 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52221845
Invoice No. 55345 - 52221845

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs left front tire		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,254 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs left front tire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Mar-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	1	108.36	108.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Mar-19	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	108.36
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**108.36**

Work Order Footer

Work Order 52221845 Total	
Parts:	108.36
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**108.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52207655
Invoice No. 55345 - 52207655

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle has a vibration		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,574 - DH

Chronology		
Reported	Feb 27, 2019 1:56:24 PM	Feb 27, 2019 1:56:24 PM
Started	Feb 27, 2019 12:00:00 AM	
Completed	Feb 27, 2019 2:50:05 PM	Feb 27, 2019 2:50:05 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle has a vibration

Cause: check front tires found they¿re out round causing the vehicle to vibrate

Correction:replaced both front tires road test vehicle ok at this time

Parts:
2 new tires 002-760

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 27-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
20 - Miles			JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
30 - Kilometers			JAPEREZ	Feb 27, 2019 2:04:37 PM	No	
40 - Hours			JAPEREZ	Feb 27, 2019 2:04:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52207655
Invoice No. 55345 - 52207655

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Vehicle has a vibration		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,574 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Vehicle has a vibration
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Feb-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	2	108.36	216.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-19	Perez,Javier	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order Footer

Work Order 52207655 Total	
Parts:	216.72
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52111085
Invoice No. 55345 - 52111085

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,406 - DH

Chronology		
Reported	Feb 25, 2019 8:06:37 AM	Feb 25, 2019 8:06:37 AM
Started	Feb 25, 2019 12:00:00 AM	
Completed	Feb 26, 2019 9:33:00 AM	Feb 26, 2019 9:33:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA

CAUSE: Preventive Maintenance

CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,420 - Check Hood	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,631 - Tread Depth RF	14 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,632 - Tread Depth LF	14 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch	need front brake pads	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,135 - Brake Rotor LF	1.3 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,136 - Brake Rotor RF	1.3 Inch	need front rotors	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Feb 25, 2019 1:27:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Feb 25, 2019 1:27:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52111085
Invoice No. 55345 - 52111085

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,406 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-19	P9600	FILTER, OIL SEE LF16424	1	3.45	3.45
26-Feb-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 25, 2019 1:28:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 25, 2019 1:28:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 25, 2019 1:28:08 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	5.41
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52111085
Invoice No. 55345 - 52111085

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,406 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
20 - Miles			HPIERRE	Feb 25, 2019 1:30:01 PM	No	
30 - Kilometers	6		HPIERRE	Feb 25, 2019 1:30:01 PM	No	
40 - Hours	6		HPIERRE	Feb 25, 2019 1:30:01 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52111085 Total	
Parts:	5.41
Labor:	0.00
Labor Hours:	6.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52199706
Invoice No. 55345 - 52199706

Client Department:
Department: 55345M
Work Order Description
Pma follow up need front brake pads and rotors
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 210,406 - DH

Chronology		
Reported	Feb 25, 2019 1:32:21 PM	Feb 25, 2019 1:32:21 PM
Started	Feb 25, 2019 12:00:00 AM	
Completed	Feb 26, 2019 9:03:08 AM	Feb 26, 2019 9:03:08 AM
Down Time		

Work Order Notes

Line 10 PmA follow up need need front brake pads and rotors

Preventive maintenance

Replaced Front rotors seals bearings and front pads completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
20 - Miles			HPIERRE	Feb 25, 2019 1:41:36 PM	No	
30 - Kilometers	4		HPIERRE	Feb 25, 2019 1:41:36 PM	No	
40 - Hours	5		HPIERRE	Feb 25, 2019 1:41:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52199706
Invoice No. 55345 - 52199706

Client Department:
Department: 55345M
Work Order Description
Pma follow up need front brake pads and rotors
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 210,406 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note: Front Brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Feb-19	CR24000	SEAL, WHEEL, HUB, FRONT	2	6.92	13.84
25-Feb-19	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	7.44	14.88
25-Feb-19	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	4	112.53	450.12
25-Feb-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	42.88	42.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Feb-19	Pierre,Hubert J	0.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	521.72
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**521.72**

Work Order Footer

Work Order 52199706 Total	
Parts:	521.72
Labor:	0.00
Labor Hours:	5.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**521.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52144251
Invoice No. 55345 - 52144251

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear A/C		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	207,682 - DH

Chronology		
Reported	Feb 5, 2019 7:32:18 PM	Feb 5, 2019 7:32:18 PM
Started	Feb 5, 2019 12:00:00 AM	
Completed	Feb 5, 2019 9:26:00 PM	Feb 5, 2019 9:26:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear A/C

Cause: Rear A/C Condenser high Pressure hose leaking.

Correction:Remove Rear A/C condenser hose from condenser to service port & Replace. Replace rear Orifice tube . Add (4) Oz pag Oil Recharge. A/ C (7.5) lbs Freon Replace A/C filter.
Parts# 3411885 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 5, 2019 8:04:43 PM	No	
20 - Miles			DARTHURS	Feb 5, 2019 8:04:43 PM	No	
30 - Kilometers			DARTHURS	Feb 5, 2019 8:04:43 PM	No	
40 - Hours			DARTHURS	Feb 5, 2019 8:04:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52144251
Invoice No. 55345 - 52144251

Client Department:
Department: 55345M
Work Order Description
Rear A/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 207,682 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Feb-19	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
13-Feb-19	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	26.66	26.66
13-Feb-19	9C2Z-19893-AC	LOUVER, DASH, CENTER	1	39.88	39.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-19	Arthurs,Durvin	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	67.29
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.29**

Work Order Footer

Work Order 52144251 Total	
Parts:	67.29
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52111052
Invoice No. 55345 - 52111052

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear brakes		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,083 - DH

Chronology		
Reported	Jan 24, 2019 10:27:18 PM	Jan 24, 2019 10:27:18 PM
Started	Jan 24, 2019 12:00:00 AM	
Completed	Jan 24, 2019 10:57:00 PM	Jan 24, 2019 10:57:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 24, 2019 10:28:35 PM	No	
20 - Miles			DARTHURS	Jan 24, 2019 10:28:35 PM	No	
30 - Kilometers			DARTHURS	Jan 24, 2019 10:28:35 PM	No	
40 - Hours			DARTHURS	Jan 24, 2019 10:28:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52033776
Invoice No. 55345 - 52033776

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,083 - DH

Chronology		
Reported	Jan 24, 2019 12:29:04 PM	Jan 24, 2019 12:29:04 PM
Started	Jan 24, 2019 12:00:00 AM	
Completed	Jan 24, 2019 10:57:00 PM	Jan 24, 2019 10:57:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE:Service Due by Mileage.

CORRECTION: Change Oil& Filter. Lube all Pivoting Points.check Brakes. Clean batteries. Replace Air Filter. Replace drain plugs
Parts#B329 Qty (1)
Parts#PA4075 Qty (1)
Parts#65266 Qty (1)
Oil 5W20QTY Qty (6.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 24-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		DARTHURS	Jan 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				10:18:20 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:18:20 PM		
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate	No	NA	DARTHURS	Jan 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
with a Yes or No)				10:18:20 PM		
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,614 - Air Pressure RRI	65 Pounds per		DARTHURS	Jan 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:18:20 PM		
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,670 - Check Dual Mating With Square	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
70,780 - Check Driveline, U-joint and Slip	Done		DARTHURS	Jan 24, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Yokes				10:18:20 PM		
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,135 - Brake Rotor LF	1.553 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,136 - Brake Rotor RF	1.553 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,138 - Brake Rotor RR	1.415 Inch		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 24, 2019 10:18:20 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 24, 2019 10:18:20 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52111052
Invoice No. 55345 - 52111052

Client Department:
Department: 55345M
Work Order Description
Rear brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 206,083 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-19	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order Footer

Work Order 52111052 Total	
Parts:	46.22
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52033776
Invoice No. 55345 - 52033776

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 206,083 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
24-Jan-19	65266	PLUG, DRAIN, OIL, ENGINE	1	5.79	5.79
24-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 24-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 24, 2019 10:19:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jan 24, 2019 10:19:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 24, 2019 10:19:17 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	13.03
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52033776
Invoice No. 55345 - 52033776

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 206,083 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 24, 2019 10:20:02 PM	No	
20 - Miles			DARTHURS	Jan 24, 2019 10:20:02 PM	No	
30 - Kilometers			DARTHURS	Jan 24, 2019 10:20:02 PM	No	
40 - Hours			DARTHURS	Jan 24, 2019 10:20:02 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52033776 Total	
Parts:	13.03
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.03**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52045248
Invoice No. 55345 - 52045248

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 Transmission DTC P-0713		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	203,025 - DH

Chronology		
Reported	Jan 4, 2019 10:47:27 AM	Jan 4, 2019 10:47:27 AM
Started	Jan 4, 2019 12:00:00 AM	
Completed	Jan 4, 2019 2:53:20 PM	Jan 4, 2019 2:53:20 PM
Down Time		

Work Order Notes

Line 10

Complaint.P0713 Transmission Check engine light is on.

Cause.Found P0713 code Transmission Temperature sensor

Correction.Drain Transmission. Removed trans oil pan, oil filter, Valve body, valve body harness, temperature sensor, and valve body gasket.

Installed a new valve body gasket, harness, temperature sensor, and transmission oil filter. Washed oil pan, in the parts washer. Dried oil pan and installed back onto transmission. Tightened drain plug.

Filled transmission with 9.8 Qts of transmission fluid. Ran vehicle for about 15 mins. Change transmission through all the gears. Checked transmission oil level, it¿s on the full line. Test drove and then I checked transmission level again. At this time, transmission is shifting properly.

Placed back in service.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 04-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
20 - Miles			RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	
40 - Hours			RAURODRIGUEZ	Jan 4, 2019 11:05:21 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52045248
Invoice No. 55345 - 52045248

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 Transmission DTC P-0713		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	203,025 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jan-19	8C3Z-7A194-B	PAN, OIL, TRANSMISSION	1	56.44	56.44
04-Jan-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	-1	109.68	-109.68
04-Jan-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	109.68	109.68
04-Jan-19	F6TZ-7A191-A	GASKET, PAN, OIL, TRANSMISSION, 4R100	1	30.6	30.6
04-Jan-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	10.14	10.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-19	Rodriguez,Raul	2.2333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	206.86
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.86**

Work Order Footer

Work Order 52045248 Total	
Parts:	206.86
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52039775
Invoice No. 55345 - 52039775

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs lift belt retractor		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,758 - DH

Chronology		
Reported	Jan 2, 2019 11:51:15 PM	Jan 2, 2019 11:51:15 PM
Started	Jan 2, 2019 12:00:00 AM	
Completed	Jan 2, 2019 11:56:00 PM	Jan 2, 2019 11:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs lift belt retractor

Cause: broken

Correction:replaced lift belt retractor
Part number 31579KS Qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-19	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 2, 2019 11:54:03 PM	No	
20 - Miles			RGASPARD	Jan 2, 2019 11:54:03 PM	No	
30 - Kilometers			RGASPARD	Jan 2, 2019 11:54:03 PM	No	
40 - Hours			RGASPARD	Jan 2, 2019 11:54:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52039775
Invoice No. 55345 - 52039775

Client Department:
Department: 55345M
Work Order Description
Needs lift belt retractor
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,758 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Needs lift belt retractor
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-19	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 52039775 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52030145
Invoice No. 55345 - 52030145

Client Department:
Department: 55345M
Work Order Description
Pmc follow up need rear tires
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 202,105 - DH

Chronology		
Reported	Dec 28, 2018 12:25:15 PM	Dec 28, 2018 12:25:15 PM
Started	Dec 28, 2018 12:00:00 AM	
Completed	Dec 31, 2018 10:02:15 AM	Dec 31, 2018 10:02:15 AM
Down Time		

Work Order Notes

Line 10 Pmc follow up need rear tires

Normal wear

Replace all rear tires mounted and balanced completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Dec-18	Pierre,Hubert J	4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 28-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
20 - Miles			HPIERRE	Dec 28, 2018 12:27:44 PM	No	
30 - Kilometers	7		HPIERRE	Dec 28, 2018 12:27:44 PM	No	
40 - Hours	6		HPIERRE	Dec 28, 2018 12:27:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52030145
Invoice No. 55345 - 52030145

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Pmc follow up need rear tires		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,105 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Dec-18	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	4	108.36	433.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Dec-18	Pierre,Hubert J	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	433.44
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**433.44**

Work Order Footer

Work Order 52030145 Total	
Parts:	433.44
Labor:	0.00
Labor Hours:	4.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**433.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51953538
Invoice No. 55345 - 51953538

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,105 - DH

Chronology		
Reported	Dec 28, 2018 8:15:28 AM	Dec 28, 2018 8:15:28 AM
Started		
Completed	Dec 31, 2018 8:48:00 AM	Dec 31, 2018 8:48:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all Pivoting Points cross Rotate Tires completed

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 28-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,420 - Check Hood	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,670 - Check Dual Mating With Square	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Dec 28, 2018 11:59:44 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Dec 28, 2018 11:59:44 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51953538
Invoice No. 55345 - 51953538

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,105 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-18	P9600	FILTER, OIL SEE LF16424	1	3.45	3.45

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 28-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Dec 28, 2018 12:02:02 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Dec 28, 2018 12:02:02 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/a	HPIERRE	Dec 28, 2018 12:02:02 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	N/A	HPIERRE	Dec 28, 2018 12:02:02 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Dec 28, 2018 12:02:02 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	3.45
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51953538
Invoice No. 55345 - 51953538

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,105 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 28-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
20 - Miles			HPIERRE	Dec 28, 2018 12:04:01 PM	No	
30 - Kilometers	8		HPIERRE	Dec 28, 2018 12:04:01 PM	No	
40 - Hours	6		HPIERRE	Dec 28, 2018 12:04:01 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51953538 Total	
Parts:	3.45
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51863175
Invoice No. 55345 - 51863175

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	198,090 - DH

Chronology		
Reported	Nov 30, 2018 11:55:19 AM	Nov 30, 2018 11:55:19 AM
Started	Nov 30, 2018 12:00:00 AM	
Completed	Nov 30, 2018 11:55:00 PM	Nov 30, 2018 11:55:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 30, 2018 11:08:47 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 30, 2018 11:08:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51863175
Invoice No. 55345 - 51863175

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 198,090 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Gaspard,Ronald	1.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 30, 2018 11:09:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 30, 2018 11:09:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 30, 2018 11:09:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 30, 2018 11:09:37 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 30, 2018 11:09:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 30, 2018 11:09:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 30, 2018 11:09:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 30, 2018 11:09:37 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51863175
Invoice No. 55345 - 51863175

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 198,090 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 30, 2018 11:10:14 PM	No	
20 - Miles			RGASPARD	Nov 30, 2018 11:10:14 PM	No	
30 - Kilometers			RGASPARD	Nov 30, 2018 11:10:14 PM	No	
40 - Hours			RGASPARD	Nov 30, 2018 11:10:14 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51863175 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51862388
Invoice No. 55345 - 51862388

Client Department:
Department: 55345M
Work Order Description
Front and rear brakes
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 194,051 - DH

Chronology		
Reported	Oct 30, 2018 11:04:01 PM	Oct 30, 2018 11:04:01 PM
Started	Oct 30, 2018 12:00:00 AM	
Completed	Oct 31, 2018 10:52:08 AM	Oct 31, 2018 10:52:08 AM
Down Time		

Work Order Notes

Line 10 Replaced front brakes
Replaced rear brakes
Part# 8C2Z-2V001-D
Part# 9C2Z-2V200-B

Activity Header
Activity: 10 013/000/000 BRAKES
Activity Note: Front brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Oct-18	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	48.87
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51862388
Invoice No. 55345 - 51862388

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front and rear brakes		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,051 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note: Rear brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Oct-18	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.33	46.33

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	46.33
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51862388
Invoice No. 55345 - 51862388

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front and rear brakes		Ford E350 Champion Crusaders	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,051 - DH

Activity Header
Activity: 30 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 30-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
20 - Miles			VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 30, 2018 11:11:34 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51862388 Total	
Parts:	95.20
Labor:	0.00
Labor Hours:	3.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51763257
Invoice No. 55345 - 51763257

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,051 - DH

Chronology		
Reported	Oct 30, 2018 4:05:21 PM	Oct 30, 2018 4:05:21 PM
Started	Oct 30, 2018 12:00:00 AM	
Completed	Oct 31, 2018 8:17:00 AM	Oct 31, 2018 8:17:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Preventive Maintenance

CORRECTION: Performed and completed PMA Service
Part# B329 Qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 30-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,133 - Brake Pad Thickness LR	5 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,134 - Brake Pad Thickness RR	5 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,135 - Brake Rotor LF	39.27 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,136 - Brake Rotor RF	39.21 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,137 - Brake Rotor LR	35.73 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,138 - Brake Rotor RR	35.65 Inch		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Oct 30, 2018 10:54:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51763257
Invoice No. 55345 - 51763257

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,051 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Oct-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 30-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Oct 30, 2018 10:55:55 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51763257
Invoice No. 55345 - 51763257

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,051 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 30-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
20 - Miles			VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 30, 2018 10:42:08 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51763257 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51762245
Invoice No. 55345 - 51762245

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs left front tire		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,574 - DH

Chronology		
Reported	Sep 27, 2018 11:18:44 PM	Sep 27, 2018 11:18:44 PM
Started	Sep 27, 2018 12:00:00 AM	
Completed	Sep 28, 2018 9:59:54 AM	Sep 28, 2018 9:59:54 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs left front tire

Cause: low tread

Correction:1 tire mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part number 189752 qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-18	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 27, 2018 11:21:20 PM	No	
20 - Miles			RGASPARD	Sep 27, 2018 11:21:20 PM	No	
30 - Kilometers			RGASPARD	Sep 27, 2018 11:21:20 PM	No	
40 - Hours			RGASPARD	Sep 27, 2018 11:21:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51762245
Invoice No. 55345 - 51762245

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs left front tire		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,574 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs left front tire
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-18	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51762245 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51669025
Invoice No. 55345 - 51669025

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 189,729 - DH

Chronology		
Reported	Sep 27, 2018 2:29:07 PM	Sep 27, 2018 2:29:07 PM
Started	Sep 27, 2018 12:00:00 AM	
Completed	Sep 28, 2018 9:07:07 AM	Sep 28, 2018 9:07:07 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB

CAUSE Service

CORRECTION:Perform PMB Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-18	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,632 - Tread Depth LF	5 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 27, 2018 11:13:33 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 27, 2018 11:13:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51669025
Invoice No. 55345 - 51669025

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 189,729 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 27-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 27, 2018 11:14:54 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 27, 2018 11:14:54 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Sep 27, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:14:54 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 27, 2018 11:14:54 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 27, 2018 11:14:54 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51669025
Invoice No. 55345 - 51669025

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 189,729 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 27, 2018 11:15:18 PM	No	
20 - Miles			RGASPARD	Sep 27, 2018 11:15:18 PM	No	
30 - Kilometers			RGASPARD	Sep 27, 2018 11:15:18 PM	No	
40 - Hours			RGASPARD	Sep 27, 2018 11:15:18 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51669025 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.83

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51668993
Invoice No. 55345 - 51668993

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replace transmission		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Chronology		
Reported	Aug 29, 2018 11:09:07 PM	Aug 29, 2018 11:09:07 PM
Started	Aug 30, 2018 12:00:00 AM	
Completed	Aug 30, 2018 11:09:00 PM	Aug 30, 2018 11:09:00 PM
Down Time		

Work Order Notes

Line 10 Tech scanned a P0751 code
Tech replace the trans as TSB
remain Qty1 part#19180251
Trans filter Qty1 part#20021
Planetary gear Qty1 part#3C3Z-7G299-AA
Harness Qty1 part#4C3Z-7G276-AA
Clutch forward Qty1 part#6C3Z-7A262-AA
Clutch Qty1 part#7C3Z-7G387-B
Body gasket Qty1 part#8C3Z-7C155-A
Temp sensor Qty1 part#BC3Z-7H141-A
Snap ring Qty:1 part#F81Z-7A527-AA

Tech test drove vehicle, no issues found at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 30-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 30, 2018 4:37:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			CKARLENS	Aug 30, 2018 4:37:39 PM	No	
30 - Kilometers			CKARLENS	Aug 30, 2018 4:37:39 PM	No	
40 - Hours			CKARLENS	Aug 30, 2018 4:37:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51668993
Invoice No. 55345 - 51668993

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replace transmission		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Activity Header
Activity:20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Aug-18	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	22.21	22.21
30-Aug-18	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.49	2.49
30-Aug-18	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	76.54	76.54
30-Aug-18	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.14	9.14
30-Aug-18	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	10.93	10.93
30-Aug-18	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	110.33	110.33
29-Aug-18	19180251	TRANSMISSION, REMANUFACTURED	1	340.18	340.18
30-Aug-18	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	10.32	10.32
30-Aug-18	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-18	KARLENS,Cyrius	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: CKARLENS Performed on: 30-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		CKARLENS	Aug 30, 2018 4:38:18 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	616.68
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**616.68**

Work Order Footer

Work Order 51668993 Total	
Parts:	616.68
Labor:	0.00
Labor Hours:	5.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**616.68**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51556866
Invoice No. 55345 - 51556866

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	185,508 - DH

Chronology		
Reported	Aug 29, 2018 11:28:23 AM	Aug 29, 2018 11:28:23 AM
Started	Aug 29, 2018 12:00:00 AM	
Completed	Aug 29, 2018 11:35:00 PM	Aug 29, 2018 11:35:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:Perform pmA

CAUSE:Preventive Maintenance

CORRECTION:Tech Performed pmA

Part used
Oil filter Qty1 part#B329
Oil Qty:6.5

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 29-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,420 - Check Hood	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Aug 29, 2018 11:08:52 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Aug 29, 2018 11:08:52 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51556866
Invoice No. 55345 - 51556866

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 185,508 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Aug-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 29-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Aug 29, 2018 10:59:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Aug 29, 2018 10:59:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Aug 29, 2018 10:59:29 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	6.66
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**6.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51556866
Invoice No. 55345 - 51556866

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 185,508 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-18	KARLENS,Cyrius	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 29-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 29, 2018 10:58:39 PM	No	
20 - Miles			CKARLENS	Aug 29, 2018 10:58:39 PM	No	
30 - Kilometers			CKARLENS	Aug 29, 2018 10:58:39 PM	No	
40 - Hours			CKARLENS	Aug 29, 2018 10:58:39 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51556866 Total	
Parts:	6.66
Labor:	0.00
Labor Hours:	4.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**6.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51643903
Invoice No. 55345 - 51643903

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE RIGHT FRONT TIRE		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	184,177 - DH

Chronology		
Reported	Aug 21, 2018 11:47:00 PM	Aug 21, 2018 11:47:00 PM
Started	Aug 21, 2018 12:00:00 AM	
Completed	Aug 21, 2018 11:54:00 PM	Aug 21, 2018 11:54:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: FLAT TIRE

Cause: NAIL INSIDE SIDE WALL

Correction: MOUNT AND BALANCE NEW TIRE SET TIRE TO 65 PSI
PART# 189752 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-18	Owens,Arthur	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 21-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Aug 21, 2018 11:53:20 PM	No	
20 - Miles			AOWENS	Aug 21, 2018 11:53:20 PM	No	
30 - Kilometers			AOWENS	Aug 21, 2018 11:53:20 PM	No	
40 - Hours			AOWENS	Aug 21, 2018 11:53:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51643903
Invoice No. 55345 - 51643903

Client Department:
Department: 55345M
Work Order Description
REPLACE RIGHT FRONT TIRE
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 184,177 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: RIGHT FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Aug-18	Owens,Arthur	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51643903 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51556838
Invoice No. 55345 - 51556838

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs rear hub seal and brakes		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,414 - DH

Chronology		
Reported	Jul 31, 2018 11:51:51 PM	Jul 31, 2018 11:51:51 PM
Started	Aug 1, 2018 12:00:00 AM	
Completed	Aug 1, 2018 12:34:00 AM	Aug 1, 2018 12:34:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear hub Seal and rear brakes

Cause: wear

Correction: Replaced rear brake pads lubed guide pins and hub seal
Torque wheels 140 lbs second torque 140 lbs
Brakes part number 9C2Z-2V200-B qty1
Rear seal part number 9864S qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 01-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 1, 2018 12:34:11 AM	No	
20 - Miles			RGASPARD	Aug 1, 2018 12:34:11 AM	No	
30 - Kilometers			RGASPARD	Aug 1, 2018 12:34:11 AM	No	
40 - Hours			RGASPARD	Aug 1, 2018 12:34:11 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51556838
Invoice No. 55345 - 51556838

Client Department:
Department: 55345M
Work Order Description
Needs rear hub seal and brakes
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,414 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs rear hub sealand brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jul-18	9864S	SEAL, BEARING, INNER, WHEEL, DRIVE	1	5.33	5.33
01-Aug-18	8C2Z-2C026-A	ROTOR, BRAKE, DISC, REAR, E350 SUPERSEDED BY NC2Z-2C026-A	1	88.18	88.18
01-Aug-18	9864S	SEAL, BEARING, INNER, WHEEL, DRIVE	1	5.33	5.33
03-Aug-18	8C2Z-2C026-B	ROTOR, BRAKE, DISC, REAR, E450	1	87.98	87.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-18	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	186.82
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.82**

Work Order Footer

Work Order 51556838 Total	
Parts:	186.82
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51464421
Invoice No. 55345 - 51464421

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,414 - DH

Chronology		
Reported	Jul 31, 2018 12:44:25 PM	Jul 31, 2018 12:44:25 PM
Started	Jul 31, 2018 12:00:00 AM	
Completed	Aug 1, 2018 12:32:00 AM	Aug 1, 2018 12:32:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 31-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jul 31, 2018 11:48:34 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jul 31, 2018 11:48:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51464421
Invoice No. 55345 - 51464421

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,414 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 31-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 31, 2018 11:49:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 31, 2018 11:49:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 31, 2018 11:49:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 31, 2018 11:49:16 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 31, 2018 11:49:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 31, 2018 11:49:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 31, 2018 11:49:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 31, 2018 11:49:16 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51464421
Invoice No. 55345 - 51464421

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,414 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Jul-18	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 31, 2018 11:49:35 PM	No	
20 - Miles			RGASPARD	Jul 31, 2018 11:49:35 PM	No	
30 - Kilometers			RGASPARD	Jul 31, 2018 11:49:35 PM	No	
40 - Hours			RGASPARD	Jul 31, 2018 11:49:35 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51464421 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.87

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51463468
Invoice No. 55345 - 51463468

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 BATTERY		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,263 - DH

Chronology		
Reported	Jun 26, 2018 3:22:40 PM	Jun 26, 2018 3:22:40 PM
Started	Jun 26, 2018 12:00:00 AM	
Completed	Jun 27, 2018 9:45:34 AM	Jun 27, 2018 9:45:34 AM
Down Time		

Work Order Notes

Line 10 C:vehicle won¿t start

C:jump start vehicle, check starting system found batteries are not working properly

C: Replaced batteries and retest system ok at this time

Parts:
2 new batteries

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 26-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 26, 2018 3:28:43 PM	No	
20 - Miles			JAPEREZ	Jun 26, 2018 3:28:43 PM	No	
30 - Kilometers			JAPEREZ	Jun 26, 2018 3:28:43 PM	No	
40 - Hours			JAPEREZ	Jun 26, 2018 3:28:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51463468
Invoice No. 55345 - 51463468

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 BATTERY		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,263 - DH

Activity Header
Activity:20 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jun-18	34AGM	BATTERY, AGM, GROUP-34	2	114.74	229.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-18	Perez,Javier	1.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	229.48
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.48**

Work Order Footer

Work Order 51463468 Total	
Parts:	229.48
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**229.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51372050
Invoice No. 55345 - 51372050

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,263 - DH

Chronology		
Reported	Jun 26, 2018 10:52:41 AM	Jun 26, 2018 10:52:41 AM
Started	Jun 26, 2018 12:00:00 AM	
Completed	Jun 26, 2018 11:45:00 PM	Jun 26, 2018 11:45:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMA Service change Oil & Filter. lube all Pivoting Points. check brakes. Clean batteries.Replace A/C Filter . Replace rear door red warning light. Replace drain plugs. Change transmission oil& Filter. Per form differential . Service.
Parts#33250R3 Qty (1) Shop Supply
Parts# 20021 Qty (1)
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qt
ATF Fluid Qty (9.5) Qt
Gear Oil 80W90 Qty (3) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-18	Arthurs,Durvin	3.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 26-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,137 - Brake Rotor LR	1.416 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,138 - Brake Rotor RR	1.417 Inch		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jun 26, 2018 10:29:33 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jun 26, 2018 10:29:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51372050
Invoice No. 55345 - 51372050

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 177,263 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Jun-18	20021	FILTER, TRANSMISSION 20021	1	17.26	17.26
26-Jun-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
26-Jun-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 26-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done	Replace A/C Filter	DARTHURS	Jun 26, 2018 10:31:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jun 26, 2018 10:31:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jun 26, 2018 10:31:31 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Jun 26, 2018 10:31:31 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jun 26, 2018 10:31:31 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jun 26, 2018 10:31:31 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Jun 26, 2018 10:31:31 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	25.88
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51372050
Invoice No. 55345 - 51372050

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 177,263 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 26, 2018 10:31:57 PM	No	
20 - Miles			DARTHURS	Jun 26, 2018 10:31:57 PM	No	
30 - Kilometers			DARTHURS	Jun 26, 2018 10:31:57 PM	No	
40 - Hours			DARTHURS	Jun 26, 2018 10:31:57 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51372050 Total	
Parts:	25.88
Labor:	0.00
Labor Hours:	4.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**25.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51458146
Invoice No. 55345 - 51458146

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front AC evaporator is leaking		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,174 - DH

Chronology		
Reported	Jun 25, 2018 12:54:23 PM	Jun 25, 2018 12:54:23 PM
Started	Jun 25, 2018 12:00:00 AM	
Completed	Jun 26, 2018 8:29:00 AM	Jun 26, 2018 8:29:00 AM
Down Time		

Work Order Notes

Line 10 Front AC evaporator is leaking

Recovered the remaining Freon .53lbs and 1oz of oil.
Removed bad evaporator. Installed a new evaporator and orifice tube.

Charged system with 1.88lbs of Freon and 1.5 oz of oil.
System is now working properly.

Found that the lower front quick connector for the heater hose is broken.
Replaced the bad heater hose quick connector.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 25-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 25, 2018 1:01:34 PM	No	
20 - Miles			EDTORRES	Jun 25, 2018 1:01:34 PM	No	
30 - Kilometers			EDTORRES	Jun 25, 2018 1:01:34 PM	No	
40 - Hours			EDTORRES	Jun 25, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:01:34 PM		

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51458146
Invoice No. 55345 - 51458146

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front AC evaporator is leaking		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,174 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC evaporator is leaking
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jun-18	800-404	CONNECTOR, HOSE, HEATER, 3/4"	1	11.76	11.76
25-Jun-18	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jun-18	Torres,Edwin	3.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	12.51
Labor:	0.00
Labor Hours:	3.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.51**

Work Order Footer

Work Order 51458146 Total	
Parts:	12.51
Labor:	0.00
Labor Hours:	3.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**12.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51452233
Invoice No. 55345 - 51452233

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Battery light is lit on the cluster.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	176,894 - DH

Chronology		
Reported	Jun 22, 2018 1:02:46 PM	Jun 22, 2018 1:02:46 PM
Started	Jun 22, 2018 12:00:00 AM	
Completed	Jun 25, 2018 7:22:57 AM	Jun 25, 2018 7:22:57 AM
Down Time		

Work Order Notes

Line 10 Battery light is lit on the cluster.

Checked voltage, with load its at 13.6, without load its at 13.7.
All main wire connections are tight, including alternator pigtail.
I suspect the alternator is bad.

Replaced alternator
New alternator is putting with load 14.1 and without load14.25
As a preventive measure for future complaint, I changed out the alternator pigtail.
Charging system is now with specs, the battery light is no longer lit on cluster.
Placed vehicle back in service.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 22-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 22, 2018 1:09:33 PM	No	
20 - Miles			EDTORRES	Jun 22, 2018 1:09:33 PM	No	
30 - Kilometers			EDTORRES	Jun 22, 2018 1:09:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			EDTORRES	Jun 22, 2018 1:09:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51452233
Invoice No. 55345 - 51452233

Client Department:
Department: 55345M
Work Order Description
Battery light is lit on the cluster.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 176,894 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jun-18	GC2Z-10346-B	ALTERNATOR, E450	1	495	495
22-Jun-18	WPT118	PIGTAIL, SENSOR, CAM SAME AS 1U2Z-14S411-TA	1	36.57	36.57

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-18	Torres,Edwin	1.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	531.57
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**531.57**

Work Order Footer

Work Order 51452233 Total	
Parts:	531.57
Labor:	0.00
Labor Hours:	1.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**531.57**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51386838
Invoice No. 55345 - 51386838

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Steering box leaking oil		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,045 - DH

Chronology		
Reported	Jun 1, 2018 11:13:21 AM	Jun 1, 2018 11:13:21 AM
Started	Jun 1, 2018 12:00:00 AM	
Completed	Jun 1, 2018 1:58:56 PM	Jun 1, 2018 1:58:56 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:steering box is leaking oil

Cause: top seals leaking oil

Correction:Replaced steering box with a new update box, is warranty. Also adjust steering wheel to be straight

Part:
1 new steering box

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 01-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 1, 2018 11:22:13 AM	No	
20 - Miles			JAPEREZ	Jun 1, 2018 11:22:13 AM	No	
30 - Kilometers			JAPEREZ	Jun 1, 2018 11:22:13 AM	No	
40 - Hours			JAPEREZ	Jun 1, 2018 11:22:13 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51386838
Invoice No. 55345 - 51386838

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Steering box leaking oil		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	174,045 - DH

Activity Header
Activity: 15 015 STEERING
Activity Note: Steering box is leaking oil
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-18	Perez,Javier	4.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51386838 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51302109
Invoice No. 55345 - 51302109

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,063 - DH

Chronology		
Reported	May 24, 2018 1:16:43 PM	May 24, 2018 1:16:43 PM
Started	May 24, 2018 12:00:00 AM	
Completed	May 24, 2018 11:07:00 PM	May 24, 2018 11:07:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:perform PM-A

CAUSE: preventive maintenance

CORRECTION: tech performed PM-A
Parts used
Oil filter Qty:1 part# B328
Oil Qty:6.5qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 24-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,120 - FRA Check All Warning Lights and	Done		CKARLENS	May 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:06:49 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	May 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:06:49 PM		
20,260 - Check Stop Request System	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,420 - Check Hood	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,442 - Freeze Point	0 Degree	na	CKARLENS	May 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:06:49 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,615 - Air Pressure LRI	70 Pounds per		CKARLENS	May 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:06:49 PM		
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		CKARLENS	May 24, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:06:49 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	May 24, 2018 11:06:49 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	May 24, 2018 11:06:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51372032
Invoice No. 55345 - 51372032

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE SHIFTER CABLE		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,063 - DH

Chronology

Reported	May 24, 2018 10:49:49 PM	May 24, 2018 10:49:49 PM
Started	May 24, 2018 12:00:00 AM	
Completed	May 24, 2018 11:07:00 PM	May 24, 2018 11:07:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced shifter cable
Part # 8C2Z-7E395-A Qty1

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	KARLENS,Cyrius	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 24, 2018 10:52:51 PM	No	
20 - Miles			CKARLENS	May 24, 2018 10:52:51 PM	No	
30 - Kilometers			CKARLENS	May 24, 2018 10:52:51 PM	No	
40 - Hours			CKARLENS	May 24, 2018 10:52:51 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.35

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51302109
Invoice No. 55345 - 51302109

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 173,063 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-May-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 24-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	May 24, 2018 10:41:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	May 24, 2018 10:41:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	May 24, 2018 10:41:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	May 24, 2018 10:41:00 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	May 24, 2018 10:41:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	May 24, 2018 10:41:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	May 24, 2018 10:41:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	May 24, 2018 10:41:00 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51372032
Invoice No. 55345 - 51372032

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE SHIFTER CABLE		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	173,063 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: REPLACE SHIFTER CABLE
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-May-18	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	44.69	44.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	KARLENS,Cyrius	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	44.69
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.69**

Work Order Footer

Work Order 51372032 Total	
Parts:	44.69
Labor:	0.00
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51302109
Invoice No. 55345 - 51302109

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 173,063 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-18	KARLENS,Cyrius	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 24, 2018 10:40:34 PM	No	
20 - Miles			CKARLENS	May 24, 2018 10:40:34 PM	No	
30 - Kilometers			CKARLENS	May 24, 2018 10:40:34 PM	No	
40 - Hours			CKARLENS	May 24, 2018 10:40:34 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51302109 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.35

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51360916
Invoice No. 55345 - 51360916

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 172,167 - DH

Chronology		
Reported	May 20, 2018 1:07:52 PM	May 20, 2018 1:07:52 PM
Started	May 21, 2018 12:00:00 AM	
Completed	May 21, 2018 11:10:00 PM	May 21, 2018 11:10:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: broken mirror.

Cause: Driver stated that mirror was hit by an other car.

Correction: Tech Replace mirror

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-May-18	KARLENS,Cyrius	0.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 21-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 21, 2018 3:34:27 PM	No	
20 - Miles			CKARLENS	May 21, 2018 3:34:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			CKARLENS	May 21, 2018 3:34:27 PM	No	
40 - Hours			CKARLENS	May 21, 2018 3:34:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51360916
Invoice No. 55345 - 51360916

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 172,167 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL/Replace driver mirror
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51360916 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51302061
Invoice No. 55345 - 51302061

Client Department:
Department: 55345M
Work Order Description
Needs 2 new tires and rear hub seal
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,100 - DH

Chronology		
Reported	Apr 27, 2018 11:44:10 PM	Apr 27, 2018 11:44:10 PM
Started	Apr 27, 2018 12:00:00 AM	
Completed	Apr 27, 2018 11:58:00 PM	Apr 27, 2018 11:58:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs 2 new tires and rear hub seal

Cause: wear

Correction:2 new tires mounted and balance
Rotate tires and washed rims
Replaced left rear hub seal
Torque wheels 140 lbs second torque 140 lbs
Tires part number 189752 qty2
Rear hub seal part number 9864S qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 27, 2018 11:46:12 PM	No	
20 - Miles			RGASPARD	Apr 27, 2018 11:46:12 PM	No	
30 - Kilometers			RGASPARD	Apr 27, 2018 11:46:12 PM	No	
40 - Hours			RGASPARD	Apr 27, 2018 11:46:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51144156
Invoice No. 55345 - 51144156

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,100 - DH

Chronology		
Reported	Apr 27, 2018 1:59:22 PM	Apr 27, 2018 1:59:22 PM
Started	Apr 27, 2018 12:00:00 AM	
Completed	Apr 27, 2018 11:58:00 PM	Apr 27, 2018 11:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,420 - Check Hood	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,636 - Tread Depth LRO	2 32nds of an inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Apr 27, 2018 11:40:32 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Apr 27, 2018 11:40:32 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51302061
Invoice No. 55345 - 51302061

Client Department:
Department: 55345M
Work Order Description
Needs 2 new tires and rear hub seal
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,100 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Apr-18	9864S	SEAL, BEARING, INNER, WHEEL, DRIVE	1	7.83	7.83
27-Apr-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-18	Gaspard,Ronald	2.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	214.71
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.71**

Work Order Footer

Work Order 51302061 Total	
Parts:	214.71
Labor:	0.00
Labor Hours:	2.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51144156
Invoice No. 55345 - 51144156

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,100 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Apr-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-18	Gaspard,Ronald	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 27, 2018 11:41:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 27, 2018 11:41:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 27, 2018 11:41:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 27, 2018 11:41:13 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Apr 27, 2018 11:41:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 27, 2018 11:41:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Apr 27, 2018 11:41:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 27, 2018 11:41:13 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.07
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51144156
Invoice No. 55345 - 51144156

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,100 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 27, 2018 11:41:33 PM	No	
20 - Miles			RGASPARD	Apr 27, 2018 11:41:33 PM	No	
30 - Kilometers			RGASPARD	Apr 27, 2018 11:41:33 PM	No	
40 - Hours			RGASPARD	Apr 27, 2018 11:41:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51144156 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.87

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51222358
Invoice No. 55345 - 51222358

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 Transmission DTC P-0713		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,765 - DH

Chronology		
Reported	Apr 13, 2018 7:36:15 AM	Apr 13, 2018 7:36:15 AM
Started	Apr 13, 2018 12:00:00 AM	
Completed	Apr 13, 2018 9:50:16 AM	Apr 13, 2018 9:50:16 AM
Down Time		

Work Order Notes

Line 10 Transmission D TC P-0713

Bad wire harness

Replace wire harness add fluids completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-18	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 13-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 13, 2018 8:12:38 AM	No	
20 - Miles			HPIERRE	Apr 13, 2018 8:12:38 AM	No	
30 - Kilometers			HPIERRE	Apr 13, 2018 8:12:38 AM	No	
40 - Hours			HPIERRE	Apr 13, 2018 8:12:38 AM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	6.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51222358
Invoice No. 55345 - 51222358

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 Transmission DTC P-0713		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,765 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Apr-18	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	11.83	11.83
13-Apr-18	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	114.91	114.91
13-Apr-18	20021	FILTER, TRANSMISSION 20021	1	17.24	17.24
13-Apr-18	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	10.63	10.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	154.61
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**154.61**

Work Order Footer

Work Order 51222358 Total	
Parts:	154.61
Labor:	0.00
Labor Hours:	6.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**154.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51197640
Invoice No. 55345 - 51197640

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Replace passenger front tire		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,264 - DH

Chronology		
Reported	Apr 8, 2018 11:20:40 AM	Apr 8, 2018 11:20:40 AM
Started	Apr 8, 2018 12:00:00 AM	
Completed	Apr 9, 2018 8:15:00 AM	Apr 9, 2018 8:15:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:driver reported that the tire is low on pressure

Cause: nail in tire

Correction: Tech Replace Tire to save time
Part used
Tire Qty:1 part#189752

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-18	KARLENS,Cyrius	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 08-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 8, 2018 11:26:53 AM	No	
20 - Miles			CKARLENS	Apr 8, 2018 11:26:53 AM	No	
30 - Kilometers			CKARLENS	Apr 8, 2018 11:26:53 AM	No	
40 - Hours			CKARLENS	Apr 8, 2018 11:26:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51197640
Invoice No. 55345 - 51197640

Client Department:
Department: 55345M
Work Order Description
Replace passenger front tire
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 166,264 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Replace passenger front tire
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Apr-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	1	103.44	103.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-18	KARLENS,Cyrius	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order Footer

Work Order 51197640 Total	
Parts:	103.44
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**103.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51164897
Invoice No. 55345 - 51164897

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 HEADLIGHTS		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,459 - DH

Chronology		
Reported	Apr 2, 2018 11:53:09 AM	Apr 2, 2018 11:53:09 AM
Started		
Completed	Apr 3, 2018 8:15:57 AM	Apr 3, 2018 8:15:57 AM
Down Time		

Work Order Notes

Line 10 Headlight D

COMPLAINT:
Driver side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced driverside headlight bulb.

PARTS:
Under shop supply

Activity Header
Activity: 10 034/001/000 HEADLAMP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51164897
Invoice No. 55345 - 51164897

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
55345 HEADLIGHTS		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	165,459 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 02-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Apr 2, 2018 12:06:03 PM	No	
20 - Miles			EDTORRES	Apr 2, 2018 12:06:03 PM	No	
30 - Kilometers			EDTORRES	Apr 2, 2018 12:06:03 PM	No	
40 - Hours			EDTORRES	Apr 2, 2018 12:06:03 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51164897 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51068137
Invoice No. 55345 - 51068137

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 164,982 - DH

Chronology		
Reported	Mar 28, 2018 9:55:47 AM	Mar 28, 2018 9:55:47 AM
Started	Mar 28, 2018 12:00:00 AM	
Completed	Mar 28, 2018 11:02:00 PM	Mar 28, 2018 11:02:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:Service

CORRECTION:perform pmB Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-18	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 28-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,137 - Brake Rotor LR	36 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,138 - Brake Rotor RR	36 Inch		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 28, 2018 9:54:14 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 28, 2018 9:54:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51068137
Invoice No. 55345 - 51068137

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 164,982 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Mar-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-18	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 28-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 28, 2018 9:55:14 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 28, 2018 9:55:14 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Mar 28, 2018 9:55:14 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Mar 28, 2018 9:55:14 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51068137
Invoice No. 55345 - 51068137

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	164,982 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-18	Gaspard,Ronald	0.2166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 28-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 28, 2018 9:55:38 PM	No	
20 - Miles			RGASPARD	Mar 28, 2018 9:55:38 PM	No	
30 - Kilometers			RGASPARD	Mar 28, 2018 9:55:38 PM	No	
40 - Hours			RGASPARD	Mar 28, 2018 9:55:38 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51068137 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.83

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51068114
Invoice No. 55345 - 51068114

Client Department:
Department: 55345M
Work Order Description
Follow------> (51019917)Vehicle needed rear and front brakes/ air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,004 - DH

Chronology		
Reported	Feb 28, 2018 11:05:21 PM	Feb 28, 2018 11:05:21 PM
Started	Feb 28, 2018 12:00:00 AM	
Completed	Feb 28, 2018 11:30:00 PM	Feb 28, 2018 11:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Replace front/ rear brake pads and air filter

Cause: wear and tear

Correction: Tech replace front/brake pads and air filter

Parts used
Front brake pad Qty:1 part#BRSD-1328
Rear brake pad Qty:1 part#BRSD-1329
Air filter Qty:1 part#PA-4075

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	0.3666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 28-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 28, 2018 11:26:48 PM	No	
20 - Miles			CKARLENS	Feb 28, 2018 11:26:48 PM	No	
30 - Kilometers			CKARLENS	Feb 28, 2018 11:26:48 PM	No	
40 - Hours			CKARLENS	Feb 28, 2018 11:26:48 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51068114
Invoice No. 55345 - 51068114

Client Department:
Department: 55345M
Work Order Description
Follow------> (51019917)Vehicle needed rear and front brakes/ air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,004 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note: Replace front and rear brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-18	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	51.66	51.66
28-Feb-18	BRSD1329	PADS, BRAKE, DISC, E450	1	45.82	45.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	97.48
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51068114
Invoice No. 55345 - 51068114

Client Department:
Department: 55345M
Work Order Description
Follow------> (51019917)Vehicle needed rear and front brakes/ air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,004 - DH

Activity Header
Activity:25 050/000 GROUP, ACCESSORIES
Activity Note: Replace air filter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-18	PA4075	FILTER, AIR SEE P546597	1	5.25	5.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	0.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	5.25
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.25**

Work Order Footer

Work Order 51068114 Total	
Parts:	102.73
Labor:	0.00
Labor Hours:	5.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.73**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51019917
Invoice No. 55345 - 51019917

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	161,004 - DH

Chronology		
Reported	Feb 28, 2018 2:17:23 PM	Feb 28, 2018 2:17:23 PM
Started	Feb 28, 2018 12:00:00 AM	
Completed	Feb 28, 2018 11:28:00 PM	Feb 28, 2018 11:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Wear and tear

CORRECTION: Tech performed PM-A

Parts used
Oil filter Qty:1 part# B329
Oil Qty:6qts

Vehicle needed front and rear brakes and air filter

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-18	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 28-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,420 - Check Hood	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,133 - Brake Pad Thickness LR	5 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,134 - Brake Pad Thickness RR	5 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,135 - Brake Rotor LF	38.8 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,136 - Brake Rotor RF	38.8 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Feb 28, 2018 11:03:27 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Feb 28, 2018 11:03:27 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51019917
Invoice No. 55345 - 51019917

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,004 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 28-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Feb 28, 2018 11:26:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	Feb 28, 2018 11:26:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Feb 28, 2018 11:26:20 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51019917
Invoice No. 55345 - 51019917

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 161,004 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 28-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 28, 2018 11:05:13 PM	No	
20 - Miles			CKARLENS	Feb 28, 2018 11:05:13 PM	No	
30 - Kilometers			CKARLENS	Feb 28, 2018 11:05:13 PM	No	
40 - Hours			CKARLENS	Feb 28, 2018 11:05:13 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51019917 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	5.28

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51062604
Invoice No. 55345 - 51062604

Client Department:
Department: 55345M
Work Order Description
A/C is blowing out through the defroster
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 160,096 - DH

Chronology		
Reported	Feb 26, 2018 11:29:12 AM	Feb 26, 2018 11:29:12 AM
Started	Feb 26, 2018 12:00:00 AM	
Completed	Feb 27, 2018 11:39:15 AM	Feb 27, 2018 11:39:15 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
A/C is blowing out through the defroster

Cause:
The vacuum hose for the vacuum reservoir broke off the of its vacuum splitter or connection.

Correction:
Installed a new splitter for the vacuum hose. A/C is working properly at this time.

Parts
Shop supply Line 20

Passenger mirror is loose, making noise.

Tightened the mirror, no longer making noise. Line 30

Lift arms are loose.

Tightened lift arms.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 27-FEB-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 27, 2018 11:02:55 AM	No	
20 - Miles			EDTORRES	Feb 27, 2018 11:02:55 AM	No	
30 - Kilometers			EDTORRES	Feb 27, 2018 11:02:55 AM	No	
40 - Hours			EDTORRES	Feb 27, 2018 11:02:55 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51062604
Invoice No. 55345 - 51062604

Client Department:
Department: 55345M
Work Order Description
A/C is blowing out through the defroster
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 160,096 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: A/C is blowing out through the defroster
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Feb-18	Torres,Edwin	1.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51062604 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51042656
Invoice No. 55345 - 51042656

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
A/c blower motor not working		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,745 - DH

Chronology		
Reported	Feb 15, 2018 8:20:47 AM	Feb 15, 2018 8:20:47 AM
Started	Feb 15, 2018 12:00:00 AM	
Completed	Feb 15, 2018 12:16:09 PM	Feb 15, 2018 12:16:09 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:front a/c blower motor not working

Cause: internal failure of blower motor

Correction:replaced blower motor retest system ok at this time

Part: 1 blower motor mm-840
1 fan mm-1081

Line 20 C: spark plugs

C: maintenance

C:replaced spark plugs as per maintenance schedule

Parts: 8 spark plugs sp521
8 spark plugs boots wr-6128

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 15-FEB-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 15, 2018 8:45:53 AM	No	
20 - Miles			JAPEREZ	Feb 15, 2018 8:45:53 AM	No	
30 - Kilometers			JAPEREZ	Feb 15, 2018 8:45:53 AM	No	
40 - Hours			JAPEREZ	Feb 15, 2018 8:45:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51042656
Invoice No. 55345 - 51042656

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
A/c blower motor not working		Ford E350 Champion Crusaders	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	158,745 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: A/c blower motor not working
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Feb-18	MM840	MOTOR, BLOWER, HVAC	1	58.35	58.35
15-Feb-18	MM1081	WHEEL, MOTOR, BLOWER SAME AS AC2Z-19834-A	1	13.48	13.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-18	Perez,Javier	1.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	71.83
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**71.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51042656
Invoice No. 55345 - 51042656

Client Department:
Department: 55345M
Work Order Description
A/c blower motor not working
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 158,745 - DH

Activity Header
Activity: 25 033 IGNITION
Activity Note: Spark plugs
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Feb-18	WR6128	BOOT, PLUG, SPARK	8	5.66	45.28
15-Feb-18	SP521	PLUG, SPARK, 5.4L, FORD	8	4.22	33.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-18	Perez,Javier	2.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	79.04
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**79.04**

Work Order Footer

Work Order 51042656 Total	
Parts:	150.87
Labor:	0.00
Labor Hours:	3.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**150.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51019685
Invoice No. 55345 - 51019685

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP¿¿¿->replace wipers
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 156,693 - DH

Chronology		
Reported	Feb 1, 2018 8:21:10 PM	Feb 1, 2018 8:21:10 PM
Started	Feb 1, 2018 12:00:00 AM	
Completed	Feb 2, 2018 8:19:00 AM	Feb 2, 2018 8:19:00 AM
Down Time		

Work Order Notes

Line 10 Tech Replaced wipers
Part number4520 Qty:2

Activity Header
Activity: 10 050/000 GROUP, ACCESSORIES
Activity Note: replace wiper blades
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Feb-18	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.28	8.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-18	KARLENS,Cyrius	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51019685
Invoice No. 55345 - 51019685

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP¿¿¿->replace wipers
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 156,693 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 01-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 1, 2018 11:53:56 PM	No	
20 - Miles			CKARLENS	Feb 1, 2018 11:53:56 PM	No	
30 - Kilometers			CKARLENS	Feb 1, 2018 11:53:56 PM	No	
40 - Hours			CKARLENS	Feb 1, 2018 11:53:56 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51019685 Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	1.03

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 50974001
Invoice No. 55345 - 50974001

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,693 - DH

Chronology		
Reported	Feb 1, 2018 5:09:18 PM	Feb 1, 2018 5:09:18 PM
Started	Feb 1, 2018 12:00:00 AM	
Completed	Feb 1, 2018 11:32:00 PM	Feb 1, 2018 11:32:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Preventive maintenance

CORRECTION: Tech Performed PM-A

Parts used
Oil filter Qty:1
Oil Qty:6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 01-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Feb 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:21:10 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Feb 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:21:10 PM		
20,240 - FRA Check Interior Lights	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,370 - Check Wiper Blade and Arm Condition	-	replace wiper blades	CKARLENS	Feb 1, 2018 8:21:10 PM	Yes	51019685
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,420 - Check Hood	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,440 - Test Coolant System Using Test	-	na	CKARLENS	Feb 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Strips and Record Results				8:21:10 PM		
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,613 - Air Pressure RRO	70 Pounds per		CKARLENS	Feb 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			8:21:10 PM		
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Feb 1, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:21:10 PM		
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,135 - Brake Rotor LF	39.7 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,136 - Brake Rotor RF	39.7 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Feb 1, 2018 8:21:10 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Feb 1, 2018 8:21:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 50974001
Invoice No. 55345 - 50974001

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,693 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 01-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Feb 1, 2018 8:11:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	Feb 1, 2018 8:11:12 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Feb 1, 2018 8:11:12 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 50974001
Invoice No. 55345 - 50974001

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 156,693 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	-1	1.96	-1.96
01-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Feb-18	KARLENS,Cyrius	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 01-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 1, 2018 8:10:33 PM	No	
20 - Miles			CKARLENS	Feb 1, 2018 8:10:33 PM	No	
30 - Kilometers			CKARLENS	Feb 1, 2018 8:10:33 PM	No	
40 - Hours			CKARLENS	Feb 1, 2018 8:10:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 50974001
Invoice No. 55345 - 50974001

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,693 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50974001 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	5.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 49671484
Invoice No. 55345 - 49671484

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,666 - DH

Chronology		
Reported	Jan 2, 2018 12:17:49 PM	Jan 2, 2018 12:17:49 PM
Started	Jan 2, 2018 12:00:00 AM	
Completed	Jan 3, 2018 12:05:00 AM	Jan 3, 2018 12:05:00 AM
Down Time		

Work Order Notes

Line 10 Perform PMC Service . Change Oil& Filter ,Lube all Pivoting Points ,Check Brakes .Clean batteries .&Perform Transmissions Service.drain& Fill/Replace filter,Perform differential service.drain& Fill
Parts# B329 Qty (1)
Parts# 20021 Qty (1)
Oil 5W 20 Qty (6.5) Qt
ATF Fluid Qty (9.5) Qt
Gear Oil Qty (3) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	3.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 02-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch	Rear tires	DARTHURS	Jan 2, 2018 10:42:03 PM	Yes	50973896
60,634 - Tread Depth RRI	3 32nds of an inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,635 - Tread Depth LRI	2 32nds of an inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,720 - Check Engine and Transmission Mounts	-	Right Engine mount broke	DARTHURS	Jan 2, 2018 10:42:03 PM	Yes	50973896
70,730 - FRA Check Starter	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,120 - Check Suspension Components	-	Front shocks	DARTHURS	Jan 2, 2018 10:42:03 PM	Yes	50973896
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,135 - Brake Rotor LF	1.562 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,136 - Brake Rotor RF	1.56 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,137 - Brake Rotor LR	1.423 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,138 - Brake Rotor RR	1.424 Inch		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 2, 2018 10:42:03 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 2, 2018 10:42:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 49671484
Invoice No. 55345 - 49671484

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jan-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92
02-Jan-18	20021	FILTER, TRANSMISSION 20021	1	16.93	16.93

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 02-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jan 2, 2018 10:43:40 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jan 2, 2018 10:43:40 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Jan 2, 2018 10:43:40 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jan 2, 2018 10:43:40 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jan 2, 2018 10:43:40 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Jan 2, 2018 10:43:40 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	18.85
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**18.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 49671484
Invoice No. 55345 - 49671484

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 02-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 2, 2018 10:44:03 PM	No	
20 - Miles			DARTHURS	Jan 2, 2018 10:44:03 PM	No	
30 - Kilometers			DARTHURS	Jan 2, 2018 10:44:03 PM	No	
40 - Hours			DARTHURS	Jan 2, 2018 10:44:03 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 49671484 Total	
Parts:	18.85
Labor:	0.00
Labor Hours:	4.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**18.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 50973896
Invoice No. 55345 - 50973896

Client Department:
Department: 55345M
Work Order Description
PMC follow Up<<<<<<<<Rear tire& Front Shocks/Right engine mount
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Chronology		
Reported	Jan 2, 2018 10:42:03 PM	Jan 2, 2018 10:42:03 PM
Started	Jan 2, 2018 12:00:00 AM	
Completed	Jan 3, 2018 12:04:00 AM	Jan 3, 2018 12:04:00 AM
Down Time		

Work Order Notes

Line 10 Mount& Balance tire.Rotate L/F to L/R inner& Replace two new on R/R& two new on front.Remove&Replace front shocks/Remove&Replace Right Engine mount.& Replace shocks upper bushing
Parts#.F7UZ-6038-DC Qty (1)
Parts#189752 Qty (4)
Parts#8C2Z-18124-D Qty (2)
Parts#6C3Z-18197-AA Qty (2)

Activity Header
Activity: 10 014/003 MOUNTING, ENGINE
Activity Note: Right Engine mount broke
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-18	F7UZ-6038-DC	INSULATOR	1	52.58	52.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	52.58
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 50973896
Invoice No. 55345 - 50973896

Client Department:
Department: 55345M
Work Order Description
PMC follow Up<<<<<<<<Rear tire& Front Shocks/Right engine mount
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Activity Header
Activity: 20 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jan-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 50973896
Invoice No. 55345 - 50973896

Client Department:
Department: 55345M
Work Order Description
PMC follow Up<<<<<<<<Rear tire& Front Shocks/Right engine mount
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Activity Header
Activity: 30 016 SUSPENSION
Activity Note: Front shocks
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jan-18	8C2Z-18124-D	ABSORBER, SHOCK, FRONT, E450, '08 SAME AS ASH1154	2	39.03	78.06
02-Jan-18	6C3Z-18197-AA	BUSHING, ABSORBER, SHOCK, FRONT, UPPER, ECONOLINE, '08	2	4.15	8.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	86.36
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**86.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 50973896
Invoice No. 55345 - 50973896

Client Department:
Department: 55345M
Work Order Description
PMC follow Up<<<<<<<<Rear tire& Front Shocks/Right engine mount
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,666 - DH

Activity Header
Activity: 40 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jan-18	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

40 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 02-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 2, 2018 11:02:52 PM	No	
20 - Miles			DARTHURS	Jan 2, 2018 11:02:52 PM	No	
30 - Kilometers			DARTHURS	Jan 2, 2018 11:02:52 PM	No	
40 - Hours			DARTHURS	Jan 2, 2018 11:02:52 PM	No	

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50973896 Total	
Parts:	552.70
Labor:	0.00
Labor Hours:	4.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**552.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 46822090
Invoice No. 55345 - 46822090

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	148,502 - DH

Chronology		
Reported	Nov 30, 2017 8:45:47 AM	Nov 30, 2017 8:45:47 AM
Started	Nov 30, 2017 12:00:00 AM	
Completed	Nov 30, 2017 1:17:00 PM	Nov 30, 2017 1:17:00 PM
Down Time		

Work Order Notes

Line 10 PM A
¿
CAUSE:
PM
¿
CORRECTION:
Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.
¿
Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts
1 Air Filter # PA4075
1 drive belt # 5061360

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-17	Rodriguez,Raul	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done				No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done				No	
10,120 - FRA Check All Warning Lights and Alarms	Done				No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done				No	
10,140 - Check Service Brakes	Done				No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done				No	
10,160 - FRA Check Instruments and Horns	Done				No	
10,170 - Check Fast Idle	Done				No	
10,180 - Check Starter Protection Circuit	Done				No	
10,190 - Check Reverse Warning System	Done				No	
11,100 - Check Parking Brake	Done				No	
11,110 - Check HVAC Switches and Other Controls	Done				No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done				No	
11,130 - FRA Check Wiper and Washer Operation	Done				No	
11,140 - Road Test: Check for Proper Operation	Done				No	
11,150 - Perform Brake Test	Done				No	
11,152 - Decelerometer Results Test 1	0 FEET	n/a			No	
11,154 - Decelerometer Results Test 2	FEET	n/a			No	
11,156 - Decelerometer Results Test 3	FEET	n/a			No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a			No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a			No	
11,170 - FRA Check Door Operation	Done				No	
11,180 - FRA Check Operation of All Other Accessories	Done				No	
20,000 - SECTION 2 Interior Circle Inspection	Done				No	
20,210 - Check Condition of Operator's Area	Done				No	
20,220 - Check Accelerator and Brake Pedals	Done				No	
20,230 - FRA Check Wiring Under Dash	Done				No	
20,240 - FRA Check Interior Lights	Done				No	
20,250 - FRA Check Interior Electrical Panels	Done				No	
20,260 - Check Stop Request System	-	n/a			No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a			No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done				No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done				No	
22,100 - Check Emergency Windows and Glass Condition	Done				No	
22,110 - Check Emergency Hatches	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,120 - Check All Safety Equipment	Done				No	
30,000 - SECTION 3 Exterior Circle Inspection	Done				No	
30,310 - Check Passenger Doors	Done				No	
30,320 - Inspect Step-well and Hand Rails	Done				No	
30,330 - Check Wheelchair Lift Operation	Done				No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a			No	
30,350 - FRA Inspect Mirror and Mountings	Done				No	
30,360 - Check for Physical Damage and Decals	Done				No	
30,370 - Check Wiper Blade and Arm Condition	Done				No	
30,380 - Check Exterior Compartment Doors	Done				No	
30,390 - FRA Check Fuel Tank Cap	Done				No	
33,100 - Check Lights and Reflectors	Done				No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done				No	
40,000 - SECTION 4 Engine Compartment Inspection	Done				No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done				No	
40,420 - Check Hood	Done				No	
40,430 - Check Fan, Shroud and Radiator	Done				No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a			No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a			No	
40,442 - Freeze Point	Degree Fahrenheit	n/a			No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done				No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a			No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a			No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done				No	
40,480 - FRA Check Coolant Hose Condition	Done				No	
40,490 - FRA Check Alternator Mount and Condition	Done				No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done				No	
44,110 - FRA Check Master Cylinder Fluid Level	Done				No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done				No	
44,130 - FRA Check Exhaust System	Done				No	
44,140 - FRA Check Intake System	Done				No	
44,150 - FRA Inspect Turbocharger	-	n/a			No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
44,170 - FRA Check All Engine or Belt Driven Components	Done				No	
44,180 - FRA Check for Leaks	Done				No	
44,190 - FRA Perform Battery Inspection	Done				No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done				No	
50,000 - SECTION 5 Steering System Inspection	Done				No	
50,510 - Check Entire Steering System	Done				No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done				No	
60,610 - FRA Check and Record Air Pressure	Done				No	
60,611 - Air Pressure RF	65 Pounds per Square Inch				No	
60,612 - Air Pressure LF	65 Pounds per Square Inch				No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch				No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch				No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch				No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch				No	
60,620 - Check Valve Stems and Caps	Done				No	
60,630 - Check and Record Tread Depth	Done				No	
60,631 - Tread Depth RF	10 32nds of an inch				No	
60,632 - Tread Depth LF	10 32nds of an inch				No	
60,633 - Tread Depth RRO	7 32nds of an inch				No	
60,634 - Tread Depth RRI	7 32nds of an inch				No	
60,635 - Tread Depth LRI	8 32nds of an inch				No	
60,636 - Tread Depth LRO	7 32nds of an inch				No	
60,640 - Check for Mismatched Tread or Casing Design	Done				No	
60,650 - Check Sidewall Wear	Done				No	
60,660 - Inspect for Cuts and Tears	Done				No	
60,670 - Check Dual Mating With Square	Done				No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done				No	
60,690 - Check Tires for Irregular or Alignment Wear	Done				No	
66,100 - FRA Check Outer Hubs for Leaks	Done				No	
70,000 - SECTION 7 Under Vehicle Inspection	Done				No	
70,710 - Check Vibration Damper	Done				No	
70,720 - Check Engine and Transmission Mounts	Done				No	
70,730 - FRA Check Starter	Done				No	
70,740 - FRA Check Bottom of Engine for Fluid	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks						
70,750 - FRA Check Transmission for Leaks	Done				No	
70,760 - FRA Check Differential Breather and Fluid	Done				No	
70,770 - FRA Check Exhaust System	Done				No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done				No	
70,790 - Check All Body Mounts and Chassis Frame	Done				No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done				No	
77,110 - FRA Check Fuel Tank	Done				No	
77,120 - Check Suspension Components	Done				No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done				No	
77,131 - Brake Pad Thickness LF	Inch	8mm			No	
77,132 - Brake Pad Thickness RF	Inch	8mm			No	
77,133 - Brake Pad Thickness LR	Inch	9mm			No	
77,134 - Brake Pad Thickness RR	Inch	9mm			No	
77,135 - Brake Rotor LF	Inch	39.7mm			No	
77,136 - Brake Rotor RF	Inch	39.7mm			No	
77,137 - Brake Rotor LR	Inch	35.8mm			No	
77,138 - Brake Rotor RR	Inch	35.8mm			No	
77,140 - FRA Check Brake Hoses	Done				No	
77,150 - Check King Pins	-	n/a			No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done				No	
80,000 - SECTION 8 PMI Report Completion	Done				No	
80,810 - Completion of PMI Report	Done				No	
90,000 - SECTION 9 Completion of PMI	Done				No	
90,910 - Vehicle Returned to predetermined location	Done				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 46822090
Invoice No. 55345 - 46822090

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 148,502 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Nov-17	5061360	BELT, SERPENTINE, 6-RIB, 136.02"L X 0.82"W	1	27.31	27.31
30-Nov-17	PA4075	FILTER, AIR SEE P546597	1	5.18	5.18
30-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Nov-17	Rodriguez,Raul	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 30-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	Nov 30, 2017 12:41:57 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	34.41
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 46822090
Invoice No. 55345 - 46822090

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	148,502 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 30-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Nov 30, 2017 12:43:05 PM	No	
20 - Miles			RAURODRIGUEZ	Nov 30, 2017 12:43:05 PM	No	
30 - Kilometers			RAURODRIGUEZ	Nov 30, 2017 12:43:05 PM	No	
40 - Hours			RAURODRIGUEZ	Nov 30, 2017 12:43:05 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 46822090 Total	
Parts:	34.41
Labor:	0.00
Labor Hours:	2.57
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**34.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 47455349
Invoice No. 55345 - 47455349

Client Department:
Department: 55345M
Work Order Description
The pressure safety switch for the lift buzzered is going off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,367 - DH

Chronology		
Reported	Nov 7, 2017 12:41:13 PM	Nov 7, 2017 12:41:13 PM
Started	Nov 7, 2017 12:00:00 AM	
Completed	Nov 9, 2017 1:03:00 PM	Nov 9, 2017 1:03:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
pressure safety switch for the lift buzzered is going off.

CAUSE:
One of the studs that holds the spring which suspends the plate off the switch broke from its welding point

CORRECTION: installed a new plate over the threshold

Parts qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 07-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Nov 7, 2017 12:47:39 PM	No	
20 - Miles			EDTORRES	Nov 7, 2017 12:47:39 PM	No	
30 - Kilometers			EDTORRES	Nov 7, 2017 12:47:39 PM	No	
40 - Hours			EDTORRES	Nov 7, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:47:39 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 47455349
Invoice No. 55345 - 47455349

Client Department:
Department: 55345M
Work Order Description
The pressure safety switch for the lift buzzered is going off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,367 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: pressure safety switch for the lift buzzered is going off.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Nov-17	Torres,Edwin	0.7833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 47455349 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 42753270
Invoice No. 55345 - 42753270

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
+		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	144,325 - DH

Chronology		
Reported	Oct 31, 2017 12:47:11 PM	Oct 31, 2017 12:47:11 PM
Started	Oct 31, 2017 12:00:00 AM	
Completed	Nov 1, 2017 12:18:00 AM	Nov 1, 2017 12:18:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 31-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	needs rear brakes job	RGASPARD	Oct 31, 2017 11:06:19 PM	Yes	46817229
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 31, 2017 11:06:19 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 31, 2017 11:06:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 46817229
Invoice No. 55345 - 46817229

Client Department:
Department: 55345M
Work Order Description
Followup---------> needs rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 144,325 - DH

Chronology		
Reported	Oct 31, 2017 11:06:19 PM	Oct 31, 2017 11:06:19 PM
Started	Oct 31, 2017 12:00:00 AM	
Completed	Nov 1, 2017 12:18:00 AM	Nov 1, 2017 12:18:00 AM
Down Time		

Work Order Notes

Line 10 Needs rear brakes job
Wear
Replaced rear brake pads and lubed guide pins
Part number BRSD1329 qty 1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: needs rear brakes job
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Oct-17	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 42753270
Invoice No. 55345 - 42753270

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
+			Ford E350 Champion Crusaders
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	144,325 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
31-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 31-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 31, 2017 11:07:07 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 31, 2017 11:07:07 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 31, 2017 11:07:07 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 31, 2017 11:07:07 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 31, 2017 11:07:07 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 31, 2017 11:07:07 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 31, 2017 11:07:07 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 31, 2017 11:07:07 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 46817229
Invoice No. 55345 - 46817229

Client Department:
Department: 55345M
Work Order Description
Followup---------> needs rear brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 144,325 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 31, 2017 11:13:22 PM	No	
20 - Miles			RGASPARD	Oct 31, 2017 11:13:22 PM	No	
30 - Kilometers			RGASPARD	Oct 31, 2017 11:13:22 PM	No	
40 - Hours			RGASPARD	Oct 31, 2017 11:13:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 46817229 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 42753270
Invoice No. 55345 - 42753270

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
+			Ford E350 Champion Crusaders
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	144,325 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-17	Gaspard,Ronald	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 31-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 31, 2017 11:07:30 PM	No	
20 - Miles			RGASPARD	Oct 31, 2017 11:07:30 PM	No	
30 - Kilometers			RGASPARD	Oct 31, 2017 11:07:30 PM	No	
40 - Hours			RGASPARD	Oct 31, 2017 11:07:30 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 42753270 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.67

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 34736256
Invoice No. 55345 - 34736256

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FOLLOW-UP		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Chronology		
Reported	Mar 31, 2017 1:22:31 PM	Mar 31, 2017 1:22:31 PM
Started	Oct 9, 2017 12:00:00 AM	
Completed	Oct 17, 2017 7:29:00 AM	Oct 17, 2017 7:29:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Driver side head light is out

Cause: normal wear

Correction: removed and replaced head light bulb

Part: shop supply

Activity Header
Activity: 10 030 ELECTRICAL GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-17	Rodriguez,Raul	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34736256 Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 44062887
Invoice No. 55345 - 44062887

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front end inspeccion		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	140,077 - DH

Chronology		
Reported	Oct 3, 2017 11:27:15 AM	Oct 3, 2017 11:27:15 AM
Started	Oct 3, 2017 12:00:00 AM	
Completed	Oct 9, 2017 1:19:00 PM	Oct 9, 2017 1:19:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Front end Inspeccion routine

CAUSE:
Found drag link, upper-lower ball joints (right side) and steering damper with little play.
NORMAL WEAR.
CORRECTION:
Removed and replaced the parts below and road tested, theme send to alignment place.
1 upper ball joint # mcsoe-3
1 lower ball joint # mcf-3
1 drag link # 8c2z-3304-C
Line 20 UNIT WAS SENT TO CALLAGHAN FOR WHEEL ALIGNAMENT .

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 09-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Oct 9, 2017 11:06:45 AM	No	
20 - Miles			RAURODRIGUEZ	Oct 9, 2017 11:06:45 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			RAURODRIGUEZ	Oct 9, 2017 11:06:45 AM	No	
40 - Hours			RAURODRIGUEZ	Oct 9, 2017 11:06:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 44062887
Invoice No. 55345 - 44062887

Client Department:
Department: 55345M
Work Order Description
Front end inspeccion
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Activity Header
Activity: 15 015 STEERING
Activity Note: Front end inspeccion
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-17	MCF3	JOINT, BALL, LOWER SAME AS 8C2Z-3050-A	1	39.45	39.45
03-Oct-17	MCSOE3	JOINT, BALL, UPPER, E450	1	38.39	38.39
09-Oct-17	8C2Z-3304-C	LINK, DRAG, STEERING	1	177.99	177.99
06-Oct-17	8C2Z-3E651-B	DAMPER, STEERING SUPERSEDES 6C2Z-3E651-B	1	46.38	46.38

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-17	Rodriguez,Raul	3.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	302.21
Labor:	0.00
Labor Hours:	3.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**302.21**

Work Order Footer

Work Order 44062887 Total	
Parts:	302.21
Labor:	0.00
Labor Hours:	3.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**302.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 39402418
Invoice No. 55345 - 39402418

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	140,077 - DH

Chronology		
Reported	Sep 18, 2017 12:07:42 PM	Sep 18, 2017 12:07:42 PM
Started	Sep 19, 2017 12:00:00 AM	
Completed	Sep 19, 2017 9:58:00 PM	Sep 19, 2017 9:58:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter Lube all Pivoting Points. Check brakes. Clean batteries. Replace A/C Filter
Parts# B329 Qty (1)
Oil 5W20 Qty (6.5) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 19-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,420 - Check Hood	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	-	Serpentine belts	DARTHURS	Sep 19, 2017 5:12:17 PM	Yes	42734095
44,130 - FRA Check Exhaust System	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,631 - Tread Depth RF	2 32nds of an inch	R/F Tire	DARTHURS	Sep 19, 2017 5:12:17 PM	Yes	42734095
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,135 - Brake Rotor LF	1.566 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,136 - Brake Rotor RF	1.565 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,138 - Brake Rotor RR	1.414 Inch		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Sep 19, 2017 5:12:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Sep 19, 2017 5:12:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 42734095
Invoice No. 55345 - 42734095

Client Department:
Department: 55345M
Work Order Description
PMB Follow up >>>>>>>>>Front tire& Serpentine belt
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Chronology		
Reported	Sep 19, 2017 5:12:17 PM	Sep 19, 2017 5:12:17 PM
Started	Sep 19, 2017 12:00:00 AM	
Completed	Sep 19, 2017 9:58:00 PM	Sep 19, 2017 9:58:00 PM
Down Time		

Work Order Notes

Line 10 Mount& Balance both front tire/Replace& Remove/Replace serpentine belt.
Parts# 189752 Qty (2)
Parts#5061360 Qty (1)

Activity Header
Activity: 10 042 COOLING SYSTEM
Activity Note: Serpentine belts
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-17	5061360	BELT, SERPENTINE, 6-RIB, 136.02"L X 0.82"W	1	27.31	27.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	27.31
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**27.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 39402418
Invoice No. 55345 - 39402418

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 19-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done	Replace A/C Filter	DARTHURS	Sep 19, 2017 5:14:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Sep 19, 2017 5:14:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Sep 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				5:14:21 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Sep 19, 2017 5:14:21 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		DARTHURS	Sep 19, 2017 5:14:21 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Sep 19, 2017 5:14:21 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 42734095
Invoice No. 55345 - 42734095

Client Department:
Department: 55345M
Work Order Description
PMB Follow up >>>>>>>>>Front tire& Serpentine belt
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Activity Header
Activity: 20 017 TIRES, TUBES, LINERS & VALVES
Activity Note: R/F Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	108.25	216.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	216.50
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**216.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 39402418
Invoice No. 55345 - 39402418

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 19, 2017 5:14:55 PM	No	
20 - Miles			DARTHURS	Sep 19, 2017 5:14:55 PM	No	
30 - Kilometers			DARTHURS	Sep 19, 2017 5:14:55 PM	No	
40 - Hours			DARTHURS	Sep 19, 2017 5:14:55 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 39402418 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 42734095
Invoice No. 55345 - 42734095

Client Department:
Department: 55345M
Work Order Description
PMB Follow up >>>>>>>>>Front tire& Serpentine belt
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 140,077 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 19, 2017 5:23:39 PM	No	
20 - Miles			DARTHURS	Sep 19, 2017 5:23:39 PM	No	
30 - Kilometers			DARTHURS	Sep 19, 2017 5:23:39 PM	No	
40 - Hours			DARTHURS	Sep 19, 2017 5:23:39 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 42734095 Total	
Parts:	243.81
Labor:	0.00
Labor Hours:	1.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**243.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 36812575
Invoice No. 55345 - 36812575

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 136,060 - DH

Chronology		
Reported	Aug 16, 2017 8:13:52 AM	Aug 16, 2017 8:13:52 AM
Started	Aug 16, 2017 12:00:00 AM	
Completed	Aug 16, 2017 11:59:00 PM	Aug 16, 2017 11:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 16-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 16, 2017 11:09:35 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 16, 2017 11:09:35 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 36812575
Invoice No. 55345 - 36812575

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 136,060 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Aug-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 16-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 16, 2017 11:10:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 16, 2017 11:10:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 16, 2017 11:10:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 16, 2017 11:10:22 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 16, 2017 11:10:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 16, 2017 11:10:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 16, 2017 11:10:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 16, 2017 11:10:22 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 36812575
Invoice No. 55345 - 36812575

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 136,060 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 16, 2017 11:10:43 PM	No	
20 - Miles			RGASPARD	Aug 16, 2017 11:10:43 PM	No	
30 - Kilometers			RGASPARD	Aug 16, 2017 11:10:43 PM	No	
40 - Hours			RGASPARD	Aug 16, 2017 11:10:43 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 36812575 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.60

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34978944
Invoice No. 55345 - 34978944

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	132,106 - DH

Chronology		
Reported	Jul 20, 2017 8:38:32 AM	Jul 20, 2017 8:38:32 AM
Started	Jul 20, 2017 12:00:00 AM	
Completed	Jul 20, 2017 11:55:00 PM	Jul 20, 2017 11:55:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Air filter PA4075 qty1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jul 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:44:56 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jul 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:44:56 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Jul 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:44:56 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Jul 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:44:56 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Jul 20, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:44:56 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch	needs front brakes job	RGASPARD	Jul 20, 2017 10:44:56 PM	Yes	36807890
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jul 20, 2017 10:44:56 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jul 20, 2017 10:44:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 36807890
Invoice No. 55345 - 36807890

Client Department:
Department: 55345M
Work Order Description
Followup-----> needs front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 132,106 - DH

Chronology		
Reported	Jul 20, 2017 10:44:56 PM	Jul 20, 2017 10:44:56 PM
Started	Jul 20, 2017 12:00:00 AM	
Completed	Jul 20, 2017 11:55:00 PM	Jul 20, 2017 11:55:00 PM
Down Time		

Work Order Notes

Line 10 Needs front brake pads
Wear
Replaced front brake pads lubed guide pins
Part number BRSD1328 qty 1
Torque wheels 140 lbs second torque wheels 140 lbs

Activity Header
Activity: 10 013/001 BRAKES & DRUMS, FRONT
Activity Note: needs front brakes job
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34978944
Invoice No. 55345 - 34978944

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 132,106 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jul-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
20-Jul-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 20, 2017 10:45:46 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 20, 2017 10:45:46 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 20, 2017 10:45:46 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 20, 2017 10:45:46 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 20, 2017 10:45:46 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 20, 2017 10:45:46 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 20, 2017 10:45:46 PM	No	
108,000 - Lube all pivoting	Done		RGASPARD	Jul 20, 2017 10:45:46	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 36807890
Invoice No. 55345 - 36807890

Client Department:
Department: 55345M
Work Order Description
Followup-----> needs front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 132,106 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Gaspard,Ronald	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 20, 2017 10:52:11 PM	No	
20 - Miles			RGASPARD	Jul 20, 2017 10:52:11 PM	No	
30 - Kilometers			RGASPARD	Jul 20, 2017 10:52:11 PM	No	
40 - Hours			RGASPARD	Jul 20, 2017 10:52:11 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 36807890 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.03

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34978944
Invoice No. 55345 - 34978944

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	132,106 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 20, 2017 10:46:10 PM	No	
20 - Miles			RGASPARD	Jul 20, 2017 10:46:10 PM	No	
30 - Kilometers			RGASPARD	Jul 20, 2017 10:46:10 PM	No	
40 - Hours			RGASPARD	Jul 20, 2017 10:46:10 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34978944 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 35480815
Invoice No. 55345 - 35480815

Client Department:
Department: 55345M
Work Order Description
RIGHT SIDE HEAD LIGHT NOT BRIGHT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 130,061 - DH

Chronology		
Reported	Jul 6, 2017 10:59:00 PM	Jul 6, 2017 10:59:00 PM
Started	Jul 6, 2017 12:00:00 AM	
Completed	Jul 6, 2017 11:09:00 PM	Jul 6, 2017 11:09:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: RIGHT SIDE HEADLIGHT IS NOT BRIGHT

CAUSE:CONNECTOR IS BURNED

CORRECTION: REMOVE OLD CONNECTOR REINSTALL NEW CONNECTOR RIGHT SIDE HEADLIGHT IS BRIGHT AT THIS TIME
PARTS# 891669 QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-17	Owens,Arthur	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 06-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 6, 2017 11:09:06 PM	No	
20 - Miles			AOWENS	Jul 6, 2017 11:09:06 PM	No	
30 - Kilometers			AOWENS	Jul 6, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:09:06 PM		
40 - Hours			AOWENS	Jul 6, 2017 11:09:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 35480815
Invoice No. 55345 - 35480815

Client Department:
Department: 55345M
Work Order Description
RIGHT SIDE HEAD LIGHT NOT BRIGHT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 130,061 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: RIGHT SIDE NOT BRIGHT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jul-17	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jul-17	Owens,Arthur	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order Footer

Work Order 35480815 Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34998820
Invoice No. 55345 - 34998820

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear Tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	129,181 - DH

Chronology		
Reported	Jun 29, 2017 6:37:05 PM	Jun 29, 2017 6:37:05 PM
Started	Jun 29, 2017 12:00:00 AM	
Completed	Jun 30, 2017 12:18:00 AM	Jun 30, 2017 12:18:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Rear tires

CAUSE: Nail in both rear outer tire all so inner rear tire low,

CORRECTION: Mount & Balance Rear tire& Replace,
Parts# 189752 Qty (4)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 29, 2017 6:40:20 PM	No	
20 - Miles			DARTHURS	Jun 29, 2017 6:40:20 PM	No	
30 - Kilometers			DARTHURS	Jun 29, 2017 6:40:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Jun 29, 2017 6:40:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34998820
Invoice No. 55345 - 34998820

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear Tires		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	129,181 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Mount&Balance &Replace 4 Rear Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jun-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	105.25	421

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	421.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**421.00**

Work Order Footer

Work Order 34998820 Total	
Parts:	421.00
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**421.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34985058
Invoice No. 55345 - 34985058

Client Department:
Department: 55345M
Work Order Description
REPLACE RIGHT FRONT SIGNAL LIGHT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 128,181 - DH

Chronology		
Reported	Jun 22, 2017 10:19:00 PM	Jun 22, 2017 10:19:00 PM
Started	Jun 22, 2017 12:00:00 AM	
Completed	Jun 22, 2017 10:25:00 PM	Jun 22, 2017 10:25:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: RIGHT FRONT SIGNAL IS OUT

CAUSE: SIGNAL BULB BLOWN

CORRECTION: REPLACE RIGHT FRONT TURN SIGNAL
PARTS # 3157N/A QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-17	Owens,Arthur	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 22-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 22, 2017 10:24:17 PM	No	
20 - Miles			AOWENS	Jun 22, 2017 10:24:17 PM	No	
30 - Kilometers			AOWENS	Jun 22, 2017 10:24:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			AOWENS	Jun 22, 2017 10:24:17 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34985058
Invoice No. 55345 - 34985058

Client Department:
Department: 55345M
Work Order Description
REPLACE RIGHT FRONT SIGNAL LIGHT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 128,181 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE RIGHT FRONT TURN SIGNAL
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jun-17	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	1	0.85	0.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-17	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order Footer

Work Order 34985058 Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	0.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34875521
Invoice No. 55345 - 34875521

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	128,050 - DH

Chronology		
Reported	Jun 21, 2017 8:25:29 AM	Jun 21, 2017 8:25:29 AM
Started	Jun 21, 2017 12:00:00 AM	
Completed	Jun 21, 2017 11:15:00 PM	Jun 21, 2017 11:15:00 PM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform pmc Service
Oil filter B329 Qty 1
Engine oil 5W20Qty 7 Qts
Transmission filter 20021 qty 1
Transmission fluid 10 Qts
Gear Oil 80w90 Qty 4qts

Activity Header

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-17	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 21-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jun 21, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:53:18 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 21, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:53:18 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Jun 21, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:53:18 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Jun 21, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:53:18 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Jun 21, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:53:18 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 21, 2017 10:53:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 21, 2017 10:53:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34875521
Invoice No. 55345 - 34875521

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 128,050 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
21-Jun-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-17	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 21-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 21, 2017 10:55:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jun 21, 2017 10:55:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jun 21, 2017 10:55:00 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jun 21, 2017 10:55:00 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jun 21, 2017 10:55:00 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Jun 21, 2017 10:55:00 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	18.86
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**18.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34875521
Invoice No. 55345 - 34875521

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 128,050 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-17	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 21, 2017 10:55:24 PM	No	
20 - Miles			RGASPARD	Jun 21, 2017 10:55:24 PM	No	
30 - Kilometers			RGASPARD	Jun 21, 2017 10:55:24 PM	No	
40 - Hours			RGASPARD	Jun 21, 2017 10:55:24 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34875521 Total	
Parts:	18.86
Labor:	0.00
Labor Hours:	3.60

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**18.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34947593
Invoice No. 55345 - 34947593

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wipers blade arm clip		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,983 - DH

Chronology		
Reported	Jun 7, 2017 11:43:28 AM	Jun 7, 2017 11:43:28 AM
Started	Jun 7, 2017 12:00:00 AM	
Completed	Jun 7, 2017 11:56:00 AM	Jun 7, 2017 11:56:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Wiper arm clip

CAUSE:
Preventive maintenance

CORRECTION:
Remove&Replace Wiper arm clip

Part:1 wiper arm clip # E3TZ-17531-A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 7, 2017 11:49:36 AM	No	
20 - Miles			RAURODRIGUEZ	Jun 7, 2017 11:49:36 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 7, 2017 11:49:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RAURODRIGUEZ	Jun 7, 2017 11:49:36 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34947593
Invoice No. 55345 - 34947593

Client Department:
Department: 55345M
Work Order Description
Wipers blade arm clip
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,983 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Wiper blades arm clip
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jun-17	E3TZ-17531-A	CLIP, ARM, WPER	1	10.51	10.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-17	Rodriguez,Raul	0.6333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order Footer

Work Order 34947593 Total	
Parts:	10.51
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.51**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34792624
Invoice No. 55345 - 34792624

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,126 - DH

Chronology		
Reported	May 23, 2017 7:15:32 AM	May 23, 2017 7:15:32 AM
Started	May 23, 2017 12:00:00 AM	
Completed	May 24, 2017 8:16:00 AM	May 24, 2017 8:16:00 AM
Down Time		

Work Order Notes

Line 10

CAUSE:
PM A

CORRECTION:
Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter part # B329 qty 1
engine oil. 5W20 Qty 6 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Rodriguez,Raul	1.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 24-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,260 - Check Stop Request System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	70 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,131 - Brake Pad Thickness LF	Inch	6mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,132 - Brake Pad Thickness RF	Inch	6mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,133 - Brake Pad Thickness LR	Inch	7mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,134 - Brake Pad Thickness RR	Inch	7mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,135 - Brake Rotor LF	0 Inch	39.7mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,136 - Brake Rotor RF	Inch	39.7mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,137 - Brake Rotor LR	Inch	35.8mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,138 - Brake Rotor RR	Inch	35.9mm	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,150 - Check King Pins	-	N/A	RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	May 24, 2017 10:09:34 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34792624
Invoice No. 55345 - 34792624

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,126 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Rodriguez,Raul	0.8166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RAURODRIGUEZ	May 23, 2017 11:50:01 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.82
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34792624
Invoice No. 55345 - 34792624

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,126 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 23, 2017 11:50:32 AM	No	
20 - Miles			RAURODRIGUEZ	May 23, 2017 11:50:32 AM	No	
30 - Kilometers			RAURODRIGUEZ	May 23, 2017 11:50:32 AM	No	
40 - Hours			RAURODRIGUEZ	May 23, 2017 11:50:32 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34792624 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.10
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34873707
Invoice No. 55345 - 34873707

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Front tires near minimum specs		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	124,027 - DH

Chronology		
Reported	May 23, 2017 11:51:56 AM	May 23, 2017 11:51:56 AM
Started	May 23, 2017 12:00:00 AM	
Completed	May 23, 2017 1:44:00 PM	May 23, 2017 1:44:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Front tires near minimum specs

CAUSE:
Normal wear

CORRECTION:
Remove&Replace front tires. Torque and re torque tires 140 f/pounds

Part: 2 tires # 189752

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 23, 2017 12:12:52 PM	No	
20 - Miles			RAURODRIGUEZ	May 23, 2017 12:12:52 PM	No	
30 - Kilometers			RAURODRIGUEZ	May 23, 2017 12:12:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RAURODRIGUEZ	May 23, 2017 12:12:52 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34873707
Invoice No. 55345 - 34873707

Client Department:
Department: 55345M
Work Order Description
Front tires near minimum specs
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 124,027 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Front tires near minimum specs
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Rodriguez,Raul	1.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order Footer

Work Order 34873707 Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34738263
Invoice No. 55345 - 34738263

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 119,932 - DH

Chronology		
Reported	Apr 27, 2017 4:01:45 PM	Apr 27, 2017 4:01:45 PM
Started	Apr 27, 2017 12:00:00 AM	
Completed	Apr 27, 2017 11:07:00 PM	Apr 27, 2017 11:07:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-17	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,420 - Check Hood	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Apr 27, 2017 10:36:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Apr 27, 2017 10:36:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34738263
Invoice No. 55345 - 34738263

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 119,932 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-17	Gaspard,Ronald	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 27, 2017 10:37:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 27, 2017 10:37:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 27, 2017 10:37:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 27, 2017 10:37:01 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Apr 27, 2017 10:37:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 27, 2017 10:37:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Apr 27, 2017 10:37:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 27, 2017 10:37:01 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34738263
Invoice No. 55345 - 34738263

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	119,932 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 27, 2017 10:37:23 PM	No	
20 - Miles			RGASPARD	Apr 27, 2017 10:37:23 PM	No	
30 - Kilometers			RGASPARD	Apr 27, 2017 10:37:23 PM	No	
40 - Hours			RGASPARD	Apr 27, 2017 10:37:23 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34738263 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.68

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34747119
Invoice No. 55345 - 34747119

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Passenger Seat belts		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	117,072 - DH

Chronology		
Reported	Apr 7, 2017 7:31:27 PM	Apr 7, 2017 7:31:27 PM
Started	Apr 7, 2017 12:00:00 AM	
Completed	Apr 7, 2017 10:43:00 PM	Apr 7, 2017 10:43:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Driver Side Passenger front seat belt,

CAUSE:seat belt not retracking ,bad

CORRECTION: Remove& Replace seat belt,
Parts shop supply, Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Apr-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 7, 2017 7:35:01 PM	No	
20 - Miles			DARTHURS	Apr 7, 2017 7:35:01 PM	No	
30 - Kilometers			DARTHURS	Apr 7, 2017 7:35:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Apr 7, 2017 7:35:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34747119
Invoice No. 55345 - 34747119

Client Department:
Department: 55345M
Work Order Description
Passenger Seat belts
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 117,072 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Driver Sides seat belts bad
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Apr-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34747119 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34736215
Invoice No. 55345 - 34736215

Client Department:
Department: 55345M
Work Order Description
Rear brakes FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 115,962 - DH

Chronology		
Reported	Mar 31, 2017 12:54:26 PM	Mar 31, 2017 12:54:26 PM
Started	Mar 31, 2017 12:00:00 AM	
Completed	Apr 3, 2017 12:02:00 PM	Apr 3, 2017 12:02:00 PM
Down Time		

Work Order Notes

Line 10 PMB follow up

Rear brake pads replaced
Air filter replaced

Part used:
One (1) brake pads BRSD1329
One (1) - air filter #PA-4075

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: 3mm
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Apr-17	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48
03-Apr-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	49.66
Labor:	0.00

	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**49.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34736215
Invoice No. 55345 - 34736215

Client Department:
Department: 55345M
Work Order Description
Rear brakes FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 115,962 - DH

Activity Header
Activity: 20
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 03-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 3, 2017 9:34:52 AM	No	
20 - Miles			FSIMON	Apr 3, 2017 9:34:52 AM	No	
30 - Kilometers			FSIMON	Apr 3, 2017 9:34:52 AM	No	
40 - Hours			FSIMON	Apr 3, 2017 9:34:52 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34736215 Total	
Parts:	49.66
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**49.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34636473
Invoice No. 55345 - 34636473

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Chronology		
Reported	Mar 30, 2017 10:10:46 AM	Mar 30, 2017 10:10:46 AM
Started		
Completed	Apr 3, 2017 8:29:00 AM	Apr 3, 2017 8:29:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB service

CAUSE:PMB due

CORRECTION:PMB completion

PMB performed

Engine oil changed
Engine oil filter replaced
Grease fittings lubricated

Materials used:
One (1) engine oil filter#B329
Six (6) quarts of oil 5w20

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Mediun Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,100 - Safety Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,140 - Check Service Brakes	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,170 - Check Fast Idle	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,100 - Check Parking Brake	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,150 - Perform Brake Test	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,240 - FRA Check Interior Lights	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,260 - Check Stop Request System	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,310 - Check Passenger Doors	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,420 - Check Hood	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,140 - FRA Check Intake System	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
50,510 - Check Entire Steering System	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	65 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,710 - Check Vibration Damper	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,730 - FRA Check Starter	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,120 - Check Suspension Components	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,131 - Brake Pad Thickness LF	0 Inch	8mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,132 - Brake Pad Thickness RF	0 Inch	8mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,133 - Brake Pad Thickness LR	Inch	3mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,134 - Brake Pad Thickness RR	Inch	3mm	FSIMON	Mar 31, 2017 12:54:26 PM	Yes	34736215
77,135 - Brake Rotor LF	Inch	40mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,136 - Brake Rotor RF	Inch	40mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,137 - Brake Rotor LR	Inch	35mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,138 - Brake Rotor RR	Inch	35mm	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,150 - Check King Pins	-	NA	FSIMON	Mar 31, 2017 12:54:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
80,810 - Completion of PMI Report	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	Mar 31, 2017 12:54:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34636473
Invoice No. 55345 - 34636473

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: FSIMON Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	Mar 31, 2017 12:44:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		FSIMON	Mar 31, 2017 12:44:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
104,000 - Lubricate Chassis	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	FSIMON	Mar 31, 2017 12:44:12 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
201,000 - Service Crankcase Breather	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		FSIMON	Mar 31, 2017 12:44:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
204,000 - FRA Change Power Steering Fluid and Filter	Yes		FSIMON	Mar 31, 2017 12:44:12 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		FSIMON	Mar 31, 2017 12:44:12 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34636473
Invoice No. 55345 - 34636473

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 31, 2017 12:42:04 PM	No	
20 - Miles			FSIMON	Mar 31, 2017 12:42:04 PM	No	
30 - Kilometers			FSIMON	Mar 31, 2017 12:42:04 PM	No	
40 - Hours			FSIMON	Mar 31, 2017 12:42:04 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34636473 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34736228
Invoice No. 55345 - 34736228

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
W/C Lift inspection		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Chronology		
Reported	Mar 31, 2017 1:04:57 PM	Mar 31, 2017 1:04:57 PM
Started	Mar 31, 2017 12:00:00 AM	
Completed	Apr 3, 2017 8:11:00 AM	Apr 3, 2017 8:11:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:W/C lift inspection

CAUSE:Preventive maintenance

CORRECTION:W/C lift inspection completion

W/C lift inspection completed
Outer barrier switch found defective
Outer barrier switch replaced

Parts used:
One (1) harness rollstop occ nlc2 #400374AKS(under warranty).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 31, 2017 1:22:58 PM	No	
20 - Miles			FSIMON	Mar 31, 2017 1:22:58 PM	No	
30 - Kilometers			FSIMON	Mar 31, 2017 1:22:58 PM	No	
40 - Hours			FSIMON	Mar 31, 2017 1:22:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34736228
Invoice No. 55345 - 34736228

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
W/C Lift inspection		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	115,962 - DH

Activity Header
Activity: 15 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc:
Task: Braun Wheelchair Lift Inspection Performed by: FSIMON Performed on: 31-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done	NCL-954FIB3454HB-2	FSIMON	Mar 31, 2017 1:22:31 PM	No	
200 - Record Serial # in Notes	Done	GA-106175	FSIMON	Mar 31, 2017 1:22:31 PM	No	
300 - Cycle Count	Cycles	6175cycles	FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,000 - A - GENERAL INSPECTION	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,200 - Lift Ground & Secondary Ground	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,300 - Vehicle Interlock Power	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,400 - Vehicle Interlock Prohits Vehicle Movement	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,500 - Lift Door Condition	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
10,600 - Hand Pendant Codition/Function	Done		FSIMON	Mar 31, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:22:31 PM		
10,700 - Inspect Mounting Components	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,000 - B - CYCLE CHECK	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,100 - General Operation Throug Comple Cycle	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,300 - Floor Level Adjustment	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,400 - Platform Angle Adjustment	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,500 - Outer Barrier Interlock	Done		FSIMON	Mar 31, 2017 1:22:31 PM	Yes	34736256
20,600 - Inner Barrier Interlock	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,700 - Threshold Warning Interlock	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,800 - 50 Pound Fold Interlock	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
20,900 - Platform Lights	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
21,000 - Anti-Skid	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
21,100 - Operation & Warning Decals	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
21,200 - Back Pump Handdle Location	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
21,300 - Manual Override/Back-up System Function	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,400 - Pivot Pin Fasteners	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,500 - Pivot Pins & Bushing Condition	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,600 - Handrails	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
30,700 - Lift-Tite System	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,100 - Leaks	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,300 - Remove Pump Cover & Check Fluid Level	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,400 - Fluid Condition	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,500 - LiftPump Motor Cables/Connections	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		FSIMON	Mar 31, 2017 1:22:31 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34736228 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 33750167
Invoice No. 55345 - 33750167

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 111,521 - DH

Chronology		
Reported	Mar 3, 2017 12:28:31 PM	Mar 3, 2017 12:28:31 PM
Started	Mar 3, 2017 12:00:00 AM	
Completed	Mar 3, 2017 10:28:00 PM	Mar 3, 2017 10:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 03-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 3, 2017 10:23:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 3, 2017 10:23:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 33750167
Invoice No. 55345 - 33750167

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	111,521 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Mar-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-17	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 03-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 3, 2017 10:24:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 3, 2017 10:24:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 3, 2017 10:24:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 3, 2017 10:24:56 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 3, 2017 10:24:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 3, 2017 10:24:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 3, 2017 10:24:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 3, 2017 10:24:56 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 33750167
Invoice No. 55345 - 33750167

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	111,521 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Mar-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 3, 2017 10:25:19 PM	No	
20 - Miles			RGASPARD	Mar 3, 2017 10:25:19 PM	No	
30 - Kilometers			RGASPARD	Mar 3, 2017 10:25:19 PM	No	
40 - Hours			RGASPARD	Mar 3, 2017 10:25:19 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33750167 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.63

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 32929407
Invoice No. 55345 - 32929407

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	107,770 - DH

Chronology		
Reported	Feb 8, 2017 7:48:34 AM	Feb 8, 2017 7:48:34 AM
Started	Feb 8, 2017 12:00:00 AM	
Completed	Feb 9, 2017 8:08:00 AM	Feb 9, 2017 8:08:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION:perform service lube all pivoting points cross rotate tires completed
Parts #b329 qty1
Oil#5w20 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 09-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,230 - FRA Check Wiring Under Dash	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,420 - Check Hood	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	need rear tires	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,710 - Check Vibration Damper	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,133 - Brake Pad Thickness LR	10 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Feb 9, 2017 7:50:43 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Feb 9, 2017 7:50:43 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 32929407
Invoice No. 55345 - 32929407

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	107,770 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 08-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 8, 2017 1:16:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 8, 2017 1:16:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 8, 2017 1:16:22 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.33
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 32929407
Invoice No. 55345 - 32929407

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 107,770 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 8, 2017 1:17:02 PM	No	
20 - Miles			HPIERRE	Feb 8, 2017 1:17:02 PM	No	
30 - Kilometers			HPIERRE	Feb 8, 2017 1:17:02 PM	No	
40 - Hours			HPIERRE	Feb 8, 2017 1:17:02 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 32929407
Invoice No. 55345 - 32929407

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	107,770 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32929407 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 33705213
Invoice No. 55345 - 33705213

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PMA follow up need rear tires		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	107,770 - DH

Chronology		
Reported	Feb 8, 2017 1:22:38 PM	Feb 8, 2017 1:22:38 PM
Started	Feb 8, 2017 12:00:00 AM	
Completed	Feb 9, 2017 8:02:00 AM	Feb 9, 2017 8:02:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: PMA Follow up need rear tires

CAUSE:below spect

CORRECTION: mount and balance 4 tires completed
Part#050017 qty 4

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 8, 2017 1:25:28 PM	No	
20 - Miles			HPIERRE	Feb 8, 2017 1:25:28 PM	No	
30 - Kilometers			HPIERRE	Feb 8, 2017 1:25:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Feb 8, 2017 1:25:28 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 33705213
Invoice No. 55345 - 33705213

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PMA follow up need rear tires		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	107,770 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Feb-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	4	89.73	358.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-17	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	358.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**358.92**

Work Order Footer

Work Order 33705213 Total	
Parts:	358.92
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**358.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 33386204
Invoice No. 55345 - 33386204

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Passenger side headlight is out		Ford E350 Champion Crusaders	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	Yes	**Meter:**	106,675 - DH

Chronology		
Reported	Feb 2, 2017 11:08:58 AM	Feb 2, 2017 11:08:58 AM
Started	Feb 2, 2017 12:00:00 AM	
Completed	Feb 2, 2017 2:29:00 PM	Feb 2, 2017 2:29:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:
Passenger side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced passenger side headlight bulb.

PARTS:
83982 headlight bulb qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 02-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Feb 2, 2017 12:29:54 PM	No	
20 - Miles			RAURODRIGUEZ	Feb 2, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:29:54 PM		
30 - Kilometers			RAURODRIGUEZ	Feb 2, 2017 12:29:54 PM	No	
40 - Hours			RAURODRIGUEZ	Feb 2, 2017 12:29:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 33386204
Invoice No. 55345 - 33386204

Client Department:
Department: 55345M
Work Order Description
Passenger side headlight is out
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: Yes

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 106,675 - DH

Activity Header
Activity: 15
Activity Note: Passenger side headlight is out
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Feb-17	83982	BULB, HALOGEN, 9008	1	7.8	7.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-17	Rodriguez,Raul	0.2333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.80
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.80**

Work Order Footer

Work Order 33386204 Total	
Parts:	7.80
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 30310161
Invoice No. 55345 - 30310161

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Chronology		
Reported	Jan 13, 2017 12:30:20 PM	Jan 13, 2017 12:30:20 PM
Started	Jan 13, 2017 12:00:00 AM	
Completed	Jan 13, 2017 11:11:00 PM	Jan 13, 2017 11:11:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service Change Oil And Filter , Lube all Pivoting Points check brakes clean rear A/C Filter ,clean batteries Replace strip drain plug Swap (2) Right Rear tire, 4/32 each
Parts #B329 Qty (1)
Oil 5W20 Qty (6.5) Qts
Parts #F75Z-6730-BA Qty (1)

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 13-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,632 - Tread Depth LF	13 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,750 - FRA Check Transmission for Leaks	-	Transmission Service	DARTHURS	Jan 13, 2017 10:31:46 PM	Yes	32929184
70,760 - FRA Check Differential Breather and Fluid	-	differential Service	DARTHURS	Jan 13, 2017 10:31:46 PM	Yes	32929184
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,131 - Brake Pad Thickness LF	4 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,132 - Brake Pad Thickness RF	3 Inch	Front Pads	DARTHURS	Jan 13, 2017 10:31:46 PM	Yes	32929184
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,136 - Brake Rotor RF	1.567 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,138 - Brake Rotor RR	1.413 Inch		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jan 13, 2017 10:31:46 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jan 13, 2017 10:31:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 32929184
Invoice No. 55345 - 32929184

Client Department:

Department: 55345M

Work Order Description
PMC Follow up>>>>>>>Front Pads& differential Service &Transmission Service

Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Chronology		
Reported	Jan 13, 2017 10:31:46 PM	Jan 13, 2017 10:31:46 PM
Started	Jan 13, 2017 12:00:00 AM	
Completed	Jan 13, 2017 11:11:00 PM	Jan 13, 2017 11:11:00 PM
Down Time		

Work Order Notes

Line 10 Drain& Fill transmissions fluid /Replace filter,Remove and ReplaceFront Pads& Drain/Fill Differential fluid,
Parts#FT180 Qty (1) Fluid Qty (9.5) Qts
Parts#1328 Qty (1)
Gear Oil 80W90 Qty (3)Qts

Activity Header
Activity: 10 013/001 BRAKES & DRUMS, FRONT
Activity Note: Front Pads
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jan-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 30310161
Invoice No. 55345 - 30310161

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
13-Jan-17	F757-6730-BA	PLUG, DRAIN, OIL, ENGINE	1	6.66	6.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 13-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jan 13, 2017 10:33:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jan 13, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:33:41 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jan 13, 2017 10:33:41 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Jan 13, 2017 10:33:41 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jan 13, 2017 10:33:41 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jan 13, 2017 10:33:41 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Jan 13, 2017 10:33:41 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 32929184
Invoice No. 55345 - 32929184

Client Department:

Department: 55345M

Work Order Description
PMC Follow up>>>>>>>Front Pads& differential Service &Transmission Service

Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Activity Header
Activity: 20 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Transmission Service
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jan-17	FT180	FILTER, TRANSMISSION	1	36.27	36.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	36.27
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 30310161
Invoice No. 55345 - 30310161

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 13-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 13, 2017 10:34:07 PM	No	
20 - Miles			DARTHURS	Jan 13, 2017 10:34:07 PM	No	
30 - Kilometers			DARTHURS	Jan 13, 2017 10:34:07 PM	No	
40 - Hours			DARTHURS	Jan 13, 2017 10:34:07 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 30310161 Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	3.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 32929184
Invoice No. 55345 - 32929184

Client Department:

Department: 55345M

Work Order Description
PMC Follow up>>>>>>>Front Pads& differential Service &Transmission Service

Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Activity Header
Activity: 30 022/003 CARRIER, DIFFERENTIAL
Activity Note: differential Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 32929184
Invoice No. 55345 - 32929184

Client Department:

Department: 55345M

Work Order Description
PMC Follow up>>>>>>>Front Pads& differential Service &Transmission Service

Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 103,892 - DH

Activity Header
Activity: 40 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-17	Arthurs,Durvin	0.0833333	0	0
13-Jan-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

40 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 13-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 13, 2017 10:48:04 PM	No	
20 - Miles			DARTHURS	Jan 13, 2017 10:48:04 PM	No	
30 - Kilometers			DARTHURS	Jan 13, 2017 10:48:04 PM	No	
40 - Hours			DARTHURS	Jan 13, 2017 10:48:04 PM	No	

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

	Work Order 32929184 Total	
	Parts:	86.59
	Labor:	0.00
	Labor Hours:	3.58
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**86.59**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 30309760
Invoice No. 55345 - 30309760

Client Department:
Department: 55345M
Work Order Description
Followup--------->needs 2 front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,891 - DH

Chronology		
Reported	Dec 15, 2016 10:36:07 PM	Dec 15, 2016 10:36:07 PM
Started	Dec 15, 2016 12:00:00 AM	
Completed	Dec 15, 2016 11:01:00 PM	Dec 15, 2016 11:01:00 PM
Down Time		

Work Order Notes

Line 10 Needs 2 front tires
Wear
Replaced front tires
2 new tires mounted and balanced
Torque tires 140 lbs second torque 140 lbs
Part number brid 192659 qty 2

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs 2 front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jan-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	89.9	179.8
15-Dec-16	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	109.61	219.22
09-Jan-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	-2	109.61	-219.22
09-Jan-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	109.61	219.22
09-Jan-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	-2	89.9	-179.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Gaspard,Ronald	0.0333333	0	0
15-Dec-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	219.22
Labor:	0.00

	Labor Hours:	1.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**219.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 30309760
Invoice No. 55345 - 30309760

Client Department:
Department: 55345M
Work Order Description
Followup--------->needs 2 front tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,891 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Gaspard,Ronald	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 15, 2016 10:52:26 PM	No	
20 - Miles			RGASPARD	Dec 15, 2016 10:52:26 PM	No	
30 - Kilometers			RGASPARD	Dec 15, 2016 10:52:26 PM	No	
40 - Hours			RGASPARD	Dec 15, 2016 10:52:26 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 30309760 Total	
Parts:	219.22
Labor:	0.00
Labor Hours:	1.07

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**219.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 28206508
Invoice No. 55345 - 28206508

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	99,891 - DH

Chronology		
Reported	Dec 15, 2016 1:56:29 PM	Dec 15, 2016 1:56:29 PM
Started	Dec 15, 2016 12:00:00 AM	
Completed	Dec 15, 2016 10:42:00 PM	Dec 15, 2016 10:42:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Dec-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch	needs 2 front tires	RGASPARD	Dec 15, 2016 10:36:07 PM	Yes	30309760
60,632 - Tread Depth LF	2 32nds of an inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Dec 15, 2016 10:36:07 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 15, 2016 10:36:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 28206508
Invoice No. 55345 - 28206508

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,891 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 15, 2016 10:36:54 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 15, 2016 10:36:54 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 15, 2016 10:36:54 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 15, 2016 10:36:54 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Dec 15, 2016 10:36:54 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 15, 2016 10:36:54 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Dec 15, 2016 10:36:54 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 15, 2016 10:36:54 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 28206508
Invoice No. 55345 - 28206508

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	99,891 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 15-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 15, 2016 10:37:18 PM	No	
20 - Miles			RGASPARD	Dec 15, 2016 10:37:18 PM	No	
30 - Kilometers			RGASPARD	Dec 15, 2016 10:37:18 PM	No	
40 - Hours			RGASPARD	Dec 15, 2016 10:37:18 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 28206508 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 28173059
Invoice No. 55345 - 28173059

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PmA follow up need rear brake		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	95,538 - DH

Chronology		
Reported	Nov 16, 2016 11:12:39 AM	Nov 16, 2016 11:12:39 AM
Started	Nov 16, 2016 12:00:00 AM	
Completed	Nov 17, 2016 10:20:00 AM	Nov 17, 2016 10:20:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: PMA follow up need rear brake pads

CAUSE: below spect

CORRECTION: replace rear brake pads completed
Part# BRSD 1329 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 16, 2016 11:17:26 AM	No	
20 - Miles			HPIERRE	Nov 16, 2016 11:17:26 AM	No	
30 - Kilometers			HPIERRE	Nov 16, 2016 11:17:26 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Nov 16, 2016 11:17:26 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 28173059
Invoice No. 55345 - 28173059

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PmA follow up need rear brake		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	95,538 - DH

Activity Header
Activity: 15 013/002/000 REAR BRAKES & DRUMS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-16	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-16	Pierre,Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
15 Desc: Task: STARTER REPLACE Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - personal risk assessment and meter update	Done				No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 28173059 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27751838
Invoice No. 55345 - 27751838

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,538 - DH

Chronology		
Reported	Nov 16, 2016 10:13:42 AM	Nov 16, 2016 10:13:42 AM
Started	Nov 16, 2016 12:00:00 AM	
Completed	Nov 17, 2016 8:59:00 AM	Nov 17, 2016 8:59:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: preventive maintenance

CORRECTION: perform service lube all pivoting points and cross rotate front tires completed
Parts #B329 qty 1 oil filter
Oil # 5w20 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-16	Pierre,Hubert J	4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1400 Pounds per Square Inch	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,420 - Check Hood	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,632 - Tread Depth LF	7 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,133 - Brake Pad Thickness LR	3 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,134 - Brake Pad Thickness RR	3 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,135 - Brake Rotor LF	1.7 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,136 - Brake Rotor RF	1.7 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Nov 16, 2016 11:02:04 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Nov 16, 2016 11:02:04 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27751838
Invoice No. 55345 - 27751838

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,538 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 16, 2016 11:03:09 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Nov 16, 2016 11:03:09 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 16, 2016 11:03:09 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27751838
Invoice No. 55345 - 27751838

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,538 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 16, 2016 11:03:30 AM	No	
20 - Miles			HPIERRE	Nov 16, 2016 11:03:30 AM	No	
30 - Kilometers			HPIERRE	Nov 16, 2016 11:03:30 AM	No	
40 - Hours			HPIERRE	Nov 16, 2016 11:03:30 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27751838 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27781785
Invoice No. 55345 - 27781785

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Left door won't open		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,850 - DH

Chronology		
Reported	Oct 24, 2016 3:58:10 PM	Oct 24, 2016 3:58:10 PM
Started	Oct 24, 2016 12:00:00 AM	
Completed	Oct 24, 2016 8:10:00 PM	Oct 24, 2016 8:10:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: left door won't open

CAUSE: the lock is broken

CORRECTION: replace door lock completed
Part under warranty # door lock 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 24-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 24, 2016 4:12:11 PM	No	
20 - Miles			HPIERRE	Oct 24, 2016 4:12:11 PM	No	
30 - Kilometers			HPIERRE	Oct 24, 2016 4:12:11 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Oct 24, 2016 4:12:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27781785
Invoice No. 55345 - 27781785

Client Department:
Department: 55345M
Work Order Description
Left door won't open
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,850 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27781785 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27451221
Invoice No. 55345 - 27451221

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,209 - DH

Chronology		
Reported	Oct 20, 2016 11:19:59 AM	Oct 20, 2016 11:19:59 AM
Started	Oct 20, 2016 12:00:00 AM	
Completed	Oct 21, 2016 12:07:00 AM	Oct 21, 2016 12:07:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE:Service Due By Mileage

CORRECTION:Change Oil& Filter Lube All Pivoting Points Replace Air Filter clean batteries Check brakes,
Parts#B329 Qty (1)
parts#PA 4075 Qty (1)
Oil 5W20 Qty (6) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				9:48:53 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
20,280 - Check Seats, Seat Belts, Hand	Done		DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Rails and Floor Covering				9:48:53 PM		
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,461 - Refractometer Reading	Degree	NA	DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			9:48:53 PM		
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:48:53 PM		
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch	Both front tire Cupping	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:48:53 PM		
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,135 - Brake Rotor LF	1.598 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,136 - Brake Rotor RF	1.597 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,137 - Brake Rotor LR	1.415 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,138 - Brake Rotor RR	1.415 Inch		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 20, 2016 9:48:53 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	-	front Wheel bearing loose	DARTHURS	Oct 20, 2016 9:48:53 PM	Yes	27751071
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 20, 2016 9:48:53 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27451221
Invoice No. 55345 - 27451221

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,209 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
20-Oct-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 20, 2016 9:50:12 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:50:12 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Oct 20, 2016 9:50:12 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Oct 20, 2016 9:50:12 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Oct 20, 2016 9:50:12 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27451221
Invoice No. 55345 - 27451221

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,209 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 20, 2016 9:50:46 PM	No	
20 - Miles			DARTHURS	Oct 20, 2016 9:50:46 PM	No	
30 - Kilometers			DARTHURS	Oct 20, 2016 9:50:46 PM	No	
40 - Hours			DARTHURS	Oct 20, 2016 9:50:46 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27451221 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27751071
Invoice No. 55345 - 27751071

Client Department:
Department: 55345M
Work Order Description
PMB Follow up-------->Repack front wheel bearing
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,209 - DH

Chronology		
Reported	Oct 20, 2016 9:48:53 PM	Oct 20, 2016 9:48:53 PM
Started	Oct 20, 2016 12:00:00 AM	
Completed	Oct 21, 2016 12:06:00 AM	Oct 21, 2016 12:06:00 AM
Down Time		

Work Order Notes

Line 10 Repack both front wheel bearing&Rotate both front tire . Cupping front to right rear & both right rear tire to front,

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: front Wheel bearing loose
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27751071
Invoice No. 55345 - 27751071

Client Department:
Department: 55345M
Work Order Description
PMB Follow up-------->Repack front wheel bearing
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,209 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 20, 2016 11:23:36 PM	No	
20 - Miles			DARTHURS	Oct 20, 2016 11:23:36 PM	No	
30 - Kilometers			DARTHURS	Oct 20, 2016 11:23:36 PM	No	
40 - Hours			DARTHURS	Oct 20, 2016 11:23:36 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27751071 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27490134
Invoice No. 55345 - 27490134

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Rear A/C check		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	88,584 - DH

Chronology		
Reported	Sep 30, 2016 12:48:54 PM	Sep 30, 2016 12:48:54 PM
Started	Sep 30, 2016 12:00:00 AM	
Completed	Oct 4, 2016 11:04:00 AM	Oct 4, 2016 11:04:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Rear A/C not blowing cold

CAUSE:Clogged orifice tube

CORRECTION:Orifice tube replacement

Complaint verified
Rear A/C system tested
High and low sides pressures are out of range
Orifice tube replaced
A/C system refrigerant recovered ,vacuum performed ,leak test and recharge done.

NB:Small leak suspected(to be monitored)

Parts used :
One (1) orifice tube #YG-380

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 3, 2016 3:06:53 PM	No	
20 - Miles			FSIMON	Oct 3, 2016 3:06:53 PM	No	
30 - Kilometers			FSIMON	Oct 3, 2016 3:06:53 PM	No	
40 - Hours			FSIMON	Oct 3, 2016 3:06:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27490134
Invoice No. 55345 - 27490134

Client Department:
Department: 55345M
Work Order Description
Rear A/C check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 88,584 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Sep-16	YG-380	TUBE, ORIFICE, A/C	1	4.36	4.36

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Sep-16	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	4.36
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.36**

Work Order Footer

Work Order 27490134 Total	
Parts:	4.36
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.36**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27399775
Invoice No. 55345 - 27399775

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 86,877 - DH

Chronology		
Reported	Sep 20, 2016 8:59:52 AM	Sep 20, 2016 8:59:52 AM
Started		
Completed	Sep 20, 2016 2:29:00 PM	Sep 20, 2016 2:29:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE:preventive maintenance

CORRECTION: perform service lube all pivoting points cross rotate tires and replace driver side light bulb complete
Parts #B329 oil filter qty 1
Oil 5w20 qts6
Light bulb 9008 H13 qty 1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
20-Sep-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 20-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,420 - Check Hood	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Sep 20, 2016 9:59:34 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Sep 20, 2016 9:59:34 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.71
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27399775
Invoice No. 55345 - 27399775

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	86,877 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 20-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Sep 20, 2016 10:00:23 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Sep 20, 2016 10:00:23 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Sep 20, 2016 10:00:23 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27399775
Invoice No. 55345 - 27399775

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	86,877 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 20-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 20, 2016 10:00:41 AM	No	
20 - Miles			HPIERRE	Sep 20, 2016 10:00:41 AM	No	
30 - Kilometers			HPIERRE	Sep 20, 2016 10:00:41 AM	No	
40 - Hours			HPIERRE	Sep 20, 2016 10:00:41 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27399775 Total	
Parts:	7.71
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**7.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27444402
Invoice No. 55345 - 27444402

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Tune up		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	86,298 - DH

Chronology		
Reported	Sep 15, 2016 8:56:50 PM	Sep 15, 2016 8:56:50 PM
Started	Sep 15, 2016 12:00:00 AM	
Completed	Sep 15, 2016 9:33:00 PM	Sep 15, 2016 9:33:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: tune up

CAUSE:tune up due by mileage

CORRECTION: Remove Spark plug&Replace plugs/ boots
Parts#SP521 Qty(8)
Parts#wR6128 Qty (8)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 15-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 15, 2016 8:58:21 PM	No	
20 - Miles			DARTHURS	Sep 15, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:58:21 PM		
30 - Kilometers			DARTHURS	Sep 15, 2016 8:58:21 PM	No	
40 - Hours			DARTHURS	Sep 15, 2016 8:58:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27444402
Invoice No. 55345 - 27444402

Client Department:
Department: 55345M
Work Order Description
Tune up
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 86,298 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Tune up sparks plug & plug boots
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-16	WR6128	BOOT, PLUG, SPARK	8	5.28	42.24
15-Sep-16	SP521	PLUG, SPARK, 5.4L, FORD	8	4.15	33.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-16	Arthurs,Durvin	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	75.44
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.44**

Work Order Footer

Work Order 27444402 Total	
Parts:	75.44
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**75.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27439097
Invoice No. 55345 - 27439097

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
INTERIOR LIGHT OUT		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,718 - DH

Chronology		
Reported	Sep 12, 2016 7:32:21 PM	Sep 12, 2016 7:32:21 PM
Started	Sep 12, 2016 12:00:00 AM	
Completed	Sep 12, 2016 10:34:00 PM	Sep 12, 2016 10:34:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: INTERIOR LIGHT OUT

CAUSE:BLOWN L.E.D ASSY BULB

CORRECTION: REWIRE AND REPLACE L.E.D. ASSY BULB
PARTS:WARRANTY QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Sep-16	Owens,Arthur	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 12-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Sep 12, 2016 10:33:06 PM	No	
20 - Miles			AOWENS	Sep 12, 2016 10:33:06 PM	No	
30 - Kilometers			AOWENS	Sep 12, 2016 10:33:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			AOWENS	Sep 12, 2016 10:33:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27439097
Invoice No. 55345 - 27439097

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
INTERIOR LIGHT OUT		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	85,718 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: INTERIOR LIGHT OUT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Sep-16	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27439097 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27417313
Invoice No. 55345 - 27417313

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Passenger headlight is out		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	84,128 - DH

Chronology		
Reported	Sep 1, 2016 9:54:54 AM	Sep 1, 2016 9:54:54 AM
Started	Sep 1, 2016 12:00:00 AM	
Completed	Sep 1, 2016 2:48:00 PM	Sep 1, 2016 2:48:00 PM
Down Time		

Work Order Notes

Line 10 Headlight P

COMPLAINT:
Passenger side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced passenger side headlight bulb.

PARTS:
9008 headlight bulb qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 01-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 1, 2016 10:08:01 AM	No	
20 - Miles			EDTORRES	Sep 1, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:08:01 AM		
30 - Kilometers			EDTORRES	Sep 1, 2016 10:08:01 AM	No	
40 - Hours			EDTORRES	Sep 1, 2016 10:08:01 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27417313
Invoice No. 55345 - 27417313

Client Department:
Department: 55345M
Work Order Description
Passenger headlight is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 84,128 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Passenger headlight is out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Sep-16	Torres,Edwin	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27417313 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27399751
Invoice No. 55345 - 27399751

Client Department:
Department: 55345M
Work Order Description
Followup---------->needs 2 left rear tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 82,574 - DH

Chronology		
Reported	Aug 22, 2016 10:02:28 PM	Aug 22, 2016 10:02:28 PM
Started	Aug 22, 2016 12:00:00 AM	
Completed	Aug 22, 2016 11:04:00 PM	Aug 22, 2016 11:04:00 PM
Down Time		

Work Order Notes

Line 10 Needs 2 left rear tires
Low thread 3 and 2
2 new tires mounted and balanced
Torque tires 140 lbs second torque 140 lbs part number 050017 qty 2

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Aug-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	81.5	163

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27399751
Invoice No. 55345 - 27399751

Client Department:
Department: 55345M
Work Order Description
Followup---------->needs 2 left rear tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 82,574 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 22, 2016 10:23:05 PM	No	
20 - Miles			RGASPARD	Aug 22, 2016 10:23:05 PM	No	
30 - Kilometers			RGASPARD	Aug 22, 2016 10:23:05 PM	No	
40 - Hours			RGASPARD	Aug 22, 2016 10:23:05 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27399751 Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.07

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27345380
Invoice No. 55345 - 27345380

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,574 - DH

Chronology		
Reported	Aug 22, 2016 1:10:21 PM	Aug 22, 2016 1:10:21 PM
Started	Aug 22, 2016 12:00:00 AM	
Completed	Aug 22, 2016 10:20:00 PM	Aug 22, 2016 10:20:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-16	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,636 - Tread Depth LRO	2 32nds of an inch		RGASPARD	Aug 22, 2016 10:02:28 PM	Yes	27399751
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 22, 2016 10:02:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 22, 2016 10:02:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27345380
Invoice No. 55345 - 27345380

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 82,574 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-16	Gaspard,Ronald	1	0	0
22-Aug-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 22, 2016 10:03:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 22, 2016 10:03:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 22, 2016 10:03:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 22, 2016 10:03:13 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 22, 2016 10:03:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 22, 2016 10:03:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 22, 2016 10:03:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 22, 2016 10:03:13 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	1.07
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27345380
Invoice No. 55345 - 27345380

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	82,574 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 22, 2016 10:03:36 PM	No	
20 - Miles			RGASPARD	Aug 22, 2016 10:03:36 PM	No	
30 - Kilometers			RGASPARD	Aug 22, 2016 10:03:36 PM	No	
40 - Hours			RGASPARD	Aug 22, 2016 10:03:36 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27345380 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27345248
Invoice No. 55345 - 27345248

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs front brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,531 - DH

Chronology		
Reported	Jul 27, 2016 10:23:39 PM	Jul 27, 2016 10:23:39 PM
Started	Jul 27, 2016 12:00:00 AM	
Completed	Jul 27, 2016 11:37:00 PM	Jul 27, 2016 11:37:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs front brakes job

CAUSE:normal wear

CORRECTION: replaced front brake pads , lubed guide pins.
Torque tires 140 lbs second torque 140 lbs
Parts number BRSD1328 qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 27, 2016 10:25:57 PM	No	
20 - Miles			RGASPARD	Jul 27, 2016 10:25:57 PM	No	
30 - Kilometers			RGASPARD	Jul 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:25:57 PM		
40 - Hours			RGASPARD	Jul 27, 2016 10:25:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27215769
Invoice No. 55345 - 27215769

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,531 - DH

Chronology		
Reported	Jul 27, 2016 3:53:59 PM	Jul 27, 2016 3:53:59 PM
Started	Jul 27, 2016 12:00:00 AM	
Completed	Jul 27, 2016 11:37:00 PM	Jul 27, 2016 11:37:00 PM
Down Time		

Work Order Notes

Line 10 PmC
Service
Perform pmC service
Oil filter B329 qty1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jul-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,132 - Brake Pad Thickness RF	3 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jul 27, 2016 10:18:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jul 27, 2016 10:18:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27345248
Invoice No. 55345 - 27345248

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs front brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,531 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 27345248 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27215769
Invoice No. 55345 - 27215769

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,531 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 27-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jul 27, 2016 10:19:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jul 27, 2016 10:19:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jul 27, 2016 10:19:34 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jul 27, 2016 10:19:34 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jul 27, 2016 10:19:34 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Jul 27, 2016 10:19:34 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27215769
Invoice No. 55345 - 27215769

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,531 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 27, 2016 10:19:56 PM	No	
20 - Miles			RGASPARD	Jul 27, 2016 10:19:56 PM	No	
30 - Kilometers			RGASPARD	Jul 27, 2016 10:19:56 PM	No	
40 - Hours			RGASPARD	Jul 27, 2016 10:19:56 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27215769 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	3.07

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27298013
Invoice No. 55345 - 27298013

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE INTERIOR LIGHT		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,355 - DH

Chronology		
Reported	Jul 26, 2016 8:28:27 PM	Jul 26, 2016 8:28:27 PM
Started	Jul 26, 2016 12:00:00 AM	
Completed	Jul 26, 2016 8:33:00 PM	Jul 26, 2016 8:33:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: L.E.D INTERIOR LIGHT OUT

CAUSE:L.E.D. ASSY INTERIOR LIGHT BLEW

CORRECTION: REWIRE AND REPLACE L.E.D. ASSY LIGHT INTERIOR
PARTS: WARRSNTY

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jul-16	Owens,Arthur	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 26-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 26, 2016 8:31:40 PM	No	
20 - Miles			AOWENS	Jul 26, 2016 8:31:40 PM	No	
30 - Kilometers			AOWENS	Jul 26, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:31:40 PM		
40 - Hours			AOWENS	Jul 26, 2016 8:31:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27298013
Invoice No. 55345 - 27298013

Client Department:
Department: 55345M
Work Order Description
REPLACE INTERIOR LIGHT
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,355 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE INTERIOR LIGHT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jul-16	Owens,Arthur	0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27298013 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27260200
Invoice No. 55345 - 27260200

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Bus pulling		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,017 - DH

Chronology		
Reported	Jul 22, 2016 4:18:48 PM	Jul 22, 2016 4:18:48 PM
Started	Jul 25, 2016 12:00:00 AM	
Completed	Jul 25, 2016 3:31:40 PM	Jul 25, 2016 3:31:40 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Pulling

CAUSE:Defective power Steering gear box

CORRECTION:Power steering gear box replacement

Complaint verified
Visual inspection performed and found steering gear box leaking
Power steering gear box replaced
Road test performed ok

Parts used:
One (1) power steering gear box #AC2Z-3504-A

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 25-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 25, 2016 7:53:34 AM	No	
20 - Miles			FSIMON	Jul 25, 2016 7:53:34 AM	No	
30 - Kilometers			FSIMON	Jul 25, 2016 7:53:34 AM	No	
40 - Hours			FSIMON	Jul 25, 2016 7:53:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27260200
Invoice No. 55345 - 27260200

Client Department:
Department: 55345M
Work Order Description
Bus pulling
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,017 - DH

Activity Header
Activity: 15
Activity Note: Power steering gear box
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jul-16	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	1	225	225
06-Feb-17	AC2Z-3504-A-COR	CORE, BOX, GEAR, STEERING, E450 REPLACED BY GU2Z-3504-A	-1	225	-225
25-Jul-16	AC2Z-3504-A	BOX, GEAR, STEERING, E450, '08-'10 REPLACED BY GU2Z-3504-A	1	469.28	469.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jul-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	469.28
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.28**

Work Order Footer

Work Order 27260200 Total	
Parts:	469.28
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**469.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27258659
Invoice No. 55345 - 27258659

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Clearance light is out. Door hinge is bad.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,017 - DH

Chronology		
Reported	Jul 22, 2016 12:11:16 PM	Jul 22, 2016 12:11:16 PM
Started	Jul 22, 2016 12:00:00 AM	
Completed	Jul 22, 2016 12:29:00 PM	Jul 22, 2016 12:29:00 PM
Down Time		

Work Order Notes

Line 10 Hinge

COMPLAINT:
Driver door lower hinge is bad

CAUSE:
The roller and pin thats on the hinge are defected and have snapped out of place.

CORRECTION:
Removed bad hinge and installed a new lower hinge ob driver side

Parts
Qty 1 driver door lower hinge 6C2Z-1522-810Ab Line 20

COMPLAINT:
1 clearance light is out.

CAUSE:
Normal wear

CORRECTION:
Replaced 1 clearance light. parts under warranty. Had to take interior panel out because the wires came off the harness fir the center clearance light.

PARTS:
Parts under warranty.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 22-JUL-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jul 22, 2016 12:23:46 PM	No	
20 - Miles			EDTORRES	Jul 22, 2016 12:23:46 PM	No	
30 - Kilometers			EDTORRES	Jul 22, 2016 12:23:46 PM	No	
40 - Hours			EDTORRES	Jul 22, 2016 12:23:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27258659
Invoice No. 55345 - 27258659

Client Department:
Department: 55345M
Work Order Description
Clearance light is out. Door hinge is bad.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,017 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Clearance light is out.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-16	Torres,Edwin	1.3666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27258659
Invoice No. 55345 - 27258659

Client Department:
Department: 55345M
Work Order Description
Clearance light is out. Door hinge is bad.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,017 - DH

Activity Header
Activity: 25 050/000 GROUP, ACCESSORIES
Activity Note: Door hinge is bad.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Jul-16	6C2Z-1522-810A	OUT OF SERVICE HINGE, DOOR, LOWER, LH, E450	1	46.61	46.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-16	Torres,Edwin	0.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order Footer

Work Order 27258659 Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	1.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27233399
Invoice No. 55345 - 27233399

Client Department:
Department: 55345M
Work Order Description
Needs 1 interior light first right
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,937 - DH

Chronology		
Reported	Jul 8, 2016 9:11:32 PM	Jul 8, 2016 9:11:32 PM
Started	Jul 8, 2016 12:00:00 AM	
Completed	Jul 8, 2016 11:40:00 PM	Jul 8, 2016 11:40:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs 1 interior light

CAUSE:blew

CORRECTION: replaced interior light
Warranty qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 8, 2016 9:14:57 PM	No	
20 - Miles			RGASPARD	Jul 8, 2016 9:14:57 PM	No	
30 - Kilometers			RGASPARD	Jul 8, 2016 9:14:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RGASPARD	Jul 8, 2016 9:14:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27233399
Invoice No. 55345 - 27233399

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs 1 interior light first right		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,937 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jul-16	168	BULB, WEDGE, 12V/3CP	2	0.23	0.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-16	Gaspard,Ronald	0.4333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.46
Labor:	0.00
Labor Hours:	0.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.46**

Work Order Footer

Work Order 27233399 Total	
Parts:	0.46
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27226064
Invoice No. 55345 - 27226064

Client Department:
Department: 55345M
Work Order Description
Driver said driver headlight not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,129 - DH

Chronology		
Reported	Jul 3, 2016 5:30:04 PM	Jul 3, 2016 5:30:04 PM
Started	Jul 3, 2016 12:00:00 AM	
Completed	Jul 5, 2016 8:37:00 AM	Jul 5, 2016 8:37:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said headlight not working

CAUSE:pigtail burn light bulb

CORRECTION: replace pigtail and light bulb completed
Parts# bulb9008 qty 1
Pigtail# 891699 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 3, 2016 7:14:04 PM	No	
20 - Miles			HPIERRE	Jul 3, 2016 7:14:04 PM	No	
30 - Kilometers			HPIERRE	Jul 3, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:14:04 PM		
40 - Hours			HPIERRE	Jul 3, 2016 7:14:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27226064
Invoice No. 55345 - 27226064

Client Department:
Department: 55345M
Work Order Description
Driver said driver headlight not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,129 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41
05-Jul-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jul-16	Pierre,Hubert J	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order Footer

Work Order 27226064 Total	
Parts:	13.20
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27215696
Invoice No. 55345 - 27215696

Client Department:
Department: 55345M
Work Order Description
Needs 2 right rear tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,405 - DH

Chronology		
Reported	Jun 27, 2016 11:05:52 PM	Jun 27, 2016 11:05:52 PM
Started	Jun 27, 2016 12:00:00 AM	
Completed	Jun 27, 2016 11:39:00 PM	Jun 27, 2016 11:39:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs 2 right rear tires

CAUSE:wear

CORRECTION: replaced right rear tires mounted balanced
Torque 140 lbs second torque 140 lbs
LTR2072LL qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 27, 2016 11:08:18 PM	No	
20 - Miles			RGASPARD	Jun 27, 2016 11:08:18 PM	No	
30 - Kilometers			RGASPARD	Jun 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:08:18 PM		
40 - Hours			RGASPARD	Jun 27, 2016 11:08:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27215696
Invoice No. 55345 - 27215696

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs 2 right rear tires		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-16	LTR2072LL	OUT OF SERVICE DO NOT USE TIRE, LT225 75/R16, L780, LING-LONG	2	81.5	163

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order Footer

Work Order 27215696 Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27215714
Invoice No. 55345 - 27215714

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs rear brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Chronology		
Reported	Jun 27, 2016 11:13:05 PM	Jun 27, 2016 11:13:05 PM
Started	Jun 27, 2016 12:00:00 AM	
Completed	Jun 27, 2016 11:38:00 PM	Jun 27, 2016 11:38:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs rear brakes job

CAUSE:cease caliper

CORRECTION: replaced rear brake pads . Cleaned , lubed guide pins
Part number BRSD 1329 qty 1
Torque tires 140 lbs second torque 140 lbs

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 27, 2016 11:15:04 PM	No	
20 - Miles			RGASPARD	Jun 27, 2016 11:15:04 PM	No	
30 - Kilometers			RGASPARD	Jun 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:15:04 PM		
40 - Hours			RGASPARD	Jun 27, 2016 11:15:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27215755
Invoice No. 55345 - 27215755

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs 1 interior light left side		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Chronology		
Reported	Jun 27, 2016 11:30:20 PM	Jun 27, 2016 11:30:20 PM
Started	Jun 27, 2016 12:00:00 AM	
Completed	Jun 27, 2016 11:38:00 PM	Jun 27, 2016 11:38:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs left side interior light

CAUSE:blew

CORRECTION: replaced interior light left side
Under waranty

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 27, 2016 11:35:06 PM	No	
20 - Miles			RGASPARD	Jun 27, 2016 11:35:06 PM	No	
30 - Kilometers			RGASPARD	Jun 27, 2016 11:35:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RGASPARD	Jun 27, 2016 11:35:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27150639
Invoice No. 55345 - 27150639

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Chronology		
Reported	Jun 27, 2016 11:46:27 AM	Jun 27, 2016 11:46:27 AM
Started	Jun 27, 2016 12:00:00 AM	
Completed	Jun 27, 2016 11:38:00 PM	Jun 27, 2016 11:38:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 7qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	1.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 27, 2016 11:01:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 27, 2016 11:01:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27215714
Invoice No. 55345 - 27215714

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs rear brakes job		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-16	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 27215714 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27215755
Invoice No. 55345 - 27215755

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Needs 1 interior light left side		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,405 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27215755 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27150639
Invoice No. 55345 - 27150639

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,405 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
104,000 - Lubricate Chassis	Done		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 27, 2016 11:01:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jun 27, 2016 11:01:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 27, 2016 11:01:52 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27150639
Invoice No. 55345 - 27150639

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,405 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 27, 2016 11:02:12 PM	No	
20 - Miles			RGASPARD	Jun 27, 2016 11:02:12 PM	No	
30 - Kilometers			RGASPARD	Jun 27, 2016 11:02:12 PM	No	
40 - Hours			RGASPARD	Jun 27, 2016 11:02:12 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27150639 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.60

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27168182
Invoice No. 55345 - 27168182

Client Department:
Department: 55345M
Work Order Description
Upper mirror on driver side fell and shattered.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,415 - DH

Chronology		
Reported	Jun 2, 2016 10:06:05 AM	Jun 2, 2016 10:06:05 AM
Started	Jun 2, 2016 12:00:00 AM	
Completed	Jun 2, 2016 11:55:00 AM	Jun 2, 2016 11:55:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Upper mirror fell and shattered after hitting the ground. Driver states that this happened when vehicle went through many pot holes.

CAUSE:
Impact of vehicle going through a pot hole caused the mirror to pop out of place and gravity pulled it to the grow where it shattered.

CORRECTION:
Install a new upper mirror to the passenger mirror housing.

PARTS:
Qty 1 upper mirror passenger side 709644

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 2, 2016 10:14:47 AM	No	
20 - Miles			EDTORRES	Jun 2, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:14:47 AM		
30 - Kilometers			EDTORRES	Jun 2, 2016 10:14:47 AM	No	
40 - Hours			EDTORRES	Jun 2, 2016 10:14:47 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27168182
Invoice No. 55345 - 27168182

Client Department:
Department: 55345M
Work Order Description
Upper mirror on driver side fell and shattered.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,415 - DH

Activity Header
Activity: 15 174 BODY, BUS
Activity Note: Upper mirror on passeneger side fell and shattered.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Torres,Edwin	0.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27168182 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27161950
Invoice No. 55345 - 27161950

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wheel chair bag rip off		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,689 - DH

Chronology		
Reported	May 27, 2016 9:15:39 PM	May 27, 2016 9:15:39 PM
Started	May 27, 2016 12:00:00 AM	
Completed	May 31, 2016 7:55:00 AM	May 31, 2016 7:55:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: wheel chair bag rip off

CAUSE: normal wear

CORRECTION: replace wheel chair bag completed
Part # warranty qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 27, 2016 9:21:29 PM	No	
20 - Miles			HPIERRE	May 27, 2016 9:21:29 PM	No	
30 - Kilometers			HPIERRE	May 27, 2016 9:21:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	May 27, 2016 9:21:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27161950
Invoice No. 55345 - 27161950

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Wheel chair bag rip off		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	70,689 - DH

Activity Header
Activity: 15 002 CAB & SHEET METAL
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-May-16	Pierre,Hubert J	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27161950 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 27071247
Invoice No. 55345 - 27071247

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 69,960 - DH

Chronology		
Reported	May 23, 2016 4:06:29 PM	May 23, 2016 4:06:29 PM
Started	May 23, 2016 12:00:00 AM	
Completed	May 23, 2016 11:10:00 PM	May 23, 2016 11:10:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: service

CORRECTION: perform PMA service
Oil filter B329 qty1
Engine oil 5w20 qty 7qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 23-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 23, 2016 10:25:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	13 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	May 23, 2016 10:25:58 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 23, 2016 10:25:58 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 27071247
Invoice No. 55345 - 27071247

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,960 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-16	Gaspard,Ronald	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 23-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 23, 2016 10:26:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 23, 2016 10:26:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 23, 2016 10:26:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 23, 2016 10:26:51 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 23, 2016 10:26:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 23, 2016 10:26:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 23, 2016 10:26:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 23, 2016 10:26:51 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.60
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 27071247
Invoice No. 55345 - 27071247

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,960 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 23, 2016 10:27:18 PM	No	
20 - Miles			RGASPARD	May 23, 2016 10:27:18 PM	No	
30 - Kilometers			RGASPARD	May 23, 2016 10:27:18 PM	No	
40 - Hours			RGASPARD	May 23, 2016 10:27:18 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 27071247
Invoice No. 55345 - 27071247

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,960 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27071247 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27108111
Invoice No. 55345 - 27108111

Client Department:
Department: 55345M
Work Order Description
INSPECT AND ADJUST DRIVER SIDE CAMERA.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 68,101 - DH

Chronology		
Reported	May 10, 2016 2:18:00 PM	May 10, 2016 2:18:00 PM
Started	May 10, 2016 12:00:00 AM	
Completed	May 10, 2016 9:35:00 PM	May 10, 2016 9:35:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: CAMERA OUT ADJUSTMENT

CAUSE:NO PROBLEM FOUND

CORRECTION: CAMERA IS ALREADY ADJUST TO STAIR WELL AND DRIVER SEAT

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-16	Owens,Arthur	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 10-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	May 10, 2016 9:30:42 PM	No	
20 - Miles			AOWENS	May 10, 2016 9:30:42 PM	No	
30 - Kilometers			AOWENS	May 10, 2016 9:30:42 PM	No	
40 - Hours			AOWENS	May 10, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:30:42 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27108111
Invoice No. 55345 - 27108111

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
INSPECT AND ADJUST DRIVER SIDE CAMERA.		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	68,101 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: INSPECT AND AJUST DRIVER SIDE CAMERA ,PER P.T.C IS POINTING TO THE ROOF.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-16	Owens,Arthur	0.2166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27108111 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27096423
Invoice No. 55345 - 27096423

Client Department:
Department: 55345M
Work Order Description
Uneven wear on front tires. Vehicle sent for an alignment.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 67,782 - DH

Chronology		
Reported	May 5, 2016 8:21:30 AM	May 5, 2016 8:21:30 AM
Started	May 5, 2016 12:00:00 AM	
Completed	May 5, 2016 11:48:00 AM	May 5, 2016 11:48:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Uneven wear on front tires.

CAUSE:
Alignment is off.

CORRECTION:
Mounted and balanced 2 new Bridgestone tires. Placed them in the front of vehicle and set tire pressure to 65 PSI. Torqued lug nuts to 140 lbs. test drove vehicle and re-torqued to 140 LBS. Alignment performed by Callaghan Tires in Rivera Beach, FL.

PARTS:
192659 Bridgestone tires qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 05-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 5, 2016 11:38:48 AM	No	
20 - Miles			EDTORRES	May 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:38:48 AM		
30 - Kilometers			EDTORRES	May 5, 2016 11:38:48 AM	No	
40 - Hours			EDTORRES	May 5, 2016 11:38:48 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27096423
Invoice No. 55345 - 27096423

Client Department:
Department: 55345M
Work Order Description
Uneven wear on front tires. Vehicle sent for an alignment.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 67,782 - DH

Activity Header
Activity: 15
Activity Note: Uneven wear on front tires.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-May-16	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	109.61	109.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-May-16	Torres,Edwin	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	219.22
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**219.22**

Work Order Footer

Work Order 27096423 Total	
Parts:	219.22
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**219.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27012988
Invoice No. 55345 - 27012988

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	65,580 - DH

Chronology		
Reported	Apr 22, 2016 9:13:25 AM	Apr 22, 2016 9:13:25 AM
Started	Apr 22, 2016 12:00:00 AM	
Completed	Apr 22, 2016 9:55:00 PM	Apr 22, 2016 9:55:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE:Service Due by Mileage

CORRECTION: Drain/ Fill Oil and Filter, clean rear AC Filter ,Battery Service lube All pivoting points
Parts# B329 oil Filter Qty (1)
Parts#PA 4075 AirFilter Qty (1)!
Oil (6) Qts 5w20

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
25-Apr-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 22-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,240 - FRA Check Interior Lights	Done	one interior light out	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
33,100 - Check Lights and Reflectors	Done	R/F head light out	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,135 - Brake Rotor LF	1.587 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,136 - Brake Rotor RF	1.598 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,137 - Brake Rotor LR	1.419 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,138 - Brake Rotor RR	1.418 Inch		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 22, 2016 9:37:22 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 22, 2016 9:37:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27012988
Invoice No. 55345 - 27012988

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 65,580 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 22-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 22, 2016 9:39:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Apr 22, 2016 9:39:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Apr 22, 2016 9:39:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Apr 22, 2016 9:39:00 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27012988
Invoice No. 55345 - 27012988

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 65,580 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 22, 2016 9:39:28 PM	No	
20 - Miles			DARTHURS	Apr 22, 2016 9:39:28 PM	No	
30 - Kilometers			DARTHURS	Apr 22, 2016 9:39:28 PM	No	
40 - Hours			DARTHURS	Apr 22, 2016 9:39:28 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27012988 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27071233
Invoice No. 55345 - 27071233

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
R/F head light/interior light		Ford E350 Champion Crusaders	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	65,580 - DH

Chronology		
Reported	Apr 22, 2016 9:41:32 PM	Apr 22, 2016 9:41:32 PM
Started	Apr 22, 2016 12:00:00 AM	
Completed	Apr 22, 2016 9:54:00 PM	Apr 22, 2016 9:54:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: interior light/R/F head light out

CAUSE:blown bulbs

CORRECTION: replace R/F head light bulb /interior light
Part#H13 Qty (1)
Parts interior light Qty (2) under warranty,

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 22, 2016 9:53:38 PM	No	
20 - Miles			DARTHURS	Apr 22, 2016 9:53:38 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			DARTHURS	Apr 22, 2016 9:53:38 PM	No	
40 - Hours			DARTHURS	Apr 22, 2016 9:53:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27071233
Invoice No. 55345 - 27071233

Client Department:
Department: 55345M
Work Order Description
R/F head light/interior light
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 65,580 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Head light/ interior light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27071233 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27048831
Invoice No. 55345 - 27048831

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Check Clearance lights		Ford E350 Champion Crusaders	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	64,384 - DH

Chronology		
Reported	Apr 13, 2016 8:19:35 AM	Apr 13, 2016 8:19:35 AM
Started	Apr 13, 2016 12:00:00 AM	
Completed	Apr 13, 2016 10:55:00 AM	Apr 13, 2016 10:55:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Clearance lights not working

CAUSE:Defective fuse

CORRECTION: Fuse replacement

Complaint verified
One (1) fuse replaced
Clearance lights glowing ok
Bus returned to its predetermined spot

Parts used :
One (1) fuse 15 amps

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 13-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done		FSIMON	Apr 13, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:28:10 AM		
20 - Miles			FSIMON	Apr 13, 2016 9:28:10 AM	No	
30 - Kilometers			FSIMON	Apr 13, 2016 9:28:10 AM	No	
40 - Hours			FSIMON	Apr 13, 2016 9:28:10 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27048831
Invoice No. 55345 - 27048831

Client Department:
Department: 55345M
Work Order Description
Check Clearance lights
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 64,384 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-16	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27048831 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26915278
Invoice No. 55345 - 26915278

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,400 - DH

Chronology		
Reported	Mar 22, 2016 10:16:18 AM	Mar 22, 2016 10:16:18 AM
Started	Mar 22, 2016 12:00:00 AM	
Completed	Mar 22, 2016 11:40:00 PM	Mar 22, 2016 11:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: regular maintenance

CORRECTION: perform service,lube all pivoting point and cross rotate front tires complete
Parts # oil filter B329 qty1

Oil #5w20 qt 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 22-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,135 - Brake Rotor LF	40 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,136 - Brake Rotor RF	40 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,137 - Brake Rotor LR	38 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,138 - Brake Rotor RR	38 Inch		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 22, 2016 8:43:39 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 22, 2016 8:43:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26915278
Invoice No. 55345 - 26915278

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,400 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 22-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 22, 2016 8:44:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 22, 2016 8:44:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 22, 2016 8:44:21 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26915278
Invoice No. 55345 - 26915278

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 61,400 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 22-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 22, 2016 8:44:36 PM	No	
20 - Miles			HPIERRE	Mar 22, 2016 8:44:36 PM	No	
30 - Kilometers			HPIERRE	Mar 22, 2016 8:44:36 PM	No	
40 - Hours			HPIERRE	Mar 22, 2016 8:44:36 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26915278 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27006321
Invoice No. 55345 - 27006321

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE INTERIOR LIGHT		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	60,426 - DH

Chronology		
Reported	Mar 16, 2016 5:57:02 PM	Mar 16, 2016 5:57:02 PM
Started	Mar 16, 2016 12:00:00 AM	
Completed	Mar 16, 2016 11:04:00 PM	Mar 16, 2016 11:04:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: interior light not working

CAUSE:blew out

CORRECTION: replaced right rear interior light.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 16, 2016 11:01:51 PM	No	
20 - Miles			RGASPARD	Mar 16, 2016 11:01:51 PM	No	
30 - Kilometers			RGASPARD	Mar 16, 2016 11:01:51 PM	No	
40 - Hours			RGASPARD	Mar 16, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:01:51 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27006321
Invoice No. 55345 - 27006321

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE INTERIOR LIGHT		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	60,426 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE INTERIOR LIGHT
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Gaspard,Ronald	0.9333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27006321 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26948966
Invoice No. 55345 - 26948966

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE WHEEL CHAIR BAG		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,446 - DH

Chronology		
Reported	Mar 8, 2016 9:48:15 PM	Mar 8, 2016 9:48:15 PM
Started	Mar 10, 2016 12:00:00 AM	
Completed	Mar 10, 2016 10:42:00 PM	Mar 10, 2016 10:42:00 PM
Down Time		

Work Order Notes

Line 10 Needs wheel chair bag
Ripped
Replaced whell chair bag qty1

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE WHEEL CHAIR BAG
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-16	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26948966
Invoice No. 55345 - 26948966

Client Department:
Department: 55345M
Work Order Description
REPLACE WHEEL CHAIR BAG
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,446 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-16	Gaspard,Ronald	0.95	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 10, 2016 10:37:35 PM	No	
20 - Miles			RGASPARD	Mar 10, 2016 10:37:35 PM	No	
30 - Kilometers			RGASPARD	Mar 10, 2016 10:37:35 PM	No	
40 - Hours			RGASPARD	Mar 10, 2016 10:37:35 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26948966 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26837170
Invoice No. 55345 - 26837170

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,060 - DH

Chronology		
Reported	Feb 18, 2016 2:31:10 PM	Feb 18, 2016 2:31:10 PM
Started	Feb 18, 2016 12:00:00 AM	
Completed	Feb 18, 2016 11:36:00 PM	Feb 18, 2016 11:36:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:service

CORRECTION: perform pmA
Oil filter B329 qty1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Feb-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Feb-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 18-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Feb 18, 2016 11:30:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 18, 2016 11:30:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26837170
Invoice No. 55345 - 26837170

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,060 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Feb-16	Gaspard,Ronald	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 18-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 18, 2016 11:31:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 18, 2016 11:31:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 18, 2016 11:31:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 18, 2016 11:31:05 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 18, 2016 11:31:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 18, 2016 11:31:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 18, 2016 11:31:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 18, 2016 11:31:05 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26837170
Invoice No. 55345 - 26837170

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,060 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Feb-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 18-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 18, 2016 11:31:33 PM	No	
20 - Miles			RGASPARD	Feb 18, 2016 11:31:33 PM	No	
30 - Kilometers			RGASPARD	Feb 18, 2016 11:31:33 PM	No	
40 - Hours			RGASPARD	Feb 18, 2016 11:31:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26837170 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.23

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26883736
Invoice No. 55345 - 26883736

Client Department:
Department: 55345M
Work Order Description
TRANSMISSION SERVICE PERFORM
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 55,780 - DH

Chronology		
Reported	Feb 9, 2016 4:14:00 PM	Feb 9, 2016 4:14:00 PM
Started	Feb 10, 2016 12:00:00 AM	
Completed	Feb 10, 2016 7:47:00 AM	Feb 10, 2016 7:47:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Transmission service

CAUSE:Transmission service due

CORRECTION:Transmission service completion

Transmission fluid changed
Transmission filter replaced
Ten (10 quarts) transmission fluid added to trani

Parts utilized:
One (1) transmission filter #8C3Z-7A098-D

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done		FSIMON	Feb 10, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				4:06:09 PM		
20 - Miles			FSIMON	Feb 10, 2016 4:06:09 PM	No	
30 - Kilometers			FSIMON	Feb 10, 2016 4:06:09 PM	No	
40 - Hours			FSIMON	Feb 10, 2016 4:06:09 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26883736
Invoice No. 55345 - 26883736

Client Department:
Department: 55345M
Work Order Description
TRANSMISSION SERVICE PERFORM
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 55,780 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: PERFORM TRANSMISSION SERVICE
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Feb-16	8C3Z-7A098-D	FILTER, TRANSMISSION	1	36.5	36.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Feb-16	Simon,Fritz	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	36.50
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.50**

Work Order Footer

Work Order 26883736 Total	
Parts:	36.50
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**36.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26866134
Invoice No. 55345 - 26866134

Client Department:
Department: 55345M
Work Order Description
Send to mobility works for wheel chair lift repair under warranty
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 53,892 - DH

Chronology		
Reported	Jan 27, 2016 1:29:37 PM	Jan 27, 2016 1:29:37 PM
Started	Jan 27, 2016 12:00:00 AM	
Completed	Jan 27, 2016 2:23:00 PM	Jan 27, 2016 2:23:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: wheel chair lift bridgeplate would not raise.

CAUSE: shocks worn out on bridgeplate arms.

CORRECTION: replace both front and rear arms and gas shocks.
Tested and issue resolved.

No parts used, covered under warranty.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-16	Manzino,Robert C	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 27-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Jan 27, 2016 1:51:00 PM	No	
20 - Miles			RMANZINO	Jan 27, 2016 1:51:00 PM	No	
30 - Kilometers			RMANZINO	Jan 27, 2016 1:51:00 PM	No	
40 - Hours			RMANZINO	Jan 27, 2016 1:51:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26866134
Invoice No. 55345 - 26866134

Client Department:
Department: 55345M
Work Order Description
Send to mobility works for wheel chair lift repair under warranty
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 53,892 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: Send vehicle for wheel chair lift repair under warranty
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-16	Manzino,Robert C	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26866134 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26833680
Invoice No. 55345 - 26833680

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE FRONT BRAKES		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,669 - DH

Chronology		
Reported	Jan 18, 2016 7:44:35 PM	Jan 18, 2016 7:44:35 PM
Started	Jan 19, 2016 12:00:00 AM	
Completed	Jan 19, 2016 12:28:00 AM	Jan 19, 2016 12:28:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs front brakes job

CAUSE:normal wear

CORRECTION: replaced front brake pads lubed guide pins
Torque 140lbs second torque 140lbs
Part number BRSD 1328 qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jan-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 19, 2016 12:24:13 AM	No	
20 - Miles			RGASPARD	Jan 19, 2016 12:24:13 AM	No	
30 - Kilometers			RGASPARD	Jan 19, 2016 12:24:13 AM	No	
40 - Hours			RGASPARD	Jan 19, 2016 12:24:13 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26833680
Invoice No. 55345 - 26833680

Client Department:
Department: 55345M
Work Order Description
REPLACE FRONT BRAKES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,669 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE FRONT BRAKES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26833680 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 26712467
Invoice No. 55345 - 26712467

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,669 - DH

Chronology		
Reported	Jan 18, 2016 11:30:15 AM	Jan 18, 2016 11:30:15 AM
Started	Jan 19, 2016 12:00:00 AM	
Completed	Jan 19, 2016 12:23:00 AM	Jan 19, 2016 12:23:00 AM
Down Time		

Work Order Notes

Line 10 Pmc
Service
Perform pmC service
Oil filter B 329 qty1
Engine oil 5w20 qty 6qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 19-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 19, 2016 12:12:59 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 19, 2016 12:12:59 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 26712467
Invoice No. 55345 - 26712467

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,669 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Gaspard,Ronald	1.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 19-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 19, 2016 12:14:53 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jan 19, 2016 12:14:53 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jan 19, 2016 12:14:53 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jan 19, 2016 12:14:53 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jan 19, 2016 12:14:53 AM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Jan 19, 2016 12:14:53 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 26712467
Invoice No. 55345 - 26712467

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,669 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 19, 2016 12:15:32 AM	No	
20 - Miles			RGASPARD	Jan 19, 2016 12:15:32 AM	No	
30 - Kilometers			RGASPARD	Jan 19, 2016 12:15:32 AM	No	
40 - Hours			RGASPARD	Jan 19, 2016 12:15:32 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 26712467
Invoice No. 55345 - 26712467

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,669 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26712467 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26776084
Invoice No. 55345 - 26776084

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FRONT TIRES UNDER SPECS		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	51,518 - DH

Chronology		
Reported	Jan 11, 2016 10:20:00 AM	Jan 11, 2016 10:20:00 AM
Started	Jan 11, 2016 12:00:00 AM	
Completed	Jan 11, 2016 11:20:00 AM	Jan 11, 2016 11:20:00 AM
Down Time		

Work Order Notes

Line 10 Tires

COMPLAINT:
Check tires for low tread

CAUSE:
Normal wear

CORRECTION:
Mounted and balanced 2 Crosswind tires. Set tires to 65 psi. Install 2 new tires in the front. Torque lug nuts to 140 LBS. Test drove. Re-torqued to 140 LBS.

Parts. Crosswind tires. Part # LTR2072LL qty2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-16	Torres,Edwin	1	0	0
11-Jan-16	Torres,Edwin	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 11-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jan 11, 2016 11:10:13 AM	No	
20 - Miles			EDTORRES	Jan 11, 2016 11:10:13 AM	No	
30 - Kilometers			EDTORRES	Jan 11, 2016 11:10:13 AM	No	
40 - Hours			EDTORRES	Jan 11, 2016 11:10:13 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26776084
Invoice No. 55345 - 26776084

Client Department:
Department: 55345M
Work Order Description
FRONT TIRES UNDER SPECS
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 51,518 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jan-16	LTR2072LL	OUT OF SERVICE DO NOT USE TIRE, LT225 75/R16, L780, LING-LONG	-2	75.71	-151.42
11-Jan-16	LTR2072LL	OUT OF SERVICE DO NOT USE TIRE, LT225 75/R16, L780, LING-LONG	2	75.71	151.42
13-Jan-16	LTR2072LL	OUT OF SERVICE DO NOT USE TIRE, LT225 75/R16, L780, LING-LONG	2	79.95	159.9

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	159.90
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**159.90**

Work Order Footer

Work Order 26776084 Total	
Parts:	159.90
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**159.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26737944
Invoice No. 55345 - 26737944

Client Department:
Department: 55345M
Work Order Description
Camera red light button not flashing
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: Yes

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 50,641 - DH

Chronology		
Reported	Jan 4, 2016 7:31:01 AM	Jan 4, 2016 7:31:01 AM
Started	Jan 4, 2016 12:00:00 AM	
Completed	Jan 4, 2016 1:54:00 PM	Jan 4, 2016 1:54:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT Camera red button not flashing

CAUSE:Dirt

CORRECTION:Camera software cleaned

Camera software cleaned
Ignition turned on
Red button has being flashing ok

No parts used

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 04-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 4, 2016 9:35:36 AM	No	
20 - Miles			FSIMON	Jan 4, 2016 9:35:36 AM	No	
30 - Kilometers			FSIMON	Jan 4, 2016 9:35:36 AM	No	
40 - Hours			FSIMON	Jan 4, 2016 9:35:36 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26737944
Invoice No. 55345 - 26737944

Client Department:
Department: 55345M
Work Order Description
Camera red light button not flashing
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: Yes

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 50,641 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-16	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26737944 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26713078
Invoice No. 55345 - 26713078

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Driver side headlight out		Ford E350 Champion Crusaders	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,472 - DH

Chronology		
Reported	Dec 17, 2015 10:31:58 AM	Dec 17, 2015 10:31:58 AM
Started		
Completed	Dec 18, 2015 8:51:00 AM	Dec 18, 2015 8:51:00 AM
Down Time		

Work Order Notes

Line 10 . Line 20 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: driver complaint that driver side headlight is out

CAUSE: confirmed complaint and found low beam bulb blown.

CORRECTION: removed driver side headlight assembly.
Removed headlight bulb.
Installed new headlight bulb, applied dielectric grease to connector.
Tested operation of all lights in front end.
All ok.
Reinstalled headlight assembly.
Issue resolved.

H13 (1) qty - headlight bulb

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 18-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Dec 18, 2015 6:25:17 AM	No	
20 - Miles			RMANZINO	Dec 18, 2015 6:25:17 AM	No	
30 - Kilometers			RMANZINO	Dec 18, 2015 6:25:17 AM	No	
40 - Hours			RMANZINO	Dec 18, 2015 6:25:17 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26713078
Invoice No. 55345 - 26713078

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Driver side headlight out		Ford E350 Champion Crusaders	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,472 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Install new driver side headlight
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Dec-15	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Dec-15	Manzino,Robert C	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order Footer

Work Order 26713078 Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26595980
Invoice No. 55345 - 26595980

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,237 - DH

Chronology		
Reported	Dec 16, 2015 3:05:06 PM	Dec 16, 2015 3:05:06 PM
Started	Dec 16, 2015 12:00:00 AM	
Completed	Dec 16, 2015 11:20:00 PM	Dec 16, 2015 11:20:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm a

CAUSE: regular maintenance

CORRECTION: perform service lube all pivoting point cross rotate front tires completed
Parts # oil filter b329 qty 1
Oil # 5w20 qt 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Dec-15	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,420 - Check Hood	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,135 - Brake Rotor LF	37 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,136 - Brake Rotor RF	37 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,137 - Brake Rotor LR	34 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,138 - Brake Rotor RR	34 Inch		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Dec 16, 2015 9:26:47 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Dec 16, 2015 9:26:47 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26595980
Invoice No. 55345 - 26595980

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,237 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Dec-15	Pierre,Hubert J	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 16, 2015 9:28:10 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Dec 16, 2015 9:28:10 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 16, 2015 9:28:10 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.45
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26595980
Invoice No. 55345 - 26595980

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,237 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Dec-15	Pierre,Hubert J	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 16, 2015 9:28:33 PM	No	
20 - Miles			HPIERRE	Dec 16, 2015 9:28:33 PM	No	
30 - Kilometers			HPIERRE	Dec 16, 2015 9:28:33 PM	No	
40 - Hours			HPIERRE	Dec 16, 2015 9:28:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26595980 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26691490
Invoice No. 55345 - 26691490

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REPLACE INTERIOR LIGHTS		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	47,045 - DH

Chronology		
Reported	Dec 8, 2015 7:28:53 PM	Dec 8, 2015 7:28:53 PM
Started	Dec 8, 2015 12:00:00 AM	
Completed	Dec 8, 2015 11:21:00 PM	Dec 8, 2015 11:21:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: left side interior light not working.

CAUSE:blew.

CORRECTION: replaced interior light.
Part under warranty

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 08-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 8, 2015 11:15:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			RGASPARD	Dec 8, 2015 11:15:19 PM	No	
30 - Kilometers			RGASPARD	Dec 8, 2015 11:15:19 PM	No	
40 - Hours			RGASPARD	Dec 8, 2015 11:15:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26691490
Invoice No. 55345 - 26691490

Client Department:
Department: 55345M
Work Order Description
REPLACE INTERIOR LIGHTS
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 47,045 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE INTERIOR Lights
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-15	Gaspard,Ronald	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26691490 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 26595974
Invoice No. 55345 - 26595974

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---->BRAKE PADS
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,953 - DH

Chronology		
Reported	Nov 16, 2015 11:31:19 PM	Nov 16, 2015 11:31:19 PM
Started	Nov 16, 2015 12:00:00 AM	
Completed	Nov 16, 2015 11:42:00 PM	Nov 16, 2015 11:42:00 PM
Down Time		

Work Order Notes

Line 10 Needs rear brakes job.
Replaced rear brake pads , lubed guide pins.
Part number BRSD1329 qty1
Torque tires to spec...
First torque 140lbs ,test drive second torque 140lbs.

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: needs rear brakes job.
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-15	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 26595974 Total	
Parts:	44.48
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26546453
Invoice No. 55345 - 26546453

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,953 - DH

Chronology		
Reported	Nov 16, 2015 1:18:06 PM	Nov 16, 2015 1:18:06 PM
Started	Nov 16, 2015 12:00:00 AM	
Completed	Nov 16, 2015 11:37:00 PM	Nov 16, 2015 11:37:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA
Engine oil 5w20 qty 6qts
Oil filter B329 qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.84	1.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Gaspard,Ronald	1.8833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 16-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch	needs rear brakes job.	RGASPARD	Nov 16, 2015 11:31:40 PM	Yes	26595974
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 16, 2015 11:31:40 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 16, 2015 11:31:40 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.84
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26546453
Invoice No. 55345 - 26546453

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,953 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Gaspard,Ronald	0.8	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 16-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 16, 2015 11:32:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 16, 2015 11:32:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 16, 2015 11:32:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 16, 2015 11:32:37 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 16, 2015 11:32:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 16, 2015 11:32:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 16, 2015 11:32:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 16, 2015 11:32:37 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.80
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26546453
Invoice No. 55345 - 26546453

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,953 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Nov-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 16-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 16, 2015 11:33:13 PM	No	
20 - Miles			RGASPARD	Nov 16, 2015 11:33:13 PM	No	
30 - Kilometers			RGASPARD	Nov 16, 2015 11:33:13 PM	No	
40 - Hours			RGASPARD	Nov 16, 2015 11:33:13 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26546453 Total	
Parts:	1.84
Labor:	0.00
Labor Hours:	2.73

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26591219
Invoice No. 55345 - 26591219

Client Department:
Department: 55345M
Work Order Description
Check headlight
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 43,411 - DH

Chronology		
Reported	Nov 13, 2015 6:38:34 AM	Nov 13, 2015 6:38:34 AM
Started	Nov 13, 2015 6:40:00 AM	
Completed	Nov 13, 2015 7:16:00 AM	Nov 13, 2015 7:16:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:left head light not glowing

CAUSE:Burnt headlight bulb

CORRECTION:Headlight bulb replacement

Driver's complaint verified
Headlight bulb burnt
Headlight bulb replaced
Headlight glowing ok

Part utilized:
Headlight bulb# H13 (1)QTY

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Nov-15	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	5.79	5.79

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 13-NOV-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 13, 2015 6:41:20 AM	No	
20 - Miles			FSIMON	Nov 13, 2015 6:41:20 AM	No	
30 - Kilometers			FSIMON	Nov 13, 2015 6:41:20 AM	No	
40 - Hours			FSIMON	Nov 13, 2015 6:41:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26591219
Invoice No. 55345 - 26591219

Client Department:
Department: 55345M
Work Order Description
Check headlight
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 43,411 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-15	Simon,Fritz	0.48	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26591219 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26574518
Invoice No. 55345 - 26574518

Client Department:
Department: 55345M
Work Order Description
W/C door strut bracket came off, also right rear mud flap fell off
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 42,627 - DH

Chronology		
Reported	Nov 6, 2015 6:36:15 AM	Nov 6, 2015 6:36:15 AM
Started	Nov 6, 2015 12:00:00 AM	
Completed	Nov 9, 2015 9:00:00 AM	Nov 9, 2015 9:00:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: wheel chair door strut broke off door frame

CAUSE: door was most likely over extended, causing bracket to pull off door frame

CORRECTION: inspected and found no further damages.
Drilled out old rivets.
Reinstalled bracket with new rivets
Tested operation and issue resolved

No parts used Line 20 Driver complaint that the right rear mud flap was missing

Confirmed complaint, and inspected for any damages.
No further damage found, but mud flap and bracket that mud flap is attached to is missing.
Measured bracket size and mudflap pattern from another vehicle.
Cut new mudflap to correct size
Cut L bracket to correct size
Drilled new holes in mud flap and bracket to mount to vehicle.
Installed new mud flap and bracket assembly onto vehicle.
Issue resolved.

0541037(1) qty - mudflap

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Nov-15	0541037	FLAP, MUD, 18 X 24 W/LOGO	1	7.27	7.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Manzino,Robert C	0.1666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 06-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Nov 6, 2015 8:30:45 AM	No	
20 - Miles			RMANZINO	Nov 6, 2015 8:30:45 AM	No	
30 - Kilometers			RMANZINO	Nov 6, 2015 8:30:45 AM	No	
40 - Hours			RMANZINO	Nov 6, 2015 8:30:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	7.27
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26574518
Invoice No. 55345 - 26574518

Client Department:
Department: 55345M
Work Order Description
W/C door strut bracket came off, also right rear mud flap fell off
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 42,627 - DH

Activity Header
Activity: 15 000 CAB, CLIMATE CONTROL, INSTRUMENTS & AERODYNAMIC DEVICES
Activity Note: Wheel chair door strut bracket came off door frame
Reason for Repair: 41 Abuse of Equipment - 56210
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Nov-15	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	-1	77.86	-77.86
09-Nov-15	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	1	77.86	77.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Manzino,Robert C	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26574518
Invoice No. 55345 - 26574518

Client Department:
Department: 55345M
Work Order Description
W/C door strut bracket came off, also right rear mud flap fell off
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 42,627 - DH

Activity Header
Activity: 25 002 CAB & SHEET METAL
Activity Note: Right rear mud flap fell off vehicle
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Manzino,Robert C	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26574518 Total	
Parts:	7.27
Labor:	0.00
Labor Hours:	2.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26567440
Invoice No. 55345 - 26567440

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Driver report of nail in front left tire		Ford E350 Champion Crusaders	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,599 - DH

Chronology		
Reported	Nov 2, 2015 7:30:14 AM	Nov 2, 2015 7:30:14 AM
Started	Nov 2, 2015 12:00:00 AM	
Completed	Nov 2, 2015 7:37:00 AM	Nov 2, 2015 7:37:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: driver report of nail in front left tire

CAUSE: inspected tire and found small nail in tread. Checked tire pressure and it was at 65 psi

CORRECTION: removed nail and checked for leaks with soap and water.
No leak was found
Issue resolved and returned to service

No parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Nov-15	Manzino,Robert C	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 02-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Nov 2, 2015 7:36:05 AM	No	
20 - Miles			RMANZINO	Nov 2, 2015 7:36:05 AM	No	
30 - Kilometers			RMANZINO	Nov 2, 2015 7:36:05 AM	No	
40 - Hours			RMANZINO	Nov 2, 2015 7:36:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26567440
Invoice No. 55345 - 26567440

Client Department:
Department: 55345M
Work Order Description
Driver report of nail in front left tire
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,599 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note: Driver report of nail in front left tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Nov-15	Manzino,Robert C	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26567440 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26563578
Invoice No. 55345 - 26563578

Client Department:
Department: 55345M
Work Order Description
Driver report that ac evap fan was hanging from under vehicle
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,283 - DH

Chronology		
Reported	Oct 29, 2015 8:16:00 AM	Oct 29, 2015 8:16:00 AM
Started	Oct 29, 2015 12:00:00 AM	
Completed	Oct 29, 2015 8:23:00 AM	Oct 29, 2015 8:23:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: driver report that the rear ac evaporator fan was hanging from under vehicle.

CAUSE: confirmed report. Found fan hanging with broken fan blades.

CORRECTION: inspected for damages and none found.
Removed old clips
Installed new clips onto new fan assembly
Installed new fan assembly onto evap
Tested and fans did not run
Diagnosed as no power to fans
Found fuse blown.
Installed new fuse and tested working
All ok at this time.
Vehicle returned to service. Line 20 27059482a (1) qty rear ac evaporator fan assembly

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Nov-15	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	1	77.86	77.86

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-15	Manzino,Robert C	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 29-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Oct 29, 2015 8:22:45 AM	No	
20 - Miles			RMANZINO	Oct 29, 2015 8:22:45 AM	No	
30 - Kilometers			RMANZINO	Oct 29, 2015 8:22:45 AM	No	
40 - Hours			RMANZINO	Oct 29, 2015 8:22:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	77.86
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26563578
Invoice No. 55345 - 26563578

Client Department:
Department: 55345M
Work Order Description
Driver report that ac evap fan was hanging from under vehicle
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,283 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear ac evap fan hanging from vehicle
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-15	Manzino,Robert C	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26563578 Total	
Parts:	77.86
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**77.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26454344
Invoice No. 55345 - 26454344

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,502 - DH

Chronology		
Reported	Oct 15, 2015 2:48:39 PM	Oct 15, 2015 2:48:39 PM
Started	Oct 15, 2015 12:00:00 AM	
Completed	Oct 15, 2015 10:28:00 PM	Oct 15, 2015 10:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:service.

CORRECTION:perform pmB service
Engine oil 5w20 qty 6 qts
Oil filter B329 qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Oct-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.82	1.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-15	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 15-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 15, 2015 10:22:01 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 15, 2015 10:22:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.82
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26454344
Invoice No. 55345 - 26454344

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 39,502 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-15	Gaspard,Ronald	0.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 15-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 15, 2015 10:23:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 15, 2015 10:23:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Oct 15, 2015 10:23:16 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Oct 15, 2015 10:23:16 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26454344
Invoice No. 55345 - 26454344

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	39,502 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-15	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 15-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 15, 2015 10:23:51 PM	No	
20 - Miles			RGASPARD	Oct 15, 2015 10:23:51 PM	No	
30 - Kilometers			RGASPARD	Oct 15, 2015 10:23:51 PM	No	
40 - Hours			RGASPARD	Oct 15, 2015 10:23:51 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26454344 Total	
Parts:	1.82
Labor:	0.00
Labor Hours:	2.90

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26530582
Invoice No. 55345 - 26530582

Client Department:
Department: 55345M
Work Order Description
Driver complaint of camera not blinking
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 38,080 - DH

Chronology		
Reported	Oct 7, 2015 6:48:24 AM	Oct 7, 2015 6:48:24 AM
Started	Oct 7, 2015 12:00:00 AM	
Completed	Oct 7, 2015 6:54:00 AM	Oct 7, 2015 6:54:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: driver complaint of camera event marker not blinking

CAUSE: could not replicate problem. Camera system was working correctly when vehicle brought in to diagnose.

CORRECTION: no issue found at this time. Line 20 No parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 07-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Oct 7, 2015 6:54:24 AM	No	
20 - Miles			RMANZINO	Oct 7, 2015 6:54:24 AM	No	
30 - Kilometers			RMANZINO	Oct 7, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:54:24 AM		
40 - Hours			RMANZINO	Oct 7, 2015 6:54:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26530582
Invoice No. 55345 - 26530582

Client Department:
Department: 55345M
Work Order Description
Driver complaint of camera not blinking
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 38,080 - DH

Activity Header
Activity: 15
Activity Note: Diagnose camera issue
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-15	Manzino,Robert C	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26530582 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26506006
Invoice No. 55345 - 26506006

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Repair exhaust hangers		Ford E350 Champion Crusaders	
Requested By:	RMANZINO	**Status:**	40 - Closed (40)
Created By:	RMANZINO	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,795 - DH

Chronology		
Reported	Sep 24, 2015 7:52:06 AM	Sep 24, 2015 7:52:06 AM
Started	Sep 24, 2015 12:00:00 AM	
Completed	Sep 24, 2015 7:59:00 AM	Sep 24, 2015 7:59:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: tailpipe hanging from vehicle

CAUSE: found both rear exhaust hangers not attached and third exhaust hanger had bolt loose

CORRECTION: removed and straightened the two rear most exhaust hangers and reinstalled. Tightened bolt for third hanger. All exhaust is now tightly secured at this time. Line 20 No parts used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 24-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Sep 24, 2015 7:59:38 AM	No	
20 - Miles			RMANZINO	Sep 24, 2015 7:59:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			RMANZINO	Sep 24, 2015 7:59:38 AM	No	
40 - Hours			RMANZINO	Sep 24, 2015 7:59:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26506006
Invoice No. 55345 - 26506006

Client Department:
Department: 55345M
Work Order Description
Repair exhaust hangers
Requested By: RMANZINO
Created By: RMANZINO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 36,795 - DH

Activity Header
Activity: 15
Activity Note: Repair exhaust hangers
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Sep-15	Manzino,Robert C	1.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26506006 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26260684
Invoice No. 55345 - 26260684

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,276 - DH

Chronology		
Reported	Sep 14, 2015 3:26:44 PM	Sep 14, 2015 3:26:44 PM
Started	Sep 14, 2015 6:15:00 PM	
Completed	Sep 15, 2015 3:59:41 PM	Sep 15, 2015 3:59:41 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PMA SERVICE COMPLETED

B329 1QTY

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Pierre,Hubert J	1.77	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 14-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,420 - Check Hood	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	need 4 rear tire	HPIERRE	Sep 14, 2015 8:01:13 PM	Yes	26453967
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,135 - Brake Rotor LF	38 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,136 - Brake Rotor RF	38 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,137 - Brake Rotor LR	34 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,138 - Brake Rotor RR	34 Inch		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Sep 14, 2015 8:01:13 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Sep 14, 2015 8:01:13 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26260684
Invoice No. 55345 - 26260684

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 35,276 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Pierre,Hubert J	0.58	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 14-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Sep 14, 2015 8:36:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Sep 14, 2015 8:36:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Sep 14, 2015 8:36:29 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.58
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26260684
Invoice No. 55345 - 26260684

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,276 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Pierre,Hubert J	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 14, 2015 8:37:16 PM	No	
20 - Miles			HPIERRE	Sep 14, 2015 8:37:16 PM	No	
30 - Kilometers			HPIERRE	Sep 14, 2015 8:37:16 PM	No	
40 - Hours			HPIERRE	Sep 14, 2015 8:37:16 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26260684 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	2.37

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26453259
Invoice No. 55345 - 26453259

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Install driver side step rail		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,276 - DH

Chronology		
Reported	Sep 14, 2015 6:46:21 PM	Sep 14, 2015 6:46:21 PM
Started	Sep 14, 2015 9:50:00 PM	
Completed	Sep 14, 2015 11:13:00 PM	Sep 14, 2015 11:13:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 Install driver side step rail completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Pierre,Hubert J	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 14, 2015 11:09:00 PM	No	
20 - Miles			HPIERRE	Sep 14, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:09:00 PM		
30 - Kilometers			HPIERRE	Sep 14, 2015 11:09:00 PM	No	
40 - Hours			HPIERRE	Sep 14, 2015 11:09:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26453259
Invoice No. 55345 - 26453259

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Install driver side step rail		Ford E350 Champion Crusaders	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,276 - DH

Activity Header
Activity: 15 078 TRIM & MISCELLANEOUS HARDWARE
Activity Note: Install driver side step rail
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26453259 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 26453967
Invoice No. 55345 - 26453967

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
FTLMPMI_FOLLOWUP		Ford E350 Champion Crusaders	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	35,276 - DH

Chronology

Reported	Sep 14, 2015 8:01:14 PM	Sep 14, 2015 8:01:14 PM
Started	Sep 14, 2015 12:00:00 AM	
Completed	Sep 14, 2015 9:49:00 PM	Sep 14, 2015 9:49:00 PM
Down Time		

Work Order Notes

Line 10 Mount and balance 4 tire completed
Parts # bridgestone # 206361 Line 20 Torque vehicle to 40 ft pound and drive re-torque to 40 ft pound completed

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: need 4 rear tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Sep-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	4	151.66	606.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-15	Pierre,Hubert J	2.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	606.64
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**606.64**

Work Order Footer

Work Order 26453967 Total	
Parts:	606.64
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**606.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26269194
Invoice No. 55345 - 26269194

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
tires		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,661 - DH

Chronology		
Reported	Aug 20, 2015 11:44:00 AM	Aug 20, 2015 11:44:00 AM
Started	Aug 20, 2015 12:00:00 AM	
Completed	Aug 20, 2015 1:36:00 PM	Aug 20, 2015 1:36:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: check tires

CAUSE: routine inspection

CORRECTION: inspected tires and found rears to be out of spec.
Installed four good used rear tires and torqued to 140 ft lbs
Road tested and retorqued to 140 ft lbs
(No parts used)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Aug-15	Manzino,Robert C	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 20-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Aug 20, 2015 1:36:19 PM	No	
20 - Miles			RMANZINO	Aug 20, 2015 1:36:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26269194
Invoice No. 55345 - 26269194

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
tires		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,661 - DH

Activity Header
Activity: 15 017/001/000 TIRE, PNEUMATIC
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 05 Replace Used
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26269194 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26117648
Invoice No. 55345 - 26117648

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,897 - DH

Chronology		
Reported	Aug 13, 2015 2:54:54 PM	Aug 13, 2015 2:54:54 PM
Started	Aug 13, 2015 7:05:00 PM	
Completed	Aug 13, 2015 7:53:00 PM	Aug 13, 2015 7:53:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:replaced 6 qt oil 5w20. Replaced 1 oil filter. Part number b 329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: light med. duty
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-15	Capazzoli,Louis	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: light med. duty
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 13-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	Yes	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,131 - Brake Pad Thickness LF	10 Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Aug 13, 2015 7:45:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26117648
Invoice No. 55345 - 26117648

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,897 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.26	1.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Aug-15	Capazzoli,Louis	0.77	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 13-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Aug 13, 2015 7:47:04 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.26
	Labor:	0.00
	Labor Hours:	0.77
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26117648
Invoice No. 55345 - 26117648

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,897 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 13-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Aug 13, 2015 7:48:10 PM	No	
20 - Miles			LCAPAZZOLI	Aug 13, 2015 7:48:10 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26117648 Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	2.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26255310
Invoice No. 55345 - 26255310

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Change engine air filter.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,585 - DH

Chronology		
Reported	Aug 10, 2015 11:27:07 PM	Aug 10, 2015 11:27:07 PM
Started	Aug 10, 2015 12:00:00 AM	
Completed	Aug 11, 2015 12:05:00 AM	Aug 11, 2015 12:05:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:
Change engine air filter.

CAUSE:
Manufacturer recommended maintenance.

CORRECTION:
Replaced engine air filter with a new Baldwin filter.

Parts- Baldwin engine air filter Part # PA4075 QTY-1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 11, 2015 12:04:27 AM	No	
20 - Miles			RGASPARD	Aug 11, 2015 12:04:27 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26255310
Invoice No. 55345 - 26255310

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
Change engine air filter.		Ford E350 Champion Crusaders	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,585 - DH

Activity Header
Activity: 15 041 INTAKE, AIR
Activity Note: Change engine air filter.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Aug-15	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-15	Torres,Edwin	0.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order Footer

Work Order 26255310 Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26251477
Invoice No. 55345 - 26251477

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
perform front brake job		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,147 - DH

Chronology		
Reported	Aug 7, 2015 3:25:00 PM	Aug 7, 2015 3:25:00 PM
Started		
Completed	Aug 7, 2015 7:17:00 PM	Aug 7, 2015 7:17:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: replaced front brake pads. Lubed guide pins, replaced clips, firts torque 140 lbs. second torque 140lbs.
Parts number.....brsd1228. (1) QTY

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 7, 2015 6:12:57 PM	No	
20 - Miles			RGASPARD	Aug 7, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:12:57 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26251477
Invoice No. 55345 - 26251477

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
perform front brake job		Ford E350 Champion Crusaders	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	30,147 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 26251477 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26049572
Invoice No. 55345 - 26049572

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,698 - DH

Chronology		
Reported	Jul 10, 2015 12:00:00 AM	Jul 10, 2015 12:00:00 AM
Started	Jul 10, 2015 12:00:00 AM	
Completed	Jul 14, 2015 9:52:46 AM	Jul 14, 2015 9:52:46 AM
Down Time		

Work Order Notes

Line 10 PM-C SERVICE COMPLETED

REPLACED OIL FILTER

CHANGED ENGINE OIL
WASHER FLUID ADDED
CHECKED FRONT BRAKES
TORQUE TIRES TO SPEC

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: 55345-PM C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.18	1.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-15	Gaspard,Ronald	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26049572
Invoice No. 55345 - 26049572

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,698 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: 55345-PM C SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26049572
Invoice No. 55345 - 26049572

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM C		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	26,698 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26049572 Total	
Parts:	1.18
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26069092
Invoice No. 55345 - 26069092

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
INSTALL BELT		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	22,658 - DH

Chronology		
Reported	Jun 17, 2015 11:55:00 AM	Jun 17, 2015 11:55:00 AM
Started	Jun 17, 2015 12:00:00 AM	
Completed	Jun 18, 2015 12:30:09 PM	Jun 18, 2015 12:30:09 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 INSTALL BELT LUBRICATE ON ENGINE SERPENTINE BELT
TEST

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26069092
Invoice No. 55345 - 26069092

Client Department:
Department: 55345M
Work Order Description
INSTALL BELT
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 22,658 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-15	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	28.79	28.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-15	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	28.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.79**

Work Order Footer

Work Order 26069092 Total	
Parts:	28.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25936828
Invoice No. 55345 - 25936828

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,696 - DH

Chronology		
Reported	Jun 8, 2015 12:00:00 AM	Jun 8, 2015 12:00:00 AM
Started	Jun 8, 2015 12:00:00 AM	
Completed	Jun 10, 2015 9:19:58 AM	Jun 10, 2015 9:19:58 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-A SERVICE COMPLETED
MOUNT & BALANCE 3 TIRES, INSPECT BRAKES, INSPECT TIRES

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.77	1.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-15	Owens,Arthur	4.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25936828
Invoice No. 55345 - 25936828

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,696 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25936828
Invoice No. 55345 - 25936828

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	21,696 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25936828 Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	4.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 25973998
Invoice No. 55345 - 25973998

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REAR BRAKES		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,842 - DH

Chronology		
Reported	May 26, 2015 11:38:00 AM	May 26, 2015 11:38:00 AM
Started	May 26, 2015 12:00:00 AM	
Completed	Jun 5, 2015 11:40:30 AM	Jun 5, 2015 11:40:30 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 REPLACED REAR BRAKES

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 25973998
Invoice No. 55345 - 25973998

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
REAR BRAKES		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	20,842 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jun-15	BRSD1329	PADS, BRAKE, DISC, E450	1	44.48	44.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-May-15	Owens,Arthur	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order Footer

Work Order 25973998 Total	
Parts:	44.48
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25827719
Invoice No. 55345 - 25827719

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,113 - DH

Chronology		
Reported	May 14, 2015 12:00:00 AM	May 14, 2015 12:00:00 AM
Started	May 14, 2015 12:00:00 AM	
Completed	May 15, 2015 9:07:26 AM	May 15, 2015 9:07:26 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-A SERVICE PERFORM.

REPLACED OIL FILTER.

CHANGED ENGINE OIL.

WASHER FLUID ADDED.

CHECKED TIRES PRESSURE ROTATE AND TORQUE TIRES TO SPEC.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-May-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.71	1.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.71

	Labor:	0.00
	Labor Hours:	2.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25827719
Invoice No. 55345 - 25827719

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,113 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25827719
Invoice No. 55345 - 25827719

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,113 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25827719 Total	
Parts:	1.71
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25739606
Invoice No. 55345 - 25739606

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,576 - DH

Chronology		
Reported	Apr 14, 2015 12:00:00 AM	Apr 14, 2015 12:00:00 AM
Started		
Completed	Apr 15, 2015 10:26:08 AM	Apr 15, 2015 10:26:08 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PMB- SERVICE PERFOM
B329- OIL FILTER
5W20- ENGINE OIL

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM B INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.63	1.63

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25739606
Invoice No. 55345 - 25739606

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,576 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25739606
Invoice No. 55345 - 25739606

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM B		Ford E350 Champion Crusaders	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	12,576 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25739606 Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25732780
Invoice No. 55345 - 25732780

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	JBOND	**Status:**	40 - Closed (40)
Created By:	JBOND	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,925 - DH

Chronology		
Reported	Mar 10, 2015 12:00:00 AM	Mar 10, 2015 12:00:00 AM
Started	Mar 10, 2015 12:00:00 AM	
Completed	Mar 18, 2015 1:02:28 PM	Mar 18, 2015 1:02:28 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-15	Owens,Arthur	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25732780
Invoice No. 55345 - 25732780

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	JBOND	**Status:**	40 - Closed (40)
Created By:	JBOND	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,925 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25732780
Invoice No. 55345 - 25732780

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
PM A		Ford E350 Champion Crusaders	
Requested By:	JBOND	**Status:**	40 - Closed (40)
Created By:	JBOND	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,925 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25732780 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 24687446
Invoice No. 55345 - 24687446

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
--> Followup on WO 25507262		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,491 - DH

Chronology		
Reported	Feb 22, 2015 12:00:00 AM	Feb 22, 2015 12:00:00 AM
Started		
Completed	Mar 16, 2015 10:11:09 AM	Mar 16, 2015 10:11:09 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 24687446
Invoice No. 55345 - 24687446

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
--> Followup on WO 25507262		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,491 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 24687446
Invoice No. 55345 - 24687446

Client Department:			
Department:	55345M	**Equipment No.:**	5412
Work Order Description		**VIN:**	1FDEE3FL2FDA06809
--> Followup on WO 25507262		Ford E350 Champion Crusaders	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	3,491 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 24687446 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 25507262
Invoice No. 55345 - 25507262

Client Department:
Department: 55345M
Work Order Description
Followup to PM WO 24687446
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 5412
VIN: 1FDEE3FL2FDA06809
Ford E350 Champion Crusaders
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 3,491 - DH

Chronology		
Reported	Feb 9, 2015 12:00:00 AM	Feb 9, 2015 12:00:00 AM
Started	Feb 9, 2015 12:00:00 AM	
Completed	Mar 12, 2015 10:29:05 AM	Mar 12, 2015 10:29:05 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

Activity Header
Activity: 1
Activity Note:
Reason for Repair: 11 Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Mar-15	FL820S	OUT OF SERVICE DO NOT ORDER OUT OF SERVICE FILTER, OIL, SPIN-ON SEE BALDWIN B329	1	3.85	3.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-15	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 1 Sub Total	
Parts:	3.85
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.85**

Work Order Footer

Work Order 25507262 Total	
Parts:	3.85

	Labor:	0.00
	Labor Hours:	2.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**3.85**

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51302109
Invoice Number: 55345-51302109

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 24, 2018	1:16 PM
Started	May 24, 2018	
Completed	May 24, 2018	11:07 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	173,063	DH
System	173,213	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:perform PM-A CAUSE: preventive maintenance CORRECTION: tech performed PM-A Parts used Oil filter Qty:1 part# B328 Oil Qty:6.5qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51302109
Invoice Number: 55345-51302109

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
24-May-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-May-18	KARLENS,Cyrius	0.35	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51302109 Grand Total

Parts:	1.96
Labor:	0.00
Labor Hours: 4.35	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.96**

Recent Repair History

WorkOrder: 51302109
Invoice Number: 55345-51302109

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
51386838	1-Jun-18	174,045	WO	Steering box leaking oil
51302109	24-May-18	173,063	WO	PM A
51144156	27-Apr-18	169,100	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51302061	27-Apr-18	169,100	WO	Needs 2 new tires and rear hub seal

PH: Work Order: 51302109 Desc: PM A
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 24, 2018 10:46:46 PM	No	
10,100	Safety Inspection	Done		CKARLENS	May 24, 2018 10:46:46 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 24, 2018 10:46:46 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 24, 2018 10:46:46 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,140	Check Service Brakes	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,160	FRA Check Instruments and Horns	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,170	Check Fast Idle	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,180	Check Starter Protection Circuit	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
10,190	Check Reverse Warning System	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
11,100	Check Parking Brake	Done		CKARLENS	May 24, 2018 10:46:47 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		CKARLENS	May 24, 2018 10:46:48 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 24, 2018 10:46:48 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		CKARLENS	May 24, 2018 10:46:48 PM	No	
11,140	Road Test: Check for Proper Operation	Done		CKARLENS	May 24, 2018 10:46:48 PM	No	
11,150	Perform Brake Test	Done		CKARLENS	May 24, 2018 10:46:48 PM	No	
11,152	Decelerometer Results Test 1	FEET	na	CKARLENS	May 24, 2018 10:46:48 PM	No	
11,154	Decelerometer Results Test 2	FEET	na	CKARLENS	May 24, 2018 10:46:48 PM	No	
11,156	Decelerometer Results Test 3	FEET	na	CKARLENS	May 24, 2018 10:46:48 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 24, 2018 10:46:49 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 24, 2018 10:46:49 PM	No	
11,170	FRA Check Door Operation	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
20,230	FRA Check Wiring Under Dash	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
20,240	FRA Check Interior Lights	Done		CKARLENS	May 24, 2018 10:46:49 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
20,260	Check Stop Request System	-	na	CKARLENS	May 24, 2018 10:46:50 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	May 24, 2018 10:46:50 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
22,110	Check Emergency Hatches	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
22,120	Check All Safety Equipment	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 24, 2018 10:46:50 PM	No	
30,310	Check Passenger Doors	Done		CKARLENS	May 24, 2018 10:46:51 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		CKARLENS	May 24, 2018 10:46:51 PM	No	
30,330	Check Wheelchair Lift Operation	Done		CKARLENS	May 24, 2018 10:46:51 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 24, 2018 10:46:51 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
30,360	Check for Physical Damage and Decals	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
30,380	Check Exterior Compartment Doors	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		CKARLENS	May 24, 2018 11:06:32 PM	No	
33,100	Check Lights and Reflectors	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 24, 2018 10:46:52 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 24, 2018 10:46:53 PM	No	
40,420	Check Hood	Done		CKARLENS	May 24, 2018 10:46:53 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		CKARLENS	May 24, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:46:53 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 24, 2018 10:46:53 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 24, 2018 10:46:53 PM	No	
40,442	Freeze Point	0 Degree Fahrenheit	na	CKARLENS	May 24, 2018 10:46:54 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 24, 2018 10:46:54 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	May 24, 2018 10:46:54 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 24, 2018 10:46:54 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 24, 2018 10:46:54 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		CKARLENS	May 24, 2018 10:46:54 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		CKARLENS	May 24, 2018 10:46:54 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 24, 2018 10:46:54 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,130	FRA Check Exhaust System	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,140	FRA Check Intake System	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,150	FRA Inspect Turbocharger	-	na	CKARLENS	May 24, 2018 10:46:55 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 24, 2018 10:46:55 PM	No	
44,180	FRA Check for Leaks	Done		CKARLENS	May 24, 2018 10:46:56 PM	No	
44,190	FRA Perform Battery Inspection	Done		CKARLENS	May 24, 2018 10:46:56 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 24, 2018 10:46:56 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		CKARLENS	May 24, 2018 10:46:56 PM	No	
50,510	Check Entire Steering System	Done		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,610	FRA Check and Record Air Pressure	Done		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:57 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:57 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 24, 2018 10:46:58 PM	No	
60,620	Check Valve Stems and Caps	Done		CKARLENS	May 24, 2018 10:46:58 PM	No	
60,630	Check and Record Tread Depth	Done		CKARLENS	May 24, 2018 10:46:58 PM	No	
60,631	Tread Depth RF	13 32nds of an inch		CKARLENS	May 24, 2018 10:46:58 PM	No	
60,632	Tread Depth LF	13 32nds of an inch		CKARLENS	May 24, 2018 10:46:58 PM	No	
60,633	Tread Depth RRO	8 32nds of an inch		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,634	Tread Depth RRI	8 32nds of an inch		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,635	Tread Depth LRI	9 32nds of an inch		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,636	Tread Depth LRO	8 32nds of an inch		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,650	Check Sidewall Wear	Done		CKARLENS	May 24, 2018 10:46:59 PM	No	
60,660	Inspect for Cuts and Tears	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
60,670	Check Dual Mating With Square	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
70,710	Check Vibration Damper	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
70,720	Check Engine and Transmission Mounts	Done		CKARLENS	May 24, 2018 10:47:00 PM	No	
70,730	FRA Check Starter	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,750	FRA Check Transmission for Leaks	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,770	FRA Check Exhaust System	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 24, 2018 10:47:01 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		CKARLENS	May 24, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:47:01 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,110	FRA Check Fuel Tank	Done		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,120	Check Suspension Components	Done		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		CKARLENS	May 24, 2018 10:47:02 PM	No	
77,133	Brake Pad Thickness LR	7 Inch		CKARLENS	May 24, 2018 10:47:03 PM	No	
77,134	Brake Pad Thickness RR	7 Inch		CKARLENS	May 24, 2018 10:47:03 PM	No	
77,135	Brake Rotor LF	39.8 Inch		CKARLENS	May 24, 2018 10:47:41 PM	No	
77,136	Brake Rotor RF	39.8 Inch		CKARLENS	May 24, 2018 10:47:42 PM	No	
77,137	Brake Rotor LR	35.8 Inch		CKARLENS	May 24, 2018 10:47:41 PM	No	
77,138	Brake Rotor RR	35.8 Inch		CKARLENS	May 24, 2018 10:47:41 PM	No	
77,140	FRA Check Brake Hoses	Done		CKARLENS	May 24, 2018 10:47:42 PM	No	
77,150	Check King Pins	-	na	CKARLENS	May 24, 2018 10:47:42 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 24, 2018 10:47:42 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		CKARLENS	May 24, 2018 10:47:42 PM	No	
80,810	Completion of PMI Report	Done		CKARLENS	May 24, 2018 10:47:43 PM	No	
90,000	SECTION 9 Completion of PMI	Done		CKARLENS	May 24, 2018 10:47:43 PM	No	
90,910	Vehicle Returned to predetermined location	Done		CKARLENS	May 24, 2018 10:47:43 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		CKARLENS	May 24, 2018 10:40:51 PM	No	
101,000	FRA Change Oil Filters	Yes		CKARLENS	May 24, 2018 10:40:51 PM	No	
102,000	FRA Drain Engine Oil	Yes		CKARLENS	May 24, 2018 10:40:51 PM	No	
103,000	FRA Check Transmission Fluid	Done		CKARLENS	May 24, 2018 10:40:51 PM	No	
104,000	Lubricate Chassis	Done		CKARLENS	May 24, 2018 10:40:51 PM	No	
105,000	Replace or Clean A/C Filters	Done		CKARLENS	May 24, 2018 10:40:52 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	CKARLENS	May 24, 2018 10:40:52 PM	No	
108,000	Lube all pivoting Mechanisms	Done		CKARLENS	May 24, 2018 10:40:51 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 24, 2018 10:40:20 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51464421
Invoice Number: 55345-51464421

Client Department:			
MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 31, 2018	12:44 PM
Started	Jul 31, 2018	
Completed	Aug 1, 2018	12:32 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	181,414	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Jul-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
31-Jul-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51863175
Invoice Number: 55345-51863175

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 30, 2018	11:55 AM
Started	Nov 30, 2018	
Completed	Nov 30, 2018	11:55 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	198,090	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Nov-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.55	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
30-Nov-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55266379
Invoice Number: 55345-55266379

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 1, 2022	12:00 AM
Started	Mar 3, 2022	
Completed	Mar 3, 2022	3:35 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	323,562	DH
System	323,367	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: vehicle came in for service CAUSE: service by miles CORRECTION: job complete change oil filter part # B329 change rear A / C filter no part # return vehicle back to work

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10

Activity Note: Light Duty PMI
Reason for Repair: -
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 55266379
Invoice Number: 55345-55266379

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Technician	Hours	Rate	Extended
03-Mar-22	Junior Hurst	0.65	0.00	0.00
03-Mar-22	Junior Hurst	1.08	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.73	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-Mar-22	B329		FILTER, OIL, SPIN-ON	1.00	1.99	1.99

Labor Posted

Date	Technician	Hours	Rate	Extended
03-Mar-22	Junior Hurst	0.53	0.00	0.00

Activity 20 Sub Total

Parts:	1.99
Labor:	0.00
Labor Hours: 0.53	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

WorkOrder 55266379 Grand Total

Parts:	1.99
Labor:	0.00
Labor Hours: 2.26	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.99**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55401308	15-Apr-22	328,502	WO	55345-LIGHT DUTY PMA

WorkOrder: 55266379
Invoice Number: 55345-55266379

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55498577	6-Apr-22	327,226	WO	Check Engine Light On
55493983	5-Apr-22	327,226	WO	PER PTC RANDOM INSPECTION
55482393	31-Mar-22	326,921	WO	55345 PER DVIR (Check PTC Camera)
55465227	27-Mar-22	326,496	WO	WHEEL CHAIR INSPECTION
55426804	15-Mar-22	324,554	WO	55345 PER DVIR (Repair Light Signal)
55426103	11-Mar-22	324,554	WO	PER DRIVER SLIGHT SMELL OF GAS IN THE VEHICLE
55398988	7-Mar-22	323,562	WO	Wheelchair Lift
55266379	3-Mar-22	323,562	WO	55345-LIGHT DUTY PMA
55398260	2-Mar-22	323,367	WO	Check Wheel Chair Lift
55323580	4-Feb-22	320,389	WO	55345 PER DVIR (Emergency Brake Goes to Floor)

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55472645	28-Mar-22	326,578	WO	WC lift malfunction.

PH: Work Order: 55266379 Desc: 55345-LIGHT DUTY PMA
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 03-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Mar 3, 2022 12:50:23 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Mar 3, 2022 12:50:24 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Mar 3, 2022 12:50:42 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Mar 3, 2022 12:50:43 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Mar 3, 2022 12:51:08 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Mar 3, 2022 12:51:04 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Mar 3, 2022 2:34:31 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Mar 3, 2022 2:34:44 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Mar 3, 2022 2:34:53 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Mar 3, 2022 2:35:00 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Mar 3, 2022 2:35:08 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Mar 3, 2022 2:35:15 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Mar 3, 2022 2:35:28 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Mar 3, 2022 2:35:34 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Mar 3, 2022 2:35:44 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Mar 3, 2022 2:35:52 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Mar 3, 2022 2:36:10 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Mar 3, 2022 2:36:06 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Mar 3, 2022 2:36:18 PM	No	
20,800	INSPECT_High Idle Control	Done		JUHURST	Mar 3, 2022 2:36:28 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Mar 3, 2022 2:36:37 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Mar 3, 2022 2:36:48 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Mar 3, 2022 2:36:53 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Mar 3, 2022 2:37:03 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Mar 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:20:28 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Mar 3, 2022 2:37:13 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Mar 3, 2022 2:37:28 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Mar 3, 2022 2:37:24 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Mar 3, 2022 2:37:42 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Mar 3, 2022 2:38:08 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Mar 3, 2022 2:38:04 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Mar 3, 2022 2:40:08 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 3, 2022 2:40:22 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 3, 2022 2:40:55 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 2:41:09 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 3, 2022 2:41:20 PM	No	
32,000	Engine Inspection	Done		JUHURST	Mar 3, 2022 2:41:30 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Mar 3, 2022 2:41:36 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Mar 3, 2022 2:41:43 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Mar 3, 2022 2:41:52 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Mar 3, 2022 2:42:07 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Mar 3, 2022 2:42:16 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Mar 3, 2022 2:42:24 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Mar 3, 2022 2:42:33 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Mar 3, 2022 2:42:40 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Mar 3, 2022 2:42:49 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Mar 3, 2022 2:42:55 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Mar 3, 2022 2:43:11 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Mar 3, 2022 2:43:21 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 3, 2022 2:43:28 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 3, 2022 2:43:37 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 2:43:57 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 3, 2022 2:43:53 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Mar 3, 2022 2:44:06 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Mar 3, 2022 2:44:30 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Mar 3, 2022 2:44:46 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Mar 3, 2022 2:44:54 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Mar 3, 2022 2:45:00 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Mar 3, 2022 2:45:10 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Mar 3, 2022 2:45:16 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Mar 3, 2022 2:45:21 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Mar 3, 2022 2:45:32 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Mar 3, 2022 2:45:38 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Mar 3, 2022 2:45:46 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Mar 3, 2022 2:45:54 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Mar 3, 2022 2:46:01 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Mar 3, 2022 2:46:10 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Mar 3, 2022 2:46:17 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Mar 3, 2022 2:46:26 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Mar 3, 2022 2:46:39 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Mar 3, 2022 2:46:49 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Mar 3, 2022 2:46:56 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Mar 3, 2022 2:47:03 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Mar 3, 2022 2:47:13 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Mar 3, 2022 2:47:26 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Mar 3, 2022 2:47:21 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Mar 3, 2022 2:47:36 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Mar 3, 2022 2:47:45 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 3, 2022 2:47:54 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose	Done		JUHURST	Mar 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Lugs/Indicators, Outer Hub Leaks				2:48:05 PM		
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Mar 3, 2022 2:48:27 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:27:55 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 2:49:15 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 2:49:48 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Mar 3, 2022 2:49:54 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Mar 3, 2022 2:50:06 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Mar 3, 2022 2:50:13 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 2:52:24 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 2:52:45 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 3, 2022 2:54:09 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 3, 2022 2:55:24 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Mar 3, 2022 2:55:31 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Mar 3, 2022 2:55:40 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		JUHURST	Mar 3, 2022 2:55:48 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Mar 3, 2022 2:55:56 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Mar 3, 2022 2:56:10 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Mar 3, 2022 2:56:20 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Mar 3, 2022 2:56:31 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Mar 3, 2022 2:56:57 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Mar 3, 2022 2:57:07 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Mar 3, 2022 2:57:16 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Mar 3, 2022 2:57:25 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Mar 3, 2022 2:57:36 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Mar 3, 2022 2:57:45 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Mar 3, 2022 2:57:50 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 3, 2022 2:57:55 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Mar 3, 2022 2:58:00 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Mar 3, 2022 2:58:08 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Mar 3, 2022 2:58:20 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 3, 2022 2:58:27 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 2:58:42 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 2:59:07 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 2:59:20 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 2:59:42 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:00:01 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Mar 3, 2022 3:00:11 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:00:23 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 3, 2022 3:00:34 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Mar 3, 2022 3:00:43 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Mar 3, 2022 3:00:51 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Mar 3, 2022 3:00:58 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:01:20 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 3, 2022 3:01:29 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Mar 3, 2022 3:01:54 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.299 Inch		JUHURST	Mar 3, 2022 3:02:11 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Mar 3, 2022 3:02:28 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Mar 3, 2022 3:02:45 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Mar 3, 2022 3:03:07 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Mar 3, 2022 3:03:18 PM	No	
60,100	RECORD_Wheelchair Cycle Count	21119 Cycles		JUHURST	Mar 3, 2022 3:03:42 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Mar 3, 2022 3:03:51 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Mar 3, 2022 3:03:59 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Mar 3, 2022 3:04:07 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Mar 3, 2022 3:04:42 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Mar 3, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:04:36 PM		
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Mar 3, 2022 3:04:28 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Mar 3, 2022 3:05:35 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Mar 3, 2022 3:06:18 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Mar 3, 2022 3:06:23 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Mar 3, 2022 3:06:28 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Mar 3, 2022 3:06:36 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Mar 3, 2022 3:06:42 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Mar 3, 2022 3:06:51 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Mar 3, 2022 3:06:57 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Mar 3, 2022 3:07:05 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Mar 3, 2022 3:07:19 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Mar 3, 2022 3:07:26 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Mar 3, 2022 3:07:30 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Mar 3, 2022 3:07:38 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Mar 3, 2022 3:07:46 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Mar 3, 2022 3:07:51 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Mar 3, 2022 3:07:56 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Mar 3, 2022 3:08:01 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Mar 3, 2022 3:08:05 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Mar 3, 2022 3:08:14 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Mar 3, 2022 3:08:24 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Mar 3, 2022 3:08:39 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		JUHURST	Mar 3, 2022 3:08:48 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Mar 3, 2022 3:08:54 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 03-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Mar 3, 2022 2:02:09 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
101,000	FRA Change Oil Filters	Yes		JUHURST	Mar 3, 2022 2:02:04 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Mar 3, 2022 2:02:31 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Mar 3, 2022 2:02:41 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Mar 3, 2022 2:02:59 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Mar 3, 2022 2:03:09 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Mar 3, 2022 2:03:28 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Mar 3, 2022 2:03:41 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-MAR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Mar 3, 2022 12:46:20 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 3, 2022 12:46:21 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Mar 3, 2022 12:46:21 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Mar 3, 2022 12:46:22 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 3, 2022 12:46:22 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 3, 2022 12:46:23 PM	No	

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 51556866
Invoice Number: 55345-51556866

Client Department:			
MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 29, 2018	11:28 AM
Started	Aug 29, 2018	
Completed	Aug 29, 2018	11:35 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	185,508	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:Perform pmA CAUSE:Preventive Maintenance CORRECTION:Tech Performed pmA Part used Oil filter Qty1 part#B329 Oil Qty:6.5

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
29-Aug-18	KARLENS,Cyrius	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51763257
Invoice Number: 55345-51763257

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 30, 2018	4:05 PM
Started	Oct 30, 2018	
Completed	Oct 31, 2018	8:17 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	194,051	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: Preventive Maintenance CORRECTION: Performed and completed PMA Service Part# B329 Qty1

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Oct-18	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
30-Oct-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52033776
Invoice Number: 55345-52033776

Client Department:			
MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 24, 2019	12:29 PM
Started	Jan 24, 2019	
Completed	Jan 24, 2019	10:57 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	206,083	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE:Service Due by Mileage. CORRECTION: Change Oil& Filter. Lube all Pivoting Points.check Brakes. Clean batteries. Replace Air Filter. Replace drain plugs Parts#B329 Qty (1) Parts#PA4075 Qty (1) Parts#65266 Qty (1) Oil 5W20QTY Qty (6.0) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Jan-19	Arthurs,Durvin	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase
by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52111085
Invoice Number: 55345-52111085

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	DARTHURS	**Status:**	40
Created By:	DARTHURS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 25, 2019	8:06 AM
Started	Feb 25, 2019	
Completed	Feb 26, 2019	9:33 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	210,406	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Preventive Maintenance CORRECTION: perform PmA Service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
25-Feb-19	Pierre,Hubert J	6.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 6.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
25-Feb-19	P9600		FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45
26-Feb-19	B329		FILTER, OIL (FGA0000399/FSC0000399)	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52300269
Invoice Number: 55345-52300269

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 3, 2019	11:03 AM
Started	May 3, 2019	
Completed	May 3, 2019	10:56 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	219,224	DH
System	219,363	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
03-May-19	AMRIT TEEMAL,VISHNU	1.00	65.00	65.00

Activity 10 Sub Total

Parts:	0.00
Labor:	65.00
Labor Hours: 1.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
03-May-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52400877
Invoice Number: 55345-52400877

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 32
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 5, 2019	11:59 AM
Started	Jun 5, 2019	
Completed	Jun 6, 2019	12:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	223,455	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA CAUSE: Service CORRECTION:perform PmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-Jun-19	Gaspard,Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52591115
Invoice Number: 55345-52591115

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 9, 2019	4:25 PM
Started	Aug 9, 2019	
Completed	Aug 10, 2019	12:09 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	231,796	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check Brakes. Clean batteries.replace A/C Filter. Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-Aug-19	Arthurs,Durvin	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
09-Aug-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52677776
Invoice Number: 55345-52677776

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Sep 12, 2019	2:41 PM
Started	Sep 12, 2019	
Completed	Sep 13, 2019	7:42 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	236,237	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts Replaced exhaust hanger

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Sep-19	Gaspard,Ronald	1.60	65.00	104.00

Activity 10 Sub Total

Parts:	0.00
Labor:	104.00
Labor Hours: 1.60	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**104.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52898742
Invoice Number: 55345-52898742

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 18, 2019	12:00 AM
Started	Nov 18, 2019	
Completed	Nov 19, 2019	12:04 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	245,234	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
18-Nov-19	Gaspard,Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
18-Nov-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53014228
Invoice Number: 55345-53014228

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 20, 2019	8:59 AM
Started	Dec 22, 2019	
Completed	Dec 22, 2019	12:50 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	249,496	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Dec-19	AMRIT TEEMAL,VISHNU	0.85	65.00	55.25

Activity 10 Sub Total

Parts:	0.00
Labor:	55.25
Labor Hours: 0.85	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.25**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
22-Dec-19	PA4075		FILTER, AIR, PAPER SAME AS AF25590	1.00	5.28	5.28

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53211916
Invoice Number: 55345-53211916

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM A		**VIN:**	1FDEE3FL2FDA06809
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 26, 2020	11:22 AM
Started	Feb 26, 2020	
Completed	Feb 27, 2020	12:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	257,670	DH
System	257,812	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Drain plug oil 65266 qty1 Engine oil 10w20 qty 7 Qts

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Feb-20	Gaspard,Ronald	1.70	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.70	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53328355
Invoice Number: 55345-53328355

Client Department:
MRC: 55345M
WO Desc:
PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	May 5, 2020	10:39 AM
Started	May 5, 2020	
Completed	May 7, 2020	10:19 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	261,828	DH
System	261,828	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 10w30qty 7qts Replaced AC filter

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
05-May-20	Gaspard,Ronald	0.72	0.00	0.00
06-May-20	Gaspard,Ronald	1.05	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.77	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53670872
Invoice Number: 55345-53670872

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 28, 2020	12:00 AM
Started	Aug 28, 2020	
Completed	Aug 29, 2020	12:28 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	270,467	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: service CORRECTION: Perform PMA service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53826309
Invoice Number: 55345-53826309

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Oct 16, 2020	12:00 AM
Started	Oct 16, 2020	
Completed	Oct 19, 2020	9:51 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	274,820	DH
System	274,932	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION:Perform pmA Service Oil filter B329 qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54088547
Invoice Number: 55345-54088547

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 11, 2021	12:00 AM
Started	Jan 11, 2021	
Completed	Jan 11, 2021	8:17 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	283,604	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM A service CAUSE: Due by Mileage. CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Jan-21	Earl Johnson	0.05	0.00	0.00

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.05	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10

Activity Note:	Light Duty PMI
Reason for Repair:	-
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54198859
Invoice Number: 55345-54198859

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	EARJOHNSON	**Status:**	40
Created By:	EARJOHNSON	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Feb 19, 2021	7:22 AM
Started	Feb 19, 2021	
Completed	Feb 19, 2021	12:22 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	287,823	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: preventive maintenance CORRECTION: Performed service lube all pivoting point cross tires completed

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **017 TIRES, TUBES, LINERS & VALVES**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54433352
Invoice Number: 55345-54433352

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 11, 2021	11:45 AM
Started	May 11, 2021	
Completed	May 12, 2021	9:36 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	296,372	DH
System	296,372	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA CAUSE: Service CORRECTION: perform PmA Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54557747
Invoice Number: 55345-54557747

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	DKNOTT	**Status:**	40
Created By:	DKNOTT	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 18, 2021	11:19 AM
Started	Jun 21, 2021	
Completed	Jun 21, 2021	11:52 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	300,754	DH
System	300,754	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service CAUSE: preventive maintenance CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54785064
Invoice Number: 55345-54785064

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 9, 2021	12:00 AM
Started		
Completed	Sep 10, 2021	12:46 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	309,490	DH
System	309,490	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service CAUSE: preventive maintenance CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54887282
Invoice Number: 55345-54887282

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 23, 2021	12:00 AM
Started	Nov 24, 2021	
Completed	Nov 24, 2021	1:48 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	313,973	DH
System	313,973	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA service CAUSE: preventive maintenance CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55401308
Invoice Number: 55345-55401308

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 12, 2022	12:00 AM
Started	Apr 14, 2022	
Completed	Apr 15, 2022	2:39 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	328,502	DH
System	328,120	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE:preventive maintenance CORRECTION:performed PMA Service and lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	-2.50	0.00	0.00
15-Apr-22	NELSON PIERRE-LOUIS	2.50	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder: 55401308
Invoice Number: 55345-55401308

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	1.75	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.75	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Apr-22	B329		FILTER, OIL, SPIN-ON	1.00	1.99	1.99

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Apr-22	NELSON PIERRE-LOUIS	0.75	0.00	0.00

Activity 20 Sub Total

Parts:	1.99
Labor:	0.00
Labor Hours: 0.75	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.99**

WorkOrder 55401308 Grand Total

Parts:	1.99
Labor:	0.00
Labor Hours: 2.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**1.99**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55401308	15-Apr-22	328,502	WO	55345-LIGHT DUTY PMA

WorkOrder: 55401308
Invoice Number: 55345-55401308

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	JUHURST	**Status:**	40
Created By:	JUHURST	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55498577	6-Apr-22	327,226	WO	Check Engine Light On
55493983	5-Apr-22	327,226	WO	PER PTC RANDOM INSPECTION
55482393	31-Mar-22	326,921	WO	55345 PER DVIR (Check PTC Camera)
55465227	27-Mar-22	326,496	WO	WHEEL CHAIR INSPECTION
55426804	15-Mar-22	324,554	WO	55345 PER DVIR (Repair Light Signal)

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55472645	28-Mar-22	326,578	WO	WC lift malfunction.

PH: Work Order: 55401308 Desc: 55345-LIGHT DUTY PMA
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:26:57 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Apr 15, 2022 2:26:58 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:26:58 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:26:59 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Apr 15, 2022 2:26:59 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:00 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:00 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:01 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:01 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:01 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:02 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:02 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:03 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:03 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:17 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:04 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:28 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:35 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:04 PM	No	
20,800	INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:05 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:43 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:48 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:05 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:06 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-	Apr 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	2:27:06 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Apr 15, 2022 2:16:59 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:06 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:07 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Apr 15, 2022 2:17:10 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:08 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:08 PM	No	
31,000	SSF (Street Side Front)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:09 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 15, 2022 2:17:23 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:17:32 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:09 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:10 PM	No	
32,000	Engine Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:10 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:11 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:11 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:12 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:12 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Apr 15, 2022 2:27:12 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:13 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Apr 15, 2022 2:18:02 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Apr 15, 2022 2:18:13 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Apr 15, 2022 2:18:19 PM	No	
32,100	INSPECT_Intake System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:13 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:30:29 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.5 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:18:34 PM	No	
33,010	CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:14 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Apr 15, 2022 2:18:40 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:18:44 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,040	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:14 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:15 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:15 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	Apr 15, 2022 2:19:01 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:16 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:16 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Apr 15, 2022 2:19:15 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:17 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:17 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:18 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:18 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:19 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:19:35 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Apr 15, 2022 2:19:42 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:19 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:20 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:20 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:21 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Apr 15, 2022 2:19:53 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Apr 15, 2022 2:20:00 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:21 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Apr 15, 2022 2:20:06 PM	No	
50,200	INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:22 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:22 PM	No	
50,400	LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:23 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:23 PM	No	
50,700	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:24 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-	Apr 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	2:27:24 PM		
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:25 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:25 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:26 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:26 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:27 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:27 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:28 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:28 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:29 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:29 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:30 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:30 PM	No	
52,100	INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:30 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:31 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:31 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:32 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:32 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:33 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:33 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:34 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Apr 15, 2022 2:22:28 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Apr 15, 2022 2:22:37 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Apr 15, 2022 2:22:42 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:22:48 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:34 PM	No	
53,600	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:35 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:35 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:36 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:36 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:37 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:37 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:38 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:38 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	64 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:39 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:39 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:40 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:40 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:41 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:41 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:42 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:42 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:43 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4.5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:43 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4.5 32nds of an inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:44 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:44 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.3 Inch		NPIERRE-LOUIS	Apr 15, 2022 2:27:45 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:46 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Apr 15, 2022 2:25:39 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Apr 15, 2022 2:25:44 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:46 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Apr 15, 2022 2:27:46 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:47 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:48 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:48 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		NPIERRE-	Apr 15, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	2:27:49 PM		
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:49 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:50 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:50 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:51 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:51 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:52 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:52 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:53 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:53 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:54 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:54 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:55 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:55 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:56 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:56 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:57 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:58 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:58 PM	No	
62,400	INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:58 PM	No	
62,500	INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:59 PM	No	
62,600	INSPECT_Rollers	Done		NPIERRE-LOUIS	Apr 15, 2022 2:27:59 PM	No	
62,700	INSPECT_All Linkages	Done		NPIERRE-LOUIS	Apr 15, 2022 2:28:00 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Apr 15, 2022 2:28:00 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Apr 15, 2022 2:28:01 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Apr 15, 2022 2:28:01 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Apr 15, 2022 2:34:59 PM	No	
101,000	FRA Change Oil Filters	No		NPIERRE-LOUIS	Apr 15, 2022 2:34:59 PM	No	
102,000	FRA Drain Engine Oil	No		NPIERRE-LOUIS	Apr 15, 2022 2:35:00 PM	No	
103,000	FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:00 PM	No	
104,000	Lubricate Chassis	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:01 PM	No	
105,000	Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:02 PM	No	
107,000	FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Apr 15, 2022 2:35:02 PM	No	
108,000	Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Apr 15, 2022 2:35:03 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 15-APR-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:49 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:49 PM	No	
4	Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:50 PM	No	
7	Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:50 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:51 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Apr 15, 2022 2:31:51 PM	No	

FIRSTstudent
First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55630425
Invoice Number: 55345-55630425

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 11, 2022	12:00 AM
Started	Jul 19, 2022	
Completed	Jul 19, 2022	10:59 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	338,052	DH
System	337,726	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION:perform PMA Service oil filter B329 qty1 engine oil 10w30 qty 7 qts check inflate tires to spec

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
19-Jul-22	B329		FILTER, OIL, SPIN-ON	1.00	2.19	2.19

WorkOrder: 55630425
Invoice Number: 55345-55630425

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Jul-22	Gaspard,Ronald	1.75	0.00	0.00

Activity 10 Sub Total

Parts:	2.19
Labor:	0.00
Labor Hours: 1.75	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.19**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
19-Jul-22	Gaspard,Ronald	0.20	0.00	0.00

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.20	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 55630425 Grand Total

Parts:	2.19
Labor:	0.00
Labor Hours: 1.95	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**2.19**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55787156	20-Jul-22	338,052	WO	FOLLOWUP-FT Light Duty
55630425	19-Jul-22	338,052	WO	55345-LIGHT DUTY PMA

WorkOrder: 55630425
Invoice Number: 55345-55630425

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMA		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
54732649	13-Jul-22	337,832	WO	QCC FLEET INSPECTION
55771354	13-Jul-22	337,832	WO	Check AC (Rear AC)

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 55630425 Desc: 55345-LIGHT DUTY PMA
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 19-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		RGASPARD	Jul 19, 2022 9:49:48 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jul 19, 2022 9:49:53 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		RGASPARD	Jul 19, 2022 9:49:59 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jul 19, 2022 9:50:10 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jul 19, 2022 9:50:15 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jul 19, 2022 9:50:24 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jul 19, 2022 9:50:34 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jul 19, 2022 9:50:40 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jul 19, 2022 9:50:47 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jul 19, 2022 9:50:53 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jul 19, 2022 9:50:58 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jul 19, 2022 9:51:07 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jul 19, 2022 9:51:13 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jul 19, 2022 9:51:29 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jul 19, 2022 9:51:34 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jul 19, 2022 9:51:41 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jul 19, 2022 9:51:48 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jul 19, 2022 9:52:16 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jul 19, 2022 9:52:25 PM	No	
20,800	INSPECT_High Idle Control	Done		RGASPARD	Jul 19, 2022 9:52:34 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jul 19, 2022 9:52:46 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jul 19, 2022 9:52:52 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		RGASPARD	Jul 19, 2022 9:53:01 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jul 19, 2022 9:53:06 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jul 19, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					9:53:14 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jul 19, 2022 9:53:30 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jul 19, 2022 9:53:35 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Jul 19, 2022 9:53:40 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jul 19, 2022 9:53:48 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		RGASPARD	Jul 19, 2022 9:53:54 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jul 19, 2022 9:53:59 PM	No	
31,000	SSF (Street Side Front)	Done		RGASPARD	Jul 19, 2022 9:54:08 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 19, 2022 9:54:14 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jul 19, 2022 9:54:19 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 9:54:26 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 19, 2022 9:54:31 PM	No	
32,000	Engine Inspection	Done		RGASPARD	Jul 19, 2022 9:54:36 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		RGASPARD	Jul 19, 2022 9:54:41 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jul 19, 2022 9:54:49 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jul 19, 2022 9:54:59 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jul 19, 2022 9:55:17 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jul 19, 2022 9:55:26 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jul 19, 2022 9:55:33 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jul 19, 2022 9:56:02 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jul 19, 2022 9:56:07 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jul 19, 2022 9:56:13 PM	No	
32,100	INSPECT_Intake System	Done		RGASPARD	Jul 19, 2022 9:56:18 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 19, 2022 9:56:46 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14.1 Volt*		RGASPARD	Jul 19, 2022 9:56:26 PM	No	
33,010	CSF (Curb Side Front)	Done		RGASPARD	Jul 19, 2022 9:56:52 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jul 19, 2022 9:56:56 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring	Done		RGASPARD	Jul 19, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Shackles				9:57:05 PM		
33,040	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 9:57:11 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jul 19, 2022 9:57:16 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jul 19, 2022 9:57:21 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jul 19, 2022 9:57:39 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jul 19, 2022 9:57:50 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		RGASPARD	Jul 19, 2022 9:57:56 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jul 19, 2022 9:58:02 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Jul 19, 2022 9:58:07 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jul 19, 2022 9:58:12 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Jul 19, 2022 9:58:17 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jul 19, 2022 9:58:22 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jul 19, 2022 9:58:27 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jul 19, 2022 9:58:33 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jul 19, 2022 9:58:43 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jul 19, 2022 9:58:51 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jul 19, 2022 9:58:57 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done	needs AC filter	RGASPARD	Jul 19, 2022 9:59:14 PM	Yes	55787156
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		RGASPARD	Jul 19, 2022 9:59:30 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jul 19, 2022 9:59:35 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jul 19, 2022 9:59:42 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jul 19, 2022 9:59:55 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jul 19, 2022 10:00:01 PM	No	
50,200	INSPECT_Ball Joint Play	Done		RGASPARD	Jul 19, 2022 10:00:06 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jul 19, 2022 10:00:10 PM	No	
50,400	LUBE_All Chassis Components	Done	na	RGASPARD	Jul 19, 2022 10:00:38 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jul 19, 2022 10:01:05 PM	No	
50,700	INSPECT_Tire Condition	Done		RGASPARD	Jul 19, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:01:10 PM		
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 19, 2022 10:01:16 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 19, 2022 10:01:37 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	2 32nds of an inch	needs front tires	RGASPARD	Jul 19, 2022 10:02:10 PM	Yes	55787156
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:02:34 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Jul 19, 2022 10:02:56 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:03:03 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jul 19, 2022 10:03:10 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jul 19, 2022 10:03:16 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jul 19, 2022 10:03:26 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jul 19, 2022 10:03:37 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Jul 19, 2022 10:03:45 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 19, 2022 10:04:01 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jul 19, 2022 10:04:09 PM	No	
52,100	INSPECT_Vibration Damper	Done		RGASPARD	Jul 19, 2022 10:04:13 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jul 19, 2022 10:04:19 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jul 19, 2022 10:04:24 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jul 19, 2022 10:04:29 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jul 19, 2022 10:05:02 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jul 19, 2022 10:05:15 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jul 19, 2022 10:05:24 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jul 19, 2022 10:05:37 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jul 19, 2022 10:05:47 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jul 19, 2022 10:05:53 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jul 19, 2022 10:06:13 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jul 19, 2022 10:06:27 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jul 19, 2022 10:06:39 PM	No	
53,600	INSPECT_Tire Condition	Done		RGASPARD	Jul 19, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:06:45 PM		
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jul 19, 2022 10:06:50 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jul 19, 2022 10:06:58 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jul 19, 2022 10:07:04 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jul 19, 2022 10:07:10 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jul 19, 2022 10:07:23 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:08:48 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:08:55 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:09:08 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:09:27 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:09:33 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	4 32nds of an inch		RGASPARD	Jul 19, 2022 10:09:39 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:09:45 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jul 19, 2022 10:09:54 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jul 19, 2022 10:09:59 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jul 19, 2022 10:10:07 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Jul 19, 2022 10:10:13 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 19, 2022 10:10:20 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		RGASPARD	Jul 19, 2022 10:10:25 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Jul 19, 2022 10:10:37 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	36 Inch		RGASPARD	Jul 19, 2022 10:10:43 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jul 19, 2022 10:10:48 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jul 19, 2022 10:10:54 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jul 19, 2022 10:11:12 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jul 19, 2022 10:11:37 PM	No	
60,100	RECORD_Wheelchair Cycle Count	11245 Cycles		RGASPARD	Jul 19, 2022 10:12:09 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 19, 2022 10:12:15 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 19, 2022 10:12:20 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jul 19, 2022 10:12:24 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jul 19, 2022 10:12:29 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 19, 2022 10:12:34 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 19, 2022 10:12:39 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 19, 2022 10:12:43 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 19, 2022 10:12:48 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jul 19, 2022 10:12:53 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 19, 2022 10:12:58 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 19, 2022 10:13:03 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 19, 2022 10:13:08 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 19, 2022 10:13:13 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 19, 2022 10:13:20 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jul 19, 2022 10:13:27 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jul 19, 2022 10:13:32 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jul 19, 2022 10:13:37 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jul 19, 2022 10:13:42 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jul 19, 2022 10:13:47 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jul 19, 2022 10:13:51 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 19, 2022 10:13:56 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jul 19, 2022 10:14:01 PM	No	
62,400	INSPECT_All Pivot Points	Done		RGASPARD	Jul 19, 2022 10:14:07 PM	No	
62,500	INSPECT_Cams and Slots	Done		RGASPARD	Jul 19, 2022 10:14:13 PM	No	
62,600	INSPECT_Rollers	Done		RGASPARD	Jul 19, 2022 10:14:29 PM	No	
62,700	INSPECT_All Linkages	Done		RGASPARD	Jul 19, 2022 10:14:34 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		RGASPARD	Jul 19, 2022 10:14:39 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jul 19, 2022 10:14:43 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jul 19, 2022 10:14:49 PM	No	

LH: 20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 19-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 19, 2022 10:32:25 PM	No	
101,000	FRA Change Oil Filters	Yes		RGASPARD	Jul 19, 2022 10:32:31 PM	No	
102,000	FRA Drain Engine Oil	Yes		RGASPARD	Jul 19, 2022 10:32:37 PM	No	
103,000	FRA Check Transmission Fluid	Done		RGASPARD	Jul 19, 2022 10:32:42 PM	No	
104,000	Lubricate Chassis	-	na	RGASPARD	Jul 19, 2022 10:32:49 PM	No	
105,000	Replace or Clean A/C Filters	Done		RGASPARD	Jul 19, 2022 10:32:54 PM	No	
107,000	FRA Change Primary Fuel Filter	No	na	RGASPARD	Jul 19, 2022 10:33:02 PM	No	
108,000	Lube all pivoting Mechanisms	Done		RGASPARD	Jul 19, 2022 10:33:08 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		RGASPARD	Jul 19, 2022 8:45:59 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 19, 2022 8:46:04 PM	No	
4	Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 19, 2022 8:46:09 PM	No	
7	Have you performed the proper LOTO?	Done		RGASPARD	Jul 19, 2022 8:46:13 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 19, 2022 8:46:18 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 19, 2022 8:46:23 PM	No	

FirstBase by First Transit

WorkOrder
55345 Palm Tran Connection
v 2.2

WorkOrder: 51669025
Invoice Number: 55345-51669025

Client Department:			
MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06809
Requested By:	AOWENS	**Status:**	40
Created By:	AOWENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Sep 27, 2018	2:29 PM
Started	Sep 27, 2018	
Completed	Sep 28, 2018	9:07 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	189,729	DH
System	189,729	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE Service CORRECTION:Perform PMB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
27-Sep-18	Gaspard,Ronald	1.53	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.53	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
27-Sep-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52202373
Invoice Number: 55345-52202373

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM B		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Mar 29, 2019	12:30 PM
Started	Mar 31, 2019	
Completed	Mar 31, 2019	5:38 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	214,836	DH
System	214,975	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMB Service. CAUSE: Service Due by Mileage. CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check brakes . Clean batteries. Replace two front clearance light. Parts #B329 Qty (1) Oil 5W20QTY (6.5) Qt.

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
31-Mar-19	Arthurs,Durvin	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
31-Mar-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52787692
Invoice Number: 55345-52787692

Client Department:
MRC: 55345M
WO Desc:
PM B
Requested By: RRENE
Created By: RRENE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 14, 2019	3:08 PM
Started	Oct 15, 2019	
Completed	Oct 15, 2019	3:26 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	240,675	DH
System	240,675	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMB SERVICE

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	1.50	65.00	97.50

Activity 10 Sub Total

Parts:	0.00
Labor:	97.50
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
15-Oct-19	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53558541
Invoice Number: 55345-53558541

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NSTOLFO	**Status:**	40
Created By:	NSTOLFO	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jul 3, 2020	12:00 AM
Started	Jul 3, 2020	
Completed	Jul 4, 2020	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	266,164	DH
System	266,231	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION: perform PMB Service Oil filter B329 Qty1 Engine oil 10w30 Qty1 Replaced marker light Qty1 Replaced left Pigtail and head light bulb Headlight bulb 9008 Qty1

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54312892
Invoice Number: 55345-54312892

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FL2FDA06809
Requested By:	HPIERRE	**Status:**	40
Created By:	HPIERRE	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Apr 1, 2021	12:00 AM
Started	Apr 1, 2021	
Completed	Apr 2, 2021	12:13 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	292,093	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE: Service CORRECTION: perform pmB Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Drain plug oil 65266 Qty1 Fixed rear AC high side hose ;leaking from the valve .charge System to spec

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55120849
Invoice Number: 55345-55120849

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMB		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	32
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jan 10, 2022	12:00 AM
Started	Jan 17, 2022	
Completed	Jan 17, 2022	4:01 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	318,797	DH
System	318,425	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: service by miles CORRECTION: job cmplete new oil filter replace part # B329 aiso replace two wiper blade Part # 40520 Replace rear A/C filter road test unit working asdesign. Unit back to work

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
17-Jan-22	Junior Hurst	0.03	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.03	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **011RTD SUSPENSION**

Activity Note: Light Duty PMI
Reason for Repair: 11 - Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
17-Jan-22	40520	W	BLADE, WIPER, WINDSHIELD, 20"	1.00	4.40	4.40

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 51372050
Invoice Number: 55345-51372050

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Jun 26, 2018	10:52 AM
Started	Jun 26, 2018	
Completed	Jun 26, 2018	11:45 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	177,263	DH
System	177,348	DH

WorkOrder Notes

Line	Comment
10	Perform PMA Service change Oil & Filter. lube all Pivoting Points. check brakes. Clean batteries.Replace A/C Filter . Replace rear door red warning light. Replace drain plugs. Change transmission oil& Filter. Per form differential . Service. Parts#33250R3 Qty (1) Shop Supply Parts# 20021 Qty (1) Parts# B329 Qty (1) Oil 5W20 Qty (6.5) Qt ATF Fluid Qty (9.5) Qt Gear Oil 80W90 Qty (3) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Jun-18	Arthurs,Durvin	3.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 3.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

WorkOrder: 51372050
Invoice Number: 55345-51372050

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Date	Part Number		Description	Qty.	Each	Extended
26-Jun-18	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.26	17.26
26-Jun-18	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96
26-Jun-18	F75Z-6730-BA		PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Jun-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts:	25.88
Labor:	0.00
Labor Hours: 0.42	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.88**

Activity: 30 **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
26-Jun-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.08	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

WorkOrder 51372050 Grand Total

Parts:	25.88
Labor:	0.00
Labor Hours: 4.00	
Sublet Parts:	0.00

WorkOrder: 51372050
Invoice Number: 55345-51372050

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CKARLENS	**Status:**	40
Created By:	CKARLENS	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Sublet Labor:	0.00
WorkOrder Grand Total	**25.88**

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51372050	26-Jun-18	177,263	WO	PM C
51452233	25-Jun-18	176,894	WO	Battery light is lit on the cluster.
51386838	1-Jun-18	174,045	WO	Steering box leaking oil

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
51302061	27-Apr-18	169,100	WO	Needs 2 new tires and rear hub seal

PH: Work Order: 51372050 Desc: PM C
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 26-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,100	Safety Inspection	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	Jun 26, 2018 10:28:55 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	Jun 26, 2018 10:28:56 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:28:57 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	Jun 26, 2018 10:28:58 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	Jun 26, 2018 10:28:59 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jun 26, 2018 10:28:59 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jun 26, 2018 10:28:59 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	Jun 26, 2018 10:29:00 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jun 26, 2018 10:29:01 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jun 26, 2018 10:29:02 PM	No	
40,420	Check Hood	Done		DARTHURS	Jun 26, 2018 10:29:02 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	Jun 26, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:29:02 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jun 26, 2018 10:29:02 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jun 26, 2018 10:29:02 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:29:02 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:03 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jun 26, 2018 10:29:03 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jun 26, 2018 10:29:03 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:03 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	Jun 26, 2018 10:29:03 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	Jun 26, 2018 10:29:03 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jun 26, 2018 10:29:03 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jun 26, 2018 10:29:04 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jun 26, 2018 10:29:05 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	Jun 26, 2018 10:29:06 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:06 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:06 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:06 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:06 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,631	Tread Depth RF	10 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,632	Tread Depth LF	10 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,633	Tread Depth RRO	6 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:07 PM	No	
60,635	Tread Depth LRI	9 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,636	Tread Depth LRO	5 32nds of an inch		DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	Jun 26, 2018 10:29:08 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	Jun 26, 2018 10:29:10 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jun 26, 2018 10:29:09 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	Jun 26, 2018 10:29:10 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	Jun 26, 2018 10:29:10 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	Jun 26, 2018 10:29:10 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jun 26, 2018 10:29:10 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jun 26, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:29:11 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jun 26, 2018 10:29:11 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	Jun 26, 2018 10:29:11 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	Jun 26, 2018 10:29:11 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jun 26, 2018 10:29:11 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,133	Brake Pad Thickness LR	6 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,134	Brake Pad Thickness RR	6 Inch		DARTHURS	Jun 26, 2018 10:29:11 PM	No	
77,135	Brake Rotor LF	1.556 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,136	Brake Rotor RF	1.557 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,137	Brake Rotor LR	1.416 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,138	Brake Rotor RR	1.417 Inch		DARTHURS	Jun 26, 2018 10:29:12 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	Jun 26, 2018 10:29:13 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	Jun 26, 2018 10:29:13 PM	No	

LH: 20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 26-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jun 26, 2018 10:31:13 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jun 26, 2018 10:31:13 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jun 26, 2018 10:31:13 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jun 26, 2018 10:31:13 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jun 26, 2018 10:31:14 PM	No	
105,000	Replace or Clean A/C Filters	Done	Replace A/C	DARTHURS	Jun 26, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
			Filter		10:31:14 PM		
107,000	FRA Change Primary Fuel Filter	-	NA	DARTHURS	Jun 26, 2018 10:31:14 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jun 26, 2018 10:31:14 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Jun 26, 2018 10:31:14 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	Jun 26, 2018 10:31:14 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Jun 26, 2018 10:31:14 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jun 26, 2018 10:31:15 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jun 26, 2018 10:31:15 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Jun 26, 2018 10:31:15 PM	No	
301,000	Check and Lubricate Door Linkages	Done		DARTHURS	Jun 26, 2018 10:31:15 PM	No	
302,000	Check Toe-In and Record Reading	-	NA	DARTHURS	Jun 26, 2018 10:31:15 PM	No	
302,001	Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Jun 26, 2018 10:31:15 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Jun 26, 2018 10:31:15 PM	No	
305,000	FRA Change Differential Fluid	Yes		DARTHURS	Jun 26, 2018 10:31:15 PM	No	

LH: 30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 26, 2018 10:31:42 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	

WorkOrder: 51953538
Invoice Number: 55345-51953538

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
PM C		**VIN:**	1FDEE3FL2FDA06809
Requested By:	RGASPARD	**Status:**	40
Created By:	RGASPARD	**Priority:**	1
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Dec 28, 2018	8:15 AM
Started		
Completed	Dec 31, 2018	8:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	202,105	DH
System	202,329	DH

WorkOrder Notes

Line	Comment
10	PMC Preventive maintenance Perform service lube all Pivoting Points cross Rotate Tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
28-Dec-18	P9600		FILTER, OIL SAME AS 68191349AA	1.00	3.45	3.45

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 52493509
Invoice Number: 55345-52493509

Client Department:
MRC: 55345M
WO Desc:
PM C
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jul 10, 2019	9:11 AM
Started	Jul 10, 2019	
Completed	Jul 11, 2019	12:14 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	227,611	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service. Change Oil & Filter. Lube all Pivoting Points. Check Brakes Clean batteries.Perform Transmission Service./ Perform Differential Service . drain& Fill Replace Air Filter. Parts# B329 Qty (1) Parts # PA4075 Qty (1) Parts# 20021 Qty (1) Oil 5W20 Qty (6.5) Qt Gear Oil 80W90 Qty (3) Qt

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
10-Jul-19	Arthurs,Durvin	3.50	65.00	227.50

Activity 10 Sub Total

Parts:	0.00
Labor:	227.50
Labor Hours: 3.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.50**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
10-Jul-19	20021		FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS	1.00	17.27	17.27

FirstBase by First Transit

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53119506
Invoice Number: 55345-53119506

Client Department:
MRC: 55345M
WO Desc:
PM C
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 23, 2020	4:10 PM
Started	Jan 24, 2020	
Completed	Jan 24, 2020	9:55 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	253,581	DH
System	253,581	DH

WorkOrder Notes

Line	Comment
10	Pic Preventing maintenance Perform pm lube all pivoted point cross rotate tire completed

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
24-Jan-20	B329(F)		FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 53973572
Invoice Number: 55345-53973572

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL2FDA06809
Requested By:	CVERGARA	**Status:**	40
Created By:	CVERGARA	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Nov 26, 2020	12:00 AM
Started	Nov 27, 2020	
Completed	Nov 27, 2020	12:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	279,246	DH
System	279,246	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC service Cause: preventive maintenance Correction: perform PMC service and Lube all Pivoting Points,Service rear end

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
27-Nov-20	40520		BLADE, WIPER, WINDSHIELD, 20"	1.00	4.11	4.11

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	4.11
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.11**

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 54666818
Invoice Number: 55345-54666818

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	Aug 4, 2021	12:00 AM
Started	Aug 4, 2021	
Completed	Aug 5, 2021	12:15 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	305,020	DH
System	305,146	DH

WorkOrder Notes

Line	Comment
10	PMC Service Perform PMC Service Oil filter B329 qty1 Engine oil 10w30 qty 7qts Air filter PA4075 qty1 Fixed washer fluid hose

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**

Activity Note:	Light Duty PMI
Reason for Repair:	05 - Inspection, Routine
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder

55345 Palm Tran Connection
v 2.2

WorkOrder: 55524489
Invoice Number: 55345-55524489

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

Chronology		
Reported	May 19, 2022	12:00 AM
Started	May 23, 2022	
Completed	May 23, 2022	12:26 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	333,288	DH
System	333,288	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC Service Cause: preventive maintenance Correction: PMC Service and lube, transmission service, and rear end service, front tire rotation lift ,batteries service

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note:	PERSONAL RISK ASSESSMENT
Reason for Repair:	SW - Shop Work Order
Work Accomplished:	06 - Inspect
Part Failure:	00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 10 **999 TOTAL VEHICLE**

Activity Note:	Light Duty PMI
Reason for Repair:	08 - Preventive Maintenance
Work Accomplished:	-
Part Failure:	-

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

WorkOrder: 55524489
Invoice Number: 55345-55524489

Client Department:
MRC: 55345M
WO Desc:
55345-LIGHT DUTY PMC
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 5412
Ford E350 Champion Crusaders
VIN: 1FDEE3FL2FDA06809
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
23-May-22	NELSON PIERRE-LOUIS	2.30	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.30	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
23-May-22	20021		FILTER, TRANSMISSION 20021	1.00	17.44	17.44
23-May-22	65266		PLUG, DRAIN, OIL, ENGINE	1.00	4.90	4.90
23-May-22	B329		FILTER, OIL, SPIN-ON	1.00	2.14	2.14

Labor Posted

Date	Technician	Hours	Rate	Extended
23-May-22	NELSON PIERRE-LOUIS	1.58	0.00	0.00

Activity 20 Sub Total

Parts:	24.48
Labor:	0.00
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**24.48**

WorkOrder 55524489 Grand Total

Parts:	24.48
Labor:	0.00
Labor Hours: 3.88	
Sublet Parts:	0.00
Sublet Labor:	0.00
WorkOrder Grand Total	**24.48**

Recent Repair History

WorkOrder: 55524489
Invoice Number: 55345-55524489

Client Department:

MRC:	55345M	**Equipment:**	5412
WO Desc:			Ford E350 Champion Crusaders
55345-LIGHT DUTY PMC		**VIN:**	1FDEE3FL2FDA06809
Requested By:	NPIERRE-LOUIS	**Status:**	40
Created By:	NPIERRE-LOUIS	**Priority:**	3
Class:	WO	**Driver:**	
Arrangement:	Unassigned	**Phone:**	
Potential Warranty:	No	**ETA:**	

WorkOrder	Date Completed	Life Meter	Class	Description
55524489	23-May-22	333,288	WO	55345-LIGHT DUTY PMC

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 55524489 Desc: 55345-LIGHT DUTY PMC
Equip: 5412 Desc: Ford E350 Champion Crusaders VIN: 1FDEE3FL2FDA06809

LH: 10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:18:44 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	May 23, 2022 12:18:44 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:18:45 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	May 23, 2022 12:18:45 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	May 23, 2022 12:18:46 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	May 23, 2022 12:18:46 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	May 23, 2022 12:18:47 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	May 23, 2022 12:18:47 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	May 23, 2022 12:09:42 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	May 23, 2022 12:18:48 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	May 23, 2022 12:18:48 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:18:49 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	May 23, 2022 12:18:50 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	May 23, 2022 12:18:50 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	May 23, 2022 12:09:54 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	May 23, 2022 12:18:51 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	May 23, 2022 12:10:01 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	May 23, 2022 12:10:10 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:18:51 PM	No	
20,800	INSPECT_High Idle Control	Done		NPIERRE-LOUIS	May 23, 2022 12:18:52 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:10:19 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	May 23, 2022 12:10:24 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:18:53 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	May 23, 2022 12:18:53 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-	May 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	12:18:54 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	May 23, 2022 12:10:34 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	May 23, 2022 12:18:54 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:18:55 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	May 23, 2022 12:10:42 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	May 23, 2022 12:18:56 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	May 23, 2022 12:18:57 PM	No	
31,000	SSF (Street Side Front)	Done		NPIERRE-LOUIS	May 23, 2022 12:18:57 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 23, 2022 12:10:52 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 23, 2022 12:10:58 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 23, 2022 12:18:58 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 23, 2022 12:18:58 PM	No	
32,000	Engine Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:18:59 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	May 23, 2022 12:19:00 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	May 23, 2022 12:19:01 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	May 23, 2022 12:19:02 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	May 23, 2022 12:19:03 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	May 23, 2022 12:19:03 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:04 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	May 23, 2022 12:11:24 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	May 23, 2022 12:11:29 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	May 23, 2022 12:11:34 PM	No	
32,100	INSPECT_Intake System	Done		NPIERRE-LOUIS	May 23, 2022 12:19:05 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	May 23, 2022 12:11:50 PM	No	
33,010	CSF (Curb Side Front)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:05 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	May 23, 2022 12:11:58 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	May 23, 2022 12:12:05 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	May 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	12:19:06 PM		
33,050	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	May 23, 2022 12:19:06 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	May 23, 2022 12:19:07 PM	No	
33,070	*RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	May 23, 2022 12:12:24 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:08 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:19:08 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	May 23, 2022 12:12:34 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	May 23, 2022 12:19:09 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:09 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	May 23, 2022 12:19:10 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	May 23, 2022 12:19:10 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	May 23, 2022 12:19:11 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:12:57 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	May 23, 2022 12:13:50 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	May 23, 2022 12:19:11 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:12 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	May 23, 2022 12:19:12 PM	No	
41,200	INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:13 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	May 23, 2022 12:14:00 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	May 23, 2022 12:14:05 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	May 23, 2022 12:19:13 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	May 23, 2022 12:14:11 PM	No	
50,200	INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	May 23, 2022 12:19:14 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	May 23, 2022 12:19:14 PM	No	
50,400	LUBE_All Chassis Components	Done		NPIERRE-LOUIS	May 23, 2022 12:19:15 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	May 23, 2022 12:19:15 PM	No	
50,700	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:19:16 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 23, 2022 12:19:16 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:17 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:17 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:18 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:18 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:19 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	May 23, 2022 12:19:19 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:20 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	May 23, 2022 12:19:20 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:21 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:22 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:19:22 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:19:23 PM	No	
52,100	INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	May 23, 2022 12:19:23 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	May 23, 2022 12:19:24 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	May 23, 2022 12:19:24 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	May 23, 2022 12:19:25 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	May 23, 2022 12:19:25 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:26 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	May 23, 2022 12:19:26 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	May 23, 2022 12:19:27 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	May 23, 2022 12:15:35 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	May 23, 2022 12:15:40 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	May 23, 2022 12:15:45 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	May 23, 2022 12:15:50 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	May 23, 2022 12:19:27 PM	No	
53,600	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	May 23, 2022 12:19:28 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	May 23, 2022 12:19:28 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-	May 23, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	12:19:29 PM		
53,900	INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	May 23, 2022 12:19:29 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:30 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	May 23, 2022 12:19:30 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:31 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	6 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:31 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	68 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:32 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:32 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:33 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:33 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:34 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	May 23, 2022 12:19:34 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	May 23, 2022 12:19:35 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:35 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:35 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:36 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		NPIERRE-LOUIS	May 23, 2022 12:19:36 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:19:37 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	May 23, 2022 12:19:37 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	May 23, 2022 12:19:38 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	May 23, 2022 12:17:15 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	May 23, 2022 12:17:20 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	May 23, 2022 12:19:38 PM	No	
60,100	RECORD_Wheelchair Cycle Count	21567 Cycles		NPIERRE-LOUIS	May 23, 2022 12:19:39 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	May 23, 2022 12:19:39 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:19:40 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	May 23, 2022 12:19:40 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:19:41 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	May 23, 2022 12:19:41 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	May 23, 2022 12:19:42 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:19:42 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	May 23, 2022 12:19:43 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:43 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	May 23, 2022 12:19:44 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	May 23, 2022 12:19:44 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	May 23, 2022 12:19:45 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	May 23, 2022 12:19:45 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:46 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	May 23, 2022 12:19:46 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	May 23, 2022 12:19:47 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	May 23, 2022 12:19:47 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	May 23, 2022 12:19:48 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	May 23, 2022 12:19:48 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:19:49 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	May 23, 2022 12:19:49 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	May 23, 2022 12:19:50 PM	No	
62,400	INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	May 23, 2022 12:19:50 PM	No	
62,500	INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	May 23, 2022 12:19:51 PM	No	
62,600	INSPECT_Rollers	Done		NPIERRE-LOUIS	May 23, 2022 12:19:51 PM	No	
62,700	INSPECT_All Linkages	Done		NPIERRE-LOUIS	May 23, 2022 12:19:52 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	May 23, 2022 12:19:52 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	May 23, 2022 12:19:52 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	May 23, 2022 12:19:53 PM	No	

LH: 20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	May 23, 2022 12:08:43 PM	No	
101,000	FRA Change Oil Filters	Yes		NPIERRE-LOUIS	May 23, 2022 12:08:44 PM	No	
102,000	FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	May 23, 2022 12:08:44 PM	No	
103,000	FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	May 23, 2022 12:08:45 PM	No	
104,000	Lubricate Chassis	Done		NPIERRE-LOUIS	May 23, 2022 12:06:26 PM	No	
105,000	Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	May 23, 2022 12:06:26 PM	No	
107,000	FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	May 23, 2022 12:06:27 PM	No	
108,000	Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	May 23, 2022 12:06:27 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	May 23, 2022 12:06:28 PM	No	
201,000	Service Crankcase Breather	Done		NPIERRE-LOUIS	May 23, 2022 12:06:29 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	May 23, 2022 12:08:43 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	May 23, 2022 12:07:52 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	May 23, 2022 12:06:30 PM	No	
300,000	"C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	May 23, 2022 12:06:31 PM	No	
301,000	Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	May 23, 2022 12:06:31 PM	No	
302,000	Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	May 23, 2022 12:06:31 PM	No	
302,001	Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	May 23, 2022 12:06:32 PM	No	
304,000	1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		NPIERRE-LOUIS	May 23, 2022 12:06:32 PM	No	
305,000	FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	May 23, 2022 12:06:54 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 23-MAY-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:26 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:26 PM	No	
4	Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:27 PM	No	
7	Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:28 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:28 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	May 23, 2022 12:05:29 PM	No	

Vehicle Processing Checklist

Form FAMO 2-010

Date Conducted:_____/_____/_____
Conducted By: _____
Phone Number: (_____)_____

Inspection Date/Time: _____
Location: _____
_____

Vehicle Year/Make/Model►

General Information

VIN: _____
Asset No: _____
Odometer: _____
Engine: ____4 cyl_____6 cyl ____ 8 cyl ____ Other
Engine Displacement: ____Liter ____ CID ____ HP
Fuel Type:_____Diesel ____CNG ____Other

General Condition (circle one in each category)

Exterior	Bad	2	3	4	Excllnt
Interior	Bad	2	3	4	Excllnt
Tires	Bad	2	3	4	Excllnt
Glass	Bad	2	3	4	Excllnt
Mechanical	DNR		Runs		Other

_____
(describe "Other")

Options & Equipment (✓each box that applies)

- ☐ A/C
- ☐ P/S
- ☐ P/B
- ☐ P/W
- ☐ A/T
- ☐ Manual Transmission (_____forward speeds)
- ☐ AM/FM Radio
- ☐ CD Player
- ☐ Cruise Control
- ☐ Airbags (circle one) 1 2 3 4
- ☐ Performance Package: _____

- ☐ ABS
- ☐ 4x4
- ☐ Power Door Locks
- ☐ Power Seats
- ☐ Sunroof
- ☐ Tilt Steering
- ☐ Tinted Windows
- ☐ _____
- ☐ _____
- ☐ _____
- ☐ _____

- ☐ Air Brakes
- ☐ Boom/Bucket
- ☐ Crane
- ☐ Dump Bed _____
- ☐ Tank Bed _____
- ☐ Lightbar/beacon
- ☐ Power Liftgate
- ☐ Tool Box
- ☐ Trailer Hitch
- ☐ Utility Bed
- ☐ Winch

Key

4X4	4-Wheel Drive	CID	Cubic Inch Displacement	P/B	Power Brakes
ABS	Antilock Braking System	CNG	Compressed Natural Gas	P/S	Power Steering
A/C	Air Conditioner	DNR	Does Not Run	P/W	Power Windows
A/T	Automatic Transmission	HP	Horsepower	VIN	Vehicle Identification Number

In order to show your vehicles and equipment at their best, use the following chart and descriptions as a guide for preferred camera angles, lighting conditions, and background.

1) Take the photos with a high-resolution digital camera (a minimum of 3 mega pixels is recommended).

2) Take the photo in an area that is well lighted, but not in a glare, and position yourself so that the sun or artificial light source does not cast your shadow into the picture.

3) Make sure the vehicle is washed and all logo decals have been removed with automotive adhesive remover (3M or similar). If primer must be used, select a primer color that closely matches the vehicle. If possible, pressure wash off-road equipment to remove grease and caked mud caught in treads, tracks and body panels. Make sure that truck beds are free of accumulated trash.

4) Select an area with a neutral background; avoid clutter showing up behind the vehicle. Shrubbery generally makes a good backdrop.

5) The preferred camera locations for common vehicles are the right or left front corners of the vehicle, at approximately a 40 degree angle from straight-on, standing 8-10 feet back from the vehicle, and holding the camera at just above rooftop level (except for very tall equipment). By pointing the camera about one-third of the distance down the right or left side of the vehicle, the entire vehicle should be in the photo frame. Under these conditions, the vehicle will be well displayed and you will avoid "fish-eye" distortions of shooting directly at the leading edge (the front edge of the front fender).