Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57351824
Invoice No. 55345 - 57351824

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,176 -

Chronology		
Reported	Jun 8, 2025 12:38:42 PM	Jun 8, 2025 12:38:42 PM
Started		
Completed	Jun 8, 2025 1:06:14 PM	Jun 8, 2025 1:06:14 PM
Down Time		

Work Order Notes

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57351824
Invoice No. 55345 - 57351824

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,176 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 57351824 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56483843
Invoice No. 55345 - 56483843

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,176 -

Chronology		
Reported	Mar 23, 2024 3:16:58 PM	Mar 23, 2024 3:16:58 PM
Started		
Completed	Mar 23, 2024 3:19:35 PM	Mar 23, 2024 3:19:35 PM
Down Time		

Work Order Notes

Line 10 vehicle out of service

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56483843
Invoice No. 55345 - 56483843

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	262,176 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56483843 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 57283726
Invoice No. 55345 - 57283726

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
No Start		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,893 - DH

Chronology		
Reported	Jan 3, 2024 8:17:00 AM	Jan 3, 2024 8:17:00 AM
Started	Jan 3, 2024 8:24:00 AM	
Completed	Jan 4, 2024 1:22:00 PM	Jan 4, 2024 1:22:00 PM
Down Time		

Work Order Notes

Line 10 Check For No Start check an found inter lock light stay on when ignition switch off and draining battery disconnect inter lock system over night bus start up right away the next morning.

Activity Header

Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: No. Start
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-24	Arthurs,Durvin	2.88	65	187.2

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	187.20
Labor Hours:	2.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.20**

Work Order Footer

Work Order 57283726 Total	
Parts:	0.00
Labor:	187.20
Labor Hours:	2.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**187.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57273155
Invoice No. 55345 - 57273155

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Charging System		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,892 - DH

Chronology		
Reported	Dec 19, 2023 7:52:37 AM	Dec 19, 2023 7:52:37 AM
Started	Dec 19, 2023 7:55:00 AM	
Completed	Dec 21, 2023 7:53:00 AM	Dec 21, 2023 7:53:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Charging System,

Cause: Battery Bad cells

Correction: Remove & Replace both Battery& Check Charging System Charging at (14.43) Ok
Parts #ER658 Qty (2)

Line 20 Disconnect drive cam over night to check for battery dicharge no issues in the morning.connect drive cam bus start right up no issues.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 19, 2023 7:56:25 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57273155
Invoice No. 55345 - 57273155

Client Department:
Department: 55345M
Work Order Description
Check Charging System
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,892 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Charging System
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-23	ER65850	BATTERY, GROUP-65, 850CCA, 150MIN RESERVE	2	79.36	158.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Dec-23	Arthurs,Durvin	3.12	65	202.8
20-Dec-23	Arthurs,Durvin	1.47	65	95.55
20-Dec-23	Arthurs,Durvin	1.38	65	89.7
19-Dec-23	Arthurs,Durvin	1.37	65	89.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	158.72
Labor:	477.10
Labor Hours:	7.34
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**635.82**

Work Order Footer

Work Order 57273155 Total	
Parts:	158.72
Labor:	477.10
Labor Hours:	7.34
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**635.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 57210964
Invoice No. 55345 - 57210964

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front tires shaking while driving		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	261,160 - DH

Chronology		
Reported	Oct 26, 2023 12:08:40 AM	Oct 26, 2023 12:08:40 AM
Started	Oct 26, 2023 12:17:00 AM	
Completed	Oct 26, 2023 1:11:00 AM	Oct 26, 2023 1:11:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:front tires shaking while driving

Cause: shaking

Correction:check tires pressure inflate to spec
Balance front tires
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 26-OCT-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
700 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 26, 2023 12:17:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 57210964
Invoice No. 55345 - 57210964

Client Department:
Department: 55345M
Work Order Description
Front tires shaking while driving
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 261,160 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Front tires shaking while driving
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-23	Gaspard,Ronald	0.88	65	57.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	57.20
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.20**

Work Order Footer

Work Order 57210964 Total	
Parts:	0.00
Labor:	57.20
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56945419
Invoice No. 55345 - 56945419

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
STALLING & SMELLING PROPANE		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Chronology		
Reported	Aug 2, 2023 10:45:06 AM	Aug 2, 2023 10:45:06 AM
Started	Aug 2, 2023 10:48:00 AM	
Completed	Oct 10, 2023 2:47:00 PM	Oct 10, 2023 2:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Stalling and fuel smell

Cause:Multiple misfiring (cyl:2 ,3 and 7).

Correction:Precedently ,when replacing the spark plugs two of the spark plugs #2 and 3 keep spinning they cannot be removed.
Bus running at idle ok ,when putting on gear it is shaking ,.Test drive the vehicle ,at each stop light it is shaking but it is not stalling and it is not smelling propane. Line 20 Fix rear AC
Got rear AC running but Condenser fan stays on when ignition on Line 30 Found rear ac electrical diode wire broken, replaced with a good used one.. Line 40 Installed two (2) used battery

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Aug 2, 2023 3:15:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56945419
Invoice No. 55345 - 56945419

Client Department:
Department: 55345M
Work Order Description
STALLING & SMELLING PROPANE
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,836 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Secure dog house and igcoil 1 7 9
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Oct-23	ER65850	BATTERY, GROUP-65, 850CCA, 150MIN RESERVE	2	79.08	158.16
06-Oct-23	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	2	42.06	84.12
21-Sep-23	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	4	39.76	159.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-23	Fritz Simon	4	65	260
06-Oct-23	Pierre,Hubert J	3.13	65	203.45
05-Oct-23	Pierre,Hubert J	0.55	65	35.75
06-Oct-23	Delva,Terry	2	65	130
06-Oct-23	Pierre,Hubert J	3.55	65	230.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	401.32
Labor:	859.95
Labor Hours:	13.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,261.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56945419
Invoice No. 55345 - 56945419

Client Department:
Department: 55345M
Work Order Description
STALLING & SMELLING PROPANE
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,836 - DH

Activity Header
Activity: 25 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Oct-23	Delva,Terry	4.28	65	278.2
10-Oct-23	Delva,Terry	0.67	65	43.55
08-Oct-23	Delva,Terry	4.37	65	284.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	605.80
Labor Hours:	9.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**605.80**

Work Order Footer

Work Order 56945419 Total	
Parts:	401.32
Labor:	1,465.75
Labor Hours:	22.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,867.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56934986
Invoice No. 55345 - 56934986

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Dead battery		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Chronology

Reported	Jul 28, 2023 7:05:03 PM	Jul 28, 2023 7:05:03 PM
Started	Jul 28, 2023 7:12:00 PM	
Completed	Jul 28, 2023 8:46:00 PM	Jul 28, 2023 8:46:00 PM
Down Time		

Work Order Notes

Line 10 Check battery they were completely ded no power So replce two new battery AEVEREADY # 850 please charge the battery out for me

Activity Header

Activity: 10 020 GROUP, DRIVETRAIN
Activity Note: Dead battery
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Aug-23	ER65850	BATTERY, GROUP-65, 850CCA, 150MIN RESERVE	2	79.08	158.16

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-23	Junior Hurst	1.55	65	100.75

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	158.16
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**258.91**

Work Order Footer

Work Order 56934986 Total	
Parts:	158.16
Labor:	100.75
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**258.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 56797521
Invoice No. 55345 - 56797521

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
STALLING		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Chronology		
Reported	Jun 7, 2023 6:54:46 PM	Jun 7, 2023 6:54:46 PM
Started	Jun 7, 2023 6:58:00 PM	
Completed	Jul 26, 2023 5:42:00 PM	Jul 26, 2023 5:42:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Bus cut off three times

Cause:Random misfirings,Mixing coolant and oil found on cylinders 5 and 7.Low vacuum.

Correction:Coolant drained ,radiator,alternator ,rear compressor removed and reinstalled,Intake manifold and spark plugs replaced.

Note: Air intake hose attached to the throttle body leaking needs to be replaced.

Parts :1 ignition coil3W7Z-120129
8 Spark plug#SP521
10 Boots#357006
1 Hose #800-403
1 Set gasket #VS5054R
1 Gasket manifold #4C2Z-9339-AA Line 20 Air intake hose attached to trothle body replaced, vehicle returned to service

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-JUN-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 7, 2023 6:58:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 56797521
Invoice No. 55345 - 56797521

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
STALLING		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: STALLING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jun-23	357006	BOOT, COIL-ON-PLUG, IGNITION	4	7.83	31.32
19-Jun-23	357006	BOOT, COIL-ON-PLUG, IGNITION	10	7.83	78.3
09-Jun-23	VS50547R	SET, GASKET, COVER, VALVE	1	88.17	88.17
19-Jun-23	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	1	57.91	57.91
19-Jun-23	SP521	PLUG, SPARK, 5.4L, FORD	8	4.36	34.88
09-Jun-23	4C2Z-9439-AA	GASKET, MANIFOLD, INTAKE	1	55.47	55.47

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-23	Fritz Simon	4.6	65	299

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	346.05
Labor:	299.00
Labor Hours:	4.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**645.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 56797521
Invoice No. 55345 - 56797521

Client Department:
Department: 55345M
Work Order Description
STALLING
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,836 - DH

Activity Header
Activity: 25 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: INTAKE REPLACEMENT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Jun-23	800-403	CONNECTOR, HOSE, HEATER. 5/8"	1	9.29	9.29
20-Jun-23	F1VY-8255-A	SEAL, THERMOSTAT	1	2.01	2.01
26-Jul-23	5C2Z-9B659-BA	HOSE, INTAKE, AIR, COMPLETE	1	89.02	89.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-23	Fritz Simon	5.23	65	339.95
16-Jun-23	Fritz Simon	1.25	65	81.25
16-Jun-23	Fritz Simon	0.05	65	3.25
15-Jun-23	Fritz Simon	1.48	65	96.2
14-Jun-23	Fritz Simon	4.78	65	310.7
15-Jun-23	Fritz Simon	6.78	65	440.7
16-Jun-23	Fritz Simon	0.33	65	21.45
26-Jul-23	Nicolas Barreto	1.83	65	118.95
17-Jun-23	Fritz Simon	1.43	65	92.95
14-Jun-23	Fritz Simon	0.42	65	27.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	100.32
Labor:	1,532.70
Labor Hours:	23.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,633.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 56797521
Invoice No. 55345 - 56797521

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
STALLING		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Activity Header
Activity: 35 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR A/C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jun-23	Fritz Simon	1.98	65	128.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	128.70
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**128.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 56797521
Invoice No. 55345 - 56797521

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
STALLING		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,836 - DH

Activity Header
Activity: 45 030 ELECTRICAL GROUP
Activity Note: WIRES CONNECTIONS REPAIR
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jun-23	Fritz Simon	0.72	65	46.8
21-Jun-23	Fritz Simon	2.78	65	180.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 45 Sub Total	
Parts:	0.00
Labor:	227.50
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.50**

Work Order Footer

Work Order 56797521 Total	
Parts:	446.37
Labor:	2,187.90
Labor Hours:	33.66
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2,634.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56794233
Invoice No. 55345 - 56794233

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,836 - DH

Chronology		
Reported	Jun 7, 2023 6:33:34 AM	Jun 7, 2023 6:33:34 AM
Started	Jun 7, 2023 6:35:00 AM	
Completed	Jun 14, 2023 1:59:00 PM	Jun 14, 2023 1:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle cut off 3 time

Cause: preventive maintenance

Correction:exchange the vehicle with the driver , test drive vehicle run ok un idlo but bad at the light and cut off at the stop

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 07-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 7, 2023 8:54:43 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56794233
Invoice No. 55345 - 56794233

Client Department:
Department: 55345M
Work Order Description
Road Call
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,836 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jun-23	NELSON PIERRE-LOUIS	2.33	65	151.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	151.45
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.45**

Work Order Footer

Work Order 56794233 Total	
Parts:	0.00
Labor:	151.45
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56783701
Invoice No. 55345 - 56783701

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,684 - DH

Chronology		
Reported	Jun 2, 2023 5:21:40 PM	Jun 2, 2023 5:21:40 PM
Started	Jun 2, 2023 5:25:00 PM	
Completed	Jun 6, 2023 1:02:00 AM	Jun 6, 2023 1:02:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:check bus

Cause: inspection

Correction:check and some scrathes,AC fine
Good tires ,brakes good,check front end

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-JUN-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 2, 2023 5:25:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56783701
Invoice No. 55345 - 56783701

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,684 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Needs inspection
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-23	Gaspard,Ronald	2.23	65	144.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.95**

Work Order Footer

Work Order 56783701 Total	
Parts:	0.00
Labor:	144.95
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**144.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56721931
Invoice No. 55345 - 56721931

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,684 - DH

Chronology		
Reported	May 13, 2023 12:01:21 AM	May 13, 2023 12:01:21 AM
Started	May 13, 2023 12:05:00 AM	
Completed	May 13, 2023 1:35:00 AM	May 13, 2023 1:35:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Catalytic theft deterrent kit installed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 13-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 13, 2023 1:34:16 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56721931
Invoice No. 55345 - 56721931

Client Department:
Department: 55345M
Work Order Description
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,684 - DH

Activity Header
Activity: 15 043/001/030 CONVERTER, CATALYTIC
Activity Note: CATALYTIC CONVERTER HEFT DETERRENT KIT INSTALLATO
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-23	Fritz Simon	1.47	65	95.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	95.55
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.55**

Work Order Footer

Work Order 56721931 Total	
Parts:	0.00
Labor:	95.55
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 56665600
Invoice No. 55345 - 56665600

Client Department:
Department: 55345M
Work Order Description
FRONT AND REAR AC SYSTEM
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,684 - DH

Chronology		
Reported	Apr 28, 2023 5:57:45 PM	Apr 28, 2023 5:57:45 PM
Started	May 11, 2023 5:09:00 PM	
Completed	May 13, 2023 1:33:00 AM	May 13, 2023 1:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Front and Rear A/C systems not working

Cause:Misfirings,low ac lines pressures ,obstructed ac lines ,

Correction:Front and rear AC repaired

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 2, 2023 1:42:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 56665600
Invoice No. 55345 - 56665600

Client Department:
Department: 55345M
Work Order Description
FRONT AND REAR AC SYSTEM
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,684 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC NOT WORKING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-23	Fritz Simon	3.48	65	226.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	226.20
Labor Hours:	3.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**226.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 56665600
Invoice No. 55345 - 56665600

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FRONT AND REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,684 - DH

Activity Header
Activity: 25 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REAR AC REPAIR
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-May-23	Fritz Simon	2.62	65	170.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	170.30
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**170.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 56665600
Invoice No. 55345 - 56665600

Client Department:
Department: 55345M
Work Order Description
FRONT AND REAR AC SYSTEM
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 260,684 - DH

Activity Header
Activity: 35 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: FRONT AC REPAIR
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-23	Fritz Simon	2.63	65	170.95
11-May-23	Fritz Simon	0.45	65	29.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	0.00
Labor:	200.20
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.20**

Work Order Footer

Work Order 56665600 Total	
Parts:	0.00
Labor:	596.70
Labor Hours:	9.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**596.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56643666
Invoice No. 55345 - 56643666

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front AC not working .		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Chronology		
Reported	Apr 21, 2023 4:26:34 PM	Apr 21, 2023 4:26:34 PM
Started	Apr 21, 2023 4:27:00 PM	
Completed	Apr 22, 2023 12:33:00 AM	Apr 22, 2023 12:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front AC not working.

Cause: Front AC compressor cycling (high system pressure).

Correction: Recovered freon. Remove and replaced orifice tube. Vacuumed, leak tested, added PAG oil and recharged to spec.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 22, 2023 12:30:28 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56643666
Invoice No. 55345 - 56643666

Client Department:
Department: 55345M
Work Order Description
Front AC not working .
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,398 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front AC not working.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Apr-23	3411885	TUBE, ORIFICE, A/C, FORD	1	1.06	1.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Apr-23	Earl Johnson	3.4	65	221

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.06
Labor:	221.00
Labor Hours:	3.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**222.06**

Work Order Footer

Work Order 56643666 Total	
Parts:	1.06
Labor:	221.00
Labor Hours:	3.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**222.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56640199
Invoice No. 55345 - 56640199

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Passenger AC doesnt work.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Chronology		
Reported	Apr 20, 2023 4:24:37 PM	Apr 20, 2023 4:24:37 PM
Started	Apr 20, 2023 4:26:00 PM	
Completed	Apr 21, 2023 12:49:00 AM	Apr 21, 2023 12:49:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Restriction in rear AC system.

Correction: Recovered freon. Remove and replaced orifice tube. Vacuum, leak tested added PAG oil and recharged to spec. Rear AC blows cold.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 21, 2023 12:23:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56640199
Invoice No. 55345 - 56640199

Client Department:
Department: 55345M
Work Order Description
Passenger AC doesnt work.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,398 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC doesnt work.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Apr-23	3411885	TUBE, ORIFICE, A/C, FORD	1	1.06	1.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-23	Earl Johnson	3.28	65	213.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.06
Labor:	213.20
Labor Hours:	3.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.26**

Work Order Footer

Work Order 56640199 Total	
Parts:	1.06
Labor:	213.20
Labor Hours:	3.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**214.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56634892
Invoice No. 55345 - 56634892

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Road call		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Chronology		
Reported	Apr 19, 2023 10:52:27 AM	Apr 19, 2023 10:52:27 AM
Started	Apr 19, 2023 10:53:00 AM	
Completed	Apr 19, 2023 2:03:00 PM	Apr 19, 2023 2:03:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: road call

Cause: driver lock the keys in side the bus

Correction: when in open bus door completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 19, 2023 2:02:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		HPIERRE	Apr 19, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				2:02:49 PM		
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 19, 2023 2:02:49 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 19, 2023 2:02:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 19, 2023 2:02:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 19, 2023 2:02:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56634892
Invoice No. 55345 - 56634892

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Road call		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-23	Pierre,Hubert J	3.12	65	202.8

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	202.80
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.80**

Work Order Footer

Work Order 56634892 Total	
Parts:	0.00
Labor:	202.80
Labor Hours:	3.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**202.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56632956
Invoice No. 55345 - 56632956

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Right headlight out.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Chronology		
Reported	Apr 18, 2023 4:20:54 PM	Apr 18, 2023 4:20:54 PM
Started	Apr 18, 2023 4:22:00 PM	
Completed	Apr 18, 2023 10:52:00 PM	Apr 18, 2023 10:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Headlight out/ Drivers side mirror.

Cause: Defective bulb/ Damaged during operation.

Correction: Remove and replaced right headlight bulb/ Remove and replaced mirror head with good used unit.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 18-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 18, 2023 6:02:16 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Apr 18, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				6:02:16 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 18, 2023 6:02:16 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 18, 2023 6:02:16 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 18, 2023 6:02:16 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 18, 2023 6:02:16 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56632956
Invoice No. 55345 - 56632956

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Right headlight out.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,398 - DH

Activity Header
Activity: 15 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note: Right headlight out.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-23	Earl Johnson	0.95	65	61.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	61.75
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56632956
Invoice No. 55345 - 56632956

Client Department:
Department: 55345M
Work Order Description
Right headlight out.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 260,398 - DH

Activity Header
Activity: 25 002/010 MIRRORS
Activity Note: Drivers side mirror damaged.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Apr-23	H13BP	BULB, HEADLAMP, HALOGEN	1	10.17	10.17
04-Jan-24	3976389	LAMP, INTERIOR, LED	5	21.42	107.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-23	Earl Johnson	1.58	65	102.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	117.27
Labor:	102.70
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**219.97**

Work Order Footer

Work Order 56632956 Total	
Parts:	117.27
Labor:	164.45
Labor Hours:	2.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**281.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 56626794
Invoice No. 55345 - 56626794

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver said abs light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,160 - DH

Chronology		
Reported	Apr 17, 2023 8:57:21 AM	Apr 17, 2023 8:57:21 AM
Started	Apr 17, 2023 8:59:00 AM	
Completed	Apr 17, 2023 1:20:00 PM	Apr 17, 2023 1:20:00 PM
Down Time		

Work Order Notes

Line 10 Driver said abs is on

Right front abs sensor open

Check and repair wires completed

Activity Header
Activity: 10 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-23	Pierre,Hubert J	4.08	65	265.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	265.20
Labor Hours:	4.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**265.20**

Work Order Footer

Work Order 56626794 Total	
Parts:	0.00
Labor:	265.20
Labor Hours:	4.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**265.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56614565
Invoice No. 55345 - 56614565

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check engine light is on		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	260,160 - DH

Chronology		
Reported	Apr 13, 2023 11:41:20 AM	Apr 13, 2023 11:41:20 AM
Started	Apr 13, 2023 11:43:00 AM	
Completed	Apr 14, 2023 9:40:00 AM	Apr 14, 2023 9:40:00 AM
Down Time		

Work Order Notes

Line 10 4/13/23

CONVERTER QTY 1

PART # 9C2Z-5E212-E Line 20 Check engine light is on

Code catalytic converter

Replace catalytic converter and bearings completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-23	Pierre,Hubert J	1.17	65	76.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 14, 2023 9:40:05 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	76.05
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**76.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56614565
Invoice No. 55345 - 56614565

Client Department:
Department: 55345M
Work Order Description
Check engine light is on
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 260,160 - DH

Activity Header
Activity: 20 043/000/000 EXHAUST SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-23	9C2Z-5E212-E	CONVERTER, CATALYTIC	1	1,082.83	1,082.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-23	Pierre,Hubert J	1.97	65	128.05
14-Apr-23	Pierre,Hubert J	1.27	65	82.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	1,082.83
Labor:	210.60
Labor Hours:	3.24
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,293.43**

Work Order Footer

Work Order 56614565 Total	
Parts:	1,082.83
Labor:	286.65
Labor Hours:	4.41
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,369.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Chronology		
Reported	Mar 16, 2023 5:42:26 PM	Mar 16, 2023 5:42:26 PM
Started	Mar 21, 2023 4:09:00 PM	
Completed	Apr 6, 2023 12:56:00 PM	Apr 6, 2023 12:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:qcc inspection

Cause: preventive maintenance

Correction: replace shifter cable compressor office tube dryer valve cover gasket passenger side and replace the circuit board completed

Activity Header
Activity: 10 016 SUSPENSION
Activity Note: TOP 3 Clearance Lights Are Out
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-23	3974688	LAMP, LED, AMBER	3	8.9	26.7

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-23	Pierre,Hubert J	2.68	65	174.2
23-Mar-23	Pierre,Hubert J	1.8	65	117

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	26.70
Labor:	291.20
Labor Hours:	4.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**317.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 20 017 TIRES, TUBES, LINERS & VALVES
Activity Note: CHECK ENGINE LIGHT ON
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-23	Pierre,Hubert J	1.75	65	113.75
22-Mar-23	Pierre,Hubert J	2.97	65	193.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	306.80
Labor Hours:	4.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**306.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 30 002 CAB & SHEET METAL
Activity Note: Replace Shifter Level Bushings
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-23	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	30.45	30.45

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-23	Pierre,Hubert J	2.62	65	170.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	30.45
Labor:	170.30
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 40 043/002/001 MANIFOLD, EXHAUST
Activity Note: Has Exhaust Leak
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-23	Pierre,Hubert J	1.93	65	125.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	125.45
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**125.45**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 50 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Shifter cable cracked
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-23	Pierre,Hubert J	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 60 099/000/000 SAFETY DEVICES INSTRUMENTS & GAUGES (POWER UNITS, TRAILERS, ETC.)
Activity Note: White light by entrance door not operating.
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Mar-23	Pierre,Hubert J	5.6	65	364
28-Mar-23	Pierre,Hubert J	14.3	65	929.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	1,293.50
Labor Hours:	19.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,293.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 70 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Serpentine belt making noise.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-23	Pierre,Hubert J	0.03	65	1.95

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	0.00
Labor:	1.95
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 80 999/999/999 TOTAL VEHICLE
Activity Note: Fire extinguisher missing
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 90 002/011/003 BELT & RETAINER, SEAT
Activity Note: Secure seat belt behind driver
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-23	32831	SPRING, SHOCK, GAS, W/C	1	26.3	26.3

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 90 Sub Total	
Parts:	26.30
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.30**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 10 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 100 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Value Cover Gasket Leak
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Mar-23	DC2Z-6582-C	COVER, VALVE, RH, V10	1	87.15	87.15
27-Mar-23	VS50547R	SET, GASKET, COVER, VALVE	1	92.91	92.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-23	Pierre,Hubert J	0.83	65	53.95
23-Mar-23	Pierre,Hubert J	1.82	65	118.3
30-Mar-23	Pierre,Hubert J	8.02	65	521.3

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 100 Sub Total	
Parts:	180.06
Labor:	693.55
Labor Hours:	10.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**873.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 11 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOW UP TO QCC INSP		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 110 043/001/030 CONVERTER, CATALYTIC
Activity Note: Catalytic Converter Very Loud
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 110 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 12 of 12

Work Order No. 56514755
Invoice No. 55345 - 56514755

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO QCC INSP
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 120 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Apr-23	6512723	COMPRESSOR, A/C	1	282.22	282.22
04-Apr-23	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	28.22	28.22

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Apr-23	Pierre,Hubert J	2.77	65	180.05
30-Mar-23	Arthurs,Durvin	2.32	65	150.8
31-Mar-23	Arthurs,Durvin	4.47	65	290.55
04-Apr-23	Pierre,Hubert J	5.82	65	378.3
04-Apr-23	Pierre,Hubert J	5.58	65	362.7
31-Mar-23	Pierre,Hubert J	7.88	65	512.2
06-Apr-23	Pierre,Hubert J	3.33	65	216.45
03-Apr-23	Pierre,Hubert J	11.95	65	776.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 120 Sub Total	
Parts:	310.44
Labor:	2,867.80
Labor Hours:	44.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3,178.24**

Work Order Footer

Work Order 56514755 Total	
Parts:	573.95
Labor:	5,880.55

	Labor Hours:	90.47
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**6,454.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56504391
Invoice No. 55345 - 56504391

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO A/C INSPECTION
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Chronology

Reported	Mar 14, 2023 11:54:00 AM	Mar 14, 2023 11:54:00 AM
Started	Mar 15, 2023 10:11:00 AM	
Completed	Mar 17, 2023 10:45:00 AM	Mar 17, 2023 10:45:00 AM
Down Time		

Work Order Notes

Line 10 Installed geotab, FT camera and MDT and batteries, vehicle is back in service

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: Rear AC system non operable.
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-23	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	2	128.88	257.76

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	257.76
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**257.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56504391
Invoice No. 55345 - 56504391

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO A/C INSPECTION
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 20 051/000/000 ACCESSORIES, GENERAL
Activity Note: Camera and geo tab install
Reason for Repair: 23 Modification
Work Accomplished: 14 Install
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-23	Rodriguez,Raul	2.07	65	134.55

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	134.55
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**134.55**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56504391
Invoice No. 55345 - 56504391

Client Department:
Department: 55345M
Work Order Description
FOLLOW UP TO A/C INSPECTION
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 30 032/001/001 BATTERY
Activity Note: replace batteries
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-23	34AGM	BATTERY, AGM, GROUP-34	2	166.95	333.9
17-Mar-23	3411885	TUBE, ORIFICE, A/C, FORD	1	0.77	0.77

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	334.67
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**334.67**

Work Order Footer

Work Order 56504391 Total	
Parts:	592.43
Labor:	134.55
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**726.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55481823
Invoice No. 55345 - 55481823

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 -

Chronology		
Reported	Mar 16, 2023 11:53:52 AM	Mar 16, 2023 11:53:52 AM
Started	Mar 16, 2023 4:24:00 PM	
Completed	Mar 16, 2023 6:46:00 PM	Mar 16, 2023 6:46:00 PM
Down Time		

Work Order Notes

Line 10

PERFORM QCC INSPECTION VEHICLE HAS CHECK ENGINE LIGHT ON

Check ENGINE CODE IS P0141 02 SENSOR BANK 1 Sensor 2

Vehicle has exhaust leak also needs shifter level bushings

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 16-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Mar 16, 2023 6:42:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55481823
Invoice No. 55345 - 55481823

Client Department:
Department: 55345M
Work Order Description
QCC FLEET INSPECTION
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 -

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-23	Owens,Arthur	1.92	65	124.8

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: QCC FLEET INSPECTION
Task: 55345 QCC FLEET INSPECTION Performed by: AOWENS Performed on: 16-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		AOWENS	Mar 16, 2023 6:41:44 PM	No	
20 - Cleanliness	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
30 - Entrance Door Operation/Seals/Glass	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
40 - Body/Fenders/Bumpers	C	Scratches All Over Vehicle	AOWENS	Mar 16, 2023 6:41:44 PM	No	
50 - Tires/Wheels/Lugs	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
60 - Mirrors and Attachments	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
70 - Lights and Accessories	B	TOP 3 Clearance Lights Are Out	AOWENS	Mar 16, 2023 6:41:44 PM	Yes	56514755
80 - Compartment Doors	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
90 - Battery Compartment	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
100 - Check All Fluids	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
110 - Belt Drives	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
120 - Air Induction	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
130 - Exhaust System	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
140 - Engine Compartmetn Wiring	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
150 - DRIVERS AREA INSPECTION	Done		AOWENS	Mar 16, 2023 6:41:44 PM	No	
160 - Air System	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
170 - Audible Warnings	B	CHECK ENGINE LIGHT ON	AOWENS	Mar 16, 2023 6:41:44 PM	Yes	56514755
180 - Dash and Gauges	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
190 - Accessory components	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
200 - Exit Door Operation	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
210 - Exit Door Interlock	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
220 - Fare box and ticket cutter.	E		AOWENS	Mar 16, 2023 6:41:44 PM	No	
230 - Fast Idle	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
240 - Glass & Mirrors	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
250 - Floor Covering	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
260 - Horn and Lamps	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
270 - Start Function	C	Slow Start Check Batteries	AOWENS	Mar 16, 2023 6:41:44 PM	No	
280 - PA System	E		AOWENS	Mar 16, 2023 6:41:44 PM	No	
290 - Pedal Condition and Adjustment	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
300 - Reverse System	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
310 - Seat	C		AOWENS	Mar 16, 2023 6:41:44 PM	No	
320 - Steering Wheel & Column	A	Replace Shifter Level Bushings	AOWENS	Mar 16, 2023 6:41:44 PM	Yes	56514755
330 - Sun Visor	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
340 - Turn Signals Switch	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
350 - Electrical Compartment	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
360 - Wheel Chair Operation	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
370 - INTERIOR CIRCLE	Done		AOWENS	Mar 16, 2023 6:41:44 PM	No	
380 - Cleanliness	C	Needs To Be Washed	AOWENS	Mar 16, 2023 6:41:44 PM	No	
390 - HVAC	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
400 - Interior Passenger Area	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
410 - Stop Request	E		AOWENS	Mar 16, 2023 6:41:44 PM	No	
420 - Safety Equipment	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
430 - UNDERCARRIAGE	-	Has Exhaust Leak	AOWENS	Mar 16, 2023 6:41:44 PM	Yes	56514755
440 - Air System	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
450 - Steering components	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
460 - Brake Inspection	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
470 - Suspension Components	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
480 - Frame	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
490 - Fluid Leakage	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	
500 - Fuel System	A		AOWENS	Mar 16, 2023 6:41:44 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	124.80
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**124.80**

Work Order Footer

Work Order 55481823 Total	
Parts:	0.00
Labor:	124.80
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**124.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 56195693
Invoice No. 55345 - 56195693

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Chronology		
Reported	Mar 15, 2023 6:22:30 PM	Mar 15, 2023 6:22:30 PM
Started	Mar 16, 2023 12:22:00 AM	
Completed	Mar 16, 2023 11:03:00 AM	Mar 16, 2023 11:03:00 AM
Down Time		

Work Order Notes

Line 10 PMB

Preventive maintenance

Performed PMB service completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 16, 2023 9:48:12 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 16, 2023 9:48:12 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 16, 2023 9:48:12 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 16, 2023 9:48:12 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 16, 2023 9:48:12 AM	No	
11 - Have you successfully completed the Personal	Done		HPIERRE	Mar 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:48:12 AM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 56195693
Invoice No. 55345 - 56195693

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Mar-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.51	2.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-23	Pierre,Hubert J	1.27	65	82.55

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 16-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
10,800 - CHECK_All Destination Signage	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,200 - CHECK_Public Address System	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	60 Second*		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,700 - RECORD_Brake Performance Test Speed	60 Miles per Hour		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,800 - RECORD_Brake Performance Test Distance	6 FEET		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	6 FEET		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	60 Gravitational Force		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,500 - INSPECT_High Idle Control	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper	Done		HPIERRE	Mar 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Routing/Chafing/Securement				11:02:01 AM		
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,000 - CSF (Curb Side Front)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,300 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	24 Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	24 Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	24 Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	24 Inch		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	2139 Cycles		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Mar 16, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:02:01 AM		
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Mar 16, 2023 11:02:01 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	2.51
Labor:	82.55
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 56195693
Invoice No. 55345 - 56195693

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 56195693 Total	
Parts:	2.51
Labor:	82.55
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**85.06**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 56109028
Invoice No. 55345 - 56109028

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 -

Chronology		
Reported	Feb 28, 2023 4:12:15 PM	Feb 28, 2023 4:12:15 PM
Started	Feb 28, 2023 4:12:00 PM	
Completed	Mar 11, 2023 8:27:00 PM	Mar 11, 2023 8:27:00 PM
Down Time		

Work Order Notes

Line 10 Performed AC inspection. Front system AC compressor was intially cycling and exhibiting low pressures. Recovered freon. Remove and replaced orifice tube. Vacuum, leak tested, added PAG oil and recharged to spec. Front system now operates proper, getting 20* below ambient tempurature.

Rear AC system non operable. Blowers work but compressor and condenser fans not engaging. Line 20 Noted for repair.

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assesment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assesment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 1, 2023 12:30:24 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 56109028
Invoice No. 55345 - 56109028

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	SPACE	**Status:**	40 - Closed (40)
Created By:	SPACE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 -

Activity Header
Activity: 10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-23	Earl Johnson	1.42	65	92.3
10-Mar-23	Rodriguez,Raul	1.87	65	121.55
28-Feb-23	Earl Johnson	3.97	65	258.05

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: FIRST TRANSIT AC INSPECTION
Task: FIRST TRANSIT AC INSPECTION Performed by: CKARLENS Performed on: 14-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done	Rear AC Evaporator cover disassembled.	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done	Rear AC system non operable.	CKARLENS	Mar 14, 2023 11:55:11 AM	Yes	56504391
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done	81*	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done	125psi	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done	10psi	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done	60*	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done	Front AC compressor cycling.	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done	0.0173in	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done	Orifice Tube restricted.	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
50,100 - CHECK INLINE DRIER	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
50,200 - CHECK ACCUMULATOR	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done	1.88lb	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
60,200 - CHECK FOR LEAKS AFTER	Done		CKARLENS	Mar 14, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
CHARGING				11:55:11 AM		
70,000 - SECTION 7 FAN MOTORS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
70,200 - INSPECT BLOWER WHEELS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
80,300 - CHECK DEFROST MODE	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done	65*	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done	290psi	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done	30psi	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done	40*	CKARLENS	Mar 14, 2023 11:55:11 AM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
100,100 - DISCONNECT GAUGES	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		CKARLENS	Mar 14, 2023 11:55:11 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	471.90
Labor Hours:	7.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**471.90**

Work Order Footer

Work Order 56109028 Total	
Parts:	0.00
Labor:	471.90
Labor Hours:	7.26
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**471.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55971512
Invoice No. 55345 - 55971512

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CATALYTIC CONVERTER REPLACEMENT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Chronology		
Reported	Sep 21, 2022 1:59:00 PM	Sep 21, 2022 1:59:00 PM
Started	Sep 21, 2022 2:08:00 PM	
Completed	Sep 21, 2022 5:35:00 PM	Sep 21, 2022 5:35:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: VEHICLE CAME IN FOR CATALYTIC REPLAEMENT

Cause: NEED ONE

Correction: INSTALL NEW CATALYTIC CONVERTED TO UNIT PART 16773 AFTER PUT BATTERY ON CHARGE for ONE HOURS

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-SEP-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 21, 2022 5:33:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55971512
Invoice No. 55345 - 55971512

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CATALYTIC CONVERTER REPLACEMENT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 - DH

Activity Header
Activity: 15 043 EXHAUST SYSTEM
Activity Note: CATALYTIC CONVERTER REPLACEMENT (PROVIDED BY MV TRANSPORTATION)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Sep-22	Junior Hurst	3.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55971512 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55473564
Invoice No. 55345 - 55473564

Client Department:
Department: 55345M
Work Order Description
REAR AC SYSTEM MALFUNCTION
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Chronology		
Reported	Mar 29, 2022 8:54:43 AM	Mar 29, 2022 8:54:43 AM
Started	Mar 29, 2022 8:56:00 AM	
Completed	Jul 7, 2022 2:14:00 PM	Jul 7, 2022 2:14:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: No check engine lights
ABS light on/off
rear AC condenser fans stay on
codes: p0090:00-28 fuel pressure regulator A control circuit/open
p2665:00-28 fuel shutoff valve #B control circuit open
cylinders 3,5,6 misfires
C1145-20 & c1234-30 left front wheel sensor
p1602:00-28 immobilizer/ECM Communication errror
Park (P) indicator light in dashboard doesn't light when vehicle's in Parked
Cause:

Correction: Line 20 C: vehicle has rear a/c fans on all the time

C: check a/c system found fans stays on even when ignition key is off, follow diagnosis test to verify what module is causing the problem, replaced rear module, complete circuit board, front control module, open harness to verify why the main wire that controls the fans doesn't switch from ground to positive to make the relay work. compare all circuits with a good known bus to verify what circuit is not working as it should. when comparing system discover that main control wire is grounded and has a resistor connected to the circuit while testing circuit found that by disconnecting the circuit wire from ground fans now work as is designed but now the a/c compressor doesn't come on when system is turn on. at this time i call the company that manufactured the a/c system and explained what is happening with the vehicle the tech that i talk to he didn't know this system because is a few years old but he sent me a diagram but it was the wrong system not the one on this vehicle i call them back and he told me that the person that knew about this system it wasn't available. in order to fix this vehicle i need to talk to engineering who designed this a/c system because since the vehicle was new it had problems with the a/c not working properly

C: vehicle needs further diagnosis

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: PRAMETER Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 07-JUL-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jul 7, 2022 2:13:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55473564
Invoice No. 55345 - 55473564

Client Department:
Department: 55345M
Work Order Description
REAR AC SYSTEM MALFUNCTION
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Mar-22	Delva,Terry	2.92	0	0
30-Mar-22	Perez,Javier	2.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	5.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55473564
Invoice No. 55345 - 55473564

Client Department:
Department: 55345M
Work Order Description
REAR AC SYSTEM MALFUNCTION
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 - DH

Activity Header
Activity: 20 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Apr-22	Perez,Javier	2.42	0	0
02-May-22	Perez,Javier	2.95	0	0
29-Apr-22	Perez,Javier	1.67	0	0
04-May-22	Perez,Javier	2.82	0	0
02-May-22	Perez,Javier	4.3	0	0
08-Apr-22	Perez,Javier	5.38	0	0
07-Apr-22	Perez,Javier	5.88	0	0
01-Apr-22	Perez,Javier	7.38	0	0
06-Apr-22	Perez,Javier	5.05	0	0
03-May-22	Perez,Javier	2.43	0	0
09-May-22	Perez,Javier	1.83	0	0
31-Mar-22	Perez,Javier	2.1	0	0
03-May-22	Perez,Javier	1.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	45.94
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

	Work Order 55473564 Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	51.61
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54432274
Invoice No. 55345 - 54432274

Client Department:
Department: 55345M
Work Order Description
QCC FLEET INSPECTION
Requested By: DKNOTT
Created By: DKNOTT
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,852 -

Chronology		
Reported	Mar 29, 2022 8:33:39 AM	Mar 29, 2022 8:33:39 AM
Started		
Completed	Mar 31, 2022 2:39:00 PM	Mar 31, 2022 2:39:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION PERFORMED

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 31-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	
7 - Have you performed the proper LOTO?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	Mar 31, 2022 2:38:58 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54432274
Invoice No. 55345 - 54432274

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,852 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54432274 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Chronology		
Reported	Mar 23, 2022 8:45:19 PM	Mar 23, 2022 8:45:19 PM
Started	Mar 23, 2022 8:45:00 PM	
Completed	Mar 24, 2022 5:00:00 PM	Mar 24, 2022 5:00:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

==========

To file warranty be sure to do the following:

1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front rotors and brake pads, needs 6 new tires, needs rear brakes job

Cause: tires low spec, front rotors glaze and groove . rear brakes low spec

Correction:replaced front rotors, bearings ,seals pack bearings and replace
front brake pads. replaced 6 tires mount and balance.
rotors part number BRRF 115 qty2
front pads 8C2Z-2V001-D qty1
seals SL260029 qty2
inner bearings LM102949 qty2
outer bearings 15101 qty2
tires part number 192659 qty 6

Activity Header
Activity: 10 002/035/059 HARDWARE, MOUNTING, ARM, WIPER, WINDSHIELD, APFI - 002-035-016
Activity Note: needs wiper blades
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity: 20 042/004 PUMP, WATER
Activity Note: needs serpentine belt
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity:30 032/001/001 BATTERY
Activity Note: charging system not working , needs alternator
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity:40 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 front tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-22	Gaspard,Ronald	0.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity: 50 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front rotors and brake pads
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-22	Gaspard,Ronald	1.53	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 50 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity:60 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 right rear tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Gaspard,Ronald	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 60 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 259,447 - DH

Activity Header
Activity:70 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note: needs 2left rear tires
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	6	135.26	811.56
24-Mar-22	SL260029	SEAL, WHEEL	2	8.04	16.08
24-Mar-22	15101	BEARING, WHEEL, OUTER, FRONT	2	7.24	14.48
24-Mar-22	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	10.91	21.82
24-Mar-22	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	56.82	56.82
24-Mar-22	BRRF115	ROTOR & HUB, BRAKE, DISC, FRONT, E350	2	122.85	245.7

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	Gaspard,Ronald	0.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 70 Sub Total	
Parts:	1,166.46
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,166.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 8

Work Order No. 55459802
Invoice No. 55345 - 55459802

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 259,447 - DH

Activity Header
Activity: 80 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-22	BRCF418	CALIPER, BRAKE, DISC, REAR, LH	1	79.59	79.59
24-Mar-22	BC2Z-2C150-B	PIN, CALIPER, BRAKE, DISC, UPDATED, E450, '08	1	10.9	10.9
24-Mar-22	8C2Z-2200-B	PADS, BRAKE, DISC, REAR, E450 SAME AS PFH133020	1	41.4	41.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-22	NELSON PIERRE-LOUIS	2.88	0	0
23-Mar-22	Gaspard,Ronald	1	0	0
24-Mar-22	Gaspard,Ronald	0.18	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 80 Sub Total	
Parts:	131.89
Labor:	0.00
Labor Hours:	4.06
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.89**

Work Order Footer

Work Order 55459802 Total	
Parts:	1,298.35
Labor:	0.00
Labor Hours:	7.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,298.35**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55255351
Invoice No. 55345 - 55255351

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Chronology		
Reported	Mar 22, 2022 12:00:00 AM	Mar 22, 2022 12:00:00 AM
Started	Mar 23, 2022 4:11:00 PM	
Completed	Mar 23, 2022 11:40:00 PM	Mar 23, 2022 11:40:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:perform PMA Service
oil filter B329 qty1
engine oil 10w30 qty 7 qts
replaced AC filter PA 4075 qty1
clean batteries

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 23, 2022 4:55:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55255351
Invoice No. 55345 - 55255351

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 259,447 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Mar-22	PA4075	FILTER, AIR SEE P546597	1	7.92	7.92
23-Mar-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Mar-22	Gaspard,Ronald	3.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 23-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done	needs wiper blades	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done	needs serpentine belt	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.3 Volt*	charging system not working , needs alternator	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.3 Volt*		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Mar 23, 2022 8:44:35 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/ Lights;CHECK_for Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	2 32nds of an inch	needs 2 front tires	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	60 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	36 Inch	needs front rotors and brake pads	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	36 Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	3 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	2 32nds of an inch	needs 2 right rear tires	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	2 32nds of an inch	needs 2left rear tires	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	2 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	needs rear brakes job	RGASPARD	Mar 23, 2022 8:44:35 PM	Yes	55459802
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	39 Inch		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19224 Cycles		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Mar 23, 2022 8:44:35 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	9.91
Labor:	0.00
Labor Hours:	3.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55255351
Invoice No. 55345 - 55255351

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	259,447 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 23-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 23, 2022 8:16:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 23, 2022 8:16:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 23, 2022 8:16:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 23, 2022 8:16:22 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 23, 2022 8:16:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 23, 2022 8:16:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 23, 2022 8:16:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 23, 2022 8:16:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 55255351 Total	
Parts:	9.91
Labor:	0.00
Labor Hours:	3.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**9.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55423631
Invoice No. 55345 - 55423631

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Repair Tag Light		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,106 - DH

Chronology		
Reported	Mar 10, 2022 8:50:00 PM	Mar 10, 2022 8:50:00 PM
Started	Mar 10, 2022 8:51:00 PM	
Completed	Mar 10, 2022 9:36:00 PM	Mar 10, 2022 9:36:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Tag Light

Cause: tag Light out

Correction: Swap tag Light from bus 5425 ,Rellace on bus4606

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 10, 2022 9:33:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55423631
Invoice No. 55345 - 55423631

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Repair Tag Light		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	258,106 - DH

Activity Header
Activity: 15 174/024/001 HARNESS, WIRING, BODY, BUS, MAIN
Activity Note: Replace Tag Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-22	Arthurs,Durvin	0.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55423631 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55413011
Invoice No. 55345 - 55413011

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CATALYTIC CONVERTER		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	257,617 - DH

Chronology		
Reported	Mar 8, 2022 6:49:00 AM	Mar 8, 2022 6:49:00 AM
Started	Mar 8, 2022 7:05:00 AM	
Completed	Mar 8, 2022 12:05:00 PM	Mar 8, 2022 12:05:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT. check engine light on

Cause. Code P0420, bad catalytic converter

Correction. Removed and replaced catalytic converter.

Installed geotab.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-MAR-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 8, 2022 12:00:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55413011
Invoice No. 55345 - 55413011

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CATALYTIC CONVERTER		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	257,617 - DH

Activity Header
Activity: 20 043/000/000 EXHAUST SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Mar-22	9C2Z-5E212-E	CONVERTER, CATALYTIC	1	1,082.83	1,082.83
08-Mar-22	GU2Z-9G444-A	SENSOR, OXYGEN, DOWNSTREAM	1	26.02	26.02
08-Mar-22	F6TZ-5C226-BA	GASKET, FLANGE, CONVERTER, CATALYTIC	1	4.44	4.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-22	Rodriguez,Raul	2.03	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	1,113.29
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,113.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55413011
Invoice No. 55345 - 55413011

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CATALYTIC CONVERTER		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	257,617 - DH

Activity Header
Activity: 30 051/000/000 ACCESSORIES, GENERAL
Activity Note:
Reason for Repair: 23 Modification
Work Accomplished: 14 Install
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-22	Rodriguez,Raul	1.45	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55413011 Total	
Parts:	1,113.29
Labor:	0.00
Labor Hours:	3.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1,113.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55350568
Invoice No. 55345 - 55350568

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 255,755 - DH

Chronology		
Reported	Feb 14, 2022 8:58:00 PM	Feb 14, 2022 8:58:00 PM
Started	Feb 14, 2022 8:59:00 PM	
Completed	Feb 15, 2022 12:15:00 AM	Feb 15, 2022 12:15:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Rear AC malfunction.

Cause: TBD.

Correction: No correction performed. Could not verify Complaint. Let vehicle idle for an hour without any issues. Rear AC blows cold and on all speeds. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 14-FEB-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Feb 14, 2022 11:22:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55350568
Invoice No. 55345 - 55350568

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Rear AC)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 255,755 - DH

Activity Header
Activity: 20 001/001/001 AIR CONDITIONING
Activity Note: VERIFY COMPLAINT (Check Rear)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-22	Earl Johnson	1.23	0	0
15-Feb-22	Earl Johnson	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55350568 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 55036108
Invoice No. 55345 - 55036108

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,466 - DH

Chronology		
Reported	Dec 23, 2021 12:00:00 AM	Dec 23, 2021 12:00:00 AM
Started	Jan 12, 2022 4:09:00 PM	
Completed	Jan 12, 2022 7:43:00 PM	Jan 12, 2022 7:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Time for service. By miles

CORRECTION: Job complete oil filter replace part # B329 change rear A /C filter

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jan-22	Junior Hurst	0.12	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 12-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 12, 2022 4:14:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 55036108
Invoice No. 55345 - 55036108

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 254,466 - DH

Activity Header
Activity: 10 011RTD SUSPENSION
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jan-22	Junior Hurst	1.65	0	0
12-Jan-22	Junior Hurst	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 12-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Jan 12, 2022 5:56:05 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.16 Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.16 Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.18 Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.18 Inch		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19671 Cycles		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Jan 12, 2022 5:56:05 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 55036108
Invoice No. 55345 - 55036108

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 254,466 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jan-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.99	1.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jan-22	Junior Hurst	0.02	0	0
12-Jan-22	Junior Hurst	0.07	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 12-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Jan 12, 2022 6:38:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Jan 12, 2022 6:38:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Jan 12, 2022 6:38:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Jan 12, 2022 6:38:05 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Jan 12, 2022 6:38:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Jan 12, 2022 6:38:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Jan 12, 2022 6:38:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Jan 12, 2022 6:38:05 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.99
	Labor:	0.00
	Labor Hours:	0.09
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.99**

Work Order Footer

	Work Order 55036108 Total	
	Parts:	1.99
	Labor:	0.00
	Labor Hours:	2.51
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.99**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55252061
Invoice No. 55345 - 55252061

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,217 - DH

Chronology		
Reported	Jan 11, 2022 10:59:29 PM	Jan 11, 2022 10:59:29 PM
Started	Jan 11, 2022 11:00:00 PM	
Completed	Jan 12, 2022 12:11:00 AM	Jan 12, 2022 12:11:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: TBD.

Correction: Let vehicle idle for an hour with AC on without any issues. AC blows cold and on all fan speeds. Couldnot duplicate issue, will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 11-JAN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 11, 2022 11:58:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55252061
Invoice No. 55345 - 55252061

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	254,217 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-22	Earl Johnson	0.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55252061 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55171895
Invoice No. 55345 - 55171895

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Coolant Leaking		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	253,303 - DH

Chronology		
Reported	Dec 12, 2021 12:54:48 PM	Dec 12, 2021 12:54:48 PM
Started	Dec 12, 2021 2:29:00 PM	
Completed	Dec 12, 2021 4:43:00 PM	Dec 12, 2021 4:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Coolant Leak

Cause: Water Pump Leaking.

Correction: Remove & Replace Water Pump & Replace Coolant.
Parts # 4C3Z-8501-B Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-DEC-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:30:07 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 12, 2021 2:30:07 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 12, 2021 2:30:07 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 12, 2021 2:30:07 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 12, 2021 2:30:07 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 12, 2021 2:30:07 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55171895
Invoice No. 55345 - 55171895

Client Department:
Department: 55345M
Work Order Description
Coolant Leaking
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 253,303 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove & Replace Water Pump.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Dec-21	4C3Z-8501-B	PUMP, WATER, 6.8L	1	112.13	112.13

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-21	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	112.13
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.13**

Work Order Footer

Work Order 55171895 Total	
Parts:	112.13
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**112.13**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55099070
Invoice No. 55345 - 55099070

Client Department:
Department: 55345M
Work Order Description
WHEEL CHAIR LIFT NOT WORKING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 250,831 - DH

Chronology		
Reported	Nov 17, 2021 7:50:00 AM	Nov 17, 2021 7:50:00 AM
Started	Nov 17, 2021 9:33:00 AM	
Completed	Nov 18, 2021 10:06:00 AM	Nov 18, 2021 10:06:00 AM
Down Time		

Work Order Notes

Line 10 Lift not working properly

Bad inner shocks

Replace inner shocks completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 18-NOV-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 18, 2021 10:05:15 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55099070
Invoice No. 55345 - 55099070

Client Department:
Department: 55345M
Work Order Description
WHEEL CHAIR LIFT NOT WORKING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 250,831 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Nov-21	32831	SPRING, SHOCK, GAS, W/C	1	27.27	27.27
22-Nov-21	45554	BOARD, CIRCUIT, PRINTED, W/C, RICON W/BRACKET KIT	1	316	316

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Nov-21	Pierre,Hubert J	4.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	343.27
Labor:	0.00
Labor Hours:	4.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**343.27**

Work Order Footer

Work Order 55099070 Total	
Parts:	343.27
Labor:	0.00
Labor Hours:	4.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**343.27**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55036091
Invoice No. 55345 - 55036091

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,863 - DH

Chronology		
Reported	Oct 27, 2021 12:30:05 PM	Oct 27, 2021 12:30:05 PM
Started	Oct 27, 2021 12:33:00 PM	
Completed	Oct 27, 2021 1:55:00 PM	Oct 27, 2021 1:55:00 PM
Down Time		

Work Order Notes

Line 10 PMB follows up need front brake and driver side caliper

Preventive maintenance

Replace front brake pads and caliper completed

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: Need front brake pads
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55036091
Invoice No. 55345 - 55036091

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,863 - DH

Activity Header
Activity: 20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Oct-21	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	51.88	51.88
28-Oct-21	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	1	9.49	9.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-21	Pierre,Hubert J	1.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	61.37
Labor:	0.00
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.37**

Work Order Footer

Work Order 55036091 Total	
Parts:	61.37
Labor:	0.00
Labor Hours:	1.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**61.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54816715
Invoice No. 55345 - 54816715

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,863 - DH

Chronology		
Reported	Oct 26, 2021 12:00:00 AM	Oct 26, 2021 12:00:00 AM
Started	Oct 27, 2021 12:13:00 PM	
Completed	Oct 27, 2021 12:32:00 PM	Oct 27, 2021 12:32:00 PM
Down Time		

Work Order Notes

Line 10 PMB
Preventive maintenance

Perform PMB lube all pivoting point cross rotate tires completed

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 27, 2021 12:15:54 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54816715
Invoice No. 55345 - 54816715

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,863 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 27-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Oct 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:30:34 PM		
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical	Done		HPIERRE	Oct 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Inputs/Outputs-SOP M038				12:30:34 PM		
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch	Need front brake pads	HPIERRE	Oct 27, 2021 12:30:34 PM	Yes	55036091
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.6 Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.6 Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	70 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.6 Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.6 Inch		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	2232 Cycles		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		HPIERRE	Oct 27, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				12:30:34 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Oct 27, 2021 12:30:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54816715
Invoice No. 55345 - 54816715

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 249,863 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Oct-21	P9600	FILTER, OIL SEE LF16424	1	3.49	3.49

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-21	Pierre,Hubert J	0.32	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 27-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
302,000 - Check Toe-In and Record Reading	Done		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Oct 27, 2021 12:15:22 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Oct 27, 2021 12:15:22 PM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Oct 27, 2021 12:15:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	3.49
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.49**

Work Order Footer

Work Order 54816715 Total	
Parts:	3.49
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.49**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 55013196
Invoice No. 55345 - 55013196

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fixed Flat Tire		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,588 - DH

Chronology		
Reported	Oct 21, 2021 5:42:00 PM	Oct 21, 2021 5:42:00 PM
Started	Oct 21, 2021 5:43:00 PM	
Completed	Oct 22, 2021 12:13:00 AM	Oct 22, 2021 12:13:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:left rear tire flat

Cause: screw

Correction:patched tire mount and balance
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-OCT-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 21, 2021 6:17:00 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 55013196
Invoice No. 55345 - 55013196

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fixed Flat Tire		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	249,588 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-21	Gaspard,Ronald	0.65	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 55013196 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54931371
Invoice No. 55345 - 54931371

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace Drain Plug		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	248,555 - DH

Chronology		
Reported	Sep 24, 2021 5:29:00 PM	Sep 24, 2021 5:29:00 PM
Started		
Completed	Sep 24, 2021 5:34:00 PM	Sep 24, 2021 5:34:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 24-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Sep 24, 2021 5:34:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		AOWENS	Sep 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				5:34:12 PM		
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Sep 24, 2021 5:34:12 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Sep 24, 2021 5:34:12 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Sep 24, 2021 5:34:12 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Sep 24, 2021 5:34:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54931371
Invoice No. 55345 - 54931371

Client Department:
Department: 55345M
Work Order Description
Replace Drain Plug
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 248,555 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Drain Plug
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Sep-21	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order Footer

Work Order 54931371 Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54895406
Invoice No. 55345 - 54895406

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front A/C blower		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,283 - DH

Chronology		
Reported	Sep 13, 2021 2:40:02 PM	Sep 13, 2021 2:40:02 PM
Started	Sep 13, 2021 2:57:00 PM	
Completed	Sep 13, 2021 4:30:00 PM	Sep 13, 2021 4:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
Vehicle came in for front blower

Cause: Worn out

Correction: removed and replaced new one part # XC2Z-19805-BA. blower now working as design return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 13-SEP-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Sep 13, 2021 4:25:50 PM	No	
20 - Miles			JUHURST	Sep 13, 2021 4:25:50 PM	No	
30 - Kilometers			JUHURST	Sep 13, 2021 4:25:50 PM	No	
40 - Hours			JUHURST	Sep 13, 2021 4:25:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54895406
Invoice No. 55345 - 54895406

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front A/C blower		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	247,283 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front A/C blower
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-21	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	37.24	37.24
13-Sep-21	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	37.24	37.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-21	Junior Hurst	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	74.48
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**74.48**

Work Order Footer

Work Order 54895406 Total	
Parts:	74.48
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**74.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54432670
Invoice No. 55345 - 54432670

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	245,359 - DH

Chronology		
Reported	Aug 16, 2021 12:07:06 PM	Aug 16, 2021 12:07:06 PM
Started	Aug 16, 2021 2:22:00 PM	
Completed	Aug 16, 2021 4:51:00 PM	Aug 16, 2021 4:51:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Service by miles

CORRECTION: change oil filter part # 329 also change rear A /C filter Job complete return vehicle back to work

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-21	Junior Hurst	0.1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 16-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 16, 2021 2:26:27 PM	No	
20 - Miles			JUHURST	Aug 16, 2021 2:26:27 PM	No	
30 - Kilometers			JUHURST	Aug 16, 2021 2:26:27 PM	No	
40 - Hours			JUHURST	Aug 16, 2021 2:26:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54432670
Invoice No. 55345 - 54432670

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,359 - DH

Activity Header
Activity: 10
Activity Note: Light Duty PMI
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Aug-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-21	Junior Hurst	2.28	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 16-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Aug 16, 2021 4:26:12 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,250 - INSPECT_Overhead Compartment for Water	Done		JUHURST	Aug 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks				4:26:12 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
41,200 - INSPECT_ Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	7.22 Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	7.22 Inch		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19257 Cycles		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		JUHURST	Aug 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				4:26:12 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Aug 16, 2021 4:26:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	2.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54432670
Invoice No. 55345 - 54432670

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 245,359 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Aug-21	Junior Hurst	0.08	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 16-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Aug 16, 2021 4:47:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Aug 16, 2021 4:47:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Aug 16, 2021 4:47:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Aug 16, 2021 4:47:50 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Aug 16, 2021 4:47:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Aug 16, 2021 4:47:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Aug 16, 2021 4:47:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Aug 16, 2021 4:47:50 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 54432670 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	2.46
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54733193
Invoice No. 55345 - 54733193

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,949 - DH

Chronology		
Reported	Jul 15, 2021 10:11:09 PM	Jul 15, 2021 10:11:09 PM
Started	Jul 15, 2021 10:13:00 PM	
Completed	Jul 16, 2021 12:21:00 AM	Jul 16, 2021 12:21:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: Condenser fans not working properly.

Correction: Remove and replaced 2 condenser fans. Remove and replaced rear Orifice tube and performed AC tune up.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 16-JUL-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
20 - Miles			EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
30 - Kilometers			EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	
40 - Hours			EARJOHNSON	Jul 16, 2021 12:05:56 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54733193
Invoice No. 55345 - 54733193

Client Department:
Department: 55345M
Work Order Description
Rear AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 242,949 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jul-21	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	2	69.54	139.08
16-Jul-21	3411885	TUBE, ORIFICE, A/C, FORD	1	0.73	0.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jul-21	Earl Johnson	0.35	0	0
15-Jul-21	Earl Johnson	1.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	139.81
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**139.81**

Work Order Footer

Work Order 54733193 Total	
Parts:	139.81
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**139.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54695082
Invoice No. 55345 - 54695082

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine misfire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 - DH

Chronology		
Reported	Jun 30, 2021 4:54:28 PM	Jun 30, 2021 4:54:28 PM
Started	Jun 30, 2021 4:56:00 PM	
Completed	Jun 30, 2021 11:58:00 PM	Jun 30, 2021 11:58:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Engine Misfire

Cause: Scan Bus Found Code PO300 / PO 306;/PO308 / P2096 & 2098 post Catalytic

Correction: Check Compression Check Plugs.Swap # (6) & # (8) Coil & Replace DownStream O2 sensor but P2096&P2098 Won¿t Clear.Possible PCM.
Parts # GU2Z-9G444-A Qty (1).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 30-JUN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 30, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:50:18 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 30, 2021 11:50:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 30, 2021 11:50:18 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 30, 2021 11:50:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 30, 2021 11:50:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 30, 2021 11:50:18 PM	No	
20 - Miles			DARTHURS	Jun 30, 2021 11:50:18 PM	No	
30 - Kilometers			DARTHURS	Jun 30, 2021 11:50:18 PM	No	
40 - Hours			DARTHURS	Jun 30, 2021 11:50:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54695082
Invoice No. 55345 - 54695082

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine misfire		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Engine misfire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-21	GU2Z-9G444-A	SENSOR, OXYGEN, DOWNSTREAM	1	26.02	26.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-21	Arthurs,Durvin	6.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	26.02
Labor:	0.00
Labor Hours:	6.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.02**

Work Order Footer

Work Order 54695082 Total	
Parts:	26.02
Labor:	0.00
Labor Hours:	6.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54432225
Invoice No. 55345 - 54432225

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	99 - Cancelled (99)
Created By:	JUHURST	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,341 - DH

Chronology		
Reported	Apr 1, 2021 2:49:16 PM	Apr 1, 2021 2:49:16 PM
Started		
Completed	Jun 14, 2021 2:34:07 PM	Jun 14, 2021 2:34:07 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 10 017/009/016 VALVE, PROTECTION, PRESSURE, TIRE
Activity Note:
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54432225 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53558167
Invoice No. 55345 - 53558167

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 -

Chronology		
Reported	Jun 14, 2021 2:01:42 PM	Jun 14, 2021 2:01:42 PM
Started		
Completed	Jun 14, 2021 2:33:48 PM	Jun 14, 2021 2:33:48 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53558167
Invoice No. 55345 - 53558167

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 -

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: ANNUAL A/C INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53558167 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557983
Invoice No. 55345 - 53557983

Client Department:
Department: 55345M
Work Order Description
55345-FIRE SAFETY INSPECTION
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 242,556 -

Chronology		
Reported	Jun 14, 2021 2:01:42 PM	Jun 14, 2021 2:01:42 PM
Started		
Completed	Jun 14, 2021 2:33:06 PM	Jun 14, 2021 2:33:06 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557983
Invoice No. 55345 - 53557983

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-FIRE SAFETY INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: ANNUAL FIRE SAFETY INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557983 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53557808
Invoice No. 55345 - 53557808

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 -

Chronology		
Reported	Jun 14, 2021 2:01:43 PM	Jun 14, 2021 2:01:43 PM
Started		
Completed	Jun 14, 2021 2:29:38 PM	Jun 14, 2021 2:29:38 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53557808
Invoice No. 55345 - 53557808

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	99 - Cancelled (99)
Created By:	NSTOLFO	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 -

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: PTC INSPECTION
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53557808 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54557243
Invoice No. 55345 - 54557243

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 - DH

Chronology

Reported	May 12, 2021 7:08:20 AM	May 12, 2021 7:08:20 AM
Started	May 24, 2021 12:00:00 AM	
Completed	May 24, 2021 10:59:00 AM	May 24, 2021 10:59:00 AM
Down Time		

Work Order Notes

Line 10 Removed camera and MDT, INSTALLED TO NEW BUS

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-May-21	Rodriguez,Raul	2.15	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 24-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
20 - Miles			RAURODRIGUEZ	May 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:58:34 AM		
30 - Kilometers			RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	
40 - Hours			RAURODRIGUEZ	May 24, 2021 10:58:34 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54557243
Invoice No. 55345 - 54557243

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54557243 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54546647
Invoice No. 55345 - 54546647

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Requested By: DGALLAGHER
Created By: DGALLAGHER
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 242,556 - DH

Chronology		
Reported	May 11, 2021 2:27:25 PM	May 11, 2021 2:27:25 PM
Started		
Completed	May 19, 2021 1:41:35 PM	May 19, 2021 1:41:35 PM
Down Time		

Work Order Notes

Line 10 Unit is out of service

Activity Header
Activity: 10 999/999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54546647
Invoice No. 55345 - 54546647

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FIRST TRANSIT - NORTH AMERICA - CONSPICUITY		Ford E450 Champion Challenger	
Requested By:	DGALLAGHER	**Status:**	99 - Cancelled (99)
Created By:	DGALLAGHER	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,556 - DH

Activity Header
Activity:20 053/005/018 TAPE, REFLECTIVE
Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Reason for Repair: IC Internal Campaign
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY
Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:					No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54546647 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54492533
Invoice No. 55345 - 54492533

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	242,217 - DH

Chronology		
Reported	Apr 22, 2021 4:13:39 PM	Apr 22, 2021 4:13:39 PM
Started	Apr 22, 2021 4:19:00 PM	
Completed	Apr 22, 2021 7:12:00 PM	Apr 22, 2021 7:12:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for rear A/C not cooling

Cause: Office tube not clean

Correction: removed and replaced new office tube recharge unit 6 pound 08 Oz free on A/C now working as design return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 22, 2021 7:10:18 PM	No	
20 - Miles			JUHURST	Apr 22, 2021 7:10:18 PM	No	
30 - Kilometers			JUHURST	Apr 22, 2021 7:10:18 PM	No	
40 - Hours			JUHURST	Apr 22, 2021 7:10:18 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54492533
Invoice No. 55345 - 54492533

Client Department:
Department: 55345M
Work Order Description
Rear A/C
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 242,217 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Apr-21	3411885	TUBE, ORIFICE, A/C, FORD	1	0.74	0.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-21	Junior Hurst	2.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.74
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.74**

Work Order Footer

Work Order 54492533 Total	
Parts:	0.74
Labor:	0.00
Labor Hours:	2.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54467731
Invoice No. 55345 - 54467731

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,635 - DH

Chronology		
Reported	Apr 14, 2021 1:19:00 PM	Apr 14, 2021 1:19:00 PM
Started	Apr 14, 2021 2:02:00 PM	
Completed	Apr 15, 2021 9:54:00 AM	Apr 15, 2021 9:54:00 AM
Down Time		

Work Order Notes

Line 10 C: Check engine light on

C: Check computer system found codes for lean condition on both banks and o2 sensors bias lean condition

C: inspect all systems found intake hose was disconnected and replaced one ignition coil. Retest and road test vehicle ok at this time

Part:
1 ignition coil 26326

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 15-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
20 - Miles			JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
30 - Kilometers			JAPEREZ	Apr 15, 2021 9:54:16 AM	No	
40 - Hours			JAPEREZ	Apr 15, 2021 9:54:16 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54467731
Invoice No. 55345 - 54467731

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,635 - DH

Activity Header
Activity: 20 033 IGNITION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Apr-21	26326	PLUG, COIL, IGNITION	1	28.89	28.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-21	Perez,Javier	1.53	0	0
15-Apr-21	Perez,Javier	2.22	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	28.89
Labor:	0.00
Labor Hours:	3.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.89**

Work Order Footer

Work Order 54467731 Total	
Parts:	28.89
Labor:	0.00
Labor Hours:	3.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 54319333
Invoice No. 55345 - 54319333

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,341 - DH

Chronology		
Reported	Apr 1, 2021 12:00:00 AM	Apr 1, 2021 12:00:00 AM
Started	Apr 1, 2021 12:21:00 PM	
Completed	Apr 1, 2021 4:26:00 PM	Apr 1, 2021 4:26:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Unit in service

CAUSE: Time for service

CORRECTION: service job complete Line 20 Rear brakes below specifications Line 30 Rear brake was below specification replaced new set. Part # 8C2Z-2V200-C not showing in stock also B329 oil filter

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Junior Hurst	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 1, 2021 12:21:46 PM	No	
20 - Miles			JUHURST	Apr 1, 2021 12:21:46 PM	No	
30 - Kilometers			JUHURST	Apr 1, 2021 12:21:46 PM	No	
40 - Hours			JUHURST	Apr 1, 2021 12:21:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 54319333
Invoice No. 55345 - 54319333

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 241,341 - DH

Activity Header
Activity: 10 020 GROUP, DRIVETRAIN
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Junior Hurst	2.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:48:56 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Apr 1, 2021 2:48:56 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		JUHURST	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				2:48:56 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	5 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	Yes	54432225
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	9 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	.799 Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	.799 Inch		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19065 Cycles		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		JUHURST	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				2:48:56 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 1, 2021 2:48:56 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 54319333
Invoice No. 55345 - 54319333

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 241,341 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Junior Hurst	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: JUHURST Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 1, 2021 2:51:16 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 1, 2021 2:51:16 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 1, 2021 2:51:16 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 1, 2021 2:51:16 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 1, 2021 2:51:16 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 1, 2021 2:51:16 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Apr 1, 2021 2:51:16 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 1, 2021 2:51:16 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 54319333
Invoice No. 55345 - 54319333

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 241,341 - DH

Activity Header
Activity: 30 021RTD BRAKES
Activity Note: Rear brakes
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Apr-21	Junior Hurst	1.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54319333 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53544619
Invoice No. 55345 - 53544619

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	**Status:**	40 - Closed (40)
Created By:	RBOOTH	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,341 -

Chronology		
Reported	Apr 1, 2021 2:52:30 PM	Apr 1, 2021 2:52:30 PM
Started		
Completed	Apr 1, 2021 2:58:48 PM	Apr 1, 2021 2:58:48 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: DKNOTT Performed on: 01-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
4 - Have you performed the proper LOTO?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DKNOTT	Apr 1, 2021 2:58:01 PM	No	
20 - Miles			DKNOTT	Apr 1, 2021 2:58:01 PM	No	
30 - Kilometers			DKNOTT	Apr 1, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:58:01 PM		
40 - Hours			DKNOTT	Apr 1, 2021 2:58:01 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53544619
Invoice No. 55345 - 53544619

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	**Status:**	40 - Closed (40)
Created By:	RBOOTH	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	241,341 -

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: QCC FLEET INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53544619 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54371662
Invoice No. 55345 - 54371662

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,389 - DH

Chronology		
Reported	Mar 11, 2021 1:38:31 PM	Mar 11, 2021 1:38:31 PM
Started	Mar 11, 2021 1:45:00 PM	
Completed	Mar 11, 2021 4:10:00 PM	Mar 11, 2021 4:10:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: rear A/C not cooling

Cause: low power

Correction: clean battery connector and check AC complete unit now working as design this unit has 6 lbs. 8 oz. of Freon inside for the rear Return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 11, 2021 3:35:25 PM	No	
20 - Miles			JUHURST	Mar 11, 2021 3:35:25 PM	No	
30 - Kilometers			JUHURST	Mar 11, 2021 3:35:25 PM	No	
40 - Hours			JUHURST	Mar 11, 2021 3:35:25 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54371662
Invoice No. 55345 - 54371662

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	239,389 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rea A/C
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Mar-21	Junior Hurst	2.4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54371662 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54189890
Invoice No. 55345 - 54189890

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	237,030 - DH

Chronology		
Reported	Feb 22, 2021 1:46:55 PM	Feb 22, 2021 1:46:55 PM
Started	Feb 22, 2021 12:00:00 AM	
Completed	Feb 22, 2021 1:59:00 PM	Feb 22, 2021 1:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 22-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Feb 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	1:58:36 PM		
20 - Miles			NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	
40 - Hours			NPIERRE-LOUIS	Feb 22, 2021 1:58:36 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54189890
Invoice No. 55345 - 54189890

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 237,030 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-21	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 22-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Feb 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:56:36 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.3 Volt*		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.5 Volt*		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Feb 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	1:56:36 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.9 Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		NPIERRE-	Feb 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment			LOUIS	1:56:36 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Feb 22, 2021 1:56:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54189890
Invoice No. 55345 - 54189890

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMB
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 237,030 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: NPIERRE-LOUIS Performed on: 22-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Feb 22, 2021 1:59:39 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 54189890 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54272195
Invoice No. 55345 - 54272195

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 235,341 - DH

Chronology		
Reported	Feb 4, 2021 10:29:00 PM	Feb 4, 2021 10:29:00 PM
Started	Feb 4, 2021 11:44:00 PM	
Completed	Feb 5, 2021 12:18:00 AM	Feb 5, 2021 12:18:00 AM
Down Time		

Work Order Notes

Line 10 Check engine light illuminated. Cleared lean DTCs and road tested without any issues. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Feb-21	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
20 - Miles			EARJOHNSON	Feb 4, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:47:30 PM		
30 - Kilometers			EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	
40 - Hours			EARJOHNSON	Feb 4, 2021 11:47:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54272195
Invoice No. 55345 - 54272195

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 235,341 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT (Check Engine Light On)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Feb-21	Earl Johnson	0.27	0	0
05-Feb-21	Earl Johnson	0.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.54
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54272195 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.59
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54259949
Invoice No. 55345 - 54259949

Client Department:
Department: 55345M
Work Order Description
Road Call TRANSMISSION ISSUE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 235,016 - DH

Chronology		
Reported	Feb 1, 2021 2:06:00 PM	Feb 1, 2021 2:06:00 PM
Started	Feb 2, 2021 9:33:00 AM	
Completed	Feb 4, 2021 10:30:00 AM	Feb 4, 2021 10:30:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: transmission

Cause: internal defective

Correction: Replaced transmission

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 04-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Feb 4, 2021 10:11:44 AM	No	
20 - Miles			TDELVA	Feb 4, 2021 10:11:44 AM	No	
30 - Kilometers			TDELVA	Feb 4, 2021 10:11:44 AM	No	
40 - Hours			TDELVA	Feb 4, 2021 10:11:44 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54259949
Invoice No. 55345 - 54259949

Client Department:
Department: 55345M
Work Order Description
Road Call TRANSMISSION ISSUE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 235,016 - DH

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: ROAD CALL
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-21	Delva,Terry	2.98	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54259949
Invoice No. 55345 - 54259949

Client Department:
Department: 55345M
Work Order Description
Road Call TRANSMISSION ISSUE
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WORC - WORK ORDER ROAD CALL
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 235,016 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Feb-21	19180251	TRANSMISSION, REMANUFACTURED	1	261.5	261.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Feb-21	Delva,Terry	7.9	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
20 Desc: Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: TDELVA Performed on: 04-FEB-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		TDELVA	Feb 4, 2021 10:11:27 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	261.50
Labor:	0.00
Labor Hours:	7.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.50**

Work Order Footer

Work Order 54259949 Total	
Parts:	261.50
Labor:	0.00
Labor Hours:	10.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**261.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54229537
Invoice No. 55345 - 54229537

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check engine light		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	234,012 - DH

Chronology		
Reported	Jan 21, 2021 1:05:24 PM	Jan 21, 2021 1:05:24 PM
Started	Jan 21, 2021 1:39:00 PM	
Completed	Jan 22, 2021 12:25:00 PM	Jan 22, 2021 12:25:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for check engine light

Cause: Worn out plugs

Correction: removed all plugs and replaced Ten new. Part # zap 103 change one coil part # 26326 and replace five coil Boot part #35-7006 after return vehicle back to work

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jan-21	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 21, 2021 1:39:57 PM	No	
20 - Miles			JUHURST	Jan 21, 2021 1:39:57 PM	No	
30 - Kilometers			JUHURST	Jan 21, 2021 1:39:57 PM	No	
40 - Hours			JUHURST	Jan 21, 2021 1:39:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54229537
Invoice No. 55345 - 54229537

Client Department:
Department: 55345M
Work Order Description
Check engine light
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 234,012 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Check engine light
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jan-21	26326	PLUG, COIL, IGNITION	1	25.01	25.01
21-Jan-21	AP103	PLUG, SPARK	10	3.52	35.2

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jan-21	Junior Hurst	7.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	60.21
Labor:	0.00
Labor Hours:	7.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.21**

Work Order Footer

Work Order 54229537 Total	
Parts:	60.21
Labor:	0.00
Labor Hours:	7.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**60.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54216656
Invoice No. 55345 - 54216656

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift / REAR A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,638 - DH

Chronology		
Reported	Jan 18, 2021 1:03:35 PM	Jan 18, 2021 1:03:35 PM
Started	Jan 18, 2021 1:07:00 PM	
Completed	Jan 18, 2021 1:44:00 PM	Jan 18, 2021 1:44:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for lift /. A/C check

Cause:

Correction: unit working good

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jan-21	Junior Hurst	0.02	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 18-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jan 18, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:41:04 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jan 18, 2021 1:41:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Jan 18, 2021 1:41:04 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Jan 18, 2021 1:41:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jan 18, 2021 1:41:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jan 18, 2021 1:41:04 PM	No	
20 - Miles			JUHURST	Jan 18, 2021 1:41:04 PM	No	
30 - Kilometers			JUHURST	Jan 18, 2021 1:41:04 PM	No	
40 - Hours			JUHURST	Jan 18, 2021 1:41:04 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54216656
Invoice No. 55345 - 54216656

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift / REAR A/C		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,638 - DH

Activity Header
Activity: 15 004 AERODYNAMIC DEVICES (POWER UNITS & TRAILERS)
Activity Note: Lift/A/C
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Jan-21	Junior Hurst	0.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54216656 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54206677
Invoice No. 55345 - 54206677

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fuel filler neck.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,323 - DH

Chronology		
Reported	Jan 13, 2021 8:50:01 PM	Jan 13, 2021 8:50:01 PM
Started	Jan 13, 2021 8:52:00 PM	
Completed	Jan 13, 2021 11:12:00 PM	Jan 13, 2021 11:12:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction: Line 20 Fuel filler neck support damaged, will need to be replaced.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-21	Earl Johnson	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 13, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:52:05 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
20 - Miles			EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
30 - Kilometers			EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	
40 - Hours			EARJOHNSON	Jan 13, 2021 9:52:05 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54206677
Invoice No. 55345 - 54206677

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fuel filler neck.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	233,323 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Fuel filler neck.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-21	Earl Johnson	0.98	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54206677 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 54189888
Invoice No. 55345 - 54189888

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---> Replace Rear Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 232,863 - DH

Chronology		
Reported	Jan 8, 2021 12:33:00 AM	Jan 8, 2021 12:33:00 AM
Started	Jan 8, 2021 4:25:00 PM	
Completed	Jan 8, 2021 5:13:00 PM	Jan 8, 2021 5:13:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint:needs rear brakes job

Cause: wear

Correction: replaced rear brake pads and lubed guide pins
Part number 8C2Z-2V200-C Qty1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity: 10 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs rear brakes job.
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jan-21	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	44.97	44.97

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-21	Gaspard,Ronald	0.78	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	44.97
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.97**

Work Order Footer

Work Order 54189888 Total	
Parts:	44.97
Labor:	0.00
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54190286
Invoice No. 55345 - 54190286

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lights		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,863 - DH

Chronology		
Reported	Jan 8, 2021 7:45:00 AM	Jan 8, 2021 7:45:00 AM
Started	Jan 8, 2021 7:54:00 AM	
Completed	Jan 8, 2021 9:46:00 AM	Jan 8, 2021 9:46:00 AM
Down Time		

Work Order Notes

Line 10 C: Left side interior lights not working

C: inspect interior lights system found main board rear connector install in the wrong side

C: install pug in the right connector, install lights

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 08-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
20 - Miles			JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
30 - Kilometers			JAPEREZ	Jan 8, 2021 9:46:16 AM	No	
40 - Hours			JAPEREZ	Jan 8, 2021 9:46:16 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54190286
Invoice No. 55345 - 54190286

Client Department:
Department: 55345M
Work Order Description
Lights
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 232,863 - DH

Activity Header
Activity: 20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-21	Perez,Javier	1.82	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54190286 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54053822
Invoice No. 55345 - 54053822

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,863 - DH

Chronology		
Reported	Jan 7, 2021 12:00:00 AM	Jan 7, 2021 12:00:00 AM
Started	Jan 7, 2021 10:36:00 PM	
Completed	Jan 8, 2021 12:37:00 AM	Jan 8, 2021 12:37:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 qts

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 7, 2021 10:36:31 PM	No	
20 - Miles			RGASPARD	Jan 7, 2021 10:36:31 PM	No	
30 - Kilometers			RGASPARD	Jan 7, 2021 10:36:31 PM	No	
40 - Hours			RGASPARD	Jan 7, 2021 10:36:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54053822
Invoice No. 55345 - 54053822

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 232,863 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Light Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-21	Gaspard,Ronald	0.53	0	0
07-Jan-21	Gaspard,Ronald	0.35	0	0
07-Jan-21	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 08-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jan 8, 2021 12:32:38 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,200 - INSPECT_Insurance/Registration/ Regulatory Forms Dates	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,250 - INSPECT_Overhead Compartment for	Done		RGASPARD	Jan 8, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Water Leaks				12:32:38 AM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	6 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings,	Done		RGASPARD	Jan 8, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Sensors, Routing of Cables				12:32:38 AM		
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch	needs rear brakes job.	RGASPARD	Jan 8, 2021 12:32:38 AM	Yes	54189888
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	4 32nds of an inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	12125 Cycles		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jan 8, 2021 12:32:38 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54053822
Invoice No. 55345 - 54053822

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 232,863 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jan-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jan-21	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 08-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 8, 2021 12:33:39 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 8, 2021 12:33:39 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 8, 2021 12:33:39 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 8, 2021 12:33:39 AM	No	
104,000 - Lubricate Chassis	Done	na	RGASPARD	Jan 8, 2021 12:33:39 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 8, 2021 12:33:39 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 8, 2021 12:33:39 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 8, 2021 12:33:39 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order Footer

Work Order 54053822 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54169427
Invoice No. 55345 - 54169427

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
CHECK ENGINE LIGHT ON +REAR AC		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	232,444 - DH

Chronology		
Reported	Dec 30, 2020 9:42:00 AM	Dec 30, 2020 9:42:00 AM
Started	Dec 30, 2020 9:46:00 AM	
Completed	Jan 5, 2021 11:58:00 AM	Jan 5, 2021 11:58:00 AM
Down Time		

Work Order Notes

Line 10 C: Rear a/c not working properly

C: inspect and test system, remove wire harness related to compressor ohms harness and connectors test all items related to turn compressor on, a/c module shows low voltage randomly, test alternator found low amperage when is loaded, retest a/c still shows low voltage. Compare signals and system with another vehicle found the other vehicle has an extra circuit board containing a relay

C: install circuit board retest system and road test vehicle ok at this time

Part:
1 new alternator gc2z-10346-c

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 05-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
20 - Miles			JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
30 - Kilometers			JAPEREZ	Jan 5, 2021 11:57:47 AM	No	
40 - Hours			JAPEREZ	Jan 5, 2021 11:57:47 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54169427
Invoice No. 55345 - 54169427

Client Department:
Department: 55345M
Work Order Description
CHECK ENGINE LIGHT ON +REAR AC
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 232,444 - DH

Activity Header
Activity: 20 030 ELECTRICAL GROUP
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jan-21	GC2Z-10346-C	ALTERNATOR, 6.8L, E350	1	207.44	207.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Dec-20	Perez,Javier	3.07	0	0
04-Jan-21	Perez,Javier	7.82	0	0
05-Jan-21	Perez,Javier	3.95	0	0
30-Dec-20	Perez,Javier	1.48	0	0
01-Jan-21	Perez,Javier	3.02	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	207.44
Labor:	0.00
Labor Hours:	19.34
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**207.44**

Work Order Footer

Work Order 54169427 Total	
Parts:	207.44
Labor:	0.00
Labor Hours:	19.34
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**207.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54122297
Invoice No. 55345 - 54122297

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front Air Conditioning System		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,541 - DH

Chronology		
Reported	Dec 10, 2020 9:45:00 AM	Dec 10, 2020 9:45:00 AM
Started	Dec 10, 2020 9:54:00 AM	
Completed	Dec 10, 2020 11:14:00 AM	Dec 10, 2020 11:14:00 AM
Down Time		

Work Order Notes

Line 10 C: Front heater is not working

C: Check a/c and heater system found blend door is not working

C: Replaced blend door retest system ok at this time

Part:
1 new blend door motor 604-200

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 10-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 10, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:14:32 AM		
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
20 - Miles			JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
30 - Kilometers			JAPEREZ	Dec 10, 2020 11:14:32 AM	No	
40 - Hours			JAPEREZ	Dec 10, 2020 11:14:32 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54122297
Invoice No. 55345 - 54122297

Client Department:
Department: 55345M
Work Order Description
Front Air Conditioning System
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 230,541 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Dec-20	604-200	ACTUATOR, DOOR, BLEND	1	26.83	26.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Dec-20	Perez,Javier	1.27	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order Footer

Work Order 54122297 Total	
Parts:	26.83
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**26.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54121186
Invoice No. 55345 - 54121186

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 230,541 - DH

Chronology		
Reported	Dec 9, 2020 10:03:00 PM	Dec 9, 2020 10:03:00 PM
Started	Dec 9, 2020 12:00:00 AM	
Completed	Dec 9, 2020 10:16:00 PM	Dec 9, 2020 10:16:00 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 09-DEC-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Dec 9, 2020 10:08:33 PM	No	
20 - Miles			AOWENS	Dec 9, 2020 10:08:33 PM	No	
30 - Kilometers			AOWENS	Dec 9, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:08:33 PM		
40 - Hours			AOWENS	Dec 9, 2020 10:08:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54121186
Invoice No. 55345 - 54121186

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check Engine Light On)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	230,541 - DH

Activity Header
Activity: 20 043/000/000 EXHAUST SYSTEM
Activity Note: VERIFY COMPLAINT(Check Engine Light On)
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54121186
Invoice No. 55345 - 54121186

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 230,541 - DH

Activity Header
Activity: 30 043/000/000 EXHAUST SYSTEM
Activity Note: Replace O2 Sensor
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-20	8F9Z-9F472-H	SENSOR, OXYGEN	1	70.83	70.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-20	Owens,Arthur	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	70.83
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.83**

Work Order Footer

Work Order 54121186 Total	
Parts:	70.83
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**70.83**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54083750
Invoice No. 55345 - 54083750

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
W/C Lift No Power To Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	229,502 - DH

Chronology		
Reported	Nov 24, 2020 8:39:30 PM	Nov 24, 2020 8:39:30 PM
Started	Nov 24, 2020 8:41:00 PM	
Completed	Nov 24, 2020 10:59:00 PM	Nov 24, 2020 10:59:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: No Power To the small wire

Cause: Wire From Circuit Board To inter lock module was loose.

Correction: Secure Wire & Swap Relay . All is good at This time. No parts needed.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 24, 2020 8:42:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		DARTHURS	Nov 24, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				8:42:13 PM		
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 24, 2020 8:42:13 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 24, 2020 8:42:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 24, 2020 8:42:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 24, 2020 8:42:13 PM	No	
20 - Miles			DARTHURS	Nov 24, 2020 8:42:13 PM	No	
30 - Kilometers			DARTHURS	Nov 24, 2020 8:42:13 PM	No	
40 - Hours			DARTHURS	Nov 24, 2020 8:42:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54083750
Invoice No. 55345 - 54083750

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
W/C Lift No Power To Lift		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	229,502 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check W/C Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Nov-20	Arthurs,Durvin	2.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54083750 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 53907361
Invoice No. 55345 - 53907361

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,600 - DH

Chronology		
Reported	Nov 11, 2020 12:00:00 AM	Nov 11, 2020 12:00:00 AM
Started	Nov 13, 2020 6:04:00 AM	
Completed	Nov 14, 2020 9:42:00 AM	Nov 14, 2020 9:42:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: Performed service lube all pivoting point cross tires replace transmission pin and gasket motor mount completed

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 13-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
20 - Miles			HPIERRE	Nov 13, 2020 8:03:14 AM	No	
30 - Kilometers	12		HPIERRE	Nov 13, 2020 8:03:14 AM	No	
40 - Hours	4		HPIERRE	Nov 13, 2020 8:03:14 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 53907361
Invoice No. 55345 - 53907361

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,600 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: HPIERRE Performed on: 13-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,800 - INSPECT_High Idle Control	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
31,000 - SSF (Street Side Front)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
31,020 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,000 - Engine Inspection	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,010 - INSPECT_Hood, Springs and Props	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	190 Degree Fahrenheit		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,100 - INSPECT_Intake System	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12 Volt*		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,010 - CSF (Curb Side Front)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,030 - *RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,070 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12 Volt*		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
41,200 - INSPECT_ Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,400 - LUBE_All Chassis Components	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,700 - INSPECT_Tire Condition	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,900 - INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.6 Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,000 - INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.6 Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,100 - INSPECT_Vibration Damper	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,400 - !FRA!INSPECT_ Starter Mounting	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,700 - INSPECT_ Engine, Transmission Mounts	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
52,900 - INSPECT_ Shift Cable Adjustment - All Transmissions	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,000 - !FRA!INSPECT_ Transmission Breather and Clean	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,300 - *RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,600 - INSPECT_Tire Condition	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,800 - INSPECT_ Mismatched Tire Tread, Casing Design	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.7 Inch		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	2331 Cycles		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,400 - INSPECT_All Pivot Points	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,500 - INSPECT_Cams and Slots	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,600 - INSPECT_Rollers	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
62,700 - INSPECT_All Linkages	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		HPIERRE	Nov 13, 2020 8:16:50 AM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 53907361
Invoice No. 55345 - 53907361

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 228,600 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
13-Nov-20	P7398	FILTER, OIL	1	1.41	1.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-20	Pierre,Hubert J	2.12	0	0
13-Nov-20	Pierre,Hubert J	5.08	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 13-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 13, 2020 8:17:47 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		HPIERRE	Nov 13, 2020 8:17:47 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 13, 2020 8:17:47 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	3.37
Labor:	0.00
Labor Hours:	7.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.37**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 53907361
Invoice No. 55345 - 53907361

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,600 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-20	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	152.75	152.75
13-Nov-20	8C3Z-7A194-B	PAN, OIL, TRANSMISSION	1	30.51	30.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-20	Pierre,Hubert J	0.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	183.26
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**183.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 53907361
Invoice No. 55345 - 53907361

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	228,600 - DH

Activity Header
Activity: 40 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53907361 Total	
Parts:	186.63
Labor:	0.00
Labor Hours:	7.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54012392
Invoice No. 55345 - 54012392

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Brakes		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,471 - DH

Chronology		
Reported	Oct 30, 2020 11:45:00 PM	Oct 30, 2020 11:45:00 PM
Started	Nov 1, 2020 12:00:00 AM	
Completed	Nov 12, 2020 4:42:32 PM	Nov 12, 2020 4:42:32 PM
Down Time		

Work Order Notes

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54012392
Invoice No. 55345 - 54012392

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Brakes		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	99 - Cancelled (99)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,471 - DH

Activity Header
Activity: 20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54012392
Invoice No. 55345 - 54012392

Client Department:
Department: 55345M
Work Order Description
Check Brakes
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,471 - DH

Activity Header
Activity: 30 013/000/000 BRAKES
Activity Note: Replace brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-20	Arthurs,Durvin	3.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54012392 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54013348
Invoice No. 55345 - 54013348

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
4819		Ford E450 Champion Challenger	
Requested By:	SHARRINGTON	**Status:**	99 - Cancelled (99)
Created By:	SHARRINGTON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,471 - DH

Chronology		
Reported	Nov 1, 2020 12:46:04 PM	Nov 1, 2020 12:46:04 PM
Started		
Completed	Nov 12, 2020 4:41:53 PM	Nov 12, 2020 4:41:53 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:

Cause:

Correction:

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54013348
Invoice No. 55345 - 54013348

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
4819		Ford E450 Champion Challenger	
Requested By:	SHARRINGTON	**Status:**	99 - Cancelled (99)
Created By:	SHARRINGTON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,471 - DH

Activity Header
Activity: 20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54013348 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 54013378
Invoice No. 55345 - 54013378

Client Department:
Department: 55345M
Work Order Description
Front Brakes / R/R Rubber Spring /Ball joint
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,471 - DH

Chronology		
Reported	Nov 1, 2020 1:50:07 PM	Nov 1, 2020 1:50:07 PM
Started	Nov 1, 2020 3:20:00 PM	
Completed	Nov 2, 2020 4:22:00 PM	Nov 2, 2020 4:22:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: R/R Rubber Spring / Front Brakes / Ball joints

Cause: Rubber Spring Torn / Front Brakes uneven Wear / ball joints Loose.

Correction: Remove and Replaced Rubber spring / Remove & Replace Both side upper & Lower ball joint. Replace Right Side Caliper bracket & Slide pins.need Left side caliper bracket & slide pin none in stock. Rotate both front tire to R/R & Both R/R To Front.
Parts #8C2Z-3050-A Qty (2)
Parts# 8C2Z-2C150 -C Qty (2)
Parts #8C3Z-3049-B Qty (1)
Parts# 141096 Qty (1)
Parts# 8C 2Z-2V001-D Qty (1)
Parts#DSR108-075 Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-NOV-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 1, 2020 6:05:21 PM	No	
20 - Miles			DARTHURS	Nov 1, 2020 6:05:21 PM	No	
30 - Kilometers			DARTHURS	Nov 1, 2020 6:05:21 PM	No	
40 - Hours			DARTHURS	Nov 1, 2020 6:05:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 54013378
Invoice No. 55345 - 54013378

Client Department:
Department: 55345M
Work Order Description
Front Brakes / R/R Rubber Spring /Ball joint
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,471 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Front brakes /
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	44.18	44.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-20	Arthurs,Durvin	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.18
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 54013378
Invoice No. 55345 - 54013378

Client Department:
Department: 55345M
Work Order Description
Front Brakes / R/R Rubber Spring /Ball joint
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,471 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace ball Joint
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-20	8C2Z-3050-A	JOINT, BALL, LOWER	2	53.96	107.92
01-Nov-20	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	2	9.49	18.98
01-Nov-20	8C3Z-3049-B	JOINT, BALL, UPPER	2	37.01	74.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-20	Arthurs,Durvin	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	200.92
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 54013378
Invoice No. 55345 - 54013378

Client Department:
Department: 55345M
Work Order Description
Front Brakes / R/R Rubber Spring /Ball joint
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,471 - DH

Activity Header
Activity: 35 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace R/R Moryde
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Nov-20	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RYDE	1	152.75	152.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-20	Arthurs,Durvin	2.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	152.75
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**152.75**

Work Order Footer

Work Order 54013378 Total	
Parts:	397.85
Labor:	0.00
Labor Hours:	5.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**397.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 54001614
Invoice No. 55345 - 54001614

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check Engine Light On)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,052 - DH

Chronology		
Reported	Oct 27, 2020 10:21:00 PM	Oct 27, 2020 10:21:00 PM
Started	Oct 29, 2020 9:46:00 AM	
Completed	Oct 30, 2020 7:51:00 AM	Oct 30, 2020 7:51:00 AM
Down Time		

Work Order Notes

Line 10 C: Vehicle stalled on the road

C: Check all systems found codes for lost of communication with SRM and misfires

C: follow diagnostic test to verify SRM is in good condition found internal failure of module, replaced SRM tight all fuses terminals and relays. Retest system and road test vehicle ok at this time

Part:
1 new SRM p13jc03p205ac

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 30-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
20 - Miles			JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
30 - Kilometers			JAPEREZ	Oct 30, 2020 7:50:58 AM	No	
40 - Hours			JAPEREZ	Oct 30, 2020 7:50:58 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 54001614
Invoice No. 55345 - 54001614

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check Engine Light On)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,052 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 54001614
Invoice No. 55345 - 54001614

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,052 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine On
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Oct-20	P13JC03P205AC	MODULE, RELAY, SMART, PROPANE, ROUSH	1	472.31	472.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-20	Perez,Javier	5.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	472.31
Labor:	0.00
Labor Hours:	5.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**472.31**

Work Order Footer

Work Order 54001614 Total	
Parts:	472.31
Labor:	0.00
Labor Hours:	5.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**472.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 54001671
Invoice No. 55345 - 54001671

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Engine Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	227,052 - DH

Chronology		
Reported	Oct 27, 2020 10:55:05 PM	Oct 27, 2020 10:55:05 PM
Started	Oct 27, 2020 10:57:00 PM	
Completed	Oct 27, 2020 11:52:00 PM	Oct 27, 2020 11:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Check Rear A/C & Check Engine Light On

Cause: A/C low Voltage / Lean Code PO 171 & PO174 / Post cat P2096

Correction: Clear Code Road Test .to Verify Complaint Code did no return. Check A/C pressure O/K. Reset thermostat Switch all is OK at this time.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 27, 2020 11:52:13 PM	No	
20 - Miles			DARTHURS	Oct 27, 2020 11:52:13 PM	No	
30 - Kilometers			DARTHURS	Oct 27, 2020 11:52:13 PM	No	
40 - Hours			DARTHURS	Oct 27, 2020 11:52:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 54001671
Invoice No. 55345 - 54001671

Client Department:
Department: 55345M
Work Order Description
Check Engine Light / Rear A/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 227,052 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Rear A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-20	Arthurs,Durvin	0.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 54001671 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53984249
Invoice No. 55345 - 53984249

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,585 - DH

Chronology		
Reported	Oct 21, 2020 10:01:00 PM	Oct 21, 2020 10:01:00 PM
Started	Oct 21, 2020 10:34:00 PM	
Completed	Oct 22, 2020 12:16:00 AM	Oct 22, 2020 12:16:00 AM
Down Time		

Work Order Notes

Line 10 Check engine light illuminated. Found that the vehicle had a lean code stored, cleared and road tested with no issues. Will monitor.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
20 - Miles			EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	
40 - Hours			EARJOHNSON	Oct 21, 2020 11:24:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53984249
Invoice No. 55345 - 53984249

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,585 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-20	Earl Johnson	0.82	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53984249
Invoice No. 55345 - 53984249

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check Engine Light On)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,585 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light On
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53984249 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53966750
Invoice No. 55345 - 53966750

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check Engine Light On) P0713 & P0710		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	226,191 - DH

Chronology		
Reported	Oct 15, 2020 11:48:00 PM	Oct 15, 2020 11:48:00 PM
Started	Oct 16, 2020 11:25:00 AM	
Completed	Oct 16, 2020 1:34:00 PM	Oct 16, 2020 1:34:00 PM
Down Time		

Work Order Notes

Line 10

P0713 Transmission Check engine light is on.

Found P0713 code Transmission Temperature sensor

Drain Transmission. Removed trans oil pan, oil filter, Valve body, valve body harness, temperature sensor, and valve body gasket.

Installed a new valve body gasket, harness, temperature sensor, and transmission oil filter. Washed oil pan, in the parts washer. Dried oil pan and installed back onto transmission. Tightened drain plug.

Filled transmission with 9.8 Qts of transmission fluid. Ran vehicle for about 15 mins. Change transmission through all the gears. Checked transmission oil level, it¿s on the full line. Test drove and then I checked transmissipon level again. At this time, transmission is shifting properly.

Parts. Internal harness (no found part)

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PRA Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 16-OCT-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
20 - Miles			RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
30 - Kilometers			RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	
40 - Hours			RAURODRIGUEZ	Oct 16, 2020 1:22:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53966750
Invoice No. 55345 - 53966750

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On) P0713 & P0710
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,191 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: VERIFY COMPLAINT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-20	Rodriguez,Raul	1.92	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53966750
Invoice No. 55345 - 53966750

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check Engine Light On) P0713 & P0710
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 226,191 - DH

Activity Header
Activity: 30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check Engine Light On
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Oct-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	10.74	10.74

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Oct-20	Rodriguez,Raul	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	10.74
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.74**

Work Order Footer

Work Order 53966750 Total	
Parts:	10.74
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**10.74**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53772814
Invoice No. 55345 - 53772814

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,103 - DH

Chronology		
Reported	Sep 25, 2020 12:00:00 AM	Sep 25, 2020 12:00:00 AM
Started	Sep 25, 2020 8:05:00 PM	
Completed	Sep 26, 2020 12:26:00 AM	Sep 26, 2020 12:26:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC Service
Oil filter B329 qty1
Engine oil 10w30 qty 7 Qts
Air filter PA4075 qty1
Gear Oil 80w90 qty 5 Qts

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 25-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 25, 2020 8:05:44 PM	No	
20 - Miles			RGASPARD	Sep 25, 2020 8:05:44 PM	No	
30 - Kilometers			RGASPARD	Sep 25, 2020 8:05:44 PM	No	
40 - Hours			RGASPARD	Sep 25, 2020 8:05:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53772814
Invoice No. 55345 - 53772814

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	224,103 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Sep-20	Gaspard,Ronald	1.72	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53772814
Invoice No. 55345 - 53772814

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMC
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 224,103 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Sep-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
25-Sep-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Sep-20	Gaspard,Ronald	0.35	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 25-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 25, 2020 9:50:54 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	RGASPARD	Sep 25, 2020 9:50:54 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	RGASPARD	Sep 25, 2020 9:50:54 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	RGASPARD	Sep 25, 2020 9:50:54 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Sep 25, 2020 9:50:54 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Sep 25, 2020 9:50:54 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order Footer

Work Order 53772814 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	2.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53853317
Invoice No. 55345 - 53853317

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 PER DVIR (Check brakes)		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,223 - DH

Chronology		
Reported	Sep 8, 2020 5:26:00 PM	Sep 8, 2020 5:26:00 PM
Started	Sep 20, 2020 12:00:00 AM	
Completed	Sep 20, 2020 8:29:00 AM	Sep 20, 2020 8:29:00 AM
Down Time		

Work Order Notes

Line 10 Brakes okay
Front pads about 6-7 mm
Rear beads 8-9 mm
Noisy idler pulley
Weak/noisy belt tensioner
Cracked belt
Replaced idler pulley, belt tensioner, and belt

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 20-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
20 - Miles			VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
30 - Kilometers			VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	
40 - Hours			VAMRITTEEMAL	Sep 20, 2020 8:29:27 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53853317
Invoice No. 55345 - 53853317

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check brakes)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 222,223 - DH

Activity Header
Activity:20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-20	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53853317
Invoice No. 55345 - 53853317

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Check brakes)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 222,223 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear A/C Blowing Hot Air
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-20	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21	21
20-Sep-20	89263	TENSIONER, BELT, SERPENTINE	1	29.42	29.42
20-Sep-20	89006	PULLEY, IDLER, GM	1	17.35	17.35

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-20	AMRIT TEEMAL,VISHNU	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	67.77
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.77**

Work Order Footer

Work Order 53853317 Total	
Parts:	67.77
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**67.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53849166
Invoice No. 55345 - 53849166

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Washer Fluid		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,071 - DH

Chronology		
Reported	Sep 7, 2020 4:31:00 PM	Sep 7, 2020 4:31:00 PM
Started	Sep 7, 2020 5:26:00 PM	
Completed	Sep 7, 2020 5:59:00 PM	Sep 7, 2020 5:59:00 PM
Down Time		

Work Order Notes

Line 10 Driver complained of washer fluid being empty. Refilled washer fluid and checked the operation of the wipers. All components work properly.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 07-SEP-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
20 - Miles			EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	
40 - Hours			EARJOHNSON	Sep 7, 2020 5:52:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53849166
Invoice No. 55345 - 53849166

Client Department:
Department: 55345M
Work Order Description
Check Washer Fluid
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 222,071 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: VERIFY COMPLAINT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Sep-20	Earl Johnson	0.42	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53849166
Invoice No. 55345 - 53849166

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Washer Fluid		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	222,071 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Washer Fluid
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Sep-20	Earl Johnson	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53849166 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53771507
Invoice No. 55345 - 53771507

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,771 - DH

Chronology		
Reported	Aug 11, 2020 8:55:00 AM	Aug 11, 2020 8:55:00 AM
Started	Aug 12, 2020 6:03:00 AM	
Completed	Aug 12, 2020 7:57:00 AM	Aug 12, 2020 7:57:00 AM
Down Time		

Work Order Notes

Line 10 P.T.C INSPECTION PERFORMED.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Reason for Repair: 11 Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53771507
Invoice No. 55345 - 53771507

Client Department:
Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,771 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-20	Pierre,Hubert J	1.88	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
20 - Miles			HPIERRE	Aug 12, 2020 7:57:43 AM	No	
30 - Kilometers	10		HPIERRE	Aug 12, 2020 7:57:43 AM	No	
40 - Hours	2		HPIERRE	Aug 12, 2020 7:57:43 AM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.88
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53771507 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53605872
Invoice No. 55345 - 53605872

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,771 - DH

Chronology		
Reported	Aug 10, 2020 12:00:00 AM	Aug 10, 2020 12:00:00 AM
Started	Aug 11, 2020 6:05:00 AM	
Completed	Aug 11, 2020 1:46:00 PM	Aug 11, 2020 1:46:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 11-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Aug 11, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				10:12:34 AM		
20 - Miles			HPIERRE	Aug 11, 2020 10:12:34 AM	No	
30 - Kilometers	5		HPIERRE	Aug 11, 2020 10:12:34 AM	No	
40 - Hours			HPIERRE	Aug 11, 2020 10:12:34 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53605872
Invoice No. 55345 - 53605872

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,771 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-20	Pierre,Hubert J	7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53605872
Invoice No. 55345 - 53605872

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,771 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 11-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		HPIERRE	Aug 11, 2020 10:27:39 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Aug 11, 2020 10:27:39 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53605872
Invoice No. 55345 - 53605872

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	219,771 - DH

Activity Header
Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-20	Pierre,Hubert J	0.67	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION
Task: First Transit Wheelchair Lift Inspection Performed by: HPIERRE Performed on: 11-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	1212 Cycles		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
3,003 - A.3 Unusual Noises	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
3,004 - A.4 Jerky Operation	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
3,006 - A.6 Drift Down	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SrvcManual for Fluid to Use.	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
21,000 - A.21 Check WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
91,000 - Lubricate (Don¿t OVER Lubricate)	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
300,000 - B.3 Bridgeplate Hinge	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
400,000 - B.4 All Pivot Points	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
500,000 - B.5 Cams and Slots	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
600,000 - B.6 Rollers	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	
700,000 - B.7 All Linkages	Done		HPIERRE	Aug 11, 2020 10:29:18 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53605872 Total	
Parts:	0.00

	Labor:	0.00
	Labor Hours:	7.67
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53724648
Invoice No. 55345 - 53724648

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift + P.T.C CAMERA
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,975 - DH

Chronology		
Reported	Jul 23, 2020 11:02:00 AM	Jul 23, 2020 11:02:00 AM
Started	Jul 23, 2020 1:27:00 PM	
Completed	Jul 23, 2020 4:18:00 PM	Jul 23, 2020 4:18:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: W/C lift¿s flap and camera not working

Cause: couldn¿t duplicate the issues

Correction: lubricate the lift and inspect the camera harness

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 23-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jul 23, 2020 4:17:22 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jul 23, 2020 4:17:22 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jul 23, 2020 4:17:22 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jul 23, 2020 4:17:22 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jul 23, 2020 4:17:22 PM	No	
10 - Have you successfully completed the Personal	Done		TDELVA	Jul 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				4:17:22 PM		
20 - Miles			TDELVA	Jul 23, 2020 4:17:22 PM	No	
30 - Kilometers			TDELVA	Jul 23, 2020 4:17:22 PM	No	
40 - Hours			TDELVA	Jul 23, 2020 4:17:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53724648
Invoice No. 55345 - 53724648

Client Department:
Department: 55345M
Work Order Description
Wheelchair Lift + P.T.C CAMERA
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,975 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jul-20	32408	BUMPER, RUBBER, W/C, BRAUN SAME AS 32408-10KS	2	1.31	2.62

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jul-20	Delva,Terry	1.47	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	2.62
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.62**

Work Order Footer

Work Order 53724648 Total	
Parts:	2.62
Labor:	0.00
Labor Hours:	1.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53716033
Invoice No. 55345 - 53716033

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Make Brake Noise Over 60 MPH)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,469 - DH

Chronology		
Reported	Jul 20, 2020 9:34:00 PM	Jul 20, 2020 9:34:00 PM
Started	Jul 20, 2020 9:35:00 PM	
Completed	Jul 21, 2020 12:30:00 AM	Jul 21, 2020 12:30:00 AM
Down Time		

Work Order Notes

Line 10 Driver complained of brakes making noise at 60 MPH. Road tested vehicle and could not confirm any noise. Racked vehicle and found that the rear brake pads were near out of spec, remove and replaced.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
20 - Miles			EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	
40 - Hours			EARJOHNSON	Jul 21, 2020 12:27:28 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53716033
Invoice No. 55345 - 53716033

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Make Brake Noise Over 60 MPH)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,469 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-20	Earl Johnson	1.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53716033
Invoice No. 55345 - 53716033

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Make Brake Noise Over 60 MPH)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 217,469 - DH

Activity Header
Activity: 30 013/000/000 BRAKES
Activity Note: Replace Rear Brakes
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-20	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	44.81	44.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-20	Earl Johnson	0.32	0	0
21-Jul-20	Earl Johnson	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	44.81
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.81**

Work Order Footer

Work Order 53716033 Total	
Parts:	44.81
Labor:	0.00
Labor Hours:	2.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.81**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53676532
Invoice No. 55345 - 53676532

Client Department:
Department: 55345M
Work Order Description
55345 TRANSMISSION DTC P0751
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 216,431 - DH

Chronology		
Reported	Jul 7, 2020 10:24:00 AM	Jul 7, 2020 10:24:00 AM
Started	Jul 8, 2020 7:23:00 AM	
Completed	Jul 9, 2020 10:49:00 AM	Jul 9, 2020 10:49:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: vehicle won¿t move

Cause: Transmission issue ,p051

Correction: replaced the transmission Line 20 C: Vehicle is overheating

C: Check coolant system found radiator top adapter broke off causing to leak coolant and overheat

C: Replaced radiator and thermostat, retest system and road test vehicle ok at this time

Part:
1 new radiator G 1000
1 thermostat 7c3z-8575-b
1 gasket f1vy-8255-a

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
20 - Miles			NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	
40 - Hours			NPIERRE-LOUIS	Jul 8, 2020 12:40:03 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53676532
Invoice No. 55345 - 53676532

Client Department:
Department: 55345M
Work Order Description
55345 TRANSMISSION DTC P0751
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 216,431 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
14-Jul-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	10.48	10.48
14-Jul-20	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	7.53	7.53
13-Jul-20	19180251	TRANSMISSION, REMANUFACTURED	1	388.32	388.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-20	NELSON PIERRE-LOUIS	5.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: NPIERRE-LOUIS Performed on: 08-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		NPIERRE-LOUIS	Jul 8, 2020 12:39:35 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	423.60
Labor:	0.00
Labor Hours:	5.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**423.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53676532
Invoice No. 55345 - 53676532

Client Department:
Department: 55345M
Work Order Description
55345 TRANSMISSION DTC P0751
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 216,431 - DH

Activity Header
Activity: 30 042/004/000 PUMP, WATER
Activity Note: RADIATOR LEAKS .
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jul-20	7C3Z-8575-B	THERMOSTAT	1	9.94	9.94
09-Jul-20	G1000382282CSF	RADIATOR, E450	1	204.35	204.35
09-Jul-20	F1VY-8255-A	SEAL, THERMOSTAT	1	4.13	4.13

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-20	Perez,Javier	2.32	0	0
09-Jul-20	Perez,Javier	2.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	218.42
Labor:	0.00
Labor Hours:	5.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**218.42**

Work Order Footer

Work Order 53676532 Total	
Parts:	642.02
Labor:	0.00
Labor Hours:	10.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**642.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53665470
Invoice No. 55345 - 53665470

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	216,331 - DH

Chronology		
Reported	Jul 1, 2020 1:19:00 PM	Jul 1, 2020 1:19:00 PM
Started	Jul 1, 2020 1:22:00 PM	
Completed	Jul 6, 2020 1:01:00 PM	Jul 6, 2020 1:01:00 PM
Down Time		

Work Order Notes

Line 10 C:Rear a/c cuts out randomly

C: Check rear a/c system found compressor cuts out due to low voltage message from a/c module. Inspect all circuits related to that system, check values and compare it with another vehicle found it ok. Inspect power source to module with diagram found power is shared with 2 different wires that supplied power to different systems

C:route power source to independent power voltage, retest system at this a/c system works ok

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 06-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
20 - Miles			JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
30 - Kilometers			JAPEREZ	Jul 6, 2020 1:01:25 PM	No	
40 - Hours			JAPEREZ	Jul 6, 2020 1:01:25 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53665470
Invoice No. 55345 - 53665470

Client Department:
Department: 55345M
Work Order Description
REAR AC SYSTEM
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 216,331 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jul-20	Perez,Javier	0.12	0	0
03-Jul-20	Perez,Javier	7.38	0	0
02-Jul-20	Perez,Javier	6.45	0	0
01-Jul-20	Perez,Javier	2.3	0	0
06-Jul-20	Perez,Javier	4.58	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	20.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53665470 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	20.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53628573
Invoice No. 55345 - 53628573

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Scheduled		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,882 - DH

Chronology		
Reported	Jun 17, 2020 9:28:06 AM	Jun 17, 2020 9:28:06 AM
Started	Jun 17, 2020 9:30:00 AM	
Completed	Jun 17, 2020 11:23:00 AM	Jun 17, 2020 11:23:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle won¿t start

Cause: Tech Found Starter not good

Correction: replaced the starter vehicle start,drove test,everything ok at this time

Part : dl3z-11003-a

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 17-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
20 - Miles			NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 17, 2020 11:23:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53628573
Invoice No. 55345 - 53628573

Client Department:
Department: 55345M
Work Order Description
Scheduled
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 215,882 - DH

Activity Header
Activity: 15 032/000/000 CRANKING
Activity Note: No start
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jun-20	DL3Z-11002-A	STARTER, E350, '14	1	133.95	133.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	NELSON PIERRE-LOUIS	1.77	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order Footer

Work Order 53628573 Total	
Parts:	133.95
Labor:	0.00
Labor Hours:	1.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**133.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53610522
Invoice No. 55345 - 53610522

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Lift Shorting Out)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 215,223 - DH

Chronology		
Reported	Jun 9, 2020 11:29:00 PM	Jun 9, 2020 11:29:00 PM
Started	Jun 10, 2020 9:37:00 AM	
Completed	Jun 11, 2020 6:46:00 AM	Jun 11, 2020 6:46:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Lift is not working properly

Cause. Found bad outer barrier shocks

Correction. Removed and replaced outer shocks

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 10-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Jun 10, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				9:37:13 AM		
20 - Miles			RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	
40 - Hours			RAURODRIGUEZ	Jun 10, 2020 9:37:13 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53610522
Invoice No. 55345 - 53610522

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Lift Shorting Out)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 215,223 - DH

Activity Header
Activity:20
Activity Note: VERIFY COMPLAINT
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-20	32831	SPRING, SHOCK, GAS, W/C	2	25.21	50.42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jun-20	Rodriguez,Raul	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.42
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.42**

Work Order Footer

Work Order 53610522 Total	
Parts:	50.42
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5

Work Order No. 53558506
Invoice No. 55345 - 53558506

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,223 - DH

Chronology		
Reported	Jun 5, 2020 12:38:12 PM	Jun 5, 2020 12:38:12 PM
Started	Jun 8, 2020 6:44:00 AM	
Completed	Jun 8, 2020 10:17:00 AM	Jun 8, 2020 10:17:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA service

CAUSE: preventive maintenance

CORRECTION: perform pmA service and lube all Pivoting Points,Replace all 4 Rear Tires,Lube the Lift.

Activity Header
Activity:5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Jun 8, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	10:12:49 AM		
20 - Miles			NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	
40 - Hours			NPIERRE-LOUIS	Jun 8, 2020 10:12:49 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5

Work Order No. 53558506
Invoice No. 55345 - 53558506

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,223 - DH

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-20	NELSON PIERRE-LOUIS	2.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5

Work Order No. 53558506
Invoice No. 55345 - 53558506

Client Department:
Department: 55345M
Work Order Description
55345-LIGHT DUTY PMA
Requested By: NSTOLFO
Created By: NSTOLFO
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 215,223 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-20	65266	PLUG, DRAIN, OIL, ENGINE	1	4.25	4.25
08-Jun-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 08-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Jun 8, 2020 10:13:22 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	10.46
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**10.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5

Work Order No. 53558506
Invoice No. 55345 - 53558506

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,223 - DH

Activity Header
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: 55345-W/C LIFT INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5

Work Order No. 53558506
Invoice No. 55345 - 53558506

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	**Status:**	40 - Closed (40)
Created By:	NSTOLFO	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	215,223 - DH

Activity Header
Activity:40 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Low tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	117.62	470.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-20	NELSON PIERRE-LOUIS	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	470.48
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**470.48**

Work Order Footer

Work Order 53558506 Total	
Parts:	480.94
Labor:	0.00
Labor Hours:	3.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**480.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53594673
Invoice No. 55345 - 53594673

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wiper Blades)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 214,774 - DH

Chronology		
Reported	Jun 2, 2020 10:21:00 PM	Jun 2, 2020 10:21:00 PM
Started		
Completed	Jun 2, 2020 10:25:00 PM	Jun 2, 2020 10:25:00 PM
Down Time		

Work Order Notes

Line 10

Replace Wiper blades part# 40520 Qty 2

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 02-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 2, 2020 10:25:00 PM	No	
20 - Miles			AOWENS	Jun 2, 2020 10:25:00 PM	No	
30 - Kilometers			AOWENS	Jun 2, 2020 10:25:00 PM	No	
40 - Hours			AOWENS	Jun 2, 2020 10:25:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53594673
Invoice No. 55345 - 53594673

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Replace Wiper Blades)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 214,774 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note: VERIFY COMPLAINT (Replace Wipers Blades)
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jun-20	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.16	8.32

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.32**

Work Order Footer

Work Order 53594673 Total	
Parts:	8.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53591074
Invoice No. 55345 - 53591074

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wiper Busted Per Hubert)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 214,636 - DH

Chronology		
Reported	Jun 1, 2020 10:13:00 PM	Jun 1, 2020 10:13:00 PM
Started	Jun 2, 2020 7:31:00 AM	
Completed	Jun 2, 2020 8:45:00 AM	Jun 2, 2020 8:45:00 AM
Down Time		

Work Order Notes

Line 10 Windshield hose leaking

Bad hose

Remove windshield battle replace hose completed

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PRA
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PRA
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 02-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jun 2, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				8:40:38 AM		
20 - Miles			HPIERRE	Jun 2, 2020 8:40:38 AM	No	
30 - Kilometers	2		HPIERRE	Jun 2, 2020 8:40:38 AM	No	
40 - Hours	2		HPIERRE	Jun 2, 2020 8:40:38 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53591074
Invoice No. 55345 - 53591074

Client Department:
Department: 55345M
Work Order Description
55345 PER DVIR (Wiper Busted Per Hubert)
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 214,636 - DH

Activity Header
Activity: 20 050 GROUP, ACCESSORIES
Activity Note: VERIFY COMPLAINT
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-20	Pierre,Hubert J	1.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53591074 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53562316
Invoice No. 55345 - 53562316

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,697 - DH

Chronology		
Reported	May 19, 2020 9:40:53 PM	May 19, 2020 9:40:53 PM
Started	May 19, 2020 9:46:00 PM	
Completed	May 19, 2020 10:42:00 PM	May 19, 2020 10:42:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear AC malfunction.

Cause: TBD.

Correction: Could not duplicate issue. Front and rear ac pressure within spec. Will monitor.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 19-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 19, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:30:23 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 19, 2020 10:30:23 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 19, 2020 10:30:23 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 19, 2020 10:30:23 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 19, 2020 10:30:23 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 19, 2020 10:30:23 PM	No	
20 - Miles			EARJOHNSON	May 19, 2020 10:30:23 PM	No	
30 - Kilometers			EARJOHNSON	May 19, 2020 10:30:23 PM	No	
40 - Hours			EARJOHNSON	May 19, 2020 10:30:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53562316
Invoice No. 55345 - 53562316

Client Department:
Department: 55345M
Work Order Description
Rear AC malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 213,697 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear ac malfuntion.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-May-20	Earl Johnson	0.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53562316 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53543751
Invoice No. 55345 - 53543751

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,238 - DH

Chronology		
Reported	May 12, 2020 1:21:52 PM	May 12, 2020 1:21:52 PM
Started	May 12, 2020 1:25:00 PM	
Completed	May 12, 2020 5:08:00 PM	May 12, 2020 5:08:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Vehicle came in for lift issue. Check lift on found NO. Problem can¿t duplicate the issue
Check Rear A/C

Cause: Control worn

Correction: Replace new part Control # 04257712A also replace one connector. Component now working as design

Please charge out the part for me the System say not available. # 04257712A. After check vehicle complete on return vehicle back to work

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 12-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 12, 2020 5:08:38 PM	No	
20 - Miles			JUHURST	May 12, 2020 5:08:38 PM	No	
30 - Kilometers			JUHURST	May 12, 2020 5:08:38 PM	No	
40 - Hours			JUHURST	May 12, 2020 5:08:38 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53543751
Invoice No. 55345 - 53543751

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	213,238 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Vehicle infor Lift / Rear A/C
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-May-20	04257712A	DISPLAY, DASH, HVAC	1	296.69	296.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-May-20	Junior Hurst	3.68	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	296.69
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.69**

Work Order Footer

Work Order 53543751 Total	
Parts:	296.69
Labor:	0.00
Labor Hours:	3.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53495245
Invoice No. 55345 - 53495245

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Air condition		Ford E450 Champion Challenger	
Requested By:	JUHURST	**Status:**	40 - Closed (40)
Created By:	JUHURST	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,624 - DH

Chronology		
Reported	Apr 21, 2020 12:57:57 PM	Apr 21, 2020 12:57:57 PM
Started	Apr 21, 2020 1:12:00 PM	
Completed	Apr 21, 2020 7:31:00 PM	Apr 21, 2020 7:31:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front air conditioner blowing hot

Cause: EVAPORATOR LEAKING

Correction: REMOVED on replace new one part # 6C2Z 19860 C one office tube p# 3411885

Replace new accumulator part # GC2419C913. Please charge out this part for me can¿t fine

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 21, 2020 7:17:27 PM	No	
20 - Miles			JUHURST	Apr 21, 2020 7:17:27 PM	No	
30 - Kilometers			JUHURST	Apr 21, 2020 7:17:27 PM	No	
40 - Hours			JUHURST	Apr 21, 2020 7:17:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53495245
Invoice No. 55345 - 53495245

Client Department:
Department: 55345M
Work Order Description
Air condition
Requested By: JUHURST
Created By: JUHURST
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 211,624 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front air condition
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Apr-20	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19
21-Apr-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
21-Apr-20	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Apr-20	Junior Hurst	6.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	203.13
Labor:	0.00
Labor Hours:	6.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.13**

Work Order Footer

Work Order 53495245 Total	
Parts:	203.13
Labor:	0.00
Labor Hours:	6.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.13**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53483134
Invoice No. 55345 - 53483134

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear ac malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	211,177 - DH

Chronology		
Reported	Apr 15, 2020 11:21:34 PM	Apr 15, 2020 11:21:34 PM
Started	Apr 15, 2020 11:22:00 PM	
Completed	Apr 15, 2020 11:45:00 PM	Apr 15, 2020 11:45:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear ac blowing warm.

Cause: Faulty rear ac thermostat display.

Correction: Remove and replaced rear ac display.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-20	Earl Johnson	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 15-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Apr 15, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:40:59 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
20 - Miles			EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
30 - Kilometers			EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	
40 - Hours			EARJOHNSON	Apr 15, 2020 11:40:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53483134
Invoice No. 55345 - 53483134

Client Department:
Department: 55345M
Work Order Description
Rear ac malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 211,177 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear ac malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-20	04257712A	DISPLAY, DASH, HVAC	1	296.48	296.48

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-20	Earl Johnson	0.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	296.48
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.48**

Work Order Footer

Work Order 53483134 Total	
Parts:	296.48
Labor:	0.00
Labor Hours:	0.44
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.48**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 53439402
Invoice No. 55345 - 53439402

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP---->Replace Front 2 tires
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,879 - DH

Chronology		
Reported	Apr 2, 2020 9:41:43 PM	Apr 2, 2020 9:41:43 PM
Started	Apr 3, 2020 3:35:00 PM	
Completed	Apr 3, 2020 4:37:00 PM	Apr 3, 2020 4:37:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========
To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.
==========

Complaint: needs 2 front tires

Cause: wear

Correction:2 new tires mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part number 192659 qty2

Activity Header
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD
Activity Note: needs 2 front tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Apr-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Apr-20	Gaspard,Ronald	0.97	0	0

Activity Sublet
No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order Footer

Work Order 53439402 Total	
Parts:	235.24
Labor:	0.00
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**235.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53331486
Invoice No. 55345 - 53331486

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,879 - DH

Chronology		
Reported	Apr 2, 2020 11:44:47 AM	Apr 2, 2020 11:44:47 AM
Started	Apr 2, 2020 8:21:00 PM	
Completed	Apr 3, 2020 12:08:00 AM	Apr 3, 2020 12:08:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: Service

CORRECTION: perform PMB service
Oil filter B329 qty1
Engine oil 10w30 qty 7 Qts

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-20	Gaspard,Ronald	1.88	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53331486
Invoice No. 55345 - 53331486

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 210,879 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Apr-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-20	Gaspard,Ronald	1.15	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 02-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Apr 2, 2020 10:40:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Apr 2, 2020 10:40:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Apr 2, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				10:40:04 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Apr 2, 2020 10:40:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Apr 2, 2020 10:40:04 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53331486
Invoice No. 55345 - 53331486

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,879 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 2, 2020 10:40:36 PM	No	
20 - Miles			RGASPARD	Apr 2, 2020 10:40:36 PM	No	
30 - Kilometers			RGASPARD	Apr 2, 2020 10:40:36 PM	No	
40 - Hours			RGASPARD	Apr 2, 2020 10:40:36 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53331486 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53432443
Invoice No. 55345 - 53432443

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,773 - DH

Chronology		
Reported	Mar 31, 2020 7:34:54 PM	Mar 31, 2020 7:34:54 PM
Started	Mar 31, 2020 7:37:00 PM	
Completed	Mar 31, 2020 9:52:00 PM	Mar 31, 2020 9:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front A/C cycling on/off & Bus stalling.

Cause: Front A/C Low on Freon Evacuate 1.31 Lbs & Mass Air flow sensor harness Plug fell out.

Correction: Evacuate & Recharge A/C Pass leak test .no Leak found. Charge (1.88) lbs Freon add (2) Oz oil secure Mass air flow plug back in Air cleaner housing . All seams Ok at this time.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 31-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 31, 2020 7:38:40 PM	No	
20 - Miles			DARTHURS	Mar 31, 2020 7:38:40 PM	No	
30 - Kilometers			DARTHURS	Mar 31, 2020 7:38:40 PM	No	
40 - Hours			DARTHURS	Mar 31, 2020 7:38:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53432443
Invoice No. 55345 - 53432443

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	210,773 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Front A/C
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Mar-20	Arthurs,Durvin	1.53	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 53432443 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53393733
Invoice No. 55345 - 53393733

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Transmission		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	209,472 - DH

Chronology		
Reported	Mar 17, 2020 4:13:14 PM	Mar 17, 2020 4:13:14 PM
Started	Mar 17, 2020 4:15:00 PM	
Completed	Mar 17, 2020 11:53:00 PM	Mar 17, 2020 11:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Check Engine Light On.

Cause: Bad Transmission Code PO (751).

Correction: Remove & Replace Transmission With a good use One
ATF Fluid (12) Qts

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 17, 2020 11:01:31 PM	No	
20 - Miles			DARTHURS	Mar 17, 2020 11:01:31 PM	No	
30 - Kilometers			DARTHURS	Mar 17, 2020 11:01:31 PM	No	
40 - Hours			DARTHURS	Mar 17, 2020 11:01:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53393733
Invoice No. 55345 - 53393733

Client Department:
Department: 55345M
Work Order Description
Transmission
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 209,472 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove & Replace transmission
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-20	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	-1	9.09	-9.09
24-Apr-20	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
24-Apr-20	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
24-Apr-20	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
23-Mar-20	19180251	TRANSMISSION, REMANUFACTURED	1	475.88	475.88
24-Apr-20	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99
24-Apr-20	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.09	9.09
24-Apr-20	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.39	2.39

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Mar-20	Arthurs,Durvin	5.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	645.01
Labor:	0.00
Labor Hours:	5.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**645.01**

Work Order Footer

Work Order 53393733 Total	
Parts:	645.01
Labor:	0.00
Labor Hours:	5.62
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**645.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53227070
Invoice No. 55345 - 53227070

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,893 - DH

Chronology		
Reported	Feb 27, 2020 12:35:57 PM	Feb 27, 2020 12:35:57 PM
Started	Feb 27, 2020 12:39:00 PM	
Completed	Feb 27, 2020 5:36:00 PM	Feb 27, 2020 5:36:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-20	AMRIT TEEMAL,VISHNU	0.83	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53227070
Invoice No. 55345 - 53227070

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,893 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Feb-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 27-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:49 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53227070
Invoice No. 55345 - 53227070

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	206,893 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 27-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 27, 2020 5:26:24 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53227070 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53287820
Invoice No. 55345 - 53287820

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Passenger mirrors missing		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,984 - DH

Chronology

Reported	Feb 16, 2020 10:44:25 AM	Feb 16, 2020 10:44:25 AM
Started	Feb 16, 2020 10:46:00 AM	
Completed	Feb 18, 2020 5:45:00 PM	Feb 18, 2020 5:45:00 PM
Down Time		

Work Order Notes

Line 10 Replaced passenger side rear view mirror

Activity Header

Activity: 10 099/000/000 SAFETY DEVICES INSTRUMENTS & GAUGES (POWER UNITS, TRAILERS, ETC.)
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-20	AMRIT TEEMAL,VISHNU	0.33	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53287820
Invoice No. 55345 - 53287820

Client Department:
Department: 55345M
Work Order Description
Passenger mirrors missing
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 204,984 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Feb-20	709770	PIVOT, HOUSING, GLASS, UPPER	1	28.6	28.6

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 18-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 18, 2020 5:45:19 PM	No	

Activity Sub Total

Activity 20 Sub Total

	Parts:	28.60
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**28.60**

Work Order Footer

Work Order 53287820 Total	
Parts:	28.60
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53274670
Invoice No. 55345 - 53274670

Client Department:
Department: 55345M
Work Order Description
Front Air Conditioning System
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 204,857 - DH

Chronology		
Reported	Feb 11, 2020 5:17:11 PM	Feb 11, 2020 5:17:11 PM
Started	Feb 11, 2020 5:18:00 PM	
Completed	Feb 13, 2020 7:59:00 PM	Feb 13, 2020 7:59:00 PM
Down Time		

Work Order Notes

Line 10 Front a/c not cooling
Found a/c line from condenser to orifice tube cracked
Replaced line
Replaced orifice tube
Vacuumed down and recharged system
A/c cold at this time Line 20 Rear a/c compressor making noise/clutch not engaging
Replaced compressor
Replaced high pressure a/c line
Replaced orifice tube
Replaced accumulator
Vacuumed down and recharged
A/c cold at this time Line 30 Replaced 1 idler pulley due to noise

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 13-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Feb 13, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:58:58 PM		
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
20 - Miles			VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
30 - Kilometers			VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	
40 - Hours			VAMRITTEEMAL	Feb 13, 2020 7:58:58 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53274670
Invoice No. 55345 - 53274670

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front Air Conditioning System		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	204,857 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Feb-20	3411885	TUBE, ORIFICE, A/C, FORD	2	0.75	1.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-20	AMRIT TEEMAL,VISHNU	1.45	0	0
11-Feb-20	AMRIT TEEMAL,VISHNU	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.50
Labor:	0.00
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53274670
Invoice No. 55345 - 53274670

Client Department:
Department: 55345M
Work Order Description
Front Air Conditioning System
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 204,857 - DH

Activity Header
Activity: 30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Feb-20	CC2Z-19835-B	HOSE, CONDENSER, E450, '11	1	20.68	20.68
13-Feb-20	27059875A	ACCUMULATOR, A/C	1	32.54	32.54
13-Feb-20	89026	PULLEY, IDLER, SMOOTH	1	13.57	13.57
13-Feb-20	8025005	COMPRESSOR, A/C, TM21	1	279.73	279.73

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-20	AMRIT TEEMAL,VISHNU	2.43	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	346.52
Labor:	0.00
Labor Hours:	2.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**346.52**

Work Order Footer

Work Order 53274670 Total	
Parts:	348.02
Labor:	0.00
Labor Hours:	4.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**348.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 53225445
Invoice No. 55345 - 53225445

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,788 - DH

Chronology		
Reported	Jan 28, 2020 1:17:59 PM	Jan 28, 2020 1:17:59 PM
Started	Jan 28, 2020 1:27:00 PM	
Completed	Jan 28, 2020 8:40:00 PM	Jan 28, 2020 8:40:00 PM
Down Time		

Work Order Notes

Line 10 Rear a/c blowing warm
A-pad flashing low voltage
Loose battery terminal
Brake booster leaking
Normal wear
Replaced booster
Front brakes low
Seized caliper pins
Remove and cleaned caliper pins replaced brake pads

Activity Header
Activity: 10 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: rear a/c inoperable
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-20	AMRIT TEEMAL,VISHNU	0.17	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 53225445
Invoice No. 55345 - 53225445

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 202,788 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note: brake booster
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jan-20	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	189.14	189.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-20	AMRIT TEEMAL,VISHNU	1.73	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	189.14
Labor:	0.00
Labor Hours:	1.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**189.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 53225445
Invoice No. 55345 - 53225445

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,788 - DH

Activity Header
Activity: 30 013/000/000 BRAKES
Activity Note: front brakes low
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jan-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-20	AMRIT TEEMAL,VISHNU	0.63	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	48.87
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.87**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 53225445
Invoice No. 55345 - 53225445

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	3 - High
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,788 - DH

Activity Header
Activity: 40 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

40 Desc:
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 28-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 28, 2020 8:34:09 PM	No	

Activity Sub Total

Activity 40 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53225445 Total	
Parts:	238.01
Labor:	0.00
Labor Hours:	2.53
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**238.01**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53133850
Invoice No. 55345 - 53133850

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	**Status:**	40 - Closed (40)
Created By:	NPIERRE-LOUIS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	202,788 - DH

Chronology		
Reported	Jan 28, 2020 9:56:20 AM	Jan 28, 2020 9:56:20 AM
Started	Jan 28, 2020 12:26:00 PM	
Completed	Jan 28, 2020 8:39:00 PM	Jan 28, 2020 8:39:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE
REPLACED AIR FILTER

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-20	AMRIT TEEMAL,VISHNU	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53133850
Invoice No. 55345 - 53133850

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,788 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jan-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
28-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-20	AMRIT TEEMAL,VISHNU	0.23	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 28-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Jan 28, 2020 8:34:39 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53133850
Invoice No. 55345 - 53133850

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 202,788 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 28-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 28, 2020 8:35:03 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53133850 Total	
Parts:	7.24
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 53037306
Invoice No. 55345 - 53037306

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	198,747 - DH

Chronology		
Reported	Dec 27, 2019 10:22:49 AM	Dec 27, 2019 10:22:49 AM
Started	Dec 29, 2019 12:00:00 AM	
Completed	Dec 29, 2019 11:41:00 AM	Dec 29, 2019 11:41:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: PMC service

Cause: preventive maintenance

Correction: perform PmC Service

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Light Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-19	NELSON PIERRE-LOUIS	4	65	260

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**260.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 53037306
Invoice No. 55345 - 53037306

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 198,747 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Dec-19	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.07	8.14
29-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
29-Dec-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 29-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Dec 29, 2019 11:40:31 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	15.38
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 53037306
Invoice No. 55345 - 53037306

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	198,747 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
20 - Miles			NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	
40 - Hours			NPIERRE-LOUIS	Dec 29, 2019 11:30:53 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 53037306 Total	
Parts:	15.38
Labor:	260.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**275.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 53090773
Invoice No. 55345 - 53090773

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Engine Light aon		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,903 - DH

Chronology		
Reported	Dec 12, 2019 4:25:06 PM	Dec 12, 2019 4:25:06 PM
Started	Dec 12, 2019 4:39:00 PM	
Completed	Dec 12, 2019 7:15:00 PM	Dec 12, 2019 7:15:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:CheckEngine Light On Code PO 205

Cause: injector Circuit open

Correction: Check & Found green wire to injector # 5 circuit Open . Cut #5 injector Pig tail and.solder/ heat shrink a with a use Pig tail. Clear code all is ok at this time.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 12, 2019 4:27:40 PM	No	
20 - Miles			DARTHURS	Dec 12, 2019 4:27:40 PM	No	
30 - Kilometers			DARTHURS	Dec 12, 2019 4:27:40 PM	No	
40 - Hours			DARTHURS	Dec 12, 2019 4:27:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 53090773
Invoice No. 55345 - 53090773

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Engine Light aon		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	196,903 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Engine Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-19	Arthurs,Durvin	2.55	65	165.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	165.75
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.75**

Work Order Footer

Work Order 53090773 Total	
Parts:	0.00
Labor:	165.75
Labor Hours:	2.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**165.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52926601
Invoice No. 55345 - 52926601

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,766 - DH

Chronology		
Reported	Nov 22, 2019 4:28:03 PM	Nov 22, 2019 4:28:03 PM
Started		
Completed	Nov 25, 2019 1:34:12 PM	Nov 25, 2019 1:34:12 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA service

CAUSE: preventive maintenance

CORRECTION: perform pmA service

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:40:06 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	12:40:06 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	12:40:06 PM		
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:40:06 PM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Nov 25, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:40:06 PM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,135 - Brake Rotor LF	41.9 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,136 - Brake Rotor RF	45.9 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,137 - Brake Rotor LR	35.9 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,138 - Brake Rotor RR	35.9 Inch		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:06 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52926601
Invoice No. 55345 - 52926601

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 194,766 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Nov 25, 2019 12:40:53 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52926601
Invoice No. 55345 - 52926601

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	194,766 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 25-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
20 - Miles			NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	
40 - Hours			NPIERRE-LOUIS	Nov 25, 2019 12:31:08 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52926601 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52999478
Invoice No. 55345 - 52999478

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	193,253 - DH

Chronology		
Reported	Nov 13, 2019 10:57:30 PM	Nov 13, 2019 10:57:30 PM
Started	Nov 13, 2019 12:00:00 AM	
Completed	Nov 14, 2019 12:08:00 AM	Nov 14, 2019 12:08:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC Lift malfunction.

Cause: Faulty Out board gas shock.

Correction: Remove and replaced 1 gas shock.
Part# 32831 Qty. (1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-19	Earl Johnson	0.1	65	6.5

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 13-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
20 - Miles			EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
30 - Kilometers			EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	
40 - Hours			EARJOHNSON	Nov 13, 2019 11:04:57 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	6.50
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52999478
Invoice No. 55345 - 52999478

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 193,253 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Nov-19	32831	SPRING, SHOCK, GAS, W/C	1	26.72	26.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Nov-19	Earl Johnson	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	26.72
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**91.72**

Work Order Footer

Work Order 52999478 Total	
Parts:	26.72
Labor:	71.50
Labor Hours:	1.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**98.22**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52981353
Invoice No. 55345 - 52981353

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	192,814 - DH

Chronology		
Reported	Nov 8, 2019 12:22:23 PM	Nov 8, 2019 12:22:23 PM
Started	Nov 8, 2019 12:00:00 AM	
Completed	Nov 12, 2019 11:12:15 AM	Nov 12, 2019 11:12:15 AM
Down Time		

Work Order Notes

Line 10

P0713 Transmission Check engine light is on.

Found P0713 code Transmission Temperature sensor

Drain Transmission. Removed trans oil pan, oil filter, Valve body, valve body harness, temperature sensor, and valve body gasket.

Installed a new valve body gasket, internal and external harness, temperature sensor, and transmission oil filter. Washed oil pan, in the parts washer. Dried oil pan and installed back onto transmission. Tightened drain plug.

Filled transmission with 9.8 Qts of transmission fluid. Ran vehicle for about 15 mins. Change transmission through all the gears. Checked transmission oil level, it¿s on the full line. Test drove and then I checked transmission level again. At this time, transmission is shifting properly.

Placed back in service.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
20 - Miles			RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
30 - Kilometers			RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	
40 - Hours			RAURODRIGUEZ	Nov 8, 2019 12:23:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52981353
Invoice No. 55345 - 52981353

Client Department:
Department: 55345M
Work Order Description
55345 Transmission DTC P-0713
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 192,814 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Nov-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
08-Nov-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99
08-Nov-19	DC2Z-7C078-S	HARNESS, TRANSMISSION, EXTERNAL, E450	1	72.4	72.4
08-Nov-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
08-Nov-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Nov-19	Rodriguez,Raul	3.3666666	65	218.833329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	230.05
Labor:	218.83
Labor Hours:	3.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**448.88**

Work Order Footer

Work Order 52981353 Total	
Parts:	230.05
Labor:	218.83
Labor Hours:	3.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**448.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 52926472
Invoice No. 55345 - 52926472

Client Department:
Department: 55345M
Work Order Description
Rear Brakes / R/ F caliper / Radiator / Thermostat
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Chronology		
Reported	Oct 23, 2019 5:10:23 PM	Oct 23, 2019 5:10:23 PM
Started	Oct 23, 2019 12:00:00 AM	
Completed	Oct 23, 2019 5:49:00 PM	Oct 23, 2019 5:49:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Rear Brakes / Radiator / R/F Caliper

Cause: Rear Brakes Low / R/F Caliper Leaking / Radiator Leaking.

Correction: Remove & Replace Radiator /Remove & Replace R/F Caliper / Replace Rear Brakes Replace thermostat /Gasket.
Parts #G1000382282CSF Qty (1)
Parts #8C2Z-2B120-CR Qty (1)
Parts #7C3Z-8575-B. Qty (1)
Parts #F1VY-8255-A Qty (1)
Parts# 8C2Z-2V200-C Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 23, 2019 5:12:35 PM	No	
20 - Miles			DARTHURS	Oct 23, 2019 5:12:35 PM	No	
30 - Kilometers			DARTHURS	Oct 23, 2019 5:12:35 PM	No	
40 - Hours			DARTHURS	Oct 23, 2019 5:12:35 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52814044
Invoice No. 55345 - 52814044

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Chronology		
Reported	Oct 22, 2019 12:11:07 PM	Oct 22, 2019 12:11:07 PM
Started	Oct 23, 2019 12:00:00 AM	
Completed	Oct 23, 2019 5:49:00 PM	Oct 23, 2019 5:49:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter. Lube all Pivoting Points. Check Brakes . Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 23-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,136 - Brake Rotor RF	1.554 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,137 - Brake Rotor LR	1.656 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,138 - Brake Rotor RR	1.656 Inch		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 23, 2019 5:04:40 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 23, 2019 5:04:40 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 52926472
Invoice No. 55345 - 52926472

Client Department:
Department: 55345M
Work Order Description
Rear Brakes / R/ F caliper / Radiator / Thermostat
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	47.81
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52814044
Invoice No. 55345 - 52814044

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 23-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 23, 2019 5:05:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 23, 2019 5:05:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 23, 2019 5:05:41 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	27.08
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**29.04**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 52926472
Invoice No. 55345 - 52926472

Client Department:
Department: 55345M
Work Order Description
Rear Brakes / R/ F caliper / Radiator / Thermostat
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Activity Header
Activity:25 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**65.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52814044
Invoice No. 55345 - 52814044

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	190,429 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 23, 2019 5:06:17 PM	No	
20 - Miles			DARTHURS	Oct 23, 2019 5:06:17 PM	No	
30 - Kilometers			DARTHURS	Oct 23, 2019 5:06:17 PM	No	
40 - Hours			DARTHURS	Oct 23, 2019 5:06:17 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52814044 Total	
Parts:	1.96
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**131.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 52926472
Invoice No. 55345 - 52926472

Client Department:
Department: 55345M
Work Order Description
Rear Brakes / R/ F caliper / Radiator / Thermostat
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,429 - DH

Activity Header
Activity: 35 042/004/000 PUMP, WATER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 18 Leaking
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Oct-19	F1VY-8255-A	SEAL, THERMOSTAT	1	4.3	4.3
23-Oct-19	G1000382282CSF	RADIATOR, E450	1	119.89	119.89
23-Oct-19	7C3Z-8575-B	THERMOSTAT	1	10.02	10.02

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Oct-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 35 Sub Total	
Parts:	134.21
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**199.21**

Work Order Footer

Work Order 52926472 Total	
Parts:	182.02
Labor:	232.92
Labor Hours:	3.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**414.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52898011
Invoice No. 55345 - 52898011

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replaced coolant reservoir		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	189,317 - DH

Chronology		
Reported	Oct 15, 2019 1:09:10 PM	Oct 15, 2019 1:09:10 PM
Started	Oct 15, 2019 12:00:00 AM	
Completed	Oct 15, 2019 2:00:00 PM	Oct 15, 2019 2:00:00 PM
Down Time		

Work Order Notes

Line 10 Coolant reservoir cracked/leaking
Replaced coolant reservoir and coolant reservoir cap
No problem at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 15-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Oct 15, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:14:33 PM		
20 - Miles			VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 15, 2019 1:14:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52898011
Invoice No. 55345 - 52898011

Client Department:
Department: 55345M
Work Order Description
Replaced coolant reservoir
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 189,317 - DH

Activity Header
Activity: 20 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Oct-19	8C2Z-8A080-C	TANK, SURGE, COOLANT	1	121.26	121.26
15-Oct-19	10238	CAP, RADIATOR, FORD	1	6.23	6.23

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Oct-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	127.49
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**257.49**

Work Order Footer

Work Order 52898011 Total	
Parts:	127.49
Labor:	147.33
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**274.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52876312
Invoice No. 55345 - 52876312

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replaced 1 tire		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,367 - DH

Chronology		
Reported	Oct 8, 2019 3:22:37 PM	Oct 8, 2019 3:22:37 PM
Started	Oct 8, 2019 12:00:00 AM	
Completed	Oct 9, 2019 8:53:56 AM	Oct 9, 2019 8:53:56 AM
Down Time		

Work Order Notes

Line 10 Flat tire
Replaced 1 tire
Torqued wheels to 140ftlb test driven and retorqued

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 08-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Oct 8, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				3:26:04 PM		
20 - Miles			VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	
40 - Hours			VAMRITTEEMAL	Oct 8, 2019 3:26:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.33**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52876312
Invoice No. 55345 - 52876312

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replaced 1 tire		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,367 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Oct-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	121.55	121.55

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-19	AMRIT TEEMAL,VISHNU	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	121.55
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**186.55**

Work Order Footer

Work Order 52876312 Total	
Parts:	121.55
Labor:	82.33
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**203.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52875284
Invoice No. 55345 - 52875284

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 BATTERY		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,367 - DH

Chronology		
Reported	Oct 8, 2019 11:56:18 AM	Oct 8, 2019 11:56:18 AM
Started	Oct 8, 2019 12:00:00 AM	
Completed	Oct 8, 2019 1:57:05 PM	Oct 8, 2019 1:57:05 PM
Down Time		

Work Order Notes

Line 10 Complaint. Vehicle die multiple times

Cause. Bad batteries, normal wear

Correction. Remove&Replace Batteries

Part. 2 new batteries

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
20 - Miles			RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
30 - Kilometers			RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	
40 - Hours			RAURODRIGUEZ	Oct 8, 2019 11:57:41 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52875284
Invoice No. 55345 - 52875284

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 BATTERY		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	188,367 - DH

Activity Header
Activity: 20 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Oct-19	34AGM	BATTERY, AGM, GROUP-34	2	115.73	231.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Oct-19	Rodriguez,Raul	0.7833333	65	50.9166645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	231.46
Labor:	50.92
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**282.38**

Work Order Footer

Work Order 52875284 Total	
Parts:	231.46
Labor:	50.92
Labor Hours:	0.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**282.38**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52861284
Invoice No. 55345 - 52861284

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	**Status:**	40 - Closed (40)
Created By:	EARJOHNSON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	187,892 - DH

Chronology		
Reported	Oct 3, 2019 5:13:12 PM	Oct 3, 2019 5:13:12 PM
Started	Oct 3, 2019 12:00:00 AM	
Completed	Oct 3, 2019 10:04:00 PM	Oct 3, 2019 10:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WC Lift malfunction.

Cause: Worn bridge-plate switch.

Correction: Remove and replaced bridge plate switch.

Part# 32519KS Qty. (1).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Earl Johnson	0.1333333	65	8.6666645

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
20 - Miles			EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
30 - Kilometers			EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	
40 - Hours			EARJOHNSON	Oct 3, 2019 5:22:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	8.67
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52861284
Invoice No. 55345 - 52861284

Client Department:
Department: 55345M
Work Order Description
WC lift malfunction.
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 187,892 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfuntion.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-19	32519KS	SWITCH, RAISED, W/C	1	29.26	29.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Earl Johnson	0.0666666	65	4.333329
03-Oct-19	Earl Johnson	0.7666666	65	49.833329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	29.26
Labor:	54.17
Labor Hours:	0.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**83.43**

Work Order Footer

Work Order 52861284 Total	
Parts:	29.26
Labor:	62.83
Labor Hours:	0.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**92.09**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52814080
Invoice No. 55345 - 52814080

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,000 - DH

Chronology		
Reported	Sep 20, 2019 8:24:48 AM	Sep 20, 2019 8:24:48 AM
Started	Sep 20, 2019 12:00:00 AM	
Completed	Sep 20, 2019 8:54:58 AM	Sep 20, 2019 8:54:58 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle won¿t start

Cause: check computer system found no ground signal to rear main solenoid and fuel pump follow diagnostic test found internal failure of propane fuel control module

Correction:replaced module retest and road test vehicle ok at this time

Part:
1 new fuel control module p11 jc- 03p205-ab

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 20-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
20 - Miles			JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
30 - Kilometers			JAPEREZ	Sep 20, 2019 8:38:23 AM	No	
40 - Hours			JAPEREZ	Sep 20, 2019 8:38:23 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52814080
Invoice No. 55345 - 52814080

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,000 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Vehicle wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-19	P11JC-03P205-AB	MODULE, RELAY, SMART	1	472.31	472.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-19	Perez,Javier	2.3333333	65	151.6666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	472.31
Labor:	151.67
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**623.98**

Work Order Footer

Work Order 52814080 Total	
Parts:	472.31
Labor:	151.67
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**623.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52691670
Invoice No. 55345 - 52691670

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,000 - DH

Chronology		
Reported	Sep 17, 2019 2:53:29 PM	Sep 17, 2019 2:53:29 PM
Started		
Completed	Sep 20, 2019 8:15:59 AM	Sep 20, 2019 8:15:59 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmB Service

CAUSE: preventive maintenance

CORRECTION: perform pmB service

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 19-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,140 - Check Service Brakes	Done		NPIERRE-	Sep 19, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:14:04 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,270 - Check Fare Box Mounting (If	Done		NPIERRE-	Sep 19, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)			LOUIS	12:14:04 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,460 - Record Antifreeze Protection Level	Done		NPIERRE-	Sep 19, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer			LOUIS	12:14:04 PM		
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-	Sep 19, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:14:04 PM		
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-	Sep 19, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	12:14:04 PM		
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,135 - Brake Rotor LF	45.5 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,136 - Brake Rotor RF	45.5 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,137 - Brake Rotor LR	35.5 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,138 - Brake Rotor RR	35.5 Inch		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Sep 19, 2019 12:14:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52691670
Invoice No. 55345 - 52691670

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 186,000 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: NPIERRE-LOUIS Performed on: 19-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Sep 19, 2019 12:15:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52691670
Invoice No. 55345 - 52691670

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	186,000 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 19-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
20 - Miles			NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	
40 - Hours			NPIERRE-LOUIS	Sep 19, 2019 11:21:33 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52691670 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52691658
Invoice No. 55345 - 52691658

Client Department:
Department: 55345M
Work Order Description
Tires / Front Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,430 - DH

Chronology		
Reported	Aug 14, 2019 11:52:43 PM	Aug 14, 2019 11:52:43 PM
Started	Aug 15, 2019 12:00:00 AM	
Completed	Aug 15, 2019 12:10:00 AM	Aug 15, 2019 12:10:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: Front Brakes / Both L/R Tires

Cause: Front Pads Uneven Wear /Both L/R Tire Low tread

Correction: Mount & Balance Both L/R tire rotate To Front & Both front to L/R. Remove&Replace Front Pads .Clean Slide Pins & Lubricate.
Parts # 192659 Qty (2)
Parts #8C2Z-2V001-D Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 14, 2019 11:56:11 PM	No	
20 - Miles			DARTHURS	Aug 14, 2019 11:56:11 PM	No	
30 - Kilometers			DARTHURS	Aug 14, 2019 11:56:11 PM	No	
40 - Hours			DARTHURS	Aug 14, 2019 11:56:11 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.42**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52591127
Invoice No. 55345 - 52591127

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,430 - DH

Chronology		
Reported	Aug 14, 2019 11:04:32 AM	Aug 14, 2019 11:04:32 AM
Started	Aug 14, 2019 12:00:00 AM	
Completed	Aug 15, 2019 12:10:00 AM	Aug 15, 2019 12:10:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter .Lube all Pivoting Points. Check Brakes. Clean batteries.Replace Air Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qt
Parts # PA4075 Qty (1)

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Aug-19	Arthurs,Durvin	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 14-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Aug 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:44:42 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Aug 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:44:42 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,420 - Check Hood	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Aug 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:44:42 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Aug 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:44:42 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Aug 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:44:42 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,132 - Brake Pad Thickness RF	5 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,138 - Brake Rotor RR	1.415 Inch		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Aug 14, 2019 11:44:42 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Aug 14, 2019 11:44:42 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52691658
Invoice No. 55345 - 52691658

Client Department:
Department: 55345M
Work Order Description
Tires / Front Brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,430 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	46.85	46.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.85
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**111.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52591127
Invoice No. 55345 - 52591127

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,430 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Aug-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
14-Aug-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Aug-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 14-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Aug 14, 2019 11:46:55 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Aug 14, 2019 11:46:55 PM	No	
108,000 - Lube all pivoting Mechanisms	-	NA	DARTHURS	Aug 14, 2019 11:46:55 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.24
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**34.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52691658
Invoice No. 55345 - 52691658

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Tires / Front Brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	181,430 - DH

Activity Header
Activity:25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	120.48	240.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Aug-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	240.96
Labor:	65.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**305.96**

Work Order Footer

Work Order 52691658 Total	
Parts:	287.81
Labor:	135.42
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**423.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52591127
Invoice No. 55345 - 52591127

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: EARJOHNSON
Created By: EARJOHNSON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 181,430 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 14, 2019 11:47:52 PM	No	
20 - Miles			DARTHURS	Aug 14, 2019 11:47:52 PM	No	
30 - Kilometers			DARTHURS	Aug 14, 2019 11:47:52 PM	No	
40 - Hours			DARTHURS	Aug 14, 2019 11:47:52 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.42**

Work Order Footer

Work Order 52591127 Total	
Parts:	7.24
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**137.24**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52662925
Invoice No. 55345 - 52662925

Client Department:
Department: 55345M
Work Order Description
Transmission is not shifting properly
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 180,036 - DH

Chronology		
Reported	Aug 5, 2019 2:24:16 PM	Aug 5, 2019 2:24:16 PM
Started	Aug 5, 2019 12:00:00 AM	
Completed	Aug 6, 2019 1:20:49 PM	Aug 6, 2019 1:20:49 PM
Down Time		

Work Order Notes

Line 10 Complaint: Transmission is not shifting properly

Cause: trouble code p0713, internal transmission wire harness (TFT). Normal wear.

Correction: Removed and replaced internal wire harness and sensor, test drive, all okay at this time.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 05-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
10 - Have you successfully completed the	Done		RAURODRIGUEZ	Aug 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				2:44:44 PM		
20 - Miles			RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
30 - Kilometers			RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	
40 - Hours			RAURODRIGUEZ	Aug 5, 2019 2:44:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52662925
Invoice No. 55345 - 52662925

Client Department:
Department: 55345M
Work Order Description
Transmission is not shifting properly
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 180,036 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Aug-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
05-Aug-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
05-Aug-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
05-Aug-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-19	Rodriguez,Raul	2.2666666	65	147.333329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	157.65
Labor:	147.33
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**304.98**

Work Order Footer

Work Order 52662925 Total	
Parts:	157.65
Labor:	147.33
Labor Hours:	2.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**304.98**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52653747
Invoice No. 55345 - 52653747

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Air bag light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	179,796 - DH

Chronology		
Reported	Aug 1, 2019 10:52:31 AM	Aug 1, 2019 10:52:31 AM
Started	Aug 1, 2019 12:00:00 AM	
Completed	Aug 6, 2019 11:33:20 AM	Aug 6, 2019 11:33:20 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:air bag light on

Cause: check computer system found driver side circuit 1 open, as per diagnostic test found circuit has high resistance over 4.00 ohms

Correction:as per diagnostic charts replaced clock spring retest system and road test vehicle as this time light didn¿t come back on

Part:
1 clock spring ac2z-14a664-c

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
20 - Miles			JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
30 - Kilometers			JAPEREZ	Aug 1, 2019 11:03:08 AM	No	
40 - Hours			JAPEREZ	Aug 1, 2019 11:03:08 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52653747
Invoice No. 55345 - 52653747

Client Department:
Department: 55345M
Work Order Description
Air bag light on
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 179,796 - DH

Activity Header
Activity: 15 036 DEVICES, INFORMATION, SUPPLEMENTAL
Activity Note: Air bag light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-19	AC2Z-14A664-C	SPRING, CLOCK, W/CRUISE CONTROL	1	81.53	81.53

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	Perez,Javier	1.8333333	65	119.1666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	81.53
Labor:	119.17
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.70**

Work Order Footer

Work Order 52653747 Total	
Parts:	81.53
Labor:	119.17
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**200.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52624172
Invoice No. 55345 - 52624172

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	178,385 - DH

Chronology		
Reported	Jul 22, 2019 3:08:13 PM	Jul 22, 2019 3:08:13 PM
Started	Jul 22, 2019 12:00:00 AM	
Completed	Jul 23, 2019 9:14:31 AM	Jul 23, 2019 9:14:31 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle won¿t start

Cause: check computer system found no codes, further test indicates that fuel pumps are not working. Follow diagnostic test and diagrams found both fuel pump relays doesn¿t have ground, aftermarket connector doesn¿t have good connection causing not to transfer good ground to relays

Correction:removed ground wire from harness and connected directly to chassis retest system vehicle works ok at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 22-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
20 - Miles			JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
30 - Kilometers			JAPEREZ	Jul 22, 2019 3:16:16 PM	No	
40 - Hours			JAPEREZ	Jul 22, 2019 3:16:16 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52624172
Invoice No. 55345 - 52624172

Client Department:
Department: 55345M
Work Order Description
Vehicle wont start
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 178,385 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Vehicle wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jul-19	Perez,Javier	6.75	65	438.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	438.75
Labor Hours:	6.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**438.75**

Work Order Footer

Work Order 52624172 Total	
Parts:	0.00
Labor:	438.75
Labor Hours:	6.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**438.75**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52489496
Invoice No. 55345 - 52489496

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,319 - DH

Chronology		
Reported	Jul 10, 2019 9:11:24 AM	Jul 10, 2019 9:11:24 AM
Started	Jul 11, 2019 12:00:00 AM	
Completed	Jul 11, 2019 12:19:00 AM	Jul 11, 2019 12:19:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA service.

CAUSE: Due by Mileage.

CORRECTION: LOF engine oil and filter. Performed tire and brake inspection.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jul-19	Earl Johnson	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: EARJOHNSON Performed on: 11-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,100 - Safety Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,160 - FRA Check Instruments and Horns	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,170 - Check Fast Idle	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,180 - Check Starter Protection Circuit	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
10,190 - Check Reverse Warning System	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,100 - Check Parking Brake	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,150 - Perform Brake Test	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,170 - FRA Check Door Operation	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,210 - Check Condition of Operator's Area	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,240 - FRA Check Interior Lights	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,260 - Check Stop Request System	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
22,110 - Check Emergency Hatches	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
22,120 - Check All Safety Equipment	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,310 - Check Passenger Doors	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,360 - Check for Physical Damage and Decals	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,380 - Check Exterior Compartment Doors	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
33,100 - Check Lights and Reflectors	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,420 - Check Hood	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,130 - FRA Check Exhaust System	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,140 - FRA Check Intake System	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,180 - FRA Check for Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,190 - FRA Perform Battery Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
50,510 - Check Entire Steering System	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,630 - Check and Record Tread Depth	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,631 - Tread Depth RF	9 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,650 - Check Sidewall Wear	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,660 - Inspect for Cuts and Tears	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,670 - Check Dual Mating With Square	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,710 - Check Vibration Damper	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,730 - FRA Check Starter	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,770 - FRA Check Exhaust System	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,120 - Check Suspension Components	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,131 - Brake Pad Thickness LF	6 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,132 - Brake Pad Thickness RF	7 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,133 - Brake Pad Thickness LR	9 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,134 - Brake Pad Thickness RR	9 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,135 - Brake Rotor LF	1.478 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,136 - Brake Rotor RF	1.489 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,137 - Brake Rotor LR	1.488 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,138 - Brake Rotor RR	1.49 Inch		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,140 - FRA Check Brake Hoses	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,150 - Check King Pins	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
80,810 - Completion of PMI Report	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		EARJOHNSON	Jul 11, 2019 12:15:20 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**97.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52489496
Invoice No. 55345 - 52489496

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 177,319 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jul-19	Earl Johnson	1	65	65

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: EARJOHNSON Performed on: 11-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
101,000 - FRA Change Oil Filters	Yes		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
102,000 - FRA Drain Engine Oil	Yes		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
103,000 - FRA Check Transmission Fluid	Done		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
104,000 - Lubricate Chassis	Done		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
105,000 - Replace or Clean A/C Filters	Done		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		EARJOHNSON	Jul 11, 2019 12:15:03 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	65.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**66.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52489496
Invoice No. 55345 - 52489496

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	**Status:**	40 - Closed (40)
Created By:	VAMRITTEEMAL	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	177,319 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jul-19	Earl Johnson	0.1666666	65	10.833329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 11-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
20 - Miles			EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
30 - Kilometers			EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	
40 - Hours			EARJOHNSON	Jul 11, 2019 12:14:30 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	10.83
	Labor Hours:	0.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**10.83**

Work Order Footer

Work Order 52489496 Total	
Parts:	1.96
Labor:	173.33
Labor Hours:	2.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**175.29**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52560374
Invoice No. 55345 - 52560374

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check engine light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	176,069 - DH

Chronology		
Reported	Jun 28, 2019 1:47:34 PM	Jun 28, 2019 1:47:34 PM
Started	Jun 28, 2019 12:00:00 AM	
Completed	Jul 1, 2019 8:33:57 AM	Jul 1, 2019 8:33:57 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:check engine light on

Cause: check computer system found P0172 system too rich bank 1

Correction:Replaced left and right front O2 sensors retest system ok at this time

Parts:
1 new O2 sensor 8f9z-9f472-h
1 new O2 sensor 8f9z-9f472-j

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 28-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
20 - Miles			JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
30 - Kilometers			JAPEREZ	Jun 28, 2019 1:55:13 PM	No	
40 - Hours			JAPEREZ	Jun 28, 2019 1:55:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52560374
Invoice No. 55345 - 52560374

Client Department:
Department: 55345M
Work Order Description
Check engine light on
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 176,069 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Check engine light on
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-19	8F9Z-9F472-H	SENSOR, OXYGEN	1	64.39	64.39
28-Jun-19	8F9Z-9F472-J	SENSOR, OXYGEN, UPSTREAM, RH	1	137.99	137.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-19	Perez,Javier	1.3333333	65	86.6666645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	202.38
Labor:	86.67
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**289.05**

Work Order Footer

Work Order 52560374 Total	
Parts:	202.38
Labor:	86.67
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**289.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52397456
Invoice No. 55345 - 52397456

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 172,979 - DH

Chronology		
Reported	Jun 4, 2019 11:54:56 AM	Jun 4, 2019 11:54:56 AM
Started	Jun 4, 2019 12:00:00 AM	
Completed	Jun 4, 2019 9:32:00 PM	Jun 4, 2019 9:32:00 PM
Down Time		

Work Order Notes

Line 10 PMC SERVICE
PREVENTIVE MAINTENANCE
PERFORM AND COMPLETED PMC SERVICE
REPLACED EXHAUST HANGER

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jun-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 04-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,135 - Brake Rotor LF	39.9 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,136 - Brake Rotor RF	39.91 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,137 - Brake Rotor LR	35.87 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,138 - Brake Rotor RR	35.85 Inch		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Jun 4, 2019 9:05:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**130.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52397456
Invoice No. 55345 - 52397456

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 172,979 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
04-Jun-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jun-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: VAMRITTEEMAL Performed on: 04-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
201,000 - Service Crankcase Breather	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No	n/a	VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	
305,000 - FRA Change Differential Fluid	Yes		VAMRITTEEMAL	Jun 4, 2019 9:08:03 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**149.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52397456
Invoice No. 55345 - 52397456

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	172,979 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jun-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 04-JUN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
20 - Miles			VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	
40 - Hours			VAMRITTEEMAL	Jun 4, 2019 8:45:59 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52397456 Total	
Parts:	19.23
Labor:	277.33
Labor Hours:	4.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52429191
Invoice No. 55345 - 52429191

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace Evap		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,402 - DH

Chronology		
Reported	May 14, 2019 12:31:35 PM	May 14, 2019 12:31:35 PM
Started	May 14, 2019 12:00:00 AM	
Completed	May 15, 2019 8:29:00 AM	May 15, 2019 8:29:00 AM
Down Time		

Work Order Notes

Line 10 Tech replaced front A/C Evap and Orifice tube. Added oil and charge system

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-19	KARLENS,Cyrius	0.3333333	65	21.6666645

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 14-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
3 - Are you wearing the appropriate PPE?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
4 - Have you performed the proper LOTO?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 14, 2019 12:40:34 PM	No	
20 - Miles		na	CKARLENS	May 14, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:40:34 PM		
30 - Kilometers		na	CKARLENS	May 14, 2019 12:40:34 PM	No	
40 - Hours		na	CKARLENS	May 14, 2019 12:40:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	21.67
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**21.67**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52429191
Invoice No. 55345 - 52429191

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace Evap		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	170,402 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-May-19	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19
14-May-19	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-19	KARLENS,Cyrius	3	65	195

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	101.94
Labor:	195.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**296.94**

Work Order Footer

Work Order 52429191 Total	
Parts:	101.94
Labor:	216.67
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**318.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52410610
Invoice No. 55345 - 52410610

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
TURNING SIGNAL NOT WORKING		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	169,376 - DH

Chronology		
Reported	May 8, 2019 12:07:00 AM	May 8, 2019 12:07:00 AM
Started	May 8, 2019 12:00:00 AM	
Completed	May 8, 2019 12:13:00 AM	May 8, 2019 12:13:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: TURNING SIGNAL NOT WORKING

Cause: MALTIFUNCITON SWITCH

Correction: REPLACE MALTIFUNCTION SWITCH
PARTS# 7-1Z-13K359-AB QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-19	Owens,Arthur	0.2	65	13

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 08-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	May 8, 2019 12:12:37 AM	No	
20 - Miles			AOWENS	May 8, 2019 12:12:37 AM	No	
30 - Kilometers			AOWENS	May 8, 2019 12:12:37 AM	No	
40 - Hours			AOWENS	May 8, 2019 12:12:37 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	13.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**13.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52410610
Invoice No. 55345 - 52410610

Client Department:
Department: 55345M
Work Order Description
TURNING SIGNAL NOT WORKING
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 169,376 - DH

Activity Header
Activity: 15 050/000/000 GROUP, ACCESSORIES
Activity Note: TURNING SIGNAL NOT WORKING
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-May-19	7F1Z-13K359-AB	SWITCH, MULTIFUNCTION, SIGNAL, TURN	1	145.35	145.35

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-May-19	Owens,Arthur	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	145.35
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**242.85**

Work Order Footer

Work Order 52410610 Total	
Parts:	145.35
Labor:	110.50
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**255.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52397396
Invoice No. 55345 - 52397396

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes and 4 new tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 168,735 - DH

Chronology		
Reported	May 2, 2019 11:27:09 PM	May 2, 2019 11:27:09 PM
Started	May 2, 2019 12:00:00 AM	
Completed	May 3, 2019 12:28:00 AM	May 3, 2019 12:28:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes and 4 tires

Cause: wear

Correction:Replaced rear brake pads and lubed guide pins
4 new tires mounted and balanced
Washed rims and rotate tires
Torque wheels 140 lbs second torque 140 lbs
Tires part number 192659 qty4
Brakes part number 8C2Z-2V200-C Qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	0.1	65	6.5

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 2, 2019 11:31:10 PM	No	
20 - Miles			RGASPARD	May 2, 2019 11:31:10 PM	No	
30 - Kilometers			RGASPARD	May 2, 2019 11:31:10 PM	No	
40 - Hours			RGASPARD	May 2, 2019 11:31:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	6.50
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52308527
Invoice No. 55345 - 52308527

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	168,735 - DH

Chronology		
Reported	May 2, 2019 2:21:47 PM	May 2, 2019 2:21:47 PM
Started	May 2, 2019 12:00:00 AM	
Completed	May 3, 2019 12:28:00 AM	May 3, 2019 12:28:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	1.5833333	65	102.9166645

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 02-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,420 - Check Hood	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	May 2, 2019 11:23:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	May 2, 2019 11:23:23 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	May 2, 2019 11:23:23 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**102.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52397396
Invoice No. 55345 - 52397396

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes and 4 new tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 168,735 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs rear brakes and 4 new tires
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-May-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	-1	46.22	-46.22
08-May-19	9C2Z-2V200-B	PADS, BRAKE, DISC, REAR SAME AS BRSD1329B	1	46.22	46.22
02-May-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	1.5	65	97.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	47.81
Labor:	97.50
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**145.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52308527
Invoice No. 55345 - 52308527

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	168,735 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	1.1	65	71.5

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 02-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 2, 2019 11:24:06 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 2, 2019 11:24:06 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 2, 2019 11:24:06 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 2, 2019 11:24:06 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	May 2, 2019 11:24:06 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 2, 2019 11:24:06 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	May 2, 2019 11:24:06 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 2, 2019 11:24:06 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	71.50
	Labor Hours:	1.10
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**73.46**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52397396
Invoice No. 55345 - 52397396

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes and 4 new tires
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 168,735 - DH

Activity Header
Activity: 25 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	0.00
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**162.50**

Work Order Footer

Work Order 52397396 Total	
Parts:	47.81
Labor:	266.50
Labor Hours:	4.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**314.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52308527
Invoice No. 55345 - 52308527

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	168,735 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Gaspard,Ronald	0.2666666	65	17.333329

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 2, 2019 11:24:37 PM	No	
20 - Miles			RGASPARD	May 2, 2019 11:24:37 PM	No	
30 - Kilometers			RGASPARD	May 2, 2019 11:24:37 PM	No	
40 - Hours			RGASPARD	May 2, 2019 11:24:37 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.33**

Work Order Footer

Work Order 52308527 Total	
Parts:	1.96
Labor:	191.75
Labor Hours:	2.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52353771
Invoice No. 55345 - 52353771

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FRONT A/C NOT WORKING		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	166,920 - DH

Chronology		
Reported	Apr 17, 2019 11:06:00 PM	Apr 17, 2019 11:06:00 PM
Started	Apr 17, 2019 12:00:00 AM	
Completed	Apr 17, 2019 11:14:00 PM	Apr 17, 2019 11:14:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: FRONT A/C NOT WORKING

Cause: FRONT A/C BLOWER MOTOR

Correction: REPLACE FRONT A/C BLOWER MOTOR AND RESISTOR
PART # XC2Z-19805-BA QTY 1
4C2Z-19A706-AA QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-19	Owens,Arthur	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 17-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Apr 17, 2019 11:14:01 PM	No	
20 - Miles			AOWENS	Apr 17, 2019 11:14:01 PM	No	
30 - Kilometers			AOWENS	Apr 17, 2019 11:14:01 PM	No	
40 - Hours			AOWENS	Apr 17, 2019 11:14:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52353771
Invoice No. 55345 - 52353771

Client Department:
Department: 55345M
Work Order Description
FRONT A/C NOT WORKING
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 166,920 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: FRONT A/C
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Apr-19	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	37.71	37.71
17-Apr-19	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	17.83	17.83

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Apr-19	Owens,Arthur	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	55.54
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.54**

Work Order Footer

Work Order 52353771 Total	
Parts:	55.54
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**55.54**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52317935
Invoice No. 55345 - 52317935

Client Department:
Department: 55345M
Work Order Description
Driver said the battery light on
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 165,328 - DH

Chronology		
Reported	Apr 5, 2019 11:19:36 AM	Apr 5, 2019 11:19:36 AM
Started	Apr 5, 2019 12:00:00 AM	
Completed	Apr 9, 2019 11:15:36 AM	Apr 9, 2019 11:15:36 AM
Down Time		

Work Order Notes

Line 10 Driver called saying the batterie light on,technician found voltage reference to the alternator wire was broken;
Tech made repair. No problem at this time

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Apr-19	NELSON PIERRE-LOUIS	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc:
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 05-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Apr 5, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	11:40:33 AM		
20 - Miles		NA	NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
30 - Kilometers		NA	NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	
40 - Hours		NA	NPIERRE-LOUIS	Apr 5, 2019 11:40:33 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52317935
Invoice No. 55345 - 52317935

Client Department:
Department: 55345M
Work Order Description
Driver said the battery light on
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 165,328 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Apr-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	-1	108.36	-108.36
08-Apr-19	8C2Z-3050-A	JOINT, BALL, LOWER	1	44.35	44.35
08-Apr-19	8C2Z-3050-A	JOINT, BALL, LOWER	-1	44.35	-44.35
08-Apr-19	MCSOE3	JOINT, BALL, UPPER, E450	-1	38.97	-38.97
08-Apr-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	1	108.36	108.36
08-Apr-19	MCSOE3	JOINT, BALL, UPPER, E450	1	38.97	38.97

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Apr-19	NELSON PIERRE-LOUIS	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 52317935 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52155838
Invoice No. 55345 - 52155838

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	164,722 - DH

Chronology		
Reported	Apr 2, 2019 11:55:54 AM	Apr 2, 2019 11:55:54 AM
Started	Apr 2, 2019 12:00:00 AM	
Completed	Apr 2, 2019 11:55:00 PM	Apr 2, 2019 11:55:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE: Service

CORRECTION: Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts
Replaced exhaust hanger qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-19	Gaspard,Ronald	1.75	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 02-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Apr 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:49:30 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Apr 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:49:30 PM		
20,260 - Check Stop Request System	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,420 - Check Hood	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,442 - Freeze Point	Degree	NA	RGASPARD	Apr 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:49:30 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Apr 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:49:30 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Apr 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:49:30 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Apr 2, 2019 10:49:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Apr 2, 2019 10:49:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52155838
Invoice No. 55345 - 52155838

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 164,722 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-19	Gaspard,Ronald	1.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 02-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Apr 2, 2019 10:50:19 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Apr 2, 2019 10:50:19 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Apr 2, 2019 10:50:19 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Apr 2, 2019 10:50:19 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Apr 2, 2019 10:50:19 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Apr 2, 2019 10:50:19 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Apr 2, 2019 10:50:19 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Apr 2, 2019 10:50:19 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52155838
Invoice No. 55345 - 52155838

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 164,722 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-19	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 2, 2019 10:50:53 PM	No	
20 - Miles			RGASPARD	Apr 2, 2019 10:50:53 PM	No	
30 - Kilometers			RGASPARD	Apr 2, 2019 10:50:53 PM	No	
40 - Hours			RGASPARD	Apr 2, 2019 10:50:53 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52155838 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	3.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52283087
Invoice No. 55345 - 52283087

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Wrench light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,782 - DH

Chronology		
Reported	Mar 25, 2019 2:30:53 PM	Mar 25, 2019 2:30:53 PM
Started	Mar 25, 2019 12:00:00 AM	
Completed	Mar 26, 2019 7:40:14 AM	Mar 26, 2019 7:40:14 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:wrench light on

Cause: check computer system found code U016c fuel pump module relay 2 loss communication with PCM. Follow diagnostic procedures found broken wire on SRM connector also found a broken connector for fuel gauge main ground

Correction:removed SRM connector to repair wire and replaced connector for fuel gauge ground, retest system and road test vehicle ok at this time

Part:
1 new fuel pump relay aa8z-9d370-b

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 25-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
20 - Miles			JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
30 - Kilometers			JAPEREZ	Mar 25, 2019 2:42:55 PM	No	
40 - Hours			JAPEREZ	Mar 25, 2019 2:42:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52283087
Invoice No. 55345 - 52283087

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Wrench light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,782 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Wrench light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Mar-19	AA8Z-9D370-B	MODULE, RELAY, PUMP, FUEL	1	39.21	39.21

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Mar-19	Perez,Javier	19.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	39.21
Labor:	0.00
Labor Hours:	19.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.21**

Work Order Footer

Work Order 52283087 Total	
Parts:	39.21
Labor:	0.00
Labor Hours:	19.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**39.21**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52238766
Invoice No. 55345 - 52238766

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Heather hose/Serpentine belt /PCV Valve		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,471 - DH

Chronology		
Reported	Mar 7, 2019 10:58:36 PM	Mar 7, 2019 10:58:36 PM
Started	Mar 10, 2019 12:00:00 AM	
Completed	Mar 10, 2019 8:18:00 PM	Mar 10, 2019 8:18:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: heather hose/ Serpentine belt / PCV Valve.

Cause: Heather hose leaking/ Serpentine belt cracks/ hissing noise coming from PCV Valve.
Parts #BC2Z-18472-CA Qty (1)
Parts#BC2Z-18472-DA Qty (1)
Parts#1360K6 Qty (1)
Parts#7L3Z-6A666-A Qty (1)

Correction:

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 10-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 10, 2019 8:00:27 PM	No	
20 - Miles			DARTHURS	Mar 10, 2019 8:00:27 PM	No	
30 - Kilometers			DARTHURS	Mar 10, 2019 8:00:27 PM	No	
40 - Hours			DARTHURS	Mar 10, 2019 8:00:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52238766
Invoice No. 55345 - 52238766

Client Department:
Department: 55345M
Work Order Description
Heather hose/Serpentine belt /PCV Valve
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 163,471 - DH

Activity Header
Activity: 15 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Mar-19	BC2Z-18472-CA	TUBE, HEATER, WATER	1	59.05	59.05
10-Mar-19	BC2Z-18472-DA	TUBE, HEATER, WATER	1	55.95	55.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-19	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	115.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**115.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52238766
Invoice No. 55345 - 52238766

Client Department:
Department: 55345M
Work Order Description
Heather hose/Serpentine belt /PCV Valve
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 163,471 - DH

Activity Header
Activity: 25 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Mar-19	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.5	21.5
10-Mar-19	7L3Z-6A666-A	VALVE, PCV	1	6.9	6.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-19	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	28.40
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**28.40**

Work Order Footer

Work Order 52238766 Total	
Parts:	143.40
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**143.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52221831
Invoice No. 55345 - 52221831

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
WHEEL CHAIR LIFT WILL NOT LET DOWN		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	163,004 - DH

Chronology		
Reported	Mar 4, 2019 11:46:00 PM	Mar 4, 2019 11:46:00 PM
Started	Mar 4, 2019 12:00:00 AM	
Completed	Mar 4, 2019 11:54:00 PM	Mar 4, 2019 11:54:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: WHEEL CHAIR LIFT WILL NOT LET DOWN

Cause: HARNESS ROLLSTOP SWITCH

Correction: REPLACE HARNESS ROLL STOP SWITCH
PART# 400374AKS QTY 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-19	Owens,Arthur	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 04-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
3 - Are you wearing the appropriate PPE?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
4 - Have you performed the proper LOTO?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Mar 4, 2019 11:53:41 PM	No	
20 - Miles			AOWENS	Mar 4, 2019 11:53:41 PM	No	
30 - Kilometers			AOWENS	Mar 4, 2019 11:53:41 PM	No	
40 - Hours			AOWENS	Mar 4, 2019 11:53:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52221831
Invoice No. 55345 - 52221831

Client Department:
Department: 55345M
Work Order Description
WHEEL CHAIR LIFT WILL NOT LET DOWN
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 163,004 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WHEEL CHAIR LIFT WILL NOT GO DOWN
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Mar-19	400374AKS	SWITCH, BARRIER, OUTER, W/C, BRAUN	1	20.14	20.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Mar-19	Owens,Arthur	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	20.14
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.14**

Work Order Footer

Work Order 52221831 Total	
Parts:	20.14
Labor:	0.00
Labor Hours:	1.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**20.14**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52207709
Invoice No. 55345 - 52207709

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Cylinder #1 misfire		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	162,412 - DH

Chronology		
Reported	Feb 27, 2019 2:04:47 PM	Feb 27, 2019 2:04:47 PM
Started	Feb 27, 2019 12:00:00 AM	
Completed	Feb 27, 2019 2:50:40 PM	Feb 27, 2019 2:50:40 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:Cylinder #1 misfire

Cause: check computer system found cylinder 1 has a misfire due to electric connector for fuel injector is broken

Correction:replaced fuel injector pig tail connector with a good used one

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 27-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
20 - Miles			JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
30 - Kilometers			JAPEREZ	Feb 27, 2019 2:11:19 PM	No	
40 - Hours			JAPEREZ	Feb 27, 2019 2:11:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52207709
Invoice No. 55345 - 52207709

Client Department:
Department: 55345M
Work Order Description
Cylinder #1 misfire
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 162,412 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Cylinder #1 misfire
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-19	Perez,Javier	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 52207709 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52175365
Invoice No. 55345 - 52175365

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle stalls		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,991 - DH

Chronology		
Reported	Feb 15, 2019 1:46:53 PM	Feb 15, 2019 1:46:53 PM
Started	Feb 15, 2019 12:00:00 AM	
Completed	Feb 18, 2019 9:32:32 AM	Feb 18, 2019 9:32:32 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:vehicle stalls

Cause: check computer system found no codes, check fuel system found fuel pressure is low

Correction:replaced fuel pump kit and SRM module

Parts:
1 fuel pump kit 11396002
1 SRM module

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 15-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done	I	JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
20 - Miles			JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
30 - Kilometers			JAPEREZ	Feb 15, 2019 2:04:26 PM	No	
40 - Hours			JAPEREZ	Feb 15, 2019 2:04:26 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52175365
Invoice No. 55345 - 52175365

Client Department:
Department: 55345M
Work Order Description
Vehicle stalls
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 160,991 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Vehicle stalls
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Feb-19	P11JC-03P205-AB	MODULE, RELAY, SMART	1	472.31	472.31
15-Feb-19	11396002	PUMP, FUEL, GASEOUS, GEN-3 W/KIT	1	414.31	414.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-19	Perez,Javier	3.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	886.62
Labor:	0.00
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**886.62**

Work Order Footer

Work Order 52175365 Total	
Parts:	886.62
Labor:	0.00
Labor Hours:	3.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**886.62**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52154352
Invoice No. 55345 - 52154352

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fire prevention system		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,387 - DH

Chronology		
Reported	Feb 8, 2019 1:32:01 PM	Feb 8, 2019 1:32:01 PM
Started	Feb 8, 2019 12:00:00 AM	
Completed	Feb 11, 2019 10:58:00 AM	Feb 11, 2019 10:58:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:fire prevention system not working

Cause: system got discharged,

Correction:Replaced all terminals nozzles and PA valve retest system ok at this time

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 08-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
20 - Miles			JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
30 - Kilometers			JAPEREZ	Feb 8, 2019 1:48:24 PM	No	
40 - Hours			JAPEREZ	Feb 8, 2019 1:48:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52154352
Invoice No. 55345 - 52154352

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Fire prevention system		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,387 - DH

Activity Header
Activity: 15 051 GENERAL ACCESSORIES (POWER UNITS, TRAILERS, ETC.)
Activity Note: Fire prevention system
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Perez,Javier	3.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 52154352 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52155769
Invoice No. 55345 - 52155769

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Tires		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,387 - DH

Chronology		
Reported	Feb 8, 2019 10:25:21 PM	Feb 8, 2019 10:25:21 PM
Started	Feb 8, 2019 12:00:00 AM	
Completed	Feb 8, 2019 11:25:00 PM	Feb 8, 2019 11:25:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: both L/R Tire

Cause: Tire low tread depth

Correction: Mount & Balance two Tire . Rotate both front tire to L/ Rear. New tire on front.Patch & Balance R/R inner tire / Replace
Parts# 002760 Qty (2)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 8, 2019 10:26:50 PM	No	
20 - Miles			DARTHURS	Feb 8, 2019 10:26:50 PM	No	
30 - Kilometers			DARTHURS	Feb 8, 2019 10:26:50 PM	No	
40 - Hours			DARTHURS	Feb 8, 2019 10:26:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 52047399
Invoice No. 55345 - 52047399

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,387 - DH

Chronology		
Reported	Feb 8, 2019 1:46:28 PM	Feb 8, 2019 1:46:28 PM
Started	Feb 8, 2019 12:00:00 AM	
Completed	Feb 8, 2019 11:25:00 PM	Feb 8, 2019 11:25:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM B Service.

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter.lube all Pivoting Points .check brakes clean batteries. Replace A/C Filter.
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qt

Activity Header

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Arthurs,Durvin	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 08-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,420 - Check Hood	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,135 - Brake Rotor LF	1.555 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,137 - Brake Rotor LR	1.656 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,138 - Brake Rotor RR	1.654 Inch		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Feb 8, 2019 10:16:48 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Feb 8, 2019 10:16:48 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52155769
Invoice No. 55345 - 52155769

Client Department:
Department: 55345M
Work Order Description
Tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 160,387 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-19	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	2	120.05	240.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	240.10
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**240.10**

Work Order Footer

Work Order 52155769 Total	
Parts:	240.10
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**240.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 52047399
Invoice No. 55345 - 52047399

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 160,387 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Feb-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 08-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Feb 8, 2019 10:18:21 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Feb 8, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				10:18:21 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Feb 8, 2019 10:18:21 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Feb 8, 2019 10:18:21 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Feb 8, 2019 10:18:21 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 52047399
Invoice No. 55345 - 52047399

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	160,387 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 8, 2019 10:20:04 PM	No	
20 - Miles			DARTHURS	Feb 8, 2019 10:20:04 PM	No	
30 - Kilometers			DARTHURS	Feb 8, 2019 10:20:04 PM	No	
40 - Hours			DARTHURS	Feb 8, 2019 10:20:04 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 52047399 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52047386
Invoice No. 55345 - 52047386

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs right side motor mount		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,393 - DH

Chronology		
Reported	Jan 5, 2019 12:06:03 AM	Jan 5, 2019 12:06:03 AM
Started	Jan 5, 2019 12:00:00 AM	
Completed	Jan 5, 2019 12:19:00 AM	Jan 5, 2019 12:19:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs right side motor mount

Cause: cracked

Correction:Replaced right side motor mount
Part number 5U9Z-6038-AA Qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-19	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 5, 2019 12:08:26 AM	No	
20 - Miles			RGASPARD	Jan 5, 2019 12:08:26 AM	No	
30 - Kilometers			RGASPARD	Jan 5, 2019 12:08:26 AM	No	
40 - Hours			RGASPARD	Jan 5, 2019 12:08:26 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51968657
Invoice No. 55345 - 51968657

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,393 - DH

Chronology		
Reported	Jan 4, 2019 10:21:42 AM	Jan 4, 2019 10:21:42 AM
Started	Jan 5, 2019 12:00:00 AM	
Completed	Jan 5, 2019 12:19:00 AM	Jan 5, 2019 12:19:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-19	Gaspard,Ronald	1.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 05-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 5, 2019 12:01:53 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 5, 2019 12:01:53 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52047386
Invoice No. 55345 - 52047386

Client Department:
Department: 55345M
Work Order Description
Needs right side motor mount
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 156,393 - DH

Activity Header
Activity: 15 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Needs right side motor mount
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jan-19	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	52	52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-19	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	52.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order Footer

Work Order 52047386 Total	
Parts:	52.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**52.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51968657
Invoice No. 55345 - 51968657

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 156,393 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-19	Gaspard,Ronald	1.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 05-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 5, 2019 12:12:35 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 5, 2019 12:12:35 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 5, 2019 12:12:35 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 5, 2019 12:12:35 AM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 5, 2019 12:12:35 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 5, 2019 12:12:35 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 5, 2019 12:12:35 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 5, 2019 12:12:35 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51968657
Invoice No. 55345 - 51968657

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	156,393 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jan-19	Gaspard,Ronald	0.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 5, 2019 12:03:03 AM	No	
20 - Miles			RGASPARD	Jan 5, 2019 12:03:03 AM	No	
30 - Kilometers			RGASPARD	Jan 5, 2019 12:03:03 AM	No	
40 - Hours			RGASPARD	Jan 5, 2019 12:03:03 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51968657 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 52003128
Invoice No. 55345 - 52003128

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Spark plugs		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	154,176 - DH

Chronology		
Reported	Dec 17, 2018 2:39:42 PM	Dec 17, 2018 2:39:42 PM
Started	Dec 17, 2018 12:00:00 AM	
Completed	Dec 18, 2018 9:49:14 AM	Dec 18, 2018 9:49:14 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:spark plugs

Cause: Preventive Maintenance

Correction:replaced spark plugs and boots. Clean throttle body

Parts:
10 new spark plugs ap 103
10 boots 357006

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 17-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
20 - Miles			JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
30 - Kilometers			JAPEREZ	Dec 17, 2018 2:46:59 PM	No	
40 - Hours			JAPEREZ	Dec 17, 2018 2:46:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 52003128
Invoice No. 55345 - 52003128

Client Department:
Department: 55345M
Work Order Description
Spark plugs
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 154,176 - DH

Activity Header
Activity: 15 033 IGNITION
Activity Note: Spark plugs
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Dec-18	357006	BOOT, COIL-ON-PLUG, IGNITION	10	3.95	39.5
17-Dec-18	AP103	PLUG, SPARK	10	2.9	29

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Dec-18	Perez,Javier	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	68.50
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.50**

Work Order Footer

Work Order 52003128 Total	
Parts:	68.50
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**68.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51968595
Invoice No. 55345 - 51968595

Client Department:
Department: 55345M
Work Order Description
Needs front rotors and brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,504 - DH

Chronology		
Reported	Dec 5, 2018 11:11:42 PM	Dec 5, 2018 11:11:42 PM
Started	Dec 5, 2018 12:00:00 AM	
Completed	Dec 6, 2018 12:02:00 AM	Dec 6, 2018 12:02:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front brakes and rotors

Cause: wear

Correction:Replaced front rotors repacked bearings
Replaced brake pads lubed guide pins
Torque wheels 140 lbs second torque wheels 140 lbs
Brake pads:8C2Z-2V001-D Qty1
Front rotors:8C2Z-1102-B qty2
Outer bearings 15101 qty2
Inner bearings LM102949 qty2
SealsCR24000 qty2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-DEC-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 5, 2018 11:15:47 PM	No	
20 - Miles			RGASPARD	Dec 5, 2018 11:15:47 PM	No	
30 - Kilometers			RGASPARD	Dec 5, 2018 11:15:47 PM	No	
40 - Hours			RGASPARD	Dec 5, 2018 11:15:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51968595
Invoice No. 55345 - 51968595

Client Department:
Department: 55345M
Work Order Description
Needs front rotors and brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 152,504 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs front rotors and brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-18	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	7.44	14.88
05-Dec-18	CR24000	SEAL, WHEEL, HUB, FRONT	2	6.92	13.84
05-Dec-18	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	2	112.53	225.06
05-Dec-18	TM15101	BEARING, WHEEL, OUTER, CONE, ROLLER, TAPERED	2	8.16	16.32
05-Dec-18	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87
06-Dec-18	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Gaspard,Ronald	3.8333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	367.84
Labor:	0.00
Labor Hours:	3.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**367.84**

Work Order Footer

Work Order 51968595 Total	
Parts:	367.84
Labor:	0.00
Labor Hours:	3.97
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**367.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51923323
Invoice No. 55345 - 51923323

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,504 - DH

Chronology		
Reported	Dec 5, 2018 10:50:01 AM	Dec 5, 2018 10:50:01 AM
Started	Dec 5, 2018 12:00:00 AM	
Completed	Dec 6, 2018 12:01:00 AM	Dec 6, 2018 12:01:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Gaspard,Ronald	1.5666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Dec 5, 2018 11:08:21 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 5, 2018 11:08:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51923323
Invoice No. 55345 - 51923323

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,504 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Gaspard,Ronald	1.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 5, 2018 11:08:55 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 5, 2018 11:08:55 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 5, 2018 11:08:55 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 5, 2018 11:08:55 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Dec 5, 2018 11:08:55 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 5, 2018 11:08:55 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Dec 5, 2018 11:08:55 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 5, 2018 11:08:55 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.12
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51923323
Invoice No. 55345 - 51923323

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	152,504 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-18	Gaspard,Ronald	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 5, 2018 11:09:25 PM	No	
20 - Miles			RGASPARD	Dec 5, 2018 11:09:25 PM	No	
30 - Kilometers			RGASPARD	Dec 5, 2018 11:09:25 PM	No	
40 - Hours			RGASPARD	Dec 5, 2018 11:09:25 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51923323 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51696805
Invoice No. 55345 - 51696805

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 148,326 - DH

Chronology		
Reported	Nov 19, 2018 12:00:00 AM	Nov 19, 2018 12:00:00 AM
Started	Nov 19, 2018 12:00:00 AM	
Completed	Nov 20, 2018 12:07:00 AM	Nov 20, 2018 12:07:00 AM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform PMC Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts
Gear Oil 80w90 qty 6 Qts
Air filter PA4075 Qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 19-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,133 - Brake Pad Thickness LR	11 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,134 - Brake Pad Thickness RR	11 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Nov 19, 2018 11:50:14 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 19, 2018 11:50:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51696805
Invoice No. 55345 - 51696805

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 148,326 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Nov-18	PA4075	FILTER, AIR SEE P546597	1	5.27	5.27
19-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-18	Gaspard,Ronald	1.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 19-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 19, 2018 11:51:51 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	RGASPARD	Nov 19, 2018 11:51:51 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	RGASPARD	Nov 19, 2018 11:51:51 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	RGASPARD	Nov 19, 2018 11:51:51 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Nov 19, 2018 11:51:51 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Nov 19, 2018 11:51:51 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.23
Labor:	0.00
Labor Hours:	1.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51696805
Invoice No. 55345 - 51696805

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	148,326 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-18	Gaspard,Ronald	0.3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 19, 2018 11:52:33 PM	No	
20 - Miles			RGASPARD	Nov 19, 2018 11:52:33 PM	No	
30 - Kilometers			RGASPARD	Nov 19, 2018 11:52:33 PM	No	
40 - Hours			RGASPARD	Nov 19, 2018 11:52:33 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order Footer

Work Order 51696805 Total	
Parts:	7.23
Labor:	0.00
Labor Hours:	3.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51899451
Invoice No. 55345 - 51899451

Client Department:
Department: 55345M
Work Order Description
Bus making noise when turn string wheel
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,890 - DH

Chronology		
Reported	Nov 12, 2018 11:00:27 AM	Nov 12, 2018 11:00:27 AM
Started	Nov 12, 2018 12:00:00 AM	
Completed	Nov 12, 2018 12:50:55 PM	Nov 12, 2018 12:50:55 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: bus making noise when turn string

Cause: gear box leaking

Correction: replaced gear box add fluid completed

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
20 - Miles			HPIERRE	Nov 12, 2018 11:20:07 AM	No	
30 - Kilometers	4		HPIERRE	Nov 12, 2018 11:20:07 AM	No	
40 - Hours	4		HPIERRE	Nov 12, 2018 11:20:07 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51899451
Invoice No. 55345 - 51899451

Client Department:
Department: 55345M
Work Order Description
Bus making noise when turn string wheel
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 145,890 - DH

Activity Header
Activity: 15 015/005 PUMP, STEERING, POWER
Activity Note:
Reason for Repair: 33 Manufacturer's Recall
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Nov-18	277632	BOX, GEAR, STEERING, POWER, REMANUFACTURED	1	94.07	94.07

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Nov-18	Pierre,Hubert J	4	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	94.07
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.07**

Work Order Footer

Work Order 51899451 Total	
Parts:	94.07
Labor:	0.00
Labor Hours:	4.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**94.07**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51612140
Invoice No. 55345 - 51612140

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,397 - DH

Chronology

Reported	Sep 6, 2018 10:43:29 AM	Sep 6, 2018 10:43:29 AM
Started	Sep 6, 2018 12:00:00 AM	
Completed	Sep 6, 2018 11:44:00 PM	Sep 6, 2018 11:44:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PmA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Gaspard,Ronald	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 06-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Sep 6, 2018 11:21:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 6, 2018 11:21:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51612140
Invoice No. 55345 - 51612140

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,397 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Gaspard,Ronald	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 06-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 6, 2018 11:22:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 6, 2018 11:22:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 6, 2018 11:22:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 6, 2018 11:22:09 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Sep 6, 2018 11:22:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 6, 2018 11:22:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Sep 6, 2018 11:22:09 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 6, 2018 11:22:09 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.05
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51612140
Invoice No. 55345 - 51612140

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	143,397 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 6, 2018 11:22:30 PM	No	
20 - Miles			RGASPARD	Sep 6, 2018 11:22:30 PM	No	
30 - Kilometers			RGASPARD	Sep 6, 2018 11:22:30 PM	No	
40 - Hours			RGASPARD	Sep 6, 2018 11:22:30 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51612140 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.85

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51696780
Invoice No. 55345 - 51696780

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes job and tires rotation
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,397 - DH

Chronology		
Reported	Sep 6, 2018 11:25:11 PM	Sep 6, 2018 11:25:11 PM
Started	Sep 6, 2018 12:00:00 AM	
Completed	Sep 6, 2018 11:43:00 PM	Sep 6, 2018 11:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes job and tires rotation

Cause: wear

Correction:replaced rear brake pads and lubed GUIDE pins
Rotate tires and washed rims torque wheels 140 lbs second torque 140 lbs
Brakes part number 8C2Z-2V200-B Qty1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 6, 2018 11:27:23 PM	No	
20 - Miles			RGASPARD	Sep 6, 2018 11:27:23 PM	No	
30 - Kilometers			RGASPARD	Sep 6, 2018 11:27:23 PM	No	
40 - Hours			RGASPARD	Sep 6, 2018 11:27:23 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51696780
Invoice No. 55345 - 51696780

Client Department:
Department: 55345M
Work Order Description
Needs rear brakes job and tires rotation
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 143,397 - DH

Activity Header
Activity: 15 013/000/000 BRAKES
Activity Note: Needs rear brakes job
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Sep-18	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	48.89	48.89

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Gaspard,Ronald	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	48.89
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.89**

Work Order Footer

Work Order 51696780 Total	
Parts:	48.89
Labor:	0.00
Labor Hours:	2.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**48.89**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51505566
Invoice No. 55345 - 51505566

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	139,052 - DH

Chronology		
Reported	Aug 9, 2018 11:32:52 AM	Aug 9, 2018 11:32:52 AM
Started	Aug 10, 2018 12:00:00 AM	
Completed	Aug 10, 2018 7:50:00 AM	Aug 10, 2018 7:50:00 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pmA service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Parts. Engine oil filter
engine oil. 5W20

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RAURODRIGUEZ Performed on: 10-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,100 - Safety Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,170 - Check Fast Idle	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,180 - Check Starter Protection Circuit	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
10,190 - Check Reverse Warning System	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,100 - Check Parking Brake	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,150 - Perform Brake Test	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,170 - FRA Check Door Operation	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,210 - Check Condition of Operator's Area	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,240 - FRA Check Interior Lights	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,260 - Check Stop Request System	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
22,110 - Check Emergency Hatches	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
22,120 - Check All Safety Equipment	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,310 - Check Passenger Doors	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
33,100 - Check Lights and Reflectors	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,420 - Check Hood	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,130 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,140 - FRA Check Intake System	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,180 - FRA Check for Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
50,510 - Check Entire Steering System	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,630 - Check and Record Tread Depth	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,631 - Tread Depth RF	9 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,633 - Tread Depth RRO	14 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,634 - Tread Depth RRI	14 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,635 - Tread Depth LRI	14 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,636 - Tread Depth LRO	14 32nds of an inch		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,650 - Check Sidewall Wear	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,670 - Check Dual Mating With Square	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,710 - Check Vibration Damper	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,730 - FRA Check Starter	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,770 - FRA Check Exhaust System	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,120 - Check Suspension Components	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,131 - Brake Pad Thickness LF	Inch	7mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,132 - Brake Pad Thickness RF	Inch	7mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,133 - Brake Pad Thickness LR	Inch	5mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,134 - Brake Pad Thickness RR	Inch	5mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,135 - Brake Rotor LF	Inch	39.7mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,136 - Brake Rotor RF	Inch	39.7mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,137 - Brake Rotor LR	Inch	35.6mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,138 - Brake Rotor RR	Inch	35.6mm	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,140 - FRA Check Brake Hoses	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,150 - Check King Pins	-	na	RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
80,810 - Completion of PMI Report	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RAURODRIGUEZ	Aug 10, 2018 7:48:02 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51505566
Invoice No. 55345 - 51505566

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,052 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-18	Rodriguez,Raul	1.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RAURODRIGUEZ Performed on: 10-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
101,000 - FRA Change Oil Filters	Yes		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
104,000 - Lubricate Chassis	Done		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	
108,000 - Lube all pivoting Mechanisms	-	na	RAURODRIGUEZ	Aug 10, 2018 7:49:47 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51505566
Invoice No. 55345 - 51505566

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 139,052 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-18	Rodriguez,Raul	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 10-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Aug 10, 2018 7:50:10 AM	No	
20 - Miles			RAURODRIGUEZ	Aug 10, 2018 7:50:10 AM	No	
30 - Kilometers			RAURODRIGUEZ	Aug 10, 2018 7:50:10 AM	No	
40 - Hours			RAURODRIGUEZ	Aug 10, 2018 7:50:10 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51505566 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.95

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51575793
Invoice No. 55345 - 51575793

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs 4 new tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,498 - DH

Chronology		
Reported	Aug 6, 2018 11:49:04 PM	Aug 6, 2018 11:49:04 PM
Started	Aug 6, 2018 12:00:00 AM	
Completed	Aug 7, 2018 12:24:00 AM	Aug 7, 2018 12:24:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs 4 new tire

Cause: wear

Correction:4 new tires mounted and balance
Torque wheels 140 lbs second torque 140 lbs
Part number 189752 qty 4

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-18	Gaspard,Ronald	0.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 6, 2018 11:51:03 PM	No	
20 - Miles			RGASPARD	Aug 6, 2018 11:51:03 PM	No	
30 - Kilometers			RGASPARD	Aug 6, 2018 11:51:03 PM	No	
40 - Hours			RGASPARD	Aug 6, 2018 11:51:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51575793
Invoice No. 55345 - 51575793

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs 4 new tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	138,498 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Needs 4 new tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Aug-18	Gaspard,Ronald	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order Footer

Work Order 51575793 Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	2.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51514052
Invoice No. 55345 - 51514052

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 HEADLIGHTS		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,275 - DH

Chronology		
Reported	Jul 16, 2018 2:03:42 PM	Jul 16, 2018 2:03:42 PM
Started	Jul 16, 2018 12:00:00 AM	
Completed	Jul 16, 2018 9:17:00 PM	Jul 16, 2018 9:17:00 PM
Down Time		

Work Order Notes

Line 10 Left Front HeadLight out
Replaced left front headlight

Shop supply

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jul-18	Delva,Terry	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jul 16, 2018 2:07:20 PM	No	
20 - Miles			TDELVA	Jul 16, 2018 2:07:20 PM	No	
30 - Kilometers			TDELVA	Jul 16, 2018 2:07:20 PM	No	
40 - Hours			TDELVA	Jul 16, 2018 2:07:20 PM	No	

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.07
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51514052
Invoice No. 55345 - 51514052

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
55345 HEADLIGHTS		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	135,275 - DH

Activity Header
Activity: 20 034/001/000 HEADLAMP
Activity Note: Left Front HeadLight
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jul-18	Delva,Terry	0.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51514052 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51427075
Invoice No. 55345 - 51427075

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 134,686 - DH

Chronology		
Reported	Jul 12, 2018 5:34:25 PM	Jul 12, 2018 5:34:25 PM
Started	Jul 12, 2018 12:00:00 AM	
Completed	Jul 12, 2018 11:26:00 PM	Jul 12, 2018 11:26:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter.Lube all Pivoting Points. Check brakes. Clean batteries.replace A/ Filter
Parts# B329 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,136 - Brake Rotor RF	1.558 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,137 - Brake Rotor LR	1.653 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,138 - Brake Rotor RR	1.654 Inch		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 12, 2018 11:26:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 12, 2018 11:26:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51427075
Invoice No. 55345 - 51427075

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 134,686 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
105,000 - Replace or Clean A/C Filters	-	NA	DARTHURS	Jul 12, 2018 11:10:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 12, 2018 11:10:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Jul 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:10:05 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Jul 12, 2018 11:10:05 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Jul 12, 2018 11:10:05 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Jul 12, 2018 11:10:05 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51427075
Invoice No. 55345 - 51427075

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	134,686 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 12, 2018 11:10:31 PM	No	
20 - Miles			DARTHURS	Jul 12, 2018 11:10:31 PM	No	
30 - Kilometers			DARTHURS	Jul 12, 2018 11:10:31 PM	No	
40 - Hours			DARTHURS	Jul 12, 2018 11:10:31 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51427075 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51469027
Invoice No. 55345 - 51469027

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Left lift arm is broken.		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,032 - DH

Chronology		
Reported	Jun 28, 2018 12:12:09 PM	Jun 28, 2018 12:12:09 PM
Started	Jun 28, 2018 12:00:00 AM	
Completed	Jul 2, 2018 12:32:05 PM	Jul 2, 2018 12:32:05 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:
Lift arm is broken

Cause:
The weld broke.

Correction:
Replaced lift arm under warranty.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: PERSONAL RISK ASSESMENT Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 28-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 28, 2018 12:29:50 PM	No	
20 - Miles			EDTORRES	Jun 28, 2018 12:29:50 PM	No	
30 - Kilometers			EDTORRES	Jun 28, 2018 12:29:50 PM	No	
40 - Hours			EDTORRES	Jun 28, 2018 12:29:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51469027
Invoice No. 55345 - 51469027

Client Department:
Department: 55345M
Work Order Description
Left lift arm is broken.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 133,032 - DH

Activity Header
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-18	Torres,Edwin	1.55	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51469027 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51468587
Invoice No. 55345 - 51468587

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front Air Conditioning System		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,032 - DH

Chronology		
Reported	Jun 28, 2018 10:33:02 AM	Jun 28, 2018 10:33:02 AM
Started	Jun 28, 2018 12:00:00 AM	
Completed	Jul 2, 2018 12:21:07 PM	Jul 2, 2018 12:21:07 PM
Down Time		

Work Order Notes

Line 10 Complaint: front and rear a/c are not blowing cold air

Cause: Both orifice tube are blocked.

Correction: removed and replaced orifices tube, charged systems with Freon and oil, all okay at this time.

Parts : 2 orifice tube # 3411885.

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 28-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 28, 2018 10:44:20 AM	No	
20 - Miles			RAURODRIGUEZ	Jun 28, 2018 10:44:20 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 28, 2018 10:44:20 AM	No	
40 - Hours			RAURODRIGUEZ	Jun 28, 2018 10:44:20 AM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51468587
Invoice No. 55345 - 51468587

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front Air Conditioning System		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	133,032 - DH

Activity Header
Activity: 20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-18	Rodriguez,Raul	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51468587 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51427057
Invoice No. 55345 - 51427057

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace shifter cable		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,555 - DH

Chronology		
Reported	Jun 13, 2018 10:37:17 PM	Jun 13, 2018 10:37:17 PM
Started		
Completed	Jun 13, 2018 10:57:00 PM	Jun 13, 2018 10:57:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced
Shifter cable Qty1 part# 8C2Z-7E395-A
Air filter Qty1 part# PA4075

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 13-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 13, 2018 10:52:14 PM	No	
20 - Miles			CKARLENS	Jun 13, 2018 10:52:14 PM	No	
30 - Kilometers			CKARLENS	Jun 13, 2018 10:52:14 PM	No	
40 - Hours			CKARLENS	Jun 13, 2018 10:52:14 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51427057
Invoice No. 55345 - 51427057

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace shifter cable		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,555 - DH

Activity Header
Activity: 20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51427057
Invoice No. 55345 - 51427057

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Replace shifter cable		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	-
Assigned To:		**Driver:**	
Class:	-	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,555 - DH

Activity Header
Activity: 30 041/000/000 INTAKE, AIR
Activity Note: Replace air filter
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jun-18	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	5.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.28**

Work Order Footer

Work Order 51427057 Total	
Parts:	5.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51360911
Invoice No. 55345 - 51360911

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,555 - DH

Chronology		
Reported	Jun 13, 2018 12:00:00 AM	Jun 13, 2018 12:00:00 AM
Started	Jun 13, 2018 12:00:00 AM	
Completed	Jun 13, 2018 10:55:00 PM	Jun 13, 2018 10:55:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Preventive Maintenance

CORRECTION: Tech Performed PM-A

Parts used
Oil filter Qty:1 part#B329
Oil Qty:6.5qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 13-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,420 - Check Hood	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,137 - Brake Rotor LR	35.8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,138 - Brake Rotor RR	35.8 Inch		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Jun 13, 2018 10:21:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Jun 13, 2018 10:21:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51360911
Invoice No. 55345 - 51360911

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 130,555 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jun-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 13-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Jun 13, 2018 7:36:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Jun 13, 2018 7:36:42 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Jun 13, 2018 7:36:42 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51360911
Invoice No. 55345 - 51360911

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	130,555 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 13-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 13, 2018 7:36:09 PM	No	
20 - Miles			CKARLENS	Jun 13, 2018 7:36:09 PM	No	
30 - Kilometers			CKARLENS	Jun 13, 2018 7:36:09 PM	No	
40 - Hours			CKARLENS	Jun 13, 2018 7:36:09 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51360911 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.33

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51383019
Invoice No. 55345 - 51383019

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
REPLACE WIPER BLADES		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	126,354 - DH

Chronology		
Reported	May 30, 2018 9:43:00 PM	May 30, 2018 9:43:00 PM
Started	May 30, 2018 12:00:00 AM	
Completed	May 30, 2018 9:55:00 PM	May 30, 2018 9:55:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: REPLACE WIPER BLADES

Cause: NORMAL WEAR TEAR

Correction: REPLACE WIPER BLADES

PART# 40520 QTY 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 30-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done		AOWENS	May 30, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				9:54:40 PM		
20 - Miles			AOWENS	May 30, 2018 9:54:40 PM	No	
30 - Kilometers			AOWENS	May 30, 2018 9:54:40 PM	No	
40 - Hours			AOWENS	May 30, 2018 9:54:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51383019
Invoice No. 55345 - 51383019

Client Department:
Department: 55345M
Work Order Description
REPLACE WIPER BLADES
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 126,354 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: REPLACE WIPER BLADES
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-May-18	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.17	8.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-May-18	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order Footer

Work Order 51383019 Total	
Parts:	8.34
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.34**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51282340
Invoice No. 55345 - 51282340

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,999 - DH

Chronology		
Reported	May 17, 2018 12:00:00 AM	May 17, 2018 12:00:00 AM
Started		
Completed	May 20, 2018 1:01:00 PM	May 20, 2018 1:01:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 17-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	May 17, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:38:29 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
20,270 - Check Fare Box Mounting (If	Done		CKARLENS	May 17, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				10:38:29 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,420 - Check Hood	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,460 - Record Antifreeze Protection Level	-	na	CKARLENS	May 17, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				10:38:29 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	May 17, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:38:29 PM		
60,630 - Check and Record Tread Depth	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch	REPLACE FRONT TIRES	CKARLENS	May 17, 2018 10:38:29 PM	Yes	51355423
60,633 - Tread Depth RRO	7 32nds of an inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	May 17, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:38:29 PM		
77,120 - Check Suspension Components	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,135 - Brake Rotor LF	38.8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,136 - Brake Rotor RF	38.8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,137 - Brake Rotor LR	40.8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,138 - Brake Rotor RR	40.8 Inch		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	May 17, 2018 10:38:29 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	May 17, 2018 10:38:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51282340
Invoice No. 55345 - 51282340

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,999 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 17-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	May 17, 2018 8:30:12 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	May 17, 2018 8:30:12 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	May 17, 2018 8:30:12 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	May 17, 2018 8:30:12 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	May 17, 2018 8:30:12 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	May 17, 2018 8:30:12 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	May 17, 2018 8:30:12 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	May 17, 2018 8:30:12 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51282340
Invoice No. 55345 - 51282340

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	125,999 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 17-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 17, 2018 8:29:33 PM	No	
20 - Miles			CKARLENS	May 17, 2018 8:29:33 PM	No	
30 - Kilometers			CKARLENS	May 17, 2018 8:29:33 PM	No	
40 - Hours			CKARLENS	May 17, 2018 8:29:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51282340 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51355423
Invoice No. 55345 - 51355423

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP¿¿REPLACE FRONT TIRES
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,999 - DH

Chronology		
Reported	May 17, 2018 10:38:16 PM	May 17, 2018 10:38:16 PM
Started	May 17, 2018 12:00:00 AM	
Completed	May 18, 2018 7:38:07 AM	May 18, 2018 7:38:07 AM
Down Time		

Work Order Notes

Line 10 Tech replaced front tires
Qty:2 part#189752

Activity Header
Activity: 10 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: REPLACE FRONT TIRES
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-May-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-May-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51355423
Invoice No. 55345 - 51355423

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP¿¿REPLACE FRONT TIRES
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 125,999 - DH

Activity Header
Activity: 20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-May-18	KARLENS,Cyrius	0.3166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 17-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	May 17, 2018 10:46:31 PM	No	
20 - Miles			CKARLENS	May 17, 2018 10:46:31 PM	No	
30 - Kilometers			CKARLENS	May 17, 2018 10:46:31 PM	No	
40 - Hours			CKARLENS	May 17, 2018 10:46:31 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.32
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51355423 Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	2.32

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**206.88**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51058443
Invoice No. 55345 - 51058443

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,999 - DH

Chronology		
Reported	Apr 20, 2018 12:00:00 AM	Apr 20, 2018 12:00:00 AM
Started	Apr 24, 2018 12:00:00 AM	
Completed	Apr 24, 2018 1:51:21 PM	Apr 24, 2018 1:51:21 PM
Down Time		

Work Order Notes

Line 10 PMC
Preventive maintenance

Perform service lube all Pivoting Points cross rotate tires complete

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-18	Pierre,Hubert J	7	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 23-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,260 - Check Stop Request System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,420 - Check Hood	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,630 - Check and Record Tread Depth	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,670 - Check Dual Mating With Square	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,150 - Check King Pins	-	NA	HPIERRE	Apr 23, 2018 2:05:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Apr 23, 2018 2:05:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	7.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51058443
Invoice No. 55345 - 51058443

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 120,999 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Apr-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
24-Apr-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
24-Apr-18	20021	FILTER, TRANSMISSION 20021	1	17.24	17.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 24-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Apr 24, 2018 7:11:13 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Apr 24, 2018 7:11:13 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Apr 24, 2018 7:11:13 AM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Apr 24, 2018 7:11:13 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	25.86
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**25.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51058443
Invoice No. 55345 - 51058443

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,999 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Apr-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 24-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 24, 2018 7:12:12 AM	No	
20 - Miles			HPIERRE	Apr 24, 2018 7:12:12 AM	No	
30 - Kilometers			HPIERRE	Apr 24, 2018 7:12:12 AM	No	
40 - Hours			HPIERRE	Apr 24, 2018 7:12:12 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51058443 Total	
Parts:	25.86
Labor:	0.00
Labor Hours:	7.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**25.86**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51220656
Invoice No. 55345 - 51220656

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs driver s seat adjuster		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,268 - DH

Chronology		
Reported	Apr 12, 2018 9:18:09 PM	Apr 12, 2018 9:18:09 PM
Started	Apr 12, 2018 12:00:00 AM	
Completed	Apr 13, 2018 9:39:08 AM	Apr 13, 2018 9:39:08 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs driver s seat adjuster

Cause: broken

Correction:replaced driver seat adjuster
Part number 1014651 qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Apr 12, 2018 9:21:19 PM	No	
20 - Miles			RGASPARD	Apr 12, 2018 9:21:19 PM	No	
30 - Kilometers			RGASPARD	Apr 12, 2018 9:21:19 PM	No	
40 - Hours			RGASPARD	Apr 12, 2018 9:21:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51220656
Invoice No. 55345 - 51220656

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs driver s seat adjuster		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	120,268 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-18	1014651	OUT OF SERVICE LEVER, RECLINER, SEAT, FORD W/SPACER	1	2.23	2.23

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	Gaspard,Ronald	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	2.23
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.23**

Work Order Footer

Work Order 51220656 Total	
Parts:	2.23
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**2.23**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51140895
Invoice No. 55345 - 51140895

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Passenger side head light is out		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	118,716 - DH

Chronology		
Reported	Mar 28, 2018 9:14:38 AM	Mar 28, 2018 9:14:38 AM
Started	Mar 28, 2018 12:00:00 AM	
Completed	Mar 28, 2018 12:22:00 PM	Mar 28, 2018 12:22:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

COMPLAINT:
Passenger side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced passenger side headlight bulb.

PARTS:
Shop supply.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 28-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Mar 28, 2018 9:27:41 AM	No	
20 - Miles			RAURODRIGUEZ	Mar 28, 2018 9:27:41 AM	No	
30 - Kilometers			RAURODRIGUEZ	Mar 28, 2018 9:27:41 AM	No	
40 - Hours			RAURODRIGUEZ	Mar 28, 2018 9:27:41 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51140895
Invoice No. 55345 - 51140895

Client Department:
Department: 55345M
Work Order Description
Passenger side head light is out
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 118,716 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: Passenger side head light is out
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Mar-18	Rodriguez,Raul	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51140895 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51114133
Invoice No. 55345 - 51114133

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
R/f head light is out		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	118,254 - DH

Chronology		
Reported	Mar 22, 2018 10:49:23 AM	Mar 22, 2018 10:49:23 AM
Started	Mar 22, 2018 12:00:00 AM	
Completed	Mar 22, 2018 11:58:31 AM	Mar 22, 2018 11:58:31 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:r/f Head Light is out

Cause: bulb is burn

Correction:replaced bulb

Part: 1 Bulb 9008

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 22-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 22, 2018 10:58:42 AM	No	
20 - Miles			JAPEREZ	Mar 22, 2018 10:58:42 AM	No	
30 - Kilometers			JAPEREZ	Mar 22, 2018 10:58:42 AM	No	
40 - Hours			JAPEREZ	Mar 22, 2018 10:58:42 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51114133
Invoice No. 55345 - 51114133

Client Department:
Department: 55345M
Work Order Description
R/f head light is out
Requested By: JAPEREZ
Created By: JAPEREZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 118,254 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note: R/f head light is out
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-18	Perez,Javier	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51114133 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51065981
Invoice No. 55345 - 51065981

Client Department:
Department: 55345M
Work Order Description
Follow up------>{51018040}Vehicle need shifter cable and air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,958 - DH

Chronology		
Reported	Feb 27, 2018 11:37:26 PM	Feb 27, 2018 11:37:26 PM
Started	Feb 27, 2018 12:00:00 AM	
Completed	Feb 28, 2018 12:01:00 AM	Feb 28, 2018 12:01:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint: vehicle needed shifter cable and air filter

Cause: wear and tear

Correction:tech replaced damaged items

Part used
Shifter cable. Qty:1 part number 8C2Z-7E395-A
Air filter Qty:1 part number PA4075

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 28-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Feb 28, 2018 12:23:44 AM	No	
20 - Miles			CKARLENS	Feb 28, 2018 12:23:44 AM	No	
30 - Kilometers			CKARLENS	Feb 28, 2018 12:23:44 AM	No	
40 - Hours			CKARLENS	Feb 28, 2018 12:23:44 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51065981
Invoice No. 55345 - 51065981

Client Department:
Department: 55345M
Work Order Description
Follow up------>{51018040}Vehicle need shifter cable and air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,958 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: Replace shifter cable
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Feb-18	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	44.69	44.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	44.69
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**44.69**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51065981
Invoice No. 55345 - 51065981

Client Department:
Department: 55345M
Work Order Description
Follow up------>{51018040}Vehicle need shifter cable and air filter
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,958 - DH

Activity Header
Activity:25 050/000 GROUP, ACCESSORIES
Activity Note: Replace air filter
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Feb-18	PA4075	FILTER, AIR SEE P546597	1	5.25	5.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-18	KARLENS,Cyrius	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	5.25
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.25**

Work Order Footer

Work Order 51065981 Total	
Parts:	49.94
Labor:	0.00
Labor Hours:	2.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**49.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51057993
Invoice No. 55345 - 51057993

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs front brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,494 - DH

Chronology		
Reported	Feb 22, 2018 11:51:54 PM	Feb 22, 2018 11:51:54 PM
Started	Feb 22, 2018 12:00:00 AM	
Completed	Feb 23, 2018 9:07:00 AM	Feb 23, 2018 9:07:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs front brakes job

Cause: wear and cease guide pins

Correction:replaced front brake pads cleaned and lubed guide pins
Part number BRSD1328 qty1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 22, 2018 11:53:39 PM	No	
20 - Miles			RGASPARD	Feb 22, 2018 11:53:39 PM	No	
30 - Kilometers			RGASPARD	Feb 22, 2018 11:53:39 PM	No	
40 - Hours			RGASPARD	Feb 22, 2018 11:53:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51057993
Invoice No. 55345 - 51057993

Client Department:
Department: 55345M
Work Order Description
Needs front brakes job
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,494 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-18	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	51.66	51.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-18	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	51.66
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.66**

Work Order Footer

Work Order 51057993 Total	
Parts:	51.66
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**51.66**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 51009176
Invoice No. 55345 - 51009176

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,494 - DH

Chronology		
Reported	Feb 22, 2018 11:52:50 AM	Feb 22, 2018 11:52:50 AM
Started	Feb 22, 2018 12:00:00 AM	
Completed	Feb 23, 2018 9:02:19 AM	Feb 23, 2018 9:02:19 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform pmA Service
Oil filter B329 qty1
Engine oil 5w20 qty 7 Qts
Replaced left side clearance light qty1

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-18	Gaspard,Ronald	1.5833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Feb 22, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:47:51 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 22, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:47:51 PM		
20,260 - Check Stop Request System	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,442 - Freeze Point	Degree	NA	RGASPARD	Feb 22, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:47:51 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Feb 22, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:47:51 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Feb 22, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:47:51 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,132 - Brake Pad Thickness RF	3 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Feb 22, 2018 11:47:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 22, 2018 11:47:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 51009176
Invoice No. 55345 - 51009176

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CKARLENS	**Status:**	40 - Closed (40)
Created By:	CKARLENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,494 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-18	Gaspard,Ronald	1.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 22, 2018 11:48:29 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 22, 2018 11:48:29 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 22, 2018 11:48:29 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 22, 2018 11:48:29 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Feb 22, 2018 11:48:29 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 22, 2018 11:48:29 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Feb 22, 2018 11:48:29 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 22, 2018 11:48:29 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.18
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 51009176
Invoice No. 55345 - 51009176

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CKARLENS
Created By: CKARLENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 116,494 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-18	Gaspard,Ronald	0.2166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 22, 2018 11:48:48 PM	No	
20 - Miles			RGASPARD	Feb 22, 2018 11:48:48 PM	No	
30 - Kilometers			RGASPARD	Feb 22, 2018 11:48:48 PM	No	
40 - Hours			RGASPARD	Feb 22, 2018 11:48:48 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.22
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 51009176 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.98

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.96**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 51057999
Invoice No. 55345 - 51057999

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,494 - DH

Chronology		
Reported	Feb 22, 2018 11:57:09 PM	Feb 22, 2018 11:57:09 PM
Started	Feb 23, 2018 12:00:00 AM	
Completed	Feb 23, 2018 7:32:00 AM	Feb 23, 2018 7:32:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

==========

Complaint:needs rear brakes job

Cause: wear , cease guide pins

Correction:replace brake pads cleaned and lubed pins
Part number BRSD1330 B qty1
Torque wheels 140 lbs second torque 140 lbs

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Feb-18	Gaspard,Ronald	0.1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 22, 2018 11:58:27 PM	No	
20 - Miles			RGASPARD	Feb 22, 2018 11:58:27 PM	No	
30 - Kilometers			RGASPARD	Feb 22, 2018 11:58:27 PM	No	
40 - Hours			RGASPARD	Feb 22, 2018 11:58:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 51057999
Invoice No. 55345 - 51057999

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	116,494 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Feb-18	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.9	43.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Feb-18	Gaspard,Ronald	2.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	43.90
Labor:	0.00
Labor Hours:	2.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.90**

Work Order Footer

Work Order 51057999 Total	
Parts:	43.90
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.90**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 50957167
Invoice No. 55345 - 50957167

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,313 - DH

Chronology		
Reported	Jan 25, 2018 10:35:01 AM	Jan 25, 2018 10:35:01 AM
Started	Jan 25, 2018 12:00:00 AM	
Completed	Jan 25, 2018 11:43:00 PM	Jan 25, 2018 11:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PM-A

CAUSE: Preventive maintenance

CORRECTION: Tech Performed PM-A

Part used
Oil Qty:6qts
Oil filter Qty:1 part#B329
Air filter Qty:1 part#PA4075

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Jan-18	PA4075	FILTER, AIR SEE P546597	1	5.18	5.18
25-Jan-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-18	KARLENS,Cyrius	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 25-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,420 - Check Hood	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,612 - Air Pressure LF	65 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Jan 25, 2018 9:52:48 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Jan 25, 2018 9:52:48 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 50957167
Invoice No. 55345 - 50957167

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 112,313 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-18	KARLENS,Cyrius	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: CKARLENS Performed on: 25-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Jan 25, 2018 7:34:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	CKARLENS	Jan 25, 2018 7:34:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Jan 25, 2018 7:34:56 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 50957167
Invoice No. 55345 - 50957167

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	112,313 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-18	KARLENS,Cyrius	0.2833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 25-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jan 25, 2018 7:34:17 PM	No	
20 - Miles			CKARLENS	Jan 25, 2018 7:34:17 PM	No	
30 - Kilometers			CKARLENS	Jan 25, 2018 7:34:17 PM	No	
40 - Hours			CKARLENS	Jan 25, 2018 7:34:17 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50957167 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	5.28

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 50968117
Invoice No. 55345 - 50968117

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine is stalling		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,824 - DH

Chronology		
Reported	Dec 28, 2017 1:01:04 PM	Dec 28, 2017 1:01:04 PM
Started	Dec 28, 2017 12:00:00 AM	
Completed	Jan 9, 2018 9:20:00 AM	Jan 9, 2018 9:20:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: vehicle is stalling

CAUSE: check engine found fuel pump low pressure

CORRECTION: replace fuel pump, retest system ok at this time

Parts:
1 p15gd-fpkitt-aa

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 08-JAN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jan 8, 2018 3:45:37 PM	No	
20 - Miles			JAPEREZ	Jan 8, 2018 3:45:37 PM	No	
30 - Kilometers			JAPEREZ	Jan 8, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:45:37 PM		
40 - Hours			JAPEREZ	Jan 8, 2018 3:45:37 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 50968117
Invoice No. 55345 - 50968117

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine is stalling		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	**Status:**	40 - Closed (40)
Created By:	JAPEREZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,824 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Engine is stalling
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-17	P15GD-FPKITT-AA	PUMP, FUEL, ROUSH	1	414.31	414.31

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Dec-17	Perez,Javier	3.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	414.31
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**414.31**

Work Order Footer

Work Order 50968117 Total	
Parts:	414.31
Labor:	0.00
Labor Hours:	3.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**414.31**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 48175047
Invoice No. 55345 - 48175047

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	108,253 - DH

Chronology		
Reported	Dec 19, 2017 2:30:01 PM	Dec 19, 2017 2:30:01 PM
Started	Dec 19, 2017 12:00:00 AM	
Completed	Dec 19, 2017 11:28:00 PM	Dec 19, 2017 11:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil& Filter .Lube all Pivoting Points .Check Brakes. clean batteries
Parts# B329 Qty (1)
Oil5W20 Qty (7) Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 19-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:04:28 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:04:28 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	-	Wiper blade	DARTHURS	Dec 19, 2017 11:04:28 PM	Yes	50957139
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,420 - Check Hood	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:04:28 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:04:28 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,634 - Tread Depth RRI	4 32nds of an inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	RearTires	DARTHURS	Dec 19, 2017 11:04:28 PM	Yes	50957139
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:04:28 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,135 - Brake Rotor LF	1.559 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,137 - Brake Rotor LR	1.655 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,138 - Brake Rotor RR	1.657 Inch		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Dec 19, 2017 11:04:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Dec 19, 2017 11:04:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 48175047
Invoice No. 55345 - 48175047

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,253 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 19-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Dec 19, 2017 11:05:54 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Dec 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				11:05:54 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Dec 19, 2017 11:05:54 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Dec 19, 2017 11:05:54 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Dec 19, 2017 11:05:54 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 48175047
Invoice No. 55345 - 48175047

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,253 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 19, 2017 11:06:22 PM	No	
20 - Miles			DARTHURS	Dec 19, 2017 11:06:22 PM	No	
30 - Kilometers			DARTHURS	Dec 19, 2017 11:06:22 PM	No	
40 - Hours			DARTHURS	Dec 19, 2017 11:06:22 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 48175047 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 50957139
Invoice No. 55345 - 50957139

Client Department:
Department: 55345M
Work Order Description
PMB Follow up <<<<<<<<<Rear Tires& Wiper blades
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,253 - DH

Chronology		
Reported	Dec 19, 2017 11:04:28 PM	Dec 19, 2017 11:04:28 PM
Started	Dec 19, 2017 12:00:00 AM	
Completed	Dec 19, 2017 11:25:00 PM	Dec 19, 2017 11:25:00 PM
Down Time		

Work Order Notes

Line 10 Mount&Balance Rear Tire /Replace on rear& Replace wiper Blades.
Parts# 189752 Qty (4)
Parts#40520 Qty (2)

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: RearTires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	413.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**413.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 50957139
Invoice No. 55345 - 50957139

Client Department:
Department: 55345M
Work Order Description
PMB Follow up <<<<<<<<<Rear Tires& Wiper blades
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,253 - DH

Activity Header
Activity:20 002/035 WIPER & WASHER, WINDSHIELD
Activity Note: Wiper blade
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-17	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.28	8.56

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.56
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.56**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 50957139
Invoice No. 55345 - 50957139

Client Department:
Department: 55345M
Work Order Description
PMB Follow up <<<<<<<<<Rear Tires& Wiper blades
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 108,253 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 19, 2017 11:14:39 PM	No	
20 - Miles			DARTHURS	Dec 19, 2017 11:14:39 PM	No	
30 - Kilometers			DARTHURS	Dec 19, 2017 11:14:39 PM	No	
40 - Hours			DARTHURS	Dec 19, 2017 11:14:39 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 50957139 Total	
Parts:	422.32
Labor:	0.00
Labor Hours:	2.17

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**422.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4

Work Order No. 44212550
Invoice No. 55345 - 44212550

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,177 - DH

Chronology		
Reported	Nov 14, 2017 10:40:49 PM	Nov 14, 2017 10:40:49 PM
Started	Nov 14, 2017 12:00:00 AM	
Completed	Nov 14, 2017 11:28:00 PM	Nov 14, 2017 11:28:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage.

CORRECTION: Change oil & Filter Lube all Pivoting Points check brakes. Replace A/C Filter Clean batteries.
Parts # B329 Qty (1)
Oil 5W20 Qty (7)Qt

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 14-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,420 - Check Hood	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,632 - Tread Depth LF	2 32nds of an inch	Front Tire	DARTHURS	Nov 14, 2017 11:11:43 PM	Yes	48173887
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,135 - Brake Rotor LF	1.5568 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,136 - Brake Rotor RF	1.5569 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,137 - Brake Rotor LR	1.642 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,138 - Brake Rotor RR	1.646 Inch		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Nov 14, 2017 11:11:43 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Nov 14, 2017 11:11:43 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 48173887
Invoice No. 55345 - 48173887

Client Department:
Department: 55345M
Work Order Description
PMA Follow up <<<<<<<< Front tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,177 - DH

Chronology		
Reported	Nov 14, 2017 11:11:43 PM	Nov 14, 2017 11:11:43 PM
Started	Nov 14, 2017 12:00:00 AM	
Completed	Nov 14, 2017 11:28:00 PM	Nov 14, 2017 11:28:00 PM
Down Time		

Work Order Notes

Line 10 Mount&Balance both front Tire & Replace on Front.
Parts# 189752 Qty (2)

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Front Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	106.72	213.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	213.44
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**213.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4

Work Order No. 44212550
Invoice No. 55345 - 44212550

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,177 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 14-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Nov 14, 2017 11:13:22 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Nov 14, 2017 11:13:22 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Nov 14, 2017 11:13:22 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Nov 14, 2017 11:13:22 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Nov 14, 2017 11:13:22 PM	No	
105,000 - Replace or Clean A/C Filters	Done	Replace A/C Filter	DARTHURS	Nov 14, 2017 11:13:22 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Nov 14, 2017 11:13:22 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Nov 14, 2017 11:13:22 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 48173887
Invoice No. 55345 - 48173887

Client Department:
Department: 55345M
Work Order Description
PMA Follow up <<<<<<<< Front tires
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 104,177 - DH

Activity Header
Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 14, 2017 11:22:21 PM	No	
20 - Miles			DARTHURS	Nov 14, 2017 11:22:21 PM	No	
30 - Kilometers			DARTHURS	Nov 14, 2017 11:22:21 PM	No	
40 - Hours			DARTHURS	Nov 14, 2017 11:22:21 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 48173887 Total	
Parts:	213.44
Labor:	0.00
Labor Hours:	1.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**213.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4

Work Order No. 44212550
Invoice No. 55345 - 44212550

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,177 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 14, 2017 11:13:45 PM	No	
20 - Miles			DARTHURS	Nov 14, 2017 11:13:45 PM	No	
30 - Kilometers			DARTHURS	Nov 14, 2017 11:13:45 PM	No	
40 - Hours			DARTHURS	Nov 14, 2017 11:13:45 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4

Work Order No. 44212550
Invoice No. 55345 - 44212550

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	AOWENS	**Status:**	40 - Closed (40)
Created By:	AOWENS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	104,177 - DH

Activity Header
Activity: 40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 44212550 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 46368874
Invoice No. 55345 - 46368874

Client Department:
Department: 55345M
Work Order Description
Vehicle involved in accident. Damage to passenger side.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 101,477 - DH

Chronology		
Reported	Oct 27, 2017 8:03:26 AM	Oct 27, 2017 8:03:26 AM
Started	Oct 27, 2017 12:00:00 AM	
Completed	Oct 27, 2017 8:48:00 AM	Oct 27, 2017 8:48:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Vehicle involved in accident. Damage to passenger side.

CAUSE:
Driver hit a pole

CORRECTION:
Replaced panel around the battery compartment and replaced frame for the battery door. David k. Painted panel.

Parts
Body Panel Line 20 SHEET METAL PANEL PART 4342879

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 27-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Oct 27, 2017 8:07:48 AM	No	
20 - Miles			EDTORRES	Oct 27, 2017 8:07:48 AM	No	
30 - Kilometers			EDTORRES	Oct 27, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:07:48 AM		
40 - Hours			EDTORRES	Oct 27, 2017 8:07:48 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 46368874
Invoice No. 55345 - 46368874

Client Department:
Department: 55345M
Work Order Description
Vehicle involved in accident. Damage to passenger side.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 101,477 - DH

Activity Header
Activity: 15 999 TOTAL VEHICLE
Activity Note: Vehicle involved in accident. Damage to passenger side.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Oct-17	4342879	OUT OF SERVICE PANEL, BUMPER, REAR	18	17.04	306.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-17	Torres,Edwin	5.2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	306.72
Labor:	0.00
Labor Hours:	5.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**306.72**

Work Order Footer

Work Order 46368874 Total	
Parts:	306.72
Labor:	0.00
Labor Hours:	5.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**306.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 46197604
Invoice No. 55345 - 46197604

Client Department:
Department: 55345M
Work Order Description
Driver bus loose power while driving
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 101,477 - DH

Chronology		
Reported	Oct 25, 2017 11:28:35 AM	Oct 25, 2017 11:28:35 AM
Started	Oct 25, 2017 12:00:00 AM	
Completed	Oct 25, 2017 11:52:00 AM	Oct 25, 2017 11:52:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver bus loose power while driving

CAUSE: checking system bad alternator

CORRECTION: replace alternator and checking charging system good completed
Patt# GC2Z-10346-Bqty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 25-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 25, 2017 11:43:40 AM	No	
20 - Miles			HPIERRE	Oct 25, 2017 11:43:40 AM	No	
30 - Kilometers			HPIERRE	Oct 25, 2017 11:43:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			HPIERRE	Oct 25, 2017 11:43:40 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 46197604
Invoice No. 55345 - 46197604

Client Department:
Department: 55345M
Work Order Description
Driver bus loose power while driving
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 101,477 - DH

Activity Header
Activity: 15 031/002/001 REGULATOR, VOLTAGE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Oct-17	GC2Z-10346-B	ALTERNATOR, E450	1	345.97	345.97

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Oct-17	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	345.97
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**345.97**

Work Order Footer

Work Order 46197604 Total	
Parts:	345.97
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**345.97**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 38045036
Invoice No. 55345 - 38045036

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,948 - DH

Chronology		
Reported	Oct 4, 2017 1:26:31 PM	Oct 4, 2017 1:26:31 PM
Started	Oct 5, 2017 12:00:00 AM	
Completed	Oct 5, 2017 12:36:00 AM	Oct 5, 2017 12:36:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter Lube .all Pivoting Points. Check brakes Clean batteries,
Parts# B329 Qty (1)
Oil 5W20 Qty (7) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 05-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,100 - Safety Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,420 - Check Hood	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,632 - Tread Depth LF	7 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,135 - Brake Rotor LF	1.559 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,136 - Brake Rotor RF	1.558 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,137 - Brake Rotor LR	1.623 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,138 - Brake Rotor RR	1.632 Inch		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Oct 5, 2017 12:19:27 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Oct 5, 2017 12:19:27 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 38045036
Invoice No. 55345 - 38045036

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,948 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 05-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Oct 5, 2017 12:20:12 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Oct 5, 2017 12:20:12 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Oct 5, 2017 12:20:12 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 38045036
Invoice No. 55345 - 38045036

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 99,948 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 5, 2017 12:20:34 AM	No	
20 - Miles			DARTHURS	Oct 5, 2017 12:20:34 AM	No	
30 - Kilometers			DARTHURS	Oct 5, 2017 12:20:34 AM	No	
40 - Hours			DARTHURS	Oct 5, 2017 12:20:34 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 38045036 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 43617252
Invoice No. 55345 - 43617252

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	99,330 - DH

Chronology		
Reported	Sep 28, 2017 8:25:51 PM	Sep 28, 2017 8:25:51 PM
Started	Sep 28, 2017 12:00:00 AM	
Completed	Sep 29, 2017 12:07:00 AM	Sep 29, 2017 12:07:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Rear A/C blown Hot Air

CAUSE:Bad rear A/C Circuit board relay.

CORRECTION: Remove& Replace rear A/C Circuit board and check A/C Pressure all is ok at this time.
Parts under warranty .Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 29, 2017 12:06:36 AM	No	
20 - Miles			DARTHURS	Sep 29, 2017 12:06:36 AM	No	
30 - Kilometers			DARTHURS	Sep 29, 2017 12:06:36 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Sep 29, 2017 12:06:36 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 43617252
Invoice No. 55345 - 43617252

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	99,330 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove&Replace Rear A/C Circuit board
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Sep-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 43617252 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 42270578
Invoice No. 55345 - 42270578

Client Department:
Department: 55345M
Work Order Description
Rear A/C Fans
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 98,449 - DH

Chronology		
Reported	Sep 15, 2017 3:17:54 PM	Sep 15, 2017 3:17:54 PM
Started	Sep 15, 2017 12:00:00 AM	
Completed	Sep 15, 2017 4:11:00 PM	Sep 15, 2017 4:11:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Preventive Maintenance

CAUSE: Change Rear A/C Fans

CORRECTION: Replaced Rear A/C "both" Fans (2)
Parts Used : Under Warranty

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-17	Delva,Terry	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Sep 15, 2017 4:10:29 PM	No	
20 - Miles			TDELVA	Sep 15, 2017 4:10:29 PM	No	
30 - Kilometers			TDELVA	Sep 15, 2017 4:10:29 PM	No	
40 - Hours			TDELVA	Sep 15, 2017 4:10:29 PM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 42270578
Invoice No. 55345 - 42270578

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C Fans		Ford E450 Champion Challenger	
Requested By:	TDELVA	**Status:**	40 - Closed (40)
Created By:	TDELVA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	98,449 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note: Rear A/C Fans
Reason for Repair: 05 Inspection, Routine
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-17	Delva,Terry	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

15 Desc: Rear A/C Fans
Task: ELECTRICAL SYSTEM Performed by: TDELVA Performed on: 15-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - A/C SYSTEM CHECK	Done		TDELVA	Sep 15, 2017 4:10:57 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 42270578 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 39912817
Invoice No. 55345 - 39912817

Client Department:
Department: 55345M
Work Order Description
The shock for one of the wheelchair doors came off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 97,746 - DH

Chronology		
Reported	Aug 22, 2017 6:45:01 AM	Aug 22, 2017 6:45:01 AM
Started	Aug 22, 2017 12:00:00 AM	
Completed	Aug 22, 2017 12:16:00 PM	Aug 22, 2017 12:16:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Front Lift door shock absorber inner bracket came off rivets.

CAUSE:
Unknown.

CORRECTION:
Drilled out bad rivets. Mounted shock absorber bracket back onto door frame by inserting new rivets.

Parts

No parts used.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 22-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Aug 22, 2017 6:49:09 AM	No	
20 - Miles			EDTORRES	Aug 22, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:49:09 AM		
30 - Kilometers			EDTORRES	Aug 22, 2017 6:49:09 AM	No	
40 - Hours			EDTORRES	Aug 22, 2017 6:49:09 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 39912817
Invoice No. 55345 - 39912817

Client Department:
Department: 55345M
Work Order Description
The shock for one of the wheelchair doors came off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 97,746 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: The shock for one of the wheelchair doors came off.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Aug-17	Torres,Edwin	0.6166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 39912817 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34991587
Invoice No. 55345 - 34991587

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,930 - DH

Chronology		
Reported	Aug 2, 2017 2:19:52 PM	Aug 2, 2017 2:19:52 PM
Started	Aug 2, 2017 12:00:00 AM	
Completed	Aug 2, 2017 9:47:00 PM	Aug 2, 2017 9:47:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service ,Change Oil & Filter Lube all Pivoting Points Check brakes , clean batteries.Perform Transmission Service. Change Fluid & Filter . Perform differential Service, drain /Fill differential.
Parts# B329 Qty (1)
Parts# 20021 Qty (1)
Oil5W20 Qty (7) Qts
ATF Fluid Qty (10) Qts
Gear Oil 80W90 Qty (3) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-17	Arthurs,Durvin	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 02-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,420 - Check Hood	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,133 - Brake Pad Thickness LR	11 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,134 - Brake Pad Thickness RR	11 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,135 - Brake Rotor LF	1.559 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,136 - Brake Rotor RF	1.561 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,137 - Brake Rotor LR	1.645 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,138 - Brake Rotor RR	1.65 Inch		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Aug 2, 2017 8:37:21 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Aug 2, 2017 8:37:21 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34991587
Invoice No. 55345 - 34991587

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,930 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Aug-17	20021	FILTER, TRANSMISSION 20021	1	13.68	13.68
02-Aug-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: DARTHURS Performed on: 02-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Aug 2, 2017 8:39:44 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Aug 2, 2017 8:39:44 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Aug 2, 2017 8:39:44 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Aug 2, 2017 8:39:44 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		DARTHURS	Aug 2, 2017 8:39:44 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Aug 2, 2017 8:39:44 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	15.60
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34991587
Invoice No. 55345 - 34991587

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 95,930 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 02-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 2, 2017 8:40:14 PM	No	
20 - Miles			DARTHURS	Aug 2, 2017 8:40:14 PM	No	
30 - Kilometers			DARTHURS	Aug 2, 2017 8:40:14 PM	No	
40 - Hours			DARTHURS	Aug 2, 2017 8:40:14 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34991587 Total	
Parts:	15.60
Labor:	0.00
Labor Hours:	3.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**15.60**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 36652775
Invoice No. 55345 - 36652775

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Scheduled		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	94,018 - DH

Chronology		
Reported	Jul 19, 2017 7:39:38 AM	Jul 19, 2017 7:39:38 AM
Started	Jul 19, 2017 12:00:00 AM	
Completed	Jul 19, 2017 8:33:00 AM	Jul 19, 2017 8:33:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said front A/C not working

CAUSE: evaporator leak

CORRECTION: replace evaporator orifice tube vacuum and recharge completed
Orifice tube # 3411885 qty 1
Evaporate # Yk211 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 19, 2017 7:46:54 AM	No	
20 - Miles			HPIERRE	Jul 19, 2017 7:46:54 AM	No	
30 - Kilometers			HPIERRE	Jul 19, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:46:54 AM		
40 - Hours			HPIERRE	Jul 19, 2017 7:46:54 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 36652775
Invoice No. 55345 - 36652775

Client Department:
Department: 55345M
Work Order Description
Scheduled
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 94,018 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Jul-17	YK211	CORE, EVAPORATOR, A/C	1	150.45	150.45
19-Jul-17	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-17	Pierre,Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
15 Desc: Task: ELECTRICAL SYSTEM Performed by: HPIERRE Performed on: 19-JUL-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - A/C SYSTEM CHECK	Done		HPIERRE	Jul 19, 2017 7:46:33 AM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order Footer

Work Order 36652775 Total	
Parts:	151.20
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**151.20**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 35343444
Invoice No. 55345 - 35343444

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lean condition		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	92,813 - DH

Chronology		
Reported	Jul 5, 2017 12:20:14 PM	Jul 5, 2017 12:20:14 PM
Started	Jul 5, 2017 12:00:00 AM	
Completed	Jul 7, 2017 8:31:00 AM	Jul 7, 2017 8:31:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Engine warning light on

CAUSE:Defective O2sensors

CORRECTION: O2 sensors replacement

Two (2) front o2 sensors changed

Parts used
One (1) O2sensor#DY1193
One (1) O2 sensor#DY1185

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 7, 2017 7:58:20 AM	No	
20 - Miles			FSIMON	Jul 7, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:58:20 AM		
30 - Kilometers			FSIMON	Jul 7, 2017 7:58:20 AM	No	
40 - Hours			FSIMON	Jul 7, 2017 7:58:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 35343444
Invoice No. 55345 - 35343444

Client Department:
Department: 55345M
Work Order Description
Lean condition
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,813 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-17	DY1193	SENSOR, OXYGEN	1	84.57	84.57
05-Jul-17	DY1185	SENSOR, OXYGEN, UPSTREAM, F550	1	109.25	109.25

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	193.82
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.82**

Work Order Footer

Work Order 35343444 Total	
Parts:	193.82
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**193.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34996821
Invoice No. 55345 - 34996821

Client Department:
Department: 55345M
Work Order Description
REPLACE WINDSHIELD WIPERS
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,244 - DH

Chronology		
Reported	Jun 28, 2017 7:58:00 PM	Jun 28, 2017 7:58:00 PM
Started	Jun 28, 2017 12:00:00 AM	
Completed	Jun 28, 2017 8:04:00 PM	Jun 28, 2017 8:04:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: WINDSHELD WIPERS NEEDS REPLACE

CAUSE:NORMAL USAGE

CORRECTION: REPLACE BOTH WINDSHIELD WIPER BLADES
PARTS# 40520 QTY 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-17	Owens,Arthur	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 28-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jun 28, 2017 8:03:20 PM	No	
20 - Miles			AOWENS	Jun 28, 2017 8:03:20 PM	No	
30 - Kilometers			AOWENS	Jun 28, 2017 8:03:20 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			AOWENS	Jun 28, 2017 8:03:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34996821
Invoice No. 55345 - 34996821

Client Department:
Department: 55345M
Work Order Description
REPLACE WINDSHIELD WIPERS
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 92,244 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE WINDSHIELD WIPER BLADES
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-17	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.41	8.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-17	Owens,Arthur	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	8.82
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.82**

Work Order Footer

Work Order 34996821 Total	
Parts:	8.82
Labor:	0.00
Labor Hours:	0.70
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.82**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34872205
Invoice No. 55345 - 34872205

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 91,915 - DH

Chronology		
Reported	Jun 23, 2017 7:54:06 AM	Jun 23, 2017 7:54:06 AM
Started	Jun 23, 2017 12:00:00 AM	
Completed	Jun 26, 2017 8:07:00 AM	Jun 26, 2017 8:07:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: perform service lube all pivoting points cross rotate tires completed
Part #B329qty1
Oil5w20 Qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Pierre,Hubert J	4	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done				No	
10,100 - Safety Inspection	Done				No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
& Authorization Forms						
10,120 - FRA Check All Warning Lights and Alarms	Done				No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done				No	
10,140 - Check Service Brakes	Done				No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done				No	
10,160 - FRA Check Instruments and Horns	Done				No	
10,170 - Check Fast Idle	Done				No	
10,180 - Check Starter Protection Circuit	Done				No	
10,190 - Check Reverse Warning System	Done				No	
11,100 - Check Parking Brake	Done				No	
11,110 - Check HVAC Switches and Other Controls	Done				No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done				No	
11,130 - FRA Check Wiper and Washer Operation	Done				No	
11,140 - Road Test: Check for Proper Operation	Done				No	
11,150 - Perform Brake Test	Done				No	
11,152 - Decelerometer Results Test 1	FEET	N/A			No	
11,154 - Decelerometer Results Test 2	FEET	N/A			No	
11,156 - Decelerometer Results Test 3	FEET	N/A			No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A			No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A			No	
11,170 - FRA Check Door Operation	Done				No	
11,180 - FRA Check Operation of All Other Accessories	Done				No	
20,000 - SECTION 2 Interior Circle Inspection	Done				No	
20,210 - Check Condition of Operator's Area	Done				No	
20,220 - Check Accelerator and Brake Pedals	Done				No	
20,230 - FRA Check Wiring Under Dash	Done				No	
20,240 - FRA Check Interior Lights	Done				No	
20,250 - FRA Check Interior Electrical Panels	Done				No	
20,260 - Check Stop Request System	-	N/A			No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A			No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done				No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done				No	
22,100 - Check Emergency Windows and Glass Condition	Done				No	
22,110 - Check Emergency Hatches	Done				No	
22,120 - Check All Safety Equipment	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30,000 - SECTION 3 Exterior Circle Inspection	Done				No	
30,310 - Check Passenger Doors	Done				No	
30,320 - Inspect Step-well and Hand Rails	Done				No	
30,330 - Check Wheelchair Lift Operation	Done				No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A			No	
30,350 - FRA Inspect Mirror and Mountings	Done				No	
30,360 - Check for Physical Damage and Decals	Done				No	
30,370 - Check Wiper Blade and Arm Condition	Done				No	
30,380 - Check Exterior Compartment Doors	Done				No	
30,390 - FRA Check Fuel Tank Cap	Done				No	
33,100 - Check Lights and Reflectors	Done				No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done				No	
40,000 - SECTION 4 Engine Compartment Inspection	Done				No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done				No	
40,420 - Check Hood	Done				No	
40,430 - Check Fan, Shroud and Radiator	Done				No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A			No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A			No	
40,442 - Freeze Point	Degree Fahrenheit	N/A			No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done				No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A			No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A			No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done				No	
40,480 - FRA Check Coolant Hose Condition	Done				No	
40,490 - FRA Check Alternator Mount and Condition	Done				No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done				No	
44,110 - FRA Check Master Cylinder Fluid Level	Done				No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done				No	
44,130 - FRA Check Exhaust System	Done				No	
44,140 - FRA Check Intake System	Done				No	
44,150 - FRA Inspect Turbocharger	-	N/A			No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done				No	
44,170 - FRA Check All Engine or Belt Driven Components	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
44,180 - FRA Check for Leaks	Done				No	
44,190 - FRA Perform Battery Inspection	Done				No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done				No	
50,000 - SECTION 5 Steering System Inspection	Done				No	
50,510 - Check Entire Steering System	Done				No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done				No	
60,610 - FRA Check and Record Air Pressure	Done				No	
60,611 - Air Pressure RF	65 Pounds per Square Inch				No	
60,612 - Air Pressure LF	65 Pounds per Square Inch				No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch				No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch				No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch				No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch				No	
60,620 - Check Valve Stems and Caps	Done				No	
60,630 - Check and Record Tread Depth	Done				No	
60,631 - Tread Depth RF	12 32nds of an inch				No	
60,632 - Tread Depth LF	12 32nds of an inch				No	
60,633 - Tread Depth RRO	6 32nds of an inch				No	
60,634 - Tread Depth RRI	6 32nds of an inch				No	
60,635 - Tread Depth LRI	6 32nds of an inch				No	
60,636 - Tread Depth LRO	6 32nds of an inch				No	
60,640 - Check for Mismatched Tread or Casing Design	Done				No	
60,650 - Check Sidewall Wear	Done				No	
60,660 - Inspect for Cuts and Tears	Done				No	
60,670 - Check Dual Mating With Square	-	N/A			No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done				No	
60,690 - Check Tires for Irregular or Alignment Wear	Done				No	
66,100 - FRA Check Outer Hubs for Leaks	Done				No	
70,000 - SECTION 7 Under Vehicle Inspection	Done				No	
70,710 - Check Vibration Damper	Done				No	
70,720 - Check Engine and Transmission Mounts	Done				No	
70,730 - FRA Check Starter	Done				No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done				No	
70,750 - FRA Check Transmission for Leaks	Done				No	
70,760 - FRA Check Differential Breather and Fluid	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,770 - FRA Check Exhaust System	Done				No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done				No	
70,790 - Check All Body Mounts and Chassis Frame	Done				No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done				No	
77,110 - FRA Check Fuel Tank	Done				No	
77,120 - Check Suspension Components	Done				No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done				No	
77,131 - Brake Pad Thickness LF	12 Inch				No	
77,132 - Brake Pad Thickness RF	12 Inch				No	
77,133 - Brake Pad Thickness LR	10 Inch				No	
77,134 - Brake Pad Thickness RR	10 Inch				No	
77,135 - Brake Rotor LF	1.7 Inch				No	
77,136 - Brake Rotor RF	1.7 Inch				No	
77,137 - Brake Rotor LR	1.7 Inch				No	
77,138 - Brake Rotor RR	1.7 Inch				No	
77,140 - FRA Check Brake Hoses	Done				No	
77,150 - Check King Pins	-	N/A			No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done				No	
80,000 - SECTION 8 PMI Report Completion	Done				No	
80,810 - Completion of PMI Report	Done				No	
90,000 - SECTION 9 Completion of PMI	Done				No	
90,910 - Vehicle Returned to predetermined location	Done				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34872205
Invoice No. 55345 - 34872205

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,915 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 23-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 23, 2017 1:29:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jun 23, 2017 1:29:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 23, 2017 1:29:59 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34872205
Invoice No. 55345 - 34872205

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	91,915 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 23-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 23, 2017 1:30:24 PM	No	
20 - Miles			HPIERRE	Jun 23, 2017 1:30:24 PM	No	
30 - Kilometers			HPIERRE	Jun 23, 2017 1:30:24 PM	No	
40 - Hours			HPIERRE	Jun 23, 2017 1:30:24 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34872205 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	4.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34958568
Invoice No. 55345 - 34958568

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine warning light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	90,673 - DH

Chronology		
Reported	Jun 13, 2017 6:03:54 PM	Jun 13, 2017 6:03:54 PM
Started		
Completed	Jun 16, 2017 7:24:00 AM	Jun 16, 2017 7:24:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Engine warning light on

CAUSE:Lean condition

CORRECTION:lean condition repair

Engine diagnosed with scanner
Code PO714 found
Vacuum leak repaired
Air filter replaced
Alternator pigtail replaced

Parts used
One (1) filter #PA4075
One pigtail #WPT-118

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 15-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 15, 2017 4:00:41 PM	No	
20 - Miles			FSIMON	Jun 15, 2017 4:00:41 PM	No	
30 - Kilometers			FSIMON	Jun 15, 2017 4:00:41 PM	No	
40 - Hours			FSIMON	Jun 15, 2017 4:00:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34958568
Invoice No. 55345 - 34958568

Client Department:
Department: 55345M
Work Order Description
Engine warning light on
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 90,673 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jun-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
14-Jun-17	WPT118	PIGTAIL, SENSOR, CAM SAME AS 1U2Z-14S411-TA	1	35.77	35.77

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	40.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.95**

Work Order Footer

Work Order 34958568 Total	
Parts:	40.95
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**40.95**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34872120
Invoice No. 55345 - 34872120

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,825 - DH

Chronology		
Reported	May 23, 2017 8:00:05 AM	May 23, 2017 8:00:05 AM
Started	May 23, 2017 12:00:00 AM	
Completed	May 23, 2017 9:15:00 AM	May 23, 2017 9:15:00 AM
Down Time		

Work Order Notes

Line 10 PMI follow up
Rear brake pads replaced

Parts used:
One (1) brake pads #BRSD 1330

Activity Header
Activity: 10 013/002 REAR BRAKES & DRUMS
Activity Note: 3mm
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34872120
Invoice No. 55345 - 34872120

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,825 - DH

Activity Header
Activity: 20 013 BRAKES
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc:
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 23, 2017 9:13:50 AM	No	
20 - Miles			FSIMON	May 23, 2017 9:13:50 AM	No	
30 - Kilometers			FSIMON	May 23, 2017 9:13:50 AM	No	
40 - Hours			FSIMON	May 23, 2017 9:13:50 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order Footer

Work Order 34872120 Total	
Parts:	43.15

	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34770637
Invoice No. 55345 - 34770637

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,825 - DH

Chronology		
Reported	May 18, 2017 8:36:45 AM	May 18, 2017 8:36:45 AM
Started	May 23, 2017 12:00:00 AM	
Completed	May 23, 2017 8:07:00 AM	May 23, 2017 8:07:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:PMA service due

CORRECTION:PMA completion

PMA performed
Engine oil changed
Engine oil filter changed
Engine drain plug replaced
Serpentine belt replaced
Rear brakes pads and clips replaced

Parts used:
One (1) engine oil filter B329
Six (6) quarts of oil 5w20
One (1) drain plug#F75Z-6730-BA
One (1) serpentine belt #5061360

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-17	5061360	BELT, SERPENTINE, 6-RIB, 136.02"L X 0.82"W	1	27.53	27.53

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,100 - Safety Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,140 - Check Service Brakes	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,170 - Check Fast Idle	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,100 - Check Parking Brake	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,150 - Perform Brake Test	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	May 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:00:05 AM		
20,210 - Check Condition of Operator's Area	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,240 - FRA Check Interior Lights	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,260 - Check Stop Request System	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,310 - Check Passenger Doors	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,410 - FRA Check Engine	Done		FSIMON	May 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Compartment/Condition for Fire Risk				8:00:05 AM		
40,420 - Check Hood	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,140 - FRA Check Intake System	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
50,510 - Check Entire Steering System	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	May 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:00:05 AM		
60,611 - Air Pressure RF	Pounds per Square Inch	65mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,612 - Air Pressure LF	Pounds per Square Inch	65mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,613 - Air Pressure RRO	Pounds per Square Inch	70mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,614 - Air Pressure RRI	Pounds per Square Inch	70mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,615 - Air Pressure LRI	Pounds per Square Inch	70mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,616 - Air Pressure LRO	Pounds per Square Inch	70mm	FSIMON	May 23, 2017 8:00:05 AM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,631 - Tread Depth RF	13 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,632 - Tread Depth LF	13 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		FSIMON	May 23, 2017 8:00:05 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,710 - Check Vibration Damper	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,730 - FRA Check Starter	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid	Done		FSIMON	May 23, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks				8:00:05 AM		
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,120 - Check Suspension Components	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,131 - Brake Pad Thickness LF	Inch	11mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,132 - Brake Pad Thickness RF	Inch	11mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,133 - Brake Pad Thickness LR	Inch	3mm	FSIMON	May 23, 2017 8:00:05 AM	Yes	34872120
77,134 - Brake Pad Thickness RR	Inch	3mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,135 - Brake Rotor LF	Inch	40mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,136 - Brake Rotor RF	Inch	40mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,137 - Brake Rotor LR	Inch	40mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,138 - Brake Rotor RR	Inch	40mm	FSIMON	May 23, 2017 8:00:05 AM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
77,150 - Check King Pins	-	NA	FSIMON	May 23, 2017 8:00:05 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
80,810 - Completion of PMI Report	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	May 23, 2017 8:00:05 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	May 23, 2017 8:00:05 AM	No	

Activity Sub Total

Activity 10 Sub Total

Parts: 27.53

	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**27.53**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34770637
Invoice No. 55345 - 34770637

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 87,825 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
23-May-17	F757-6730-BA	PLUG, DRAIN, OIL, ENGINE	1	6.66	6.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-May-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: FSIMON Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	May 23, 2017 7:45:38 AM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	May 23, 2017 7:45:38 AM	No	
102,000 - FRA Drain Engine Oil	Yes		FSIMON	May 23, 2017 7:45:38 AM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	May 23, 2017 7:45:38 AM	No	
104,000 - Lubricate Chassis	Done		FSIMON	May 23, 2017 7:45:38 AM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	May 23, 2017 7:45:38 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		FSIMON	May 23, 2017 7:45:38 AM	No	
108,000 - Lube all pivoting	Done		FSIMON	May 23, 2017 7:45:38	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				AM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	8.58
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**8.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34770637
Invoice No. 55345 - 34770637

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	87,825 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 23, 2017 8:01:46 AM	No	
20 - Miles			FSIMON	May 23, 2017 8:01:46 AM	No	
30 - Kilometers			FSIMON	May 23, 2017 8:01:46 AM	No	
40 - Hours			FSIMON	May 23, 2017 8:01:46 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34770637 Total	
Parts:	36.11
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**36.11**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34811868
Invoice No. 55345 - 34811868

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front Tires&Front brakes		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	86,015 - DH

Chronology		
Reported	May 7, 2017 2:27:59 PM	May 7, 2017 2:27:59 PM
Started	May 7, 2017 12:00:00 AM	
Completed	May 7, 2017 4:09:00 PM	May 7, 2017 4:09:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Front tires&Front brakes

CAUSE: tire uneven Wear Brakes Low

CORRECTION: Mount&Balance Front tires &Remove/Replace front brakes,
Parts# 189752 Qty (2)
Parts# BRSD 1328 Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 07-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 7, 2017 4:01:59 PM	No	
20 - Miles			DARTHURS	May 7, 2017 4:01:59 PM	No	
30 - Kilometers			DARTHURS	May 7, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:01:59 PM		
40 - Hours			DARTHURS	May 7, 2017 4:01:59 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34811868
Invoice No. 55345 - 34811868

Client Department:
Department: 55345M
Work Order Description
Front Tires&Front brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 86,015 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Front Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.2	210.4

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	210.40
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**210.40**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34811868
Invoice No. 55345 - 34811868

Client Department:
Department: 55345M
Work Order Description
Front Tires&Front brakes
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 86,015 - DH

Activity Header
Activity: 25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Front Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-May-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-May-17	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order Footer

Work Order 34811868 Total	
Parts:	260.72
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**260.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34803260
Invoice No. 55345 - 34803260

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended spark plug service by mileage
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 85,552 - DH

Chronology		
Reported	May 2, 2017 9:58:06 AM	May 2, 2017 9:58:06 AM
Started	May 2, 2017 12:00:00 AM	
Completed	May 2, 2017 11:39:00 AM	May 2, 2017 11:39:00 AM
Down Time		

Work Order Notes

Line 10 Spark plug

COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTS
Qty 10 Boot WR-6128
Qty 10 spark plug SP521

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 02-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 2, 2017 10:07:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	May 2, 2017 10:07:51 AM	No	
30 - Kilometers			EDTORRES	May 2, 2017 10:07:51 AM	No	
40 - Hours			EDTORRES	May 2, 2017 10:07:51 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34803260
Invoice No. 55345 - 34803260

Client Department:
Department: 55345M
Work Order Description
Manufacturer recommended spark plug service by mileage
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 85,552 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Manufacturer recommended spark plug service by mileage
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-May-17	WR6128	BOOT, PLUG, SPARK	10	5.43	54.3
02-May-17	SP521	PLUG, SPARK, 5.4L, FORD	10	4.15	41.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-17	Torres,Edwin	2.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	95.80
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.80**

Work Order Footer

Work Order 34803260 Total	
Parts:	95.80
Labor:	0.00
Labor Hours:	2.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**95.80**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34717899
Invoice No. 55345 - 34717899

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 83,531 - DH

Chronology		
Reported	Apr 18, 2017 11:07:51 AM	Apr 18, 2017 11:07:51 AM
Started	Apr 18, 2017 12:00:00 AM	
Completed	Apr 18, 2017 9:50:00 PM	Apr 18, 2017 9:50:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter Lube all Pivoting Points Clean batteries Remove wheel & Check brakes,
Parts# B329 Qty 1
Oil 5W20QTY (7) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 18-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,136 - Brake Rotor RF	1.566 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,137 - Brake Rotor LR	1.411 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,138 - Brake Rotor RR	1.412 Inch		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 18, 2017 7:19:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 18, 2017 7:19:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34717899
Invoice No. 55345 - 34717899

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 83,531 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 18-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 18, 2017 7:20:55 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Apr 18, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:20:55 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Apr 18, 2017 7:20:55 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Apr 18, 2017 7:20:55 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Apr 18, 2017 7:20:55 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34717899
Invoice No. 55345 - 34717899

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	83,531 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Apr-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 18, 2017 7:21:23 PM	No	
20 - Miles			DARTHURS	Apr 18, 2017 7:21:23 PM	No	
30 - Kilometers			DARTHURS	Apr 18, 2017 7:21:23 PM	No	
40 - Hours			DARTHURS	Apr 18, 2017 7:21:23 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34717899 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34263951
Invoice No. 55345 - 34263951

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 79,624 - DH

Chronology		
Reported	Mar 22, 2017 1:26:32 PM	Mar 22, 2017 1:26:32 PM
Started	Mar 22, 2017 12:00:00 AM	
Completed	Mar 22, 2017 6:45:00 PM	Mar 22, 2017 6:45:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:service

CORRECTION:perform PMA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-17	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 22, 2017 5:41:28 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 22, 2017 5:41:28 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34263951
Invoice No. 55345 - 34263951

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 79,624 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-17	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 22, 2017 5:42:19 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 22, 2017 5:42:19 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 22, 2017 5:42:19 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 22, 2017 5:42:19 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 22, 2017 5:42:19 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 22, 2017 5:42:19 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 22, 2017 5:42:19 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 22, 2017 5:42:19 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.92
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34263951
Invoice No. 55345 - 34263951

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	79,624 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 22, 2017 5:42:44 PM	No	
20 - Miles			RGASPARD	Mar 22, 2017 5:42:44 PM	No	
30 - Kilometers			RGASPARD	Mar 22, 2017 5:42:44 PM	No	
40 - Hours			RGASPARD	Mar 22, 2017 5:42:44 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34263951 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34665684
Invoice No. 55345 - 34665684

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver said left turn signal out		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,855 - DH

Chronology		
Reported	Mar 15, 2017 11:02:48 AM	Mar 15, 2017 11:02:48 AM
Started	Mar 15, 2017 12:00:00 AM	
Completed	Mar 15, 2017 11:31:00 AM	Mar 15, 2017 11:31:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said left turn signal light bulb out

CAUSE: bad bulb

CORRECTION: replace light bulb completed
Part# 3157 qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 15-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 15, 2017 11:08:45 AM	No	
20 - Miles			HPIERRE	Mar 15, 2017 11:08:45 AM	No	
30 - Kilometers			HPIERRE	Mar 15, 2017 11:08:45 AM	No	
40 - Hours			HPIERRE	Mar 15, 2017 11:08:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34665684
Invoice No. 55345 - 34665684

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver said left turn signal out		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	78,855 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Mar-17	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	1	0.85	0.85

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Mar-17	Pierre,Hubert J	0.4166666	0	0
15-Mar-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order Footer

Work Order 34665684 Total	
Parts:	0.85
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.85**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34663467
Invoice No. 55345 - 34663467

Client Department:
Department: 55345M
Work Order Description
TURN SIGNALS NOT WORKING
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,855 - DH

Chronology		
Reported	Mar 13, 2017 10:52:00 PM	Mar 13, 2017 10:52:00 PM
Started	Mar 13, 2017 12:00:00 AM	
Completed	Mar 13, 2017 10:59:00 PM	Mar 13, 2017 10:59:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:SIGNAL LIGHTS NOT WORKING

CAUSE:BOTH SIGNAL LIGHTS ARE BLOWN OUT

CORRECTION: REPLACE BOTH SIGNAL LIGHTS BOTH SIGNAL LIGHTS WORKS AT THIS TIME

PARTS# 3157 N/A QTY 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-17	Owens,Arthur	0.03	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 13-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Mar 13, 2017 10:58:41 PM	No	
20 - Miles			AOWENS	Mar 13, 2017 10:58:41 PM	No	
30 - Kilometers			AOWENS	Mar 13, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:58:41 PM		
40 - Hours			AOWENS	Mar 13, 2017 10:58:41 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34663467
Invoice No. 55345 - 34663467

Client Department:
Department: 55345M
Work Order Description
TURN SIGNALS NOT WORKING
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 78,855 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE SIGNAL BULBS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-17	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	2	0.85	1.7

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-17	Owens,Arthur	0.6	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	1.70
Labor:	0.00
Labor Hours:	0.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.70**

Work Order Footer

Work Order 34663467 Total	
Parts:	1.70
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34647279
Invoice No. 55345 - 34647279

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Batteries check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,653 - DH

Chronology		
Reported	Mar 6, 2017 3:48:50 PM	Mar 6, 2017 3:48:50 PM
Started	Mar 6, 2017 12:00:00 AM	
Completed	Mar 7, 2017 9:18:00 AM	Mar 7, 2017 9:18:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Not cranking in the morning

CAUSE:Defective batteries

CORRECTION: Batteries replacement

Batteries tested defective
Two batteries replaced

Materials used:
Two(2) batteries#MTP-24-SA7

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 7, 2017 8:52:07 AM	No	
20 - Miles			FSIMON	Mar 7, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:52:07 AM		
30 - Kilometers			FSIMON	Mar 7, 2017 8:52:07 AM	No	
40 - Hours			FSIMON	Mar 7, 2017 8:52:07 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34647279
Invoice No. 55345 - 34647279

Client Department:
Department: 55345M
Work Order Description
Batteries check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 77,653 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Mar-17	MTP-24S	OUT OF SERVICE BATTERY	2	79.75	159.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Mar-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	159.50
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**159.50**

Work Order Footer

Work Order 34647279 Total	
Parts:	159.50
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**159.50**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34647501
Invoice No. 55345 - 34647501

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C not turn off		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,653 - DH

Chronology		
Reported	Mar 6, 2017 4:27:53 PM	Mar 6, 2017 4:27:53 PM
Started	Mar 6, 2017 12:00:00 AM	
Completed	Mar 7, 2017 9:14:00 AM	Mar 7, 2017 9:14:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said rear A/C won't turn off

CAUSE: bad rear A/C switch

CORRECTION: replace A/C switch completed
Use part #1 switch

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Mar-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34647501
Invoice No. 55345 - 34647501

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C not turn off		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	77,653 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Mar-17	Pierre,Hubert J	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34647501 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 34609214
Invoice No. 55345 - 34609214

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	76,146 - DH

Chronology		
Reported	Feb 22, 2017 3:15:12 PM	Feb 22, 2017 3:15:12 PM
Started		
Completed	Feb 23, 2017 10:17:00 AM	Feb 23, 2017 10:17:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear A/C not blowing cold

CAUSE:Rear A/C overcharged

CORRECTION:Adjust lines pressures

Complaint verified
Rear A/C system tested,

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34609214 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 34238896
Invoice No. 55345 - 34238896

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,337 - DH

Chronology		
Reported	Feb 16, 2017 4:25:36 PM	Feb 16, 2017 4:25:36 PM
Started		
Completed	Feb 16, 2017 11:32:00 PM	Feb 16, 2017 11:32:00 PM
Down Time		

Work Order Notes

Line 10 WORK ORDER WAS RELEASE BY MISTAKE

Activity Header
Activity: 10 001/001/000 AIR CONDITIONING
Activity Note: Rear A/C
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34238896 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 32959340
Invoice No. 55345 - 32959340

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,337 - DH

Chronology		
Reported	Feb 15, 2017 10:54:07 AM	Feb 15, 2017 10:54:07 AM
Started	Feb 16, 2017 12:00:00 AM	
Completed	Feb 16, 2017 11:25:00 PM	Feb 16, 2017 11:25:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter Lube all pivoting Points ,Clean batteries check brakes,Replace Air Filter,
Parts# B329 Qty (1)
Parts# PA 4075 Qty (1)
Oil 5W20 Qty (7.0) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				4:25:36 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,110 - Check HVAC Switches and Other Controls	-	Rear A/C	DARTHURS	Feb 16, 2017 4:25:36 PM	Yes	34238896
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails	Done		DARTHURS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Floor Covering				4:25:36 PM		
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,420 - Check Hood	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,461 - Refractometer Reading	Degree	NA	DARTHURS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			4:25:36 PM		
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:25:36 PM		
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		DARTHURS	Feb 16, 2017 4:25:36 PM	Yes	34238718
60,635 - Tread Depth LRI	3 32nds of an inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	4Rear Tire	DARTHURS	Feb 16, 2017 4:25:36 PM	Yes	34238718
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Feb 16, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:25:36 PM		
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,135 - Brake Rotor LF	1.567 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,136 - Brake Rotor RF	1.565 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,137 - Brake Rotor LR	1.411 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,138 - Brake Rotor RR	1.41 Inch		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Feb 16, 2017 4:25:36 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Feb 16, 2017 4:25:36 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 32959340
Invoice No. 55345 - 32959340

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,337 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
16-Feb-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Feb 16, 2017 4:26:33 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Feb 16, 2017 4:26:33 PM	No	
108,000 - Lube all pivoting	Done		DARTHURS	Feb 16, 2017 4:26:33	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanisms				PM		

Activity Sub Total

Activity 20 Sub Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 32959340
Invoice No. 55345 - 32959340

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	75,337 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 16, 2017 4:27:05 PM	No	
20 - Miles			DARTHURS	Feb 16, 2017 4:27:05 PM	No	
30 - Kilometers			DARTHURS	Feb 16, 2017 4:27:05 PM	No	
40 - Hours			DARTHURS	Feb 16, 2017 4:27:05 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32959340 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 34238718
Invoice No. 55345 - 34238718

Client Department:
Department: 55345M
Work Order Description
PMA Follow up >>>>>>>>Rear Tire&RearA/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,337 - DH

Chronology		
Reported	Feb 16, 2017 4:23:00 PM	Feb 16, 2017 4:23:00 PM
Started	Feb 16, 2017 12:00:00 AM	
Completed	Feb 16, 2017 11:24:00 PM	Feb 16, 2017 11:24:00 PM
Down Time		

Work Order Notes

Line 10 Mount& Balance Rear Tire /Evacuate Rear A/C Remove& Replace Orifice tube &Recharge !
Parts#192659 Qty (4)
Parts#YG-380 Qty (1)
Freon (7.5) Lbs

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Feb-17	YG380	TUBE, ORIFICE, A/C, E450, BLACK	1	4.26	4.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.26
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 34238718
Invoice No. 55345 - 34238718

Client Department:
Department: 55345M
Work Order Description
PMA Follow up >>>>>>>>Rear Tire&RearA/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,337 - DH

Activity Header
Activity: 20 017 TIRES, TUBES, LINERS & VALVES
Activity Note: 4Rear Tire
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	109.61	438.44
16-Feb-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	109.61	438.44
17-Feb-17	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	-4	109.61	-438.44

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	438.44
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**438.44**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 34238718
Invoice No. 55345 - 34238718

Client Department:
Department: 55345M
Work Order Description
PMA Follow up >>>>>>>>Rear Tire&RearA/C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 75,337 - DH

Activity Header
Activity: 30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 16, 2017 4:41:20 PM	No	
20 - Miles			DARTHURS	Feb 16, 2017 4:41:20 PM	No	
30 - Kilometers			DARTHURS	Feb 16, 2017 4:41:20 PM	No	
40 - Hours			DARTHURS	Feb 16, 2017 4:41:20 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 34238718 Total	
Parts:	442.70
Labor:	0.00
Labor Hours:	3.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**442.70**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 34086894
Invoice No. 55345 - 34086894

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Blower motor		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	74,947 - DH

Chronology		
Reported	Feb 14, 2017 8:36:04 PM	Feb 14, 2017 8:36:04 PM
Started	Feb 14, 2017 12:00:00 AM	
Completed	Feb 14, 2017 8:50:00 PM	Feb 14, 2017 8:50:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: No Air coming from vent

CAUSE: Bad blower motor

CORRECTION: Remove& Replace blower motor,
Parts#MM-840 Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 14, 2017 8:40:12 PM	No	
20 - Miles			DARTHURS	Feb 14, 2017 8:40:12 PM	No	
30 - Kilometers			DARTHURS	Feb 14, 2017 8:40:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Feb 14, 2017 8:40:12 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 34086894
Invoice No. 55345 - 34086894

Client Department:
Department: 55345M
Work Order Description
Blower motor
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 74,947 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Blower motor inop
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Feb-17	MM840	MOTOR, BLOWER, HVAC	1	57.05	57.05

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-17	Arthurs,Durvin	1	0	0
14-Feb-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	57.05
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.05**

Work Order Footer

Work Order 34086894 Total	
Parts:	57.05
Labor:	0.00
Labor Hours:	1.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**57.05**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 33650258
Invoice No. 55345 - 33650258

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check fuel gauge		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	73,917 - DH

Chronology		
Reported	Feb 7, 2017 2:35:23 PM	Feb 7, 2017 2:35:23 PM
Started	Feb 7, 2017 12:00:00 AM	
Completed	Feb 8, 2017 11:20:00 AM	Feb 8, 2017 11:20:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Fuel gauge pointer stuck on full .

CAUSE:Defective FLIM

CORRECTION:FLIM replacement

Complaint verified
Fuel gauge system checked ,FLIM found faulty.
FLIM replaced
Fuel gauge reading ok

Part used:
One (1) FLIM (under warranty).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Feb-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Feb 7, 2017 2:59:31 PM	No	
20 - Miles			FSIMON	Feb 7, 2017 2:59:31 PM	No	
30 - Kilometers			FSIMON	Feb 7, 2017 2:59:31 PM	No	
40 - Hours			FSIMON	Feb 7, 2017 2:59:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 33650258
Invoice No. 55345 - 33650258

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check fuel gauge		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	73,917 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33650258 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 33436353
Invoice No. 55345 - 33436353

Client Department:
Department: 55345M
Work Order Description
Check exhaust pipe and front bumper
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 73,384 - DH

Chronology		
Reported	Feb 3, 2017 12:12:04 PM	Feb 3, 2017 12:12:04 PM
Started		
Completed	Feb 7, 2017 8:49:00 AM	Feb 7, 2017 8:49:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Exhaust tail pipe touching rear bumper .

CAUSE:Broken hanger

CORRECTION:Tail pipe hanger replaced

Complaint verified
Visual inspection performed
Tail pipe hanger found broken and front bumper misadjusted.
Hanger replaced
Front bumper adjusted

Parts used:
One (1) hanger (shop supply)
One (1) exhaust clamp (shop supply).

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 33436353
Invoice No. 55345 - 33436353

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check exhaust pipe and front bumper		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	73,384 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 33436353 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 32951965
Invoice No. 55345 - 32951965

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	99 - Cancelled (99)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,004 - DH

Chronology		
Reported	Jan 16, 2017 6:15:45 PM	Jan 16, 2017 6:15:45 PM
Started		
Completed	Jan 17, 2017 2:18:00 PM	Jan 17, 2017 2:18:00 PM
Down Time		

Work Order Notes

Line 10 per technician follow up work order created by mistake.

Activity Header
Activity: 10 018/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair:
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 32951965
Invoice No. 55345 - 32951965

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	99 - Cancelled (99)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,004 - DH

Activity Header
Activity:20
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 32951965 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 29571649
Invoice No. 55345 - 29571649

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	71,080 - DH

Chronology		
Reported	Jan 16, 2017 12:25:35 PM	Jan 16, 2017 12:25:35 PM
Started	Jan 16, 2017 12:00:00 AM	
Completed	Jan 17, 2017 1:36:00 PM	Jan 17, 2017 1:36:00 PM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all pivoting points cross rotate tires completed
Parts # oil filter qty 1
Oil# 5 w20 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-17	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done				No	
10,100 - Safety Inspection	Done				No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
& Authorization Forms						
10,120 - FRA Check All Warning Lights and Alarms	Done				No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done				No	
10,140 - Check Service Brakes	Done				No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done				No	
10,160 - FRA Check Instruments and Horns	Done				No	
10,170 - Check Fast Idle	Done				No	
10,180 - Check Starter Protection Circuit	Done				No	
10,190 - Check Reverse Warning System	Done				No	
11,100 - Check Parking Brake	Done				No	
11,110 - Check HVAC Switches and Other Controls	Done				No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done				No	
11,130 - FRA Check Wiper and Washer Operation	Done				No	
11,140 - Road Test: Check for Proper Operation	Done				No	
11,150 - Perform Brake Test	Done				No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A			No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A			No	
11,170 - FRA Check Door Operation	Done				No	
11,180 - FRA Check Operation of All Other Accessories	Done				No	
20,000 - SECTION 2 Interior Circle Inspection	Done				No	
20,210 - Check Condition of Operator's Area	Done				No	
20,220 - Check Accelerator and Brake Pedals	Done				No	
20,230 - FRA Check Wiring Under Dash	Done				No	
20,240 - FRA Check Interior Lights	Done				No	
20,250 - FRA Check Interior Electrical Panels	Done				No	
20,260 - Check Stop Request System	-	N/A			No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A			No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done				No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done				No	
22,100 - Check Emergency Windows and Glass Condition	Done				No	
22,110 - Check Emergency Hatches	Done				No	
22,120 - Check All Safety Equipment	Done				No	
30,000 - SECTION 3 Exterior Circle Inspection	Done				No	
30,310 - Check Passenger Doors	Done				No	
30,320 - Inspect Step-well and Hand Rails	Done				No	
30,330 - Check Wheelchair Lift Operation	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30,340 - FRA Check Destination Sign and Run Box	-	N/A			No	
30,350 - FRA Inspect Mirror and Mountings	Done				No	
30,360 - Check for Physical Damage and Decals	Done				No	
30,370 - Check Wiper Blade and Arm Condition	Done				No	
30,380 - Check Exterior Compartment Doors	Done				No	
30,390 - FRA Check Fuel Tank Cap	Done				No	
33,100 - Check Lights and Reflectors	Done				No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done				No	
40,000 - SECTION 4 Engine Compartment Inspection	Done				No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done				No	
40,420 - Check Hood	Done				No	
40,430 - Check Fan, Shroud and Radiator	Done				No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A			No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A			No	
40,442 - Freeze Point	Degree Fahrenheit	N/A			No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done				No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A			No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A			No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done				No	
40,480 - FRA Check Coolant Hose Condition	Done				No	
40,490 - FRA Check Alternator Mount and Condition	Done				No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done				No	
44,110 - FRA Check Master Cylinder Fluid Level	Done				No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done				No	
44,130 - FRA Check Exhaust System	Done				No	
44,140 - FRA Check Intake System	Done				No	
44,150 - FRA Inspect Turbocharger	-	N/A			No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done				No	
44,170 - FRA Check All Engine or Belt Driven Components	Done				No	
44,180 - FRA Check for Leaks	Done				No	
44,190 - FRA Perform Battery Inspection	Done				No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done				No	
50,000 - SECTION 5 Steering System Inspection	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,510 - Check Entire Steering System	Done				No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done				No	
60,610 - FRA Check and Record Air Pressure	Done				No	
60,611 - Air Pressure RF	70 Pounds per Square Inch				No	
60,612 - Air Pressure LF	70 Pounds per Square Inch				No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch				No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch				No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch				No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch				No	
60,620 - Check Valve Stems and Caps	Done				No	
60,630 - Check and Record Tread Depth	Done				No	
60,631 - Tread Depth RF	10 32nds of an inch				No	
60,632 - Tread Depth LF	10 32nds of an inch				No	
60,633 - Tread Depth RRO	8 32nds of an inch				No	
60,634 - Tread Depth RRI	8 32nds of an inch				No	
60,635 - Tread Depth LRI	8 32nds of an inch				No	
60,636 - Tread Depth LRO	8 32nds of an inch				No	
60,640 - Check for Mismatched Tread or Casing Design	Done				No	
60,650 - Check Sidewall Wear	Done				No	
60,660 - Inspect for Cuts and Tears	Done				No	
60,670 - Check Dual Mating With Square	-	N/A			No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done				No	
60,690 - Check Tires for Irregular or Alignment Wear	Done				No	
66,100 - FRA Check Outer Hubs for Leaks	Done				No	32951965
70,000 - SECTION 7 Under Vehicle Inspection	Done				No	
70,710 - Check Vibration Damper	Done				No	
70,720 - Check Engine and Transmission Mounts	Done				No	
70,730 - FRA Check Starter	Done				No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done				No	
70,750 - FRA Check Transmission for Leaks	Done				No	
70,760 - FRA Check Differential Breather and Fluid	Done				No	
70,770 - FRA Check Exhaust System	Done				No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done				No	
70,790 - Check All Body Mounts and Chassis Frame	Done				No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done				No	
77,120 - Check Suspension Components	Done				No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done				No	
77,131 - Brake Pad Thickness LF	10 Inch				No	
77,132 - Brake Pad Thickness RF	10 Inch				No	
77,133 - Brake Pad Thickness LR	8 Inch				No	
77,134 - Brake Pad Thickness RR	8 Inch				No	
77,135 - Brake Rotor LF	1.7 Inch				No	
77,136 - Brake Rotor RF	1.7 Inch				No	
77,137 - Brake Rotor LR	1.7 Inch				No	
77,138 - Brake Rotor RR	1.7 Inch				No	
77,140 - FRA Check Brake Hoses	Done				No	
77,150 - Check King Pins	-	N/A			No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done				No	
80,000 - SECTION 8 PMI Report Completion	Done				No	
80,810 - Completion of PMI Report	Done				No	
90,000 - SECTION 9 Completion of PMI	Done				No	
90,910 - Vehicle Returned to predetermined location	Done				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 29571649
Invoice No. 55345 - 29571649

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,080 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: HPIERRE Performed on: 16-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	N/A	HPIERRE	Jan 16, 2017 6:17:56 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Jan 16, 2017 6:17:56 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Jan 16, 2017 6:17:56 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Jan 16, 2017 6:17:56 PM	No	
305,000 - FRA Change Differential Fluid	No		HPIERRE	Jan 16, 2017 6:17:56 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 29571649
Invoice No. 55345 - 29571649

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 71,080 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 16, 2017 6:18:34 PM	No	
20 - Miles			HPIERRE	Jan 16, 2017 6:18:34 PM	No	
30 - Kilometers			HPIERRE	Jan 16, 2017 6:18:34 PM	No	
40 - Hours			HPIERRE	Jan 16, 2017 6:18:34 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 29571649 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 31586274
Invoice No. 55345 - 31586274

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Transmission service		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	69,002 - DH

Chronology		
Reported	Dec 26, 2016 3:35:24 PM	Dec 26, 2016 3:35:24 PM
Started	Dec 26, 2016 12:00:00 AM	
Completed	Dec 27, 2016 9:57:00 AM	Dec 27, 2016 9:57:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Transmission service

CAUSE:Preventive maintenance

CORRECTION:Transmission service completion

Transmission filter replaced
Transmission fluid changed

Material used:
One (1) filter FT 180
Nine (9) quarts ATF

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 26, 2016 3:47:13 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Dec 26, 2016 3:47:13 PM	No	
30 - Kilometers			FSIMON	Dec 26, 2016 3:47:13 PM	No	
40 - Hours			FSIMON	Dec 26, 2016 3:47:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 31586274
Invoice No. 55345 - 31586274

Client Department:
Department: 55345M
Work Order Description
Transmission service
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 69,002 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Dec-16	FT180	FILTER, TRANSMISSION	1	35.76	35.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-16	Simon,Fritz	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	35.76
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.76**

Work Order Footer

Work Order 31586274 Total	
Parts:	35.76
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**35.76**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 29569213
Invoice No. 55345 - 29569213

Client Department:
Department: 55345M
Work Order Description
PMA follow up need front tires and front brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,883 - DH

Chronology		
Reported	Dec 8, 2016 7:31:50 AM	Dec 8, 2016 7:31:50 AM
Started		
Completed	Dec 8, 2016 3:15:22 PM	Dec 8, 2016 3:15:22 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: PMA Follow up need front tires and front brake pads

CAUSE:below spect both

CORRECTION: replace front tires mounted and balance ,replace front brake pads completed
Parts # 050017 qty 2tire
Brake pads #BRSD qty 1

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 8, 2016 3:13:57 PM	No	
20 - Miles			HPIERRE	Dec 8, 2016 3:13:57 PM	No	
30 - Kilometers			HPIERRE	Dec 8, 2016 3:13:57 PM	No	
40 - Hours			HPIERRE	Dec 8, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:13:57 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 29569213
Invoice No. 55345 - 29569213

Client Department:
Department: 55345M
Work Order Description
PMA follow up need front tires and front brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,883 - DH

Activity Header
Activity: 15 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**50.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 29569213
Invoice No. 55345 - 29569213

Client Department:
Department: 55345M
Work Order Description
PMA follow up need front tires and front brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,883 - DH

Activity Header
Activity:25 017/001/000 TIRE, PNEUMATIC
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	88.85	177.7

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 25 Sub Total	
Parts:	177.70
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**177.70**

Work Order Footer

Work Order 29569213 Total	
Parts:	228.02
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**228.02**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27855715
Invoice No. 55345 - 27855715

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	66,883 - DH

Chronology		
Reported	Dec 7, 2016 11:54:47 AM	Dec 7, 2016 11:54:47 AM
Started	Dec 8, 2016 12:00:00 AM	
Completed	Dec 8, 2016 8:06:00 AM	Dec 8, 2016 8:06:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:preventive maintenance

CORRECTION: perform service lube all pivoting points and cross rotate front tires completed
Parts #B329 qty1
Oil#5w20 qts 6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-16	Pierre,Hubert J	6	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 08-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,420 - Check Hood	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,631 - Tread Depth RF	3 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,632 - Tread Depth LF	3 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,131 - Brake Pad Thickness LF	3 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,132 - Brake Pad Thickness RF	3 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,135 - Brake Rotor LF	1.7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,136 - Brake Rotor RF	1.7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Dec 8, 2016 7:12:53 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Dec 8, 2016 7:12:53 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27855715
Invoice No. 55345 - 27855715

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,883 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 08-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Dec 8, 2016 7:23:58 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Dec 8, 2016 7:23:58 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Dec 8, 2016 7:23:58 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27855715
Invoice No. 55345 - 27855715

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 66,883 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Dec 8, 2016 7:24:18 AM	No	
20 - Miles			HPIERRE	Dec 8, 2016 7:24:18 AM	No	
30 - Kilometers			HPIERRE	Dec 8, 2016 7:24:18 AM	No	
40 - Hours			HPIERRE	Dec 8, 2016 7:24:18 AM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27855715 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27469452
Invoice No. 55345 - 27469452

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,870 - DH

Chronology		
Reported	Nov 2, 2016 2:16:01 PM	Nov 2, 2016 2:16:01 PM
Started	Nov 2, 2016 12:00:00 AM	
Completed	Nov 2, 2016 11:44:00 PM	Nov 2, 2016 11:44:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filterB329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Nov-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 02-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 2, 2016 10:59:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 2, 2016 10:59:18 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27469452
Invoice No. 55345 - 27469452

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 62,870 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Nov-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 02-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 2, 2016 11:00:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 2, 2016 11:00:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 2, 2016 11:00:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 2, 2016 11:00:05 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Nov 2, 2016 11:00:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 2, 2016 11:00:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Nov 2, 2016 11:00:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 2, 2016 11:00:05 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27469452
Invoice No. 55345 - 27469452

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	62,870 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Nov-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 2, 2016 11:00:32 PM	No	
20 - Miles			RGASPARD	Nov 2, 2016 11:00:32 PM	No	
30 - Kilometers			RGASPARD	Nov 2, 2016 11:00:32 PM	No	
40 - Hours			RGASPARD	Nov 2, 2016 11:00:32 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27469452 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27754998
Invoice No. 55345 - 27754998

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Headlight driver		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,238 - DH

Chronology		
Reported	Oct 21, 2016 10:05:33 AM	Oct 21, 2016 10:05:33 AM
Started	Oct 21, 2016 12:00:00 AM	
Completed	Oct 21, 2016 1:21:00 PM	Oct 21, 2016 1:21:00 PM
Down Time		

Work Order Notes

Line 10 Headlight Pigtail

COMPLAINT:
Driver side headlight is out

CAUSE:
Pigtail harness is bad.

CORRECTION:
Replaced driver side headlight and pigtail harness.

PARTS:
9008 headlight bulb qty 1 under shop supply.
891699 headlight pigtail qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-16	Torres,Edwin	0.7166666	0	0
21-Oct-16	Torres,Edwin	-0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 21-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Oct 21, 2016 10:12:52 AM	No	
20 - Miles			EDTORRES	Oct 21, 2016 10:12:52 AM	No	
30 - Kilometers			EDTORRES	Oct 21, 2016 10:12:52 AM	No	
40 - Hours			EDTORRES	Oct 21, 2016 10:12:52 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27754998
Invoice No. 55345 - 27754998

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Headlight driver		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	61,238 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Headlight driver
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Oct-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Oct-16	Torres,Edwin	0.7166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order Footer

Work Order 27754998 Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27733520
Invoice No. 55345 - 27733520

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver lower door hinge		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	60,845 - DH

Chronology		
Reported	Oct 18, 2016 10:23:38 PM	Oct 18, 2016 10:23:38 PM
Started	Oct 18, 2016 12:00:00 AM	
Completed	Oct 18, 2016 11:46:00 PM	Oct 18, 2016 11:46:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: door hinge

CAUSE:hinge broke

CORRECTION: Remove& Replace driver lower door hinge
Parts#6C2Z-1522810-A Qty (1)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 18, 2016 11:34:58 PM	No	
20 - Miles			DARTHURS	Oct 18, 2016 11:34:58 PM	No	
30 - Kilometers			DARTHURS	Oct 18, 2016 11:34:58 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Oct 18, 2016 11:34:58 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27733520
Invoice No. 55345 - 27733520

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver lower door hinge		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	60,845 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Driver lower door hinge broken
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Oct-16	6C2Z-1522810-A	HINGE, DOOR, DRIVERS	1	46.61	46.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Oct-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order Footer

Work Order 27733520 Total	
Parts:	46.61
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**46.61**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27534595
Invoice No. 55345 - 27534595

Client Department:
Department: 55345M
Work Order Description
Driver said passenger head light not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,769 - DH

Chronology		
Reported	Oct 5, 2016 1:22:45 PM	Oct 5, 2016 1:22:45 PM
Started	Oct 5, 2016 12:00:00 AM	
Completed	Oct 10, 2016 8:28:00 AM	Oct 10, 2016 8:28:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said passenger side head light not working

CAUSE:light bulb burn

CORRECTION: replace light bulb completed

Part #9008 qty 1 bulb

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 05-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 5, 2016 1:31:31 PM	No	
20 - Miles			HPIERRE	Oct 5, 2016 1:31:31 PM	No	
30 - Kilometers			HPIERRE	Oct 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:31:31 PM		
40 - Hours			HPIERRE	Oct 5, 2016 1:31:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27534595
Invoice No. 55345 - 27534595

Client Department:
Department: 55345M
Work Order Description
Driver said passenger head light not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,769 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Oct-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27534595 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27540753
Invoice No. 55345 - 27540753

Client Department:
Department: 55345M
Work Order Description
Front AC working on high only.
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,769 - DH

Chronology		
Reported	Oct 5, 2016 10:43:39 PM	Oct 5, 2016 10:43:39 PM
Started	Oct 5, 2016 12:00:00 AM	
Completed	Oct 5, 2016 10:53:00 PM	Oct 5, 2016 10:53:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver complaint front AC Working on high only

CAUSE:check , blower resistor bad

CORRECTION: replaced blower resistor
Part number 4C2Z-19A70 qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Oct-16	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	17.93	17.93

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-16	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 05-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 5, 2016 10:47:01 PM	No	
20 - Miles			RGASPARD	Oct 5, 2016 10:47:01 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			RGASPARD	Oct 5, 2016 10:47:01 PM	No	
40 - Hours			RGASPARD	Oct 5, 2016 10:47:01 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	17.93
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.93**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27540753
Invoice No. 55345 - 27540753

Client Department:
Department: 55345M
Work Order Description
Front AC working on high only.
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 59,769 - DH

Activity Header
Activity: 15 080 HEATING & REFRIGERATION GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Oct-16	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27540753 Total	
Parts:	17.93
Labor:	0.00
Labor Hours:	0.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**17.93**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27513579
Invoice No. 55345 - 27513579

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C condenser fans check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,423 - DH

Chronology		
Reported	Oct 3, 2016 3:08:16 PM	Oct 3, 2016 3:08:16 PM
Started	Oct 3, 2016 12:00:00 AM	
Completed	Oct 4, 2016 11:06:00 AM	Oct 4, 2016 11:06:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear condenser fans noisy

CAUSE:Broken fan

CORRECTION:Fan replacement

Complaint verified
Rear A/C condenser fans visually inspected one fan found broken
Fan replaced

Rear A/C condenser fans working (ok)

Part used
One (1) condenser fan (Under warranty).

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 03-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 3, 2016 3:17:30 PM	No	
20 - Miles			FSIMON	Oct 3, 2016 3:17:30 PM	No	
30 - Kilometers			FSIMON	Oct 3, 2016 3:17:30 PM	No	
40 - Hours			FSIMON	Oct 3, 2016 3:17:30 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27513579
Invoice No. 55345 - 27513579

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C condenser fans check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	59,423 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27513579 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27469445
Invoice No. 55345 - 27469445

Client Department:
Department: 55345M
Work Order Description
PMB Follow UP ---------->Rear Brake&Rear Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,663 - DH

Chronology		
Reported	Sep 27, 2016 9:36:35 PM	Sep 27, 2016 9:36:35 PM
Started	Sep 27, 2016 12:00:00 AM	
Completed	Sep 27, 2016 10:33:00 PM	Sep 27, 2016 10:33:00 PM
Down Time		

Work Order Notes

Line 10 Replace Rear brakes &Rear tire on L/R
Parts# BRSD 1330 Qty (1)
050017 Qty(2)

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: L/R tire both has nail& worn
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-16	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	43.15
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**43.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27469445
Invoice No. 55345 - 27469445

Client Department:
Department: 55345M
Work Order Description
PMB Follow UP --------->Rear Brake&Rear Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,663 - DH

Activity Header
Activity:20 013/002 REAR BRAKES & DRUMS
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	81.5	163

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27469445
Invoice No. 55345 - 27469445

Client Department:
Department: 55345M
Work Order Description
PMB Follow UP ---------->Rear Brake&Rear Tire
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,663 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc:
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 27, 2016 10:10:59 PM	No	
20 - Miles			DARTHURS	Sep 27, 2016 10:10:59 PM	No	
30 - Kilometers			DARTHURS	Sep 27, 2016 10:10:59 PM	No	
40 - Hours			DARTHURS	Sep 27, 2016 10:10:59 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27469445 Total	
Parts:	206.15
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**206.15**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27403691
Invoice No. 55345 - 27403691

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	58,663 - DH

Chronology		
Reported	Sep 27, 2016 1:58:16 PM	Sep 27, 2016 1:58:16 PM
Started	Sep 27, 2016 12:00:00 AM	
Completed	Sep 27, 2016 10:03:00 PM	Sep 27, 2016 10:03:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB Service

CAUSE: Service due by Mileage

CORRECTION:Change Oil & Filter lube all Pivoting Points Check brakes & Tires
Parts# B329 Qty (1)
Oil 5w20 Qty (7) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 27-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,420 - Check Hood	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,615 - Air Pressure LRI	60 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,616 - Air Pressure LRO	60 Pounds per Square Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	12 32nds of an inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch	L/R tire both has nail& worn	DARTHURS	Sep 27, 2016 9:36:35 PM	Yes	27469445
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	Yes	27469445
77,134 - Brake Pad Thickness RR	4 Inch	Rear Pads	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,135 - Brake Rotor LF	1.596 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,136 - Brake Rotor RF	1.597 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,137 - Brake Rotor LR	1.414 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,138 - Brake Rotor RR	1.415 Inch		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Sep 27, 2016 9:36:35 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Sep 27, 2016 9:36:35 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27403691
Invoice No. 55345 - 27403691

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,663 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Sep-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: DARTHURS Performed on: 27-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Sep 27, 2016 9:37:52 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	Sep 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				9:37:52 PM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Sep 27, 2016 9:37:52 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	Sep 27, 2016 9:37:52 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Sep 27, 2016 9:37:52 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27403691
Invoice No. 55345 - 27403691

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 58,663 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 27, 2016 9:38:22 PM	No	
20 - Miles			DARTHURS	Sep 27, 2016 9:38:22 PM	No	
30 - Kilometers			DARTHURS	Sep 27, 2016 9:38:22 PM	No	
40 - Hours			DARTHURS	Sep 27, 2016 9:38:22 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27403691 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27446854
Invoice No. 55345 - 27446854

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front tires near low specs.		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	**Status:**	40 - Closed (40)
Created By:	RAURODRIGUEZ	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	57,414 - DH

Chronology		
Reported	Sep 18, 2016 8:13:22 AM	Sep 18, 2016 8:13:22 AM
Started	Sep 18, 2016 12:00:00 AM	
Completed	Sep 19, 2016 8:56:00 AM	Sep 19, 2016 8:56:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:
Front tires near low specs.

CAUSE:
Normal wear

CORRECTION:
Mounted and balanced 2 Kenda tires. Set tires to 65 psi and placed them in the front. Torqued lug nuts to 140 LBS. Test drove. Re-torqued to 140 LBS.

Parts. Kenda tires. Part # 050017 qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 18-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 18, 2016 8:23:50 AM	No	
20 - Miles			RAURODRIGUEZ	Sep 18, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:23:50 AM		
30 - Kilometers			RAURODRIGUEZ	Sep 18, 2016 8:23:50 AM	No	
40 - Hours			RAURODRIGUEZ	Sep 18, 2016 8:23:50 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27446854
Invoice No. 55345 - 27446854

Client Department:
Department: 55345M
Work Order Description
Front tires near low specs.
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 57,414 - DH

Activity Header
Activity: 15
Activity Note: Front tires near low specs.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Sep-16	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	81.5	163

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Sep-16	Rodriguez,Raul	1.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order Footer

Work Order 27446854 Total	
Parts:	163.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**163.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27412600
Invoice No. 55345 - 27412600

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs passenger head light		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,205 - DH

Chronology

Reported	Aug 30, 2016 6:13:49 PM	Aug 30, 2016 6:13:49 PM
Started	Aug 30, 2016 12:00:00 AM	
Completed	Aug 30, 2016 10:22:00 PM	Aug 30, 2016 10:22:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: needs passenger head light

CAUSE:blew out

CORRECTION: replaced passenger head light
Part number 9008 qty1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 30-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 30, 2016 6:18:24 PM	No	
20 - Miles			RGASPARD	Aug 30, 2016 6:18:24 PM	No	
30 - Kilometers			RGASPARD	Aug 30, 2016 6:18:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RGASPARD	Aug 30, 2016 6:18:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27412600
Invoice No. 55345 - 27412600

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Needs passenger head light		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	55,205 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Aug-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-16	Gaspard,Ronald	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27412600 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27238118
Invoice No. 55345 - 27238118

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 54,397 - DH

Chronology		
Reported	Aug 24, 2016 12:58:23 PM	Aug 24, 2016 12:58:23 PM
Started	Aug 24, 2016 12:00:00 AM	
Completed	Aug 24, 2016 11:49:00 PM	Aug 24, 2016 11:49:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,137 - Brake Rotor LR	39 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,138 - Brake Rotor RR	39 Inch		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 24, 2016 10:43:52 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 24, 2016 10:43:52 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27238118
Invoice No. 55345 - 27238118

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 54,397 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: RGASPARD Performed on: 24-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 24, 2016 10:44:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 24, 2016 10:44:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 24, 2016 10:44:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 24, 2016 10:44:34 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 24, 2016 10:44:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 24, 2016 10:44:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 24, 2016 10:44:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 24, 2016 10:44:34 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27238118
Invoice No. 55345 - 27238118

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	54,397 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Aug-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 24, 2016 10:44:55 PM	No	
20 - Miles			RGASPARD	Aug 24, 2016 10:44:55 PM	No	
30 - Kilometers			RGASPARD	Aug 24, 2016 10:44:55 PM	No	
40 - Hours			RGASPARD	Aug 24, 2016 10:44:55 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27238118 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27380957
Invoice No. 55345 - 27380957

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Main relay on circuit is bad.		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,723 - DH

Chronology		
Reported	Aug 12, 2016 4:35:45 AM	Aug 12, 2016 4:35:45 AM
Started	Aug 12, 2016 12:00:00 AM	
Completed	Aug 12, 2016 6:52:00 AM	Aug 12, 2016 6:52:00 AM
Down Time		

Work Order Notes

Line 10
Circuit board

COMPLAINT:
Interior lights are dim and passenger double doors are not working and wheelchair lift is not working.

CAUSE:
Main relay on circuit board is bad.

CORRECTION:
Turned off batteries, Removed bad circuit board and installed a new circuit board. Turn batteries back on, check that all switches are functioning properly.

PARTS
Covered under warranty.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 12-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Aug 12, 2016 4:37:50 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDTORRES	Aug 12, 2016 4:37:50 AM	No	
30 - Kilometers			EDTORRES	Aug 12, 2016 4:37:50 AM	No	
40 - Hours			EDTORRES	Aug 12, 2016 4:37:50 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27380957
Invoice No. 55345 - 27380957

Client Department:
Department: 55345M
Work Order Description
Main relay on circuit is bad.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 52,723 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Main relay on circuit board is bad.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-16	Torres,Edwin	0.7333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27380957 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27352141
Invoice No. 55345 - 27352141

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check engine warning light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,257 - DH

Chronology		
Reported	Aug 1, 2016 12:09:18 PM	Aug 1, 2016 12:09:18 PM
Started	Aug 5, 2016 12:00:00 AM	
Completed	Aug 8, 2016 7:11:00 AM	Aug 8, 2016 7:11:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Engine warning light on

CAUSE:Faulty fuel pumps

CORRECTION:Fuel pumps assy. replacement

Fuel system checked
Fuel pumps tested
Faulty Fuel pumps noticed
Fuel pumps assy replaced
Road test performed ok

Parts used:
One (1) pumps assy.(under warranty)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Aug 5, 2016 3:43:02 PM	No	
20 - Miles			FSIMON	Aug 5, 2016 3:43:02 PM	No	
30 - Kilometers			FSIMON	Aug 5, 2016 3:43:02 PM	No	
40 - Hours			FSIMON	Aug 5, 2016 3:43:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27352141
Invoice No. 55345 - 27352141

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check engine warning light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	52,257 - DH

Activity Header
Activity: 15 044 FUEL SYSTEM
Activity Note: Fuel pumps assy
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Sep-16	P11BB-9155-AB	FILTER, FUEL, ROUSH NO CROSS	1	78.94	78.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-16	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order Footer

Work Order 27352141 Total	
Parts:	78.94
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**78.94**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27346285
Invoice No. 55345 - 27346285

Client Department:
Department: 55345M
Work Order Description
W/C securement bag. Anti skid on bridge plate coming off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 51,956 - DH

Chronology		
Reported	Jul 28, 2016 9:08:47 AM	Jul 28, 2016 9:08:47 AM
Started	Jul 28, 2016 12:00:00 AM	
Completed	Jul 29, 2016 2:29:00 PM	Jul 29, 2016 2:29:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
W/C securement bag is ripped and some of the rivets popped off. . Anti skid on bridge plate peeled off.

CAUSE:
Poor Stitching on the wheelchair securement bags cause them to tear over time.

CORRECTION:
Replaced the bag with a new heavy duty bag. Removed the damaged anti skid pads and installed new anti skid pads.

PARTS-
Covered under warranty.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 28-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jul 28, 2016 9:16:21 AM	No	
20 - Miles			EDTORRES	Jul 28, 2016 9:16:21 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			EDTORRES	Jul 28, 2016 9:16:21 AM	No	
40 - Hours			EDTORRES	Jul 28, 2016 9:16:21 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27346285
Invoice No. 55345 - 27346285

Client Department:
Department: 55345M
Work Order Description
W/C securement bag. Anti skid on bridge plate coming off.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 51,956 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: W/C securement bag. Anti skid on bridge plate coming off.
Reason for Repair: 41 Abuse of Equipment
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-16	Torres,Edwin	1.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27346285 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27169138
Invoice No. 55345 - 27169138

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 50,267 - DH

Chronology		
Reported	Jul 12, 2016 10:44:32 AM	Jul 12, 2016 10:44:32 AM
Started	Jul 12, 2016 12:00:00 AM	
Completed	Jul 12, 2016 10:47:00 PM	Jul 12, 2016 10:47:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:Perform PMA Service

CAUSE:Service Due By Mileage

CORRECTION: Change Oil /Filter Lube All Pivoting Points Check Brakes /Replace Air Filter,
Parts# B329 Oil Filter Qty (1)
Parts# PA4075 Air Filter Qty (1)
Oil 5w20 Qty (7) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-16	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 12-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,420 - Check Hood	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,135 - Brake Rotor LF	1.599 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,136 - Brake Rotor RF	1.56 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,137 - Brake Rotor LR	1.653 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,138 - Brake Rotor RR	1.653 Inch		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Jul 12, 2016 8:49:22 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Jul 12, 2016 8:49:22 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27169138
Invoice No. 55345 - 27169138

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 50,267 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 12-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 12, 2016 8:50:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 12, 2016 8:50:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 12, 2016 8:50:13 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	5.18
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27169138
Invoice No. 55345 - 27169138

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	50,267 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 12, 2016 8:50:33 PM	No	
20 - Miles			DARTHURS	Jul 12, 2016 8:50:33 PM	No	
30 - Kilometers			DARTHURS	Jul 12, 2016 8:50:33 PM	No	
40 - Hours			DARTHURS	Jul 12, 2016 8:50:33 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27169138 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**7.10**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27212374
Invoice No. 55345 - 27212374

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
interior Light out		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,637 - DH

Chronology		
Reported	Jun 26, 2016 6:07:48 PM	Jun 26, 2016 6:07:48 PM
Started	Jun 26, 2016 12:00:00 AM	
Completed	Jun 26, 2016 6:14:00 PM	Jun 26, 2016 6:14:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Two interior Light out

CAUSE:Bulb blown

CORRECTION: Replace Two interior Light Light under Warranty,

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 26, 2016 6:09:55 PM	No	
20 - Miles			DARTHURS	Jun 26, 2016 6:09:55 PM	No	
30 - Kilometers			DARTHURS	Jun 26, 2016 6:09:55 PM	No	
40 - Hours			DARTHURS	Jun 26, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:09:55 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27212374
Invoice No. 55345 - 27212374

Client Department:
Department: 55345M
Work Order Description
interior Light out
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,637 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Two interior Light out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jun-16	Arthurs,Durvin	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27212374 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27209121
Invoice No. 55345 - 27209121

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,474 - DH

Chronology		
Reported	Jun 23, 2016 3:19:32 PM	Jun 23, 2016 3:19:32 PM
Started	Jun 23, 2016 12:00:00 AM	
Completed	Jun 24, 2016 9:21:26 AM	Jun 24, 2016 9:21:26 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear A/C issues

CAUSE:Faulty module

CORRECTION:Replace Rear A/C module

Rear A/C module replaced

Parts used:
One (1) rear A/C module(under warranty)
NB:Part provided by ACC

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 23-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 23, 2016 3:36:06 PM	No	
20 - Miles			FSIMON	Jun 23, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:36:06 PM		
30 - Kilometers			FSIMON	Jun 23, 2016 3:36:06 PM	No	
40 - Hours			FSIMON	Jun 23, 2016 3:36:06 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27209121
Invoice No. 55345 - 27209121

Client Department:
Department: 55345M
Work Order Description
Rear A/C
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,474 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-16	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27209121 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27207220
Invoice No. 55345 - 27207220

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Rear A/C check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	48,275 - DH

Chronology		
Reported	Jun 22, 2016 3:48:32 PM	Jun 22, 2016 3:48:32 PM
Started	Jun 23, 2016 12:00:00 AM	
Completed	Jun 23, 2016 12:29:00 PM	Jun 23, 2016 12:29:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear A/C not working

CAUSE:Dirty orifice tube

CORRECTION:Replace orifice tube

Complaint verified
Rear A/C system tested
Clogged orifice tube
Orifice tube replaced

Parts used:
One (1) orifice tube YG380

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?						
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27207220
Invoice No. 55345 - 27207220

Client Department:
Department: 55345M
Work Order Description
Rear A/C check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 48,275 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-16	YG380	TUBE, ORIFICE, A/C, E450, BLACK	1	4.26	4.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	4.26
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.26**

Work Order Footer

Work Order 27207220 Total	
Parts:	4.26
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27184403
Invoice No. 55345 - 27184403

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Driver said rear a/c not working		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	46,968 - DH

Chronology		
Reported	Jun 12, 2016 3:30:51 PM	Jun 12, 2016 3:30:51 PM
Started	Jun 12, 2016 12:00:00 AM	
Completed	Jun 13, 2016 7:54:00 AM	Jun 13, 2016 7:54:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: driver said rear a/c not working

CAUSE: rear a/c fan left unplug

CORRECTION: check rear a/c and replug the rear a/c fan completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jun-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 12, 2016 3:38:01 PM	No	
20 - Miles			HPIERRE	Jun 12, 2016 3:38:01 PM	No	
30 - Kilometers			HPIERRE	Jun 12, 2016 3:38:01 PM	No	
40 - Hours			HPIERRE	Jun 12, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:38:01 PM		

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27184403
Invoice No. 55345 - 27184403

Client Department:
Department: 55345M
Work Order Description
Driver said rear a/c not working
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 46,968 - DH

Activity Header
Activity: 15 001/001/000 AIR CONDITIONING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: C PM Level C
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jun-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27184403 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27063400
Invoice No. 55345 - 27063400

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 45,988 - DH

Chronology		
Reported	Jun 2, 2016 10:41:07 AM	Jun 2, 2016 10:41:07 AM
Started	Jun 2, 2016 12:00:00 AM	
Completed	Jun 2, 2016 9:55:00 PM	Jun 2, 2016 9:55:00 PM
Down Time		

Work Order Notes

Line 10 PmC
Service
Perform pmC service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jun-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Gaspard,Ronald	1.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jun 2, 2016 9:51:50 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jun 2, 2016 9:51:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27063400
Invoice No. 55345 - 27063400

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 45,988 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Gaspard,Ronald	1.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: RGASPARD Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jun 2, 2016 9:38:50 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Jun 2, 2016 9:38:50 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	-	na	RGASPARD	Jun 2, 2016 9:38:50 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Jun 2, 2016 9:38:50 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Jun 2, 2016 9:38:50 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Jun 2, 2016 9:38:50 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Jun 2, 2016 9:38:50 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27063400
Invoice No. 55345 - 27063400

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	45,988 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Jun-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 02-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jun 2, 2016 9:39:14 PM	No	
20 - Miles			RGASPARD	Jun 2, 2016 9:39:14 PM	No	
30 - Kilometers			RGASPARD	Jun 2, 2016 9:39:14 PM	No	
40 - Hours			RGASPARD	Jun 2, 2016 9:39:14 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27063400 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	3.07

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27106506
Invoice No. 55345 - 27106506

Client Department:
Department: 55345M
Work Order Description
Passenger headlight is out
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 43,379 - DH

Chronology		
Reported	May 10, 2016 8:11:46 AM	May 10, 2016 8:11:46 AM
Started	May 10, 2016 12:00:00 AM	
Completed	May 10, 2016 10:15:00 AM	May 10, 2016 10:15:00 AM
Down Time		

Work Order Notes

Line 10 Headlight P

COMPLAINT:
Passenger side headlight is out

CAUSE:
Normal wear

CORRECTION:
Replaced passenger side headlight bulb.

PARTS:
9008 headlight bulb qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-16	Torres,Edwin	0.4666666	0	0
10-May-16	Torres,Edwin	-0.9166666	0	0
10-May-16	Torres,Edwin	0.45	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 10-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 10, 2016 8:34:32 AM	No	
20 - Miles			EDTORRES	May 10, 2016 8:34:32 AM	No	
30 - Kilometers			EDTORRES	May 10, 2016 8:34:32 AM	No	
40 - Hours			EDTORRES	May 10, 2016 8:34:32 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27106506
Invoice No. 55345 - 27106506

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Passenger headlight is out		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	43,379 - DH

Activity Header
Activity: 15 034/001/000 HEADLAMP
Activity Note: Passenger headlight is out
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 02 Burned, Scorched, Melted, Blistered
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-May-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-May-16	Torres,Edwin	0.5166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order Footer

Work Order 27106506 Total	
Parts:	5.79
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.79**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27085689
Invoice No. 55345 - 27085689

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift not working		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	42,059 - DH

Chronology		
Reported	May 2, 2016 9:39:54 AM	May 2, 2016 9:39:54 AM
Started	May 2, 2016 12:00:00 AM	
Completed	May 2, 2016 10:00:00 AM	May 2, 2016 10:00:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Lift not working properly

CAUSE:Bad connection

CORRECTION:Lift electrical circuit repair

Complaint verified
Interlock electrical circuit repaired
Lift working ok

No part used

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 2, 2016 9:51:00 AM	No	
20 - Miles			FSIMON	May 2, 2016 9:51:00 AM	No	
30 - Kilometers			FSIMON	May 2, 2016 9:51:00 AM	No	
40 - Hours			FSIMON	May 2, 2016 9:51:00 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27085689
Invoice No. 55345 - 27085689

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Lift not working		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	42,059 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-16	Simon,Fritz	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27085689 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27081415
Invoice No. 55345 - 27081415

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Front A/C check		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,990 - DH

Chronology		
Reported	Apr 28, 2016 8:51:04 AM	Apr 28, 2016 8:51:04 AM
Started	Apr 28, 2016 12:00:00 AM	
Completed	Apr 28, 2016 2:27:00 PM	Apr 28, 2016 2:27:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Front A/C blowing to the windshield at any modes

CAUSE:Defective vacuum reservoir

CORRECTION:Vacuum reservoir replacement

Complaint verified
Vacuum reservoir tested
Vacuum reservoir found defective
Vacuum reservoir replaced
Front A/C blowing through the front vents normally

Parts utilized:
One (1) vacuum reservoir #YC2Z-19A566-AA
One (1) valve assy #D7OZ_19A563-A

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 28, 2016 9:27:57 AM	No	
20 - Miles			FSIMON	Apr 28, 2016 9:27:57 AM	No	
30 - Kilometers			FSIMON	Apr 28, 2016 9:27:57 AM	No	
40 - Hours			FSIMON	Apr 28, 2016 9:27:57 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27081415
Invoice No. 55345 - 27081415

Client Department:
Department: 55345M
Work Order Description
Front A/C check
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,990 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-16	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	25.81	25.81
28-Apr-16	D7OZ-19A563-A	VALVE, SUCTION, A/C	1	4.9	4.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	30.71
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.71**

Work Order Footer

Work Order 27081415 Total	
Parts:	30.71
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**30.71**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27080698
Invoice No. 55345 - 27080698

Client Department:
Department: 55345M
Work Order Description
Rear condenser leaking,
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,990 - DH

Chronology		
Reported	Apr 27, 2016 6:57:02 PM	Apr 27, 2016 6:57:02 PM
Started	Apr 27, 2016 12:00:00 AM	
Completed	Apr 27, 2016 11:26:00 PM	Apr 27, 2016 11:26:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Rear condenser leaking

CAUSE:normal wear/tear

CORRECTION: Remove/Replace condenser,Evacuate and Recharge with freon
Freon (7Lbs)
Condenser Qty (1) Line 20 part provided by ACC under warranty.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 27, 2016 7:01:34 PM	No	
20 - Miles			DARTHURS	Apr 27, 2016 7:01:34 PM	No	
30 - Kilometers			DARTHURS	Apr 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:01:34 PM		
40 - Hours			DARTHURS	Apr 27, 2016 7:01:34 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27080721
Invoice No. 55345 - 27080721

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Interior light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,990 - DH

Chronology		
Reported	Apr 27, 2016 7:16:24 PM	Apr 27, 2016 7:16:24 PM
Started	Apr 27, 2016 12:00:00 AM	
Completed	Apr 27, 2016 11:26:00 PM	Apr 27, 2016 11:26:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: interior light out

CAUSE:blown bulb

CORRECTION: replace interior light
Qty (1) parts under warranty

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 27-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 27, 2016 7:26:21 PM	No	
20 - Miles			DARTHURS	Apr 27, 2016 7:26:21 PM	No	
30 - Kilometers			DARTHURS	Apr 27, 2016 7:26:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			DARTHURS	Apr 27, 2016 7:26:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27080698
Invoice No. 55345 - 27080698

Client Department:
Department: 55345M
Work Order Description
Rear condenser leaking,
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,990 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear condenser leaking
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Arthurs,Durvin	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27080698 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27080721
Invoice No. 55345 - 27080721

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Interior light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	**Status:**	40 - Closed (40)
Created By:	DARTHURS	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,990 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: One interior light out
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Apr-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27080721 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27070006
Invoice No. 55345 - 27070006

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Battery holder door broke		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,990 - DH

Chronology		
Reported	Apr 22, 2016 12:57:17 PM	Apr 22, 2016 12:57:17 PM
Started	Apr 22, 2016 12:00:00 AM	
Completed	Apr 25, 2016 8:15:00 AM	Apr 25, 2016 8:15:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: battery holder door

CAUSE: normal wear

CORRECTION: replace battery holder door complete
Part # 4941688= battery holder door qty 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-17	MTP-27-COR	OUT OF SERVICE CORE, BATTERY	2	16	32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 22-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 22, 2016 1:10:24 PM	No	
20 - Miles			HPIERRE	Apr 22, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:10:24 PM		
30 - Kilometers			HPIERRE	Apr 22, 2016 1:10:24 PM	No	
40 - Hours			HPIERRE	Apr 22, 2016 1:10:24 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	32.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27070006
Invoice No. 55345 - 27070006

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Battery holder door broke		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,990 - DH

Activity Header
Activity: 15 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Apr-16	4941688	HOLDER, DOOR, COMPARTMENT, BATTERY, CHAMPION	1	0.91	0.91

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Apr-16	Pierre,Hubert J	0.9166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.91
Labor:	0.00
Labor Hours:	0.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.91**

Work Order Footer

Work Order 27070006 Total	
Parts:	32.91
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**32.91**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 27006322
Invoice No. 55345 - 27006322

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,690 - DH

Chronology		
Reported	Apr 19, 2016 9:47:12 AM	Apr 19, 2016 9:47:12 AM
Started	Apr 19, 2016 12:00:00 AM	
Completed	Apr 19, 2016 10:56:00 PM	Apr 19, 2016 10:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE:Service Due by Mileage

CORRECTION:Drain oil / replace filter lube all pivoting points clean rear AC filter
Parts# B329 oil filter Qty (1)
Oil 5w20 Qty (7) Qts

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,420 - Check Hood	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done	battery door catch missing	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,135 - Brake Rotor LF	1.601 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,137 - Brake Rotor LR	1.418 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,138 - Brake Rotor RR	1.417 Inch		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Apr 19, 2016 10:55:48 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Apr 19, 2016 10:55:48 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 27006322
Invoice No. 55345 - 27006322

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,690 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: DARTHURS Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Apr 19, 2016 9:47:58 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Apr 19, 2016 9:47:58 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Apr 19, 2016 9:47:58 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 27006322
Invoice No. 55345 - 27006322

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	41,690 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Arthurs,Durvin	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 19, 2016 9:48:28 PM	No	
20 - Miles			DARTHURS	Apr 19, 2016 9:48:28 PM	No	
30 - Kilometers			DARTHURS	Apr 19, 2016 9:48:28 PM	No	
40 - Hours			DARTHURS	Apr 19, 2016 9:48:28 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 27006322 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.48

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27063194
Invoice No. 55345 - 27063194

Client Department:
Department: 55345M
Work Order Description
Head LF/ two front marker bulb out
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,690 - DH

Chronology		
Reported	Apr 19, 2016 9:58:32 PM	Apr 19, 2016 9:58:32 PM
Started	Apr 19, 2016 12:00:00 AM	
Completed	Apr 19, 2016 10:52:00 PM	Apr 19, 2016 10:52:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: LF head light bulb out / 2 front marker bulb,

CAUSE:bulb blown

CORRECTION: Replace head light bulb/both marker light bulb
Parts # 9008 Qty (1)
Parts#168 Qty (2)

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 19, 2016 10:04:02 PM	No	
20 - Miles			DARTHURS	Apr 19, 2016 10:04:02 PM	No	
30 - Kilometers			DARTHURS	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:04:02 PM		
40 - Hours			DARTHURS	Apr 19, 2016 10:04:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27063194
Invoice No. 55345 - 27063194

Client Department:
Department: 55345M
Work Order Description
Head LF/ two front marker bulb out
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 41,690 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Pm follow up
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Apr-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
20-Apr-16	168	BULB, WEDGE, 12V/3CP	2	0.23	0.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	6.25
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.25**

Work Order Footer

Work Order 27063194 Total	
Parts:	6.25
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 27006294
Invoice No. 55345 - 27006294

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP-------->need front tires		Ford E450 Champion Challenger	
Requested By:	HPIERRE	**Status:**	40 - Closed (40)
Created By:	HPIERRE	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	37,412 - DH

Chronology		
Reported	Mar 16, 2016 9:41:30 PM	Mar 16, 2016 9:41:30 PM
Started		
Completed	Mar 16, 2016 10:34:00 PM	Mar 16, 2016 10:34:00 PM
Down Time		

Work Order Notes

Line 10 Need front tires

Front tires below spect
Replace two front tires completed
Parts 192659 qt 2

Activity Header
Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: need to front tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 27006294
Invoice No. 55345 - 27006294

Client Department:
Department: 55345M
Work Order Description
FTLMPMI_FOLLOWUP-------->need front tires
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 37,412 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: RISK ASSESSMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Mar-16	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	113.79	227.58

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: RISK ASSESSMENT
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 16, 2016 10:26:16 PM	No	
20 - Miles			HPIERRE	Mar 16, 2016 10:26:16 PM	No	
30 - Kilometers			HPIERRE	Mar 16, 2016 10:26:16 PM	No	
40 - Hours			HPIERRE	Mar 16, 2016 10:26:16 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	227.58
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**227.58**

Work Order Footer

Work Order 27006294 Total	
Parts:	227.58
Labor:	0.00
Labor Hours:	0.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**227.58**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26887407
Invoice No. 55345 - 26887407

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 37,412 - DH

Chronology		
Reported	Mar 16, 2016 3:16:59 PM	Mar 16, 2016 3:16:59 PM
Started	Mar 16, 2016 12:00:00 AM	
Completed	Mar 16, 2016 10:30:00 PM	Mar 16, 2016 10:30:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: regular maintenance

CORRECTION: perform service,lube all pivoting point and change front tires completed
Parts # oil filter B329 qty1
Oil# 5w20 qt6

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Mar-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,420 - Check Hood	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch	need to front tires	HPIERRE	Mar 16, 2016 9:41:30 PM	Yes	27006294
60,632 - Tread Depth LF	5 32nds of an inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,135 - Brake Rotor LF	42 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,136 - Brake Rotor RF	42 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,137 - Brake Rotor LR	40 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,138 - Brake Rotor RR	40 Inch		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Mar 16, 2016 9:41:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Mar 16, 2016 9:41:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26887407
Invoice No. 55345 - 26887407

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	**Status:**	40 - Closed (40)
Created By:	RGASPARD	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	37,412 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 16, 2016 9:42:35 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 16, 2016 9:42:35 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 16, 2016 9:42:35 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26887407
Invoice No. 55345 - 26887407

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 37,412 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 16, 2016 9:43:03 PM	No	
20 - Miles			HPIERRE	Mar 16, 2016 9:43:03 PM	No	
30 - Kilometers			HPIERRE	Mar 16, 2016 9:43:03 PM	No	
40 - Hours			HPIERRE	Mar 16, 2016 9:43:03 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26887407 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26941729
Invoice No. 55345 - 26941729

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Rear A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,260 - DH

Chronology		
Reported	Mar 7, 2016 1:20:07 PM	Mar 7, 2016 1:20:07 PM
Started	Mar 7, 2016 12:00:00 AM	
Completed	Mar 8, 2016 8:19:00 AM	Mar 8, 2016 8:19:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear A/C not blowing cold

CAUSE:Low in refrigerant

CORRECTION:Pressure adjustment

Driver's complaint verified
Rear compressor cycling on and off
Rear AC low and high sides found low pressures
Recovery performed
Vacuum and leak test performed
Leak test passed(Robinair A/C machine)
Oil added
Recharge completed
Rear AC working ok

Bus returned in service

NB : Bus needs to be monitored for eventual AC lines issues

No parts utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 07-MAR-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 7, 2016 3:29:39 PM	No	
20 - Miles			FSIMON	Mar 7, 2016 3:29:39 PM	No	
30 - Kilometers			FSIMON	Mar 7, 2016 3:29:39 PM	No	
40 - Hours			FSIMON	Mar 7, 2016 3:29:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26941729
Invoice No. 55345 - 26941729

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check Rear A/C		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	36,260 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26941729 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26715074
Invoice No. 55345 - 26715074

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 33,035 - DH

Chronology		
Reported	Feb 11, 2016 10:13:20 AM	Feb 11, 2016 10:13:20 AM
Started	Feb 11, 2016 12:00:00 AM	
Completed	Feb 11, 2016 11:24:00 PM	Feb 11, 2016 11:24:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty1
Engine oil 5w20 qty 6qts Line 20 H13- 2 QTY

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Mediun Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Gaspard,Ronald	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Mediun Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 11-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,632 - Tread Depth LF	6 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Feb 11, 2016 11:18:37 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 11, 2016 11:18:37 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.92**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26715074
Invoice No. 55345 - 26715074

Client Department:
Department: 55345M
Work Order Description
PM B
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 33,035 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	2	7.86	15.72

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Gaspard,Ronald	0.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM B
Task: PM B SERVICE Performed by: RGASPARD Performed on: 11-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 11, 2016 11:19:35 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Feb 11, 2016 11:19:35 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
201,000 - Service Crankcase Breather	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Feb 11, 2016 11:19:35 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Feb 11, 2016 11:19:35 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	15.72
Labor:	0.00
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**15.72**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26715074
Invoice No. 55345 - 26715074

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	33,035 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 11, 2016 11:19:59 PM	No	
20 - Miles			RGASPARD	Feb 11, 2016 11:19:59 PM	No	
30 - Kilometers			RGASPARD	Feb 11, 2016 11:19:59 PM	No	
40 - Hours			RGASPARD	Feb 11, 2016 11:19:59 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26715074 Total	
Parts:	17.64
Labor:	0.00
Labor Hours:	2.23

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**17.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26872893
Invoice No. 55345 - 26872893

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Seatbelt Extension		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,761 - DH

Chronology		
Reported	Feb 2, 2016 5:53:36 AM	Feb 2, 2016 5:53:36 AM
Started	Feb 2, 2016 12:00:00 AM	
Completed	Feb 3, 2016 9:45:00 AM	Feb 3, 2016 9:45:00 AM
Down Time		

Work Order Notes

Line 10 Missing Seatbelt Extension

Placed 2 new seatbelt extension inside vehicle because they were missing.

Parts- qty 2 seatbelt extenaion Q5-6340-24-INT

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 02-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 2, 2016 7:04:52 AM	No	
20 - Miles			EDTORRES	Feb 2, 2016 7:04:52 AM	No	
30 - Kilometers			EDTORRES	Feb 2, 2016 7:04:52 AM	No	
40 - Hours			EDTORRES	Feb 2, 2016 7:04:52 AM	No	

Activity Sub Total

Activity 5 Sub Total
Parts: 0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26872893
Invoice No. 55345 - 26872893

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Seatbelt Extension		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	31,761 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Seatbelt Extension
Reason for Repair: 41 Abuse of Equipment
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Aug-16	Q5-6340-24-INT	EXTENSION	2	20.64	41.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Feb-16	Torres,Edwin	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	41.28
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**41.28**

Work Order Footer

Work Order 26872893 Total	
Parts:	41.28
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**41.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26843069
Invoice No. 55345 - 26843069

Client Department:
Department: 55345M
Work Order Description
TRAPEZZE MDT NOT WORKING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: Yes

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,797 - DH

Chronology		
Reported	Jan 19, 2016 10:43:00 AM	Jan 19, 2016 10:43:00 AM
Started	Jan 19, 2016 12:00:00 AM	
Completed	Jan 21, 2016 3:18:43 PM	Jan 21, 2016 3:18:43 PM
Down Time		

Work Order Notes

Line 10 19Jan2016. Written by Rob

COMPLAINT: mdt will turn on but not recognize touchscreen inputs.

CAUSE: diagnosed as faulty wire harness.

CORRECTION: removed mdt from vehicle and install in another vehicle with known good working mdt system.
Mdt powered on and functioned normally with known good wire harness.
Removed and reinstalled into original vehicle with replacement wire harness.
Mdt performed normally and would accept touchscreen input.
Issue resolved.

Wire harness provided under warranty.
No parts used. Line 20

20Jan2016. Written by Edwin.

COMPLAINT.
MDT was not working when driver tried to use it this morning.

CORRECTION
Found that when I press on harness the screen starts pressing on different options. Since harness was changed yesterday I believe the problem is with the head units rear soldering for make pins. I verified that all pins are pointing straight out. Installed our spare Ranger head unit and its working properly at this time.
Was told by David K. That he will contact Palm Tran to have them change the unit to this vehicle.

PARTS-no parts used at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect

Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Manzino,Robert C	0.1666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 19-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Jan 19, 2016 11:03:05 AM	No	
20 - Miles			RMANZINO	Jan 19, 2016 11:03:05 AM	No	
30 - Kilometers			RMANZINO	Jan 19, 2016 11:03:05 AM	No	
40 - Hours			RMANZINO	Jan 19, 2016 11:03:05 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26843069
Invoice No. 55345 - 26843069

Client Department:
Department: 55345M
Work Order Description
TRAPEZZE MDT NOT WORKING PROPERLY
Requested By: CVERGARA
Created By: CVERGARA
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: Yes

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 30,797 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note: Diagnose and repair mdt issue
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Jan-16	Manzino,Robert C	2	0	0
21-Jan-16	Torres,Edwin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26843069 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26741392
Invoice No. 55345 - 26741392

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Headlight issue		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	29,270 - DH

Chronology		
Reported	Jan 6, 2016 7:58:38 AM	Jan 6, 2016 7:58:38 AM
Started	Jan 6, 2016 12:00:00 AM	
Completed	Jan 6, 2016 9:02:00 AM	Jan 6, 2016 9:02:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Left Headlight not glowing

CAUSE:Normal wear

CORRECTION:Headlight replacement

Driver's complaint verified
Left front headlight bulb found defective
Left front headlight bulb replaced

Part used:
One (1) bulb H 13

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 06-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 6, 2016 8:08:04 AM	No	
20 - Miles			FSIMON	Jan 6, 2016 8:08:04 AM	No	
30 - Kilometers			FSIMON	Jan 6, 2016 8:08:04 AM	No	
40 - Hours			FSIMON	Jan 6, 2016 8:08:04 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26741392
Invoice No. 55345 - 26741392

Client Department:
Department: 55345M
Work Order Description
Headlight issue
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 29,270 - DH

Activity Header
Activity: 15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-16	Simon,Fritz	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order Footer

Work Order 26741392 Total	
Parts:	7.41
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**7.41**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26734895
Invoice No. 55345 - 26734895

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Engine light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	29,119 - DH

Chronology		
Reported	Dec 30, 2015 3:28:36 PM	Dec 30, 2015 3:28:36 PM
Started	Dec 30, 2015 12:00:00 AM	
Completed	Dec 31, 2015 12:26:33 PM	Dec 31, 2015 12:26:33 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Engine light on

CAUSE:Lean condition (code PO174)

CORRECTION:Air filter replacement

Driver's complaint verified
Engine scanned, code Po174 found
Air filter replaced
Code cleared
Bus road test performed ok
No "engine light on"

Parts utilized:
One (1) Air filter #PA4075

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 30-DEC-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 30, 2015 3:33:02 PM	No	
20 - Miles			FSIMON	Dec 30, 2015 3:33:02 PM	No	
30 - Kilometers			FSIMON	Dec 30, 2015 3:33:02 PM	No	
40 - Hours			FSIMON	Dec 30, 2015 3:33:02 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26734895
Invoice No. 55345 - 26734895

Client Department:
Department: 55345M
Work Order Description
Engine light on
Requested By: FSIMON
Created By: FSIMON
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 2 - Medium
Driver:
Phone:
ETA:
Meter: 29,119 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Dec-15	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-15	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order Footer

Work Order 26734895 Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**5.18**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26721287
Invoice No. 55345 - 26721287

Client Department:
Department: 55345M
Work Order Description
REPLACE WHEELCHAIR SECUREMENT BAG
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,941 - DH

Chronology		
Reported	Dec 23, 2015 10:17:47 PM	Dec 23, 2015 10:17:47 PM
Started	Dec 23, 2015 12:00:00 AM	
Completed	Dec 23, 2015 10:56:00 PM	Dec 23, 2015 10:56:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs driver side tie down bag.

CAUSE:ripped.

CORRECTION: replaced tie down bag.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Dec-15	Gaspard,Ronald	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 23-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		RGASPARD	Dec 23, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				10:48:21 PM		
20 - Miles			RGASPARD	Dec 23, 2015 10:48:21 PM	No	
30 - Kilometers			RGASPARD	Dec 23, 2015 10:48:21 PM	No	
40 - Hours			RGASPARD	Dec 23, 2015 10:48:21 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26721287
Invoice No. 55345 - 26721287

Client Department:
Department: 55345M
Work Order Description
REPLACE WHEELCHAIR SECUREMENT BAG
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,941 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE WHEEL CHAIR SECUREMENT BAG
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
23-Dec-15	Gaspard,Ronald	0.95	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26721287 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26575108
Invoice No. 55345 - 26575108

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,669 - DH

Chronology		
Reported	Dec 16, 2015 3:37:04 PM	Dec 16, 2015 3:37:04 PM
Started	Dec 17, 2015 3:40:00 PM	
Completed	Dec 18, 2015 3:22:22 PM	Dec 18, 2015 3:22:22 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Inspection due

CAUSE:

CORRECTION: Replace oil and oil filter

Parts used. 6 quarts oil. 5 -w20. 1 oil filter. B-329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	2	1.92	3.84

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Dec-15	Capazzoli,Louis	0.25	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 18-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,631 - Tread Depth RF	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,632 - Tread Depth LF	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,633 - Tread Depth RRO	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,634 - Tread Depth RRI	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,635 - Tread Depth LRI	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,636 - Tread Depth LRO	14 32nds of an inch		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,131 - Brake Pad Thickness LF	Inch	12 mm	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,132 - Brake Pad Thickness RF	Inch	12 mm	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,133 - Brake Pad Thickness LR	Inch	12 mm	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,134 - Brake Pad Thickness RR	Inch	12mm	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,136 - Brake Rotor RF	Inch	n /a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Dec 18, 2015 2:36:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	3.84
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**3.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26575108
Invoice No. 55345 - 26575108

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 28,669 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Dec-15	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 18-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Dec 18, 2015 2:37:05 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26575108
Invoice No. 55345 - 26575108

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	28,669 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 18-DEC-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Dec 18, 2015 2:37:29 PM	No	
20 - Miles			LCAPAZZOLI	Dec 18, 2015 2:37:29 PM	No	
30 - Kilometers			LCAPAZZOLI	Dec 18, 2015 2:37:29 PM	No	
40 - Hours			LCAPAZZOLI	Dec 18, 2015 2:37:29 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26575108 Total	
Parts:	3.84
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	**3.84**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26652124
Invoice No. 55345 - 26652124

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	25,989 - DH

Chronology		
Reported	Nov 30, 2015 3:32:30 PM	Nov 30, 2015 3:32:30 PM
Started		
Completed	Dec 1, 2015 9:07:00 AM	Dec 1, 2015 9:07:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Deflated tires

CAUSE:unknown

CORRECTION:Tires inflated

Tires inspected
Two front tires inflated 65 psi

No parts utilized

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment

Check List

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 30-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 30, 2015 3:38:33 PM	No	
20 - Miles			FSIMON	Nov 30, 2015 3:38:33 PM	No	
30 - Kilometers			FSIMON	Nov 30, 2015 3:38:33 PM	No	
40 - Hours			FSIMON	Nov 30, 2015 3:38:33 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26652124
Invoice No. 55345 - 26652124

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Check tires		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	2 - Medium
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	25,989 - DH

Activity Header
Activity: 15 017 TIRES, TUBES, LINERS & VALVES
Activity Note: Tires air pressure check
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Dec-15	Simon,Fritz	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26652124 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26602053
Invoice No. 55345 - 26602053

Client Department:
Department: 55345M
Work Order Description
REPLACE REAR BRAKES AND ROTOR
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 25,575 - DH

Chronology		
Reported	Nov 19, 2015 4:51:54 PM	Nov 19, 2015 4:51:54 PM
Started	Nov 19, 2015 12:00:00 AM	
Completed	Nov 19, 2015 11:22:00 PM	Nov 19, 2015 11:22:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: needs left rear rotor,and brake pads . Needs front brakes job also.

CAUSE: NORMAL WEAR

CORRECTION: replaced left rear rotor , brake pads and seal. And replaced front brake pads.
Part number rear rotor: 8c2z-2c026-a qty1.
Part number seal: cc3z-1s175-a qty1.
Part number rear pads :BRSD1330 qty1.
Part number front brake pads:BRSD1328qty1.
Torque all tires to specification ,first torque to left front wheel and right front wheel and left rear wheel and right rear wheel at 140lbs. Test drive vehicle retorque left front wheel, right front wheel, left rear wheel and right rear wheel at 140 ft lbs.

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Nov-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
20-Nov-15	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Gaspard,Ronald	0.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 19-NOV-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 19, 2015 10:59:19 PM	No	
20 - Miles			RGASPARD	Nov 19, 2015 10:59:19 PM	No	
30 - Kilometers			RGASPARD	Nov 19, 2015 10:59:19 PM	No	
40 - Hours			RGASPARD	Nov 19, 2015 10:59:19 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	93.47
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**93.47**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26602053
Invoice No. 55345 - 26602053

Client Department:
Department: 55345M
Work Order Description
REPLACE REAR BRAKES AND ROTOR
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 25,575 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: INSTALL REAR BRAKES AND ROTORS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Nov-15	CC3Z-1S175-A	SEAL, HUB, REAR, E450	1	13.07	13.07
23-Nov-15	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	-1	114.61	-114.61
23-Nov-15	BC2Z-1102-B	ROTOR, BRAKE, DISC, FRONT W/INTEGRAL HUB	1	114.61	114.61
23-Nov-15	8C2Z-2C026-A	ROTOR, BRAKE, DISC, REAR, E350 SUPERSEDED BY NC2Z-2C026-A	1	87.98	87.98

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Nov-15	Gaspard,Ronald	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	101.05
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**101.05**

Work Order Footer

Work Order 26602053 Total	
Parts:	194.52
Labor:	0.00
Labor Hours:	3.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**194.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26573758
Invoice No. 55345 - 26573758

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	99 - Cancelled (99)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,981 - DH

Chronology		
Reported	Nov 5, 2015 3:25:41 PM	Nov 5, 2015 3:25:41 PM
Started		
Completed	Nov 6, 2015 11:28:49 AM	Nov 6, 2015 11:28:49 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 TECH CREATED A WORK ORDER ACCIDENTALLY.

HAD TO CANCEL PM SERVICE.

BY DANNY

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	-				No	
10,100 - Safety Inspection	-				No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	-				No	
10,120 - FRA Check All Warning Lights and Alarms	-				No	
10,130 - FRA Check Automatic Transmission Neutral	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Start Operation						
10,140 - Check Service Brakes	-				No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	-				No	
10,160 - FRA Check Instruments and Horns	-				No	
10,170 - Check Fast Idle	-				No	
10,180 - Check Starter Protection Circuit	-				No	
10,190 - Check Reverse Warning System	-				No	
11,100 - Check Parking Brake	-				No	
11,110 - Check HVAC Switches and Other Controls	-				No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	-				No	
11,130 - FRA Check Wiper and Washer Operation	-				No	
11,140 - Road Test: Check for Proper Operation	-				No	
11,150 - Perform Brake Test	-				No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch				No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit				No	
11,170 - FRA Check Door Operation	-				No	
11,180 - FRA Check Operation of All Other Accessories	-				No	
20,000 - SECTION 2 Interior Circle Inspection	-				No	
20,210 - Check Condition of Operator's Area	-				No	
20,220 - Check Accelerator and Brake Pedals	-				No	
20,230 - FRA Check Wiring Under Dash	-				No	
20,240 - FRA Check Interior Lights	-				No	
20,250 - FRA Check Interior Electrical Panels	-				No	
20,260 - Check Stop Request System	-				No	
20,270 - Check Fare Box Mounting (If Applicable)	-				No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	-				No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	-				No	
22,100 - Check Emergency Windows and Glass Condition	-				No	
22,110 - Check Emergency Hatches	-				No	
22,120 - Check All Safety Equipment	-				No	
30,000 - SECTION 3 Exterior Circle Inspection	-				No	
30,310 - Check Passenger Doors	-				No	
30,320 - Inspect Step-well and Hand Rails	-				No	
30,330 - Check Wheelchair Lift Operation	-				No	
30,340 - FRA Check Destination Sign and Run Box	-				No	
30,350 - FRA Inspect Mirror and Mountings	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30,360 - Check for Physical Damage and Decals	-				No	
30,370 - Check Wiper Blade and Arm Condition	-				No	
30,380 - Check Exterior Compartment Doors	-				No	
30,390 - FRA Check Fuel Tank Cap	-				No	
33,100 - Check Lights and Reflectors	-				No	
33,110 - Check License Plate, Permits and State Inspection Decals	-				No	
40,000 - SECTION 4 Engine Compartment Inspection	-				No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	-				No	
40,420 - Check Hood	-				No	
40,430 - Check Fan, Shroud and Radiator	-				No	
40,440 - Test Coolant System Using Test Strips and Record Results	-				No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No				No	
40,442 - Freeze Point	Degree Fahrenheit				No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	-				No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-				No	
40,461 - Refractometer Reading	Degree Fahrenheit				No	
40,470 - Pressure Test Cooling System and Check for Leaks	-				No	
40,480 - FRA Check Coolant Hose Condition	-				No	
40,490 - FRA Check Alternator Mount and Condition	-				No	
44,100 - FRA Check Fuel Control and Transmission Connections	-				No	
44,110 - FRA Check Master Cylinder Fluid Level	-				No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	-				No	
44,130 - FRA Check Exhaust System	-				No	
44,140 - FRA Check Intake System	-				No	
44,150 - FRA Inspect Turbocharger	-				No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	-				No	
44,170 - FRA Check All Engine or Belt Driven Components	-				No	
44,180 - FRA Check for Leaks	-				No	
44,190 - FRA Perform Battery Inspection	-				No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	-				No	
50,000 - SECTION 5 Steering System Inspection	-				No	
50,510 - Check Entire Steering System	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 Tires and Wheel Inspection	-				No	
60,610 - FRA Check and Record Air Pressure	-				No	
60,611 - Air Pressure RF	Pounds per Square Inch				No	
60,612 - Air Pressure LF	Pounds per Square Inch				No	
60,613 - Air Pressure RRO	Pounds per Square Inch				No	
60,614 - Air Pressure RRI	Pounds per Square Inch				No	
60,615 - Air Pressure LRI	Pounds per Square Inch				No	
60,616 - Air Pressure LRO	Pounds per Square Inch				No	
60,620 - Check Valve Stems and Caps	-				No	
60,630 - Check and Record Tread Depth	-				No	
60,631 - Tread Depth RF	32nds of an inch				No	
60,632 - Tread Depth LF	32nds of an inch				No	
60,633 - Tread Depth RRO	32nds of an inch				No	
60,634 - Tread Depth RRI	32nds of an inch				No	
60,635 - Tread Depth LRI	32nds of an inch				No	
60,636 - Tread Depth LRO	32nds of an inch				No	
60,640 - Check for Mismatched Tread or Casing Design	-				No	
60,650 - Check Sidewall Wear	-				No	
60,660 - Inspect for Cuts and Tears	-				No	
60,670 - Check Dual Mating With Square	-				No	
60,680 - Check Wheels for Cracks and Loose Lugs	-				No	
60,690 - Check Tires for Irregular or Alignment Wear	-				No	
66,100 - FRA Check Outer Hubs for Leaks	-				No	
70,000 - SECTION 7 Under Vehicle Inspection	-				No	
70,710 - Check Vibration Damper	-				No	
70,720 - Check Engine and Transmission Mounts	-				No	
70,730 - FRA Check Starter	-				No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	-				No	
70,750 - FRA Check Transmission for Leaks	-				No	
70,760 - FRA Check Differential Breather and Fluid	-				No	
70,770 - FRA Check Exhaust System	-				No	
70,780 - Check Driveline, U-joint and Slip Yokes	-				No	
70,790 - Check All Body Mounts and Chassis Frame	-				No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	-				No	
77,110 - FRA Check Fuel Tank	-				No	
77,120 - Check Suspension Components	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	-				No	
77,131 - Brake Pad Thickness LF	Inch				No	
77,132 - Brake Pad Thickness RF	Inch				No	
77,133 - Brake Pad Thickness LR	Inch				No	
77,134 - Brake Pad Thickness RR	Inch				No	
77,135 - Brake Rotor LF	Inch				No	
77,136 - Brake Rotor RF	Inch				No	
77,137 - Brake Rotor LR	Inch				No	
77,138 - Brake Rotor RR	Inch				No	
77,140 - FRA Check Brake Hoses	-				No	
77,150 - Check King Pins	-				No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	-				No	
80,000 - SECTION 8 PMI Report Completion	-				No	
80,810 - Completion of PMI Report	-				No	
90,000 - SECTION 9 Completion of PMI	-				No	
90,910 - Vehicle Returned to predetermined location	-				No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26573758
Invoice No. 55345 - 26573758

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	99 - Cancelled (99)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,981 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	-				No	
101,000 - FRA Change Oil Filters	No				No	
102,000 - FRA Drain Engine Oil	No				No	
103,000 - FRA Check Transmission Fluid	-				No	
104,000 - Lubricate Chassis	-				No	
105,000 - Replace or Clean A/C Filters	-				No	
107,000 - FRA Change Primary Fuel Filter	No				No	
108,000 - Lube all pivoting Mechanisms	-				No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26573758
Invoice No. 55345 - 26573758

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 99 - Cancelled (99)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 23,981 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26573758 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 26573734
Invoice No. 55345 - 26573734

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,909 - DH

Chronology		
Reported	Nov 5, 2015 3:08:18 PM	Nov 5, 2015 3:08:18 PM
Started	Nov 5, 2015 3:20:00 PM	
Completed	Nov 5, 2015 3:59:00 PM	Nov 5, 2015 3:59:00 PM
Down Time		

Work Order Notes

Line 10 Replaced all rear tires. Torqued tires 140 ft pounds. Road test. Torque 2 nd time.

Parts used. Qty. 4 tires. Rear. Bridgestones. 192659

Activity Header

Activity: 10 017 TIRES, TUBES, LINERS & VALVES
Activity Note: needs all rear tires
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Nov-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	122.66	490.64

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-15	Capazzoli,Louis	0.63	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	490.64
Labor:	0.00
Labor Hours:	0.63
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**490.64**

Work Order Footer

Work Order 26573734 Total	
Parts:	490.64
Labor:	0.00
Labor Hours:	0.63

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**490.64**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26517918
Invoice No. 55345 - 26517918

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 23,909 - DH

Chronology		
Reported	Nov 5, 2015 12:00:00 AM	Nov 5, 2015 12:00:00 AM
Started	Nov 5, 2015 12:00:00 AM	
Completed	Nov 5, 2015 3:20:00 PM	Nov 5, 2015 3:20:00 PM
Down Time		

Work Order Notes

Line 10 Perform. Pm. C inspection

Replace oil and oil filter. Service crankcase breather. Clear all codes.

Parts used. 6 quarts oil. 5w-20. 1 oil filter. B-329

EXHAUST HANGER PART #72660 1 QTY

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Nov-15	72660	USE PUNCH-OUT HANGER, EXHAUST, STEEL, 5PK	1	2.33	2.33
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 05-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Nov 5, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:13:49 PM		
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Nov 5, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:13:49 PM		
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,450 - FRA Check Coolant Recovery	Done		LCAPAZZOLI	Nov 5, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
System Condition & for Leaks				3:13:49 PM		
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,616 - Air Pressure LRO	70 Pounds per		LCAPAZZOLI	Nov 5, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			3:13:49 PM		
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	needs all rear tires	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	Yes	26573734
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,100 - FRA Check Security, Integrity and	Done		LCAPAZZOLI	Nov 5, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Length of Ground Straps				3:13:49 PM		
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,135 - Brake Rotor LF	0 Inch	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Nov 5, 2015 3:13:49 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26517918
Invoice No. 55345 - 26517918

Client Department:
Department: 55345M
Work Order Description
PM C
Requested By: LCAPAZZOLI
Created By: LCAPAZZOLI
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 23,909 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-15	Capazzoli,Louis	2	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM C
Task: PM C SERVICE Performed by: LCAPAZZOLI Performed on: 05-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
201,000 - Service Crankcase Breather	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
302,000 - Check Toe-In and Record Reading	-	n/a	LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	n/a	LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	
305,000 - FRA Change Differential Fluid	Yes		LCAPAZZOLI	Nov 5, 2015 3:16:04 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26517918
Invoice No. 55345 - 26517918

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM C		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	23,909 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26517918 Total	
Parts:	4.25
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**4.25**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26266426
Invoice No. 55345 - 26266426

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,401 - DH

Chronology		
Reported	Oct 2, 2015 12:00:00 AM	Oct 2, 2015 12:00:00 AM
Started	Oct 2, 2015 2:00:00 AM	
Completed	Oct 2, 2015 3:44:00 PM	Oct 2, 2015 3:44:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform. Pm. Oil and filter change

CAUSE:

CORRECTION:

Parts used. 6 quarts oil. 5w-20. 1oil filter. B-329

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Oct-15	Capazzoli,Louis	1.52	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 02-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,135 - Brake Rotor LF	0 Inch		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,140 - FRA Check Brake Hoses	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Oct 2, 2015 3:30:19 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26266426
Invoice No. 55345 - 26266426

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,401 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Oct-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 02-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Oct 2, 2015 3:31:09 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.52

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26266426
Invoice No. 55345 - 26266426

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	**Status:**	40 - Closed (40)
Created By:	LCAPAZZOLI	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,401 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment and Meter Reading
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Oct-15	Capazzoli,Louis	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: Personal Risk Assessment and Meter Reading
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 02-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Oct 2, 2015 2:11:40 PM	No	
20 - Miles			LCAPAZZOLI	Oct 2, 2015 2:11:40 PM	No	
30 - Kilometers			LCAPAZZOLI	Oct 2, 2015 2:11:40 PM	No	
40 - Hours			LCAPAZZOLI	Oct 2, 2015 2:11:40 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26266426 Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	4.02

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**1.52**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26514116
Invoice No. 55345 - 26514116

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
per driver fuel gauge fluctuates		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,022 - DH

Chronology		
Reported	Sep 30, 2015 12:59:00 PM	Sep 30, 2015 12:59:00 PM
Started		
Completed	Oct 1, 2015 4:11:00 PM	Oct 1, 2015 4:11:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:Fuel gauge fluctuation

CAUSE:Dirty fuel gauge magnet

CORRECTION: fuel gauge magnet cleaned

Fuel gauge magnet cleaned

Test drive performed ok

No parts utilized

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 01-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 1, 2015 3:55:31 PM	No	
20 - Miles			FSIMON	Oct 1, 2015 3:55:31 PM	No	
30 - Kilometers			FSIMON	Oct 1, 2015 3:55:31 PM	No	
40 - Hours			FSIMON	Oct 1, 2015 3:55:31 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26514116
Invoice No. 55345 - 26514116

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
per driver fuel gauge fluctuates		Ford E450 Champion Challenger	
Requested By:	CVERGARA	**Status:**	40 - Closed (40)
Created By:	CVERGARA	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	19,022 - DH

Activity Header
Activity: 15 003 INSTRUMENTS, GAUGES, WARNING & SHUT-DOWN DEVICES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26514116 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 26481322
Invoice No. 55345 - 26481322

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Install a new driver side step.		Ford E450 Champion Challenger	
Requested By:	EDTORRES	**Status:**	40 - Closed (40)
Created By:	EDTORRES	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	17,892 - DH

Chronology		
Reported	Sep 20, 2015 3:01:17 PM	Sep 20, 2015 3:01:17 PM
Started	Sep 20, 2015 12:00:00 AM	
Completed	Sep 20, 2015 3:08:00 PM	Sep 20, 2015 3:08:00 PM
Down Time		

Work Order Notes

Line 10 Install a new driver side step.

Installed new driver retro step. Tested step several times, feels snug and secured in place.

No shop parts used. Parts under warranty.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-15	Torres,Edwin	0.0333333	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 20-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 20, 2015 3:07:53 PM	No	
20 - Miles			EDTORRES	Sep 20, 2015 3:07:53 PM	No	
30 - Kilometers			EDTORRES	Sep 20, 2015 3:07:53 PM	No	
40 - Hours			EDTORRES	Sep 20, 2015 3:07:53 PM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.03
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 26481322
Invoice No. 55345 - 26481322

Client Department:
Department: 55345M
Work Order Description
Install a new driver side step.
Requested By: EDTORRES
Created By: EDTORRES
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 17,892 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Install a new driver side step.
Reason for Repair: 23 Modification
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Sep-15	Torres,Edwin	1.05	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26481322 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 26266429
Invoice No. 55345 - 26266429

Client Department:
Department: 55345M
Work Order Description
Exhaust tail pipe hanger loose
Requested By: AOWENS
Created By: AOWENS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 14,871 - DH

Chronology		
Reported	Aug 18, 2015 5:51:55 PM	Aug 18, 2015 5:51:55 PM
Started		
Completed	Aug 18, 2015 6:21:00 PM	Aug 18, 2015 6:21:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: exhaust tail pipe bracket broken

CAUSE:

CORRECTION: replaced. Tail pipe exhaust hanger and bracket. Parts. Exhaust clamp. Part number. 35794. Qty 1. Exhaust hanger. Part number. 72660. Qty. 1

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Aug-15	72660	USE PUNCH-OUT HANGER, EXHAUST, STEEL, 5PK	1	2.33	2.33
19-Aug-15	35794	U-CLAMP, EXHAUST, 3"	1	3.95	3.95

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 18-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				6:15:32 PM		
20 - Miles			LCAPAZZOLI	Aug 18, 2015 6:15:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	6.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.28**

Work Order Footer

Work Order 26266429 Total	
Parts:	6.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**6.28**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 26066567
Invoice No. 55345 - 26066567

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 14,871 - DH

Chronology		
Reported	Aug 18, 2015 3:10:05 PM	Aug 18, 2015 3:10:05 PM
Started	Aug 18, 2015 4:41:00 PM	
Completed	Aug 18, 2015 5:51:00 PM	Aug 18, 2015 5:51:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: completed. Pm. Replaced. Oil. And oil filter.

Parts. Oil. 6 qty 5w20. Oil filter. 1. Qty. b329.

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: light medium duty pmi
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.26	1.26

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

10 Desc: light medium duty pmi
Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 18-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				5:46:16 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,270 - Check Fare Box Mounting (If	-	n/a	LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				5:46:16 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,460 - Record Antifreeze Protection Level	-	n/a	LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				5:46:16 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:46:16 PM		
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Aug 18, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:46:16 PM		
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Aug 18, 2015 5:46:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 26066567
Invoice No. 55345 - 26066567

Client Department:
Department: 55345M
Work Order Description
PM A
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 14,871 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Aug-15	Capazzoli,Louis	1.13	0	0

Activity Sublet
No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 18-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Aug 18, 2015 5:51:18 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 26066567
Invoice No. 55345 - 26066567

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	14,871 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 18-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Aug 18, 2015 5:32:18 PM	No	
20 - Miles			LCAPAZZOLI	Aug 18, 2015 5:32:18 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26066567 Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	1.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.26**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1

Work Order No. 26253696
Invoice No. 55345 - 26253696

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Scheduled Shutting off		Ford E450 Champion Challenger	
Requested By:	FSIMON	**Status:**	40 - Closed (40)
Created By:	FSIMON	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	14,666 - DH

Chronology		
Reported	Aug 10, 2015 12:22:43 PM	Aug 10, 2015 12:22:43 PM
Started	Aug 10, 2015 12:29:00 PM	
Completed	Aug 11, 2015 8:47:00 AM	Aug 11, 2015 8:47:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: shutting off

CAUSE:Smart relay module suspected faulty(complaint cannot be verified)

CORRECTION: Vehicle diagnosed

Cannot duplicate the driver's complaint
Vehicle scanned -No codes.
Vacuum test performed Ok.
Fuses tested ok
Fuel Rail pressure control module OK.
Flow control solenoid tested ok
Bleed solenoid tested ok
Supply solenoid tested ok

Tank pressure compared to Fuel Rail Pressure tested OK.
Power tested ok.
Fuel system bled
Engine is running ok.
SRM suspected faulty.

NO PARTS WAS USE

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Aug-15	Simon,Fritz	1.43	0	0
11-Aug-15	Simon,Fritz	0.62	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 11-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Aug 11, 2015 8:52:31 AM	No	
20 - Miles			FSIMON	Aug 11, 2015 8:52:31 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 26253696 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25821514
Invoice No. 55345 - 25821514

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	10,512 - DH

Chronology		
Reported	Jun 15, 2015 12:00:00 AM	Jun 15, 2015 12:00:00 AM
Started	Jun 15, 2015 12:00:00 AM	
Completed	Jun 17, 2015 10:08:56 AM	Jun 17, 2015 10:08:56 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-B SERVICE COMPLETED
REPLACED OIL FILTER
CHANGED ENGINE OIL
WASHER FLUID ADDED

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM B INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.77	1.77

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jun-15	Gaspard,Ronald	2.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25821514
Invoice No. 55345 - 25821514

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	10,512 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM B SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25821514
Invoice No. 55345 - 25821514

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	10,512 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25821514 Total	
Parts:	1.77
Labor:	0.00
Labor Hours:	2.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.77**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 25970393
Invoice No. 55345 - 25970393

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
BridgeStone Tires		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	8,897 - DH

Chronology		
Reported	Jun 3, 2015 3:52:00 PM	Jun 3, 2015 3:52:00 PM
Started	Jun 3, 2015 12:00:00 AM	
Completed	Jun 3, 2015 3:57:49 PM	Jun 3, 2015 3:57:49 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 FRONT TIRES REPLACED

TIRES TORQUED

LUG NUT INDICATED REPLACED BACK

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?						
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 25970393
Invoice No. 55345 - 25970393

Client Department:
Department: 55345M
Work Order Description
BridgeStone Tires
Requested By: DCARTER
Created By: DCARTER
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4606-P
VIN: 1FDFE4FS7EDB17159
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 8,897 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	-2	156.63	-313.26
01-Jul-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	2	151.66	303.32
03-Jun-15	206361	TIRE, LT225/75R16, BSW, R250, DURAVIS, BRIDGESTONE	2	156.63	313.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jun-15	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order Footer

Work Order 25970393 Total	
Parts:	303.32
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**303.32**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 25951869
Invoice No. 55345 - 25951869

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle Shutting		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,599 - DH

Chronology		
Reported	May 13, 2015 11:01:00 AM	May 13, 2015 11:01:00 AM
Started	May 13, 2015 12:00:00 AM	
Completed	May 22, 2015 11:47:05 AM	May 22, 2015 11:47:05 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT: Vehicle Shutting Off.

CAUSE:

CORRECTION: Vehicle diagnosed for shutting off.
Fuel Tank pressure tested high.
Fuel Rail pressure Tested Ok.
Vacuum Test perform ok

Vehicle is working OK

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 25951869
Invoice No. 55345 - 25951869

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
Vehicle Shutting		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,599 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-15	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25951869 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2

Work Order No. 25946164
Invoice No. 55345 - 25946164

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,167 - DH

Chronology		
Reported	May 14, 2015 2:30:00 PM	May 14, 2015 2:30:00 PM
Started	May 14, 2015 12:00:00 AM	
Completed	May 20, 2015 3:02:42 PM	May 20, 2015 3:02:42 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes(__) No (__).
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.
==========

COMPLAINT:

CAUSE:

CORRECTION: Line 20 VEHICLE SCANNED CODE P0171 FOUND.

TANK PRESSURE TESTED TOO HIGH.

FRP TESTED OK.

DIFFERENCE BETWEEN IS OK.

EVAPORATIVE LINE KIN KED IS REPAIRED.

FUEL SYSTEM BLEEDED.

VEHICLE WORKING OK.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2

Work Order No. 25946164
Invoice No. 55345 - 25946164

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
ENGINE LIGHT ON		Ford E450 Champion Challenger	
Requested By:	DCARTER	**Status:**	40 - Closed (40)
Created By:	DCARTER	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	7,167 - DH

Activity Header
Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-May-15	Simon,Fritz	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25946164 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 25740024
Invoice No. 55345 - 25740024

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	5,858 - DH

Chronology		
Reported	Apr 9, 2015 12:00:00 AM	Apr 9, 2015 12:00:00 AM
Started	Apr 9, 2015 12:00:00 AM	
Completed	Apr 10, 2015 2:18:36 PM	Apr 10, 2015 2:18:36 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PMA

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.63	1.63

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-15	Owens,Arthur	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 25740024
Invoice No. 55345 - 25740024

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	5,858 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 25740024
Invoice No. 55345 - 25740024

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	KCONCEPCION	**Status:**	40 - Closed (40)
Created By:	KCONCEPCION	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	5,858 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 25740024 Total	
Parts:	1.63
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**1.63**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3

Work Order No. 24687421
Invoice No. 55345 - 24687421

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	1,198 - DH

Chronology		
Reported	Jan 27, 2015 3:47:00 PM	Jan 27, 2015 3:47:00 PM
Started	Feb 27, 2015 12:00:00 AM	
Completed	Mar 18, 2015 4:05:26 PM	Mar 18, 2015 4:05:26 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header
Activity: 10 999 TOTAL VEHICLE
Activity Note: PM A INSPECTION
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-15	Simon,Fritz	2.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3

Work Order No. 24687421
Invoice No. 55345 - 24687421

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	1,198 - DH

Activity Header
Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A SERVICE
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3

Work Order No. 24687421
Invoice No. 55345 - 24687421

Client Department:			
Department:	55345M	**Equipment No.:**	4606-P
Work Order Description		**VIN:**	1FDFE4FS7EDB17159
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	**Status:**	40 - Closed (40)
Created By:	DKNOTT	**Priority:**	1 - Low
Assigned To:		**Driver:**	
Class:	WO - WORK ORDER	**Phone:**	
Arrangement:	Unassigned	**ETA:**	
Potential Warranty:	No	**Meter:**	1,198 - DH

Activity Header
Activity: 30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER
Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**

Work Order Footer

Work Order 24687421 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	**0.00**