

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51221024
Invoice Number: 55345-51221024

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM B

VIN: 1FDFE4FSXEDB17155

Requested By: CKARLENS

Status: 40

Created By: CKARLENS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	May 9, 2018	10:33 AM
Started	May 9, 2018	
Completed	May 9, 2018	11:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	139,350	DH
System	139,535	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB Service CAUSE: Service due by Mileage. CORRECTION: Change Oil & Filter Lube all Pivoting Points. check Brakes Clean batteries. Replace drain plugs. Parts # B329 Qty (1) Oil 5W20 Qty (7.0) Qt

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
09-May-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1.00	6.66	6.66



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51410167
Invoice Number: 55345-51410167

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM A

1FDFE4FSXEDB17155

Requested By: CVERGARA

VIN: 40

Created By: CVERGARA

Status: 1

Class: WO

Priority:

Arrangement: Unassigned

Driver:

Potential Warranty: No

Phone:

ETA:

Chronology		
Reported	Jul 10, 2018	10:54 AM
Started	Jul 10, 2018	
Completed	Jul 10, 2018	10:59 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	147,683	DH
System	147,854	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform pmA CAUSE: Preventive Maintenance CORRECTION: Tech Performed pmA Oil filter Qty:1 part#329 Oil Qty:7qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
10-Jul-18	KARLENS,Cyrus	2.00	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 51616899
Invoice Number: 55345-51616899

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Sep 10, 2018	3:15 PM
Started	Sep 10, 2018	
Completed	Sep 10, 2018	11:56 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	156,549	DH
System	156,720	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
10-Sep-18	Gaspard,Ronald	1.55	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.55
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
10-Sep-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51706695
Invoice Number: 55345-51706695

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Oct 4, 2018	2:40 PM
Started	Oct 4, 2018	
Completed	Oct 5, 2018	8:15 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	160,852	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE:Service CORRECTION:Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Replaced maker lights Fixed right rear tire Torque wheels 140 lbs second torque 140 lbs

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
04-Oct-18	Gaspard, Ronald	2.25	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.25
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51910508
Invoice Number: 55345-51910508

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Dec 11, 2018	1:46 PM
Started	Dec 12, 2018	
Completed	Dec 12, 2018	12:30 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	170,013	DH
System	170,462	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMA CAUSE:Service CORRECTION:Perform PMA Service Oil filter B329 qty1 Engine oil 5W20Qty qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Dec-18	Gaspard,Ronald	1.58	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.58
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Dec-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51986864
Invoice Number: 55345-51986864

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FSXEDB17155

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Jan 15, 2019	10:07 AM
Started	Jan 15, 2019	
Completed	Jan 16, 2019	9:00 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	174,288	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service due CORRECTION: Performed and completed pma Changed engine oil and replaced engine oil filter Replaced rear AC filter

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Jan-19	Delva,Terry	1.23	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.23	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Jan-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52165553
Invoice Number: 55345-52165553

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Mar 21, 2019	11:35 AM
Started	Mar 21, 2019	
Completed	Mar 22, 2019	12:16 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	182,563	DH
System	183,071	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: Perform pmA Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts Air filter PA4075 Qty1

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Mar-19	Gaspard, Ronald	1.60	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.60
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52275365****Invoice Number: 55345-52275365****Client Department:****MRC:** 55345M**Equipment:** 4602-P**WO Desc:**

Ford E450 Champion Challenger

PM A**VIN:** 1FDFE4FSXEDB17155**Requested By:**

RGASPARD

Status: 40**Created By:**

RGASPARD

Priority: 1**Class:**

WO

Driver:**Arrangement:**

Unassigned

Phone:**Potential Warranty:**

No

ETA:

Chronology		
Reported	Apr 16, 2019	1:38 PM
Started	Apr 16, 2019	
Completed	Apr 16, 2019	11:15 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	186,582	DH
System	187,085	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity: 10**999 TOTAL VEHICLE****Activity Note:**

Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 1.50	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair: 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
16-Apr-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52442052****Invoice Number: 55345-52442052****Client Department:****MRC:** 55345M**Equipment:** 4602-P**WO Desc:**

PM A

Ford E450 Champion Challenger

Requested By:

DARTHURS

VIN:

1FDFE4FSXEDB17155

Created By:

DARTHURS

Status:

40

Class:

WO

Priority:

1

Arrangement:

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:****Chronology**

Reported	Jun 20, 2019	11:54 AM
Started	Jun 21, 2019	
Completed	Jun 21, 2019	10:00 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	195,195	DH
System	195,496	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA CAUSE: Service due CORRECTION: Performed and completed pmA Changed engine oil and replaced engine oil filter

Activity: 10**999 TOTAL VEHICLE****Activity Note:**

Light Medium Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
21-Jun-19	Delva, Terry	0.72	0.00	0.00

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.72	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
21-Jun-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52539833****Invoice Number: 55345-52539833****Client Department:****MRC:** 55345M**Equipment:** 4602-P**WO Desc:**

PM A

Requested By:

DKNOTT

VIN:

Ford E450 Champion Challenger

1FDFE4FSXEDB17155

Created By:

DKNOTT

Status:

40

Class:

WO

Priority:

1

Arrangement:

Unassigned

Driver:**Potential Warranty:**

No

Phone:**ETA:**

Chronology		
Reported	Jul 26, 2019	11:04 AM
Started		
Completed	Aug 1, 2019	8:29 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	200,136	DH
System	199,878	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PmA Service
	CAUSE: Preventive maintenance
	CORRECTION: PmA

Activity: 10**999 TOTAL VEHICLE****Activity Note:**

Light Medium Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:**

PM A

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

A - PM Level A

Part Failure:

-

Activity Comments**Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
30-Jul-19	B329(F)	FILTER, OIL SAME AS LF3681	-1.00	1.96	-1.96
29-Jul-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

**WorkOrder**55345 Palm Tran Connection
v 2.2

Page 1 of 9

**WorkOrder: 52774742****Invoice Number: 55345-52774742****Client Department:****MRC:** 55345M**Equipment:** 4602-P**WO Desc:**

PM A

Requested By: RRENE**VIN:** 1FDFE4FSXEDB17155**Created By:** RRENE**Status:** 40**Class:** WO**Priority:** 1**Arrangement:** Unassigned**Driver:****Potential Warranty:** No**Phone:****ETA:**

Chronology		
Reported	Oct 11, 2019	11:14 AM
Started		
Completed	Oct 14, 2019	8:48 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	208,774	DH
System	209,075	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: preventive maintenance CORRECTION: perform pmA service lube all Pivoting Points add some Transmission Fluids Completed

Activity: 10**999 TOTAL VEHICLE****Activity Note:** Light Medium Duty PMI**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20**999 TOTAL VEHICLE****Activity Note:** PM A**Reason for Repair:** 08 - Preventive Maintenance**Work Accomplished:** A - PM Level A**Part Failure:** -**Activity Comments****Parts Issued**

Date	Part Number	Description	Qty.	Each	Extended
11-Oct-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52890896
Invoice Number: 55345-52890896

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FSXEDB17155

Requested By:

HPIERRE

Status: 40

Created By:

HPIERRE

Priority: 1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology		
Reported	Nov 14, 2019	12:00 AM
Started	Nov 15, 2019	
Completed	Nov 17, 2019	1:14 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	213,612	DH
System	213,762	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
15-Nov-19	Gaspard, Ronald	1.58	65.00	102.92

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours: 1.58	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	102.92

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
15-Nov-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53126088
Invoice Number: 55345-53126088

Client Department:

MRC: 55345M
WO Desc:
PM A
Requested By: RGASPARD
Created By: RGASPARD
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
1FDFE4FSXEDB17155
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Jan 30, 2020	11:03 AM
Started	Jan 30, 2020	
Completed	Jan 30, 2020	7:05 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	222,027	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA SERVICE CAUSE: PREVENTIVE MAINTENANCE CORRECTION: PERFORM AND COMPLETED PMA SERVICE REPLACED AIR FILTER

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
30-Jan-20	AMRIT TEEMAL,VISHNU	1.50	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
30-Jan-20	B329(F)	FILTER, OIL	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 53235269
Invoice Number: 55345-53235269

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4602-P

Ford E450 Champion Challenger

VIN: 1FDFE4FSXEDB17155

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Mar 2, 2020	7:54 AM
Started	Mar 2, 2020	
Completed	Mar 2, 2020	10:44 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	226,297	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:
	CAUSE:
	CORRECTION:

Activity: 10 **999/999/999 TOTAL VEHICLE**
Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
02-Mar-20	B329(F)	FILTER, OIL, SPIN-ON	1.00	1.96	1.96

Labor Posted



WorkOrder

55345 Palm Tran Connection
v 2.2

Page 1 of 9



WorkOrder: 53558502

Invoice Number: 55345-53558502

Client Department:

MRC:

55345M

Equipment:

4602-P

WO Desc:

Ford E450 Champion Challenger

55345-LIGHT DUTY PMA

VIN:

1FDFE4FSXEDB17155

Requested By:

NSTOLFO

Status:

40

Created By:

NSTOLFO

Priority:

3

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology

Reported

May 28, 2020

10:46 AM

Started

May 28, 2020

Completed

May 29, 2020

12:16 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	234,229	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts

Activity: 5



999/999/999 TOTAL VEHICLE

Activity Note:

PERSONAL RISK ASSESSMENT

Reason for Repair:

SW - Shop Work Order

Work Accomplished:

06 - Inspect

Part Failure:

00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note:

Light Duty PMI

Reason for Repair:

08 - Preventive Maintenance

Work Accomplished:

-

Part Failure:

-

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53582664
Invoice Number: 55345-53582664

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

55345-LIGHT DUTY PMA

Ford E450 Champion Challenger

VIN: 1FDFE4FSXEDB17155

Requested By: RGASPARD

Status: 40

Created By: RGASPARD

Priority: 3

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology

Reported	Jul 9, 2020	9:31 AM
Started	Jul 9, 2020	
Completed	Jul 10, 2020	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	238,440	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Service CORRECTION: perform pmA service Oil filter B329 qty1 Engine oil 10w30 qty 7 Qts

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54186359
Invoice Number: 55345-54186359

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

55345-LIGHT DUTY PMA

Ford E450 Champion Challenger

1FDPE4FSXEDB17155

Requested By: RGASPARD

VIN: 40

Created By: RGASPARD

Status: 3

Class: WO

Priority:

Arrangement: Unassigned

Driver:

Potential Warranty: No

Phone:

ETA:

Chronology

Reported	Feb 11, 2021	12:00 AM
Started	Feb 12, 2021	
Completed	Feb 12, 2021	11:43 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	247,311	DH
System	247,612	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PmA Service CAUSE: preventive maintenance CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Feb-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2.00	4.40	8.80
12-Feb-21	3975927	LAMP, PLATE, LICENSE	1.00	11.96	11.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54489120
Invoice Number: 55345-54489120

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Jun 3, 2022	12:00 AM
Started	Jul 1, 2022	
Completed	Jul 1, 2022	6:36 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	260,358	DH
System	260,544	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Perform PMA Service, CAUSE: Service Due by Mileage, CORRECTION: Change Oil & Filter. Lube all Pivoting Points Check Brake. Clean batteries. Clean A/C filter, parts # B329 Qty (1) Oil 5W30 Qty (7.0) Qts

Activity: 5 **999/999/999 TOTAL VEHICLE**
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **079 DEVICES, SAFETY/STABILITY, TRAILER**
Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 10



WorkOrder: 54489120
Invoice Number: 55345-54489120

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
01-Jul-22	Arthurs,Durvin	1.92	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.92
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
01-Jul-22	B329	FILTER, OIL, SPIN-ON	1.00	2.19	2.19

Labor Posted

Date	Technician	Hours	Rate	Extended
01-Jul-22	Arthurs,Durvin	0.43	0.00	0.00

Activity 20 Sub Total

Parts: 2.19
Labor: 0.00
Labor Hours: 0.43
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 2.19

WorkOrder 54489120 Grand Total

Parts: 2.19
Labor: 0.00
Labor Hours: 2.35
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 2.19

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
54489120	1-Jul-22	260,358	WO	55345-LIGHT DUTY PMA
54648824	13-Jun-22	260,243	WO	55345-PTC INSPECTION



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 10



WorkOrder: 54489120
Invoice Number: 55345-54489120

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMA
Requested By: JUHURST
Created By: JUHURST
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
55650376	13-Jun-22	259,555	WO	F/ SUPPRESSION SYSTEM ALARM ON
54648803	20-May-22	259,254	WO	QCC FLEET INSPECTION

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
55731463	29-Jun-22	260,659	WORC	Road Call (Bus Will Not Move)
55713553	22-Jun-22	260,659	WORC	Road Call (Bus Will Not Move)

PH: Work Order: 54489120 Desc: 55345-LIGHT DUTY PMA
Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 01-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		DARTHURS	Jul 1, 2022 5:45:13 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jul 1, 2022 5:45:17 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		DARTHURS	Jul 1, 2022 5:45:22 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jul 1, 2022 5:45:30 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jul 1, 2022 5:45:37 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		DARTHURS	Jul 1, 2022 5:45:43 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 1, 2022 5:45:49 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jul 1, 2022 5:45:58 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jul 1, 2022 5:46:06 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jul 1, 2022 5:46:10 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jul 1, 2022 5:46:15 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jul 1, 2022 5:46:21 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jul 1, 2022 5:46:27 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jul 1, 2022 5:46:33 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jul 1, 2022 5:46:39 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jul 1, 2022 5:46:46 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done	Clearance Light	DARTHURS	Jul 1, 2022 6:08:01 PM	Yes	55743640
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jul 1, 2022 5:46:59 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	-	Washer Fluid Leaking	DARTHURS	Jul 1, 2022 5:47:35 PM	Yes	55743640
20,800	INSPECT_High Idle Control	Done		DARTHURS	Jul 1, 2022 5:47:42 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jul 1, 2022 5:47:51 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jul 1, 2022 5:47:57 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		DARTHURS	Jul 1, 2022 5:48:02 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jul 1, 2022 5:48:08 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jul 1, 2022 5:48:12 PM	No	
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jul 1, 2022 5:48:19 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jul 1, 2022 5:48:25 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jul 1, 2022 5:48:32 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jul 1, 2022 5:48:37 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		DARTHURS	Jul 1, 2022 5:48:41 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jul 1, 2022 5:48:46 PM	No	
31,000	SSF (Street Side Front)	Done		DARTHURS	Jul 1, 2022 5:48:50 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 1, 2022 5:48:58 PM	No	
31,020	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 1, 2022 5:49:05 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 5:49:09 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 1, 2022 5:49:14 PM	No	
32,000	Engine Inspection	Done		DARTHURS	Jul 1, 2022 5:49:19 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		DARTHURS	Jul 1, 2022 5:49:25 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jul 1, 2022 5:49:32 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jul 1, 2022 5:49:40 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Jul 1, 2022 5:49:53 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jul 1, 2022 5:50:04 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jul 1, 2022 5:50:13 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jul 1, 2022 5:50:18 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		DARTHURS	Jul 1, 2022 5:50:26 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jul 1, 2022 5:50:34 PM	No	
32,100	INSPECT_Intake System	Done		DARTHURS	Jul 1, 2022 5:50:41 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		DARTHURS	Jul 1, 2022 5:51:01 PM	No	
33,010	CSF (Curb Side Front)	Done		DARTHURS	Jul 1, 2022 5:51:08 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 1, 2022 5:51:13 PM	No	
33,030	*RPT*INSPECT_ FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 1, 2022 5:51:20 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,040	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 5:51:25 PM	No	
33,050	INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 1, 2022 5:51:32 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jul 1, 2022 5:51:36 PM	No	
33,070	*RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jul 1, 2022 5:51:49 PM	No	
33,070	*RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jul 1, 2022 6:06:33 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jul 1, 2022 5:52:19 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		DARTHURS	Jul 1, 2022 5:52:23 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jul 1, 2022 5:52:29 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jul 1, 2022 5:52:35 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jul 1, 2022 5:52:40 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		DARTHURS	Jul 1, 2022 5:52:45 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jul 1, 2022 5:52:51 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jul 1, 2022 5:52:58 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jul 1, 2022 5:53:04 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jul 1, 2022 5:53:11 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jul 1, 2022 5:53:15 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jul 1, 2022 5:53:20 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jul 1, 2022 5:53:27 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jul 1, 2022 5:53:34 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jul 1, 2022 5:53:39 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jul 1, 2022 5:53:44 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jul 1, 2022 5:53:49 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jul 1, 2022 5:53:57 PM	No	
50,200	INSPECT_Ball Joint Play	Done		DARTHURS	Jul 1, 2022 5:54:01 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jul 1, 2022 5:54:06 PM	No	
50,400	LUBE_All Chassis Components	Done		DARTHURS	Jul 1, 2022 5:54:10 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jul 1, 2022 5:54:15 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
50,700	INSPECT_Tire Condition	Done		DARTHURS	Jul 1, 2022 5:54:20 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 1, 2022 5:54:25 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 1, 2022 5:54:29 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 5:54:36 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:54:44 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jul 1, 2022 5:54:51 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:55:00 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jul 1, 2022 5:55:14 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jul 1, 2022 5:55:19 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jul 1, 2022 5:55:24 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 5:55:36 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 5:55:41 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 1, 2022 5:55:54 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 1, 2022 5:56:04 PM	No	
52,100	INSPECT_Vibration Damper	Done		DARTHURS	Jul 1, 2022 5:56:15 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jul 1, 2022 5:56:22 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		DARTHURS	Jul 1, 2022 5:56:26 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jul 1, 2022 5:56:31 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		DARTHURS	Jul 1, 2022 5:56:36 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jul 1, 2022 5:56:41 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jul 1, 2022 5:56:48 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		DARTHURS	Jul 1, 2022 5:56:53 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jul 1, 2022 5:57:00 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jul 1, 2022 5:57:06 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jul 1, 2022 5:57:13 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jul 1, 2022 5:57:19 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jul 1, 2022 5:57:24 PM	No	
53,600	INSPECT_Tire Condition	Done		DARTHURS	Jul 1, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					5:57:28 PM		
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 1, 2022 5:57:33 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jul 1, 2022 5:57:38 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jul 1, 2022 5:57:43 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 1, 2022 5:57:50 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 5:57:55 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 5:58:04 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 5:58:11 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:58:18 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:58:24 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 5:58:31 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 5:58:38 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:58:45 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 5:58:50 PM	No	
55,000	!FRA!INSPECT_REAR Brake Assemblies	Done		DARTHURS	Jul 1, 2022 5:58:56 PM	No	
55,100	!FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jul 1, 2022 5:59:01 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jul 1, 2022 5:59:09 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		DARTHURS	Jul 1, 2022 5:59:24 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		DARTHURS	Jul 1, 2022 5:59:29 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.656 Inch		DARTHURS	Jul 1, 2022 5:59:55 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.656 Inch		DARTHURS	Jul 1, 2022 6:00:03 PM	No	
55,700	!FRA!INSPECT_Under Body Exhaust System	Done		DARTHURS	Jul 1, 2022 6:00:08 PM	No	
55,800	*RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jul 1, 2022 6:00:13 PM	No	
55,900	*RPT*INSPECT_REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jul 1, 2022 6:00:18 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jul 1, 2022 6:00:22 PM	No	
60,100	RECORD_Wheelchair Cycle Count	24550 Cycles		DARTHURS	Jul 1, 2022 6:00:44 PM	No	
60,200	CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jul 1, 2022 6:00:49 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jul 1, 2022 6:00:54 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jul 1, 2022 6:00:59 PM	No	
60,500	INSPECT_Bridgeplate Operation	Done		DARTHURS	Jul 1, 2022 6:01:04 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jul 1, 2022 6:01:08 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jul 1, 2022 6:01:13 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		DARTHURS	Jul 1, 2022 6:01:17 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jul 1, 2022 6:01:22 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jul 1, 2022 6:01:27 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jul 1, 2022 6:01:33 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jul 1, 2022 6:01:39 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jul 1, 2022 6:01:43 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jul 1, 2022 6:01:51 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jul 1, 2022 6:01:55 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		DARTHURS	Jul 1, 2022 6:02:00 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jul 1, 2022 6:02:11 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jul 1, 2022 6:02:16 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jul 1, 2022 6:02:21 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jul 1, 2022 6:02:26 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jul 1, 2022 6:02:30 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jul 1, 2022 6:02:35 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jul 1, 2022 6:02:41 PM	No	
62,400	INSPECT_All Pivot Points	Done		DARTHURS	Jul 1, 2022 6:02:45 PM	No	
62,500	INSPECT_Cams and Slots	Done		DARTHURS	Jul 1, 2022 6:02:50 PM	No	
62,600	INSPECT_Rollers	Done		DARTHURS	Jul 1, 2022 6:02:55 PM	No	
62,700	INSPECT_All Linkages	Done		DARTHURS	Jul 1, 2022 6:02:59 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		DARTHURS	Jul 1, 2022 6:03:04 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		DARTHURS	Jul 1, 2022 6:03:08 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		DARTHURS	Jul 1, 2022 6:03:13 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		DARTHURS	Jul 1, 2022 6:03:18 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		DARTHURS	Jul 1, 2022 6:03:23 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		DARTHURS	Jul 1, 2022 6:03:27 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		DARTHURS	Jul 1, 2022 6:03:32 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		DARTHURS	Jul 1, 2022 6:03:37 PM	No	
80,100	COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jul 1, 2022 6:03:42 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jul 1, 2022 6:03:46 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: DARTHURS Performed on: 01-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 1, 2022 6:10:10 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	Jul 1, 2022 6:10:16 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	Jul 1, 2022 6:10:24 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	Jul 1, 2022 6:10:29 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	Jul 1, 2022 6:10:34 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	Jul 1, 2022 6:10:38 PM	No	
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 1, 2022 6:10:47 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	Jul 1, 2022 6:10:54 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-JUL-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		DARTHURS	Jul 1, 2022 6:11:31 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 1, 2022 6:11:36 PM	No	
4	Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 1, 2022 6:11:40 PM	No	
7	Have you performed the proper LOTO?	Done		DARTHURS	Jul 1, 2022 6:11:45 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 1, 2022 6:11:49 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 1, 2022 6:11:54 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 55743671
Invoice Number: 55345-55743671

Client Department:

MRC: 55345M
WO Desc: PMA SERVICE
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Chronology		
Reported	Aug 9, 2022	12:00 AM
Started	Aug 11, 2022	
Completed	Aug 12, 2022	3:00 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	265,049	DH
System	265,202	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMA Service CAUSE: preventive maintenance CORRECTION: Perform PMA Service and lube all Pivoting Points

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 10



WorkOrder: 55743671
Invoice Number: 55345-55743671

Client Department:

MRC: 55345M
WO Desc: PMA SERVICE
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
12-Aug-22	NELSON PIERRE-LOUIS	2.13	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 2.13
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Aug-22	65266	PLUG, DRAIN, OIL, ENGINE	1.00	4.90	4.90
12-Aug-22	B329	FILTER, OIL, SPIN-ON	1.00	2.19	2.19

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Aug-22	NELSON PIERRE-LOUIS	0.75	0.00	0.00

Activity 20 Sub Total

Parts: 7.09
Labor: 0.00
Labor Hours: 0.75
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 7.09

WorkOrder 55743671 Grand Total

Parts: 7.09
Labor: 0.00
Labor Hours: 2.88
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 7.09

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55851719	11-Oct-22	269,815	WO	55345-LIGHT DUTY PMB



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 10



WorkOrder: 55743671
Invoice Number: 55345-55743671

Client Department:

MRC: 55345M
WO Desc: PMA SERVICE
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
56028126	11-Oct-22	270,116	WO	Unscheduled Work
55898194	30-Aug-22	267,476	WO	check engine light on + interior light
55743671	12-Aug-22	265,049	WO	PMA SERVICE
55823775	2-Aug-22	263,902	WO	55345 PER DVIR (Check Wheel Chair Lift)
55793523	28-Jul-22	263,519	WO	Check Serptine Belt (Replace Tensioner)
55789861	21-Jul-22	263,220	WO	PER PTC RANDOM INSPECTION CHECK FRONT TIRE

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
56028126	11-Oct-22	270,116	WO	Unscheduled Work

PH: Work Order: 55743671 Desc: PMA SERVICE

Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS

Performed on: 12-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:17 AM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:18 AM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:19 AM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:19 AM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:20 AM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:21 AM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:22 AM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:22 AM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Aug 12, 2022 10:50:09 AM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:23 AM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:24 AM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:24 AM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:25 AM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:25 AM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Aug 12, 2022 10:50:32 AM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:26 AM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Aug 12, 2022 10:50:50 AM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Aug 12, 2022 10:50:45 AM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:27 AM	No	
20,800	INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:27 AM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 10:50:57 AM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Aug 12, 2022 10:51:05 AM	No	
21,100	INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:28 AM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:28 AM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-	Aug 12, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	11:01:29 AM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Aug 12, 2022 10:51:17 AM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:29 AM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:30 AM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Aug 12, 2022 10:51:36 AM	No	
21,700	INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:31 AM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:31 AM	No	
31,000	SSF (Street Side Front)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:32 AM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 12, 2022 10:51:48 AM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 12, 2022 10:51:52 AM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:33 AM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:33 AM	No	
32,000	Engine Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:34 AM	No	
32,010	INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:34 AM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:35 AM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:35 AM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:36 AM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	820 Degree Fahrenheit		NPIERRE-LOUIS	Aug 12, 2022 11:01:37 AM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:37 AM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Aug 12, 2022 10:52:23 AM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		NPIERRE-LOUIS	Aug 12, 2022 10:52:33 AM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Aug 12, 2022 10:53:24 AM	No	
32,100	INSPECT_Intake System	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:38 AM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Aug 12, 2022 10:53:38 AM	No	
33,010	CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:39 AM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 12, 2022 10:53:52 AM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 12, 2022 10:54:35 AM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-	Aug 12, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	11:01:39 AM		
33,050	INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:40 AM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:40 AM	No	
33,070	*RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	Aug 12, 2022 10:55:17 AM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:40 AM	No	
40,000	SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:41 AM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Aug 12, 2022 10:55:42 AM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:41 AM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:42 AM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:42 AM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:43 AM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:44 AM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 10:56:12 AM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Aug 12, 2022 10:56:19 AM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:44 AM	Yes	55850400
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:45 AM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:46 AM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:46 AM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Aug 12, 2022 10:56:53 AM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Aug 12, 2022 10:56:48 AM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:47 AM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Aug 12, 2022 10:57:06 AM	No	
50,200	INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:47 AM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:48 AM	No	
50,400	LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:48 AM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:49 AM	No	
50,700	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:50 AM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-	Aug 12, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
				LOUIS	11:01:50 AM		
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 11:01:51 AM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:49:53 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:49:54 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:49:55 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:49:55 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Aug 12, 2022 1:49:56 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:49:56 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		NPIERRE-LOUIS	Aug 12, 2022 1:49:57 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:49:58 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:12 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	35.1 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:14 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	35.1 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:14 PM	No	
52,100	INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:15 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:16 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:16 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:18 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:18 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:19 PM	No	
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:20 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:21 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Aug 12, 2022 1:41:35 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Aug 12, 2022 1:41:42 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Aug 12, 2022 1:41:48 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:41:53 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:21 PM	No	
53,600	INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:22 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:23 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:23 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:24 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:24 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:25 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:26 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:26 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:27 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:28 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:28 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:29 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:30 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:30 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:31 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:32 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:32 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:33 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:34 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:34 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:50:35 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:36 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Aug 12, 2022 1:44:40 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done	rubber spring,shear	NPIERRE-LOUIS	Aug 12, 2022 1:44:50 PM	Yes	55850400
60,000	SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:36 PM	No	
60,100	RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Aug 12, 2022 1:50:37 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:37 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:39 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:39 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,500	INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:40 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:40 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:41 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:41 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:42 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:42 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:43 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:44 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:44 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:45 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:45 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:46 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:46 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:47 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:48 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:49 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:49 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:50 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:51 PM	No	
62,400	INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:51 PM	No	
62,500	INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:52 PM	No	
62,600	INSPECT_Rollers	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:53 PM	No	
62,700	INSPECT_All Linkages	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:53 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:54 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:55 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:55 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:56 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting,	Done		NPIERRE-	Aug 12, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Insulation Against Vibration			LOUIS	1:50:56 PM		
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:57 PM	No	
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:57 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:58 PM	No	
80,100	COMPLETE_PMI Report; Follow-ups	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:58 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Aug 12, 2022 1:50:59 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 12-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Aug 12, 2022 2:50:27 PM	No	
101,000	FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Aug 12, 2022 2:50:28 PM	No	
102,000	FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Aug 12, 2022 2:50:29 PM	No	
103,000	FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Aug 12, 2022 2:50:29 PM	No	
104,000	Lubricate Chassis	Done		NPIERRE-LOUIS	Aug 12, 2022 2:50:30 PM	No	
105,000	Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Aug 12, 2022 2:50:30 PM	No	
107,000	FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Aug 12, 2022 2:50:31 PM	No	
108,000	Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Aug 12, 2022 2:50:32 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 12-AUG-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:37 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:38 PM	No	
4	Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:38 PM	No	
7	Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:39 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:40 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:40 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 56195682
Invoice Number: 55345-56195682

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

55345-MEDIUM DUTY PMA

Ford E450 Champion Challenger

VIN: 1FDFE4FSXEDB17155

Requested By:

SPACE

Status: 32

Created By:

SPACE

Priority: 3

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology

Reported	Apr 13, 2023	12:00 AM
Started	Apr 14, 2023	
Completed	Apr 14, 2023	5:03 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	274,813	DH
System	275,114	DH

WorkOrder Notes

Line	Comment
10	Vehicle came in for service due by mileage also change oil filter part # B329

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: Personal Risk Assessment

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **999/999/999 TOTAL VEHICLE**

Activity Note: Medium Duty PM Inspection

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Apr-23	Junior Hurst	2.82	0.00	0.00

Activity 10 Sub Total



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 11



WorkOrder: 56195682
Invoice Number: 55345-56195682

Client Department:

MRC: 55345M
WO Desc: 55345-MEDIUM DUTY PMA
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 32
Priority: 3
Driver:
Phone:
ETA:

Parts: 0.00
Labor: 0.00
Labor Hours: 2.82
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20  **999/999/999 TOTAL VEHICLE**
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: A - PM Level A
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
17-Apr-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1.00	2.51	2.51

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Apr-23	Junior Hurst	1.08	0.00	0.00

Activity 20 Sub Total

Parts: 2.51
Labor: 0.00
Labor Hours: 1.08
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 2.51

WorkOrder 56195682 Grand Total

Parts: 2.51
Labor: 0.00
Labor Hours: 3.90
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 2.51

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
56613078	16-Apr-23	274,740	WO	55345 PER DVIR(Wheel Chair Lift Not Operating Correctly)
56195682	14-Apr-23	274,813	WO	55345-MEDIUM DUTY PMA
56596671	6-Apr-23	274,385	WO	Replace Wheel Chair Bag
56374198	21-Mar-23	273,389	WO	Perform Bus Inspection

Scheduled Preventative Maintenance



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 11



WorkOrder: 56195682
Invoice Number: 55345-56195682

Client Department:

MRC: 55345M
WO Desc: 55345-MEDIUM DUTY PMA
Requested By: SPACE
Created By: SPACE
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 32
Priority: 3
Driver:
Phone:
ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 56195682 Desc: 55345-MEDIUM DUTY PMA
Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Medium Duty PM Inspection

Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST
Performed on: 14-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 14, 2023 4:00:54 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 14, 2023 4:00:54 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 14, 2023 4:01:17 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 14, 2023 4:01:17 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 14, 2023 4:01:18 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 14, 2023 4:01:18 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 14, 2023 4:01:43 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 14, 2023 4:01:43 PM	No	
10,800	CHECK_All Destination Signage	Done		JUHURST	Apr 14, 2023 4:01:43 PM	No	
10,900	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Apr 14, 2023 4:01:43 PM	No	
11,000	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 14, 2023 4:02:03 PM	No	
11,200	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 14, 2023 4:02:03 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 14, 2023 4:02:03 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 14, 2023 4:02:03 PM	No	
20,200	CHECK_Public Address System	Done		JUHURST	Apr 14, 2023 4:02:43 PM	No	
20,300	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 14, 2023 4:02:43 PM	No	
20,400	*RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Apr 14, 2023 4:02:43 PM	No	
20,500	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 14, 2023 4:03:22 PM	No	
20,600	RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Apr 14, 2023 4:03:22 PM	No	
20,700	RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Apr 14, 2023 4:03:22 PM	No	
20,800	RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Apr 14, 2023 4:03:22 PM	No	
20,900	RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Apr 14, 2023 4:53:55 PM	No	
21,000	RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Apr 14, 2023 4:04:11 PM	No	
21,100	ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Apr 14, 2023 4:04:11 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
21,200	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 14, 2023 4:04:23 PM	No	
21,300	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 14, 2023 4:06:47 PM	No	
21,400	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 14, 2023 4:06:54 PM	No	
21,500	INSPECT_High Idle Control	Done		JUHURST	Apr 14, 2023 4:07:03 PM	No	
21,600	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 14, 2023 4:07:11 PM	No	
21,700	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 14, 2023 4:07:24 PM	No	
21,800	INSPECT_Parking Brake Operation	Done		JUHURST	Apr 14, 2023 4:07:24 PM	No	
21,900	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 14, 2023 4:07:32 PM	No	
22,000	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 14, 2023 4:07:41 PM	No	
22,100	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 14, 2023 4:07:50 PM	No	
22,200	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 14, 2023 4:08:11 PM	No	
22,250	INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 14, 2023 4:08:19 PM	No	
22,300	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 14, 2023 4:08:25 PM	No	
22,400	INSPECT_Engine Fault Codes	Done		JUHURST	Apr 14, 2023 4:08:37 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Apr 14, 2023 4:09:04 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Apr 14, 2023 4:09:10 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 14, 2023 4:09:25 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 14, 2023 4:09:43 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:09:53 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 14, 2023 4:10:27 PM	No	
32,000	Engine Inspection	Done		JUHURST	Apr 14, 2023 4:10:33 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 14, 2023 4:10:41 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 14, 2023 4:10:48 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 14, 2023 4:10:57 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 14, 2023 4:11:06 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 14, 2023 4:11:22 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 14, 2023 4:11:21 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 14, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:11:36 PM		
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Apr 14, 2023 4:11:50 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 14, 2023 4:11:50 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Apr 14, 2023 4:12:14 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 14, 2023 4:12:14 PM	No	
33,000	CSF (Curb Side Front)	Done		JUHURST	Apr 14, 2023 4:12:14 PM	No	
33,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 14, 2023 4:12:33 PM	No	
33,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 14, 2023 4:12:33 PM	No	
33,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:12:33 PM	No	
33,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 14, 2023 4:12:50 PM	No	
33,050	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Apr 14, 2023 4:12:51 PM	No	
33,060	*RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Apr 14, 2023 4:13:08 PM	No	
33,070	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 14, 2023 4:13:09 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Apr 14, 2023 4:13:09 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 14, 2023 4:13:31 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 14, 2023 4:13:38 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 14, 2023 4:13:38 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 14, 2023 4:13:55 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 14, 2023 4:14:04 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 14, 2023 4:14:09 PM	No	
40,700	CHECK_Passenger Stop Request System	Done		JUHURST	Apr 14, 2023 4:14:18 PM	No	
40,800	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 14, 2023 4:14:24 PM	No	
40,900	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 14, 2023 4:14:47 PM	No	
41,000	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 14, 2023 4:14:47 PM	No	
41,100	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 14, 2023 4:14:59 PM	No	
41,200	INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 14, 2023 4:14:59 PM	No	
41,300	INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 14, 2023 4:15:17 PM	No	
41,400	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 14, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:15:17 PM		
41,500	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 14, 2023 4:15:18 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 14, 2023 4:15:31 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 14, 2023 4:15:31 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Apr 14, 2023 4:16:35 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 14, 2023 4:16:39 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Apr 14, 2023 4:16:46 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 14, 2023 4:16:52 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Apr 14, 2023 4:17:14 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 14, 2023 4:17:23 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 14, 2023 4:17:31 PM	No	
51,000	RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:18:17 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:18:54 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:18:17 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:18:29 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 14, 2023 4:18:29 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 14, 2023 4:19:04 PM	No	
51,600	!FRA!INSPECT_ Front Brake Assemblies	Done		JUHURST	Apr 14, 2023 4:19:11 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 14, 2023 4:19:41 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 14, 2023 4:19:42 PM	No	
51,900	INSPECT VISUALLY_ RECORD_ LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:20:06 PM	No	
52,000	INSPECT VISUALLY_ RECORD_ RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:20:06 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Apr 14, 2023 4:20:06 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 14, 2023 4:20:20 PM	No	
52,400	!FRA!INSPECT_ Starter Mounting	Done		JUHURST	Apr 14, 2023 4:20:20 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 14, 2023 4:20:28 PM	No	
52,700	INSPECT_ Engine, Transmission Mounts	Done	unit needs two motor mount	JUHURST	Apr 14, 2023 4:51:07 PM	Yes	56622876
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 14, 2023 4:20:39 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
52,900	INSPECT_ Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 14, 2023 4:20:39 PM	No	
53,000	!FRA!INSPECT_ Transmission Breather and Clean	Done		JUHURST	Apr 14, 2023 4:20:39 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 14, 2023 4:20:54 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 14, 2023 4:20:54 PM	No	
53,300	*RPT*INSPECT_ Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 14, 2023 4:20:54 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 14, 2023 4:57:34 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 14, 2023 4:21:23 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Apr 14, 2023 4:21:23 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 14, 2023 4:31:19 PM	No	
53,800	INSPECT_ Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 14, 2023 4:31:19 PM	No	
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 14, 2023 4:31:35 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 14, 2023 4:31:35 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:31:37 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Apr 14, 2023 4:32:39 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:32:42 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:33:36 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:33:36 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 14, 2023 4:34:24 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:34:24 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:34:24 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:34:24 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 14, 2023 4:34:24 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 14, 2023 4:34:37 PM	No	
55,200	!FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 14, 2023 4:34:37 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 14, 2023 4:35:29 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 14, 2023 4:35:30 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:35:31 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_RR	1.2699 Inch		JUHURST	Apr 14, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Drum, Rotor Condition (inches)				4:35:30 PM		
55,700	CHECK_Spring Brake Inversion Valve	Done		JUHURST	Apr 14, 2023 4:35:29 PM	No	
55,800	CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Apr 14, 2023 4:35:51 PM	No	
55,900	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 14, 2023 4:35:51 PM	No	
56,000	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 14, 2023 4:35:51 PM	No	
56,100	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 14, 2023 4:36:03 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 14, 2023 4:36:43 PM	No	
60,100	RECORD_Wheelchair Cycle Count	1435 Cycles		JUHURST	Apr 14, 2023 4:36:43 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 14, 2023 4:36:43 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 14, 2023 4:37:24 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 14, 2023 4:37:24 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 14, 2023 4:37:24 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 14, 2023 4:37:39 PM	No	
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 14, 2023 4:37:39 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 14, 2023 4:37:53 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Apr 14, 2023 4:37:53 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 14, 2023 4:38:12 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 14, 2023 4:38:12 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 14, 2023 4:38:13 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 14, 2023 4:38:13 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 14, 2023 4:38:37 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 14, 2023 4:38:37 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Apr 14, 2023 4:38:54 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 14, 2023 4:38:54 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 14, 2023 4:38:54 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 14, 2023 4:39:03 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 14, 2023 4:39:03 PM	No	
62,100	INSPECT_Emergency Platform Release	Done		JUHURST	Apr 14, 2023	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Mechanism				4:39:51 PM		
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 14, 2023 4:39:52 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 14, 2023 4:39:52 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Apr 14, 2023 4:41:25 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Apr 14, 2023 4:39:52 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Apr 14, 2023 4:42:54 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Apr 14, 2023 4:42:43 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Apr 14, 2023 4:42:54 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Apr 14, 2023 4:44:01 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Apr 14, 2023 4:44:01 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Apr 14, 2023 4:45:01 PM	No	
70,600	INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Apr 14, 2023 4:45:02 PM	No	
70,700	INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Apr 14, 2023 4:46:12 PM	No	
70,800	INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Apr 14, 2023 4:46:12 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 14, 2023 4:46:12 PM	No	
80,100	COMPLETE_PMI Report; Follow-ups	Done		JUHURST	Apr 14, 2023 4:46:31 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 14, 2023 4:46:31 PM	No	

LH: 20 Desc: Medium Duty PMA Service

Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 14-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Apr 14, 2023 2:02:47 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Apr 14, 2023 2:02:47 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Apr 14, 2023 2:02:58 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Apr 14, 2023 2:02:58 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Apr 14, 2023 2:03:05 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Apr 14, 2023 2:03:05 PM	No	
106,000	Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Apr 14, 2023 2:03:39 PM	No	
107,000	FRA Change Primary Fuel Filter	No		JUHURST	Apr 14, 2023 2:03:39 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Apr 14, 2023 2:04:11	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					PM		

LH: 5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 14-APR-23

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	
11	Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 14, 2023 4:58:49 PM	No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51336457
Invoice Number: 55345-51336457

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM A

VIN: 1FDFE4FSXEDB17155

Requested By: DARTHURS

Status: 40

Created By: DARTHURS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Jun 7, 2018	11:07 AM
Started	Jun 8, 2018	
Completed	Jun 8, 2018	12:03 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	143,520	DH
System	143,520	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: pmA CAUSE: Preventive Maintenance CORRECTION: Perform pmA Service lube all Pivoting Points cross rotate tires completed

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
08-Jun-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Pierre,Hubert J	5.00	0.00	0.00

Activity 10 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours: 5.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM A

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: A - PM Level A

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51336457
Invoice Number: 55345-51336457

Client Department:

MRC: 55345M
WO Desc: PM A
Requested By: DARTHURS
Created By: DARTHURS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FD4E4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Pierre,Hubert J	0.42	0.00	0.00

Activity 20 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.42
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: **30** **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
08-Jun-18	Pierre,Hubert J	0.08	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.08
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51336457 Grand Total

Parts: 1.96
Labor: 0.00
Labor Hours: 5.50
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 1.96

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
51336457	8-Jun-18	143,520	WO	PM A
51221024	9-May-18	139,350	WO	PM B



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51336457
Invoice Number: 55345-51336457

Client Department:

MRC: 55345M

WO Desc:

PM A

Requested By: DARTHURS

Created By: DARTHURS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4602-P

Ford E450 Champion Challenger

VIN: 1FDFE4FSXEDB17155

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51336457 Desc: PM A

Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 07-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jun 7, 2018 2:25:08 PM	No	
10,100	Safety Inspection	Done		HPIERRE	Jun 7, 2018 2:25:08 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 7, 2018 2:25:08 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jun 7, 2018 2:25:08 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,140	Check Service Brakes	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,160	FRA Check Instruments and Horns	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,170	Check Fast Idle	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,180	Check Starter Protection Circuit	Done		HPIERRE	Jun 7, 2018 2:25:09 PM	No	
10,190	Check Reverse Warning System	Done		HPIERRE	Jun 7, 2018 2:25:10 PM	No	
11,100	Check Parking Brake	Done		HPIERRE	Jun 7, 2018 2:25:10 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		HPIERRE	Jun 7, 2018 2:25:10 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jun 7, 2018 2:25:11 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		HPIERRE	Jun 7, 2018 2:25:10 PM	No	
11,140	Road Test: Check for Proper Operation	Done		HPIERRE	Jun 7, 2018 2:25:11 PM	No	
11,150	Perform Brake Test	Done		HPIERRE	Jun 7, 2018 2:25:11 PM	No	
11,152	Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jun 7, 2018 2:25:11 PM	No	
11,154	Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jun 7, 2018 2:25:12 PM	No	
11,156	Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jun 7, 2018 2:25:12 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jun 7, 2018 2:25:12 PM	No	
11,162	FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 2:25:12 PM	No	
11,170	FRA Check Door Operation	Done		HPIERRE	Jun 7, 2018 2:25:12 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		HPIERRE	Jun 7, 2018 2:25:12 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jun 7, 2018 2:25:12 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		HPIERRE	Jun 7, 2018 2:25:12 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		HPIERRE	Jun 7, 2018 2:25:13 PM	No	
20,230	FRA Check Wiring Under Dash	Done		HPIERRE	Jun 7, 2018 2:25:13 PM	No	
20,240	FRA Check Interior Lights	Done		HPIERRE	Jun 7, 2018 2:25:13 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		HPIERRE	Jun 7, 2018 2:25:13 PM	No	
20,260	Check Stop Request System	-	N/A	HPIERRE	Jun 7, 2018 2:25:14 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jun 7, 2018 2:25:14 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
22,110	Check Emergency Hatches	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
22,120	Check All Safety Equipment	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jun 7, 2018 2:25:14 PM	No	
30,310	Check Passenger Doors	Done		HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,330	Check Wheelchair Lift Operation	Done		HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,360	Check for Physical Damage and Decals	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		HPIERRE	Jun 7, 2018 2:25:15 PM	No	
30,380	Check Exterior Compartment Doors	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
33,100	Check Lights and Reflectors	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jun 7, 2018 2:25:16 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,420	Check Hood	Done		HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		HPIERRE	Jun 7, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					2:25:17 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,442	Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jun 7, 2018 2:25:17 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jun 7, 2018 2:25:18 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 2:25:18 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jun 7, 2018 2:25:18 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		HPIERRE	Jun 7, 2018 2:25:18 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		HPIERRE	Jun 7, 2018 2:25:18 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,130	FRA Check Exhaust System	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,140	FRA Check Intake System	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,150	FRA Inspect Turbocharger	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jun 7, 2018 2:25:19 PM	No	
44,180	FRA Check for Leaks	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
44,190	FRA Perform Battery Inspection	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
50,510	Check Entire Steering System	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jun 7, 2018 2:25:20 PM	No	
60,610	FRA Check and Record Air Pressure	Done		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,611	Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,612	Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,613	Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,615	Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,616	Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,620	Check Valve Stems and Caps	Done		HPIERRE	Jun 7, 2018 2:25:21 PM	No	
60,630	Check and Record Tread Depth	Done		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,631	Tread Depth RF	8 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,632	Tread Depth LF	8 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,633	Tread Depth RRO	7 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,634	Tread Depth RRI	7 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,635	Tread Depth LRI	7 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,636	Tread Depth LRO	7 32nds of an inch		HPIERRE	Jun 7, 2018 2:25:22 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jun 7, 2018 2:25:23 PM	No	
60,650	Check Sidewall Wear	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
60,660	Inspect for Cuts and Tears	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
60,670	Check Dual Mating With Square	-	N/A	HPIERRE	Jun 7, 2018 3:17:10 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jun 7, 2018 3:17:10 PM	No	
70,710	Check Vibration Damper	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,720	Check Engine and Transmission Mounts	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,730	FRA Check Starter	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,750	FRA Check Transmission for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		HPIERRE	Jun 7, 2018 3:17:11 PM	No	
70,770	FRA Check Exhaust System	Done		HPIERRE	Jun 7, 2018 3:17:12 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jun 7, 2018 3:17:12 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jun 7, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:17:12 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jun 7, 2018 3:17:12 PM	No	
77,110	FRA Check Fuel Tank	Done		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,120	Check Suspension Components	Done		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,131	Brake Pad Thickness LF	8 Inch		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,132	Brake Pad Thickness RF	8 Inch		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,133	Brake Pad Thickness LR	7 Inch		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,134	Brake Pad Thickness RR	7 Inch		HPIERRE	Jun 7, 2018 3:17:13 PM	No	
77,135	Brake Rotor LF	1.6 Inch		HPIERRE	Jun 7, 2018 3:17:14 PM	No	
77,136	Brake Rotor RF	1.6 Inch		HPIERRE	Jun 7, 2018 3:17:14 PM	No	
77,137	Brake Rotor LR	1.7 Inch		HPIERRE	Jun 7, 2018 3:17:14 PM	No	
77,138	Brake Rotor RR	1.7 Inch		HPIERRE	Jun 7, 2018 3:17:14 PM	No	
77,140	FRA Check Brake Hoses	Done		HPIERRE	Jun 7, 2018 3:17:14 PM	No	
77,150	Check King Pins	-	N/A	HPIERRE	Jun 7, 2018 3:17:15 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jun 7, 2018 3:17:15 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		HPIERRE	Jun 7, 2018 3:17:15 PM	No	
80,810	Completion of PMI Report	Done		HPIERRE	Jun 7, 2018 3:17:15 PM	No	
90,000	SECTION 9 Completion of PMI	Done		HPIERRE	Jun 7, 2018 3:17:16 PM	No	
90,910	Vehicle Returned to predetermined location	Done		HPIERRE	Jun 7, 2018 3:17:16 PM	No	

LH: 20 Desc: PM A

Task: PM A SERVICE Performed by: HPIERRE Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 8, 2018 9:48:01 AM	No	
101,000	FRA Change Oil Filters	Yes		HPIERRE	Jun 8, 2018 9:48:02 AM	No	
102,000	FRA Drain Engine Oil	Yes		HPIERRE	Jun 8, 2018 9:48:02 AM	No	
103,000	FRA Check Transmission Fluid	Done		HPIERRE	Jun 8, 2018 9:48:02 AM	No	
104,000	Lubricate Chassis	Done		HPIERRE	Jun 8, 2018 9:48:02 AM	No	
105,000	Replace or Clean A/C Filters	Done		HPIERRE	Jun 8, 2018 9:48:02 AM	No	
107,000	FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jun 8, 2018 9:48:02 AM	No	
108,000	Lube all pivoting Mechanisms	Done		HPIERRE	Jun 8, 2018 9:48:02 AM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-JUN-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 8, 2018 9:48:32 AM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 54294793
Invoice Number: 55345-54294793

Client Department:

MRC: 55345M

WO Desc:

55345-LIGHT DUTY PMA

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4602-P

VIN: Ford E450 Champion Challenger

Status: 1FDFE4FSXEDB17155

Priority: 40

Driver: 3

Phone:

ETA:

Chronology		
Reported	Mar 22, 2021	12:00 PM
Started	Mar 22, 2021	
Completed	Mar 22, 2021	3:04 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	251,429	DH
System	251,882	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: unit came in for service
	CAUSE: time for service
	CORRECTION: replace new oil filter B329 after return vehicle back to work

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW - Shop Work Order

Work Accomplished: 06 - Inspect

Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
22-Mar-21	Junior Hurst	0.02	0.00	0.00

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.02	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 020 GROUP, DRIVETRAIN

Activity Note: Light Duty PMI

Reason for Repair: 11 - Routine

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
22-Mar-21	B329(F)	SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51784945
Invoice Number: 55345-51784945

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Nov 13, 2018	12:59 PM
Started	Nov 14, 2018	
Completed	Nov 14, 2018	11:16 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	165,698	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:pmB CAUSE:Service CORRECTION:Perform PmB Service Oil filter B329 Qty1 Engine oil 5w20 qty 7 Qts

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
14-Nov-18	Gaspard,Ronald	1.57	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 1.57
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
14-Nov-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52349776
Invoice Number: 55345-52349776

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM B

VIN: 1FDFE4FSXEDB17155

Requested By: VAMRITTEEMAL

Status: 40

Created By: VAMRITTEEMAL

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	May 17, 2019	2:48 PM
Started	May 18, 2019	
Completed	May 18, 2019	12:22 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	190,817	DH
System	191,369	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PM B Service CAUSE: Service due by Mileage CORRECTION: Change Oil & Filter. Lube all Pivoting Points .Check Brakes. Clean batteries. Parts# B329 Qty (1) Oil 5W20 Qty (7.0)

Activity: 10 **999 TOTAL VEHICLE**

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
18-May-19	Arthurs,Durvin	2.00	65.00	130.00

Activity 10 Sub Total

Parts:	0.00
Labor:	130.00
Labor Hours: 2.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	130.00

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B


Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53008158
Invoice Number: 55345-53008158

Client Department:

MRC: 55345M

WO Desc:

PM B

Requested By: RRENE

Created By: RRENE

Class: WO

Arrangement: Unassigned

Potential Warranty: No

Equipment: 4602-P

Ford E450 Champion Challenger

VIN: 1FDFE4FSXEDB17155

Status: 40

Priority: 1

Driver:

Phone:

ETA:

Chronology		
Reported	Dec 24, 2019	12:26 PM
Started	Dec 24, 2019	
Completed	Dec 24, 2019	7:47 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	218,010	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: PMB CAUSE: Service CORRECTION: Performed PMB Service Oil filter B329 qty1 Engine oil 5W20Qty qty 7 Qts Rotate tires and washed rims torque wheels 140 lbs Second torque 140 lbs

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
24-Dec-19	Gaspard,Ronald	2.32	65.00	150.80

Activity 10 Sub Total

Parts: 0.00
Labor: 150.80
Labor Hours: 2.32
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 150.80

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: B - PM Level B

Part Failure: -

Activity Comments

Parts Issued



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 53685229
Invoice Number: 55345-53685229

Client Department:

MRC:	55345M	Equipment:	4602-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		VIN:	1FDFF4FSXEDB17155
Requested By:	RGASPARD	Status:	40
Created By:	RGASPARD	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Jan 6, 2021	12:00 AM
Started	Jan 6, 2021	
Completed	Jan 7, 2021	12:26 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	242,852	DH
System	243,342	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT:PMB CAUSE: Service CORRECTION:perform PMB Service Oil filter B329 Qty1 Engine oil 10w30 qty 7 qts Air filter PA4075 Qty1

Activity: 5



999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10



079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Light Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
06-Jan-21	PA4075	FILTER, AIR	1.00	5.28	5.28



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 11



WorkOrder: 55851719
Invoice Number: 55345-55851719

Client Department:

MRC:	55345M	Equipment:	4602-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMB		VIN:	1FDFE4FSXEDB17155
Requested By:	NPIERRE-LOUIS	Status:	40
Created By:	NPIERRE-LOUIS	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology		
Reported	Oct 7, 2022	12:00 AM
Started	Oct 11, 2022	
Completed	Oct 11, 2022	5:43 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	269,815	DH
System	269,927	DH

WorkOrder Notes

Line	Comment
10	COMPLAINT: Vehicle came in for service CAUSE: Service due by Mileage CORRECTION: Service job complete also change oil filter B329 and wash rear A/C filter

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **020 GROUP, DRIVETRAIN**

Activity Note: Light Duty PMI
Reason for Repair: 11 - Routine
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
11-Oct-22	B329		FILTER, OIL, SPIN-ON	1.00	4.11	4.11

Labor Posted



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 11



WorkOrder: 55851719
Invoice Number: 55345-55851719

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Date	Technician	Hours	Rate	Extended
11-Oct-22	Junior Hurst	2.60	0.00	0.00

Activity 10 Sub Total

Parts: 4.11
Labor: 0.00
Labor Hours: 2.60
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 4.11

Activity: 20 **999 TOTAL VEHICLE**

Activity Note: PM B
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: B - PM Level B
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
11-Oct-22	Junior Hurst	0.35	0.00	0.00

Activity 20 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.35
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 55851719 Grand Total

Parts: 4.11
Labor: 0.00
Labor Hours: 2.95
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 4.11

Recent Repair History

WorkOrder	Date Completed	Life Meter	Class	Description
55851719	11-Oct-22	269,815	WO	55345-LIGHT DUTY PMB
56028126	11-Oct-22	270,116	WO	Unscheduled Work

Scheduled Preventative Maintenance



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 11



WorkOrder: 55851719
Invoice Number: 55345-55851719

Client Department:

MRC: 55345M
WO Desc: 55345-LIGHT DUTY PMB
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 3
Driver:
Phone:
ETA:

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description
56028126	11-Oct-22	270,116	WO	Unscheduled Work

PH: Work Order: 55851719 Desc: 55345-LIGHT DUTY PMB
Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 11-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 - Preparation Inspection	Done		JUHURST	Oct 11, 2022 3:03:53 PM	No	
10,100	INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Oct 11, 2022 3:03:48 PM	No	
10,200	!FRA!INSPECT_Starter Operation	Done		JUHURST	Oct 11, 2022 3:19:01 PM	No	
10,300	!FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Oct 11, 2022 3:27:08 PM	No	
10,400	!FRA!INSPECT_Back Up Alarm	Done		JUHURST	Oct 11, 2022 3:30:32 PM	No	
10,500	!FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Oct 11, 2022 3:31:52 PM	No	
10,600	Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Oct 11, 2022 3:32:11 PM	No	
10,700	INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Oct 11, 2022 3:32:19 PM	No	
10,800	*RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Oct 11, 2022 3:33:02 PM	No	
10,900	INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Oct 11, 2022 3:35:16 PM	No	
11,100	INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Oct 11, 2022 3:36:47 PM	No	
20,000	SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Oct 11, 2022 3:36:42 PM	No	
20,100	INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Oct 11, 2022 3:37:52 PM	No	
20,200	TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Oct 11, 2022 3:40:19 PM	No	
20,300	*RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Oct 11, 2022 3:40:30 PM	No	
20,400	PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Oct 11, 2022 3:40:35 PM	No	
20,500	*RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Oct 11, 2022 3:40:43 PM	No	
20,600	*RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Oct 11, 2022 3:40:54 PM	No	
20,700	INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Oct 11, 2022 3:40:59 PM	No	
20,800	INSPECT_High Idle Control	Done		JUHURST	Oct 11, 2022 3:43:11 PM	No	
20,900	*RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Oct 11, 2022 3:44:08 PM	No	
21,000	*RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Oct 11, 2022 3:44:15 PM	No	
21,100	INSPECT_Parking Brake Operation	Done		JUHURST	Oct 11, 2022 3:44:20 PM	No	
21,200	!FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Oct 11, 2022 3:44:44 PM	No	
21,300	INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Oct 11, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					3:44:48 PM		
21,400	*RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Oct 11, 2022 3:45:35 PM	No	
21,500	!FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Oct 11, 2022 3:46:07 PM	No	
21,550	INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Oct 11, 2022 3:46:18 PM	No	
21,600	*RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Oct 11, 2022 3:46:26 PM	No	
21,700	INSPECT_Engine Fault Codes	Done		JUHURST	Oct 11, 2022 3:46:46 PM	No	
30,000	SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Oct 11, 2022 3:46:51 PM	No	
31,000	SSF (Street Side Front)	Done		JUHURST	Oct 11, 2022 3:47:02 PM	No	
31,010	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 11, 2022 3:47:23 PM	No	
31,020	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 11, 2022 3:47:31 PM	No	
31,030	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 3:47:51 PM	No	
31,040	INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 11, 2022 3:51:18 PM	No	
32,000	Engine Inspection	Done		JUHURST	Oct 11, 2022 3:52:37 PM	No	
32,010	INSPECT_Hood, Springs and Props	Done		JUHURST	Oct 11, 2022 3:52:46 PM	No	
32,020	!FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Oct 11, 2022 3:52:50 PM	No	
32,030	!FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Oct 11, 2022 3:52:55 PM	No	
32,040	!FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Oct 11, 2022 3:52:59 PM	No	
32,050	!FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Oct 11, 2022 3:53:11 PM	No	
32,060	PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Oct 11, 2022 3:53:23 PM	No	
32,070	*RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Oct 11, 2022 3:53:30 PM	No	
32,080	*RPT*INSPECT_Fan Assembly,Shroud,Tensioner,Belts,All Belt Driven Components	Done		JUHURST	Oct 11, 2022 3:53:39 PM	No	
32,090	*RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Oct 11, 2022 3:53:58 PM	No	
32,100	INSPECT_Intake System	Done		JUHURST	Oct 11, 2022 3:54:03 PM	No	
32,140	*RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Oct 11, 2022 3:54:13 PM	No	
33,010	CSF (Curb Side Front)	Done		JUHURST	Oct 11, 2022 3:54:41 PM	No	
33,020	*RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 11, 2022 3:54:50 PM	No	
33,030	*RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 11, 2022 3:58:37 PM	No	
33,040	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 3:58:42 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
33,050	INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 11, 2022 3:58:47 PM	No	
33,060	!FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Oct 11, 2022 3:59:33 PM	No	
33,070	*RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Oct 11, 2022 3:59:54 PM	No	
33,080	INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Oct 11, 2022 4:00:12 PM	No	
40,000	SECTION 4 - Interior Inspection	Done		JUHURST	Oct 11, 2022 4:00:20 PM	No	
40,100	*RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Oct 11, 2022 4:00:25 PM	No	
40,200	INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Oct 11, 2022 4:00:38 PM	No	
40,250	INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Oct 11, 2022 4:00:42 PM	No	
40,300	INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Oct 11, 2022 4:00:49 PM	No	
40,400	INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Oct 11, 2022 4:00:55 PM	No	
40,600	!FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Oct 11, 2022 4:01:14 PM	No	
40,700	*RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Oct 11, 2022 4:01:21 PM	No	
40,800	*RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Oct 11, 2022 4:01:29 PM	No	
40,900	!FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Oct 11, 2022 4:01:35 PM	No	
41,000	INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Oct 11, 2022 4:01:39 PM	No	
41,100	INSPECT_CLEAN_AC Filter	Done		JUHURST	Oct 11, 2022 4:01:44 PM	No	
41,200	INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Oct 11, 2022 4:01:49 PM	No	
41,300	*RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Oct 11, 2022 4:01:53 PM	No	
41,400	*RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Oct 11, 2022 4:02:01 PM	No	
50,000	SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Oct 11, 2022 4:05:43 PM	No	
50,100	*RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Oct 11, 2022 4:06:03 PM	No	
50,200	INSPECT_Ball Joint Play	Done		JUHURST	Oct 11, 2022 4:11:52 PM	No	
50,300	!FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Oct 11, 2022 4:12:27 PM	No	
50,400	LUBE_All Chassis Components	Done		JUHURST	Oct 11, 2022 4:12:35 PM	No	
50,500	!FRA!CHANGE_Engine oil,filters	Done		JUHURST	Oct 11, 2022 4:13:24 PM	No	
50,700	INSPECT_Tire Condition	Done		JUHURST	Oct 11, 2022 4:13:52 PM	No	
50,800	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 11, 2022 4:14:00 PM	No	
50,900	!FRA!INSPECT_Wheels for Cracks, Loose	Done		JUHURST	Oct 11, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Lugs/Indicators, Outer Hub Leaks				4:14:12 PM		
51,000	RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:16:32 PM	No	
51,100	RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:19:13 PM	No	
51,200	RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Oct 11, 2022 4:19:25 PM	No	
51,300	RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:20:05 PM	No	
51,400	!FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Oct 11, 2022 4:20:13 PM	No	
51,500	!FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Oct 11, 2022 4:20:23 PM	No	
51,600	!FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Oct 11, 2022 4:20:30 PM	No	
51,700	MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Oct 11, 2022 4:27:02 PM	No	
51,800	MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Oct 11, 2022 4:27:12 PM	No	
51,900	INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 11, 2022 4:27:55 PM	No	
52,000	INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 11, 2022 4:31:36 PM	No	
52,100	INSPECT_Vibration Damper	Done		JUHURST	Oct 11, 2022 4:31:41 PM	No	
52,200	!FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Oct 11, 2022 4:31:48 PM	No	
52,400	!FRA!INSPECT_Starter Mounting	Done		JUHURST	Oct 11, 2022 4:31:58 PM	No	
52,500	!FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Oct 11, 2022 4:32:02 PM	No	
52,700	INSPECT_Engine, Transmission Mounts	Done		JUHURST	Oct 11, 2022 4:32:07 PM	No	
52,800	!FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Oct 11, 2022 4:32:11 PM	No	
52,900	INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Oct 11, 2022 4:32:18 PM	No	
53,000	!FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Oct 11, 2022 4:32:24 PM	No	
53,100	*RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Oct 11, 2022 4:32:32 PM	No	
53,200	*RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Oct 11, 2022 4:32:52 PM	No	
53,300	*RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Oct 11, 2022 4:32:59 PM	No	
53,400	*RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Oct 11, 2022 4:33:06 PM	No	
53,500	!FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Oct 11, 2022 4:33:42 PM	No	
53,600	INSPECT_Tire Condition	Done		JUHURST	Oct 11, 2022 4:33:51 PM	No	
53,700	INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 11, 2022 4:34:02 PM	No	
53,800	INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Oct 11, 2022 4:34:06 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
53,900	INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Oct 11, 2022 4:34:15 PM	No	
54,000	!FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Oct 11, 2022 4:34:23 PM	No	
54,100	INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 4:34:28 PM	No	
54,200	RECORD_RRO-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Oct 11, 2022 4:36:13 PM	No	
54,300	RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:36:24 PM	No	
54,400	RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:37:20 PM	No	
54,500	RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:37:28 PM	No	
54,600	RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Oct 11, 2022 4:40:04 PM	No	
54,700	RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:40:24 PM	No	
54,800	RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:40:34 PM	No	
54,900	RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:40:39 PM	No	
55,000	!FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Oct 11, 2022 4:40:44 PM	No	
55,100	!FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Oct 11, 2022 4:41:08 PM	No	
55,200	!FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Oct 11, 2022 4:41:21 PM	No	
55,300	MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Oct 11, 2022 4:41:37 PM	No	
55,400	MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Oct 11, 2022 4:42:35 PM	No	
55,500	INSPECT VISUALLY_MEASURE_RECORD_ LR Drum, Rotor Condition (inches)	1.2266 Inch		JUHURST	Oct 11, 2022 4:44:06 PM	No	
55,600	INSPECT VISUALLY_MEASURE_RECORD_ RR Drum, Rotor Condition (inches)	1.2266 Inch		JUHURST	Oct 11, 2022 4:44:34 PM	No	
55,700	!FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Oct 11, 2022 4:44:39 PM	No	
55,800	*RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Oct 11, 2022 4:45:29 PM	No	
55,900	*RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Oct 11, 2022 4:46:06 PM	No	
60,000	SECTION 6 - Wheelchair Inspection	Done		JUHURST	Oct 11, 2022 4:46:49 PM	No	
60,100	RECORD_Wheelchair Cycle Count	25334 Cycles		JUHURST	Oct 11, 2022 4:47:05 PM	No	
60,200	CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Oct 11, 2022 4:48:21 PM	No	
60,300	CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Oct 11, 2022 4:48:28 PM	No	
60,400	OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Oct 11, 2022 4:49:13 PM	No	
60,500	INSPECT_ Bridgeplate Operation	Done		JUHURST	Oct 11, 2022 4:49:19 PM	No	
60,600	INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Oct 11, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					4:49:24 PM		
60,700	INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Oct 11, 2022 4:49:29 PM	No	
60,800	INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Oct 11, 2022 4:49:33 PM	No	
60,900	INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Oct 11, 2022 4:49:38 PM	No	
61,000	INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Oct 11, 2022 4:49:43 PM	No	
61,100	INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Oct 11, 2022 4:49:49 PM	No	
61,200	INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Oct 11, 2022 4:49:53 PM	No	
61,300	INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Oct 11, 2022 4:49:58 PM	No	
61,400	INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Oct 11, 2022 4:50:03 PM	No	
61,500	INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Oct 11, 2022 4:50:11 PM	No	
61,600	INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Oct 11, 2022 4:50:15 PM	No	
61,700	CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Oct 11, 2022 4:50:20 PM	No	
61,800	CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Oct 11, 2022 4:50:24 PM	No	
61,900	CLEAN_Linkages and Mechanisms	Done		JUHURST	Oct 11, 2022 4:50:31 PM	No	
62,000	LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Oct 11, 2022 4:50:36 PM	No	
62,100	INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Oct 11, 2022 4:50:43 PM	No	
62,200	INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Oct 11, 2022 4:50:50 PM	No	
62,300	INSPECT_Bridgeplate Hinge	Done		JUHURST	Oct 11, 2022 4:50:55 PM	No	
62,400	INSPECT_All Pivot Points	Done		JUHURST	Oct 11, 2022 4:50:59 PM	No	
62,500	INSPECT_Cams and Slots	Done		JUHURST	Oct 11, 2022 4:51:52 PM	No	
62,600	INSPECT_Rollers	Done		JUHURST	Oct 11, 2022 4:52:17 PM	No	
62,700	INSPECT_All Linkages	Done		JUHURST	Oct 11, 2022 4:52:22 PM	No	
70,000	SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Oct 11, 2022 4:52:26 PM	No	
70,300	INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Oct 11, 2022 4:52:32 PM	No	
70,400	PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Oct 11, 2022 4:53:02 PM	No	
70,500	INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Oct 11, 2022 4:53:09 PM	No	
70,600	INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Oct 11, 2022 4:53:16 PM	No	
70,700	INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Oct 11, 2022 4:53:21 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
70,800	INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Oct 11, 2022 4:53:26 PM	No	
80,000	SECTION 8 - PMI Report Completion	Done		JUHURST	Oct 11, 2022 4:53:34 PM	No	
80,100	COMPLETE_PMI Report; Follow-ups	Done		JUHURST	Oct 11, 2022 4:53:40 PM	No	
80,200	RETURN_Vehicle to Predetermined Location	Done		JUHURST	Oct 11, 2022 4:53:44 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: JUHURST Performed on: 11-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		JUHURST	Oct 11, 2022 2:41:21 PM	No	
101,000	FRA Change Oil Filters	Yes		JUHURST	Oct 11, 2022 2:41:16 PM	No	
102,000	FRA Drain Engine Oil	Yes		JUHURST	Oct 11, 2022 2:41:27 PM	No	
103,000	FRA Check Transmission Fluid	Done		JUHURST	Oct 11, 2022 2:41:34 PM	No	
104,000	Lubricate Chassis	Done		JUHURST	Oct 11, 2022 2:41:38 PM	No	
105,000	Replace or Clean A/C Filters	Done		JUHURST	Oct 11, 2022 2:41:43 PM	No	
107,000	FRA Change Primary Fuel Filter	Yes		JUHURST	Oct 11, 2022 2:41:48 PM	No	
108,000	Lube all pivoting Mechanisms	Done		JUHURST	Oct 11, 2022 2:41:52 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Oct 11, 2022 2:41:58 PM	No	
201,000	Service Crankcase Breather	Done		JUHURST	Oct 11, 2022 2:42:04 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		JUHURST	Oct 11, 2022 2:42:08 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		JUHURST	Oct 11, 2022 2:42:26 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Oct 11, 2022 2:42:41 PM	No	

LH: 5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-OCT-22

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
1	Are you properly trained to perform the task?	Done		JUHURST	Oct 11, 2022 2:39:29 PM	No	
2	If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 11, 2022 2:39:25 PM	No	
4	Are you wearing the appropriate PPE?	Done		JUHURST	Oct 11, 2022 2:39:35 PM	No	
7	Have you performed the proper LOTO?	Done		JUHURST	Oct 11, 2022 2:39:47 PM	No	
10	Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 11, 2022 2:39:42 PM	No	
11	Have you successfully completed the Personal Risk	Done		JUHURST	Oct 11, 2022	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
	Assessment?				2:39:51 PM		



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 51498919
Invoice Number: 55345-51498919

Client Department:

MRC: 55345M

WO Desc:

PM C

Requested By:

CKARLENS

Created By:

CKARLENS

Class:

WO

Arrangement:

Unassigned

Potential Warranty:

No

Equipment:

4602-P

VIN:

Ford E450 Champion Challenger

Status:

1FDFE4FSXEDB17155

Priority:

40

Driver:

1

Phone:

ETA:

Chronology

**Reported
Started
Completed**

Aug 10, 2018

1:38 PM

Aug 13, 2018

8:49 AM

Down Time

Meter	Reading	UOM
WO		DH
Life	152,083	DH
System	152,083	DH

WorkOrder Notes

Line	Comment
10	Tech performed PM-c Parts used Oil filter Qty1 part#329 Oil Qty:6.5 Transmission filter Qty1 part#20021 Transmission fluid Qts:10

Activity: 10



999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 - Inspection, Routine

Work Accomplished: 06 - Inspect

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Aug-18	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27
12-Aug-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52084014
Invoice Number: 55345-52084014

Client Department:

MRC: 55345M
WO Desc: PM C
Requested By: CVERGARA
Created By: CVERGARA
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
VIN: 1FDFE4FSXEDB17155
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Chronology		
Reported	Feb 12, 2019	12:01 PM
Started	Feb 12, 2019	
Completed	Feb 12, 2019	11:30 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	178,500	DH
System	179,000	DH

WorkOrder Notes

Line	Comment
10	Perform PMC Service Change Oil & Filter. Lube all Pivoting Points. Check brakes Clean batteries.&Perform Transmission Service/ differential service ATF Fluid Qty (9.0) Qt Gear Oil (3.0) Qt Oil 5W20QTY (7.0) Qt Parts# B329 Qty (1) Parts #20021 Qty (1)

Activity: 10 **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
12-Feb-19	Arthurs,Durvin	3.50	0.00	0.00

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 3.50
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: 20 **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
12-Feb-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 9



WorkOrder: 52653110
Invoice Number: 55345-52653110

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM C

VIN: 1FDFE4FSXEDB17155

Requested By:

CVERGARA

Status: 40

Created By:

CVERGARA

Priority: 1

Class:

WO

Driver:

Arrangement:

Unassigned

Phone:

Potential Warranty:

No

ETA:

Chronology		
Reported	Sep 6, 2019	11:44 AM
Started		
Completed	Sep 10, 2019	8:11 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	204,393	DH
System	204,694	DH

WorkOrder Notes

Line	Comment
10	Complaint: PMC Service Cause: preventive maintenance Correction: PMC Service Perform and

Activity: **10** **999 TOTAL VEHICLE**
Activity Note: Light Medium Duty PMI
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.00
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

Activity: **20** **999 TOTAL VEHICLE**
Activity Note: PM C
Reason for Repair: 08 - Preventive Maintenance
Work Accomplished: C - PM Level C
Part Failure: -


Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
09-Sep-19	20021	FILTER, TRANSMISSION, E350, '09 W/RUBBER NECK SEAL SAME AS FT180	1.00	17.27	17.27
09-Sep-19	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 1 of 10



WorkOrder: 53340379
Invoice Number: 55345-53340379

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM C

VIN: 1FDFE4FSXEDB17155

Requested By: HPIERRE

Status: 40

Created By: HPIERRE

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

Chronology		
Reported	Apr 9, 2020	4:07 PM
Started		
Completed	Apr 10, 2020	9:31 AM
Down Time		

Meter	Reading	UOM
WO		DH
Life	230,185	DH
System	230,510	DH

WorkOrder Notes

Line	Comment
10	PMC
	Preventive maintenance
	Perform service lube all pivoting point cross rotate tires completed

Activity: 10



999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: -

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 20



999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 - Preventive Maintenance

Work Accomplished: C - PM Level C

Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended
10-Apr-20	P7398	FILTER, OIL, FULL-FLOW	1.00	1.41	1.41

Labor Posted



WorkOrder: 54402187
Invoice Number: 55345-54402187

Client Department:

MRC:	55345M	Equipment:	4602-P
WO Desc:			Ford E450 Champion Challenger
55345-LIGHT DUTY PMC		VIN:	1FDFE4FSXEDB17155
Requested By:	JUHURST	Status:	40
Created By:	JUHURST	Priority:	3
Class:	WO	Driver:	
Arrangement:	Unassigned	Phone:	
Potential Warranty:	No	ETA:	

Chronology

Reported	Apr 21, 2021	12:00 AM
Started		
Completed	Apr 21, 2021	4:41 PM
Down Time		

Meter	Reading	UOM
WO		DH
Life	255,691	DH

WorkOrder Notes

Line Comment

Activity: 5 **999/999/999 TOTAL VEHICLE**

Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW - Shop Work Order
Work Accomplished: 06 - Inspect
Part Failure: 00 - No Failure

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours: 0.00	
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Activity: 10 **020 GROUP, DRIVETRAIN**

Activity Note: Light Duty PMI
Reason for Repair: SS - Sales and Service
Work Accomplished: -
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number		Description	Qty.	Each	Extended
21-Apr-21	B329(F)		SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1.00	1.98	1.98

Labor Posted

Date	Technician	Hours	Rate	Extended

Activity 10 Sub Total

Parts:	1.98



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 2 of 9



WorkOrder: 51221024
Invoice Number: 55345-51221024

Client Department:

MRC: 55345M
WO Desc: PM B
Requested By: CKARLENS
Created By: CKARLENS
Class: WO
Arrangement: Unassigned
Potential Warranty: No

Equipment: 4602-P
Ford E450 Champion Challenger
1FDFE4FSXEDB17155
VIN:
Status: 40
Priority: 1
Driver:
Phone:
ETA:

Date	Part Number	Description	Qty.	Each	Extended
09-May-18	B329(F)	FILTER, OIL SAME AS LF3681	1.00	1.96	1.96

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	0.42	0.00	0.00

Activity 20 Sub Total

Parts: 8.62
Labor: 0.00
Labor Hours: 0.42
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 8.62

Activity: 30  **999 TOTAL VEHICLE**

Activity Note: PRAMETER
Reason for Repair: 05 - Inspection, Routine
Work Accomplished: 06 - Inspect
Part Failure: -

Activity Comments

Parts Issued

Date	Part Number	Description	Qty.	Each	Extended

Labor Posted

Date	Technician	Hours	Rate	Extended
09-May-18	Arthurs,Durvin	0.08	0.00	0.00

Activity 30 Sub Total

Parts: 0.00
Labor: 0.00
Labor Hours: 0.08
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 0.00

WorkOrder 51221024 Grand Total

Parts: 8.62
Labor: 0.00
Labor Hours: 2.50
Sublet Parts: 0.00
Sublet Labor: 0.00
WorkOrder Grand Total 8.62

Recent Repair History



WorkOrder
55345 Palm Tran Connection
v 2.2
Page 3 of 9



WorkOrder: 51221024
Invoice Number: 55345-51221024

Client Department:

MRC: 55345M

Equipment: 4602-P

WO Desc:

Ford E450 Champion Challenger

PM B

VIN: 1FDFE4FSXEDB17155

Requested By: CKARLENS

Status: 40

Created By: CKARLENS

Priority: 1

Class: WO

Driver:

Arrangement: Unassigned

Phone:

Potential Warranty: No

ETA:

WorkOrder	Date Completed	Life Meter	Class	Description
51221024	9-May-18	139,350	WO	PM B
51220741	12-Apr-18	135,248	WO	FOLLOWUP??->51097962
51097962	12-Apr-18	135,248	WO	PM A

Scheduled Preventative Maintenance

Nest	PM	WorkOrder	Due Date	Due Life Meter	Due Meter Reading	Due Life Meter 2	Due Meter Reading 2

Other Open Repairs

WorkOrder8	Date Reported	Life Meter	Class	Description

PH: Work Order: 51221024 Desc: PM B

Equip: 4602-P Desc: Ford E450 Champion Challenger VIN: 1FDFE4FSXEDB17155

LH: 10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10,000	SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 9, 2018 10:44:20 PM	No	
10,100	Safety Inspection	Done		DARTHURS	May 9, 2018 10:44:20 PM	No	
10,110	FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 9, 2018 10:44:20 PM	No	
10,120	FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,130	FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,140	Check Service Brakes	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,150	FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,160	FRA Check Instruments and Horns	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,170	Check Fast Idle	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,180	Check Starter Protection Circuit	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
10,190	Check Reverse Warning System	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
11,100	Check Parking Brake	Done		DARTHURS	May 9, 2018 10:44:22 PM	No	
11,110	Check HVAC Switches and Other Controls	Done		DARTHURS	May 9, 2018 10:44:21 PM	No	
11,120	FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 9, 2018 10:44:22 PM	No	
11,130	FRA Check Wiper and Washer Operation	Done		DARTHURS	May 9, 2018 10:44:22 PM	No	
11,140	Road Test: Check for Proper Operation	Done		DARTHURS	May 9, 2018 10:44:22 PM	No	
11,150	Perform Brake Test	Done		DARTHURS	May 9, 2018 10:44:22 PM	No	
11,152	Decelerometer Results Test 1	FEET	NA	DARTHURS	May 9, 2018 10:44:22 PM	No	
11,154	Decelerometer Results Test 2	FEET	NA	DARTHURS	May 9, 2018 10:44:22 PM	No	
11,156	Decelerometer Results Test 3	FEET	NA	DARTHURS	May 9, 2018 10:44:22 PM	No	
11,161	FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 9, 2018 10:44:22 PM	No	
11,162	FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:23 PM	No	
11,170	FRA Check Door Operation	Done		DARTHURS	May 9, 2018 10:44:23 PM	No	
11,180	FRA Check Operation of All Other Accessories	Done		DARTHURS	May 9, 2018 10:44:23 PM	No	
20,000	SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 9, 2018 10:44:23 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
20,210	Check Condition of Operator's Area	Done		DARTHURS	May 9, 2018 10:44:23 PM	No	
20,220	Check Accelerator and Brake Pedals	Done		DARTHURS	May 9, 2018 10:44:23 PM	No	
20,230	FRA Check Wiring Under Dash	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
20,240	FRA Check Interior Lights	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
20,250	FRA Check Interior Electrical Panels	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
20,260	Check Stop Request System	-	NA	DARTHURS	May 9, 2018 10:44:24 PM	No	
20,270	Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 9, 2018 10:44:24 PM	No	
20,280	Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
20,290	Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
22,100	Check Emergency Windows and Glass Condition	Done		DARTHURS	May 9, 2018 10:44:24 PM	No	
22,110	Check Emergency Hatches	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
22,120	Check All Safety Equipment	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,000	SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,310	Check Passenger Doors	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,320	Inspect Step-well and Hand Rails	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,330	Check Wheelchair Lift Operation	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,340	FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 9, 2018 10:44:26 PM	No	
30,350	FRA Inspect Mirror and Mountings	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,360	Check for Physical Damage and Decals	Done		DARTHURS	May 9, 2018 10:44:25 PM	No	
30,370	Check Wiper Blade and Arm Condition	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
30,380	Check Exterior Compartment Doors	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
30,390	FRA Check Fuel Tank Cap	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
33,100	Check Lights and Reflectors	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
33,110	Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
40,000	SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
40,410	FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 9, 2018 10:44:26 PM	No	
40,420	Check Hood	Done		DARTHURS	May 9, 2018 10:44:27 PM	No	
40,430	Check Fan, Shroud and Radiator	Done		DARTHURS	May 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:44:27 PM		
40,440	Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 9, 2018 10:44:27 PM	No	
40,441	Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 9, 2018 10:44:27 PM	No	
40,442	Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:27 PM	No	
40,450	FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 9, 2018 10:44:27 PM	No	
40,460	Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 9, 2018 10:44:27 PM	No	
40,461	Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:27 PM	No	
40,470	Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
40,480	FRA Check Coolant Hose Condition	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
40,490	FRA Check Alternator Mount and Condition	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,100	FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,110	FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,120	FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,130	FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,140	FRA Check Intake System	Done		DARTHURS	May 9, 2018 10:44:28 PM	No	
44,150	FRA Inspect Turbocharger	-	NA	DARTHURS	May 9, 2018 10:44:28 PM	No	
44,160	FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
44,170	FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
44,180	FRA Check for Leaks	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
44,190	FRA Perform Battery Inspection	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
44,200	FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
50,000	SECTION 5 Steering System Inspection	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
50,510	Check Entire Steering System	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
60,000	SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
60,610	FRA Check and Record Air Pressure	Done		DARTHURS	May 9, 2018 10:44:29 PM	No	
60,611	Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:29 PM	No	
60,612	Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,613	Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:30 PM	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
60,614	Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,615	Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,616	Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,620	Check Valve Stems and Caps	Done		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,630	Check and Record Tread Depth	Done		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,631	Tread Depth RF	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:30 PM	No	
60,632	Tread Depth LF	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,633	Tread Depth RRO	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,634	Tread Depth RRI	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,635	Tread Depth LRI	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,636	Tread Depth LRO	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,640	Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,650	Check Sidewall Wear	Done		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,660	Inspect for Cuts and Tears	Done		DARTHURS	May 9, 2018 10:44:31 PM	No	
60,670	Check Dual Mating With Square	-	NA	DARTHURS	May 9, 2018 10:44:32 PM	No	
60,680	Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 9, 2018 10:44:32 PM	No	
60,690	Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 9, 2018 10:44:31 PM	No	
66,100	FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 9, 2018 10:44:32 PM	No	
70,000	SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 9, 2018 10:44:32 PM	No	
70,710	Check Vibration Damper	Done		DARTHURS	May 9, 2018 10:44:32 PM	No	
70,720	Check Engine and Transmission Mounts	Done		DARTHURS	May 9, 2018 10:44:32 PM	No	
70,730	FRA Check Starter	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,740	FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,750	FRA Check Transmission for Leaks	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,760	FRA Check Differential Breather and Fluid	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,770	FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,780	Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
70,790	Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:44:33 PM		
77,100	FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 9, 2018 10:44:33 PM	No	
77,110	FRA Check Fuel Tank	Done		DARTHURS	May 9, 2018 10:44:34 PM	No	
77,120	Check Suspension Components	Done		DARTHURS	May 9, 2018 10:44:34 PM	No	
77,130	FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 9, 2018 10:44:34 PM	No	
77,131	Brake Pad Thickness LF	11 Inch		DARTHURS	May 9, 2018 10:44:34 PM	No	
77,132	Brake Pad Thickness RF	11 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,133	Brake Pad Thickness LR	11 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,134	Brake Pad Thickness RR	11 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,135	Brake Rotor LF	1.556 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,136	Brake Rotor RF	1.557 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,137	Brake Rotor LR	1.643 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,138	Brake Rotor RR	1.645 Inch		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,140	FRA Check Brake Hoses	Done		DARTHURS	May 9, 2018 10:44:35 PM	No	
77,150	Check King Pins	-	NA	DARTHURS	May 9, 2018 10:44:36 PM	No	
77,160	FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 9, 2018 10:44:36 PM	No	
80,000	SECTION 8 PMI Report Completion	Done		DARTHURS	May 9, 2018 10:44:36 PM	No	
80,810	Completion of PMI Report	Done		DARTHURS	May 9, 2018 10:44:36 PM	No	
90,000	SECTION 9 Completion of PMI	Done		DARTHURS	May 9, 2018 10:44:36 PM	No	
90,910	Vehicle Returned to predetermined location	Done		DARTHURS	May 9, 2018 10:44:37 PM	No	

LH: 20 Desc: PM B

Task: PM B SERVICE Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
100,000	"A" PMI SERVICING ITEMS	Done		DARTHURS	May 9, 2018 10:45:58 PM	No	
101,000	FRA Change Oil Filters	Yes		DARTHURS	May 9, 2018 10:45:58 PM	No	
102,000	FRA Drain Engine Oil	Yes		DARTHURS	May 9, 2018 10:45:58 PM	No	
103,000	FRA Check Transmission Fluid	Done		DARTHURS	May 9, 2018 10:45:58 PM	No	
104,000	Lubricate Chassis	Done		DARTHURS	May 9, 2018 10:45:59 PM	No	
105,000	Replace or Clean A/C Filters	Done		DARTHURS	May 9, 2018	No	

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
					10:45:59 PM		
107,000	FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 9, 2018 10:45:59 PM	No	
108,000	Lube all pivoting Mechanisms	Done		DARTHURS	May 9, 2018 10:45:59 PM	No	
200,000	"B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	May 9, 2018 10:45:59 PM	No	
201,000	Service Crankcase Breather	-	NA	DARTHURS	May 9, 2018 10:46:00 PM	No	
203,000	FRA Change Automatic Transmission Fluid	Yes		DARTHURS	May 9, 2018 10:46:00 PM	No	
204,000	FRA Change Power Steering Fluid and Filter	No		DARTHURS	May 9, 2018 10:45:59 PM	No	
205,000	Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	May 9, 2018 10:46:00 PM	No	

LH: 30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-18

Line	Inspection	RESULTS	Notes	Performed By	Date Inspected	Follow Up	Follow Up WO
10	Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2018 10:46:26 PM	No	
20	Miles					No	
30	Kilometers					No	
40	Hours					No	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57162564
Invoice No. 55345 - 57162564

Client Department:			
Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FIRST TRANSIT AC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NBARRETO	Status:	40 - Closed (40)
Created By:	NBARRETO	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	297,087 -

Activity Header															
Activity: 10 001/001/001 AIR CONDITIONING															
Activity Note: More VEHICLE RETIRED															
Reason for Repair:	05 Inspection, Routine														
Work Accomplished:	06 Inspect														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 10 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 10 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 10 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 57162564 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 57162564 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 57162564 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57493267
Invoice No. 55345 - 57493267

Client Department:
Department: 55345M
Work Order Description wrench light
Requested By: GJUGGERDEO
Created By: GJUGGERDEO
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 297,087 - DH

Chronology		
Reported	Sep 6, 2024 5:10:00 PM	Sep 6, 2024 5:10:00 PM
Started	Sep 6, 2024 5:14:00 PM	
Completed	Sep 6, 2024 8:26:00 PM	Sep 6, 2024 8:26:00 PM
Down Time		

Work Order Notes

Line 10 Code detected. .PO3000 PO301. PO302. PO316

Drive no shake and no shut off Line 20 Check battery and both are good 12.6 volts each

Activity Header
Activity:10 999 TOTAL VEHICLE
Activity Note: CEL
Reason for Repair: * Reason for repair code
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-24	Goonashwar Juggerdeo	3.2	65	208

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total
Parts: 0.00
Labor: 208.00
Labor Hours: 3.20
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 208.00

Work Order Footer

Work Order 57493267 Total
Parts: 0.00
Labor: 208.00
Labor Hours: 3.20
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 208.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57451514
Invoice No. 55345 - 57451514

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
STUCK IN MUD		Ford E450 Champion Challenger	
Requested By:	CJOUBERT	Status:	40 - Closed (40)
Created By:	CJOUBERT	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	296,137 - DH

Chronology		
Reported	Jul 18, 2024 9:51:00 AM	Jul 18, 2024 9:51:00 AM
Started		
Completed	Jul 29, 2024 2:01:13 PM	Jul 29, 2024 2:01:13 PM
Down Time		

Work Order Notes

Line 10 VEHICLE WAS STUCK IN MUD

Activity Header					
Activity:10 999 TOTAL VEHICLE					
Activity Note: WINCH OUT VEHICLE STUCK IN MUD					
Reason for Repair: TW Towing					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Jul-24	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	165	165
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:		165.00
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		165.00
Work Order Footer					
			Work Order 57451514 Total		
			Parts:		165.00
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		165.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57449002
Invoice No. 55345 - 57449002

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	296,137 - DH

Chronology		
Reported	Jul 15, 2024 6:38:00 PM	Jul 15, 2024 6:38:00 PM
Started	Jul 15, 2024 6:44:00 PM	
Completed	Jul 15, 2024 7:49:00 PM	Jul 15, 2024 7:49:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Passenger side view mirror missing.

Cause: Unknown.

Correction: Replaced passenger side view mirror with good used unit.

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 15-JUL-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 15, 2024 7:49:03 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57449002
Invoice No. 55345 - 57449002

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Unscheduled Work		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	296,137 - DH

Activity Header				
Activity: 15 053/004/000 SAFETY EQUIPMENT				
Activity Note: Passenger side view mirror missing.				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-24	Earl Johnson	1.03	65	66.95
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	66.95
			Labor Hours:	1.03
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	66.95
Work Order Footer				
			Work Order 57449002 Total	
			Parts:	0.00
			Labor:	66.95
			Labor Hours:	1.03
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	66.95



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57427941
Invoice No. 55345 - 57427941

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
CHECK AC SYSTEM FOR PROPER OPERATION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	295,074 - DH

Chronology		
Reported	Jun 19, 2024 9:05:00 AM	Jun 19, 2024 9:05:00 AM
Started	Jun 19, 2024 9:53:00 AM	
Completed	Jun 20, 2024 3:56:00 PM	Jun 20, 2024 3:56:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: Per driver, ac is not working

Cause: Compressor comes on and off due to low Freon

Correction: Tech found that rear AC low side hose is leaking
Fix low side hose, vacuum system and recharge System
Ac is working normal at this time..

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 20-JUN-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	
103 - Are you properly trained to perform the task for this unit	Done		TDELVA	Jun 20, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and fuel type of Liquid Propane Gas (LPG) engines?				3:55:32 PM		
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 20, 2024 3:55:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57427941
Invoice No. 55345 - 57427941

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
CHECK AC SYSTEM FOR PROPER OPERATION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	295,074 - DH

Activity Header
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: INSPECT AND REPAIR AIR CONDITIONING SYSTEM PER PTC IS NOT WORKING
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jun-24	3411885	TUBE, ORIFICE, A/C, FORD	1	0.9	0.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Jun-24	Delva,Terry	2.68	65	174.2
20-Jun-24	Delva,Terry	14.28	65	928.2
19-Jun-24	Delva,Terry	9.5	65	617.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	0.90	Labor:	1,719.90
Labor Hours:	26.46	Labor Hours:	26.46
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		1,720.80	

Work Order Footer		Work Order 57427941 Total	
Parts:	0.90	Labor:	1,719.90
Labor Hours:	26.46	Labor Hours:	26.46
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		1,720.80	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57421037
Invoice No. 55345 - 57421037

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PER DRIVER AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,621 - DH

Chronology		
Reported	Jun 11, 2024 8:52:00 AM	Jun 11, 2024 8:52:00 AM
Started	Jun 11, 2024 9:10:00 AM	
Completed	Jun 11, 2024 12:43:00 PM	Jun 11, 2024 12:43:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction: Line 20 No issue found with the AC
Adjusted w/c lift so it could be folded properly

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 11-JUN-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 11, 2024 12:42:32 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57421037
Invoice No. 55345 - 57421037

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PER DRIVER AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,621 - DH

Activity Header				
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: INSPECT AND REPAIR AIR CONDITINING SYSTEM				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Jun-24	Delva,Terry	3.53	65	229.45
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	229.45
			Labor Hours:	3.53
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	229.45
Work Order Footer				
			Work Order 57421037 Total	
			Parts:	0.00
			Labor:	229.45
			Labor Hours:	3.53
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	229.45



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57411977
Invoice No. 55345 - 57411977

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
rear AC issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,621 - DH

Chronology		
Reported	May 30, 2024 9:13:00 PM	May 30, 2024 9:13:00 PM
Started	May 30, 2024 9:19:00 PM	
Completed	Jun 11, 2024 7:40:11 AM	Jun 11, 2024 7:40:11 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction: Line 20 Unit in for AC REPAIR LEAKING FROM dryer. The line is too tight can't pull. Line 30 Removed broken part from unit part on. The way Line 40 Replaced rear ac dryer and orifice tube

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 30-MAY-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	May 30, 2024 9:17:41	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				PM		
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	May 30, 2024 9:17:41 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57411977
Invoice No. 55345 - 57411977

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
rear AC issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,621 - DH

Activity Header
Activity:15 003 INSTRUMENTS, GAUGES, WARNING & SHUT-DOWN DEVICES
Activity Note: Rear AC ISSUE
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jun-24	11127164A	ACCUMULATOR, A/C, 3", 12FOX12M	1	25	25
05-Jun-24	3411885	TUBE, ORIFICE, A/C, FORD	1	0.9	0.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Jun-24	Delva,Terry	2.35	65	152.75
03-Jun-24	Junior Hurst	3.72	65	241.8
30-May-24	Junior Hurst	0.4	65	26

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			25.90
Labor:			420.55
Labor Hours:			6.47
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			446.45

Work Order Footer		Work Order 57411977 Total	
Parts:			25.90
Labor:			420.55
Labor Hours:			6.47
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			446.45



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57404816
Invoice No. 55345 - 57404816

Client Department:
Department: 55345M
Work Order Description
lift arm rest broken/REAR AC
Requested By: RGASPARD
Created By: RGASPARD
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 294,621 - DH

Chronology		
Reported	May 22, 2024 5:56:00 PM	May 22, 2024 5:56:00 PM
Started	May 22, 2024 6:01:00 PM	
Completed	May 27, 2024 5:27:00 PM	May 27, 2024 5:27:00 PM
Down Time		

Work Order Notes


Line 10 Needs lift arm rest
Broken
Disassembly the arm ,sent it to welding shop
Get it back, reinstall the lift arm rest.

Activity Header Activity: 10 Activity Note: Reason for Repair: Work Accomplished: Part Failure: Activity Comments:					
Activity Parts No Data Available					
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
23-May-24	Gaspard,Ronald	2.45	65	159.25	
22-May-24	Gaspard,Ronald	0.85	65	55.25	
Activity Sublet No Data Available					
Activity Checklist No Data Available No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:	0.00	
			Labor:	214.50	
			Labor Hours:	3.30	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	214.50	
Work Order Footer					
			Work Order 57404816 Total		
			Parts:	0.00	
			Labor:	214.50	

	Labor Hours:	3.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	214.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57400350
Invoice No. 55345 - 57400350

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Engine Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Chronology		
Reported	May 17, 2024 7:38:00 AM	May 17, 2024 7:38:00 AM
Started	May 17, 2024 7:49:00 AM	
Completed	May 17, 2024 12:25:00 PM	May 17, 2024 12:25:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction: Line 20 Drive Cam Not Working. Check Found drive cam bad Remove & Replace drive cam. Check A/C No Problem Found. Check Engine Light on Scan Found Code PO741 TCC Solenoid /PO1744 TCC Clutch Circuit performance. .Remove Transmission wire From Transmission Clean & Replace Road test Wrench Light Did not Return.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 17-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 17, 2024 7:49:06 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57400350
Invoice No. 55345 - 57400350


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Engine Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Activity Header				
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: Check Rea A/C				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
17-May-24	Arthurs,Durvin	2.12	65	137.8
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	137.80
			Labor Hours:	2.12
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	137.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57400350
Invoice No. 55345 - 57400350

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Engine Light / Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Activity Header
Activity:25 033 IGNITION
Activity Note: Check Engine Light on
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
17-May-24	Arthurs,Durvin	0.55	65	35.75
17-May-24	Arthurs,Durvin	1.68	65	109.2

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
		Parts:	0.00
		Labor:	144.95
		Labor Hours:	2.23
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	144.95

Work Order Footer		Work Order 57400350 Total	
		Parts:	0.00
		Labor:	282.75
		Labor Hours:	4.35
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	282.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57396071
Invoice No. 55345 - 57396071

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
AC vents		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Chronology		
Reported	May 13, 2024 9:04:00 AM	May 13, 2024 9:04:00 AM
Started	May 13, 2024 9:07:00 AM	
Completed	May 14, 2024 7:31:00 AM	May 14, 2024 7:31:00 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction: Line 20 Driver said wipers not working properly

Preventive maintenance

Replace wipers completed Line 30 Replaced wipers blades completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-MAY-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
400 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
700 - Have you performed the proper LOTO?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 14, 2024 7:30:57 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57396071
Invoice No. 55345 - 57396071

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
AC vents		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Activity Header				
Activity:15 999 TOTAL VEHICLE				
Activity Note: wipers				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-May-24	Pierre,Hubert J	4.7	65	305.5
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	305.50
			Labor Hours:	4.70
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	305.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57396071
Invoice No. 55345 - 57396071

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
AC vents		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,475 - DH

Activity Header
Activity:25 999 TOTAL VEHICLE
Activity Note: Rear AC vents
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-24	20CA	BLADE, WIPER, WINDSHIELD	2	7.81	15.62

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:	15.62	Labor:	0.00
Labor Hours:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		15.62	

Work Order Footer		Work Order 57396071 Total	
Parts:	15.62	Labor:	305.50
Labor Hours:	4.70	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		321.12	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5



Work Order No. 57350171
Invoice No. 55345 - 57350171

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Medium Duty
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 294,063 - DH

Chronology		
Reported	Mar 21, 2024 2:55:52 PM	Mar 21, 2024 2:55:52 PM
Started	Mar 21, 2024 3:13:00 PM	
Completed	Mar 22, 2024 5:18:53 PM	Mar 22, 2024 5:18:53 PM
Down Time		

Work Order Notes

Line 10 Change transmission filter and gasket
Change front rotors including bearings and seals
Change front brakes
Replaced wiper blades
Engine belt is being replaced

Activity Header					
Activity: 10					
Activity Note: pull right when brake					
Reason for Repair:					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	20CA	BLADE, WIPER, WINDSHIELD	1	6.25	6.25
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:		6.25
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		6.25



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5



Work Order No. 57350171
Invoice No. 55345 - 57350171

Client Department:			
Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,063 - DH

Activity Header					
Activity:20 045/009/003 BODY, PUMP, OIL, ENGINE					
Activity Note: Engine oil leaks					
Reason for Repair: FW Follow Up					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	40526	BLADE, WIPER, WINDSHIELD	1	4.79	4.79
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:		4.79
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		4.79



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5



Work Order No. 57350171
Invoice No. 55345 - 57350171

Client Department:			
Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,063 - DH

Activity Header					
Activity:30 013/002/012 SHOE & LINING, BRAKE, REAR					
Activity Note: Front Rotors Grooves					
Reason for Repair: FW Follow Up					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	15101	BEARING, WHEEL, OUTER, FRONT	2	10.28	20.56
22-Mar-24	LM102949	BEARING, WHEEL, INNER, FRONT, TAPERED	2	9.87	19.74
22-Mar-24	604-54211	ROTOR, BRAKE	2	168.17	336.34
22-Mar-24	BRS-93	SEAL, WHEEL, FRONT, ECONOLINE, '06	2	7.94	15.88
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
22-Mar-24	Delva,Terry	4.58	65	297.7	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 30 Sub Total		
			Parts:	392.52	
			Labor:	297.70	
			Labor Hours:	4.58	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	690.22	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5



Work Order No. 57350171
Invoice No. 55345 - 57350171

Client Department:			
Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	294,063 - DH

Activity Header					
Activity:40 045/009/003 BODY, PUMP, OIL, ENGINE					
Activity Note: Transmission service					
Reason for Repair: FW Follow Up					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	8C2Z-2001-C	PADS, BRAKE, DISC, FRONT SAME AS PFH132820	1	58.7	58.7
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
21-Mar-24	Delva,Terry	1.57	65	102.05	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 40 Sub Total		
			Parts: 58.70		
			Labor: 102.05		
			Labor Hours: 1.57		
			Sublet Parts: 0.00		
			Sublet Labor: 0.00		
			Activity Sub Total 160.75		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5



Work Order No. 57350171
Invoice No. 55345 - 57350171

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
FOLLOWUP-FT Medium Duty		Status:	40 - Closed (40)
Requested By:	TDELVA	Priority:	3 - High
Created By:	TDELVA	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	294,063 - DH
Potential Warranty:	No		

Activity Header															
Activity:50 999 TOTAL VEHICLE															
Activity Note: ROAD CALLbelt came of															
Reason for Repair: 10 Road Call															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 50 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 50 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 50 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 57350171 Total</td></tr><tr><td>Parts:</td><td>462.26</td></tr><tr><td>Labor:</td><td>399.75</td></tr><tr><td>Labor Hours:</td><td>6.15</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>862.01</td></tr></table>		Work Order 57350171 Total		Parts:	462.26	Labor:	399.75	Labor Hours:	6.15	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	862.01
Work Order 57350171 Total															
Parts:	462.26														
Labor:	399.75														
Labor Hours:	6.15														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	862.01														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57348843
Invoice No. 55345 - 57348843

Client Department:

Department: 55345M

Work Order Description

Road Call

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 293,936 - DH

Chronology		
Reported	Mar 20, 2024 8:15:00 AM	Mar 20, 2024 8:15:00 AM
Started	Mar 20, 2024 8:17:00 AM	
Completed	Mar 22, 2024 11:35:20 AM	Mar 22, 2024 11:35:20 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: battery light on

Cause: tech found drive belt was off

Correction: replaced the belt , drive the vehicle to base for more diagnostic , vehicle pull to the right ,check brakes

Activity Header				
Activity: 10 999 TOTAL VEHICLE				
Activity Note: ROAD CALLbelt came of				
Reason for Repair: 10 Road Call				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
20-Mar-24	NELSON PIERRE-LOUIS	2.63	65	170.95
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	170.95
			Labor Hours:	2.63



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57273725
Invoice No. 55345 - 57273725

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,762 - DH

Chronology		
Reported	Mar 21, 2024 12:23:44 PM	Mar 21, 2024 12:23:44 PM
Started	Mar 21, 2024 12:48:00 PM	
Completed	Mar 21, 2024 3:14:00 PM	Mar 21, 2024 3:14:00 PM
Down Time		

Work Order Notes

Line 10 Pmc

Service due

Performed and completed pmc

Activity Header						
Activity:5 999/999/999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure: 00 No Failure						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 21-MAR-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
400 - Are you wearing the appropriate PPE?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
700 - Have you performed the proper LOTO?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Mar 21, 2024 1:38:53 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57273725
Invoice No. 55345 - 57273725

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMC

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 293,762 - DH

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: Medium Duty PM Inspection

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-24	Delva, Terry	2.42	65	157.3

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Medium Duty PM Inspection

Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: TDELVA Performed on: 21-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,800 - CHECK_All Destination Signage	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		TDELVA	Mar 21, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				2:55:46 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done	pull right when brake	TDELVA	Mar 21, 2024 2:55:46 PM	Yes	57350171
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,200 - CHECK_Public Address System	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,500 - INSPECT_High Idle Control	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
31,000 - SSF (Street Side Front)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,000 - Engine Inspection	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done	Engine oil leaks	TDELVA	Mar 21, 2024 2:55:46 PM	Yes	57350171
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,100 - INSPECT_Intake System	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,000 - CSF (Curb Side Front)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		TDELVA	Mar 21, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:55:46 PM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		TDELVA	Mar 21, 2024 2:55:46 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,400 - LUBE_All Chassis Components	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	35.8 Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	35.8 Inch	Front Rotors Grooves	TDELVA	Mar 21, 2024 2:55:46 PM	Yes	57350171
52,100 - INSPECT_Vibration Damper	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done	Transmission service	TDELVA	Mar 21, 2024 2:55:46 PM	Yes	57350171
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,600 - INSPECT_Tire Condition	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	-	na	TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	36.8 Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	36.8 Inch		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
55,900 - !FRA!INSPECT_Under Body Exhaust System	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	89 Cycles	000	TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,500 - INSPECT_Bridgeplate Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		TDELVA	Mar 21, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:55:46 PM		
62,400 - INSPECT_All Pivot Points	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,500 - INSPECT_Cams and Slots	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,600 - INSPECT_Rollers	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
62,700 - INSPECT_All Linkages	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		TDELVA	Mar 21, 2024 2:55:46 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	157.30
Labor Hours:	2.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	157.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57273725
Invoice No. 55345 - 57273725

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,762 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM C Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Mar-24	20021	FILTER, TRANSMISSION 20021	1	36.01	36.01
21-Mar-24	75050	OIL, ENGINE, 5W/30	8	2.75	22
21-Mar-24	LF3681	FILTER, OIL, SPIN-ON SEE P550965	1	9.2	9.2

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: Medium Duty PM C Service						
Task: 55345-Medium Duty PMC Inspection Performed by: TDELVA Performed on: 21-MAR-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	-	na	TDELVA	Mar 21, 2024 3:05:53 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	TDELVA	Mar 21, 2024 3:05:53 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Mar 21, 2024	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:05:53 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
201,000 - Service Crankcase Breather	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
202,000 - FRA Change Water Separator & Secondary Fuel Filters	No	na	TDELVA	Mar 21, 2024 3:05:53 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
302,000 - Check Toe-In and Record Reading	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	TDELVA	Mar 21, 2024 3:05:53 PM	No	
303,000 - FRA Service Davco Type Water Separators (Secondary Fuel Filter)	-	na	TDELVA	Mar 21, 2024 3:05:53 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
305,000 - FRA Change Differential Fluid	Yes		TDELVA	Mar 21, 2024 3:05:53 PM	No	
306,000 - Change Spark Plugs	Done		TDELVA	Mar 21, 2024 3:05:53 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	67.21
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	67.21

Work Order Footer

Work Order 57273725 Total	
Parts:	67.21
Labor:	157.30
Labor Hours:	2.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	224.51



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57346780
Invoice No. 55345 - 57346780

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
LIFT DOOR HANDLE IS MISSING		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,406 - DH

Chronology		
Reported	Mar 18, 2024 7:59:00 AM	Mar 18, 2024 7:59:00 AM
Started	Mar 18, 2024 9:10:00 AM	
Completed	Mar 19, 2024 6:35:00 PM	Mar 19, 2024 6:35:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: LIFT DOOR HANDLE IS MISING

Cause: UNKNOWN

Correction: installed new door handle


Part. Shop supply

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 18-MAR-24

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
400 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
700 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Mar 18, 2024 9:47:33 AM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57346780
Invoice No. 55345 - 57346780

Client Department:

Department: 55345M

Work Order Description

LIFT DOOR HANDLE IS MISSING

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 293,406 - DH

Activity Header

Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING

Activity Note: LIFT DOOR HANDLE IS MISING

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-24	1017076	HANDLE, WINDOW, SLIDER, CHAMPION	6	22.68	136.08

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Mar-24	Rodriguez,Raul	0.63	65	40.95
19-Mar-24	Pierre,Hubert J	0.03	65	1.95

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	136.08
Labor:	42.90
Labor Hours:	0.66
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	178.98

Work Order Footer

Work Order 57346780 Total

Parts:	136.08
Labor:	42.90
Labor Hours:	0.66
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	178.98



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57342277
Invoice No. 55345 - 57342277

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
windshield replacement		Ford E450 Champion Challenger	
Requested By:	NBARRETO	Status:	40 - Closed (40)
Created By:	NBARRETO	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,707 - DH

Chronology		
Reported	Mar 12, 2024 5:45:00 PM	Mar 12, 2024 5:45:00 PM
Started	Mar 12, 2024 5:51:00 PM	
Completed	Mar 13, 2024 4:19:00 PM	Mar 13, 2024 4:19:00 PM
Down Time		

Work Order Notes

Line 10 Windshield replaced by external company

Drive cam re installed on new windshield

Line 20 Remove tapes, inspect bus and put it back in service

Activity Header																																			
Activity: 5 999 TOTAL VEHICLE																																			
Activity Note: Personal Risk Assessment																																			
Reason for Repair: SW Shop Work Order																																			
Work Accomplished: 06 Inspect																																			
Part Failure:																																			
Activity Comments:																																			
Activity Parts																																			
No Data Available																																			
Activity Labor																																			
No Data Available																																			
Activity Sublet																																			
No Data Available																																			
Activity Checklist																																			
Check List 5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 12-MAR-24 <table><tr><th>Inspection Item</th><th>RESULTS</th><th>Inspector's Note</th><th>Inspector</th><th>Date Inspected</th><th>Follow Up Needed</th><th>Follow Up WO</th></tr><tr><td>100 - Are you properly trained to perform the task?</td><td>Done</td><td></td><td>NBARRETO</td><td>Mar 12, 2024 5:49:31 PM</td><td>No</td><td></td></tr><tr><td>103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?</td><td>Done</td><td></td><td>NBARRETO</td><td>Mar 12, 2024 5:49:31 PM</td><td>No</td><td></td></tr><tr><td>200 - If task requires lifting, are lifts secured, are jack stands used correctly?</td><td>Done</td><td></td><td>NBARRETO</td><td>Mar 12, 2024 5:49:31 PM</td><td>No</td><td></td></tr><tr><td>400 - Are you wearing the appropriate PPE?</td><td>Done</td><td></td><td>NBARRETO</td><td>Mar 12, 2024 5:49:31 PM</td><td>No</td><td></td></tr></table>	Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	100 - Are you properly trained to perform the task?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No		103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No		200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No		400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No	
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																													
100 - Are you properly trained to perform the task?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No																														
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No																														
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No																														
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No																														

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
700 - Have you performed the proper LOTO?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Mar 12, 2024 5:49:31 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57342277
Invoice No. 55345 - 57342277

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
windshield replacement		Ford E450 Champion Challenger	
Requested By:	NBARRETO	Status:	40 - Closed (40)
Created By:	NBARRETO	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,707 - DH

Activity Header				
Activity: 15 002 CAB & SHEET METAL				
Activity Note: Windshield replacement				
Reason for Repair: 42 Physical Damage				
Work Accomplished: 03 Replace New				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Mar-24	Nicolas Barreto	1.2	65	78
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	78.00
			Labor Hours:	1.20
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	78.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57342277
Invoice No. 55345 - 57342277

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
windshield replacement		Ford E450 Champion Challenger	
Requested By:	NBARRETO	Status:	40 - Closed (40)
Created By:	NBARRETO	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	293,707 - DH

Activity Header
Activity:25 999 TOTAL VEHICLE
Activity Note: Windshiled replaced
Reason for Repair: 42 Physical Damage
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Mar-24	DSP-ACCIDENT	DIRECT PURCHASE FOR SERVICES ACCIDENT	1	368	368

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:	368.00	Parts:	368.00
Labor:	0.00	Labor:	0.00
Labor Hours:	0.00	Labor Hours:	0.00
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		368.00	

Work Order Footer		Work Order 57342277 Total	
Parts:	368.00	Parts:	368.00
Labor:	78.00	Labor:	78.00
Labor Hours:	1.20	Labor Hours:	1.20
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		446.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57313780
Invoice No. 55345 - 57313780

Client Department:

Department: 55345M

Work Order Description

Road Call

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 291,888 - DH

Chronology		
Reported	Feb 8, 2024 6:34:00 AM	Feb 8, 2024 6:34:00 AM
Started	Feb 8, 2024 6:35:00 AM	
Completed	Feb 8, 2024 7:57:00 AM	Feb 8, 2024 7:57:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: main door hard to close

Cause: preventive maintenance

Correction: adjusted the door lube everything ok at this time

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 08-FEB-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Feb 8, 2024 7:53:54 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57313780
Invoice No. 55345 - 57313780

Client Department:

Department: 55345M

Work Order Description

Road Call

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 291,888 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Feb-24	NELSON PIERRE-LOUIS	1.35	65	87.75

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	87.75
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	87.75


Work Order Footer

Work Order 57313780 Total

Parts:	0.00
Labor:	87.75
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	87.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57287114
Invoice No. 55345 - 57287114

Client Department:

Department: 55345M

Work Order Description

Rear AC malfunction.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 290,921 - DH

Chronology

Reported	Jan 7, 2024 5:52:00 PM	Jan 7, 2024 5:52:00 PM
Started	Jan 7, 2024 5:53:00 PM	
Completed	Jan 22, 2024 12:30:00 PM	Jan 22, 2024 12:30:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Front AC malfunction.

Cause: Unknown

Correction: Front AC operates as intended, pressures are within spec. Rear AC system not operating properly, noticed upon parking vehicle.

WC lift roll stop pivot points binding. Suspect interior rust, lubricated to no avail. Recommend disassembly, thorough clean and lube and replace rollers. Out of service for repair. Line 20 Driver said rear arc not working

The hose that goes on the high side of the dryer was loose

Reconnected the hose properly completed Line 30 Rear ac
Perform regular maintenance
All okay at this time

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 09-JAN-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 9, 2024 11:12:42 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:	0.00		
			Labor:	0.00		
			Labor Hours:	0.00		
			Sublet Parts:	0.00		
			Sublet Labor:	0.00		
			Activity Sub Total	0.00		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57287114
Invoice No. 55345 - 57287114

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,921 - DH

Activity Header
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear AC malfunction.
Reason for Repair: 04 Driver's Report
Work Accomplished: 09 Troubleshooting
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
18-Jan-24	Rodriguez,Raul	1.28	65	83.2	
19-Jan-24	Rodriguez,Raul	1.07	65	69.55	
08-Jan-24	Earl Johnson	1.18	65	76.7	
18-Jan-24	Pierre,Hubert J	3.55	65	230.75	
10-Jan-24	Pierre,Hubert J	1.32	65	85.8	
07-Jan-24	Earl Johnson	0.33	65	21.45	

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	567.45
		Labor Hours:	8.73
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	567.45

Work Order Footer		Work Order 57287114 Total	
		Parts:	0.00
		Labor:	567.45
		Labor Hours:	8.73
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	567.45



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57284459
Invoice No. 55345 - 57284459

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,778 - DH

Chronology		
Reported	Jan 4, 2024 1:13:00 AM	Jan 4, 2024 1:13:00 AM
Started	Jan 4, 2024 1:16:00 AM	
Completed	Jan 4, 2024 1:41:00 AM	Jan 4, 2024 1:41:00 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: WC lift malfunction.

Cause: Up cutoff micro switch out of range.

Correction: Readjusted up cutoff micro switch to spec. Ran lift thru 4 consecutive cycles without any issues.

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 04-JAN-24						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 4, 2024 1:40:53 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57284459
Invoice No. 55345 - 57284459

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,778 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WC lift malfunction.
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-24	Earl Johnson	0.42	65	27.3

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>27.30</td></tr><tr><td>Labor Hours:</td><td>0.42</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>27.30</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	27.30	Labor Hours:	0.42	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	27.30
Activity 15 Sub Total															
Parts:	0.00														
Labor:	27.30														
Labor Hours:	0.42														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	27.30														

Work Order Footer															
<table><tr><th colspan="2">Work Order 57284459 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>27.30</td></tr><tr><td>Labor Hours:</td><td>0.42</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>27.30</td></tr></table>		Work Order 57284459 Total		Parts:	0.00	Labor:	27.30	Labor Hours:	0.42	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	27.30
Work Order 57284459 Total															
Parts:	0.00														
Labor:	27.30														
Labor Hours:	0.42														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	27.30														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57280265
Invoice No. 55345 - 57280265

Client Department:

Department: 55345M

Work Order Description

Fuel gauge issue

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 290,604 - DH

Chronology

Reported	Dec 28, 2023 1:26:38 PM	Dec 28, 2023 1:26:38 PM
Started	Dec 28, 2023 1:30:00 PM	
Completed	Dec 28, 2023 4:20:00 PM	Dec 28, 2023 4:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: vehicle came in for cereal gauge issue

Cause: send a unit broken

Correction: take one from a retired unit. and change gage now working return vehicle back to work . Line 20
Recheck unit and reclean connectors. For fuel gage now working asdesign unit back on line Line 30 I try to stop
the time but i cant

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts No Data Available
Activity Labor No Data Available
Activity Sublet No Data Available
Activity Checklist
Check List 5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JUHURST Performed on: 28-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Dec 28, 2023 4:14:53 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57280265
Invoice No. 55345 - 57280265

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Fuel gauge issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,604 - DH

Activity Header				
Activity:15 020 GROUP, DRIVETRAIN				
Activity Note: Fuel gauge issues				
Reason for Repair: 11 Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Dec-23	Junior Hurst	2.77	65	180.05
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	180.05
			Labor Hours:	2.77
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	180.05
Work Order Footer				
			Work Order 57280265 Total	
			Parts:	0.00
			Labor:	180.05
			Labor Hours:	2.77
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	180.05



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57278378
Invoice No. 55345 - 57278378

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
interior Light. Keep flashing		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,604 - DH

Chronology		
Reported	Dec 26, 2023 2:02:54 PM	Dec 26, 2023 2:02:54 PM
Started	Dec 26, 2023 2:04:00 PM	
Completed	Dec 26, 2023 3:49:00 PM	Dec 26, 2023 3:49:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: interior light keep Flashing on /Off

Cause: Passenger door Stop Switch loose

Correction: Remove & Replace Passenger door cover to adjust Stop Switch. All is Ok at this time.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 26, 2023 2:05:42 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57278378
Invoice No. 55345 - 57278378

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
interior Light. Keep flashing		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,604 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Interior light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
26-Dec-23	Arthurs,Durvin	1.73	65	112.45

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:		0.00	
Labor:		112.45	
Labor Hours:		1.73	
Sublet Parts:		0.00	
Sublet Labor:		0.00	
Activity Sub Total		112.45	

Work Order Footer		Work Order 57278378 Total	
Parts:		0.00	
Labor:		112.45	
Labor Hours:		1.73	
Sublet Parts:		0.00	
Sublet Labor:		0.00	
Activity Sub Total		112.45	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57273710
Invoice No. 55345 - 57273710

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,503 - DH

Chronology		
Reported	Dec 19, 2023 4:25:30 PM	Dec 19, 2023 4:25:30 PM
Started	Dec 19, 2023 4:36:00 PM	
Completed	Dec 19, 2023 9:13:00 PM	Dec 19, 2023 9:13:00 PM
Down Time		


Work Order Notes

Line 10 Removed and replace one new BRIDGE STONE TIRE TO RIGHT FRONT SIZE 225/75R16 Line 20 CHECK AC and found hose leaking from Coplin recover Freon also removed and replace four feet hose after recharge unit now working return back to work.

Activity Header						
Activity: 10 017/003/001 TIRE, CUSHION W/TREAD						
Activity Note: right front tire need change						
Reason for Repair: FW Follow Up						
Work Accomplished:						
Part Failure:						
Activity Comments:						
Activity Parts						
Booked Date	Part Number	Part Description	Quantity	Each	Extended	
20-Dec-23	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	136.14	272.28	
19-Dec-23	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	136.14	136.14	
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
19-Dec-23	Junior Hurst	0.83	65	53.95		
Activity Sublet						
No Data Available						
Activity Checklist						
No Data Available						
No Data Available						
Activity Sub Total						
			Activity 10 Sub Total			
			Parts:		408.42	
			Labor:		53.95	
			Labor Hours:		0.83	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		462.37	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2




Work Order No. 57273710
Invoice No. 55345 - 57273710

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
FOLLOWUP-FT Medium Duty		Status:	40 - Closed (40)
Requested By:	JUHURST	Priority:	3 - High
Created By:	JUHURST	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	290,503 - DH
Potential Warranty:	No		

Activity Header				
Activity:20 001/001/062 CONDENSER, A/C				
Activity Note: rear AC NEED TO CHECK				
Reason for Repair: FW Follow Up				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-23	Junior Hurst	3.67	65	238.55
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	238.55
			Labor Hours:	3.67
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	238.55
Work Order Footer				
			Work Order 57273710 Total	
			Parts:	408.42
			Labor:	292.50
			Labor Hours:	4.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	700.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57219266
Invoice No. 55345 - 57219266

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMA

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 290,202 - DH

Chronology

Reported	Dec 19, 2023 12:00:00 AM	Dec 19, 2023 12:00:00 AM
Started	Dec 19, 2023 2:05:00 PM	
Completed	Dec 19, 2023 4:35:00 PM	Dec 19, 2023 4:35:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage change oil filter part # LF3681

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 19-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Dec 19, 2023 1:22:05 PM	No	

Activity Sub Total															
	<table><tr><td colspan="2">Activity 5 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57219266
Invoice No. 55345 - 57219266

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,202 - DH

Activity Header
Activity:10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-23	LF3681	FILTER, OIL, SPIN-ON SEE P550965	1	5.47	5.47

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-23	Junior Hurst	1.52	65	98.8

Activity Sublet
No Data Available

Activity Checklist						
Check List						
10 Desc: Medium Duty PM Inspection						
Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 19-DEC-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR &	Done		JUHURST	Dec 19,	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Authorization Forms				2023 4:25:51 PM		
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Dec 19, 2023 4:25:51 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
33,060 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	12 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	3 32nds of an inch	right front tire need change	JUHURST	Dec 19, 2023 4:25:51 PM	Yes	57273710
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done	rear AC NEED TO CHECK	JUHURST	Dec 19, 2023 4:25:51 PM	Yes	57273710
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	6 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
55,900 - !FRA!INSPECT_Under Body Exhaust System	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
56,000 - *RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
56,100 - *RPT*INSPECT_REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1536 Cycles		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,200 - CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,500 - INSPECT_Bridgeplate Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Dec 19, 2023 4:25:51 PM	No	

Activity Sub Total															
	<table> <tr> <td colspan="2">Activity 10 Sub Total</td></tr> <tr> <td>Parts:</td><td>5.47</td></tr> <tr> <td>Labor:</td><td>98.80</td></tr> <tr> <td>Labor Hours:</td><td>1.52</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>104.27</td></tr> </table>	Activity 10 Sub Total		Parts:	5.47	Labor:	98.80	Labor Hours:	1.52	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	104.27
Activity 10 Sub Total															
Parts:	5.47														
Labor:	98.80														
Labor Hours:	1.52														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	104.27														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57219266
Invoice No. 55345 - 57219266

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	290,202 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Dec-23	75050	OIL, ENGINE, 5W/30	8	2.73	21.84

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Dec-23	Junior Hurst	0.97	65	63.05

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: Medium Duty PMA Service Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 19-DEC-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Dec 19, 2023 3:03:34 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Dec 19, 2023 3:03:34 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Dec 19, 2023 3:03:34 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Dec 19, 2023 3:03:34 PM	No	

Activity Sub Total	Activity 20 Sub Total	
	Parts:	21.84
	Labor:	63.05
	Labor Hours:	0.97
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	84.89
Work Order Footer	Work Order 57219266 Total	
	Parts:	27.31
	Labor:	161.85
	Labor Hours:	2.49
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	189.16



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57263537
Invoice No. 55345 - 57263537

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Service Call for Tire Install		Ford E450 Champion Challenger	
Requested By:	RRENE	Status:	40 - Closed (40)
Created By:	RRENE	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,734 - DH

Chronology		
Reported	Dec 7, 2023 12:18:00 PM	Dec 7, 2023 12:18:00 PM
Started		
Completed	Dec 18, 2023 11:11:44 AM	Dec 18, 2023 11:11:44 AM
Down Time		

Work Order Notes

Line 10 12/7/23

Service call for tire on I-95 and Southern

Activity Header					
Activity:10 999 TOTAL VEHICLE					
Activity Note: Service call - Tire Install by Goodyear					
Reason for Repair: TS Tire Service					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Dec-23	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	136.09	136.09
14-Dec-23	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	112.5	112.5
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:	248.59	
			Labor:	0.00	
			Labor Hours:	0.00	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	248.59	
Work Order Footer					
			Work Order 57263537 Total		
			Parts:	248.59	
			Labor:	0.00	

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	248.59



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57267728
Invoice No. 55345 - 57267728

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,735 - DH

Chronology		
Reported	Dec 12, 2023 8:36:03 PM	Dec 12, 2023 8:36:03 PM
Started	Dec 12, 2023 8:37:00 PM	
Completed	Dec 12, 2023 10:06:00 PM	Dec 12, 2023 10:06:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: Rear AC malfunction.

Cause: Unknown.

Correction: Checked vehicles rear AC system and found no issues. Let idle for an hour to try and duplicate issue.
Rear AC operates as intended.

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 12-DEC-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Dec 12, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:06:20 PM		
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Dec 12, 2023 10:06:20 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57267728
Invoice No. 55345 - 57267728

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,735 - DH

Activity Header				
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: Rear AC malfunction.				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-23	Earl Johnson	1.3	65	84.5
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	84.50
			Labor Hours:	1.30
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	84.50
Work Order Footer				
			Work Order 57267728 Total	
			Parts:	0.00
			Labor:	84.50
			Labor Hours:	1.30
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	84.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57264454
Invoice No. 55345 - 57264454

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
POWER STEERING NOISE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,734 - DH

Chronology		
Reported	Dec 8, 2023 11:14:00 AM	Dec 8, 2023 11:14:00 AM
Started	Dec 8, 2023 11:27:00 AM	
Completed	Dec 8, 2023 2:47:00 PM	Dec 8, 2023 2:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Hydro booster

Cause: Hydro booster leaking

Correction: Remove & Replace hydro booster. Pump slight whining noise
Parts #DC2Z-2005-A Qty (1)

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-DEC-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
400 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
700 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 8, 2023 11:28:21 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57264454
Invoice No. 55345 - 57264454

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
POWER STEERING NOISE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,734 - DH

Activity Header					
Activity:15 015 STEERING					
Activity Note: POWER STEERING LEAK -HYDROBOOSTER					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Dec-23	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	207.39	207.39
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
08-Dec-23	Arthurs,Durvin	2.65	65	172.25	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 15 Sub Total		
			Parts:	207.39	
			Labor:	172.25	
			Labor Hours:	2.65	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	379.64	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57264454
Invoice No. 55345 - 57264454

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
POWER STEERING NOISE		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	289,734 - DH

Activity Header															
Activity:25 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING															
Activity Note: WC lift malfunction.															
Reason for Repair:	05 Inspection, Routine														
Work Accomplished:	03 Replace New														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 25 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 25 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 25 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 57264454 Total</td></tr><tr><td>Parts:</td><td>207.39</td></tr><tr><td>Labor:</td><td>172.25</td></tr><tr><td>Labor Hours:</td><td>2.65</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>379.64</td></tr></table>		Work Order 57264454 Total		Parts:	207.39	Labor:	172.25	Labor Hours:	2.65	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	379.64
Work Order 57264454 Total															
Parts:	207.39														
Labor:	172.25														
Labor Hours:	2.65														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	379.64														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57255823
Invoice No. 55345 - 57255823

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
WC lift malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	288,207 - DH

Chronology		
Reported	Nov 28, 2023 11:06:42 PM	Nov 28, 2023 11:06:42 PM
Started	Nov 28, 2023 11:07:00 PM	
Completed	Dec 8, 2023 1:28:38 PM	Dec 8, 2023 1:28:38 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: ***Key is missing***

Cause:


Correction:

Activity Header				
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING				
Activity Note: WC lift malfunction.				
Reason for Repair:		05 Inspection, Routine		
Work Accomplished:		03 Replace New		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Nov-23	Earl Johnson	0.13	65	8.45
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	8.45
			Labor Hours:	0.13

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	8.45
Work Order Footer	Work Order 57255823 Total	
	Parts:	0.00
	Labor:	8.45
	Labor Hours:	0.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	8.45



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57254542
Invoice No. 55345 - 57254542

Client Department:

Department: 55345M

Work Order Description

Lift issue

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 288,200 - DH

Chronology

Reported	Nov 27, 2023 5:35:17 PM	Nov 27, 2023 5:35:17 PM
Started	Nov 27, 2023 5:39:00 PM	
Completed	Nov 27, 2023 9:28:00 PM	Nov 27, 2023 9:28:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: vehicle came in for lift issue

Cause: lift malfunction

Correction: Check lift and found fluid was low replace the promble solve no parts replace after check unit complete and return unit back to work

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 27-NOV-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	
400 - Are you wearing the appropriate PPE?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	
700 - Have you performed the proper LOTO?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Nov 27, 2023 9:27:57 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57254542
Invoice No. 55345 - 57254542


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Lift issue		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	288,200 - DH

Activity Header				
Activity:15 020 GROUP, DRIVETRAIN				
Activity Note: Lift issue				
Reason for Repair: 11 Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-23	Junior Hurst	3.78	65	245.7
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	245.70
			Labor Hours:	3.78
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	245.70
Work Order Footer				
			Work Order 57254542 Total	
			Parts:	0.00
			Labor:	245.70
			Labor Hours:	3.78
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	245.70



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 57235942
Invoice No. 55345 - 57235942

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Loose gear shift		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	287,255 - DH

Chronology		
Reported	Nov 7, 2023 10:02:54 AM	Nov 7, 2023 10:02:54 AM
Started		
Completed	Nov 7, 2023 11:17:00 AM	Nov 7, 2023 11:17:00 AM
Down Time		

Work Order Notes

Line 20 Junior Hurst, Replaced shift bushing 1, shifter bushing 1. Checked fuel gauge no issues found

Activity Header
Activity: 10 015/010 STEERING, ALL-STEER
Activity Note: steering column bushings replaced
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Nov-23	7C2Z-7C130-A	DAMPER, VIBRATION, TUBE, SHIFTER	1	11.83	11.83
07-Nov-23	F3TZ-7L278-A	BUSHING, TUBE, SHIFTER, COLUMN, STEERING	1	2.97	2.97

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 10 Sub Total	
		Parts:	14.80
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	14.80

Work Order Footer		Work Order 57235942 Total	
		Parts:	14.80
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	14.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57219215
Invoice No. 55345 - 57219215

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty			Ford E450 Champion Challenger
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	286,601 - DH

Chronology		
Reported	Oct 29, 2023 3:09:09 PM	Oct 29, 2023 3:09:09 PM
Started	Oct 29, 2023 3:11:00 PM	
Completed	Oct 29, 2023 4:36:00 PM	Oct 29, 2023 4:36:00 PM
Down Time		

Work Order Notes

Line 10 Re-adjusted the lift ,1 interieur light 1 marke exter light

Activity Header				
Activity:10 174/032/066 RESTRAINT, OCCUPANT, TIE-DOWN, WHEELCHAIR				
Activity Note:				
Reason for Repair: FW Follow Up				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	NELSON PIERRE-LOUIS	0.87	65	56.55
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	56.55
			Labor Hours:	0.87
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	56.55



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57219215
Invoice No. 55345 - 57219215

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	286,601 - DH

Activity Header				
Activity:20 034/003/000 LAMPS, SIGNAL, PARKING & BACKUP				
Activity Note:				
Reason for Repair:	04	Driver's Report		
Work Accomplished:	03	Replace New		
Part Failure:	02	Burned, Scorched, Melted, Blistered		
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	NELSON PIERRE-LOUIS	0.5	65	32.5
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	32.50
			Labor Hours:	0.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	32.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57219215
Invoice No. 55345 - 57219215

Client Department:	
Department:	55345M
Work Order Description	
FOLLOWUP-FT Medium Duty	
Requested By:	NPIERRE-LOUIS
Created By:	NPIERRE-LOUIS
Assigned To:	
Class:	-
Arrangement:	Unassigned
Potential Warranty:	No
Equipment No.:	4602-P
VIN:	1FDFE4FSXEDB17155
Ford E450 Champion Challenger	
Status:	40 - Closed (40)
Priority:	3 - High
Driver:	
Phone:	
ETA:	
Meter:	286,601 - DH

Activity Header	
Activity:30 034/000/000 LIGHTING SYSTEM	
Activity Note:	
Reason for Repair:	04 Driver's Report
Work Accomplished:	03 Replace New
Part Failure:	02 Burned, Scorched, Melted, Blistered
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
No Data Available	
No Data Available	
Activity Sub Total	
Activity 30 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00	
Work Order Footer	
Work Order 57219215 Total Parts: 0.00 Labor: 89.05 Labor Hours: 1.37 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 89.05	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57077376
Invoice No. 55345 - 57077376

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	286,300 - DH

Chronology		
Reported	Oct 27, 2023 12:00:00 AM	Oct 27, 2023 12:00:00 AM
Started	Oct 29, 2023 11:49:00 AM	
Completed	Oct 29, 2023 4:33:00 PM	Oct 29, 2023 4:33:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: pma service

Cause: preventive maintenance

Correction : perform pma service lube all points

Activity Header						
Activity:5 999/999/999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure: 00 No Failure						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 29-OCT-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
700 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1,000 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Oct 29, 2023 3:01:09 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57077376
Invoice No. 55345 - 57077376

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	286,300 - DH

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	NELSON PIERRE-LOUIS	2.15	65	139.75

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Medium Duty PM Inspection Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 29-OCT-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Oct 29, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	3:27:29 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit	na	NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-	Oct 29, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	3:27:29 PM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,060 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.1 Volt*		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	Yes	57219215
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	78 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	78 Pounds per Square Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	39.3 Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	39.3 Inch		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
55,900 - !FRA!INSPECT_Under Body Exhaust System	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
56,000 - *RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,100 - RECORD_ Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,400 - OPERATE_ Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-	Oct 29, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	3:27:29 PM		
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Oct 29, 2023 3:27:29 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	139.75
Labor Hours:	2.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	139.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57077376
Invoice No. 55345 - 57077376

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	286,300 - DH

Activity Header

Activity:20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Oct-23	75050	OIL, ENGINE, 5W/30	8	2.73	21.84
29-Oct-23	LF16424	FILTER, OIL SUPERSEDES P9600	1	7.92	7.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Oct-23	NELSON PIERRE-LOUIS	1.22	65	79.3

Activity Sublet

No Data Available


Activity Checklist

Check List						
20 Desc: Medium Duty PMA Service Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 29-OCT-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Oct 29, 2023 3:00:24 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-	Oct 29, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	3:00:24 PM		
Activity Sub Total						
			Activity 20 Sub Total			
			Parts:		29.76	
			Labor:		79.30	
			Labor Hours:		1.22	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		109.06	
Work Order Footer						
			Work Order 57077376 Total			
			Parts:		29.76	
			Labor:		219.05	
			Labor Hours:		3.37	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		248.81	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56109030
Invoice No. 55345 - 56109030

Client Department:
Department: 55345M **Equipment No.:** 4602-P
Work Order Description **VIN:** 1FDFE4FSXEDB17155
FIRST TRANSIT AC INSPECTION Ford E450 Champion Challenger
Requested By: SPACE **Status:** 40 - Closed (40)
Created By: SPACE **Priority:** -
Assigned To: **Driver:**
Class: - **Phone:**
Arrangement: Unassigned **ETA:**
Potential Warranty: No **Meter:** 284,522 -

Chronology		
Reported	Oct 10, 2023 6:32:40 PM	Oct 10, 2023 6:32:40 PM
Started	Oct 10, 2023 6:49:00 PM	
Completed	Oct 10, 2023 8:45:00 PM	Oct 10, 2023 8:45:00 PM
Down Time		

Work Order Notes

Line 10
AC Inspection
Inspected allelectrical components. Ok
Inspected all lines and hoses. Ok
Inspected both AC compressors. Ok
Inpected both condensers. Ok
Inspected all fans and blows on every speed. Ok
No leaks.
Front AC temp. 57
Rear AC temp. 52
Outside temp. 81
Returned to services

Activity Header						
Activity: 5 999/999/999 TOTAL VEHICLE						
Activity Note: Personal Risk Assesment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure: 00 No Failure						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assesment						
Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 10-OCT-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	
400 - Are you wearing the appropriate PPE?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	
700 - Have you performed the proper LOTO?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	Oct 10, 2023 7:15:26 PM	No	


Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56109030
Invoice No. 55345 - 56109030

Client Department:
Department: 55345M
Work Order Description
FIRST TRANSIT AC INSPECTION
Requested By: SPACE
Created By: SPACE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 284,522 -

Activity Header
Activity:10 001/001/001 AIR CONDITIONING
Activity Note: FIRST TRANSIT AC INSPECTION
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Oct-23	Nicolas Barreto	1.93	65	125.45

Activity Sublet
No Data Available

Check List						
10 Desc: FIRST TRANSIT AC INSPECTION Task: FIRST TRANSIT AC INSPECTION Performed by: NBARRETO Performed on: 10-OCT-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 VISUAL INSPECTION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
10,100 - CHECK PHYSICAL DAMAGE, MISSING PARTS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
10,200 - CHECK REFRIGERANT HOSES FOR CHAFING	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
10,300 - CHECK EVAPORATOR AND CONDENSER FOR OBSTRUCTIONS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
10,400 - CHECK OPERATION OF FAST IDLE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,000 - SECTION 2 DIAGNOSE THE SYSTEM CONDITION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,100 - ATTACH GAUGES AND RUN SYSTEM 10 MINUTES	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,200 - CHECK FOR EVEN AIR DISTRIBUTION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,300 - CHECK FOR PROPER OPERATION OF ALL HVAC MODES	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,400 - CHECK DRIVERS A/C SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,500 - RECORD AMBIENT TEMPERATURE BEFORE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,600 - RECORD DISCHARGE PRESSURE BEFORE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,700 - RECORD SUCTION PRESSURE BEFORE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,710 - RECORD OUTLET TEMPERATURE BEFORE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
20,800 - CHECK HIGH AND LOW PRESSURE CUTOUT SWITCHES FOR LEAKS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,000 - SECTION 3 COMPRESSOR OPERATIONAL INSPCTION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,100 - CHECK FOR UNUSUAL NOISES	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,200 - CHECK CLUTCH RESISTANCE READING	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,300 - CHECK AIR GAP IN COMPRESSOR CLUTCH	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,400 - CHECK COMPRESSOR MOUNTING AND ALIGHMENT	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,500 - INSPECT COMPRESSOR BELT(S) OR DRIVE SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,600 - CHECK FOR CRACKS AND WEAR	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,700 - CHECK FOR PROPER WIDTH AND LENGTH	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
30,800 - CHECK FOR PROPER ALIGNMENT	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
40,000 - SECTION 4 LEAK TEST SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
40,100 - CHICK A/C LINES WITH AN ELECTRONIC LEAK DETECTOR	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
40,200 - CHECK HOSES, FITTINGS, VALVES AND COMPRESSOR SHAFT SEAL	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
40,300 - CHECK HEATER HOSES FOR LEAKS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
50,000 - SECTION 5 SYSTEM CONTAMINATION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
50,100 - CHECK INLINE DRIER	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
50,200 - CHECK ACCUMULATOR	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
60,000 - SECTION 6 CHARGE SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
60,100 - IF CHARGING IS REQUIRED, CHARGE BY WEIGHT	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
60,200 - CHECK FOR LEAKS AFTER CHARGING	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
70,000 - SECTION 7 FAN MOTORS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
70,100 - CHECK SEALED MOTORS FOR PROPER OPERATION	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,200 - INSPECT BLOWER WHEELS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
70,300 - CHECK ELECTRICAL WIRING & CONNECTIONS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
80,000 - SECTION 8 OPERATE SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
80,100 - CHECK FOR PROPER HEATING & COOLING	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
80,200 - CHECK TEMPERATURE CONTROLS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
80,300 - CHECK DEFROST MODE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
90,000 - SECTION 9 PERFORMANCE TEST READINGS	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
90,100 - RECORD AMBIENT TEMPERATURE READINGS AFTER	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
90,200 - RECORD DISCHARGE PRESSURE AFTER	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
90,300 - RECORD SUCTION PRESSURE AFTER	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
90,400 - RECORD OUTLET TEMPERATURE	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
100,000 - SECTION 10 RESTORE SYSTEM	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
100,100 - DISCONNECT GAUGES	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	
100,200 - CLOSE ALL PANELS, DOOR, ETC.	Done		NBARRETO	Oct 10, 2023 7:17:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	125.45
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	125.45

Work Order Footer

Work Order 56109030 Total	
Parts:	0.00
Labor:	125.45
Labor Hours:	1.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	125.45



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 57137802
Invoice No. 55345 - 57137802

Client Department:

Department: 55345M

Work Order Description

No crank.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 284,171 - DH

Chronology		
Reported	Oct 2, 2023 7:33:05 PM	Oct 2, 2023 7:33:05 PM
Started	Oct 3, 2023 12:00:00 AM	
Completed	Oct 3, 2023 1:31:00 AM	Oct 3, 2023 1:31:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: No crank.

Cause: Unknown.

Correction: Arrived at the location with vehicle for driver to continue to base. Attempted to boost vehicles battery to no avail. Checked fuses and relays. Checked wires at the starter and tapped. Line 20 Tech(NB) was able to get vehicle started and transport back to base. Line 30 Remove and replaced starter motor. Crank vehicle several times without any issues.

Activity Header	
Activity:5 999 TOTAL VEHICLE	
Activity Note: PRAMETER	
Reason for Repair:	SW Shop Work Order
Work Accomplished:	06 Inspect
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
Check List	
5 Desc: PRAMETER	
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 03-OCT-23	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
103 - Are you properly trained to perform the task for this unit and fuel type of Liquid Propane Gas (LPG) engines?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
200 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
400 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
700 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
1,000 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	
1,100 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 3, 2023 1:30:55 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 57137802
Invoice No. 55345 - 57137802

Client Department:

Department: 55345M

Work Order Description

No crank.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 284,171 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Oct-23	DL3Z-11002-A	STARTER, E350, '14	1	148.8	148.8

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	148.80
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	148.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 57137802
Invoice No. 55345 - 57137802

Client Department:

Department: 55345M

Work Order Description

No crank.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 284,171 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: GARDENS TOWING TOWED BUS BACK TO BASE- NOT STARTING

Reason for Repair: TW Towing

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4836646	184,142,671	1005999	PALM BEACH GARDENS TOWING CORP,FL,RIVIERA BEACH,3525 AVE K	Oct 3, 2023 12:00:00 AM	93.5

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	93.50
Sublet Labor:	0.00
Activity Sub Total	93.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 57137802
Invoice No. 55345 - 57137802

Client Department:

Department: 55345M

Work Order Description

No crank.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 284,171 - DH

Activity Header

Activity:30 032/000/000 CRANKING

Activity Note: Remove and replace starter.

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00


Work Order Footer

Work Order 57137802 Total

Parts:	148.80
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	93.50
Sublet Labor:	0.00
Activity Sub Total	242.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 57123657
Invoice No. 55345 - 57123657

Client Department:

Department: 55345M

Work Order Description

CHECK ENGINE & WRENCH LIGHTS ON

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 283,672 - DH

Chronology

Reported	Sep 27, 2023 4:50:55 PM	Sep 27, 2023 4:50:55 PM
Started	Sep 27, 2023 4:54:00 PM	
Completed	Sep 28, 2023 12:06:00 AM	Sep 28, 2023 12:06:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Check engine and wrench lights on

Cause: Unknown

Correction: Batteries , Engine compression , misfiring , power balance tests are satisfactory. Bus road tested ok. Under monitoring

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Sep 28, 2023 12:05:59 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 57123657
Invoice No. 55345 - 57123657

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
CHECK ENGINE & WRENCH LIGHTS ON		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	283,672 - DH

Activity Header
Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Sep-23	Fritz Simon	2.5	65	162.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			162.50
Labor Hours:			2.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			162.50

Work Order Footer		Work Order 57123657 Total	
Parts:			0.00
Labor:			162.50
Labor Hours:			2.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			162.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57077367
Invoice No. 55345 - 57077367

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	282,696 - DH

Chronology

Reported	Sep 14, 2023 8:18:51 AM	Sep 14, 2023 8:18:51 AM
Started	Sep 14, 2023 10:08:00 AM	
Completed	Sep 19, 2023 10:09:00 AM	Sep 19, 2023 10:09:00 AM
Down Time		

Work Order Notes

Line 10 C. Rear brakes near min. specs.

C. Normal wear

C. Removed and replaced rear parking brakes, rotors, brake pads, seals and driver side caliper Line 20 C. Bad Front shocks

C. Normal wear

C. Removed and replaced front shocks and bushings

Activity Header

Activity: 10 016/003/001 ABSORBER, SHOCK, FRONT

Activity Note: need front shocks

Reason for Repair: FW Follow Up

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Oct-23	18-B5111	CALIPER, BRAKE, DISC, READY, FRICTION, E450	-1	48.63	-48.63
19-Sep-23	18-B5111	CALIPER, BRAKE, DISC, READY, FRICTION, E450	1	48.63	48.63
19-Sep-23	8C2Z-18124-D	ABSORBER, SHOCK, FRONT, E450, '08 SAME AS ASH1154	2	60.26	120.52
19-Sep-23	6C3Z-18197-AA	BUSHING, ABSORBER, SHOCK, FRONT, UPPER, ECONOLINE, '08	2	20.18	40.36
19-Sep-23	F8UZ-4221-AA	BEARING, CARRIER, DIFFERENTIAL, 80 DYNA	1	45.97	45.97

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-23	Rodriguez, Raul	0.93	65	60.45
19-Sep-23	NELSON PIERRE-LOUIS	0.62	65	40.3

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	206.85
	Labor:	100.75
	Labor Hours:	1.55
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	307.60



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57077367
Invoice No. 55345 - 57077367

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	282,696 - DH

Activity Header
Activity:20 013/002/013 SHOE, BRAKE, REAR
Activity Note: need rear brake pads and rotors
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-23	BRSD1330B	PADS, BRAKE, DISC, REAR SAME AS 8C2Z-2V200-C	1	55.73	55.73
19-Sep-23	BRS-179	SEAL, WHEEL, REAR	3	10.86	32.58
19-Sep-23	8C2Z-2C026-B	ROTOR, BRAKE, DISC, REAR, E450	2	116.96	233.92
19-Sep-23	8C2Z-2648-A	SHOE, BRAKE, PARKING	1	32.17	32.17

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-23	Rodriguez,Raul	2.35	65	152.75
18-Sep-23	NELSON PIERRE-LOUIS	3.3	65	214.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:			354.40
Labor:			367.25
Labor Hours:			5.65
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			721.65



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57077367
Invoice No. 55345 - 57077367

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
FOLLOWUP-FT Medium Duty		Status:	40 - Closed (40)
Requested By:	RAURODRIGUEZ	Priority:	3 - High
Created By:	RAURODRIGUEZ	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	282,696 - DH
Potential Warranty:	No		

Activity Header				
Activity:30 013/000/000 BRAKES				
Activity Note:				
Reason for Repair:		39 Natural Causes		
Work Accomplished:		03 Replace New		
Part Failure:		44 Worn		
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-23	Rodriguez,Raul	7	65	455
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 30 Sub Total	
			Parts:	0.00
			Labor:	455.00
			Labor Hours:	7.00
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	455.00
Work Order Footer				
			Work Order 57077367 Total	
			Parts:	561.25
			Labor:	923.00
			Labor Hours:	14.20
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	1,484.25



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56945250
Invoice No. 55345 - 56945250

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMB

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 282,395 - DH

Chronology

Reported	Sep 12, 2023 12:00:00 AM	Sep 12, 2023 12:00:00 AM
Started	Sep 13, 2023 11:52:00 PM	
Completed	Sep 14, 2023 8:21:00 AM	Sep 14, 2023 8:21:00 AM
Down Time		

Work Order Notes

Line 10 PM.

Perform pm A service, lube front end, tire rotation, torque and re torque tires (140 f/p), R&R engine oil and filter, road test, all okay at this time.

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 14-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	
7 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 14, 2023 7:57:30 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56945250
Invoice No. 55345 - 56945250

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	282,395 - DH

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-23	LF3681	FILTER, OIL, SPIN-ON SEE P550965	-1	5.1	-5.1
14-Sep-23	LF3681	FILTER, OIL, SPIN-ON SEE P550965	1	5.1	5.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-23	Rodriguez,Raul	1.75	65	113.75

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Medium Duty PM Inspection Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: RAURODRIGUEZ Performed on: 14-SEP-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RAURODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,800 - CHECK_All Destination Signage	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
10,900 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,200 - CHECK_Public Address System	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	Second*	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,700 - RECORD_Brake Performance Test Speed	Miles per Hour	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,800 - RECORD_Brake Performance Test Distance	FEET	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	FEET	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	Gravitational Force	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	-	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,500 - INSPECT_High Idle Control	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
31,000 - SSF (Street Side Front)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
32,000 - Engine Inspection	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,100 - INSPECT_Intake System	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.7 Volt*		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,000 - CSF (Curb Side Front)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done	need front shocks	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	Yes	57077367
33,030 - INSPECT_Mud Flaps, Brackets	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
33,060 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.7 Volt*		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,700 - CHECK_Passenger Stop Request System	-	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,200 - INSPECT_Ball Joint Play	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,400 - LUBE_All Chassis Components	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,700 - INSPECT_Tire Condition	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	32nds of an inch	9mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	Inch	39.7mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	Inch	39.7mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,100 - INSPECT_Vibration Damper	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,600 - INSPECT_Tire Condition	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done	need rear brake pads and rotors	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	Yes	57077367
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	3mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	32nds of an inch	3mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	Inch	38.1mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	Inch	38.1mm	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
55,900 - !FRA!INSPECT_Under Body Exhaust System	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
56,000 - *RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
56,100 - *RPT*INSPECT_REAR Springs, Shocks, Suspension, Airbags	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,000 - SECTION 6 - Wheelchair Inspection	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	Cycles	na	RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,200 - CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,500 - INSPECT_Bridgeplate Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,900 - CLEAN_Linkages and Mechanisms	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,400 - INSPECT_All Pivot Points	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,500 - INSPECT_Cams and Slots	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,600 - INSPECT_Rollers	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
62,700 - INSPECT_All Linkages	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RAUODRIGUEZ	Sep 14, 2023 8:20:41 AM	No	

Activity Sub Total															
	<table> <tr> <td colspan="2">Activity 10 Sub Total</td></tr> <tr> <td>Parts:</td><td>0.00</td></tr> <tr> <td>Labor:</td><td>113.75</td></tr> <tr> <td>Labor Hours:</td><td>1.75</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>113.75</td></tr> </table>	Activity 10 Sub Total		Parts:	0.00	Labor:	113.75	Labor Hours:	1.75	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	113.75
Activity 10 Sub Total															
Parts:	0.00														
Labor:	113.75														
Labor Hours:	1.75														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	113.75														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56945250
Invoice No. 55345 - 56945250

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMB		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	282,395 - DH

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMB Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Sep-23	75050	OIL, ENGINE, 5W/30	8	2.71	21.68
20-Sep-23	LF16424	FILTER, OIL SUPERSEDES P9600	1	7.9	7.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-23	Rodriguez,Raul	0.98	65	63.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 20 Sub Total	
Parts:	29.58
Labor:	63.70
Labor Hours:	0.98
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	93.28

Work Order Footer	
Work Order 56945250 Total	
Parts:	29.58
Labor:	177.45
Labor Hours:	2.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	207.03



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 57030905
Invoice No. 55345 - 57030905

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	281,693 - DH

Chronology

Reported	Aug 30, 2023 10:33:14 AM	Aug 30, 2023 10:33:14 AM
Started	Aug 30, 2023 10:34:00 AM	
Completed	Sep 4, 2023 7:14:00 AM	Sep 4, 2023 7:14:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Vehicle will not go into park

Cause: Bifold doors out of adjustment

Correction: Readjust Bifold Doors test gear selection bus can go into drive with no issue at this time. Line 20 C. Rear ac inop.

C. Stop work low pressure

C. Recover, change orifice tube, bacuum and leak test pass, add 4 oz oil, recharge and test. All okay at this time.

Activity Header

Activity:10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 04-SEP-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 4, 2023 7:06:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 4, 2023 7:06:05 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 4, 2023 7:06:05 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 4, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:06:05 AM		
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 4, 2023 7:06:05 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 4, 2023 7:06:05 AM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 57030905
Invoice No. 55345 - 57030905

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	281,693 - DH

Activity Header				
Activity:20 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: REAR AC DIAG				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-23	Rodriguez,Raul	1.47	65	95.55
30-Aug-23	Rodriguez,Raul	1.68	65	109.2
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	204.75
			Labor Hours:	3.15
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	204.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 57030905
Invoice No. 55345 - 57030905

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	281,693 - DH

Activity Header
Activity:30 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Transmission Wont go into gear
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Sep-23	Owens,Arthur	1.07	65	69.55
01-Sep-23	Junior Hurst	0.58	65	37.7

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	107.25
		Labor Hours:	1.65
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	107.25

Work Order Footer		Work Order 57030905 Total	
		Parts:	0.00
		Labor:	312.00
		Labor Hours:	4.80
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	312.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56981247
Invoice No. 55345 - 56981247

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Readjust Lytx Camera		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	279,684 - DH

Chronology		
Reported	Aug 14, 2023 6:55:17 PM	Aug 14, 2023 6:55:17 PM
Started	Aug 14, 2023 10:38:00 PM	
Completed	Aug 14, 2023 11:10:00 PM	Aug 14, 2023 11:10:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: Drive Cam shows rear view mirror in the frame

Cause: place in wrong area

Correction: Remove and reposition drive cam where it is out of the rear view mirror frame

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 14-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Aug 14, 2023 11:09:51 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56981247
Invoice No. 55345 - 56981247

Client Department:

Department: 55345M

Work Order Description

Readjust Lytx Camera

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 279,684 - DH

Activity Header

Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Readjust lytx camera

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Aug-23	Owens,Arthur	0.52	65	33.8

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	0.00
Labor:	33.80
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	33.80

Work Order Footer

Work Order 56981247 Total

Parts:	0.00
Labor:	33.80
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	33.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56622911
Invoice No. 55345 - 56622911

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMA

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 278,476 - DH

Chronology

Reported	Aug 1, 2023 12:00:00 AM	Aug 1, 2023 12:00:00 AM
Started	Aug 2, 2023 12:11:00 AM	
Completed	Aug 2, 2023 10:09:00 AM	Aug 2, 2023 10:09:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: pma service

Cause : preventive maintenance

Correction: perform pma service and lube

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 02-AUG-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Aug 2, 2023 8:24:59 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 2, 2023 8:24:59 AM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 2, 2023 8:24:59 AM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 2, 2023 8:24:59 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 2, 2023 8:24:59 AM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?			LOUIS	8:24:59 AM			
Activity Sub Total			Activity 5 Sub Total				
			Parts:				
							0.00
			Labor:				
							0.00
			Labor Hours:				
							0.00
			Sublet Parts:				
							0.00
			Sublet Labor:				
							0.00
			Activity Sub Total				
							0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56622911
Invoice No. 55345 - 56622911

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	278,476 - DH

Activity Header
Activity:10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-23	NELSON PIERRE-LOUIS	2.2	65	143

Activity Sublet
No Data Available

Check List						
10 Desc: Medium Duty PM Inspection Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 02-AUG-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,800 - CHECK_All Destination Signage	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		NPIERRE-	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues			LOUIS	10:08:59 AM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,200 - CHECK_Public Address System	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,600 - RECORD_Brake Performance Test E.T.	0 Second*		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,700 - RECORD_Brake Performance Test Speed	0 Miles per Hour		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,800 - RECORD_Brake Performance Test Distance	0 FEET		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	0 FEET		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,000 - RECORD_Brake Performance Test Ave GX	0 Gravitational Force		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,500 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,800 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
22,400 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	280 Degree Fahrenheit		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,000 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:08:59 AM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,060 - *RPT*-!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.1 Volt*		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,700 - CHECK_Passenger Stop Request System	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	75 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	74 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	77 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	76 Pounds per Square Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	5 32nds of an inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
55,900 - !FRA!INSPECT_Under Body Exhaust System	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
56,000 - *RPT*INSPECT_REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,100 - RECORD_ Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	10:08:59 AM		
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Aug 2, 2023 10:08:59 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	143.00
Labor Hours:	2.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	143.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56622911
Invoice No. 55345 - 56622911

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	278,476 - DH

Activity Header

Activity:20 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PMA Service
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Aug-23	75050	OIL, ENGINE, 5W/30	8	2.11	16.88
02-Aug-23	LF16424	FILTER, OIL SUPERSEDES P9600	1	7.82	7.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-23	NELSON PIERRE-LOUIS	1.17	65	76.05

Activity Sublet

No Data Available


Activity Checklist

Check List						
20 Desc: Medium Duty PMA Service Task: 55345-Medium Duty PMA Inspection Performed by: NPIERRE-LOUIS Performed on: 02-AUG-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Aug 2, 2023 9:59:47 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-	Aug 2, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	9:59:47 AM		
Activity Sub Total						
			Activity 20 Sub Total			
			Parts:		24.70	
			Labor:		76.05	
			Labor Hours:		1.17	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		100.75	
Work Order Footer						
			Work Order 56622911 Total			
			Parts:		24.70	
			Labor:		219.05	
			Labor Hours:		3.37	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		243.75	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56931894
Invoice No. 55345 - 56931894

Client Department:
Department: 55345M **Equipment No.:** 4602-P
Work Order Description **VIN:** 1FDFE4FSXEDB17155
Wheel chair lift get stuck on the ground Ford E450 Champion Challenger
Requested By: AOWENS **Status:** 40 - Closed (40)
Created By: AOWENS **Priority:** 1 - Low
Assigned To: **Driver:**
Class: - **Phone:**
Arrangement: Unassigned **ETA:**
Potential Warranty: No **Meter:** 278,150 - DH

Chronology		
Reported	Jul 27, 2023 11:32:36 PM	Jul 27, 2023 11:32:36 PM
Started	Jul 27, 2023 11:34:00 PM	
Completed	Jul 28, 2023 12:09:00 AM	Jul 28, 2023 12:09:00 AM
Down Time		

Work Order Notes

Line 10 Complaint: Wheel chair lift get stuck when on the ground

Cause: Wheel chair lift shocks

Correction: Replace Both wheel chair lift shocks

Qty2 part# 32831

Activity Header							
Activity:10 999/999/999 TOTAL VEHICLE							
Activity Note: PRA							
Reason for Repair:		SW Shop Work Order					
Work Accomplished:		06 Inspect					
Part Failure:		00 No Failure					
Activity Comments:							
Activity Parts							
No Data Available							
Activity Labor							
No Data Available							
Activity Sublet							
No Data Available							
Activity Checklist							
Check List							
10 Desc: PRA							
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 27-JUL-23							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
1 - Are you properly trained to perform the task?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No		
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
7 - Have you performed the proper LOTO?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 27, 2023 11:37:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56931894
Invoice No. 55345 - 56931894

Client Department:

Department: 55345M

Work Order Description

Wheel chair lift get stuck on the ground

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: -

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 278,150 - DH

Activity Header

Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER

Activity Note: Wheel chair lift get stuck when on the ground

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-23	32831	SPRING, SHOCK, GAS, W/C	2	24.15	48.3

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-23	Owens,Arthur	0.13	65	8.45
27-Jul-23	Owens,Arthur	0.43	65	27.95

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	48.30
Labor:	36.40
Labor Hours:	0.56
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	84.70

Work Order Footer

Work Order 56931894 Total	
Parts:	48.30
Labor:	36.40
Labor Hours:	0.56
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	84.70



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56909549
Invoice No. 55345 - 56909549

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC ISSUES		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	277,492 - DH

Chronology		
Reported	Jul 19, 2023 5:40:05 PM	Jul 19, 2023 5:40:05 PM
Started	Jul 19, 2023 5:41:00 PM	
Completed	Jul 20, 2023 1:17:00 AM	Jul 20, 2023 1:17:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:Rear A/C issues

Cause:A/C lines pressure obstructed

Correction:Refrigerant recovery,orifice tube replacement,vacuuming,leak test,refrigerant recharge completed. Rear AC blowing cold at this time.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 20-JUL-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 20, 2023 1:14:58 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56909549
Invoice No. 55345 - 56909549

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC ISSUES		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	277,492 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jul-23	3411885	TUBE, ORIFICE, A/C, FORD	1	0.93	0.93

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Jul-23	Fritz Simon	4.25	65	276.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	0.93	Labor:	276.25
Labor Hours:	4.25	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	277.18

Work Order Footer		Work Order 56909549 Total	
Parts:	0.93	Labor:	276.25
Labor Hours:	4.25	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	277.18



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56895188
Invoice No. 55345 - 56895188

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Bus Stalling		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	277,492 - DH

Chronology		
Reported	Jul 14, 2023 10:06:15 AM	Jul 14, 2023 10:06:15 AM
Started	Jul 14, 2023 10:08:00 AM	
Completed	Jul 14, 2023 1:32:00 PM	Jul 14, 2023 1:32:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: Bus Stalling.

Cause: not Sure

Correction: Road Test Bus did not stall. Clean Throttle body & Perform induction Service.

Activity Header	
Activity:5 999 TOTAL VEHICLE	
Activity Note:	
Reason for Repair:	SW Shop Work Order
Work Accomplished:	06 Inspect
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
Check List	
5 Desc:	
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-JUL-23	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 14, 2023 10:08:45 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56895188
Invoice No. 55345 - 56895188

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Bus Stalling		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	277,492 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Bus Stalling
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Jul-23	Arthurs,Durvin	2.67	65	173.55

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			173.55
Labor Hours:			2.67
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			173.55

Work Order Footer		Work Order 56895188 Total	
Parts:			0.00
Labor:			173.55
Labor Hours:			2.67
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			173.55



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56838082
Invoice No. 55345 - 56838082

Client Department:

Department: 55345M

Work Order Description

Rear AC malfunction.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 276,787 - DH

Chronology

Reported	Jun 21, 2023 9:45:45 PM	Jun 21, 2023 9:45:45 PM
Started		
Completed	Jun 22, 2023 12:29:00 AM	Jun 22, 2023 12:29:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:

Cause:

Correction: Line 20 Complaint: Rear AC not working (clients complaining).

Cause: Both rear heaters activated.

Correction: Deactivated heaters and let vehicle idle for half hour with rear AC on. Found no issues.

Activity Header Activity: 5 999 TOTAL VEHICLE Activity Note: Personal Risk Assessment Reason for Repair: SW Shop Work Order Work Accomplished: 06 Inspect Part Failure: Activity Comments:		
Activity Parts No Data Available		
Activity Labor No Data Available		
Activity Sublet No Data Available		
Activity Checklist <table border="1"><thead><tr><th>Check List</th></tr></thead><tbody><tr><td>5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-JUN-23</td></tr></tbody></table>	Check List	5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-JUN-23
Check List		
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 22-JUN-23		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 22, 2023 12:22:17 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56838082
Invoice No. 55345 - 56838082

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header															
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION															
Activity Note: Rear AC malfunction.															
Reason for Repair:	04 Driver's Report														
Work Accomplished:	09 Troubleshooting														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 56838082 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 56838082 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 56838082 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department: 55345M

Work Order Description

FOLLOW UP TO QCC INSP(Replace Suspension)

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 276,787 - DH

Chronology

Reported	May 18, 2023 3:25:22 PM	May 18, 2023 3:25:22 PM
Started	May 18, 2023 12:00:00 AM	
Completed	Jun 1, 2023 12:22:00 AM	Jun 1, 2023 12:22:00 AM
Down Time		

Work Order Notes

Line 10 Unit came in for motor mounts change two new mounts replace part # F 7UZZ-6038. LH And part 5 U9 Z6038.

Can you charge out the mounts for me thank you Line 20 Removed and replaced upper and lower ball joint part # 8C3Z-3049. / 8C2Z-3050 job completed after test drive unit working perfect Line 30 Can't fine the ball joint please charge it out for me thank you Line 40 Remove and replaced drag link assembly.

Remove and replaced Left tie rod assembly.

Remove and replaced Right tie rod assembly.

Lubed all fittings. Line 50 Vehicle out of service for alignment. Line 60 Vehicle picked up from alignment place Line 70 VEHICLE WAS SENT TO NATIONAL COLLISION FOR RIGHT FRON UPPER CORNER CABIN REPAIR Line 80 Tech said rear emergency brake loose didn't hold upright

Preventive maintenance

Check rear emergency brake no adjustment need it Line 90 Rear differential leaking

Preventive maintenance

Resealed the differential add fluids completed

Activity Header					
Activity: 10 002 CAB & SHEET METAL					
Activity Note: metal damage by left upper windshield corner-vehicle sent to national collision					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
No Data Available					
Activity Labor					
No Data Available					
Activity Sublet					
PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4745957	181,124,199	285705	NATIONAL COLLISION & TRUCK CENTER INC,FL,FORT LAUDERDALE,5425 NW 9TH AVE	Jun 12, 2023 12:00:00 AM	4,093.64

Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
	<table> <tr> <th colspan="2">Activity 10 Sub Total</th></tr> <tr> <td>Parts:</td><td>0.00</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>0.00</td></tr> <tr> <td>Sublet Parts:</td><td>4,093.64</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>4,093.64</td></tr> </table>	Activity 10 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	4,093.64	Sublet Labor:	0.00	Activity Sub Total	4,093.64
Activity 10 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	4,093.64														
Sublet Labor:	0.00														
Activity Sub Total	4,093.64														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:20 999 TOTAL VEHICLE				
Activity Note: passenger side mirror arm broke				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Delva,Terry	1.52	65	98.8
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	98.80
			Labor Hours:	1.52
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	98.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:30 999 TOTAL VEHICLE				
Activity Note: front clearence light out				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Delva,Terry	0.55	65	35.75
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 30 Sub Total	
			Parts:	0.00
			Labor:	35.75
			Labor Hours:	0.55
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	35.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:40 999 TOTAL VEHICLE				
Activity Note: COOLANT AND OIL LEAK				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Delva,Terry	0.98	65	63.7
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 40 Sub Total	
			Parts:	0.00
			Labor:	63.70
			Labor Hours:	0.98
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	63.70



Work Order

55345 - Palm Tran Connection
v 3.0
Activity 5 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department: 55345M

Work Order Description

FOLLOW UP TO QCC INSP(Replace Suspension)

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 276,787 - DH

Activity Header

Activity:50	999	TOTAL VEHICLE

Activity Note: floor rust by driver area

Reason for Repair:	04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total	

Activity 50 Sub Total

Parts:	0.00

Labor:	0.00

Labor Hours:	0.00

Sublet Parts:	0.00

Sublet Labor:	0.00

Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header	
Activity:60 999 TOTAL VEHICLE	
Activity Note: drivers seat lower cushiong & cover needed	
Reason for Repair: 04 Driver's Report	
Work Accomplished:	
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
No Data Available	
No Data Available	
Activity Sub Total	
Activity 60 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:70 999 TOTAL VEHICLE				
Activity Note: W/C LIFT NEEDS PARTS-SEE NOTES				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-23	Delva,Terry	1.83	65	118.95
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 70 Sub Total	
			Parts:	0.00
			Labor:	118.95
			Labor Hours:	1.83
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	118.95



Work Order

55345 - Palm Tran Connection
v 3.0
Activity 8 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department: 55345M

Work Order Description

FOLLOW UP TO QCC INSP(Replace Suspension)

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 276,787 - DH

Activity Header

Activity:80	999	TOTAL VEHICLE

Activity Note: FIRE SUPPRESSION / INSPECTION REQUIRED

Reason for Repair:	04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total	

Activity 80 Sub Total

Parts:	0.00

Labor:	0.00

Labor Hours:	0.00

Sublet Parts:	0.00

Sublet Labor:	0.00

Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 9 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header
Activity:90 999 TOTAL VEHICLE
Activity Note: DRAG LINK HAS PLAY
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-23	MDOE27	LINK, DRAG, STEERING	1	115.32	115.32
19-May-23	MEOE126	END, TIE-ROD, OUTER, RH, ECONOLINE	1	34.13	34.13
24-May-23	MEOE166	END, LINK, DRAG	1	36.27	36.27
19-May-23	MEOE165	END, TIE-ROD	1	49.94	49.94

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-May-23	Earl Johnson	3.33	65	216.45

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 90 Sub Total</th></tr><tr><td>Parts:</td><td>235.66</td></tr><tr><td>Labor:</td><td>216.45</td></tr><tr><td>Labor Hours:</td><td>3.33</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>452.11</td></tr></table>	Activity 90 Sub Total		Parts:	235.66	Labor:	216.45	Labor Hours:	3.33	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	452.11	
Activity 90 Sub Total															
Parts:	235.66														
Labor:	216.45														
Labor Hours:	3.33														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	452.11														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 10 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:100 999 TOTAL VEHICLE				
Activity Note: UPPER & LOWER BALL JOINT HAVE PLAY				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-23	Junior Hurst	5.23	65	339.95
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 100 Sub Total	
			Parts:	0.00
			Labor:	339.95
			Labor Hours:	5.23
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	339.95



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 11 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:110 999 TOTAL VEHICLE				
Activity Note: LEFT AND RIGHT ENGINE MOUNT BAD				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-23	Junior Hurst	2.6	65	169
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 110 Sub Total	
			Parts:	0.00
			Labor:	169.00
			Labor Hours:	2.60
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	169.00



Work Order

55345 - Palm Tran Connection
v 3.0
Activity 12 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department: 55345M

Work Order Description

FOLLOW UP TO QCC INSP(Replace Suspension)

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty:	No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 276,787 - DH

Activity Header

Activity:120	999	TOTAL VEHICLE

Activity Note: OIL AND COOLANT LEAK

Reason for Repair:	04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total	

Activity 120 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 13 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity: 130 015/004/045 TIE-ROD, STEERING				
Activity Note: Tie rods need to be replaced.				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-May-23	Earl Johnson	3.97	65	258.05
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 130 Sub Total	
			Parts:	0.00
			Labor:	258.05
			Labor Hours:	3.97
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	258.05



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 14 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header				
Activity:140 999 TOTAL VEHICLE				
Activity Note: Pick up vehicle from alignment place				
Reason for Repair: 08 Preventive Maintenance				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
31-May-23	Nicolas Barreto	1.83	65	118.95
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 140 Sub Total	
			Parts:	0.00
			Labor:	118.95
			Labor Hours:	1.83
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	118.95



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 15 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header					
Activity:150 016 SUSPENSION					
Activity Note: Wheel Alignment done by vendor Elpex					
Reason for Repair: FW Follow Up					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
No Data Available					
Activity Labor					
No Data Available					
Activity Sublet					
PO No.	ACD Code	Supplier No.	SUPPLIER	Order Date	Received Value
4738808	180,847,178	72882	MIAMI TIRESOLES, ELPEX,FL,DEERFIELD BEACH,dba MIAMI TIRESOLES ELPEX	Jun 2, 2023 12:00:00 AM	1,038.58
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
				Activity 150 Sub Total	
				Parts:	0.00
				Labor:	0.00
				Labor Hours:	0.00
				Sublet Parts:	1,038.58
				Sublet Labor:	0.00
				Activity Sub Total	1,038.58



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 16 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header	
Activity:160 999 TOTAL VEHICLE	
Activity Note: adjust parking brakes.	
Reason for Repair: 04 Driver's Report	
Work Accomplished:	
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
No Data Available	
No Data Available	
Activity Sub Total	
Activity 160 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 17 of 17



Work Order No. 56740095
Invoice No. 55345 - 56740095

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOW UP TO QCC INSP(Replace Suspension)		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Activity Header															
Activity:170 999 TOTAL VEHICLE															
Activity Note: IN SERVICE INSPECTION															
Reason for Repair: 04 Driver's Report															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 170 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 170 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 170 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 56740095 Total</td></tr><tr><td>Parts:</td><td>235.66</td></tr><tr><td>Labor:</td><td>1,419.60</td></tr><tr><td>Labor Hours:</td><td>21.84</td></tr><tr><td>Sublet Parts:</td><td>5,132.22</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>6,787.48</td></tr></table>		Work Order 56740095 Total		Parts:	235.66	Labor:	1,419.60	Labor Hours:	21.84	Sublet Parts:	5,132.22	Sublet Labor:	0.00	Activity Sub Total	6,787.48
Work Order 56740095 Total															
Parts:	235.66														
Labor:	1,419.60														
Labor Hours:	21.84														
Sublet Parts:	5,132.22														
Sublet Labor:	0.00														
Activity Sub Total	6,787.48														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55625588
Invoice No. 55345 - 55625588

Client Department:

Department: 55345M

Work Order Description

QCC FLEET INSPECTION

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 276,486 -

Chronology

Reported	May 18, 2023 3:07:22 PM	May 18, 2023 3:07:22 PM
Started		
Completed	May 18, 2023 3:26:00 PM	May 18, 2023 3:26:00 PM
Down Time		

Work Order Notes

Line 10 QCC SERVICE PERFORMED

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 18-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	
7 - Have you performed the proper LOTO?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	May 18, 2023 3:10:57 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:

0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55625588
Invoice No. 55345 - 55625588

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,486 -

Activity Header						
Activity:20 999/999/999 TOTAL VEHICLE						
Activity Note: QCC FLEET INSPECTION						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
20 Desc: QCC FLEET INSPECTION						
Task: 55345 QCC FLEET INSPECTION Performed by: CVERGARA Performed on: 18-MAY-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - EXTERIOR CIRCLE INSPECTION	Done		CVERGARA	May 18, 2023 3:25:42 PM	No	
20 - Cleanliness			CVERGARA	May 18, 2023 3:25:42 PM	No	
30 - Entrance Door Operation/Seals/Glass	C	metal damage by left upper windshield corner	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
40 - Body/Fenders/Bumpers			CVERGARA	May 18, 2023 3:25:42 PM	No	
50 - Tires/Wheels/Lugs			CVERGARA	May 18, 2023 3:25:42 PM	No	
60 - Mirrors and Attachments	B	passenger side mirror arm broke	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
70 - Lights and Accessories		front clearance light out	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
80 - Compartment Doors			CVERGARA	May 18, 2023 3:25:42 PM	No	
90 - Battery Compartment			CVERGARA	May 18, 2023 3:25:42 PM	No	
100 - Check All Fluids	B	COOLANT AND OIL LEAK	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
110 - Belt Drives			CVERGARA	May 18, 2023 3:25:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
120 - Air Induction		n/a	CVERGARA	May 18, 2023 3:25:42 PM	No	
130 - Exhaust System			CVERGARA	May 18, 2023 3:25:42 PM	No	
140 - Engine Compartmetn Wiring			CVERGARA	May 18, 2023 3:25:42 PM	No	
150 - DRIVERS AREA INSPECTION	Done		CVERGARA	May 18, 2023 3:25:42 PM	No	
160 - Air System		n/a	CVERGARA	May 18, 2023 3:25:42 PM	No	
170 - Audible Warnings			CVERGARA	May 18, 2023 3:25:42 PM	No	
180 - Dash and Gauges			CVERGARA	May 18, 2023 3:25:42 PM	No	
190 - Accessory components			CVERGARA	May 18, 2023 3:25:42 PM	No	
200 - Exit Door Operation			CVERGARA	May 18, 2023 3:25:42 PM	No	
210 - Exit Door Interlock			CVERGARA	May 18, 2023 3:25:42 PM	No	
220 - Fare box and ticket cutter.		n/a	CVERGARA	May 18, 2023 3:25:42 PM	No	
230 - Fast Idle			CVERGARA	May 18, 2023 3:25:42 PM	No	
240 - Glass & Mirrors			CVERGARA	May 18, 2023 3:25:42 PM	No	
250 - Floor Covering		floor rust by driver area	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
260 - Horn and Lamps			CVERGARA	May 18, 2023 3:25:42 PM	No	
270 - Start Function			CVERGARA	May 18, 2023 3:25:42 PM	No	
280 - PA System		n/a	CVERGARA	May 18, 2023 3:25:42 PM	No	
290 - Pedal Condition and Adjustment			CVERGARA	May 18, 2023 3:25:42 PM	No	
300 - Reverse System			CVERGARA	May 18, 2023 3:25:42 PM	No	
310 - Seat	B	drivers seat lower cushiong & cover needed	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
320 - Steering Wheel & Column			CVERGARA	May 18, 2023 3:25:42 PM	No	
330 - Sun Visor			CVERGARA	May 18, 2023 3:25:42 PM	No	
340 - Turn Signals Switch			CVERGARA	May 18, 2023 3:25:42 PM	No	
350 - Electrical Compartment			CVERGARA	May 18, 2023 3:25:42 PM	No	
360 - Wheel Chair Operation	B	W/C LIFT NEEDS PARTS-SEE NOTES	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
370 - INTERIOR CIRCLE	-		CVERGARA	May 18, 2023 3:25:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
380 - Cleanliness			CVERGARA	May 18, 2023 3:25:42 PM	No	
390 - HVAC			CVERGARA	May 18, 2023 3:25:42 PM	No	
400 - Interior Passenger Area			CVERGARA	May 18, 2023 3:25:42 PM	No	
410 - Stop Request			CVERGARA	May 18, 2023 3:25:42 PM	No	
420 - Safety Equipment	B	FIRE SUPPRESSION / INSPECTION REQUIRED	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
430 - UNDERCARRIAGE	Done		CVERGARA	May 18, 2023 3:25:42 PM	No	
440 - Air System		N/A	CVERGARA	May 18, 2023 3:25:42 PM	No	
450 - Steering components		DRAG LINK HAS PLAY	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
460 - Brake Inspection			CVERGARA	May 18, 2023 3:25:42 PM	No	
470 - Suspension Components		UPPER & LOWER BALL JOINT HAVE PLAY	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
480 - Frame		LEFT AND RIGHT ENGINE MOUNT BAD	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
490 - Fluid Leakage		OIL AND COOLANT LEAK	CVERGARA	May 18, 2023 3:25:42 PM	Yes	56740095
500 - Fuel System			CVERGARA	May 18, 2023 3:25:42 PM	No	

Activity Sub Total


Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 55625588 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56696949
Invoice No. 55345 - 56696949

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Tag light		Ford E450 Champion Challenger	
Requested By:	NBARRETO	Status:	40 - Closed (40)
Created By:	NBARRETO	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	276,787 - DH

Chronology

Reported	May 9, 2023 1:31:41 PM	May 9, 2023 1:31:41 PM
Started	May 9, 2023 1:32:00 PM	
Completed	May 9, 2023 2:45:00 PM	May 9, 2023 2:45:00 PM
Down Time		

Work Order Notes

Line 10 Tag light repaired, connction replaced, light working fine

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: NBARRETO Performed on: 09-MAY-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	
7 - Have you performed the proper LOTO?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NBARRETO	May 9, 2023 2:15:36 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:

0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2




Work Order No. 56696949
Invoice No. 55345 - 56696949

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Tag light		Status:	40 - Closed (40)
Requested By:	NBARRETO	Priority:	-
Created By:	NBARRETO	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	276,787 - DH
Potential Warranty:	No		

Activity Header				
Activity:20 034/004/021 LAMP, MARKER (FORMERLY 034-001-019)				
Activity Note:				
Reason for Repair:	04	Driver's Report		
Work Accomplished:	03	Replace New		
Part Failure:	02	Burned, Scorched, Melted, Blistered		
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-May-23	Nicolas Barreto	1.22	65	79.3
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	79.30
			Labor Hours:	1.22
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	79.30
Work Order Footer				
			Work Order 56696949 Total	
			Parts:	0.00
			Labor:	79.30
			Labor Hours:	1.22
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	79.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 56677702
Invoice No. 55345 - 56677702

Client Department:
Department: 55345M **Equipment No.:** 4602-P
Work Order Description: Driver said bus cutting off while driving **VIN:** 1FDFE4FSXEDB17155
Requested By: HPIERRE **Status:** 40 - Closed (40)
Created By: HPIERRE **Priority:** -
Assigned To: **Driver:**
Class: - **Phone:**
Arrangement: Unassigned **ETA:**
Potential Warranty: No **Meter:** 276,312 - DH

Chronology		
Reported	May 3, 2023 8:51:17 AM	May 3, 2023 8:51:17 AM
Started	May 3, 2023 8:52:00 AM	
Completed	May 3, 2023 10:29:00 AM	May 3, 2023 10:29:00 AM
Down Time		

Work Order Notes

Line 10 Driver said bus cutting off while driving

Nothing found

Nothing found on the driver complaint completed

Activity Header
Activity:10 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-May-23	Pierre,Hubert J	1.55	65	100.75

Activity Sublet
No Data Available


Activity Checklist

Check List						
10 Desc: Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 03-MAY-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	May 3, 2023 10:29:02 AM	No	
Activity Sub Total			Activity 10 Sub Total			
			Parts: 0.00			
			Labor: 100.75			
			Labor Hours: 1.55			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 100.75			
Work Order Footer			Work Order 56677702 Total			
			Parts: 0.00			
			Labor: 100.75			
			Labor Hours: 1.55			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 100.75			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56654075
Invoice No. 55345 - 56654075

Client Department:

Department: 55345M

Work Order Description

rd call rear ac not working

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 276,312 - DH

Chronology

Reported	Apr 25, 2023 3:06:00 PM	Apr 25, 2023 3:06:00 PM
Started	Apr 25, 2023 3:07:00 PM	
Completed	Apr 25, 2023 5:41:00 PM	Apr 25, 2023 5:41:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:

Cause:

Correction: Line 20 Shuttle one vehicle to a driver far down vehicle return to shop whit unit # 4602 all component is working unit back to work Line 30 Shuttle one vehicle to a driver far down vehicle return to shop whit unit # 4602 all component is working unit back to work

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 25-APR-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 25, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:23:49 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 25, 2023 5:23:49 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 25, 2023 5:23:49 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 25, 2023 5:23:49 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 25, 2023 5:23:49 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 25, 2023 5:23:49 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56654075
Invoice No. 55345 - 56654075

Client Department:

Department: 55345M

Work Order Description

rd call rear ac not working

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 276,312 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Apr-23	Junior Hurst	2.28	65	148.2

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	148.20
Labor Hours:	2.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	148.20

Work Order Footer

Work Order 56654075 Total

Parts:	0.00
Labor:	148.20
Labor Hours:	2.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	148.20



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 56622876
Invoice No. 55345 - 56622876

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Medium Duty			Ford E450 Champion Challenger
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	275,114 - DH

Chronology

Reported	Apr 14, 2023 4:51:07 PM	Apr 14, 2023 4:51:07 PM
Started		
Completed	Apr 24, 2023 11:23:39 AM	Apr 24, 2023 11:23:39 AM
Down Time		

Work Order Notes

Activity Header

Activity: 10 027/001/013 HARDWARE, MOUNTING, CASE, TRANSMISSION, AUTOMATIC APFI - 027-001-001

Activity Note: unit needs two motor mount

Reason for Repair: FW Follow Up

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 56622876 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 56613078
Invoice No. 55345 - 56613078

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR(Wheel Chair Lift Not Operating Correctly)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	274,740 - DH

Chronology		
Reported	Apr 12, 2023 11:46:00 PM	Apr 12, 2023 11:46:00 PM
Started		
Completed	Apr 16, 2023 12:26:20 PM	Apr 16, 2023 12:26:20 PM
Down Time		

Work Order Notes

Line 10 Needs Outer Shock For Wheel Chair Flap

Part on Order

Activity Header															
Activity: 20 055/023/000 LIFT, WHEELCHAIR, PASSENGER															
Activity Note: Wheel Chair Lift Not Operating Correctly															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><th colspan="2">Activity 20 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 20 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 20 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><th colspan="2">Work Order 56613078 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 56613078 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 56613078 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56195682
Invoice No. 55345 - 56195682

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMA

Requested By: SPACE

Created By: SPACE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 274,813 - DH

Chronology

Reported	Apr 13, 2023 12:00:00 AM	Apr 13, 2023 12:00:00 AM
Started	Apr 14, 2023 1:09:00 PM	
Completed	Apr 14, 2023 5:03:00 PM	Apr 14, 2023 5:03:00 PM
Down Time		

Work Order Notes

Line 10 Vehicle came in for service due by mileage also change oil filter part # B329

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 14-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 14, 2023 4:59:13 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:

0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56195682
Invoice No. 55345 - 56195682

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-MEDIUM DUTY PMA		Ford E450 Champion Challenger	
Requested By:	SPACE	Status:	40 - Closed (40)
Created By:	SPACE	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	274,813 - DH

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: Medium Duty PM Inspection
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-23	Junior Hurst	2.82	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Medium Duty PM Inspection Task: First Transit North America Medium Duty PM Inspection Sheet Performed by: JUHURST Performed on: 14-APR-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,800 - CHECK_All Destination Signage	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
10,900 - *RPT*INSPECT_Body Damage,	Done		JUHURST	Apr 14, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Corrosion;DOCUMENT_Issues				4:57:54 PM		
11,000 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
11,200 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,200 - CHECK_Public Address System	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,300 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,400 - *RPT*INSPECT_Steering Wheel for Play,Bind; Horn Op; Turn Signal Cancelation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,500 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,600 - RECORD_Brake Performance Test E.T.	80 Second*		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,700 - RECORD_Brake Performance Test Speed	30 Miles per Hour		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,800 - RECORD_Brake Performance Test Distance	50 FEET		JUHURST	Apr 14, 2023 4:57:54 PM	No	
20,900 - RECORD_Brake Performance Test Adj Distance (20mph)	50 FEET		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,000 - RECORD_Brake Performance Test Ave GX	80 Gravitational Force		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,100 - ADD_Image of Brake Test Results to PM Work Order	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,200 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,300 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,400 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,500 - INSPECT_High Idle Control	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,600 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,700 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,800 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
21,900 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
22,000 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
22,100 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
22,200 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
22,250 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
22,300 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
22,400 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,000 - CSF (Curb Side Front)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 14, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:57:54 PM		
33,050 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,060 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Apr 14, 2023 4:57:54 PM	No	
33,070 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,700 - CHECK_Passenger Stop Request System	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,800 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
40,900 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,000 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,100 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,200 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,300 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,400 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
41,500 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done	unit needs two motor mount	JUHURST	Apr 14, 2023 4:57:54 PM	Yes	56622876
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,000 - !FRA!INSPECT_REAR Brake Assemblies	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,100 - !FRA!INSPECT_REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.2699 Inch		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,700 - CHECK_Spring Brake Inversion Valve	Done		JUHURST	Apr 14, 2023	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				4:57:54 PM		
55,800 - CHECK_Double Check Valve - Primary, Secondary	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
55,900 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
56,000 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
56,100 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	1435 Cycles		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SrvManual for Fluid to Use.	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 14, 2023 4:57:54 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.82
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56195682
Invoice No. 55345 - 56195682

Client Department:

Department: 55345M

Work Order Description
55345-MEDIUM DUTY PMA

Requested By: SPACE

Created By: SPACE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 274,813 - DH

Activity Header

Activity: 20 999/999/999 TOTAL VEHICLE

Activity Note: Medium Duty PMA Service

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Apr-23	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.51	2.51

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-23	Junior Hurst	1.08	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: Medium Duty PMA Service						
Task: 55345-Medium Duty PMA Inspection Performed by: JUHURST Performed on: 14-APR-23						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 14, 2023 2:11:38 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 14, 2023 2:11:38 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	
106,000 - Drain Water from Fuel Water Separator (where applicable)	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		JUHURST	Apr 14, 2023 2:11:38 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 14, 2023 2:11:38 PM	No	

Activity Sub Total															
	<table> <tr> <th colspan="2">Activity 20 Sub Total</th></tr> <tr> <td>Parts:</td><td>2.51</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>1.08</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>2.51</td></tr> </table>	Activity 20 Sub Total		Parts:	2.51	Labor:	0.00	Labor Hours:	1.08	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	2.51
Activity 20 Sub Total															
Parts:	2.51														
Labor:	0.00														
Labor Hours:	1.08														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	2.51														
Work Order Footer															
	<table> <tr> <th colspan="2">Work Order 56195682 Total</th></tr> <tr> <td>Parts:</td><td>2.51</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>3.90</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>2.51</td></tr> </table>	Work Order 56195682 Total		Parts:	2.51	Labor:	0.00	Labor Hours:	3.90	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	2.51
Work Order 56195682 Total															
Parts:	2.51														
Labor:	0.00														
Labor Hours:	3.90														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	2.51														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56596671
Invoice No. 55345 - 56596671

Client Department:

Department: 55345M

Work Order Description

Replace Wheel Chair Bag

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 274,385 - DH

Chronology

Reported	Apr 6, 2023 11:06:00 PM	Apr 6, 2023 11:06:00 PM
Started	Apr 6, 2023 11:07:00 PM	
Completed	Apr 6, 2023 11:11:00 PM	Apr 6, 2023 11:11:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Wheel chair bag ripped

Cause: Normal wear and tear

Correction: Replace wheel chair bag part# Q5-8522 Qty 1

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: AOWENS Performed on: 06-APR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	
4 - Are you wearing the appropriate PPE?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	
7 - Have you performed the proper LOTO?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Apr 6, 2023 11:11:14 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56596671
Invoice No. 55345 - 56596671

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Replace Wheel Chair Bag		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	274,385 - DH

Activity Header
Activity:15 055/023/000 LIFT, WHEELCHAIR, PASSENGER
Activity Note: Replace Wheel Chair Bag
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Apr-23	Q5-8522	POUCH, STORAGE, Q-STRAINT, NYLON	1	47.31	47.31

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Apr-23	Owens,Arthur	0.5	65	32.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	47.31
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	79.81

Work Order Footer	
Work Order 56596671 Total	
Parts:	47.31
Labor:	32.50
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	79.81



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5



Work Order No. 56374198
Invoice No. 55345 - 56374198

Client Department:

Department: 55345M

Work Order Description

Perform Bus Inspection

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 273,389 - DH

Chronology

Reported	Feb 3, 2023 6:10:05 PM	Feb 3, 2023 6:10:05 PM
Started	Feb 3, 2023 6:12:00 PM	
Completed	Mar 21, 2023 10:02:00 PM	Mar 21, 2023 10:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:needs to be check

Cause: Inspection

Correction:has body damage, missing driver side mirror need to be disinfect
dead batteries, not ready to drive

Line 20 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:needs to be check

Cause: Inspection

Correction:has body damage, missing driver side mirror need to be disinfect
dead batteries, not ready to drive

Rear Ac not working , do all the processing still not working

Check it found electrical problem .found by pass wire

Replace driver side mirror.

Needs front brakes found driver side caliper seized .

Heat the bolt can't loose and broken

Needs new caliper bracket.ion Line 30 Rear A/C check :

Electrical wires repaired
Rear A/C recovery,vacuum,Leak test and recharge performed.

NB:Rear A/C orifice tube needs to be replaced. However the A/C equipmenr Robinair is not working properly to replace it.

Line 40 Remove and replaced LF caliper bracket(14-1096) Qty.1.

Remove and replaced caliper slide pins.

Remove and replaced front brake pads(BC2Z-2V001-D) Qty.1.

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-FEB-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	
7 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 3, 2023 6:12:15 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5



Work Order No. 56374198
Invoice No. 55345 - 56374198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Perform Bus Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header

Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: needs inspection

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:needs to be check

Cause: Inspection

Correction:has body damage, missing driver side mirror need to be disinfect
dead batteries, not ready to drive
Rear Ac not working , do all the processing still not working
Check it found electrical problem .found by pass wire
Replace driver side mirror.
Needs front brakes found driver side caliper seized .
Heat the bolt can't loose and broken
Needs new caliper bracket.

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-23	Gaspard,Ronald	1.32	65	85.8
10-Mar-23	Gaspard,Ronald	4.8	65	312
09-Mar-23	NELSON PIERRE-LOUIS	1.75	65	113.75
03-Feb-23	Gaspard,Ronald	0.68	65	44.2
09-Mar-23	Gaspard,Ronald	1.4	65	91

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	0.00
Labor:	646.75
Labor Hours:	9.95
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	646.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5



Work Order No. 56374198
Invoice No. 55345 - 56374198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Perform Bus Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header				
Activity:25 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: Inspect Rear AC				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Mar-23	Fritz Simon	3.88	65	252.2
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 25 Sub Total	
			Parts:	0.00
			Labor:	252.20
			Labor Hours:	3.88
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	252.20



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5



Work Order No. 56374198
Invoice No. 55345 - 56374198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Perform Bus Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header					
Activity:35 043/001/030 CONVERTER, CATALYTIC					
Activity Note: CUTTING CATALYTIC CONVERTER MESH					
Reason for Repair: 08 Preventive Maintenance					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Mar-23	14212	BOLT, PIN, CALIPER, BRAKE, DISC, E450	1	8.49	8.49
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
13-Mar-23	Fritz Simon	1.35	65	87.75	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 35 Sub Total		
			Parts:	8.49	
			Labor:	87.75	
			Labor Hours:	1.35	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	96.24	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5



Work Order No. 56374198
Invoice No. 55345 - 56374198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Perform Bus Inspection		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header
Activity:45 013/001/029 PADS, BRAKE, DISC, FRONT
Activity Note: Replace Front Brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Mar-23	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	57.74	57.74
21-Mar-23	141096	BRACKET, CALIPER, BRAKE, DISC, FRONT, LH, FORD	1	38.21	38.21

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-23	Earl Johnson	2.15	65	139.75
14-Mar-23	Earl Johnson	0.15	65	9.75

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 45 Sub Total	
		Parts:	95.95
		Labor:	149.50
		Labor Hours:	2.30
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	245.45

Work Order Footer		Work Order 56374198 Total	
		Parts:	104.44
		Labor:	1,136.20
		Labor Hours:	17.48
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1,240.64



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56494085
Invoice No. 55345 - 56494085

Client Department:

Department: 55345M

Work Order Description

CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: -

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 273,389 - DH

Chronology

Reported	Mar 10, 2023 5:27:24 PM	Mar 10, 2023 5:27:24 PM
Started	Mar 10, 2023 5:35:00 PM	
Completed	Mar 10, 2023 9:16:00 PM	Mar 10, 2023 9:16:00 PM
Down Time		

Work Order Notes

Line 10 CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLED.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-23	Fritz Simon	0.02	65	1.3

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 10-MAR-23

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	
4 - Are you wearing the appropriate PPE?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	
7 - Have you performed the proper LOTO?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 10, 2023 5:36:21 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	1.30
	Labor Hours:	0.02
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56494085
Invoice No. 55345 - 56494085

Client Department:		
Department:	55345M	Equipment No.: 4602-P
Work Order Description		VIN: 1FDFE4FSXEDB17155
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION		Ford E450 Champion Challenger
Requested By:	FSIMON	Status: 40 - Closed (40)
Created By:	FSIMON	Priority: -
Assigned To:		Driver:
Class:	-	Phone:
Arrangement:	Unassigned	ETA:
Potential Warranty:	No	Meter: 273,389 - DH

Activity Header				
Activity:20 043/000/000 EXHAUST SYSTEM				
Activity Note:				
Reason for Repair:		05 Inspection, Routine		
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-23	Fritz Simon	1.82	65	118.3
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	118.30
			Labor Hours:	1.82
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	118.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56494085
Invoice No. 55345 - 56494085

Client Department:		
Department:	55345M	Equipment No.: 4602-P
Work Order Description		VIN: 1FDFE4FSXEDB17155
CATALYTIC CONVERTER THEFT DETERRENT KIT INSTALLATION		Ford E450 Champion Challenger
Requested By:	FSIMON	Status: 40 - Closed (40)
Created By:	FSIMON	Priority: -
Assigned To:		Driver:
Class:	-	Phone:
Arrangement:	Unassigned	ETA:
Potential Warranty:	No	Meter: 273,389 - DH

Activity Header				
Activity:30 043/001/030 CONVERTER, CATALYTIC				
Activity Note: CUTTING MESH				
Reason for Repair: 08 Preventive Maintenance				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Mar-23	Fritz Simon	1.77	65	115.05
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 30 Sub Total	
			Parts:	0.00
			Labor:	115.05
			Labor Hours:	1.77
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	115.05
Work Order Footer				
			Work Order 56494085 Total	
			Parts:	0.00
			Labor:	234.65
			Labor Hours:	3.61
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	234.65



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56198670
Invoice No. 55345 - 56198670

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Road Call		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Chronology		
Reported	Dec 7, 2022 8:00:00 AM	Dec 7, 2022 8:00:00 AM
Started	Dec 7, 2022 8:11:00 AM	
Completed	Dec 8, 2022 4:18:00 PM	Dec 8, 2022 4:18:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction: Line 20 Drive bus to the body shop for repair (estimate)

Activity Header							
Activity:5 999 TOTAL VEHICLE							
Activity Note: PRAMETER							
Reason for Repair: SW Shop Work Order							
Work Accomplished: 06 Inspect							
Part Failure:							
Activity Comments:							
Activity Parts							
No Data Available							
Activity Labor							
No Data Available							
Activity Sublet							
No Data Available							
Activity Checklist							
Check List							
5 Desc: PRAMETER							
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 08-DEC-22							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 8, 2022 4:04:50 PM	No		
2 - If task requires lifting, are lifts secured, are jack	Done		TDELVA	Dec 8, 2022	No		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				4:04:50 PM		
4 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 8, 2022 4:04:50 PM	No	
7 - Have you performed the proper LOTO?	Done		TDELVA	Dec 8, 2022 4:04:50 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 8, 2022 4:04:50 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 8, 2022 4:04:50 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56198670
Invoice No. 55345 - 56198670

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Road Call		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header				
Activity:10 999 TOTAL VEHICLE				
Activity Note: ROAD CALL				
Reason for Repair: 10 Road Call				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Dec-22	Pierre,Hubert J	2.78	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	2.78
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56198670
Invoice No. 55345 - 56198670


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Road Call		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	273,389 - DH

Activity Header				
Activity:20 010 CHASSIS GROUP				
Activity Note: CRACK ON UPPER WIDNSHIELD. LEAKING WATER				
Reason for Repair: 42 Physical Damage				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-22	Delva,Terry	5.15	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	5.15
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 56198670 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	7.93
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56132734
Invoice No. 55345 - 56132734

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
WIPER SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,117 - DH

Chronology		
Reported	Nov 14, 2022 7:59:00 AM	Nov 14, 2022 7:59:00 AM
Started	Nov 14, 2022 8:20:00 AM	
Completed	Nov 14, 2022 9:36:00 AM	Nov 14, 2022 9:36:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: wiper system not working

Cause: bad wiper arms

Correction: replace wiper arms completed

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-NOV-22


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	
4 - Are you wearing the appropriate PPE?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	
7 - Have you performed the proper LOTO?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 14, 2022 9:36:38 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56132734
Invoice No. 55345 - 56132734

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
WIPER SYSTEM		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,117 - DH

Activity Header
Activity:15 002/035 WIPER & WASHER, WINDSHIELD
Activity Note: WIPER ARMS NOT MOVING
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-22	1C2Z-17566-AA	LINKAGE, WIPER, WINDSHIELD	1	63.99	63.99

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-22	Pierre,Hubert J	1.18	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>63.99</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.18</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>63.99</td></tr></table>	Activity 15 Sub Total		Parts:	63.99	Labor:	0.00	Labor Hours:	1.18	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	63.99	
Activity 15 Sub Total															
Parts:	63.99														
Labor:	0.00														
Labor Hours:	1.18														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	63.99														

Work Order Footer															
<table><tr><th colspan="2">Work Order 56132734 Total</th></tr><tr><td>Parts:</td><td>63.99</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.18</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>63.99</td></tr></table>	Work Order 56132734 Total		Parts:	63.99	Labor:	0.00	Labor Hours:	1.18	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	63.99	
Work Order 56132734 Total															
Parts:	63.99														
Labor:	0.00														
Labor Hours:	1.18														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	63.99														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56093134
Invoice No. 55345 - 56093134

Client Department:

Department: 55345M

Work Order Description

REAR AC NOT WORKING

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 272,117 - DH

Chronology

Reported	Nov 1, 2022 3:26:00 PM	Nov 1, 2022 3:26:00 PM
Started	Nov 1, 2022 4:05:00 PM	
Completed	Nov 6, 2022 7:07:00 PM	Nov 6, 2022 7:07:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Rear AC not working.

Cause: Rear AC compressor clutch wires damaged.

Correction: Noted for repair. AWP.

Line 20 Remove and replaced rear AC compressor with good used unit. Vacuum, leak tested, added PAG oil and recharged to spec. Rear AC operates properly.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-NOV-22


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Nov 1, 2022 11:05:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56093134
Invoice No. 55345 - 56093134


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,117 - DH

Activity Header				
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: CHECK REAR AC				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-22	Earl Johnson	3.87	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	3.87
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56093134
Invoice No. 55345 - 56093134

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
REAR AC NOT WORKING		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,117 - DH

Activity Header
Activity:25 001/001/002 COMPRESSOR, A/C
Activity Note: REAR AC COMPRESSOR REPLACEMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-22	Earl Johnson	4.42	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	4.42
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 56093134 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	8.29
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56079685
Invoice No. 55345 - 56079685

Client Department:

Department: 55345M

Work Order Description

Vehicle making a clicking sound.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 272,003 - DH

Chronology

Reported	Oct 27, 2022 6:50:11 PM	Oct 27, 2022 6:50:11 PM
Started	Oct 27, 2022 6:53:00 PM	
Completed	Oct 28, 2022 12:05:00 AM	Oct 28, 2022 12:05:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle makes clicking sound.

Cause: Wiper linkage is detached.

Correction: Remove Wiper motor panel and reattached wiper linkage. Wipers work properly.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 28-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 28, 2022 12:01:04 AM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Oct 28, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:01:04 AM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 28, 2022 12:01:04 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 28, 2022 12:01:04 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 28, 2022 12:01:04 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 28, 2022 12:01:04 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56079685
Invoice No. 55345 - 56079685

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Vehicle making a clicking sound.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,003 - DH

Activity Header
Activity:15 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Vehicle making clicking sound.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Oct-22	Earl Johnson	2.32	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>2.32</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	2.32	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	2.32														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														

Work Order Footer															
<table><tr><th colspan="2">Work Order 56079685 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>2.32</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 56079685 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	2.32	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 56079685 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	2.32														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 56075796
Invoice No. 55345 - 56075796

Client Department:

Department: 55345M

Work Order Description

Reinstall GEO Tab And Check Washer Fluid Bottle

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 272,003 - DH

Chronology

Reported	Oct 26, 2022 4:00:00 PM	Oct 26, 2022 4:00:00 PM
Started	Oct 26, 2022 4:01:00 PM	
Completed	Oct 27, 2022 12:33:00 AM	Oct 27, 2022 12:33:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Reinstall Geotab/ washer fluid bottle.

Cause: Washer bottle hose puncture.

Correction: Remove and replaced Geotab equipment/ repaired washer bottle hose.

Line 20 SN: G9-1WA-Z1U-V3DN

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Oct 26, 2022 7:18:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 56075796
Invoice No. 55345 - 56075796

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Reinstall GEO Tab And Check Washer Fluid Bottle		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,003 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Install GEO TAB				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-22	Earl Johnson	1.92	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.92
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 56075796
Invoice No. 55345 - 56075796

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Reinstall GEO Tab And Check Washer Fluid Bottle		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	272,003 - DH

Activity Header
Activity:25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Washer Bottle
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
26-Oct-22	Earl Johnson	1.1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.10
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 56075796 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			3.02
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56056278
Invoice No. 55345 - 56056278

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 HEADLIGHTS		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	271,229 - DH

Chronology

Reported	Oct 20, 2022 8:04:49 AM	Oct 20, 2022 8:04:49 AM
Started		
Completed	Oct 24, 2022 12:22:00 PM	Oct 24, 2022 12:22:00 PM
Down Time		

Work Order Notes

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-22	H13BP	BULB, HEADLAMP, HALOGEN	1	14.74	14.74

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 24-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Oct 24, 2022 12:22:29 PM	No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	14.74
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	14.74



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56056278
Invoice No. 55345 - 56056278

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 HEADLIGHTS			Ford E450 Champion Challenger
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	271,229 - DH

Activity Header															
Activity:20 034/001/000 HEADLAMP															
Activity Note:															
Reason for Repair:	39 Natural Causes														
Work Accomplished:	03 Replace New														
Part Failure:	02 Burned, Scorched, Melted, Blistered														
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 20 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 20 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 20 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 56056278 Total</td></tr><tr><td>Parts:</td><td>14.74</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>14.74</td></tr></table>		Work Order 56056278 Total		Parts:	14.74	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	14.74
Work Order 56056278 Total															
Parts:	14.74														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	14.74														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55851719
Invoice No. 55345 - 55851719

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMB

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 269,815 - DH

Chronology

Reported	Oct 7, 2022 12:00:00 AM	Oct 7, 2022 12:00:00 AM
Started	Oct 11, 2022 2:41:00 PM	
Completed	Oct 11, 2022 5:43:00 PM	Oct 11, 2022 5:43:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Vehicle came in for service

CAUSE: Service due by Mileage

CORRECTION: Service job complete also change oil filter B329 and wash rear A/C filter

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 11, 2022 2:40:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Oct 11, 2022 2:40:13 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 11, 2022 2:40:13 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 11, 2022 2:40:13 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 11, 2022 2:40:13 PM	No	
11 - Have you successfully completed the Personal	Done		JUHURST	Oct 11, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?				2:40:13 PM			
Activity Sub Total				Activity 5 Sub Total			
				Parts:		0.00	
				Labor:		0.00	
				Labor Hours:		0.00	
				Sublet Parts:		0.00	
				Sublet Labor:		0.00	
				Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55851719
Invoice No. 55345 - 55851719

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMB

Requested By: NPIERRE-LOUIS

Created By: NPIERRE-LOUIS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 269,815 - DH

Activity Header

Activity: 10 020 GROUP, DRIVETRAIN

Activity Note: Light Duty PMI

Reason for Repair: 11 Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	4.11	4.11

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-22	Junior Hurst	2.6	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 11-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Oct 11, 2022 4:54:35 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
41,200 - INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	6 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
51,900 - INSPECT_VISUALLY_RECORD_LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,000 - INSPECT_VISUALLY_RECORD_RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	11 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.2266 Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.2266 Inch		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	25334 Cycles		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Oct 11, 2022 4:54:35 PM	No	
Activity Sub Total						
			Activity 10 Sub Total			
			Parts:			4.11
			Labor:			0.00
			Labor Hours:			2.60
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			4.11



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55851719
Invoice No. 55345 - 55851719

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	269,815 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-22	Junior Hurst	0.35	0	0


Activity Sublet
No Data Available

Check List						
20 Desc: PM B Task: PM B SERVICE Performed by: JUHURST Performed on: 11-OCT-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Oct 11, 2022 3:01:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Oct 11, 2022 3:01:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Oct 11, 2022 3:01:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
201,000 - Service Crankcase Breather	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		JUHURST	Oct 11, 2022 3:01:28 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		JUHURST	Oct 11, 2022 3:01:28 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Oct 11, 2022 3:01:28 PM	No	
Activity Sub Total						
			Activity 20 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.35
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00
Work Order Footer						
			Work Order 55851719 Total			
			Parts:			4.11
			Labor:			0.00
			Labor Hours:			2.95
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			4.11



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 56028126
Invoice No. 55345 - 56028126

Client Department:

Department: 55345M

Work Order Description

Unscheduled Work

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 270,116 - DH

Chronology

Reported	Oct 11, 2022 12:08:45 PM	Oct 11, 2022 12:08:45 PM
Started	Oct 11, 2022 1:14:00 PM	
Completed	Oct 11, 2022 2:24:00 PM	Oct 11, 2022 2:24:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle came to shop for right rear bumper repair

Cause: came a part

Correction: replaced the same cover back now can go back to work

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 11-OCT-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Oct 11, 2022 2:21:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Oct 11, 2022	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				2:21:46 PM		
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Oct 11, 2022 2:21:46 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Oct 11, 2022 2:21:46 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Oct 11, 2022 2:21:46 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Oct 11, 2022 2:21:46 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 56028126
Invoice No. 55345 - 56028126

Client Department:

Department: 55345M

Work Order Description

Unscheduled Work

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 270,116 - DH

Activity Header

Activity: 15 072 WALL & DOOR, REAR

Activity Note: unit came to shop for rear bumper

Reason for Repair: 11 Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Oct-22	Junior Hurst	0.02	0	0
11-Oct-22	Junior Hurst	1.1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 56028126 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55898194
Invoice No. 55345 - 55898194

Client Department:

Department: 55345M

Work Order Description

check engine light on + interior light

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 267,476 - DH

Chronology

Reported	Aug 30, 2022 7:19:00 AM	Aug 30, 2022 7:19:00 AM
Started	Aug 30, 2022 7:45:00 AM	
Completed	Aug 30, 2022 10:03:00 AM	Aug 30, 2022 10:03:00 AM
Down Time		

Work Order Notes

Line 10 C: as per driver vehicle drive too slow

C: Check computer system found codes that were in the memory but not active related to misfires, performed engine running test

C: road test vehicle can't duplicate concern vehicle drives ok at all speeds also lights works ok

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA


Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 30-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No	
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No	
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																						
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Aug 30, 2022 10:02:55 AM	No																							
Activity Sub Total			<table><tr><td colspan="2">Activity 10 Sub Total</td><td></td></tr><tr><td>Parts:</td><td></td><td>0.00</td></tr><tr><td>Labor:</td><td></td><td>0.00</td></tr><tr><td>Labor Hours:</td><td></td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td></td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td></td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td></td><td>0.00</td></tr></table>					Activity 10 Sub Total			Parts:		0.00	Labor:		0.00	Labor Hours:		0.00	Sublet Parts:		0.00	Sublet Labor:		0.00	Activity Sub Total		0.00
Activity 10 Sub Total																												
Parts:		0.00																										
Labor:		0.00																										
Labor Hours:		0.00																										
Sublet Parts:		0.00																										
Sublet Labor:		0.00																										
Activity Sub Total		0.00																										



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55898194
Invoice No. 55345 - 55898194


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
check engine light on + interior light		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	267,476 - DH

Activity Header				
Activity:20 040 ENGINE/MOTOR SYSTEMS GROUP				
Activity Note: check engine light on				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 09 Troubleshooting				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
30-Aug-22	Perez,Javier	2.3	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	2.30
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55898194
Invoice No. 55345 - 55898194

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
check engine light on + interior light		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	267,476 - DH

Activity Header															
Activity: 30 174/024/017 LAMP, CEILING, BUS															
Activity Note: check interior lights															
Reason for Repair: 04 Driver's Report															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 30 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 30 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 30 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 55898194 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>2.30</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 55898194 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	2.30	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 55898194 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	2.30														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55850400
Invoice No. 55345 - 55850400

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	265,350 - DH

Activity Header					
Activity:20 016/008/064 KIT, SUSPENSION, AIR					
Activity Note: rubber spring,shear					
Reason for Repair: FW Follow Up					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-22	DSR108-075	RUBBER, SPRING, SHEAR, RUBBER, REAR, MOR/RUDE	1	152.75	152.75
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
12-Aug-22	NELSON PIERRE-LOUIS	3	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:	152.75	
			Labor:	0.00	
			Labor Hours:	3.00	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	152.75	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55850400
Invoice No. 55345 - 55850400

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	265,350 - DH

Activity Header															
Activity:30 016 SUSPENSION															
Activity Note:															
Reason for Repair: 01 Breakdown															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 30 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 30 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 30 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 55850400 Total</td></tr><tr><td>Parts:</td><td>152.75</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>152.75</td></tr></table>		Work Order 55850400 Total		Parts:	152.75	Labor:	0.00	Labor Hours:	3.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	152.75
Work Order 55850400 Total															
Parts:	152.75														
Labor:	0.00														
Labor Hours:	3.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	152.75														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55743671
Invoice No. 55345 - 55743671

Client Department:

Department: 55345M

Work Order Description

PMA SERVICE

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 265,049 - DH

Chronology

Reported	Aug 9, 2022 12:00:00 AM	Aug 9, 2022 12:00:00 AM
Started	Aug 11, 2022 4:00:00 PM	
Completed	Aug 12, 2022 3:00:00 PM	Aug 12, 2022 3:00:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE:preventive maintenance

CORRECTION: Perform PMA Service and lube all Pivoting Points

Activity Header

Activity:5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 12-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Aug 12, 2022 3:00:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 12, 2022 3:00:32 PM	No	
4 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 12, 2022 3:00:32 PM	No	
7 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 12, 2022 3:00:32 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 12, 2022 3:00:32 PM	No	
11 - Have you successfully completed the Personal	Done		NPIERRE-	Aug 12, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?			LOUIS	3:00:32 PM		
Activity Sub Total			Activity 5 Sub Total			
			Parts:		0.00	
			Labor:		0.00	
			Labor Hours:		0.00	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55743671
Invoice No. 55345 - 55743671

Client Department:

Department: 55345M

Work Order Description

PMA SERVICE

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 265,049 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-22	NELSON PIERRE-LOUIS	2.13	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Light Duty PMI						
Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 12-AUG-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-	Aug 12, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
			LOUIS	1:57:18 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	820 Degree Fahrenheit		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	12.2 Volt*		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	12.3 Volt*		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		NPIERRE-	Aug 12, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression			LOUIS	1:57:18 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	Yes	55850400
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
41,200 - INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	35.1 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	35.1 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	11 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	67 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	66 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	25.5 Inch		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done	rubber spring,shear	NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	Yes	55850400
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,200 - CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,500 - INSPECT_Bridgeplate Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,600 - INSPECT_ Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,700 - INSPECT_ Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Aug 12, 2022 1:57:18 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	2.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55743671
Invoice No. 55345 - 55743671

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PMA SERVICE		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	265,049 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19
12-Aug-22	65266	PLUG, DRAIN, OIL, ENGINE	1	4.9	4.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-22	NELSON PIERRE-LOUIS	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 12-AUG-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Aug 12, 2022 2:58:28 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	7.09
	Labor:	0.00
	Labor Hours:	0.75
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.09
Work Order Footer		
	Work Order 55743671 Total	
	Parts:	7.09
	Labor:	0.00
	Labor Hours:	2.88
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.09



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55823775
Invoice No. 55345 - 55823775

Client Department:

Department: 55345M

Work Order Description

55345 PER DVIR (Check Wheel Chair Lift)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 263,902 - DH

Chronology

Reported	Aug 2, 2022 6:07:00 PM	Aug 2, 2022 6:07:00 PM
Started	Aug 2, 2022 8:43:00 PM	
Completed	Aug 2, 2022 11:40:00 PM	Aug 2, 2022 11:40:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: WC lift malfunction.

Cause: Wear and tear.

Correction: Lubricated all Pivoting Points on the WC lift. Ran through 5 consecutive cycles without any issues.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 02-AUG-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Aug 2, 2022 9:32:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Aug 2, 2022 9:32:41 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Aug 2, 2022 9:32:41 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Aug 2, 2022 9:32:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Aug 2, 2022 9:32:41 PM	No	
11 - Have you successfully completed the	Done		EARJOHNSON	Aug 2, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Personal Risk Assessment?				9:32:41 PM			
Activity Sub Total				Activity 10 Sub Total			
				Parts:		0.00	
				Labor:		0.00	
				Labor Hours:		0.00	
				Sublet Parts:		0.00	
				Sublet Labor:		0.00	
				Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55823775
Invoice No. 55345 - 55823775

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR (Check Wheel Chair Lift)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	263,902 - DH

Activity Header				
Activity:20 055/023/000 LIFT, WHEELCHAIR, PASSENGER				
Activity Note: Check Wheel Chair Lift				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
02-Aug-22	Earl Johnson	0.8	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.80
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 55823775 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.80
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55793523
Invoice No. 55345 - 55793523

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Serptine Belt (Replace Tensioner)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	263,519 - DH

Chronology		
Reported	Jul 21, 2022 6:18:00 PM	Jul 21, 2022 6:18:00 PM
Started	Jul 21, 2022 6:19:00 PM	
Completed	Jul 28, 2022 9:33:00 AM	Jul 28, 2022 9:33:00 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Check serpentine belt.

Cause: Worn tensioner.

Correction: Recommended replace. Part not in stock. AWP.

Line 20 COMPLAINT: Check serpentine belt tensioner

Cause: wrong one was installed

Correction: replaced the serpentine belt with a new one, vehicle ok at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment

Check List						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-JUL-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 21, 2022 7:30:42 PM	No	

Activity Sub Total		Activity 5 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55793523
Invoice No. 55345 - 55793523

Client Department:

Department: 55345M

Work Order Description

Check Serptine Belt (Replace Tensioner)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 263,519 - DH

Activity Header

Activity:15 045/000 POWER PLANT

Activity Note: Check Serptine Belt

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jul-22	305263	TENSIONER, BELT, V10, FORD	1	33.99	33.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jul-22	Earl Johnson	1.05	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	33.99
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	33.99



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55793523
Invoice No. 55345 - 55793523

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Serptine Belt (Replace Tensioner)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	263,519 - DH

Activity Header
Activity:25 042/003/008 PULLEY, IDLER, DRIVEN, FAN
Activity Note: engine drive belt bad tensioner
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Jul-22	NELSON PIERRE-LOUIS	3	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			3.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 55793523 Total	
Parts:			33.99
Labor:			0.00
Labor Hours:			4.05
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			33.99



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55789861
Invoice No. 55345 - 55789861

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
PER PTC RANDOM INSPECTION CHECK FRONT TIRE			Ford E450 Champion Challenger
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	263,220 - DH

Chronology		
Reported	Jul 20, 2022 3:03:00 PM	Jul 20, 2022 3:03:00 PM
Started	Jul 20, 2022 11:47:00 PM	
Completed	Jul 21, 2022 8:02:00 AM	Jul 21, 2022 8:02:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: Check front tires.

Cause: Wear and tear.

Correction: Remove and replaced 2 front tires.

Activity Header Activity: 5 999 TOTAL VEHICLE Activity Note: Personal Risk Assessment Reason for Repair: SW Shop Work Order Work Accomplished: 06 Inspect Part Failure: Activity Comments:		
Activity Parts No Data Available		
Activity Labor No Data Available		
Activity Sublet No Data Available		
Activity Checklist <table border="1"><tr><th>Check List</th></tr><tr><td>5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-JUL-22</td></tr></table>	Check List	5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-JUL-22
Check List		
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 21-JUL-22		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jul 21, 2022 12:41:20 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55789861
Invoice No. 55345 - 55789861

Client Department:

Department: 55345M

Work Order Description

PER PTC RANDOM INSPECTION CHECK FRONT TIRE

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 263,220 - DH

Activity Header

Activity: 15 017/001/000 TIRE, PNEUMATIC

Activity Note: PER PTC RANDOM INSPECTION CHECK FRONT TIRES

Reason for Repair: 04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jul-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	140.79	281.58

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Jul-22	Earl Johnson	0.22	0	0
21-Jul-22	Earl Johnson	0.72	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	281.58
Labor:	0.00
Labor Hours:	0.94
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	281.58


Work Order Footer

Work Order 55789861 Total

Parts:	281.58
Labor:	0.00
Labor Hours:	0.94
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	281.58



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55770755
Invoice No. 55345 - 55770755

Client Department:

Department: 55345M

Work Order Description

Road Call - SERPENTINE BELT

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 262,546 - DH

Chronology

Reported	Jul 13, 2022 2:50:00 PM	Jul 13, 2022 2:50:00 PM
Started	Jul 13, 2022 3:12:00 PM	
Completed	Jul 13, 2022 7:08:00 PM	Jul 13, 2022 7:08:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle down

Cause: drive belt came out

Correction: removed and replaced one good used TENSIONER AND ONE DRIVE BELT PART # 1360KK
UNIT RETURN BACK TO WORK

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 13-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	
4 - Are you wearing the appropriate PPE?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	
7 - Have you performed the proper LOTO?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Jul 13, 2022 7:05:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55770755
Invoice No. 55345 - 55770755

Client Department:

Department: 55345M

Work Order Description

Road Call - SERPENTINE BELT

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 262,546 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jul-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.99	21.99

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-22	Junior Hurst	3.9	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	21.99
Labor:	0.00
Labor Hours:	3.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	21.99

Work Order Footer

Work Order 55770755 Total	
Parts:	21.99
Labor:	0.00
Labor Hours:	3.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	21.99



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55743640
Invoice No. 55345 - 55743640

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	260,659 - DH

Chronology

Reported	Jul 1, 2022 6:08:12 PM	Jul 1, 2022 6:08:12 PM
Started	Jul 1, 2022 6:36:00 PM	
Completed	Jul 1, 2022 7:55:00 PM	Jul 1, 2022 7:55:00 PM
Down Time		

Work Order Notes

Line 10 Washer fluid Leaking / one Clearance Light Out. Washer filler neck gromet bad Swap Gromet from Another Bus & Replace One Clearance Light out. Replace Clearance ?ight parts #3974688 Qty (1)

Activity Header

Activity: 10 002/008/001 PANEL, DASH
Activity Note: Clearance Light
Reason for Repair: FW Follow Up
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jul-22	3974688	LAMP, LED, AMBER	1	8.9	8.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-22	Arthurs,Durvin	0.52	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	8.90
Labor:	0.00
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	8.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55743640
Invoice No. 55345 - 55743640

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 260,659 - DH

Activity Header				
Activity: 20 002/035/059 HARDWARE, MOUNTING, ARM, WIPER, WINDSHIELD, APFI - 002-035-016				
Activity Note: Washer Fluid Leaking				
Reason for Repair: FW Follow Up				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-22	Arthurs,Durvin	0.67	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.67
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 55743640 Total	
			Parts:	8.90
			Labor:	0.00
			Labor Hours:	1.19
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	8.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 54489120
Invoice No. 55345 - 54489120

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	260,358 - DH

Chronology

Reported	Jun 3, 2022 12:00:00 AM	Jun 3, 2022 12:00:00 AM
Started	Jul 1, 2022 3:46:00 PM	
Completed	Jul 1, 2022 6:36:00 PM	Jul 1, 2022 6:36:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform PMA Service,

CAUSE: Service Due by Mileage,

CORRECTION: Change Oil & Filter. Lube all Pivoting Points Check Brake. Clean batteries. Clean A/C filter,
parts # B329 Qty (1)
Oil 5W30 Qty (7.0) Qts

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 1, 2022 6:12:06 PM	No															
Activity Sub Total			<table><tr><th colspan="2">Activity 5 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 54489120
Invoice No. 55345 - 54489120

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,358 - DH

Activity Header

Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Light Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-22	Arthurs,Durvin	1.92	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: DARTHURS Performed on: 01-JUL-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_Exhaust for Excessive Smoke	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		DARTHURS	Jul 1, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				6:08:57 PM		
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done	Clearance Light	DARTHURS	Jul 1, 2022 6:08:57 PM	Yes	55743640
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	-	Washer Fluid Leaking	DARTHURS	Jul 1, 2022 6:08:57 PM	Yes	55743640
20,800 - INSPECT_High Idle Control	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,550 - INSPECT_Driver Floor Area for Rust/Water Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
31,000 - SSF (Street Side Front)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,000 - Engine Inspection	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	-	NA	DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	NA	DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,100 - INSPECT_Intake System	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	0 Volt*		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,010 - CSF (Curb Side Front)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.98 Volt*		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		DARTHURS	Jul 1, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				6:08:57 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
41,200 - INSPECT_Emergency Windows,Hatches,Doors,Alarms/Lights;CHECK_for Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,400 - LUBE_All Chassis Components	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,500 - !FRA!CHANGE_Engine oil,filters	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,700 - INSPECT_Tire Condition	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.554 Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,100 - INSPECT_Vibration Damper	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,600 - INSPECT_Tire Condition	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	13 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,200 - !FRA!INSPECT_REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	12 32nds of an inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	1.656 Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	1.656 Inch		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	24550 Cycles		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,200 - CHECK_Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,500 - INSPECT_Bridgeplate Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		DARTHURS	Jul 1, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				6:08:57 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,400 - INSPECT_All Pivot Points	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,500 - INSPECT_Cams and Slots	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,600 - INSPECT_Rollers	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
62,700 - INSPECT_All Linkages	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		DARTHURS	Jul 1, 2022 6:08:57 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 54489120
Invoice No. 55345 - 54489120

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	260,358 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Jul-22	B329	FILTER, OIL, SPIN-ON SEE P550965	1	2.19	2.19

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-22	Arthurs,Durvin	0.43	0	0

Activity Sublet
No Data Available


Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: DARTHURS Performed on: 01-JUL-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Jul 1, 2022 6:11:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Jul 1, 2022 6:11:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Jul 1, 2022 6:11:08 PM	No	

Activity Sub Total	
Activity 20 Sub Total	

	Parts:	2.19
	Labor:	0.00
	Labor Hours:	0.43
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	2.19
Work Order Footer		
	Work Order 54489120 Total	
	Parts:	2.19
	Labor:	0.00
	Labor Hours:	2.35
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	2.19



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 55713553
Invoice No. 55345 - 55713553

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Chronology

Reported	Jun 22, 2022 3:56:00 PM	Jun 22, 2022 3:56:00 PM
Started	Jun 22, 2022 3:57:00 PM	
Completed	Jul 1, 2022 2:13:00 PM	Jul 1, 2022 2:13:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Bus will not move.

Cause: Drive belt failed (severed wires). Radiator cracked.

Correction: Arrived at the location with vehicle for driver to continue route. Awaited tow truck to transport disabled vehicle back to base for repairs. Line 20 C: vehicle overheated

C: Check coolant system found drive belt broke causing the engine to overheat and damage radiator

C: replace belt and radiator retest and road test vehicle ok at this time

parts:

1 new belt 1360k6

1 new radiator g1000382282csf

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List																				
5 Desc: PRAMETER																				
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 27-JUN-22																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
4 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
7 - Have you performed the proper LOTO?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
10 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
11 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Jun 27, 2022 2:12:48 PM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 5 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>0.00</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.00</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>0.00</td> </tr> </tbody> </table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 55713553
Invoice No. 55345 - 55713553

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL (Bus Will Not Move)

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-22	Earl Johnson	3.87	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	3.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 55713553
Invoice No. 55345 - 55713553

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Activity Header

Activity:20 042 COOLING SYSTEM

Activity Note: CHECK FOR OVERHEATING CONDITION

Reason for Repair: 04 Driver's Report

Work Accomplished: 09 Troubleshooting

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jun-22	G1000382282CSF	RADIATOR, E450	1	280.71	280.71
27-Jun-22	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.32	21.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jun-22	Perez,Javier	8.25	0	0
24-Jun-22	Perez,Javier	7.18	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	302.03
Labor:	0.00
Labor Hours:	15.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	302.03



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 55713553
Invoice No. 55345 - 55713553

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Activity Header

Activity:30 030 ELECTRICAL GROUP

Activity Note: BUS TOWED IN (WILL NOT SHIFT)

Reason for Repair: 39 Natural Causes

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jun-22	DSP-TOWING	DIRECT PURCHASES FOR SERVICES TOWING	1	235	235

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 30 Sub Total

Parts:	235.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	235.00

Work Order Footer

Work Order 55713553 Total

Parts:	537.03
Labor:	0.00
Labor Hours:	19.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	537.03



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55731463
Invoice No. 55345 - 55731463

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Chronology

Reported	Jun 29, 2022 4:10:00 PM	Jun 29, 2022 4:10:00 PM
Started	Jun 29, 2022 4:11:00 PM	
Completed	Jun 29, 2022 7:05:00 PM	Jun 29, 2022 7:05:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle stuck in park.

Cause: TBD.

Correction: Adjusted bi fold door microswitch.

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 29-JUN-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jun 29, 2022 6:57:03 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Jun 29, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				6:57:03 PM		
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jun 29, 2022 6:57:03 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jun 29, 2022 6:57:03 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jun 29, 2022 6:57:03 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jun 29, 2022 6:57:03 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55731463
Invoice No. 55345 - 55731463

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL (Bus Will Not Move)

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-22	Earl Johnson	1.85	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.85
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55731463
Invoice No. 55345 - 55731463

Client Department:

Department: 55345M

Work Order Description

Road Call (Bus Will Not Move)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 260,659 - DH

Activity Header

Activity:20 002 CAB & SHEET METAL

Activity Note: Bifold door switch malfunction.

Reason for Repair: 04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Jun-22	Earl Johnson	0.77	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.77
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 55731463 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54648824
Invoice No. 55345 - 54648824

Client Department:

Department: 55345M

Work Order Description

55345-PTC INSPECTION

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 260,243 -

Chronology

Reported	Jun 10, 2022 10:27:50 AM	Jun 10, 2022 10:27:50 AM
Started	Jun 10, 2022 12:00:00 AM	
Completed	Jun 13, 2022 12:02:00 PM	Jun 13, 2022 12:02:00 PM
Down Time		

Work Order Notes

Line 10 perform inspection for annual PTC inspection

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 13-JUN-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	
4 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	
7 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Jun 13, 2022 12:00:28 PM	No	

Activity Sub Total

Activity 5 Sub Total


Parts:

0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54648824
Invoice No. 55345 - 54648824


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	260,243 -

Activity Header				
Activity:15 999 TOTAL VEHICLE				
Activity Note: PTC INSPECTION				
Reason for Repair: 11 Routine				
Work Accomplished: 06 Inspect				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Jun-22	Rodriguez,Raul	2.4	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	2.40
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 54648824 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	2.40
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55650376
Invoice No. 55345 - 55650376

Client Department:

Department: 55345M

Work Order Description

F/ SUPPRESSION SYSTEM ALARM ON

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 259,555 - DH

Chronology

Reported	May 31, 2022 7:43:00 AM	May 31, 2022 7:43:00 AM
Started	May 31, 2022 12:00:00 AM	
Completed	Jun 13, 2022 11:59:00 AM	Jun 13, 2022 11:59:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT. fire extinguisher suppression alarm on

Cause. bad detector bottle pressure switch

Correction. removed and replaced detector bottle and hoses, tested, all okay at this time

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA


Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 31-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	May 31, 2022 10:32:28 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	May 31, 2022 10:32:28 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	May 31, 2022 10:32:28 AM	No	
7 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	May 31, 2022 10:32:28 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	May 31, 2022 10:32:28 AM	No	
11 - Have you successfully completed the	Done		RAUODRIGUEZ	May 31, 2022	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Personal Risk Assessment?				10:32:28 AM			
Activity Sub Total				Activity 10 Sub Total			
				Parts:		0.00	
				Labor:		0.00	
				Labor Hours:		0.00	
				Sublet Parts:		0.00	
				Sublet Labor:		0.00	
				Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55650376
Invoice No. 55345 - 55650376

Client Department:

Department: 55345M

Work Order Description

F/ SUPPRESSION SYSTEM ALARM ON

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 259,555 - DH

Activity Header

Activity: 20 051/007/000 SUPPRESSION, FIRE

Activity Note: F/SUPPRESSION SYSTEM ALARM ON

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Jun-22	Rodriguez,Raul	6.02	0	0
31-May-22	Rodriguez,Raul	2.6166666	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	8.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 55650376 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	8.64
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54648803
Invoice No. 55345 - 54648803

Client Department:

Department: 55345M

Work Order Description

QCC FLEET INSPECTION

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 259,254 -

Chronology

Reported	May 3, 2022 2:00:38 PM	May 3, 2022 2:00:38 PM
Started		
Completed	May 20, 2022 3:14:00 PM	May 20, 2022 3:14:00 PM
Down Time		

Work Order Notes

Line 10 QCC INSPECTION PERFORMED

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: CVERGARA Performed on: 20-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	
4 - Are you wearing the appropriate PPE?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	
7 - Have you performed the proper LOTO?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		CVERGARA	May 20, 2022 3:13:41 PM	No	

Activity Sub Total

Activity 10 Sub Total


Parts:

0.00

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54648803
Invoice No. 55345 - 54648803

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	259,254 -

Activity Header															
Activity:20 999 TOTAL VEHICLE															
Activity Note: QCC FLEET INSPECTION															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 20 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 20 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 20 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 54648803 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 54648803 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 54648803 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 55601389
Invoice No. 55345 - 55601389

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REAR AC SYSTEM		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	259,074 - DH

Chronology

Reported	May 12, 2022 12:48:41 PM	May 12, 2022 12:48:41 PM
Started	May 12, 2022 12:00:00 AM	
Completed	May 13, 2022 8:56:00 AM	May 13, 2022 8:56:00 AM
Down Time		

Work Order Notes

Line 10 complaint. rear ac is not working

Cause. bad Compressor

Correction. removed and replaced Compressor and idle pulleys, all okay at this time

Activity Header

Activity:10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 13-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	
4 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	
7 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
11 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 13, 2022 8:55:32 AM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 55601389
Invoice No. 55345 - 55601389

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
REAR AC SYSTEM		Status:	40 - Closed (40)
Requested By:	RAURODRIGUEZ	Priority:	-
Created By:	RAURODRIGUEZ	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	259,074 - DH
Potential Warranty:	No		

Activity Header					
Activity:20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION					
Activity Note: REAR AC DIAG					
Reason for Repair:		04 Driver's Report			
Work Accomplished:		03 Replace New			
Part Failure:		51 Inoperative			
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-22	3411885	TUBE, ORIFICE, A/C, FORD	1	0.73	0.73
12-May-22	6512723	COMPRESSOR, A/C	1	274	274
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
12-May-22	Rodriguez,Raul	4.1333333	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
Parts:			274.73		
Labor:			0.00		
Labor Hours:			4.13		
Sublet Parts:			0.00		
Sublet Labor:			0.00		
Activity Sub Total			274.73		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 55601389
Invoice No. 55345 - 55601389

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
REAR AC SYSTEM		Status:	40 - Closed (40)
Requested By:	RAURODRIGUEZ	Priority:	-
Created By:	RAURODRIGUEZ	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	259,074 - DH
Potential Warranty:	No		

Activity Header
Activity:30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-May-22	89101	PULLEY, IDLER	1	24.14	24.14
12-May-22	89026	PULLEY, IDLER, SMOOTH	1	13.69	13.69

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-May-22	Rodriguez,Raul	1.4333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 30 Sub Total	
Parts:	37.83
Labor:	0.00
Labor Hours:	1.43
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	37.83

Work Order Footer	
Work Order 55601389 Total	
Parts:	312.56
Labor:	0.00
Labor Hours:	5.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	312.56



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department: 55345M

Work Order Description

INTAKE MALIFOLD

Requested By: KIVEY

Created By: KIVEY

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 258,950 - DH

Chronology

Reported	Apr 11, 2022 1:18:00 PM	Apr 11, 2022 1:18:00 PM
Started	Apr 20, 2022 4:11:00 PM	
Completed	May 3, 2022 1:47:00 PM	May 3, 2022 1:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle Mifire.. shaking

Cause: code PO 300 Random Misfire Code PO 307 & PO301 Cylinder Misfire Check found intake Leaking

Correction: Check Compression O/K Spark O/K injector Pulse O/K. replace ## (1) coil & Plugs replace # (7) Plugs engine Run O/K at this time Bus need intake /O2 sensor exhaust hanger / Rear Caliper Coil & Plugs. Remove intake . Clean intake & Replace . (10) Spark Plugs REPLACE (9) ignition Coil / Replace Replace (10) injector O-Rings / Replace Lower Intake & Upper intakeq / Replace thermostat Gasket Replace (2) intake gasket Remove & Replace (2) Rear Caliper. Replace Rear Brakes Replace Slide Pins. / Mount & Balance Rear tire & Replace on Rear. Replace Exhaust Hanger. shop Supply. Change Oil & Filter. Remove & Replace Bank (1) & Bank (2) O2 Sensor.

Parts #8F9Z-9F472-H Qty (1)

Parts #8F9Z-9F472-J. Qty (1)

parts # B 329 Qty (1)

Oil 10W30 Qty (7.0) Qt

parts # BC2Z-2C150-B Qty (2)

parts BC2Z-2553-B Qty (1)

Parts# BC2Z-2552-B Qty (1)

parts #8C2Z-2200-B Qty (1)

parts #DG508 Qty (9)

parts #F1VY-8255-A Qty (1/

parts #FOPZ-9229-A Qty (1)

parts #4C3Z-9424-AA Qty (1)

parts #DC2Z-94-A Qty (1)

parts #4C2Z-9439-AA Qty (2)

parts # SP-521 Qty (10)

parts # DG508 Qty (1)

Parts # 192-659 Qty (4) Line 20 ALL PARTS CHARGED

Activity Header
Activity:5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist


Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-APR-22						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	
4 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	
7 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 26, 2022 10:20:20 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header
Activity:15 045/007 HEAD, CYLINDER
Activity Note: ENGINE RUNS ROUGH
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts						
Booked Date	Part Number	Part Description	Quantity	Each	Extended	
06-May-22	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	-5	13.54	-67.7	
26-Apr-22	F1VY-8255-A	SEAL, THERMOSTAT	1	3.84	3.84	
22-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	41.69	41.69	
26-Apr-22	SP521	PLUG, SPARK, 5.4L, FORD	8	4.03	32.24	
22-Apr-22	AP103	PLUG, SPARK	2	3.5	7	
26-Apr-22	FOPZ-9229-A	O-RING, SEAL, INJECTOR, FUEL SAME AS CM-4717	8	13.54	108.32	

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			125.39
Labor:			0.00
Labor Hours:			0.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			125.39



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header
Activity:25 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: CYLINDER HEAD RECONDITIONING
Reason for Repair: 01 Breakdown
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Apr-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	1,250	1,250
11-Apr-22	DSP-OUTSIDESERV	DIRECT PURCHASE FOR OUTSIDE SERV GL54354	1	1,250	1,250

Activity Labor
No Data Available


Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header

Activity:35 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: intake Leaking

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-22	DC2Z-9424-A	MANIFOLD, INTAKE, FORD, 6.8L	1	637.98	637.98
26-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	9	41.69	375.21
26-Apr-22	4C2Z-9439-AA	GASKET, MANIFOLD, INTAKE	2	21.55	43.1

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Arthurs,Durvin	4.08	0	0
24-Apr-22	Arthurs,Durvin	4.48	0	0
27-Apr-22	Arthurs,Durvin	1.5	0	0
26-Apr-22	Arthurs,Durvin	4.13	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 35 Sub Total

Parts:	1,056.29
Labor:	0.00
Labor Hours:	14.19
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1,056.29



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department: 55345M

Work Order Description

INTAKE MALIFOLD

Requested By: KIVEY

Created By: KIVEY

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 258,950 - DH

Activity Header

Activity: 45 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Rear Brakes& Calipers

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-22	BC2Z-2C150-B	PIN, CALIPER, BRAKE, DISC, UPDATED, E450, '08	2	10.9	21.8
28-Apr-22	BC2Z-2552-B	CALIPER, BRAKE, DISC, REAR, RH, E450	1	67.1	67.1
28-Apr-22	BC2Z-2553-B	CALIPER, BRAKE, DISC, REAR, LH, E450	1	67.1	67.1
28-Apr-22	8C2Z-2200-B	PADS, BRAKE, DISC, REAR, E450 SAME AS PFH133020	1	53.13	53.13

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Apr-22	Arthurs,Durvin	2.25	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available


Activity Sub Total

Activity 45 Sub Total

Parts:	209.13
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	209.13



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 6 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header				
Activity:55 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Exhaust Hanger				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	Arthurs,Durvin	0.58	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 55 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.58
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 7 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header					
Activity:65 079 DEVICES, SAFETY/STABILITY, TRAILER					
Activity Note: Rear Tire					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Apr-22	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	3	135.26	405.78
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
28-Apr-22	Arthurs,Durvin	1.35	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 65 Sub Total		
			Parts:	405.78	
			Labor:	0.00	
			Labor Hours:	1.35	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	405.78	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 8 of 8



Work Order No. 55510834
Invoice No. 55345 - 55510834

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
INTAKE MALIFOLD		Ford E450 Champion Challenger	
Requested By:	KIVEY	Status:	40 - Closed (40)
Created By:	KIVEY	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header
Activity:75 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace O2 Sensor
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-May-22	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.13	8.26
29-Apr-22	8F9Z-9F472-H	SENSOR, OXYGEN	1	67.58	67.58
29-Apr-22	8F9Z-9F472-J	SENSOR, OXYGEN, UPSTREAM, RH	1	90.26	90.26

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Apr-22	Arthurs,Durvin	1.22	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 75 Sub Total</th></tr><tr><td>Parts:</td><td>166.10</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.22</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>166.10</td></tr></table>	Activity 75 Sub Total		Parts:	166.10	Labor:	0.00	Labor Hours:	1.22	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	166.10	
Activity 75 Sub Total															
Parts:	166.10														
Labor:	0.00														
Labor Hours:	1.22														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	166.10														

Work Order Footer															
<table><tr><th colspan="2">Work Order 55510834 Total</th></tr><tr><td>Parts:</td><td>1,962.69</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>19.59</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>1,962.69</td></tr></table>	Work Order 55510834 Total		Parts:	1,962.69	Labor:	0.00	Labor Hours:	19.59	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	1,962.69	
Work Order 55510834 Total															
Parts:	1,962.69														
Labor:	0.00														
Labor Hours:	19.59														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	1,962.69														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55567503
Invoice No. 55345 - 55567503

Client Department:

Department: 55345M

Work Order Description

Drivers side mirror damaged.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 258,950 - DH

Chronology

Reported	May 1, 2022 12:33:28 PM	May 1, 2022 12:33:28 PM
Started	May 1, 2022 12:35:00 PM	
Completed	May 1, 2022 2:04:00 PM	May 1, 2022 2:04:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Drivers side mirror damaged.

Cause: Damaged during operation.

Correction: Remove and replaced drivers side mirror head assembly with good used unit.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 01-MAY-22

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	
4 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	
7 - Have you performed the proper LOTO?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	
10 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	
11 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	May 1, 2022 2:01:22 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55567503
Invoice No. 55345 - 55567503

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Drivers side mirror damaged.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header				
Activity: 15 099/000/000 SAFETY DEVICES INSTRUMENTS & GAUGES (POWER UNITS, TRAILERS, ETC.)				
Activity Note: Drivers side mirror damaged.				
Reason for Repair: 39 Natural Causes				
Work Accomplished: 03 Replace New				
Part Failure: 44 Worn				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-May-22	Earl Johnson	1.4	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.40
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 55567503 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.40
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 55538839
Invoice No. 55345 - 55538839

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Vehicle inspection		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	99 - Cancelled (99)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Chronology		
Reported	Apr 20, 2022 4:06:26 PM	Apr 20, 2022 4:06:26 PM
Started	Apr 20, 2022 4:31:00 PM	
Completed	Apr 26, 2022 4:28:42 PM	Apr 26, 2022 4:28:42 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:

Cause:

Correction:

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Are you wearing the appropriate PPE?	-				No	
7 - Have you performed the proper LOTO?	-				No	
10 - Are you aware of the potential risks of performing this repair?	-				No	
11 - Have you successfully completed the Personal Risk Assessment?	-				No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 55538839
Invoice No. 55345 - 55538839

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Vehicle inspection		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	99 - Cancelled (99)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,950 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check Bus
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	-1	41.69	-41.69
20-Apr-22	DG508	COIL, IGNITION SAME AS 3W7Z-12029-AA	1	65.89	65.89
26-Apr-22	AP103	PLUG, SPARK	-2	3.5	-7
20-Apr-22	AP103	PLUG, SPARK	2	3.5	7

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
20-Apr-22	Arthurs,Durvin	4.08	0	0
20-Apr-22	Arthurs,Durvin	-4.08	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	24.20
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	24.20

Work Order Footer	
Work Order 55538839 Total	
Parts:	24.20
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	24.20



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54827265
Invoice No. 55345 - 54827265

Client Department:

Department: 55345M

Work Order Description

Battery tary

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 258,576 - DH

Chronology

Reported	Aug 19, 2021 8:04:50 PM	Aug 19, 2021 8:04:50 PM
Started	Aug 19, 2021 8:08:00 PM	
Completed	Aug 19, 2021 9:02:00 PM	Aug 19, 2021 9:02:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle came in for battery tray

Cause: spring broken

Correction: replace one new spring to unit part # 0499252 after return vehicle back to work

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Aug-21	Junior Hurst	0.03	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 19-AUG-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Aug 19, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:01:18 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Aug 19, 2021 9:01:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Aug 19, 2021 9:01:18 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Aug 19, 2021 9:01:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Aug 19, 2021 9:01:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Aug 19, 2021 9:01:18 PM	No	
20 - Miles			JUHURST	Aug 19, 2021 9:01:18 PM	No	
30 - Kilometers			JUHURST	Aug 19, 2021 9:01:18 PM	No	
40 - Hours			JUHURST	Aug 19, 2021 9:01:18 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54827265
Invoice No. 55345 - 54827265

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Battery tary		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 - DH

Activity Header
Activity:15 020 GROUP, DRIVETRAIN
Activity Note: Battery tary
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Aug-21	0499252	SPRING, TRAY, BATTERY	1	2.93	2.93

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Aug-21	Junior Hurst	0.85	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			2.93
Labor:			0.00
Labor Hours:			0.85
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			2.93

Work Order Footer		Work Order 54827265 Total	
Parts:			2.93
Labor:			0.00
Labor Hours:			0.88
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			2.93



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53558163
Invoice No. 55345 - 53558163

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Chronology		
Reported	Jun 14, 2021 2:01:00 PM	Jun 14, 2021 2:01:00 PM
Started		
Completed	Jun 14, 2021 2:27:25 PM	Jun 14, 2021 2:27:25 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header							
Activity:5 999/999/999 TOTAL VEHICLE							
Activity Note: PERSONAL RISK ASSESSMENT							
Reason for Repair: SW Shop Work Order							
Work Accomplished: 06 Inspect							
Part Failure: 00 No Failure							
Activity Comments:							
Activity Parts							
No Data Available							
Activity Labor							
No Data Available							
Activity Sublet							
No Data Available							
Activity Checklist							
Check List							
5 Desc: PERSONAL RISK ASSESSMENT							
Task: PRA and Meter Readings Performed by: Performed on:							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
1 - Are you properly trained to perform the task?	-				No		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No		
3 - Are you wearing the appropriate PPE?	-				No		
4 - Have you performed the proper LOTO?	-				No		
5 - Are you aware of the potential risks of performing this repair?	-				No		
10 - Have you successfully completed the Personal Risk Assessment?	-				No		
20 - Miles					No		
30 - Kilometers					No		
40 - Hours					No		
Activity Sub Total							

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53558163
Invoice No. 55345 - 53558163

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-A/C INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Activity Header															
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION															
Activity Note: ANNUAL A/C INSPECTION															
Reason for Repair:	08 Preventive Maintenance														
Work Accomplished:	06 Inspect														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 53558163 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 53558163 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 53558163 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53557979
Invoice No. 55345 - 53557979

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-FIRE SAFETY INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Chronology		
Reported	Jun 14, 2021 2:01:01 PM	Jun 14, 2021 2:01:01 PM
Started		
Completed	Jun 14, 2021 2:27:02 PM	Jun 14, 2021 2:27:02 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header						
Activity:5 999/999/999 TOTAL VEHICLE						
Activity Note: PERSONAL RISK ASSESSMENT						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure: 00 No Failure						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: PERSONAL RISK ASSESSMENT						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	
Activity Sub Total						

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53557979
Invoice No. 55345 - 53557979


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-FIRE SAFETY INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Activity Header															
Activity:15 999 TOTAL VEHICLE															
Activity Note: ANNUAL FIRE SAFETY INSPECTION															
Reason for Repair:	08 Preventive Maintenance														
Work Accomplished:	06 Inspect														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tbody><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></tbody></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tbody><tr><td colspan="2">Work Order 53557979 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></tbody></table>		Work Order 53557979 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 53557979 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53557803
Invoice No. 55345 - 53557803

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Chronology

Reported	Jun 14, 2021 2:01:01 PM	Jun 14, 2021 2:01:01 PM
Started		
Completed	Jun 14, 2021 2:26:44 PM	Jun 14, 2021 2:26:44 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53557803
Invoice No. 55345 - 53557803


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-PTC INSPECTION		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	99 - Cancelled (99)
Created By:	NSTOLFO	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Activity Header															
Activity:15 999 TOTAL VEHICLE															
Activity Note: PTC INSPECTION															
Reason for Repair:	11 Routine														
Work Accomplished:	06 Inspect														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tbody><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></tbody></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tbody><tr><td colspan="2">Work Order 53557803 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></tbody></table>		Work Order 53557803 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 53557803 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53544615
Invoice No. 55345 - 53544615

Client Department:

Department: 55345M

Work Order Description

QCC FLEET INSPECTION

Requested By: RBOTH

Created By: RBOTH

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 99 - Cancelled (99)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 258,576 -

Chronology

Reported	Jun 14, 2021 2:01:01 PM	Jun 14, 2021 2:01:01 PM
Started		
Completed	Jun 14, 2021 2:21:42 PM	Jun 14, 2021 2:21:42 PM
Down Time		

Work Order Notes

Line 10 Bus is retired and no longer in service.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53544615
Invoice No. 55345 - 53544615

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDDE4FSXEDB17155
QCC FLEET INSPECTION		Ford E450 Champion Challenger	
Requested By:	RBOOTH	Status:	99 - Cancelled (99)
Created By:	RBOOTH	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 -

Activity Header															
Activity:20 999 TOTAL VEHICLE															
Activity Note: QCC FLEET INSPECTION															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 20 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 20 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 20 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 53544615 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 53544615 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 53544615 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 54590477
Invoice No. 55345 - 54590477

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 - DH

Chronology

Reported	May 24, 2021 11:21:12 AM	May 24, 2021 11:21:12 AM
Started	May 24, 2021 11:24:00 AM	
Completed	May 27, 2021 11:35:40 AM	May 27, 2021 11:35:40 AM
Down Time		

Work Order Notes

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 24-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
20 - Miles			RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	
30 - Kilometers			RAURODRIGUEZ	May 24, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:24:00 AM		
40 - Hours			RAURODRIGUEZ	May 24, 2021 11:24:00 AM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 54590477
Invoice No. 55345 - 54590477

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 - DH

Activity Header				
Activity:20 999 TOTAL VEHICLE				
Activity Note:				
Reason for Repair:		08 Preventive Maintenance		
Work Accomplished:		06 Inspect		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-May-21	Rodriguez,Raul	1.17	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.17
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 54590477
Invoice No. 55345 - 54590477


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,576 - DH

Activity Header															
Activity:30 050 GROUP, ACCESSORIES															
Activity Note:															
Reason for Repair: 01 Breakdown															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 30 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 30 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 30 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 54590477 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.17</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 54590477 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	1.17	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 54590477 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	1.17														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54546643
Invoice No. 55345 - 54546643

Client Department:

Department: 55345M

Work Order Description

FIRST TRANSIT - NORTH AMERICA - CONSPICUITY

Requested By: DGALLAGHER

Created By: DGALLAGHER

Assigned To:

Class: -

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 99 - Cancelled (99)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 258,207 - DH

Chronology

Reported	May 11, 2021 2:27:20 PM	May 11, 2021 2:27:20 PM
Started		
Completed	May 19, 2021 1:40:38 PM	May 19, 2021 1:40:38 PM
Down Time		

Work Order Notes

Line 10 Unit is out of service

Activity Header

Activity: 10 999/999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	-				No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-				No	
3 - Are you wearing the appropriate PPE?	-				No	
4 - Have you performed the proper LOTO?	-				No	
5 - Are you aware of the potential risks of performing this repair?	-				No	
10 - Have you successfully completed the Personal Risk Assessment?	-				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total

	Activity 10 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54546643
Invoice No. 55345 - 54546643

Client Department:

Department: 55345M

Work Order Description

FIRST TRANSIT - NORTH AMERICA - CONSPICUITY

Requested By: DGALLAGHER

Created By: DGALLAGHER

Assigned To:

Class: -

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 99 - Cancelled (99)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 258,207 - DH

Activity Header

Activity: 20 053/005/018 TAPE, REFLECTIVE

Activity Note: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY

Reason for Repair: IC Internal Campaign

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY

Task: FIRST TRANSIT - NORTH AMERICA - CONSPICUITY Performed by: Performed on:

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Inspect Conspicuity tape:					No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 54546643 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54564037
Invoice No. 55345 - 54564037

Client Department:

Department: 55345M

Work Order Description

55345 PER DVIR BUS NOT RUNNING RIGHT

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 258,571 - DH

Chronology

Reported	May 14, 2021 7:19:00 AM	May 14, 2021 7:19:00 AM
Started	May 14, 2021 7:38:00 AM	
Completed	May 14, 2021 11:26:00 AM	May 14, 2021 11:26:00 AM
Down Time		

Work Order Notes

Line 10 C: Check engine light on

C: Check computer system found code for cylinder #5 misfire also intake manifold is leaking

C: Replaced ignition coil with a used one and add silicone to intake gasket

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA

Task: PRA and Meter Readings Performed by: JAPERREZ Performed on: 14-MAY-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPERREZ	May 14, 2021 11:25:49 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPERREZ	May 14, 2021 11:25:49 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPERREZ	May 14, 2021 11:25:49 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPERREZ	May 14, 2021 11:25:49 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPERREZ	May 14, 2021 11:25:49 AM	No	
10 - Have you successfully completed the Personal	Done		JAPERREZ	May 14, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?				11:25:49 AM			
20 - Miles			JAPEREZ	May 14, 2021 11:25:49 AM	No		
30 - Kilometers			JAPEREZ	May 14, 2021 11:25:49 AM	No		
40 - Hours			JAPEREZ	May 14, 2021 11:25:49 AM	No		
Activity Sub Total							
				Activity 10 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54564037
Invoice No. 55345 - 54564037

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR BUS NOT RUNNING RIGHT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	258,571 - DH

Activity Header				
Activity:20 033 IGNITION				
Activity Note: VERIFY COMPLAINT				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-May-21	Perez,Javier	0.67	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.67
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 54564037 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.67
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54562936
Invoice No. 55345 - 54562936

Client Department:

Department: 55345M

Work Order Description

Bus Stalling

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 258,571 - DH

Chronology

Reported	May 13, 2021 4:01:00 PM	May 13, 2021 4:01:00 PM
Started	May 13, 2021 4:03:00 PM	
Completed	May 13, 2021 11:38:00 PM	May 13, 2021 11:38:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:stalled when it's hot all dash light came on and shaking

Cause: stall

Correction:can't drive towed to shop

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 13-MAY-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 13, 2021 11:36:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		RGASPARD	May 13, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				11:36:07 PM		
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 13, 2021 11:36:07 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 13, 2021 11:36:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 13, 2021 11:36:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 13, 2021 11:36:07 PM	No	
20 - Miles			RGASPARD	May 13, 2021 11:36:07 PM	No	
30 - Kilometers			RGASPARD	May 13, 2021 11:36:07 PM	No	
40 - Hours			RGASPARD	May 13, 2021 11:36:07 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54562936
Invoice No. 55345 - 54562936

Client Department:

Department: 55345M

Work Order Description

Bus Stalling

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 258,571 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL (Stalling)

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-May-21	Gaspard,Ronald	3.13	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 54562936 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	3.13
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54489297
Invoice No. 55345 - 54489297

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Tire		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	255,691 - DH

Chronology		
Reported	Apr 21, 2021 5:40:57 PM	Apr 21, 2021 5:40:57 PM
Started		
Completed	Apr 21, 2021 6:37:00 PM	Apr 21, 2021 6:37:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: right rear tire

Cause: Nails in tire

Correction: Removed and replace one new tire to right rear of unit part #192659 after return vehicle back to work

Activity Header							
Activity:5 999 TOTAL VEHICLE							
Activity Note: Personal Risk Assessment							
Reason for Repair: SW Shop Work Order							
Work Accomplished: 06 Inspect							
Part Failure:							
Activity Comments:							
Activity Parts							
No Data Available							
Activity Labor							
No Data Available							
Activity Sublet							
No Data Available							
Activity Checklist							
Check List							
5 Desc: Personal Risk Assessment							
Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-APR-21							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 21, 2021 6:11:13 PM	No	
20 - Miles			JUHURST	Apr 21, 2021 6:11:13 PM	No	
30 - Kilometers			JUHURST	Apr 21, 2021 6:11:13 PM	No	
40 - Hours			JUHURST	Apr 21, 2021 6:11:13 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54489297
Invoice No. 55345 - 54489297

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Tire		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	255,691 - DH

Activity Header
Activity:15 016RTD TIRES / WHEELS
Activity Note: Right rear tire
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Apr-21	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	117.57	117.57

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	117.57	Labor:	0.00
Labor Hours:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Activity Sub Total	117.57

Work Order Footer		Work Order 54489297 Total	
Parts:	117.57	Labor:	0.00
Labor Hours:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Activity Sub Total	117.57



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 54402187
Invoice No. 55345 - 54402187

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMC		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	255,691 - DH

Chronology

Reported	Apr 21, 2021 12:00:00 AM	Apr 21, 2021 12:00:00 AM
Started		
Completed	Apr 21, 2021 4:41:00 PM	Apr 21, 2021 4:41:00 PM
Down Time		

Work Order Notes

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 21-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 21, 2021 4:39:13 PM	No	
20 - Miles			JUHURST	Apr 21, 2021 4:39:13 PM	No	
30 - Kilometers			JUHURST	Apr 21, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				4:39:13 PM			
40 - Hours			JUHURST	Apr 21, 2021 4:39:13 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 54402187
Invoice No. 55345 - 54402187

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMC

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 255,691 - DH

Activity Header

Activity: 10 020 GROUP, DRIVETRAIN

Activity Note: Light Duty PMI

Reason for Repair: SS Sales and Service

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Apr-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.98	1.98

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Light Duty PMI Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 21-APR-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Apr 21, 2021 4:19:32 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
41,200 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
51,900 - INSPECT_VISUALLY_RECORD_LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,000 - INSPECT_VISUALLY_RECORD_RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	7.99 Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	7.99 Inch		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	24160 Cycles		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Apr 21, 2021 4:19:32 PM	No	
Activity Sub Total						
			Activity 10 Sub Total			
			Parts:			1.98
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			1.98



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 54402187
Invoice No. 55345 - 54402187

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMC

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 255,691 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM C

Task: PM C SERVICE Performed by: JUHURST Performed on: 21-APR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
201,000 - Service Crankcase Breather	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
204,000 - FRA Change Power Steering Fluid and Filter	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
302,000 - Check Toe-In and Record Reading	Done		JUHURST	Apr 21, 2021 4:37:42 PM	No	
302,001 - Record Toe-In Reading	45 Inches, fraction-actual		JUHURST	Apr 21, 2021 4:37:42 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	
305,000 - FRA Change Differential Fluid	Yes		JUHURST	Apr 21, 2021 4:37:42 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 54402187 Total	
Parts:	1.98
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.98



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 54294793
Invoice No. 55345 - 54294793

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	251,429 - DH

Chronology

Reported	Mar 22, 2021 12:00:28 PM	Mar 22, 2021 12:00:28 PM
Started	Mar 22, 2021 12:34:00 PM	
Completed	Mar 22, 2021 3:04:00 PM	Mar 22, 2021 3:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: unit came in for service

CAUSE: time for service

CORRECTION: replace new oil filter B329 after return vehicle back to work

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESSMENT
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-21	Junior Hurst	0.02	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 22-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Mar 22, 2021 12:34:49 PM	No	
20 - Miles			JUHURST	Mar 22, 2021 12:34:49 PM	No	
30 - Kilometers			JUHURST	Mar 22, 2021 12:34:49 PM	No	
40 - Hours			JUHURST	Mar 22, 2021 12:34:49 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 54294793
Invoice No. 55345 - 54294793

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	251,429 - DH

Activity Header
Activity:10 020 GROUP, DRIVETRAIN
Activity Note: Light Duty PMI
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Mar-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-Mar-21	Junior Hurst	2.35	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
10 Desc: Light Duty PMI Task: First Transit North America Light Duty PM Inspection Sheet Performed by: JUHURST Performed on: 22-MAR-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,800 - INSPECT_High Idle Control	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
31,000 - SSF (Street Side Front)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,000 - Engine Inspection	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	26 Degree Fahrenheit		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,100 - INSPECT_Intake System	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	14 Volt*		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,010 - CSF (Curb Side Front)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	14 Volt*		JUHURST	Mar 22, 2021 2:48:02 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,250 - INSPECT_Overhead Compartment for Water	Done		JUHURST	Mar 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks				2:48:02 PM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_ Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
41,200 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,400 - LUBE_All Chassis Components	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,700 - INSPECT_Tire Condition	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	1.2299 Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,100 - INSPECT_Vibration Damper	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,600 - INSPECT_Tire Condition	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	.799 Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	.799 Inch		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	19638 Cycles		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		JUHURST	Mar 22, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism				2:48:02 PM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting;Proper Operation	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,400 - INSPECT_All Pivot Points	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,500 - INSPECT_Cams and Slots	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,600 - INSPECT_Rollers	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
62,700 - INSPECT_All Linkages	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		JUHURST	Mar 22, 2021 2:48:02 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 54294793
Invoice No. 55345 - 54294793

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	251,429 - DH

Activity Header						
Activity:20 999 TOTAL VEHICLE						
Activity Note: PM A						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: A PM Level A						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: JUHURST Performed on: 22-MAR-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		JUHURST	Mar 22, 2021 2:53:23 PM	No	
101,000 - FRA Change Oil Filters	Yes		JUHURST	Mar 22, 2021 2:53:23 PM	No	
102,000 - FRA Drain Engine Oil	Yes		JUHURST	Mar 22, 2021 2:53:23 PM	No	
103,000 - FRA Check Transmission Fluid	Done		JUHURST	Mar 22, 2021 2:53:23 PM	No	
104,000 - Lubricate Chassis	Done		JUHURST	Mar 22, 2021 2:53:23 PM	No	
105,000 - Replace or Clean A/C Filters	Done		JUHURST	Mar 22, 2021 2:53:23 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		JUHURST	Mar 22, 2021 2:53:23 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		JUHURST	Mar 22, 2021 2:53:23 PM	No	
Activity Sub Total				Activity 20 Sub Total		
				Parts:	0.00	
				Labor:	0.00	
				Labor Hours:	0.00	
				Sublet Parts:	0.00	

		Sublet Labor:	0.00
		Activity Sub Total	0.00
Work Order Footer			
		Work Order 54294793 Total	
		Parts:	1.96
		Labor:	0.00
		Labor Hours:	2.37
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54356211
Invoice No. 55345 - 54356211

Client Department:

Department: 55345M

Work Order Description

Rear AC malfunction.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 249,697 - DH

Chronology

Reported	Mar 7, 2021 1:20:47 PM	Mar 7, 2021 1:20:47 PM
Started	Mar 7, 2021 1:24:00 PM	
Completed	Mar 11, 2021 12:18:00 PM	Mar 11, 2021 12:18:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:Rear ac is not working properly

Cause: Found system little low pressure

Correction: Perform regular Maintenance, all okay at this time.

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 11-MAR-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		RAUODRIGUEZ	Mar 11, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				12:15:02 PM		
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
20 - Miles			RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
30 - Kilometers			RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	
40 - Hours			RAUODRIGUEZ	Mar 11, 2021 12:15:02 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54356211
Invoice No. 55345 - 54356211


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear AC malfunction.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	249,697 - DH

Activity Header				
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: Rear AC malfunction.				
Reason for Repair: 04 Driver's Report				
Work Accomplished: 03 Replace New				
Part Failure: 51 Inoperative				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-21	Earl Johnson	3.07	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	3.07
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 54356211 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	3.07
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54303391
Invoice No. 55345 - 54303391

Client Department:

Department: 55345M

Work Order Description

Wont crank

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 247,586 - DH

Chronology

Reported	Feb 15, 2021 9:06:06 PM	Feb 15, 2021 9:06:06 PM
Started	Feb 16, 2021 1:35:00 PM	
Completed	Feb 16, 2021 2:57:00 PM	Feb 16, 2021 2:57:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Unit won't crank

Cause: Loose cable Battery

Correction: replace different terminal and also replace right front signal lamp and return vehicle back to work

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 16-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Feb 16, 2021 2:56:43 PM	No	
2 - If task requires lifting, are lifts secured, are jack	Done		JUHURST	Feb 16, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
stands used correctly?				2:56:43 PM		
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Feb 16, 2021 2:56:43 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Feb 16, 2021 2:56:43 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Feb 16, 2021 2:56:43 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Feb 16, 2021 2:56:43 PM	No	
20 - Miles			JUHURST	Feb 16, 2021 2:56:43 PM	No	
30 - Kilometers			JUHURST	Feb 16, 2021 2:56:43 PM	No	
40 - Hours			JUHURST	Feb 16, 2021 2:56:43 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54303391
Invoice No. 55345 - 54303391


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Wont crank		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	247,586 - DH

Activity Header				
Activity:15 030 ELECTRICAL GROUP				
Activity Note: Wont crank				
Reason for Repair: 11 Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-21	Junior Hurst	1.35	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.35
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 54303391 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.35
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 54186359
Invoice No. 55345 - 54186359

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 247,311 - DH

Chronology

Reported	Feb 11, 2021 12:00:00 AM	Feb 11, 2021 12:00:00 AM
Started	Feb 12, 2021 7:09:00 AM	
Completed	Feb 12, 2021 11:43:00 AM	Feb 12, 2021 11:43:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PmA Service

CAUSE: preventive maintenance

CORRECTION: perform PmA Service and Lube all Pivoting Points

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No	
10 - Have you successfully completed the Personal	Done		NPIERRE-	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?			LOUIS	11:41:44 AM			
20 - Miles			NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No		
30 - Kilometers			NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No		
40 - Hours			NPIERRE-LOUIS	Feb 12, 2021 11:41:44 AM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 54186359
Invoice No. 55345 - 54186359

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 247,311 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-21	3975927	LAMP, PLATE, LICENSE	1	11.96	11.96
12-Feb-21	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.4	8.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-21	NELSON PIERRE-LOUIS	2.68	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: NPIERRE-LOUIS Performed on: 12-FEB-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_Exhaust for Excessive Smoke	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,800 - INSPECT_High Idle Control	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,100 - INSPECT_Parking Brake Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
21,700 - INSPECT_Engine Fault Codes	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
31,000 - SSF (Street Side Front)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,030 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
31,040 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,000 - Engine Inspection	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	0 Degree Fahrenheit		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,100 - INSPECT_Intake System	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13 Volt*		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,010 - CSF (Curb Side Front)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	13.5 Volt*		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,000 - SECTION 4 - Interior Inspection	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,250 - INSPECT_Overhead Compartment for Water	Done		NPIERRE-	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks			LOUIS	9:50:44 AM		
40,300 - INSPECT_Safety Equipment, Fire Extinguisher/Suppression	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,600 - !FRA!CHECK for HOTSPOTS_ Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
41,200 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,200 - INSPECT_Ball Joint Play	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,400 - LUBE_All Chassis Components	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,700 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,300 - RECORD_RF-Air Pressure (psi)	65 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,600 - !FRA!INSPECT_Front Brake Assemblies	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	8 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	39.5 Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,100 - INSPECT_Vibration Damper	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,600 - INSPECT_Tire Condition	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,400 - RECORD_RRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	10 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	70 Pounds per Square Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	7 32nds of an inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	35.5 Inch		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,100 - RECORD_Wheelchair Cycle Count	0 Cycles		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,400 - OPERATE_Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
60,800 - INSPECT_Operation of Platform Barrier	Done		NPIERRE-	Feb 12, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Mechanism			LOUIS	9:50:44 AM		
60,900 - INSPECT_Cam Slots for Wear and Proper Alignment	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,000 - INSPECT_Cable Condition (If Applicable)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting;Proper Operation	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,400 - INSPECT_All Pivot Points	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,500 - INSPECT_Cams and Slots	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,600 - INSPECT_Rollers	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
62,700 - INSPECT_All Linkages	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,800 - INSPECT_ Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
80,000 - SECTION 8 - PMI Report Completion	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		NPIERRE-LOUIS	Feb 12, 2021 9:50:44 AM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	20.76
Labor:	0.00
Labor Hours:	2.68
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	20.76



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 54186359
Invoice No. 55345 - 54186359

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	247,311 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 12-FEB-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Feb 12, 2021 11:42:18 AM	No	

Activity Sub Total	Activity 20 Sub Total
Parts:	1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96
Work Order Footer		
Work Order 54186359 Total		
	Parts:	22.72
	Labor:	0.00
	Labor Hours:	2.68
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	22.72



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 54268058
Invoice No. 55345 - 54268058

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Baateries spring tray broken		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	246,047 - DH

Chronology		
Reported	Feb 3, 2021 7:00:34 PM	Feb 3, 2021 7:00:34 PM
Started	Feb 3, 2021 7:02:00 PM	
Completed	Feb 4, 2021 12:23:00 AM	Feb 4, 2021 12:23:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint:needs batteries tray spring

Cause: broken

Correction: replaced batteries tray spring
Part number 0499252 Qty1

Activity Header Activity: 5 999 TOTAL VEHICLE Activity Note: Personal Risk Assessment Reason for Repair: SW Shop Work Order Work Accomplished: 06 Inspect Part Failure: Activity Comments:		
Activity Parts No Data Available		
Activity Labor No Data Available		
Activity Sublet No Data Available		
Activity Checklist <table border="1"><tr><th>Check List</th></tr><tr><td>5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-FEB-21</td></tr></table>	Check List	5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-FEB-21
Check List		
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 03-FEB-21		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 3, 2021 7:02:46 PM	No	
20 - Miles			RGASPARD	Feb 3, 2021 7:02:46 PM	No	
30 - Kilometers			RGASPARD	Feb 3, 2021 7:02:46 PM	No	
40 - Hours			RGASPARD	Feb 3, 2021 7:02:46 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 54268058
Invoice No. 55345 - 54268058

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Baateries spring tray broken		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	246,047 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Baateries tray spring broken
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Feb-21	0499252	SPRING, TRAY, BATTERY	1	2.93	2.93

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
03-Feb-21	Gaspard,Ronald	0.75	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			2.93
Labor:			0.00
Labor Hours:			0.75
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			2.93

Work Order Footer		Work Order 54268058 Total	
Parts:			2.93
Labor:			0.00
Labor Hours:			0.75
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			2.93



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53685229
Invoice No. 55345 - 53685229

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMB

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 242,852 - DH

Chronology

Reported	Jan 6, 2021 12:00:00 AM	Jan 6, 2021 12:00:00 AM
Started	Jan 6, 2021 8:29:00 PM	
Completed	Jan 7, 2021 12:26:00 AM	Jan 7, 2021 12:26:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE: Service

CORRECTION:perform PMB Service

Oil filter B329 Qty1

Engine oil 10w30 qty 7 qts

Air filter PA4075 Qty1

Activity Header

Activity:5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 06-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 6, 2021 8:29:47 PM	No	
20 - Miles			RGASPARD	Jan 6, 2021 8:29:47 PM	No	
30 - Kilometers			RGASPARD	Jan 6, 2021 8:29:47 PM	No	
40 - Hours			RGASPARD	Jan 6, 2021 8:29:47 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53685229
Invoice No. 55345 - 53685229

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMB

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 242,852 - DH

Activity Header

Activity: 10 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Light Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-21	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-21	Gaspard,Ronald	1.48	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Duty PMI

Task: First Transit North America Light Duty PM Inspection Sheet Performed by: RGASPARD Performed on: 06-JAN-21

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 - Preparation Inspection	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,100 - INSPECT_Auto-Transmission Operation/Controller; Neutral Safety Switch	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,200 - !FRA!INSPECT_Starter Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,300 - !FRA!INSPECT_Warning Lights and Alarms	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,400 - !FRA!INSPECT_Back Up Alarm	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,500 - !FRA!INSPECT_Engine Operation, OBSERVE_ Exhaust for Excessive Smoke	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,600 - Check Driver's Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,700 - INSPECT_All Exterior Lights (Turn on until Completion of this section)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
10,800 - *RPT*INSPECT_Body Damage, Corrosion;DOCUMENT_Issues	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,900 - INSPECT_Fuel Tank Cap, and Doors	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
11,100 - INSPECT_License Plate, Bracket, Bumpers	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,000 - SECTION 2 - Test Drive and Operator Area Inspection	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,100 - INSPECT_Driver Seat condition/operation/seatbelt	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,200 - TEST DRIVE_INSPECT_Proper Operation; Drive into Shop	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,300 - *RPT*INSPECT_Steering Wheel for Play/Bind/Horn Op./Turn Signal Cancelation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,400 - PERFORM_Brake Test (Apply hard enough to check wheel pull and Application)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,500 - *RPT*FRA INSPECT_Lighting/Operation of all Gauges	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,600 - *RPT*INSPECT_Windshields, Sun Visors	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,700 - INSPECT_Wiper/Washer Operation, Condition	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,800 - INSPECT_High Idle Control	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
20,900 - *RPT*!FRA!INSPECT_HVAC Controls, Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,000 - *RPT*!FRA!INSPECT_Operation of all Switches and Accessories	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,100 - INSPECT_Parking Brake Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,200 - !FRA!TEST_Service Brake Backup System (Stationary Brake Tests HYD)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,300 - INSPECT_VIN, Tire Pressure Decal, Data Tags	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,400 - *RPT*INSPECT_Drivers Door Hinges, Handles, Controls and Panels	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,500 - !FRA!INSPECT_Under Dash Wiring for Proper Routing/Chafing/Securement	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,550 - INSPECT_Driver Floor Area for Water Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,600 - *RPT*INSPECT for WEAR_Pedal Pads, Accelerator, Brake, Parking Brake	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
21,700 - INSPECT_Engine Fault Codes	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
30,000 - SECTION 3 - EXTERIOR INSPECTION - Front	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
31,000 - SSF (Street Side Front)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
31,010 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
31,020 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
31,030 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
31,040 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,000 - Engine Inspection	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,010 - INSPECT_Hood, Springs and Props	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,020 - !FRA!INSPECT_Engine Compartment Condition for Fire Risk Avoidance	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,030 - !FRA!INSPECT_for Fluid Leaks, Levels	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,040 - !FRA!INSPECT_Hyd_Brake Fluid with Test Strips	Done	na	RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,050 - !FRA!INSPECT_RECORD_Coolant Recovery with Refractometer; Test Strips	Degree Fahrenheit	na	RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,060 - PRESSURE TEST_Cooling Systems (Radiator, Cap, hoses and clamps)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,070 - *RPT*INSPECT_Radiator and Mountings, Cores	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,080 - *RPT*INSPECT_Fan Assembly, Shroud, Tensioner, Belts, All Belt Driven Components	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,090 - *RPT*!FRA!INSPECT_Mounting, Installation of Alternator, AC Compressor	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,100 - INSPECT_Intake System	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
32,140 - *RPT*!FRA!RECORD_Underhood Battery Voltages (volts)	13.9 Volt*		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,010 - CSF (Curb Side Front)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,020 - *RPT*!FRA!INSPECT_Mirror Mountings, Brackets, Glass	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,030 - *RPT*INSPECT_FRONT Springs, Shocks, Spring Shackles	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,040 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,050 - INSPECT_Wiper Blades, Arms	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,060 - !FRA!INSPECT_LUBE_Battery Box, Batteries, Tray Slides, Hold Downs	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,070 - *RPT*!FRA!RECORD_Side Mounted Battery Voltages (volts)	Volt*	na	RGASPARD	Jan 6, 2021 9:55:39 PM	No	
33,080 - INSPECT_Entry door, OPEN_with external lock/switch (if equipped)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,000 - SECTION 4 - Interior Inspection	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,100 - *RPT*INSPECT_Step-Well, Step-Tread, Hand Rails, Step-well Light	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,200 - INSPECT_Insurance/Registration/Regulatory Forms Dates	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,250 - INSPECT_Overhead Compartment for Water Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,300 - INSPECT_Safety Equipment, Fire	Done		RGASPARD	Jan 6, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Extinguisher/Suppression				9:55:39 PM		
40,400 - INSPECT_Camera Systems, Filter, Electrical Inputs/Outputs-SOP M038	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,600 - !FRA!CHECK for HOTSPOTS_Interior Elec Panel Fuses/Circuit Breakers/Connectors	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,700 - *RPT*INSPECT_Seats, Covering, Belts, Loose Cushions, Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,800 - *RPT*!FRA!INSPECT_Interior Lights; Mirrors	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
40,900 - !FRA!INSPECT_Interior Cleanliness/Potential Projectiles	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
41,000 - INSPECT_All ADA Equip (Lift Seat Belt, floor hold Downs, Belts, Cover, Alarms)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
41,100 - INSPECT_CLEAN_AC Filter	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
41,200 - INSPECT_Emergency Windows, Hatches, Doors, Associated Alarms and Lights	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
41,300 - *RPT*INSPECT_Interior Body, Floor, Stanchions	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
41,400 - *RPT*INSPECT_Passenger Doors, Glass, Seal	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,000 - SECTION 5 - UNDER VEHICLE INSPECTION	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,100 - *RPT*INSPECT_Steering components-Drag Link, Tie Rods ends and Steering Damper	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,200 - INSPECT_Ball Joint Play	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,300 - !FRA!INSPECT_Front Wheel Bearings for Play	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,400 - LUBE_All Chassis Components	Done	na	RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,500 - !FRA!CHANGE_Engine oil, filters	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,700 - INSPECT_Tire Condition	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,800 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
50,900 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,000 - RECORD_LF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,100 - RECORD_LF-Tire Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,200 - RECORD_RF-Tire Tread Depth (32nds)	7 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,300 - RECORD_RF-Air Pressure (psi)	70 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,400 - !FRA!INSPECT_FRONT ABS Tone Rings, Sensors, Routing of Cables	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,500 - !FRA!INSPECT_Wheel Seals for Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
51,600 - !FRA!INSPECT_ Front Brake Assemblies	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,700 - MEASURE_RECORD_LF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,800 - MEASURE_RECORD_RF - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
51,900 - INSPECT VISUALLY_RECORD_LF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,000 - INSPECT VISUALLY_RECORD_RF Rotor Condition (inches)	37 Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,100 - INSPECT_Vibration Damper	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,200 - !FRA!INSPECT_Battery Cable Routing from Battery Box to Starter	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,400 - !FRA!INSPECT_Starter Mounting	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,500 - !FRA!INSPECT_Engine Exhaust System	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,700 - INSPECT_Engine, Transmission Mounts	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,800 - !FRA!INSPECT_Engine, Transmission for Fluid Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
52,900 - INSPECT_Shift Cable Adjustment - All Transmissions	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,000 - !FRA!INSPECT_Transmission Breather and Clean	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,100 - *RPT*!FRA!INSPECT_Parking Brake Cables, Shoes for Wear, Contamination	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,200 - *RPT*INSPECT_A/C Condensor, Fans, Safety Grills	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,300 - *RPT*INSPECT_Driveline, Hanger Bearings, U-Joints, Slip Joints, Safety Loop	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,400 - *RPT*INSPECT_All Body Mounts and Chassis Frame for Corrosion, Cracks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,500 - !FRA!INSPECT_Fuel Tank, Mountings, Lines	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,600 - INSPECT_Tire Condition	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,700 - INSPECT_Tire Valve Stems, Double Check Caps	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,800 - INSPECT_Mismatched Tire Tread, Casing Design	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
53,900 - INSPECT_Dual Mating Tires w/Square	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,000 - !FRA!INSPECT_Wheels for Cracks, Loose Lugs/Indicators, Outer Hub Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,100 - INSPECT_Mud Flaps, Brackets	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,200 - RECORD_RRO-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,300 - RECORD_RRI-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
54,400 - RECORD_RRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,500 - RECORD_RRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,600 - RECORD_LRO-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,700 - RECORD_LRI-Tire Tread Depth (32nds)	9 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,800 - RECORD_LRO-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
54,900 - RECORD_LRI-Air Pressure (psi)	65 Pounds per Square Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,000 - !FRA!INSPECT_ REAR Brake Assemblies	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,100 - !FRA!INSPECT_ REAR Hubs, Wheel Seals for Oil Leaks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,200 - !FRA!INSPECT_ REAR ABS Tone Rings, Sensors, Routing Of Cables (if equipped)	Done	na	RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,300 - MEASURE_RECORD_LR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,400 - MEASURE_RECORD_RR - Brake Lining, Pad Thickness (32nds)	10 32nds of an inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,500 - INSPECT VISUALLY_MEASURE_RECORD_LR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,600 - INSPECT VISUALLY_MEASURE_RECORD_RR Drum, Rotor Condition (inches)	40 Inch		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,700 - !FRA!INSPECT_ Under Body Exhaust System	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,800 - *RPT*INSPECT_ REAR Axle Housing, Breather; CLEAN_Breather	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
55,900 - *RPT*INSPECT_ REAR Springs, Shocks, Suspension, Airbags	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,000 - SECTION 6 - Wheelchair Inspection	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,100 - RECORD_Wheelchair Cycle Count	12324 Cycles		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,200 - CHECK_ Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,300 - CHECK_Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,400 - OPERATE_ Lift thru Complete Cycle;CHECK_Noises,Jerky Op,Too Fast-Slow,Drift Down	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,500 - INSPECT_ Bridgeplate Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,600 - INSPECT_All Pivot Points for Wear and Looseness	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,700 - INSPECT_Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,800 - INSPECT_Operation of Platform Barrier Mechanism	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
60,900 - INSPECT_Cam Slots for Wear and Proper	Done		RGASPARD	Jan 6, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alignment				9:55:39 PM		
61,000 - INSPECT_Cable Condition (If Applicable)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,100 - INSPECT_Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,200 - INSPECT_Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,300 - INSPECT_Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,400 - INSPECT_All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,500 - INSPECT_Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,600 - INSPECT_HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,700 - CHECK_Operator Decals for Proper Positioning;CONSULT_Service Manual	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,800 - CHECK_WC Holddowns Inside Vehicle for Secure Mounting,Proper Operation	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
61,900 - CLEAN_Linkages and Mechanisms	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,000 - LUBRICATE_Linkages and Mechanisms (DO NOT OVER Lubricate)	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,100 - INSPECT_Emergency Platform Release Mechanism	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,200 - INSPECT_Platform Barrier Latch Mechanism	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,300 - INSPECT_Bridgeplate Hinge	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,400 - INSPECT_All Pivot Points	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,500 - INSPECT_Cams and Slots	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,600 - INSPECT_Rollers	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
62,700 - INSPECT_All Linkages	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,000 - SECTION 7 - ALTERNATIVE FUELS INSPECTION	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,300 - INSPECT_Condition of Fuel Pressure Gauge	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,400 - PROVIDE PROOF_Tank_Dents/Scratches and Re-Certification	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,500 - INSPECT_Tank test date, labels-Reference-ST.4 FMMVSS 304 & ANSI-CSA NGV2	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,600 - INSPECT_Tank Lines to Ensure Secure Mounting, Insulation Against Vibration	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,700 - INSPECT_Filling Nozzle for Securely Fitting Cap	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
70,800 - INSPECT_Pressure Relief Device's Venting System, Valves, Ducting to MNFR Specs	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
80,000 - SECTION 8 - PMI Report Completion	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
80,100 - COMPLETE_PM Report; Follow-ups	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
80,200 - RETURN_Vehicle to Predetermined Location	Done		RGASPARD	Jan 6, 2021 9:55:39 PM	No	
Activity Sub Total						
			Activity 10 Sub Total			
			Parts:			5.28
			Labor:			0.00
			Labor Hours:			1.48
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			5.28



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53685229
Invoice No. 55345 - 53685229

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMB		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	242,852 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-21	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-21	Gaspard,Ronald	0.58	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: RGASPARD Performed on: 06-JAN-21						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 6, 2021 9:59:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 6, 2021 9:59:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Jan 6, 2021	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:59:13 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Jan 6, 2021 9:59:13 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Jan 6, 2021 9:59:13 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96

Work Order Footer

Work Order 53685229 Total

Parts:	7.24
Labor:	0.00
Labor Hours:	2.06
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	7.24



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53823481
Invoice No. 55345 - 53823481

Client Department:

Department: 55345M

Work Order Description

DIAGNOSTIC

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 241,579 - DH

Chronology

Reported	Aug 28, 2020 7:53:00 AM	Aug 28, 2020 7:53:00 AM
Started	Aug 28, 2020 8:02:00 AM	
Completed	Dec 28, 2020 2:20:00 PM	Dec 28, 2020 2:20:00 PM
Down Time		

Work Order Notes

Line 10 C: Vehicle dies while driving

C: Check all systems found no codes related to stalling. Further test indicates no problems at all systems

C: Replaced fuel pump kit, crank sensor, engine harness and roush engine harness, retest system and road test vehicle at this time vehicle doesn't die

Parts:

1 new fuel pump kit 11396002

1 crank sensor 1w72-6c315-ab

1 engine harness dc2z-9d930-wa

1 roush engine harness n225925-p11gd-18a100 Line 20 C: Front and rear a/c not working properly

C: Check systems found front a/c blower motor damaged and rear a/c condenser fan damaged

C: Replaced blower motor and fan retest system ok at this time

Parts:

1 blower motor xc2z-19805-NA

1 fan 27059482a

Activity Header	
Activity: 10 999/999/999 TOTAL VEHICLE	
Activity Note:	
Reason for Repair:	SW Shop Work Order
Work Accomplished:	06 Inspect
Part Failure:	00 No Failure
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	

Check List																				
10 Desc: Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 28-DEC-20																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
20 - Miles			JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
30 - Kilometers			JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
40 - Hours			JAPEREZ	Dec 28, 2020 2:13:00 PM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 10 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>0.00</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.00</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>0.00</td> </tr> </tbody> </table>				Activity 10 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 10 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53823481
Invoice No. 55345 - 53823481

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
DIAGNOSTIC		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,579 - DH

Activity Header
Activity:20 030 ELECTRICAL GROUP
Activity Note: electrical issue
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-20	DC2Z-9D930-WA	HARNESS, WIRING, ENGINE	1	161.87	161.87
28-Dec-20	11396002	PUMP, FUEL, GASEOUS, GEN-3 W/KIT	1	414.31	414.31
28-Dec-20	P11GD-18A100-A2F	HARNESS, UNDERHOOD	1	261.37	261.37
28-Dec-20	1W7Z-6C315-AB	SENSOR, POSITION, CRANKSHAFT	1	28.41	28.41

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-20	Perez,Javier	3.33	0	0
28-Dec-20	Perez,Javier	0.37	0	0
24-Sep-20	Perez,Javier	4.32	0	0
29-Sep-20	Perez,Javier	2.02	0	0
01-Sep-20	Perez,Javier	16.1	0	0
15-Sep-20	Perez,Javier	3.18	0	0
25-Dec-20	Perez,Javier	2.77	0	0
16-Sep-20	Perez,Javier	3.82	0	0
22-Sep-20	Perez,Javier	6	0	0
21-Dec-20	Perez,Javier	3	0	0
27-Nov-20	Perez,Javier	0.9	0	0
28-Aug-20	Perez,Javier	7.28	0	0
25-Sep-20	Perez,Javier	1.58	0	0
02-Sep-20	Perez,Javier	7.95	0	0
23-Dec-20	Perez,Javier	8.05	0	0
24-Dec-20	Perez,Javier	3.02	0	0
24-Nov-20	Perez,Javier	7.95	0	0

Activity Sublet
No Data Available

Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
	<table> <tr> <td colspan="2">Activity 20 Sub Total</td></tr> <tr> <td>Parts:</td><td>865.96</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>81.64</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>865.96</td></tr> </table>	Activity 20 Sub Total		Parts:	865.96	Labor:	0.00	Labor Hours:	81.64	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	865.96
Activity 20 Sub Total															
Parts:	865.96														
Labor:	0.00														
Labor Hours:	81.64														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	865.96														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53823481
Invoice No. 55345 - 53823481

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
DIAGNOSTIC		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,579 - DH

Activity Header

Activity:30 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION

Activity Note:

Reason for Repair: 04 Driver's Report

Work Accomplished: 03 Replace New

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Dec-20	GC2Z-19C836-C	ACCUMULATOR, A/C, E450	1	120.7	120.7
28-Dec-20	27059482A	FAN, CONDENSER, A/C SAME AS 25-14854-S	1	85.65	85.65
03-Dec-20	4C2Z-19A706-AA	RESISTOR, MOTOR, BLOWER SAME AS YH1697	1	13.06	13.06
28-Dec-20	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	36.25	36.25
03-Dec-20	D7OZ-19A563-A	VALVE, SUCTION, A/C	1	6.79	6.79

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Nov-20	Perez,Javier	5.87	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 30 Sub Total

Parts:	262.45
Labor:	0.00
Labor Hours:	5.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	262.45

Work Order Footer

Work Order 53823481 Total

Parts:	1,128.41
Labor:	0.00
Labor Hours:	87.51
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1,128.41



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53858939
Invoice No. 55345 - 53858939

Client Department:
Department: 55345M
Work Order Description
55345 THROTTLE BODY
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 241,580 - DH

Chronology		
Reported	Sep 10, 2020 9:45:27 AM	Sep 10, 2020 9:45:27 AM
Started	Sep 10, 2020 9:49:00 AM	
Completed	Oct 2, 2020 1:48:00 PM	Oct 2, 2020 1:48:00 PM
Down Time		

Work Order Notes

Line 10 Complaint: vehicle shut off while accelerating

Cause: bad throttle body

Correction: Replaced throttle body and spacer

Activity Header						
Activity:10 999/999/999 TOTAL VEHICLE						
Activity Note:						
Reason for Repair:		SW Shop Work Order				
Work Accomplished:		06 Inspect				
Part Failure:		00 No Failure				
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc:						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 02-OCT-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Oct 2, 2020 12:33:41 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Oct 2, 2020 12:33:41 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Oct 2, 2020 12:33:41 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Oct 2, 2020 12:33:41 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Oct 2, 2020 12:33:41 PM	No	
10 - Have you successfully completed the Personal	Done		TDELVA	Oct 2, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?				12:33:41 PM			
20 - Miles			TDELVA	Oct 2, 2020 12:33:41 PM	No		
30 - Kilometers			TDELVA	Oct 2, 2020 12:33:41 PM	No		
40 - Hours			TDELVA	Oct 2, 2020 12:33:41 PM	No		
Activity Sub Total							
				Activity 10 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53858939
Invoice No. 55345 - 53858939

Client Department:
Department: 55345M
Work Order Description
55345 THROTTLE BODY
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 241,580 - DH

Activity Header
Activity: 20 037 MODULES/RELAYS, ELECTRICAL
Activity Note: Throttle Body
Reason for Repair: 39 Natural Causes
Work Accomplished: 04 Replace Rebuilt
Part Failure: 44 Worn
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Sep-20	9C3Z-9E926-C	BODY, THROTTLE	1	262.39	262.39
10-Sep-20	DC2Z-9A589-A	SPACER, BODY, THROTTLE, E450	1	55.95	55.95

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-20	Delva, Terry	4.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 20 Sub Total	
Parts:	318.34
Labor:	0.00
Labor Hours:	4.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	318.34

Work Order Footer	
Work Order 53858939 Total	
Parts:	318.34
Labor:	0.00
Labor Hours:	4.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	318.34



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53838473
Invoice No. 55345 - 53838473

Client Department:

Department: 55345M

Work Order Description

PREPARE BUS FOR P.T.C ANNUAL INSPECTION.

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Assigned To:

Class: -

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 241,580 - DH

Chronology

Reported	Sep 2, 2020 10:06:45 AM	Sep 2, 2020 10:06:45 AM
Started	Sep 2, 2020 10:07:00 AM	
Completed	Sep 2, 2020 12:05:00 PM	Sep 2, 2020 12:05:00 PM
Down Time		

Work Order Notes

Line 10 PREPARE BUS FOR P.T.C ANNUAL INSPECTION.

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: PREPARE BUS FOR P.T.C ANNUAL INSPECTION.

Reason for Repair: 11 Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Sep-20	Rodriguez,Raul	1.35	0	0
02-Sep-20	Rodriguez,Raul	0.57	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.92
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53838473
Invoice No. 55345 - 53838473

Client Department:

Department: 55345M
Work Order Description
PREPARE BUS FOR P.T.C ANNUAL INSPECTION.
Requested By: RAURODRIGUEZ
Created By: RAURODRIGUEZ
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 241,580 - DH

Activity Header																																																																												
Activity:20 999/999/999 TOTAL VEHICLE																																																																												
Activity Note:																																																																												
Reason for Repair: SW Shop Work Order																																																																												
Work Accomplished: 06 Inspect																																																																												
Part Failure: 00 No Failure																																																																												
Activity Comments:																																																																												
Activity Parts																																																																												
No Data Available																																																																												
Activity Labor																																																																												
No Data Available																																																																												
Activity Sublet																																																																												
No Data Available																																																																												
Activity Checklist																																																																												
Check List 20 Desc: Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 02-SEP-20 <table border="1"><thead><tr><th>Inspection Item</th><th>RESULTS</th><th>Inspector's Note</th><th>Inspector</th><th>Date Inspected</th><th>Follow Up Needed</th><th>Follow Up WO</th></tr></thead><tbody><tr><td>1 - Are you properly trained to perform the task?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>2 - If task requires lifting, are lifts secured, are jack stands used correctly?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>3 - Are you wearing the appropriate PPE?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>4 - Have you performed the proper LOTO?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>5 - Are you aware of the potential risks of performing this repair?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>10 - Have you successfully completed the Personal Risk Assessment?</td><td>Done</td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>20 - Miles</td><td></td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>30 - Kilometers</td><td></td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr><tr><td>40 - Hours</td><td></td><td></td><td>RAURODRIGUEZ</td><td>Sep 2, 2020 12:04:42 PM</td><td>No</td><td></td></tr></tbody></table>							Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		20 - Miles			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		30 - Kilometers			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No		40 - Hours			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No	
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																																																																						
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
20 - Miles			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
30 - Kilometers			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
40 - Hours			RAURODRIGUEZ	Sep 2, 2020 12:04:42 PM	No																																																																							
Activity Sub Total																																																																												
				Activity 20 Sub Total																																																																								
				Parts: 0.00																																																																								
				Labor: 0.00																																																																								

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 53838473 Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.92
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53818725
Invoice No. 55345 - 53818725

Client Department:

Department: 55345M

Work Order Description

Check Rear A/C

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 241,578 - DH

Chronology

Reported	Aug 26, 2020 4:06:00 PM	Aug 26, 2020 4:06:00 PM
Started	Aug 26, 2020 4:09:00 PM	
Completed	Aug 26, 2020 11:00:00 PM	Aug 26, 2020 11:00:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Rear A/C

Cause: Pressure Relieve Valve Blown Off Pressure.

Correction: Evacuate A/C System found .Oil Over Charge. Flush condenser replace Orifice tube. Recharge A/C .found low Side high / High Side Normal .Compressor weak. Check Engine Light Came On.& Wrench Light Code PO103 VAF circuit high. Mass air flow pig tail was Loose. Connect pig tail wire all is Ok at this time Charge (6) Lb Freon add (4) Oz Oil.
Parts # 4311885 Qty (1)

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 26-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 26, 2020 10:09:27 PM	No	
20 - Miles			DARTHURS	Aug 26, 2020 10:09:27 PM	No	
30 - Kilometers			DARTHURS	Aug 26, 2020 10:09:27 PM	No	
40 - Hours			DARTHURS	Aug 26, 2020 10:09:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53818725
Invoice No. 55345 - 53818725

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check Rear A/C		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,578 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Check Rear A/C
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure: 51 Inoperative
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
28-Aug-20	26068C	MOUNTING, COMPRESSOR, A/C, TYPE-B W/KIT	1	424.74	424.74

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
26-Aug-20	Arthurs,Durvin	6.17	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	425.49
Labor:	0.00
Labor Hours:	6.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	425.49

Work Order Footer	
Work Order 53818725 Total	
Parts:	425.49
Labor:	0.00
Labor Hours:	6.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	425.49



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53811292
Invoice No. 55345 - 53811292

Client Department:

Department: 55345M

Work Order Description

DIAGNOSTICS

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 241,578 - DH

Chronology

Reported	Aug 24, 2020 1:47:00 PM	Aug 24, 2020 1:47:00 PM
Started	Aug 24, 2020 2:40:00 PM	
Completed	Aug 26, 2020 8:01:00 AM	Aug 26, 2020 8:01:00 AM
Down Time		

Work Order Notes

Line 10 C: Vehicle stalls while driving

C: Check computer system found no codes follow diagnostic test and road test vehicle, inspect all systems related to fuel and spark. replace PCM with a good used one, replace SRM and fuel control modules road test vehicle

C: at this time vehicle didn't die, replaced modules confirmed that all systems works ok at this time

Parts:

1 new SRM p13jc03p205ac

2 fuel pump modules aa8z-9d370-b

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: JAPERREZ Performed on: 26-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPERREZ	Aug 26, 2020 8:01:36 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPERREZ	Aug 26, 2020 8:01:36 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPERREZ	Aug 26, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:01:36 AM		
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Aug 26, 2020 8:01:36 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Aug 26, 2020 8:01:36 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Aug 26, 2020 8:01:36 AM	No	
20 - Miles			JAPEREZ	Aug 26, 2020 8:01:36 AM	No	
30 - Kilometers			JAPEREZ	Aug 26, 2020 8:01:36 AM	No	
40 - Hours			JAPEREZ	Aug 26, 2020 8:01:36 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53811292
Invoice No. 55345 - 53811292

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
DIAGNOSTICS		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,578 - DH

Activity Header

Activity:20 030 ELECTRICAL GROUP

Activity Note:

Reason for Repair: 04 Driver's Report

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Aug-20	P13JC03P205AC	MODULE, RELAY, SMART, PROPANE, ROUSH	1	472.31	472.31
26-Aug-20	AA8Z-9D370-B	MODULE, RELAY, PUMP, FUEL	2	39.02	78.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Aug-20	Perez,Javier	7.7	0	0
24-Aug-20	Perez,Javier	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total

Parts:	550.35
Labor:	0.00
Labor Hours:	9.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	550.35

Work Order Footer

Work Order 53811292 Total

Parts:	550.35
Labor:	0.00
Labor Hours:	9.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	550.35



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5



Work Order No. 53771210
Invoice No. 55345 - 53771210

Client Department:

Department: 55345M

Work Order Description

PER DRIVER VEHICLE STALLING.

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 241,303 - DH

Chronology

Reported	Aug 11, 2020 7:38:00 AM	Aug 11, 2020 7:38:00 AM
Started	Aug 11, 2020 7:41:00 AM	
Completed	Aug 18, 2020 9:35:00 PM	Aug 18, 2020 9:35:00 PM
Down Time		

Work Order Notes

Line 10 C: Vehicle is stalling

C: Check computer system and road test vehicle found battery light was on and cylinder 4 misfire. Also when rear a/c was on Freon came from compressor

C: Vehicle needs further tests Line 20 Complaint check engine light on

Cause p0304 Misfire

Correction replaced coil 23626, spark plug ap103, and vacuum hose need fixing.

SHarrington

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA

Task: PRA and Meter Readings Performed by: SHARRINGTON Performed on: 11-AUG-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
3 - Are you wearing the appropriate PPE?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
4 - Have you performed the proper LOTO?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
20 - Miles			SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
30 - Kilometers			SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	
40 - Hours			SHARRINGTON	Aug 11, 2020 6:32:07 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5



Work Order No. 53771210
Invoice No. 55345 - 53771210

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PER DRIVER VEHICLE STALLING.		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,303 - DH

Activity Header				
Activity:20				
Activity Note: VERIFY COMPLAINT				
Reason for Repair:				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-20	Perez,Javier	2.13	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	2.13
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order

55345 - Palm Tran Connection
v 3.0
Activity 3 of 5



Work Order No. 53771210
Invoice No. 55345 - 53771210

Client Department:

Department: 55345M

Work Order Description

PER DRIVER VEHICLE STALLING.

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty:	No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 241,303 - DH

Activity Header

Activity:30 040 ENGINE/MOTOR SYSTEMS GROUP

Activity Note: PER DRIVER BUS STALLING

Reason for Repair:	01 Breakdown

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total	

Activity 30 Sub Total

Parts:	0.00

Labor:	0.00

Labor Hours:	0.00


Sublet Parts:	0.00

Sublet Labor:	0.00

Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5



Work Order No. 53771210
Invoice No. 55345 - 53771210


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PER DRIVER VEHICLE STALLING.		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,303 - DH

Activity Header				
Activity:40 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: PER CLIENT REAR AC NOT WORKING PROPERLY				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-20	Rodriguez,Raul	1.02	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 40 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.02
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5



Work Order No. 53771210
Invoice No. 55345 - 53771210

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PER DRIVER VEHICLE STALLING.		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	241,303 - DH

Activity Header
Activity:50 030 ELECTRICAL GROUP
Activity Note: mysfire cylinder # 4 and battery light on
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Aug-20	AP103	PLUG, SPARK	1	3.17	3.17
11-Aug-20	26326	PLUG, COIL, IGNITION	1	28.12	28.12

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-20	Stephen Harrington	4.78	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 50 Sub Total	
Parts:	31.29
Labor:	0.00
Labor Hours:	4.78
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	31.29

Work Order Footer	
Work Order 53771210 Total	
Parts:	31.29
Labor:	0.00
Labor Hours:	7.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	31.29



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 53582664
Invoice No. 55345 - 53582664

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 238,440 - DH

Chronology

Reported	Jul 9, 2020 9:31:56 AM	Jul 9, 2020 9:31:56 AM
Started	Jul 9, 2020 9:00:00 PM	
Completed	Jul 10, 2020 12:22:00 AM	Jul 10, 2020 12:22:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service

Oil filter B329 qty1

Engine oil 10w30 qty 7 Qts

Activity Header

Activity:5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 09-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jul 9, 2020 8:59:54 PM	No	
20 - Miles			RGASPARD	Jul 9, 2020 8:59:54 PM	No	
30 - Kilometers			RGASPARD	Jul 9, 2020 8:59:54 PM	No	
40 - Hours			RGASPARD	Jul 9, 2020 8:59:54 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 53582664
Invoice No. 55345 - 53582664

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	238,440 - DH

Activity Header				
Activity:10 999/999/999 TOTAL VEHICLE				
Activity Note: Light Duty PMI				
Reason for Repair: 08 Preventive Maintenance				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Jul-20	Gaspard,Ronald	1.37	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.37
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 53582664
Invoice No. 55345 - 53582664

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	238,440 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Jul-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Jul-20	Gaspard,Ronald	0.28	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 09-JUL-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jul 9, 2020 10:24:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jul 9, 2020 10:24:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jul 9, 2020 10:24:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jul 9, 2020 10:24:01 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Jul 9, 2020 10:24:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jul 9, 2020 10:24:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jul 9, 2020 10:24:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jul 9, 2020 10:24:01 PM	No	

Activity Sub Total

		Activity 20 Sub Total	
		Parts:	1.96
		Labor:	0.00
		Labor Hours:	0.28
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 53582664
Invoice No. 55345 - 53582664

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 238,440 - DH

Activity Header

Activity: 30 055/023 LIFT, WHEELCHAIR, PASSENGER

Activity Note: 55345-W/C LIFT INSPECTION

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Jul-20	Gaspard,Ronald	0.47	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: 55345-W/C LIFT INSPECTION

Task: First Transit Wheelchair Lift Inspection Performed by: RGASPARD Performed on: 09-JUL-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Wheelchair Cycle Count	22961 Cycles		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
1,000 - A.1 Check Lift Access Door for Ease of Opening,Latch Security,Door Hold Back	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
2,000 - A.2 Check Platform Emergency Release Mechanism for Ease of Operation	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
3,000 - Operate Lift Through Complete Cycle and Check for:	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
3,003 - A.3 Unusual Noises	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
3,004 - A.4 Jerky Operation	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
3,005 - A.5 Operated Too Slowly or Too Fast	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
3,006 - A.6 Drift Down	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
7,000 - A.7 Check Bridgeplate Operation	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
8,000 - A.8 Check All Pivot Points for Wear and Looseness	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
9,000 - A.9 Check Rollers for Wear and Smooth Rotation	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
11,000 - A.11 Check Operation of Platform Barrier Mechanism	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
12,000 - A.12 Check Cam Slots for Wear and Proper Alignment	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
13,000 - A.13 Check Cable Condition (If Applicable)	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
14,000 - A.14 Check Hydraulic Hoses for Leaks, Chafing or Cracks	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
15,000 - A.15 Check Electrical Connections and Routing of Wires and Cables	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
16,000 - A.16 Check Operation and Adjustment of All Safety Switches	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
17,000 - A.17 Check All Lift Mounting Brackets for Loose Bolts Broken Welds, etc.	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
18,000 - A.18 Check the Manual Back-up Raise/Lower System (If Applicable)	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
19,000 - A.19 Check HydrPump Reservoir Oil Level. Consult SvcManual for Fluid to Use.	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
20,000 - A.20 Are Operator Decals in Place? Consult Service Manual for Information.	Yes		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
21,000 - A.21 Check WC Holdowns Inside Vehicle for Secure Mounting, Proper Operation	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
90,000 - Clean all Linkages and Mechanisms If Needed before Lubrication	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
91,000 - Lubricate (Don't OVER Lubricate)	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
100,000 - B.1 Emergency Platform Release Mechanism	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
200,000 - B.2 Platform Barrier Latch Mechanism	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
300,000 - B.3 Bridgeplate Hinge	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
400,000 - B.4 All Pivot Points	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
500,000 - B.5 Cams and Slots	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
600,000 - B.6 Rollers	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	
700,000 - B.7 All Linkages	Done		RGASPARD	Jul 9, 2020 10:42:22 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.47
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 53582664 Total	
Parts:	1.96

	Labor:	0.00
	Labor Hours:	2.12
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53627732
Invoice No. 55345 - 53627732

Client Department:

Department: 55345M

Work Order Description

55345 PER DVIR (Engine Code P0420 Cat)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 236,060 - DH

Chronology

Reported	Jun 17, 2020 12:32:00 AM	Jun 17, 2020 12:32:00 AM
Started	Jun 17, 2020 8:48:00 AM	
Completed	Jun 23, 2020 11:53:00 AM	Jun 23, 2020 11:53:00 AM
Down Time		

Work Order Notes

Line 10 Replaced catalyst and O2 Sensor

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 23-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 23, 2020 11:53:15 AM	No	
20 - Miles			TDELVA	Jun 23, 2020 11:53:15 AM	No	
30 - Kilometers			TDELVA	Jun 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				11:53:15 AM			
40 - Hours			TDELVA	Jun 23, 2020 11:53:15 AM	No		
Activity Sub Total							
				Activity 10 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53627732
Invoice No. 55345 - 53627732

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR (Engine Code P0420 Cat)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	236,060 - DH

Activity Header
Activity:20 043/000/000 EXHAUST SYSTEM
Activity Note: REPLACE CATALYTIC CONVERTER
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jun-20	9C2Z-5E212-E	CONVERTER, CATALYTIC	1	553.93	553.93
17-Jun-20	68093232AA	GASKET, CONVERTER, CATALYTIC, CARAVAN	1	9.21	9.21
17-Jun-20	GU2Z-9G444-A	SENSOR, OXYGEN, DOWNSTREAM	1	25.34	25.34
17-Jun-20	DY1401	SENSOR, OXYGEN, DOWNSTREAM	1	24.25	24.25
17-Jun-20	DY1401	SENSOR, OXYGEN, DOWNSTREAM	-1	24.25	-24.25

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
17-Jun-20	Delva,Terry	4.62	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:	588.48	Labor:	0.00
Labor Hours:	4.62	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		588.48	

Work Order Footer		Work Order 53627732 Total	
Parts:	588.48	Labor:	0.00
Labor Hours:	4.62	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		588.48	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53624965
Invoice No. 55345 - 53624965

Client Department:

Department: 55345M

Work Order Description
55345 SAFETY EQUIPMENT

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 235,898 - DH

Chronology

Reported	Jun 16, 2020 6:52:00 AM	Jun 16, 2020 6:52:00 AM
Started	Jun 16, 2020 6:54:00 AM	
Completed	Jun 16, 2020 8:08:00 AM	Jun 16, 2020 8:08:00 AM
Down Time		

Work Order Notes

Line 10 Complaint. Angel track camera # 2 is not working

Cause. Perform test and found defective audio video board

Correction. Removed and replaced board, all okay at this time.

Parts. Provide by vendor.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 16-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
20 - Miles			RAURODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
30 - Kilometers			RAURODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	
40 - Hours			RAURODRIGUEZ	Jun 16, 2020 8:03:34 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53624965
Invoice No. 55345 - 53624965

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 SAFETY EQUIPMENT		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	235,898 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Jun-20	Rodriguez,Raul	1.12	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.12
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 53624965 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.12
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53610482
Invoice No. 55345 - 53610482

Client Department:

Department: 55345M

Work Order Description

55345 PER DVIR (Replace Wheel Chair Lift Lights)

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 235,351 - DH

Chronology

Reported	Jun 9, 2020 10:33:00 PM	Jun 9, 2020 10:33:00 PM
Started	Jun 9, 2020 10:43:00 PM	
Completed	Jun 9, 2020 11:24:00 PM	Jun 9, 2020 11:24:00 PM
Down Time		

Work Order Notes

Line 10 Check Lift light. Found light blown . Remove & Replace Lift Light
Parts#37968 Qty (1)

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PRA

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PRA

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-JUN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jun 9, 2020 11:17:04 PM	No	
20 - Miles			DARTHURS	Jun 9, 2020 11:17:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
30 - Kilometers			DARTHURS	Jun 9, 2020 11:17:04 PM	No		
40 - Hours			DARTHURS	Jun 9, 2020 11:17:04 PM	No		
Activity Sub Total							
				Activity 10 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53610482
Invoice No. 55345 - 53610482

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR (Replace Wheel Chair Lift Lights)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	235,351 - DH

Activity Header				
Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING				
Activity Note: VERIFY COMPLAINT (Wheel Chair Lift Light)				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished: 03 Replace New				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Jun-20	Arthurs,Durvin	0.2	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.20
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53610482
Invoice No. 55345 - 53610482

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 PER DVIR (Replace Wheel Chair Lift Lights)		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	235,351 - DH

Activity Header
Activity:30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Replace Wheel Chair Lift Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Jun-20	Arthurs,Durvin	0.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 30 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.33</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Activity 30 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.33	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00	
Activity 30 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.33														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53610482 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.53</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Work Order 53610482 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.53	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00	
Work Order 53610482 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.53														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53582521
Invoice No. 55345 - 53582521

Client Department:

Department: 55345M

Work Order Description

FOLLOWUP-->Replace Front Brakes and Front Tires

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 234,229 - DH

Chronology

Reported	May 28, 2020 9:23:14 PM	May 28, 2020 9:23:14 PM
Started	May 28, 2020 9:30:00 PM	
Completed	May 29, 2020 12:17:00 AM	May 29, 2020 12:17:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint:needs 2 front tires and front brakes job

Cause: tires wear and brakes low spec and needs right front caliper bracket

Correction: replaced tires mounted and balanced .

Replaced front brake pads, caliper bracket and sliding pins

Tires part number: 192659 qty2.

Brakes part number: 8C2Z-2V001-D qty1

Bracket part number:141096 qty1

Pins part number:8C2Z-2C150-C qty1

Torque wheels 140 lbs second torque 140 lbs

Activity Header

Activity:10 017/003/001 TIRE, CUSHION W/TREAD

Activity Note: needs 2 front tires

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-May-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	117.62	235.24

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended	
28-May-20	Gaspard,Ronald	0.87	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:		235.24
			Labor:		0.00
			Labor Hours:		0.87
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		235.24



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53582521
Invoice No. 55345 - 53582521

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-->Replace Front Brakes and Front Tires		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	234,229 - DH

Activity Header
Activity:20 013/002/012 SHOE & LINING, BRAKE, REAR
Activity Note: needs front brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-May-20	141096	BRACKET, CALIPER, BRAKE, DISC, FRONT, LH, FORD	-1	34.44	-34.44
28-May-20	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	1	9.61	9.61
28-May-20	141096	BRACKET, CALIPER, BRAKE, DISC, FRONT, LH, FORD	1	34.44	34.44
28-May-20	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	44.09	44.09

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-May-20	Gaspard,Ronald	0.93	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 20 Sub Total	
Parts:	88.14
Labor:	0.00
Labor Hours:	0.93
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	88.14

Work Order Footer	
Work Order 53582521 Total	
Parts:	323.38
Labor:	0.00
Labor Hours:	1.80
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	323.38



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 53558502
Invoice No. 55345 - 53558502

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: NSTOLFO

Created By: NSTOLFO

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 234,229 - DH

Chronology

Reported	May 28, 2020 10:46:18 AM	May 28, 2020 10:46:18 AM
Started	May 28, 2020 7:09:00 PM	
Completed	May 29, 2020 12:16:00 AM	May 29, 2020 12:16:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service

Oil filter B329 qty1

Engine oil 10w30 qty 7 Qts

Activity Header

Activity: 5 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESSMENT

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PERSONAL RISK ASSESSMENT


Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 28-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 28, 2020 7:09:32 PM	No	
20 - Miles			RGASPARD	May 28, 2020 7:09:32 PM	No	
30 - Kilometers			RGASPARD	May 28, 2020 7:09:32 PM	No	
40 - Hours			RGASPARD	May 28, 2020 7:09:32 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 53558502
Invoice No. 55345 - 53558502

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	40 - Closed (40)
Created By:	NSTOLFO	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	234,229 - DH

Activity Header				
Activity:10 999/999/999 TOTAL VEHICLE				
Activity Note: Light Duty PMI				
Reason for Repair: 08 Preventive Maintenance				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-May-20	Gaspard,Ronald	1.55	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.55
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 53558502
Invoice No. 55345 - 53558502

Client Department:

Department: 55345M

Work Order Description

55345-LIGHT DUTY PMA

Requested By: NSTOLFO

Created By: NSTOLFO

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 234,229 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-May-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-May-20	Gaspard,Ronald	0.2	0	0
28-May-20	Gaspard,Ronald	0.28	0	0

Activity Sublet

No Data Available


Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 28-MAY-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	May 28, 2020 8:43:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	May 28, 2020 8:43:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	May 28, 2020 8:43:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	May 28, 2020 8:43:37 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	May 28, 2020 8:43:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	May 28, 2020 8:43:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	May 28, 2020 8:43:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	May 28, 2020 8:43:37 PM	No	

Activity Sub Total	
Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	0.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 53558502
Invoice No. 55345 - 53558502

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345-LIGHT DUTY PMA		Ford E450 Champion Challenger	
Requested By:	NSTOLFO	Status:	40 - Closed (40)
Created By:	NSTOLFO	Priority:	3 - High
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	234,229 - DH

Activity Header															
Activity: 30 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING															
Activity Note: 55345-W/C LIFT INSPECTION															
Reason for Repair:	05 Inspection, Routine														
Work Accomplished:	03 Replace New														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 30 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 30 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 30 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 53558502 Total</td></tr><tr><td>Parts:</td><td>1.96</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>2.03</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>1.96</td></tr></table>		Work Order 53558502 Total		Parts:	1.96	Labor:	0.00	Labor Hours:	2.03	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	1.96
Work Order 53558502 Total															
Parts:	1.96														
Labor:	0.00														
Labor Hours:	2.03														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	1.96														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53571040
Invoice No. 55345 - 53571040

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Needs 4 rear tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	233,779 - DH

Chronology		
Reported	May 22, 2020 9:24:32 PM	May 22, 2020 9:24:32 PM
Started	May 22, 2020 9:26:00 PM	
Completed	May 22, 2020 11:00:00 PM	May 22, 2020 11:00:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:needs 4 rear tires

Cause: wear

Correction: 4 new tires mounted and balanced
Torque wheels 140 lbs second torque 140 lbs
Part number 192659 qty 2

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 22, 2020 9:26:39 PM	No	
20 - Miles			RGASPARD	May 22, 2020 9:26:39 PM	No	
30 - Kilometers			RGASPARD	May 22, 2020 9:26:39 PM	No	
40 - Hours			RGASPARD	May 22, 2020 9:26:39 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53571040
Invoice No. 55345 - 53571040

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Needs 4 rear tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	233,779 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Needs 4 rear tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-May-20	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	117.62	470.48

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-20	Gaspard,Ronald	1.57	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			470.48
Labor:			0.00
Labor Hours:			1.57
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			470.48

Work Order Footer		Work Order 53571040 Total	
Parts:			470.48
Labor:			0.00
Labor Hours:			1.57
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			470.48



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53570762
Invoice No. 55345 - 53570762

Client Department:

Department: 55345M

Work Order Description

Needs wiper blades

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 233,779 - DH

Chronology

Reported	May 22, 2020 4:26:09 PM	May 22, 2020 4:26:09 PM
Started	May 22, 2020 4:28:00 PM	
Completed	May 22, 2020 4:47:00 PM	May 22, 2020 4:47:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: needs wiper blades

Cause: bad

Correction: replaced wiper blades

Part number #20 qty2

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-MAY-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	May 22, 2020 4:28:10 PM	No	
20 - Miles			RGASPARD	May 22, 2020 4:28:10 PM	No	
30 - Kilometers			RGASPARD	May 22, 2020 4:28:10 PM	No	
40 - Hours			RGASPARD	May 22, 2020 4:28:10 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53570762
Invoice No. 55345 - 53570762

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Needs wiper blades		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	233,779 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Needs wiper blades
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Jun-20	40520	BLADE, WIPER, WINDSHIELD, 20"	2	4.16	8.32

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-20	Gaspard,Ronald	0.28	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	8.32
		Labor:	0.00
		Labor Hours:	0.28
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	8.32

Work Order Footer		Work Order 53570762 Total	
		Parts:	8.32
		Labor:	0.00
		Labor Hours:	0.28
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	8.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53477831
Invoice No. 55345 - 53477831

Client Department:

Department: 55345M

Work Order Description

Rear A/C

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 230,239 - DH

Chronology

Reported	Apr 14, 2020 3:57:42 PM	Apr 14, 2020 3:57:42 PM
Started	Apr 14, 2020 3:59:00 PM	
Completed	Apr 14, 2020 11:08:00 PM	Apr 14, 2020 11:08:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Rear A/C

Cause: High Pressure Hose Leaking.

Correction: Remove High Pressure Hose from Compressor . To service valve try to charge & hose from service valve to condenser burst. Replace hose from service valve to condenser .add (4) Oz Oil & charge (7) lbs Freon.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment


Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Apr 14, 2020 4:00:47 PM	No	
20 - Miles			DARTHURS	Apr 14, 2020 4:00:47 PM	No	
30 - Kilometers			DARTHURS	Apr 14, 2020 4:00:47 PM	No	
40 - Hours			DARTHURS	Apr 14, 2020 4:00:47 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53477831
Invoice No. 55345 - 53477831

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,239 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Rear A/C blown hot air.				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Apr-20	Arthurs,Durvin	4.97	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	4.97
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 53477831 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	4.97
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53473628
Invoice No. 55345 - 53473628

Client Department:

Department: 55345M

Work Order Description

Coils / spark plugs

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 230,209 - DH

Chronology

Reported	Apr 13, 2020 1:20:40 PM	Apr 13, 2020 1:20:40 PM
Started	Apr 13, 2020 1:26:00 PM	
Completed	Apr 13, 2020 7:25:00 PM	Apr 13, 2020 7:25:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle came in for tuneup

Cause: Time for service

Correction: Removed all ten spark plugs on replace new parts # AP 103 also tree coils boots # F7TZ-12A402-AA
AFTER check vehicle complete take unit for road test vehicle now working as design return vehicle back to work

Please charge out the coil boot for me can't fine F7TZ-12A402-AA

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 13-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 13, 2020 7:18:35 PM	No	
20 - Miles			JUHURST	Apr 13, 2020 7:18:35 PM	No	
30 - Kilometers			JUHURST	Apr 13, 2020 7:18:35 PM	No	
40 - Hours			JUHURST	Apr 13, 2020 7:18:35 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53473628
Invoice No. 55345 - 53473628

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Coils / spark plugs		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,209 - DH

Activity Header
Activity: 15 032/000/000 CRANKING
Activity Note: Engine tuneup
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Apr-20	AP103	PLUG, SPARK	10	3.15	31.5
14-Apr-20	357006	BOOT, COIL-ON-PLUG, IGNITION	10	4.36	43.6

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Apr-20	Junior Hurst	5.87	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	75.10
Labor:	0.00
Labor Hours:	5.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	75.10

Work Order Footer	
Work Order 53473628 Total	
Parts:	75.10
Labor:	0.00
Labor Hours:	5.87
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	75.10



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53465939
Invoice No. 55345 - 53465939

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,185 - DH

Chronology

Reported	Apr 10, 2020 9:28:44 AM	Apr 10, 2020 9:28:44 AM
Started	Apr 10, 2020 9:32:00 AM	
Completed	Apr 10, 2020 1:16:00 PM	Apr 10, 2020 1:16:00 PM
Down Time		

Work Order Notes

Line 10 PMC follow up need rear brakes pads

Normal wear

Replace rear brake pads completed

Activity Header

Activity:10 013/002/012 SHOE & LINING, BRAKE, REAR

Activity Note: need rear brake pads

Reason for Repair:

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53465939
Invoice No. 55345 - 53465939

Client Department:
Department: 55345M
Work Order Description
FOLLOWUP-FT Light Duty
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 3 - High
Driver:
Phone:
ETA:
Meter: 230,185 - DH

Activity Header
Activity:20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-20	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Apr-20	Pierre,Hubert J	3.7	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	3.70	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	47.81

Work Order Footer		Work Order 53465939 Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	3.70	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	47.81



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53340379
Invoice No. 55345 - 53340379

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 230,185 - DH

Chronology

Reported	Apr 9, 2020 4:07:16 PM	Apr 9, 2020 4:07:16 PM
Started		
Completed	Apr 10, 2020 9:31:00 AM	Apr 10, 2020 9:31:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service lube all pivoting point cross rotate tires completed

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available


Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53340379
Invoice No. 55345 - 53340379

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,185 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM C
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Apr-20	P7398	FILTER, OIL	1	1.41	1.41

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
20 Desc: PM C Task: PM C SERVICE Performed by: HPIERRE Performed on: 10-APR-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Apr 10, 2020 9:14:07 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Apr 10, 2020 9:14:07 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Apr 10, 2020 9:14:07 AM	No	
305,000 - FRA Change Differential Fluid	Yes		HPIERRE	Apr 10, 2020 9:14:07 AM	No	


Activity Sub Total

Activity 20 Sub Total

Parts:	1.41
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.41



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53340379
Invoice No. 55345 - 53340379

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,185 - DH

Activity Header						
Activity:30 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair:		05 Inspection, Routine				
Work Accomplished:		06 Inspect				
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 10-APR-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
20 - Miles			HPIERRE	Apr 10, 2020 9:15:18 AM	No	
30 - Kilometers	12		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
40 - Hours	6		HPIERRE	Apr 10, 2020 9:15:18 AM	No	
Activity Sub Total						
				Activity 30 Sub Total		
Parts:				0.00		
Labor:				0.00		

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 53340379 Total	
	Parts:	1.41
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.41



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53462463
Invoice No. 55345 - 53462463

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear ac maintenance sevice		Ford E450 Champion Challenger	
Requested By:	RAUODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAUODRIGUEZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,104 - DH

Chronology		
Reported	Apr 9, 2020 7:20:59 AM	Apr 9, 2020 7:20:59 AM
Started	Apr 9, 2020 7:32:00 AM	
Completed	Apr 9, 2020 10:04:00 AM	Apr 9, 2020 10:04:00 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

=====

Rear a/c

Complaint:Rear a/c

Cause: Rear a/c maintenance pre season

Correction:recovered and re charged with 7 lbs of Freon - 6 oz page Oil, Replaced Orifice tube .

Part. 1 Orifice tube.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist

Check List																				
5 Desc: Personal Risk Assessment																				
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 09-APR-20																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
20 - Miles			RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
30 - Kilometers			RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
40 - Hours			RAURODRIGUEZ	Apr 9, 2020 7:31:43 AM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 5 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>0.00</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.00</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>0.00</td> </tr> </tbody> </table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53462463
Invoice No. 55345 - 53462463

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear ac maintenance sevice		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	230,104 - DH

Activity Header
Activity:15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Rear ac
Reason for Repair: 11 Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Apr-20	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Apr-20	Rodriguez,Raul	2.37	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.75

Work Order Footer	
Work Order 53462463 Total	
Parts:	0.75
Labor:	0.00
Labor Hours:	2.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53440938
Invoice No. 55345 - 53440938

Client Department:

Department: 55345M

Work Order Description

Lift

Requested By: JUHURST

Created By: JUHURST

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 229,762 - DH

Chronology

Reported	Apr 3, 2020 12:34:55 PM	Apr 3, 2020 12:34:55 PM
Started	Apr 3, 2020 12:37:00 PM	
Completed	Apr 3, 2020 1:52:00 PM	Apr 3, 2020 1:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle came in for lift issue

Cause: loose power cable

Correction: retighten power cable also service lift no working as design check vehicle complete on return vehicle back to work. Replace one. One Battery terminal to unit no part #

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JUHURST Performed on: 03-APR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
4 - Have you performed the proper LOTO?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JUHURST	Apr 3, 2020 1:51:35 PM	No	
20 - Miles			JUHURST	Apr 3, 2020 1:51:35 PM	No	
30 - Kilometers			JUHURST	Apr 3, 2020 1:51:35 PM	No	
40 - Hours			JUHURST	Apr 3, 2020 1:51:35 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53440938
Invoice No. 55345 - 53440938

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Lift		Ford E450 Champion Challenger	
Requested By:	JUHURST	Status:	40 - Closed (40)
Created By:	JUHURST	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	229,762 - DH

Activity Header
Activity: 15 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
03-Apr-20	Junior Hurst	1.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	1.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00	
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	1.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53440938 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Work Order 53440938 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	1.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00	
Work Order 53440938 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	1.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53394346
Invoice No. 55345 - 53394346

Client Department:

Department: 55345M

Work Order Description

Check engine light illuminated.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 228,334 - DH

Chronology

Reported	Mar 17, 2020 8:32:00 PM	Mar 17, 2020 8:32:00 PM
Started	Mar 17, 2020 8:33:00 PM	
Completed	Mar 23, 2020 5:21:00 PM	Mar 23, 2020 5:21:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Check engine light illuminated.

Cause: Lean code (air cleaner bung unplugged).

Correction: Resecured air cleaner bung and cleared codes.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 23-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
2 - If task requires lifting, are lifts secured, are	Done		EARJOHNSON	Mar 23, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
jack stands used correctly?				4:47:40 PM		
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
20 - Miles			EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
30 - Kilometers			EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	
40 - Hours			EARJOHNSON	Mar 23, 2020 4:47:40 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53394346
Invoice No. 55345 - 53394346

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check engine light illuminated.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	228,334 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Check engine light illuminated.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
18-Mar-20	Earl Johnson	0.1	0	0
17-Mar-20	Earl Johnson	3.45	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 53394346 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	3.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53364142
Invoice No. 55345 - 53364142

Client Department:

Department: 55345M

Work Order Description

TBD.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 227,146 - DH

Chronology

Reported	Mar 8, 2020 3:28:47 PM	Mar 8, 2020 3:28:47 PM
Started	Mar 8, 2020 3:29:00 PM	
Completed	Mar 10, 2020 12:13:00 AM	Mar 10, 2020 12:13:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Rear ac malfunction.

Cause: Rear ac compressor seized.

Correction: Remove and replaced rear ac compressor and Accumulator.

Part# 8025005 Qty. (1). 27059875A Qty.(.).

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 09-MAR-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
20 - Miles			EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
30 - Kilometers			EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	
40 - Hours			EARJOHNSON	Mar 9, 2020 11:32:27 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53364142
Invoice No. 55345 - 53364142

Client Department:

Department: 55345M

Work Order Description

TBD.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 227,146 - DH

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: ROAD CALL

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Mar-20	Earl Johnson	2.1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	2.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53364142
Invoice No. 55345 - 53364142

Client Department:

Department: 55345M

Work Order Description

TBD.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WORC - WORK ORDER ROAD CALL

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 3 - High

Driver:

Phone:

ETA:

Meter: 227,146 - DH

Activity Header

Activity:20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION

Activity Note: Rear ac compressor siezed.

Reason for Repair: 04 Driver's Report

Work Accomplished: 03 Replace New

Part Failure: 51 Inoperative

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Mar-20	8025005	COMPRESSOR, A/C, TM21	1	279.73	279.73
09-Mar-20	27059875A	ACCUMULATOR, A/C	1	65.13	65.13

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Mar-20	Earl Johnson	7.28	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	344.86
Labor:	0.00
Labor Hours:	7.28
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	344.86

Work Order Footer

Work Order 53364142 Total	
Parts:	344.86
Labor:	0.00
Labor Hours:	9.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	344.86



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53235269
Invoice No. 55345 - 53235269

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 226,297 - DH

Chronology

Reported	Mar 2, 2020 7:54:29 AM	Mar 2, 2020 7:54:29 AM
Started	Mar 2, 2020 8:25:00 AM	
Completed	Mar 2, 2020 10:44:00 AM	Mar 2, 2020 10:44:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53235269
Invoice No. 55345 - 53235269

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	226,297 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Mar-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
02-Mar-20	Pierre,Hubert J	1.85	0	0
02-Mar-20	Pierre,Hubert J	0.43	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: HPIERRE Performed on: 02-MAR-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Mar 2, 2020 8:44:23 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Mar 2, 2020 8:44:23 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Mar 2, 2020 8:44:23 AM	No	

Activity Sub Total															
	<table> <tr> <td colspan="2">Activity 20 Sub Total</td></tr> <tr> <td>Parts:</td><td>1.96</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>2.28</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>1.96</td></tr> </table>	Activity 20 Sub Total		Parts:	1.96	Labor:	0.00	Labor Hours:	2.28	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	1.96
Activity 20 Sub Total															
Parts:	1.96														
Labor:	0.00														
Labor Hours:	2.28														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	1.96														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53235269
Invoice No. 55345 - 53235269

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	226,297 - DH

Activity Header						
Activity:30 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 02-MAR-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
20 - Miles			HPIERRE	Mar 2, 2020 8:45:17 AM	No	
30 - Kilometers	2		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
40 - Hours	8		HPIERRE	Mar 2, 2020 8:45:17 AM	No	
Activity Sub Total						
				Activity 30 Sub Total		
Parts:				0.00		
Labor:				0.00		

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 53235269 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.28
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53283821
Invoice No. 55345 - 53283821

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	223,968 - DH

Chronology

Reported	Feb 14, 2020 7:48:26 AM	Feb 14, 2020 7:48:26 AM
Started	Feb 14, 2020 7:49:00 AM	
Completed	Feb 14, 2020 1:51:00 PM	Feb 14, 2020 1:51:00 PM
Down Time		

Work Order Notes

Line 10 Complaint. Lift isn't working properly

Cause. W/C lift ramp is bent

Correction. Removed and replaced ramp and inner barrier shocks.

Parts shop supply

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 14-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
20 - Miles			RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
30 - Kilometers			RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	
40 - Hours			RAURODRIGUEZ	Feb 14, 2020 7:49:44 AM	No	


Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53283821
Invoice No. 55345 - 53283821

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Wheelchair Lift		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	223,968 - DH

Activity Header
Activity:20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING
Activity Note: WheelChair Lift
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Feb-20	Rodriguez,Raul	6.02	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:	0.00	Labor:	0.00
Labor Hours:	6.02	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		0.00	

Work Order Footer		Work Order 53283821 Total	
Parts:	0.00	Labor:	0.00
Labor Hours:	6.02	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53263816
Invoice No. 55345 - 53263816

Client Department:

Department: 55345M

Work Order Description

Passenger window latch.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 223,393 - DH

Chronology

Reported	Feb 9, 2020 2:51:41 PM	Feb 9, 2020 2:51:41 PM
Started	Feb 9, 2020 2:56:00 PM	
Completed	Feb 9, 2020 3:31:00 PM	Feb 9, 2020 3:31:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: RF rear passenger window latch missing.

Cause: TBD.

Correction: Reinstalled window latch.

Part# 1017076. Qty. (1).

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-20	Earl Johnson	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 09-FEB-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
20 - Miles			EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
30 - Kilometers			EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	
40 - Hours			EARJOHNSON	Feb 9, 2020 3:31:14 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53263816
Invoice No. 55345 - 53263816

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Passenger window latch.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	223,393 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Passenger window latch.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Feb-20	1017076	HANDLE, WINDOW, SLIDER, CHAMPION	1	22.22	22.22

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Feb-20	Earl Johnson	0.5	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>22.22</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>22.22</td></tr></table>	Activity 15 Sub Total		Parts:	22.22	Labor:	0.00	Labor Hours:	0.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	22.22	
Activity 15 Sub Total															
Parts:	22.22														
Labor:	0.00														
Labor Hours:	0.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	22.22														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53263816 Total</th></tr><tr><td>Parts:</td><td>22.22</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.58</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>22.22</td></tr></table>	Work Order 53263816 Total		Parts:	22.22	Labor:	0.00	Labor Hours:	0.58	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	22.22	
Work Order 53263816 Total															
Parts:	22.22														
Labor:	0.00														
Labor Hours:	0.58														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	22.22														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53258829
Invoice No. 55345 - 53258829

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Washer fluid empty.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	223,017 - DH

Chronology		
Reported	Feb 6, 2020 8:30:12 PM	Feb 6, 2020 8:30:12 PM
Started	Feb 6, 2020 8:36:00 PM	
Completed	Feb 6, 2020 10:19:00 PM	Feb 6, 2020 10:19:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint: Windshield washer fluid.

Cause: Empty.

Correction: Refilled washer fluid to spec.

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: SW Shop Work Order						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
06-Feb-20	Earl Johnson	0.0833333	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 06-FEB-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Feb 6, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:09:16 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
20 - Miles			EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
30 - Kilometers			EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	
40 - Hours			EARJOHNSON	Feb 6, 2020 9:09:16 PM	No	


Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53258829
Invoice No. 55345 - 53258829

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Washer fluid empty.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	223,017 - DH

Activity Header				
Activity: 15 050 GROUP, ACCESSORIES				
Activity Note: Washer fluid empty.				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished: 03 Replace New				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Feb-20	Earl Johnson	0.43	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.43
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 53258829 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.51
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53234104
Invoice No. 55345 - 53234104

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	222,027 - DH

Chronology		
Reported	Jan 30, 2020 1:53:19 PM	Jan 30, 2020 1:53:19 PM
Started	Jan 30, 2020 1:54:00 PM	
Completed	Jan 30, 2020 7:10:00 PM	Jan 30, 2020 7:10:00 PM
Down Time		


Work Order Notes

Line 10 Passenger side ball joints have play
Normal wear
Replaced upper and lower ball joints

Activity Header				
Activity: 10 016/000/000 SUSPENSION				
Activity Note: right side upper ball joint				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
30-Jan-20	AMRIT TEEMAL,VISHNU	1.85	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.85
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53234104
Invoice No. 55345 - 53234104

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP-FT Light Duty		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	3 - High
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	222,027 - DH

Activity Header

Activity: 20 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jan-20	8C3Z-3049-B	JOINT, BALL, UPPER	1	40.46	40.46
30-Jan-20	8C2Z-3050-A	JOINT, BALL, LOWER	1	42.5	42.5

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 30-JAN-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 30, 2020 7:10:23 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	82.96
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	82.96
Work Order Footer		
	Work Order 53234104 Total	
	Parts:	82.96
	Labor:	0.00
	Labor Hours:	1.85
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	82.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53126088
Invoice No. 55345 - 53126088

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 222,027 - DH

Chronology

Reported	Jan 30, 2020 11:03:02 AM	Jan 30, 2020 11:03:02 AM
Started	Jan 30, 2020 12:03:00 PM	
Completed	Jan 30, 2020 7:05:00 PM	Jan 30, 2020 7:05:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE
REPLACED AIR FILTER

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: Light Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jan-20	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53126088
Invoice No. 55345 - 53126088

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 222,027 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jan-20	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28
30-Jan-20	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jan-20	AMRIT TEEMAL,VISHNU	0.27	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 30-JAN-20						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Jan 30, 2020 7:04:49 PM	No	

Activity Sub Total															
	<table> <tr> <td colspan="2">Activity 20 Sub Total</td></tr> <tr> <td>Parts:</td><td>7.24</td></tr> <tr> <td>Labor:</td><td>0.00</td></tr> <tr> <td>Labor Hours:</td><td>0.27</td></tr> <tr> <td>Sublet Parts:</td><td>0.00</td></tr> <tr> <td>Sublet Labor:</td><td>0.00</td></tr> <tr> <td>Activity Sub Total</td><td>7.24</td></tr> </table>	Activity 20 Sub Total		Parts:	7.24	Labor:	0.00	Labor Hours:	0.27	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	7.24
Activity 20 Sub Total															
Parts:	7.24														
Labor:	0.00														
Labor Hours:	0.27														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	7.24														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53126088
Invoice No. 55345 - 53126088

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	222,027 - DH

Activity Header

Activity:30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 30-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 30, 2020 7:05:12 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts: 0.00

Labor: 0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 53126088 Total	
	Parts:	7.24
	Labor:	0.00
	Labor Hours:	1.77
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.24



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 53214992
Invoice No. 55345 - 53214992

Client Department:

Department: 55345M

Work Order Description

Camera

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 221,205 - DH

Chronology

Reported	Jan 25, 2020 7:35:21 AM	Jan 25, 2020 7:35:21 AM
Started	Jan 25, 2020 7:36:00 AM	
Completed	Jan 30, 2020 8:59:00 AM	Jan 30, 2020 8:59:00 AM
Down Time		

Work Order Notes

Line 10 Checking the camera system for issues

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-20	Delva,Terry	1.07	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 30-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 30, 2020 8:59:05 AM	No	
20 - Miles			TDELVA	Jan 30, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				8:59:05 AM		
30 - Kilometers			TDELVA	Jan 30, 2020 8:59:05 AM	No	
40 - Hours			TDELVA	Jan 30, 2020 8:59:05 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			1.07
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00
Work Order Footer						
			Work Order 53214992 Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			1.07
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53216181
Invoice No. 55345 - 53216181

Client Department:

Department: 55345M

Work Order Description

Parking brake not holding.

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 221,402 - DH

Chronology

Reported	Jan 26, 2020 1:55:45 PM	Jan 26, 2020 1:55:45 PM
Started	Jan 26, 2020 1:59:00 PM	
Completed	Jan 26, 2020 3:20:00 PM	Jan 26, 2020 3:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Parking Brake not holding.

Cause: Wear and tear.

Correction: Adjusted parking brake.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-20	Earl Johnson	0.1166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EARJOHNSON Performed on: 26-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		EARJOHNSON	Jan 26, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:19:06 PM		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
3 - Are you wearing the appropriate PPE?	Done		EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
4 - Have you performed the proper LOTO?	Done		EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
20 - Miles			EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
30 - Kilometers			EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	
40 - Hours			EARJOHNSON	Jan 26, 2020 3:19:06 PM	No	


Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53216181
Invoice No. 55345 - 53216181

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Parkinhg brake not holding.		Ford E450 Champion Challenger	
Requested By:	EARJOHNSON	Status:	40 - Closed (40)
Created By:	EARJOHNSON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	221,402 - DH

Activity Header
Activity:15 013 BRAKES
Activity Note: Parking brake not holding.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
26-Jan-20	Earl Johnson	1.33	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.33
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 53216181 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.45
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53172492
Invoice No. 55345 - 53172492

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Bus need tires		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	219,426 - DH

Chronology

Reported	Jan 13, 2020 10:19:44 AM	Jan 13, 2020 10:19:44 AM
Started	Jan 13, 2020 10:26:00 AM	
Completed	Jan 13, 2020 1:41:00 PM	Jan 13, 2020 1:41:00 PM
Down Time		

Work Order Notes

Line 10 Need tires

Preventive maintenance

Replaced and mounted 6 tire completed

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 13-JAN-20

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jan 13, 2020 12:20:24 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jan 13, 2020 12:20:24 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jan 13, 2020 12:20:24 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jan 13, 2020 12:20:24 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jan 13, 2020 12:20:24 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Jan 13, 2020	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Risk Assessment?				12:20:24 PM			
20 - Miles	219813		HPIERRE	Jan 13, 2020 12:20:24 PM	No		
30 - Kilometers	2		HPIERRE	Jan 13, 2020 12:20:24 PM	No		
40 - Hours	6		HPIERRE	Jan 13, 2020 12:20:24 PM	No		
Activity Sub Total							
				Activity 10 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53172492
Invoice No. 55345 - 53172492

Client Department:
Department: 55345M
Work Order Description
Bus need tires
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 219,426 - DH

Activity Header
Activity: 20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-20	002760	TIRE, 225/75R16, 10-PLY, BSW, HT2, TRANSFORCE, FIRESTONE	6	105.65	633.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Jan-20	Pierre, Hubert J	3.23	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 20 Sub Total</th></tr><tr><td>Parts:</td><td>633.90</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>633.90</td></tr></table>		Activity 20 Sub Total		Parts:	633.90	Labor:	0.00	Labor Hours:	3.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	633.90
Activity 20 Sub Total															
Parts:	633.90														
Labor:	0.00														
Labor Hours:	3.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	633.90														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53172492 Total</th></tr><tr><td>Parts:</td><td>633.90</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>633.90</td></tr></table>		Work Order 53172492 Total		Parts:	633.90	Labor:	0.00	Labor Hours:	3.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	633.90
Work Order 53172492 Total															
Parts:	633.90														
Labor:	0.00														
Labor Hours:	3.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	633.90														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53134996
Invoice No. 55345 - 53134996

Client Department:

Department: 55345M

Work Order Description

Stalling while driving

Requested By: JAPEREZ

Created By: JAPEREZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 218,200 - DH

Chronology

Reported	Dec 30, 2019 8:47:24 AM	Dec 30, 2019 8:47:24 AM
Started	Dec 30, 2019 8:49:00 AM	
Completed	Dec 30, 2019 11:57:00 AM	Dec 30, 2019 11:57:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:stalling while driving

Cause: Check computer system found P0148,P0300-01-02-04-09,P0316 and p2632 Performed fuel pressure test and follow diagnostic test

Correction:Road test vehicle for couple of hours can't duplicate concern at this time possible vehicle had vapor lock

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 30-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
20 - Miles			JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
30 - Kilometers			JAPEREZ	Dec 30, 2019 11:57:17 AM	No	
40 - Hours			JAPEREZ	Dec 30, 2019 11:57:17 AM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53134996
Invoice No. 55345 - 53134996

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Stalling while driving		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	218,200 - DH

Activity Header
Activity: 15 030 ELECTRICAL GROUP
Activity Note: Stalling while driving
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
30-Dec-19	Perez,Javier	2.9	65	188.5

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>188.50</td></tr><tr><td>Labor Hours:</td><td>2.90</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>188.50</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	188.50	Labor Hours:	2.90	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	188.50
Activity 15 Sub Total															
Parts:	0.00														
Labor:	188.50														
Labor Hours:	2.90														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	188.50														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53134996 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>188.50</td></tr><tr><td>Labor Hours:</td><td>2.90</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>188.50</td></tr></table>		Work Order 53134996 Total		Parts:	0.00	Labor:	188.50	Labor Hours:	2.90	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	188.50
Work Order 53134996 Total															
Parts:	0.00														
Labor:	188.50														
Labor Hours:	2.90														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	188.50														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53133897
Invoice No. 55345 - 53133897

Client Department:

Department: 55345M

Work Order Description

Bus Stalling

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 218,131 - DH

Chronology

Reported	Dec 29, 2019 1:56:16 PM	Dec 29, 2019 1:56:16 PM
Started	Dec 29, 2019 1:58:00 PM	
Completed	Dec 29, 2019 2:56:00 PM	Dec 29, 2019 2:56:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Bus Stalling while driving.

Cause: Swap Both fuel Pump module didn't make any difference. Check Plugs. Plugs Ok.

Correction: No parts Charge on bus.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 29-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 29, 2019 1:57:29 PM	No	
20 - Miles			DARTHURS	Dec 29, 2019 1:57:29 PM	No	
30 - Kilometers			DARTHURS	Dec 29, 2019 1:57:29 PM	No	
40 - Hours			DARTHURS	Dec 29, 2019 1:57:29 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53133897
Invoice No. 55345 - 53133897

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Bus Stalling		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	218,131 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Bus Stalling
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Dec-19	Arthurs,Durvin	0.97	65	63.05

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>63.05</td></tr><tr><td>Labor Hours:</td><td>0.97</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>63.05</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	63.05	Labor Hours:	0.97	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	63.05
Activity 15 Sub Total															
Parts:	0.00														
Labor:	63.05														
Labor Hours:	0.97														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	63.05														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53133897 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>63.05</td></tr><tr><td>Labor Hours:</td><td>0.97</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>63.05</td></tr></table>		Work Order 53133897 Total		Parts:	0.00	Labor:	63.05	Labor Hours:	0.97	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	63.05
Work Order 53133897 Total															
Parts:	0.00														
Labor:	63.05														
Labor Hours:	0.97														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	63.05														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 53008158
Invoice No. 55345 - 53008158

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	RRENE	Status:	40 - Closed (40)
Created By:	RRENE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	218,010 - DH

Chronology		
Reported	Dec 24, 2019 12:26:33 PM	Dec 24, 2019 12:26:33 PM
Started	Dec 24, 2019 4:48:00 PM	
Completed	Dec 24, 2019 7:47:00 PM	Dec 24, 2019 7:47:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB

CAUSE: Service

CORRECTION: Performed PMB Service
Oil filter B329 qty1
Engine oil 5W20Qty qty 7 Qts
Rotate tires and washed rims torque wheels 140 lbs
Second torque 140 lbs

Activity Header				
Activity:10 999/999/999 TOTAL VEHICLE				
Activity Note: Light Duty PMI				
Reason for Repair: 08 Preventive Maintenance				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Dec-19	Gaspard,Ronald	2.32	65	150.8
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 10 Sub Total	
			Parts:	0.00
			Labor:	150.80
			Labor Hours:	2.32
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	150.80



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 53008158
Invoice No. 55345 - 53008158

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RRENE

Created By: RRENE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 218,010 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Dec-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Dec-19	Gaspard,Ronald	0.62	65	40.3

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: RGASPARD Performed on: 24-DEC-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Dec 24, 2019 7:45:33 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Dec 24, 2019 7:45:33 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Dec 24, 2019	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				7:45:33 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Dec 24, 2019 7:45:33 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Dec 24, 2019 7:45:33 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	40.30
Labor Hours:	0.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	42.26



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 53008158
Invoice No. 55345 - 53008158

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RRENE

Created By: RRENE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 218,010 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 24, 2019 7:46:37 PM	No	
20 - Miles			RGASPARD	Dec 24, 2019 7:46:37 PM	No	
30 - Kilometers			RGASPARD	Dec 24, 2019 7:46:37 PM	No	
40 - Hours			RGASPARD	Dec 24, 2019 7:46:37 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts: 0.00

Labor: 0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 53008158 Total	
	Parts:	1.96
	Labor:	191.10
	Labor Hours:	2.94
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	193.06



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53108553
Invoice No. 55345 - 53108553

Client Department:

Department: 55345M

Work Order Description

Engine is stalling

Requested By: JAPEREZ

Created By: JAPEREZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 217,209 - DH

Chronology

Reported	Dec 18, 2019 10:26:56 AM	Dec 18, 2019 10:26:56 AM
Started	Dec 18, 2019 12:00:00 AM	
Completed	Dec 18, 2019 10:43:00 AM	Dec 18, 2019 10:43:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:engine is stalling

Cause: check computer system found multiple misfires

Correction:Replace wire harness pig tail for ignition coil cylinder #6 and ignition coil also ignition coil for cylinder #7 and all spark plugs retest system and road test vehicle ok at this time

Parts:

2 ignition coil 3w7z-12029-aa

1 pig tail 5u2z-14s411-zb

10 spark plugs AP103

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet


No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 18-DEC-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
20 - Miles			JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
30 - Kilometers			JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
40 - Hours			JAPEREZ	Dec 18, 2019 10:42:49 AM	No	
Activity Sub Total						
				Activity 5 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total <u>0.00</u>		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53108553
Invoice No. 55345 - 53108553

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Engine is stalling		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	217,209 - DH

Activity Header
Activity: 15 033 IGNITION
Activity Note: Engine is stalling
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Dec-19	5U2Z-14S411-ZB	PIGTAIL, WIRE, INJECTOR, FUEL SAME AS WPT1051	1	16.18	16.18
18-Dec-19	AP103	PLUG, SPARK	10	3.13	31.3
18-Dec-19	3W7Z-12029-AA	COIL, IGNITION SAME AS DG508	2	34.61	69.22

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
18-Dec-19	Perez, Javier	3.25	65	211.25

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			116.70
Labor:			211.25
Labor Hours:			3.25
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			327.95

Work Order Footer		Work Order 53108553 Total	
Parts:			116.70
Labor:			211.25
Labor Hours:			3.25
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			327.95



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53075205
Invoice No. 55345 - 53075205

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Replaced brake booster		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	215,817 - DH

Chronology

Reported	Dec 9, 2019 1:41:03 PM	Dec 9, 2019 1:41:03 PM
Started	Dec 9, 2019 12:00:00 AM	
Completed	Dec 9, 2019 2:36:31 PM	Dec 9, 2019 2:36:31 PM
Down Time		

Work Order Notes

Line 10 Brake booster leaking
Normal wear
Replaced brake booster

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:


Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 09-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
10 - Have you successfully completed the	Done		VAMRITTEEMAL	Dec 9, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				1:43:21 PM		
20 - Miles			VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
30 - Kilometers			VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
40 - Hours			VAMRITTEEMAL	Dec 9, 2019 1:43:21 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		17.33
				Labor Hours:		0.27
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		17.33



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53075205
Invoice No. 55345 - 53075205

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Replaced brake booster		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	215,817 - DH

Activity Header
Activity:20 013 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Dec-19	DC2Z-2005-A	BOOSTER, BRAKE, POWER, HYDRAULIC SAME AS BRB-103	1	188.55	188.55

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Dec-19	AMRIT TEEMAL,VISHNU	2	65	130

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 20 Sub Total</th></tr><tr><td>Parts:</td><td>188.55</td></tr><tr><td>Labor:</td><td>130.00</td></tr><tr><td>Labor Hours:</td><td>2.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>318.55</td></tr></table>		Activity 20 Sub Total		Parts:	188.55	Labor:	130.00	Labor Hours:	2.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	318.55
Activity 20 Sub Total															
Parts:	188.55														
Labor:	130.00														
Labor Hours:	2.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	318.55														

Work Order Footer															
<table><tr><th colspan="2">Work Order 53075205 Total</th></tr><tr><td>Parts:</td><td>188.55</td></tr><tr><td>Labor:</td><td>147.33</td></tr><tr><td>Labor Hours:</td><td>2.27</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>335.88</td></tr></table>		Work Order 53075205 Total		Parts:	188.55	Labor:	147.33	Labor Hours:	2.27	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	335.88
Work Order 53075205 Total															
Parts:	188.55														
Labor:	147.33														
Labor Hours:	2.27														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	335.88														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 53054537
Invoice No. 55345 - 53054537

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Coolant Tank and Cap			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	215,000 - DH

Chronology

Reported	Dec 2, 2019 7:27:41 PM	Dec 2, 2019 7:27:41 PM
Started	Dec 2, 2019 12:00:00 AM	
Completed	Dec 3, 2019 8:21:36 AM	Dec 3, 2019 8:21:36 AM
Down Time		

Work Order Notes

Line 10 Replaced coolant tank and cap

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-Dec-19	10238	CAP, RADIATOR, FORD	1	6.23	6.23
02-Dec-19	8C2Z-8A080-C	TANK, SURGE, COOLANT	1	121.26	121.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-Dec-19	Delva,Terry	0.5166666	65	33.583329

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 02-DEC-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Dec 2, 2019 7:37:35 PM	No	
20 - Miles			TDELVA	Dec 2, 2019 7:37:35 PM	No	
30 - Kilometers			TDELVA	Dec 2, 2019 7:37:35 PM	No	
40 - Hours			TDELVA	Dec 2, 2019 7:37:35 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	127.49
Labor:	33.58
Labor Hours:	0.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	161.07



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 53054537
Invoice No. 55345 - 53054537

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Coolant Tank and Cap		Status:	40 - Closed (40)
Requested By:	TDELVA	Priority:	-
Created By:	TDELVA	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	215,000 - DH
Potential Warranty:	No		

Activity Header
Activity:20 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Dec-19	HA10898	ACCUMULATOR, A/C	1	29.89	29.89

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
02-Dec-19	Delva, Terry	0.5833333	65	37.9166645

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:			29.89
Labor:			37.92
Labor Hours:			0.58
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			67.81

Work Order Footer		Work Order 53054537 Total	
Parts:			157.38
Labor:			71.50
Labor Hours:			1.10
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			228.88



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52890896
Invoice No. 55345 - 52890896

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 213,612 - DH

Chronology

Reported	Nov 14, 2019 12:00:00 AM	Nov 14, 2019 12:00:00 AM
Started	Nov 15, 2019 12:00:00 AM	
Completed	Nov 17, 2019 1:14:09 PM	Nov 17, 2019 1:14:09 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION: perform pmA service

Oil filter B329 qty1

Engine oil 5w20 qty 7 Qts

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-19	Gaspard,Ronald	1.5833333	65	102.9166645

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 15-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,730 - FRA Check Starter	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Nov 15, 2019 11:54:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 15, 2019 11:54:05 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	102.92
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	102.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52890896
Invoice No. 55345 - 52890896

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 213,612 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Nov-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-19	Gaspard,Ronald	1.1333333	65	73.6666645

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 15-NOV-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 15, 2019 11:54:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 15, 2019 11:54:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 15, 2019 11:54:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 15, 2019 11:54:49 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 15, 2019 11:54:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 15, 2019 11:54:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Nov 15, 2019 11:54:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 15, 2019 11:54:49 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	73.67
	Labor Hours:	1.13
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	75.63



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52890896
Invoice No. 55345 - 52890896

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 213,612 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Nov-19	Gaspard,Ronald	0.2666666	65	17.333329

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 15-NOV-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 15, 2019 11:55:15 PM	No	
20 - Miles			RGASPARD	Nov 15, 2019 11:55:15 PM	No	
30 - Kilometers			RGASPARD	Nov 15, 2019 11:55:15 PM	No	
40 - Hours			RGASPARD	Nov 15, 2019 11:55:15 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	17.33
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	17.33
Work Order Footer		
	Work Order 52890896 Total	
	Parts:	1.96
	Labor:	193.92
	Labor Hours:	2.98
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	195.88



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52971831
Invoice No. 55345 - 52971831

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Transmission		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	212,096 - DH

Chronology		
Reported	Nov 5, 2019 10:59:37 PM	Nov 5, 2019 10:59:37 PM
Started	Nov 5, 2019 12:00:00 AM	
Completed	Nov 6, 2019 12:21:00 AM	Nov 6, 2019 12:21:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:bus Shift rough

Cause: Bad Transmission. Code PO (751)

Correction:Remove & Replace Transmissions

Activity Header				
Activity:5 999 TOTAL VEHICLE				
Activity Note: Personal Risk Assessment				
Reason for Repair:		SW Shop Work Order		
Work Accomplished:		06 Inspect		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-19	Arthurs,Durvin	0.0833333	65	5.4166645
Activity Sublet				
No Data Available				
Activity Checklist				
Check List				
5 Desc: Personal Risk Assessment				
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-NOV-19				

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Nov 5, 2019 11:50:45 PM	No	
20 - Miles			DARTHURS	Nov 5, 2019 11:50:45 PM	No	
30 - Kilometers			DARTHURS	Nov 5, 2019 11:50:45 PM	No	
40 - Hours			DARTHURS	Nov 5, 2019 11:50:45 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	5.42



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52971831
Invoice No. 55345 - 52971831

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Transmission		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	212,096 - DH

Activity Header
Activity: 15 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 43 Weak
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Nov-19	19180251	TRANSMISSION, REMANUFACTURED	1	358.11	358.11

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Nov-19	Arthurs,Durvin	5.5	65	357.5

Activity Sublet
No Data Available

Activity Checklist						
Check List						
15 Desc: Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: DARTHURS Performed on: 06-NOV-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		DARTHURS	Nov 6, 2019 12:20:47 AM	No	

Activity Sub Total		Activity 15 Sub Total	
Parts:	358.11	Labor:	357.50
Labor Hours:	5.50	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		715.61	

Work Order Footer		Work Order 52971831 Total	
Parts:	358.11	Labor:	362.92
Labor Hours:	5.58	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		721.03	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52912206
Invoice No. 55345 - 52912206

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front a/c evap/ serp belt		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	209,544 - DH

Chronology

Reported	Oct 20, 2019 11:30:14 AM	Oct 20, 2019 11:30:14 AM
Started	Oct 20, 2019 12:00:00 AM	
Completed	Oct 21, 2019 9:02:46 AM	Oct 21, 2019 9:02:46 AM
Down Time		

Work Order Notes

Line 10 Front a/c blowing warm
A/c leaking
Replaced high pressure line
Replaced Evaporator
Serpentine belt cracked
Normal wear
Replaced Serpentine belt

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-19	AMRIT TEEMAL,VISHNU	0.2666666	65	17.333329

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 20-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
20 - Miles			VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
30 - Kilometers			VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	
40 - Hours			VAMRITTEEMAL	Oct 20, 2019 11:40:14 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	17.33
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	17.33



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52912206
Invoice No. 55345 - 52912206

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front a/c evap/ serp belt		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	209,544 - DH

Activity Header					
Activity:20 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION					
Activity Note:					
Reason for Repair:		04 Driver's Report			
Work Accomplished:		03 Replace New			
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-19	6C2Z-19860-C	CORE, EVAPORATOR, A/C	1	101.19	101.19
20-Oct-19	3411885	TUBE, ORIFICE, A/C, FORD	1	0.75	0.75
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
20-Oct-19	AMRIT TEEMAL,VISHNU	2.5	65	162.5	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:	101.94	
			Labor:	162.50	
			Labor Hours:	2.50	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	264.44	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52912206
Invoice No. 55345 - 52912206

Client Department:
Department: 55345M
Work Order Description
Front a/c evap/ serp belt
Requested By: VAMRITTEEMAL
Created By: VAMRITTEEMAL
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 209,544 - DH

Activity Header
Activity: 30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-19	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	21.01	21.01
20-Oct-19	GC2Z-19972-B	LINE, PRESSURE, HIGH, A/C, E450	1	41.36	41.36

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-19	AMRIT TEEMAL,VISHNU	0.75	65	48.75

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 30 Sub Total	
Parts:	62.37
Labor:	48.75
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	111.12

Work Order Footer	
Work Order 52912206 Total	
Parts:	164.31
Labor:	228.58
Labor Hours:	3.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	392.89



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52774742
Invoice No. 55345 - 52774742

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RRENE

Created By: RRENE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 208,774 - DH

Chronology

Reported	Oct 11, 2019 11:14:57 AM	Oct 11, 2019 11:14:57 AM
Started		
Completed	Oct 14, 2019 8:48:00 AM	Oct 14, 2019 8:48:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: preventive maintenance

CORRECTION: perform pmA service lube all Pivoting Points add some Transmission Fluids Completed

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 11-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:14:30 PM		
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				1:14:30 PM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,420 - Check Hood	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,460 - Record Antifreeze Protection Level	-	N/A	HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				1:14:30 PM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:14:30 PM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:14:30 PM		
77,120 - Check Suspension Components	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,133 - Brake Pad Thickness LR	3 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,134 - Brake Pad Thickness RR	3 Inch	need rear brake pads	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Oct 11, 2019 1:14:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Oct 11, 2019 1:14:30 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52774742
Invoice No. 55345 - 52774742

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RRENE

Created By: RRENE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 208,774 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: HPIERRE Performed on: 11-OCT-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Oct 11, 2019 1:15:15 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Oct 11, 2019 1:15:15 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Oct 11, 2019 1:15:15 PM	No	

Activity Sub Total

Activity 20 Sub Total
Parts: 1.96

	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52774742
Invoice No. 55345 - 52774742

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RRENE	Status:	40 - Closed (40)
Created By:	RRENE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	208,774 - DH

Activity Header						
Activity:30 999 TOTAL VEHICLE						
Activity Note: PRAMETER						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 14-OCT-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
20 - Miles			HPIERRE	Oct 14, 2019 8:48:46 AM	No	
30 - Kilometers	12		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
40 - Hours	6		HPIERRE	Oct 14, 2019 8:48:46 AM	No	
Activity Sub Total						
				Activity 30 Sub Total		
Parts:				0.00		
Labor:				0.00		

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52774742 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52887252
Invoice No. 55345 - 52887252

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Pma follow up need rear brake pads		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	208,679 - DH

Chronology

Reported	Oct 11, 2019 1:16:45 PM	Oct 11, 2019 1:16:45 PM
Started		
Completed	Oct 11, 2019 2:14:16 PM	Oct 11, 2019 2:14:16 PM
Down Time		

Work Order Notes

Line 10 PmA follow up need rear brakes pads

Preventive maintenance

Replaced rear brakes pads completed

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 11-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
4 - Have you performed the proper LOTO?	Done		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
10 - Have you successfully completed the Personal	Done		HPIERRE	Oct 11, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				1:21:03 PM		
20 - Miles			HPIERRE	Oct 11, 2019 1:21:03 PM	No	
30 - Kilometers	12		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
40 - Hours	8		HPIERRE	Oct 11, 2019 1:21:03 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52887252
Invoice No. 55345 - 52887252

Client Department:
Department: 55345M
Work Order Description
Pma follow up need rear brake pads
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 208,679 - DH

Activity Header					
Activity:20 013/000/000 BRAKES					
Activity Note:					
Reason for Repair:		39 Natural Causes			
Work Accomplished:		03 Replace New			
Part Failure:		44 Worn			
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total			Activity 20 Sub Total		
			Parts: 47.81		
			Labor: 0.00		
			Labor Hours: 0.00		
			Sublet Parts: 0.00		
			Sublet Labor: 0.00		
			Activity Sub Total 47.81		
Work Order Footer			Work Order 52887252 Total		
			Parts: 47.81		
			Labor: 0.00		
			Labor Hours: 0.00		
			Sublet Parts: 0.00		
			Sublet Labor: 0.00		
			Activity Sub Total 47.81		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52861886
Invoice No. 55345 - 52861886

Client Department:

Department: 55345M

Work Order Description

Transmission code PO751

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 207,832 - DH

Chronology

Reported	Oct 3, 2019 11:08:42 PM	Oct 3, 2019 11:08:42 PM
Started	Oct 3, 2019 12:00:00 AM	
Completed	Oct 4, 2019 12:07:00 AM	Oct 4, 2019 12:07:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Check Engine Light On Code PO751

Cause: Bad Transmission

Correction: Remove & Replace Transmission With a Rebuilds one.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 03-OCT-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 3, 2019 11:12:52 PM	No	
20 - Miles			DARTHURS	Oct 3, 2019 11:12:52 PM	No	
30 - Kilometers			DARTHURS	Oct 3, 2019 11:12:52 PM	No	
40 - Hours			DARTHURS	Oct 3, 2019 11:12:52 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	5.42



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52861886
Invoice No. 55345 - 52861886

Client Department:

Department: 55345M

Work Order Description

Transmission code PO751

Requested By: EARJOHNSON

Created By: EARJOHNSON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 207,832 - DH

Activity Header

Activity: 15 027/000/000 TRANSMISSION, MAIN, AUTOMATIC

Activity Note:

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 03 Replace New

Part Failure: 43 Weak

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Oct-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99
07-Oct-19	6C3Z-7A262-AA	CLUTCH, FORWARD, TRANSMISSION	1	21.61	21.61
07-Oct-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
07-Oct-19	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.08	9.08
07-Oct-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
07-Oct-19	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.4	2.4
07-Oct-19	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	59.29	59.29
07-Oct-19	19180251	TRANSMISSION, REMANUFACTURED	1	302.71	302.71
07-Oct-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Oct-19	Arthurs,Durvin	5	65	325

Activity Sublet

No Data Available

Activity Checklist

Check List						
15 Desc: Task: 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID Performed by: DARTHURS Performed on: 04-OCT-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - 55345 TRANSMISSION DTC P0751 SHIFT SOLENOID	Done		DARTHURS	Oct 4, 2019 12:07:03 AM	No	

Activity Sub Total


Activity 15 Sub Total

Parts:	552.74
Labor:	325.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00

Activity Sub Total		877.74
Work Order Footer		
Work Order 52861886 Total		
Parts:		552.74
Labor:		330.42
Labor Hours:		5.08
Sublet Parts:		0.00
Sublet Labor:		0.00
Activity Sub Total		883.16



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52793782
Invoice No. 55345 - 52793782

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	205,297 - DH

Chronology

Reported	Sep 16, 2019 9:46:44 AM	Sep 16, 2019 9:46:44 AM
Started	Sep 16, 2019 12:00:00 AM	
Completed	Sep 16, 2019 1:47:54 PM	Sep 16, 2019 1:47:54 PM
Down Time		

Work Order Notes

Line 10 Code P0713 transmission

Complaint. Check engine light on

Cause. Trouble code P0713 (Transmission)

Correction. Removed and replaced internal transmission harness and temperature sensor, drove test, all okay at this time.

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 16-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAURODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAURODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RAURODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
4 - Have you performed the proper LOTO?	Done		RAURODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
20 - Miles			RAUODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
30 - Kilometers			RAUODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	
40 - Hours			RAUODRIGUEZ	Sep 16, 2019 9:53:05 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52793782
Invoice No. 55345 - 52793782

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 Transmission DTC P-0713		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	205,297 - DH

Activity Header
Activity:20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
16-Sep-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
16-Sep-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
16-Sep-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Sep-19	Rodriguez,Raul	2.2666666	65	147.333329

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
		Parts:	157.65
		Labor:	147.33
		Labor Hours:	2.27
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	304.98

Work Order Footer		Work Order 52793782 Total	
		Parts:	157.65
		Labor:	147.33
		Labor Hours:	2.27
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	304.98



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52767691
Invoice No. 55345 - 52767691

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	204,393 - DH

Chronology		
Reported	Sep 9, 2019 6:21:24 AM	Sep 9, 2019 6:21:24 AM
Started	Sep 9, 2019 12:00:00 AM	
Completed	Sep 16, 2019 1:45:23 PM	Sep 16, 2019 1:45:23 PM
Down Time		

Work Order Notes

Line 10 Complaint: Low Front Brake pads

Cause: preventive maintenance

Correction: replaced front brake pads

Activity Header															
Activity:10 013 BRAKES															
Activity Note: replaced front brake pads															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 10 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 10 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 10 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52767691
Invoice No. 55345 - 52767691

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	204,393 - DH

Activity Header
Activity:20 013 BRAKES
Activity Note: Replaced front brake pads
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Sep-19	NELSON PIERRE-LOUIS	1.5	65	97.5

Activity Sublet
No Data Available


Check List						
20 Desc: Replaced front brake pads Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 09-SEP-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
20 - Miles			NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	
40 - Hours			NPIERRE-LOUIS	Sep 9, 2019 6:44:04 AM	No	

Activity Sub Total	Activity 20 Sub Total

	Parts:	0.00
	Labor:	97.50
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	97.50
Work Order Footer		
	Work Order 52767691 Total	
	Parts:	0.00
	Labor:	97.50
	Labor Hours:	1.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	97.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52653110
Invoice No. 55345 - 52653110

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 204,393 - DH

Chronology

Reported	Sep 6, 2019 11:44:57 AM	Sep 6, 2019 11:44:57 AM
Started		
Completed	Sep 10, 2019 8:11:42 AM	Sep 10, 2019 8:11:42 AM
Down Time		

Work Order Notes

Line 10 Complaint: PMC Service

Cause: preventive maintenance

Correction: PMC Service Perform and

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 09-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,140 - Check Service Brakes	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,152 - Decelerometer Results Test 1	0 FEET		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,154 - Decelerometer Results Test 2	0 FEET		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,156 - Decelerometer Results Test 3	0 FEET		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,442 - Freeze Point	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	0 Degree Fahrenheit		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,620 - Check Valve Stems and Caps	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,110 - FRA Check Fuel Tank	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,131 - Brake Pad Thickness LF	4 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,132 - Brake Pad Thickness RF	4 Inch	replaced front brake pads	NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	Yes	52767691
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,135 - Brake Rotor LF	45.5 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,136 - Brake Rotor RF	45.5 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,137 - Brake Rotor LR	35.5 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,138 - Brake Rotor RR	35.5 Inch		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Sep 9, 2019 6:23:40 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52653110
Invoice No. 55345 - 52653110

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 204,393 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-Sep-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
09-Sep-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM C						
Task: PM C SERVICE Performed by: NPIERRE-LOUIS Performed on: 09-SEP-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		NPIERRE-	Sep 9, 2019	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)			LOUIS	6:24:41 AM		
201,000 - Service Crankcase Breather	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
302,000 - Check Toe-In and Record Reading	Done		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
302,001 - Record Toe-In Reading	0 Inches, fraction-actual		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	
305,000 - FRA Change Differential Fluid	Yes		NPIERRE-LOUIS	Sep 9, 2019 6:24:41 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	19.23
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52653110
Invoice No. 55345 - 52653110

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 204,393 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 09-SEP-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
20 - Miles			NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	
40 - Hours			NPIERRE-LOUIS	Sep 9, 2019 10:28:49 AM	No	

Activity Sub Total

Activity 30 Sub Total


Parts: 0.00

Labor: 0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52653110 Total	
	Parts:	19.23
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52654106
Invoice No. 55345 - 52654106

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Wire harness soleniod		Ford E450 Champion Challenger	
Requested By:	NPIERRE-LOUIS	Status:	40 - Closed (40)
Created By:	NPIERRE-LOUIS	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	200,136 - DH

Chronology

Reported	Aug 1, 2019 12:01:23 PM	Aug 1, 2019 12:01:23 PM
Started	Aug 1, 2019 12:00:00 AM	
Completed	Aug 2, 2019 8:31:57 AM	Aug 2, 2019 8:31:57 AM
Down Time		

Work Order Notes

Line 10 Driver complaint: check engine light on

Tech found code p0713

Correction: replaced wire harness,body valve gasket,temporary sensor

Activity Header

Activity:10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	NELSON PIERRE-LOUIS	2.5	65	162.5

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
20 - Miles			NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
30 - Kilometers			NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	
40 - Hours			NPIERRE-LOUIS	Aug 1, 2019 12:15:10 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	162.50
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	162.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52654106
Invoice No. 55345 - 52654106

Client Department:
Department: 55345M
Work Order Description
Wire harness soleniod
Requested By: NPIERRE-LOUIS
Created By: NPIERRE-LOUIS
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 200,136 - DH

Activity Header					
Activity:20 027/000/000 TRANSMISSION, MAIN, AUTOMATIC					
Activity Note:					
Reason for Repair: 08 Preventive Maintenance					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
01-Aug-19	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	6.87	6.87
01-Aug-19	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	123.52	123.52
01-Aug-19	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	1	9.99	9.99
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:		157.65
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		157.65
Work Order Footer					
			Work Order 52654106 Total		
			Parts:		157.65
			Labor:		162.50
			Labor Hours:		2.50
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		320.15



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52655683
Invoice No. 55345 - 52655683

Client Department:

Department: 55345M

Work Order Description

Battery Tray

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 200,136 - DH

Chronology

Reported	Aug 1, 2019 9:11:31 PM	Aug 1, 2019 9:11:31 PM
Started	Aug 1, 2019 12:00:00 AM	
Completed	Aug 1, 2019 10:52:00 PM	Aug 1, 2019 10:52:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Battery Troy keep Sliding Out

Cause: Spring to hold the latch broken.

Correction: Replace Broken spring.

Parts #0499252 Qty (1)

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 1, 2019 10:20:26 PM	No	
20 - Miles			DARTHURS	Aug 1, 2019 10:20:26 PM	No	
30 - Kilometers			DARTHURS	Aug 1, 2019 10:20:26 PM	No	
40 - Hours			DARTHURS	Aug 1, 2019 10:20:26 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	5.42



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52655683
Invoice No. 55345 - 52655683

Client Department:

Department: 55345M

Work Order Description

Battery Tray

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 200,136 - DH

Activity Header

Activity: 15 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure: 43 Weak

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
01-Aug-19	0499252	SPRING, TRAY, BATTERY	1	2.92	2.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Aug-19	Arthurs,Durvin	0.5	65	32.5
01-Aug-19	Arthurs,Durvin	0.1666666	65	10.833329

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	2.92
Labor:	43.33
Labor Hours:	0.67
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	46.25

Work Order Footer

Work Order 52655683 Total

Parts:	2.92
Labor:	48.75
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	51.67



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52539833
Invoice No. 55345 - 52539833

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 200,136 - DH

Chronology

Reported	Jul 26, 2019 11:04:24 AM	Jul 26, 2019 11:04:24 AM
Started		
Completed	Aug 1, 2019 8:29:10 AM	Aug 1, 2019 8:29:10 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PmA Service

CAUSE: Preventive maintenance

CORRECTION: PmA

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: NPIERRE-LOUIS Performed on: 01-AUG-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,100 - Safety Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,160 - FRA Check Instruments and Horns	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,170 - Check Fast Idle	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,180 - Check Starter Protection Circuit	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
10,190 - Check Reverse Warning System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,100 - Check Parking Brake	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,150 - Perform Brake Test	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,170 - FRA Check Door Operation	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,210 - Check Condition of Operator's Area	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,240 - FRA Check Interior Lights	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,260 - Check Stop Request System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
22,110 - Check Emergency Hatches	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
22,120 - Check All Safety Equipment	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,310 - Check Passenger Doors	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,360 - Check for Physical Damage and Decals	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,380 - Check Exterior Compartment Doors	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
33,100 - Check Lights and Reflectors	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,420 - Check Hood	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,130 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,140 - FRA Check Intake System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,150 - FRA Inspect Turbocharger	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,180 - FRA Check for Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,190 - FRA Perform Battery Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
50,510 - Check Entire Steering System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,630 - Check and Record Tread Depth	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,631 - Tread Depth RF	8 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,632 - Tread Depth LF	8 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,650 - Check Sidewall Wear	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,660 - Inspect for Cuts and Tears	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,670 - Check Dual Mating With Square	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,710 - Check Vibration Damper	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,730 - FRA Check Starter	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,770 - FRA Check Exhaust System	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,120 - Check Suspension Components	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,131 - Brake Pad Thickness LF	7 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,132 - Brake Pad Thickness RF	7 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,133 - Brake Pad Thickness LR	6 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,134 - Brake Pad Thickness RR	6 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,135 - Brake Rotor LF	39.5 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,136 - Brake Rotor RF	39.5 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,137 - Brake Rotor LR	39.5 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,138 - Brake Rotor RR	39.5 Inch		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,140 - FRA Check Brake Hoses	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,150 - Check King Pins	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
80,810 - Completion of PMI Report	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:48 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52539833
Invoice No. 55345 - 52539833

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 200,136 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
30-Jul-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	-1	1.96	-1.96

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: NPIERRE-LOUIS Performed on: 01-AUG-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
101,000 - FRA Change Oil Filters	Yes		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
102,000 - FRA Drain Engine Oil	Yes		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
103,000 - FRA Check Transmission Fluid	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
104,000 - Lubricate Chassis	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
105,000 - Replace or Clean A/C Filters	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
107,000 - FRA Change Primary Fuel Filter	Yes		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		NPIERRE-LOUIS	Aug 1, 2019 8:08:22 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52539833
Invoice No. 55345 - 52539833

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 200,136 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: NPIERRE-LOUIS Performed on: 31-JUL-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
3 - Are you wearing the appropriate PPE?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
4 - Have you performed the proper LOTO?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
20 - Miles			NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
30 - Kilometers			NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	
40 - Hours			NPIERRE-LOUIS	Jul 31, 2019 9:24:37 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts: 0.00

Labor: 0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52539833 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52545413
Invoice No. 55345 - 52545413

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE FUEL PUMP ASSEMBLY		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	195,348 - DH

Chronology		
Reported	Jun 24, 2019 12:45:28 PM	Jun 24, 2019 12:45:28 PM
Started	Jun 24, 2019 12:00:00 AM	
Completed	Jun 24, 2019 2:05:15 PM	Jun 24, 2019 2:05:15 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Vehicle would not start

Cause: Bad fuel pump assembly
Code P0148 was found.

Correction: Tech Replace fuel pump assembly

Activity Header				
Activity:5 999 TOTAL VEHICLE				
Activity Note: Personal Risk Assessment				
Reason for Repair: SW Shop Work Order				
Work Accomplished: 06 Inspect				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	KARLENS,Cyrius	0.3333333	65	21.6666645
Activity Sublet				
No Data Available				
Activity Checklist				
Check List				
5 Desc: Personal Risk Assessment				
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 24-JUN-19				

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
3 - Are you wearing the appropriate PPE?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
4 - Have you performed the proper LOTO?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jun 24, 2019 1:03:14 PM	No	
20 - Miles		na	CKARLENS	Jun 24, 2019 1:03:14 PM	No	
30 - Kilometers		na	CKARLENS	Jun 24, 2019 1:03:14 PM	No	
40 - Hours		na	CKARLENS	Jun 24, 2019 1:03:14 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	21.67
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	21.67



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52545413
Invoice No. 55345 - 52545413

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE FUEL PUMP ASSEMBLY		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	195,348 - DH

Activity Header
Activity:15 044 FUEL SYSTEM
Activity Note: REPLACE FUEL PUMP ASSEMBLY
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jun-19	11396002	PUMP, FUEL, GASEOUS, GEN-3 W/KIT	1	414.31	414.31

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Jun-19	KARLENS,Cyrius	4	65	260

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>414.31</td></tr><tr><td>Labor:</td><td>260.00</td></tr><tr><td>Labor Hours:</td><td>4.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>674.31</td></tr></table>		Activity 15 Sub Total		Parts:	414.31	Labor:	260.00	Labor Hours:	4.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	674.31
Activity 15 Sub Total															
Parts:	414.31														
Labor:	260.00														
Labor Hours:	4.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	674.31														

Work Order Footer															
<table><tr><th colspan="2">Work Order 52545413 Total</th></tr><tr><td>Parts:</td><td>414.31</td></tr><tr><td>Labor:</td><td>281.67</td></tr><tr><td>Labor Hours:</td><td>4.33</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>695.98</td></tr></table>		Work Order 52545413 Total		Parts:	414.31	Labor:	281.67	Labor Hours:	4.33	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	695.98
Work Order 52545413 Total															
Parts:	414.31														
Labor:	281.67														
Labor Hours:	4.33														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	695.98														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52442052
Invoice No. 55345 - 52442052

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	195,195 - DH

Chronology		
Reported	Jun 20, 2019 11:54:23 AM	Jun 20, 2019 11:54:23 AM
Started	Jun 21, 2019 12:00:00 AM	
Completed	Jun 21, 2019 10:00:00 AM	Jun 21, 2019 10:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed and completed pmA
Changed engine oil and replaced engine oil filter

Activity Header						
Activity:10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: A PM Level A						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
21-Jun-19	Delva,Terry	0.7166666	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 21-JUN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,100 - Safety Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,152 - Decelerometer Results Test 1	FEET	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,154 - Decelerometer Results Test 2	FEET	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,156 - Decelerometer Results Test 3	FEET	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,420 - Check Hood	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,150 - FRA Inspect Turbocharger	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,670 - Check Dual Mating With Square	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,133 - Brake Pad Thickness LR	10 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,134 - Brake Pad Thickness RR	10 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,135 - Brake Rotor LF	39.7 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,136 - Brake Rotor RF	39.7 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,137 - Brake Rotor LR	38.8 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,138 - Brake Rotor RR	38.8 Inch		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,150 - Check King Pins	-	na	TDELVA	Jun 21, 2019 9:15:10 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jun 21, 2019 9:15:10 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.72
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52442052
Invoice No. 55345 - 52442052

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 195,195 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Jun-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-19	Delva,Terry	1.35	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: TDELVA Performed on: 21-JUN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jun 21, 2019 9:15:55 AM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jun 21, 2019 9:15:55 AM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jun 21, 2019 9:15:55 AM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jun 21, 2019 9:15:55 AM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jun 21, 2019 9:15:55 AM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jun 21, 2019 9:15:55 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Jun 21, 2019 9:15:55 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jun 21, 2019 9:15:55 AM	No	

Activity Sub Total

		Activity 20 Sub Total	
		Parts:	1.96
		Labor:	0.00
		Labor Hours:	1.35
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52442052
Invoice No. 55345 - 52442052

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 195,195 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Jun-19	Delva, Terry	0.9333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 21-JUN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 21, 2019 8:57:53 AM	No	
20 - Miles			TDELVA	Jun 21, 2019 8:57:53 AM	No	
30 - Kilometers			TDELVA	Jun 21, 2019 8:57:53 AM	No	
40 - Hours			TDELVA	Jun 21, 2019 8:57:53 AM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.93
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52442052 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	3.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52510133
Invoice No. 55345 - 52510133

Client Department:
Department: 55345M
Work Order Description
Need righth front tire
Requested By: HPIERRE
Created By: HPIERRE
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 193,576 - DH

Chronology		
Reported	Jun 12, 2019 8:31:12 AM	Jun 12, 2019 8:31:12 AM
Started		
Completed	Jun 12, 2019 1:55:43 PM	Jun 12, 2019 1:55:43 PM
Down Time		

Work Order Notes

Line 10 Need front tire

Preventive maintenance

Mount and balance 1 tire completed

Activity Header							
Activity: 10 999/999/999 TOTAL VEHICLE							
Activity Note: PERSONAL RISK ASSESMENT							
Reason for Repair: 05 Inspection, Routine							
Work Accomplished: 06 Inspect							
Part Failure: 00 No Failure							
Activity Comments:							
Activity Parts							
Booked Date	Part Number	Part Description			Quantity	Each	Extended
12-Jun-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE			1	120.48	120.48
Activity Labor							
No Data Available							
Activity Sublet							
No Data Available							
Activity Checklist							
Check List							
10 Desc: PERSONAL RISK ASSESMENT							
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-JUN-19							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
1 - Are you properly trained to perform the task?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No		
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No		
3 - Are you wearing the appropriate PPE?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No		
4 - Have you performed the proper LOTO?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No		
5 - Are you aware of the potential risks of performing this repair?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No		

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 12, 2019 8:38:14 AM	No	
20 - Miles			HPIERRE	Jun 12, 2019 8:38:14 AM	No	
30 - Kilometers	8		HPIERRE	Jun 12, 2019 8:38:14 AM	No	
40 - Hours	1		HPIERRE	Jun 12, 2019 8:38:14 AM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	120.48
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	120.48



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52510133
Invoice No. 55345 - 52510133

Client Department:			
Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Need righth front tire			Ford E450 Champion Challenger
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	193,576 - DH

Activity Header
Activity:20 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Jun-19	003-352	TIRE, 225/65R17, DESTINATION, FIRESTONE	1	123.58	123.58
12-Jun-19	003-352	TIRE, 225/65R17, DESTINATION, FIRESTONE	-1	123.58	-123.58

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 52510133 Total	
		Parts:	120.48
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	120.48



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 52442050
Invoice No. 55345 - 52442050

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	99 - Cancelled (99)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	190,817 - DH

Chronology		
Reported	May 18, 2019 12:20:05 AM	May 18, 2019 12:20:05 AM
Started		
Completed	Jun 7, 2019 8:50:08 AM	Jun 7, 2019 8:50:08 AM
Down Time		

Work Order Notes

Activity Header					
Activity:10 013 BRAKES					
Activity Note:					
Reason for Repair:					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-May-19	1850-10	CAP, FUEL, PROPANE	1	11.09	11.09
Activity Labor					
No Data Available					
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:		11.09
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		11.09
Work Order Footer					
			Work Order 52442050 Total		
			Parts:		11.09
			Labor:		0.00
			Labor Hours:		0.00
			Sublet Parts:		0.00
			Sublet Labor:		0.00
			Activity Sub Total		11.09



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52449839
Invoice No. 55345 - 52449839

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check engine light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	191,259 - DH

Chronology		
Reported	May 21, 2019 2:51:42 PM	May 21, 2019 2:51:42 PM
Started	May 21, 2019 12:00:00 AM	
Completed	May 22, 2019 8:22:58 AM	May 22, 2019 8:22:58 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:check engine light is on

Cause: check computer system found engine misfire on cylinder #4

Correction:replaced ignition coil and spark plug, retest system ok at this time

Parts:
1 new ignition coil E262
1 spark plug ap103

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: SW Shop Work Order
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist

Check List																				
5 Desc: Personal Risk Assessment																				
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 21-MAY-19																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
1 - Are you properly trained to perform the task?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
4 - Have you performed the proper LOTO?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	May 21, 2019 3:00:06 PM	No															
20 - Miles			JAPEREZ	May 21, 2019 3:00:06 PM	No															
30 - Kilometers			JAPEREZ	May 21, 2019 3:00:06 PM	No															
40 - Hours			JAPEREZ	May 21, 2019 3:00:06 PM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 5 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>0.00</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.00</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>0.00</td> </tr> </tbody> </table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52449839
Invoice No. 55345 - 52449839

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check engine light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	191,259 - DH

Activity Header

Activity: 15 033 IGNITION
Activity Note: Check engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-May-19	AP103	PLUG, SPARK	1	3.08	3.08
21-May-19	E262	COIL, IGNITION	1	42	42

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-May-19	Perez,Javier	1.3333333	65	86.6666645

Activity Sublet

No Data Available

Activity Checklist

No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	45.08
Labor:	86.67
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	131.75

Work Order Footer

Work Order 52449839 Total	
Parts:	45.08
Labor:	86.67
Labor Hours:	1.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	131.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 5



Work Order No. 52442051
Invoice No. 55345 - 52442051

Client Department:
Department: 55345M
Work Order Description Front Tires/Exhaust hanger/ Clamps / Alternator / Power Steering Hose
Requested By: DARTHURS
Created By: DARTHURS
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 190,817 - DH

Chronology		
Reported	May 18, 2019 12:18:34 AM	May 18, 2019 12:18:34 AM
Started	May 19, 2019 12:00:00 AM	
Completed	May 19, 2019 2:43:00 PM	May 19, 2019 2:43:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: P/S high Pressure hose/Exhaust Hanger& Clamp /Front Tires/Alternator

Cause: P/S high Pressure hose leaking/ Front Tire cupping/ Battery Light On/ Exhaust Hanger bracket broken.

Correction:Remove&Replace Alternator/Mount &Balance Both Front Tire/ Remove & Replace P/S high Pressure hose. Remove& Replace Exhaust Hanger / Clamps
Parts# 192659 Qty (2)
Parts#BC2Z-3A719-C Qty (1)
Parts # GC2Z-10346-B Qty (1) Shop Supply
Parts# Exhaust Hanger&Clamps Shop Supply.

Activity Header				
Activity:5 999 TOTAL VEHICLE				
Activity Note: Personal Risk Assessment				
Reason for Repair:		SW Shop Work Order		
Work Accomplished:		06 Inspect		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-19	Arthurs,Durvin	0.0833333	65	5.4166645
Activity Sublet				
No Data Available				

Activity Checklist**Check List**

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 19, 2019 2:10:13 PM	No	
20 - Miles			DARTHURS	May 19, 2019 2:10:13 PM	No	
30 - Kilometers			DARTHURS	May 19, 2019 2:10:13 PM	No	
40 - Hours			DARTHURS	May 19, 2019 2:10:13 PM	No	

Activity Sub Total**Activity 5 Sub Total**

Parts:	0.00
Labor:	5.42
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	5.42



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 5



Work Order No. 52442051
Invoice No. 55345 - 52442051

Client Department:		
Department:	55345M	Equipment No.: 4602-P
Work Order Description		VIN: 1FDFE4FSXEDB17155
Front Tires/Exhaust hanger/ Clamps / Alternator / Power Steering Hose		Ford E450 Champion Challenger
Requested By:	DARTHURS	Status: 40 - Closed (40)
Created By:	DARTHURS	Priority: 1 - Low
Assigned To:		Driver:
Class:	WO - WORK ORDER	Phone:
Arrangement:	Unassigned	ETA:
Potential Warranty:	No	Meter: 190,817 - DH

Activity Header					
Activity:15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS					
Activity Note:					
Reason for Repair:		08 Preventive Maintenance			
Work Accomplished:		03 Replace New			
Part Failure:		99 Replaced Before Failure			
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-19	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	1	120.48	120.48
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
19-May-19	Arthurs,Durvin	1	65	65	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 15 Sub Total		
			Parts: 240.96		
			Labor: 65.00		
			Labor Hours: 1.00		
			Sublet Parts: 0.00		
			Sublet Labor: 0.00		
			Activity Sub Total 305.96		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 5



Work Order No. 52442051
Invoice No. 55345 - 52442051

Client Department:			Equipment No.: 4602-P
Department:	55345M		VIN: 1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Front Tires/Exhaust hanger/ Clamps / Alternator / Power Steering Hose			Status: 40 - Closed (40)
Requested By:	DARTHURS		Priority: 1 - Low
Created By:	DARTHURS		Driver:
Assigned To:			Phone:
Class:	WO - WORK ORDER		ETA:
Arrangement:	Unassigned		Meter: 190,817 - DH
Potential Warranty:	No		

Activity Header					
Activity:25 031/000/000 CHARGING					
Activity Note:					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-19	HU2Z10V346	ALTERNATOR, E450, REMANUFACTURED	1	241.43	241.43
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
19-May-19	Arthurs,Durvin	1.5	65	97.5	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 25 Sub Total		
			Parts:	241.43	
			Labor:	97.50	
			Labor Hours:	1.50	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	338.93	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 5



Work Order No. 52442051
Invoice No. 55345 - 52442051

Client Department:		
Department:	55345M	Equipment No.: 4602-P
Work Order Description		VIN: 1FDFE4FSXEDB17155
Front Tires/Exhaust hanger/ Clamps / Alternator / Power Steering Hose		Ford E450 Champion Challenger
Requested By:	DARTHURS	Status: 40 - Closed (40)
Created By:	DARTHURS	Priority: 1 - Low
Assigned To:		Driver:
Class:	WO - WORK ORDER	Phone:
Arrangement:	Unassigned	ETA:
Potential Warranty:	No	Meter: 190,817 - DH

Activity Header				
Activity:35 043/000/000 EXHAUST SYSTEM				
Activity Note:				
Reason for Repair:	04	Driver's Report		
Work Accomplished:	03	Replace New		
Part Failure:	12	Broken		
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-19	Arthurs,Durvin	1	65	65
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 35 Sub Total	
			Parts:	0.00
			Labor:	65.00
			Labor Hours:	1.00
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	65.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 5 of 5



Work Order No. 52442051
Invoice No. 55345 - 52442051

Client Department:			Equipment No.: 4602-P
Department:	55345M		VIN: 1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Front Tires/Exhaust hanger/ Clamps / Alternator / Power Steering Hose			Status: 40 - Closed (40)
Requested By:	DARTHURS		Priority: 1 - Low
Created By:	DARTHURS		Driver:
Assigned To:			Phone:
Class:	WO - WORK ORDER		ETA:
Arrangement:	Unassigned		Meter: 190,817 - DH
Potential Warranty:	No		

Activity Header
Activity:45 015/003/000 GEAR, STEERING, RACK & PINION
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-May-19	BC2Z-3A719-C	HOSE, STEERING, POWER, PRESSURE, HIGH, 6.0L	1	32.01	32.01

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-May-19	Arthurs,Durvin	1	65	65

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 45 Sub Total	
Parts:	32.01	Labor:	65.00
Labor Hours:	1.00	Labor Hours:	1.00
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		97.01	

Work Order Footer		Work Order 52442051 Total	
Parts:	514.40	Labor:	297.92
Labor Hours:	4.58	Labor Hours:	4.58
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		812.32	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52349776
Invoice No. 55345 - 52349776

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 190,817 - DH

Chronology

Reported	May 17, 2019 2:48:07 PM	May 17, 2019 2:48:07 PM
Started	May 18, 2019 12:00:00 AM	
Completed	May 18, 2019 12:22:00 AM	May 18, 2019 12:22:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM B Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter. Lube all Pivoting Points .Check Brakes. Clean batteries.

Parts# B329 Qty (1)

Oil 5W20 Qty (7.0)

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-19	Arthurs,Durvin	2	65	130

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 18-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				12:08:44 AM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,152 - Decelerometer Results Test 1	FEET		DARTHURS	May 18, 2019 12:08:44 AM	Yes	52442050
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:08:44 AM		
20,260 - Check Stop Request System	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,420 - Check Hood	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			12:08:44 AM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			12:08:44 AM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,631 - Tread Depth RF	4 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,632 - Tread Depth LF	5 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				12:08:44 AM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,133 - Brake Pad Thickness LR	12 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,134 - Brake Pad Thickness RR	12 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,136 - Brake Rotor RF	1.555 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,137 - Brake Rotor LR	1.653 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,138 - Brake Rotor RR	1.654 Inch		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 18, 2019 12:08:44 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 18, 2019 12:08:44 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	130.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	130.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52349776
Invoice No. 55345 - 52349776

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 190,817 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-May-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-19	Arthurs,Durvin	0.4166666	65	27.083329

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: DARTHURS Performed on: 18-MAY-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 18, 2019 12:09:52 AM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 18, 2019 12:09:52 AM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 18, 2019 12:09:52 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		DARTHURS	May 18, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				12:09:52 AM		
201,000 - Service Crankcase Breather	-	NA	DARTHURS	May 18, 2019 12:09:52 AM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		DARTHURS	May 18, 2019 12:09:52 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		DARTHURS	May 18, 2019 12:09:52 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	May 18, 2019 12:09:52 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	27.08
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	29.04



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52349776
Invoice No. 55345 - 52349776

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: VAMRITTEEMAL

Created By: VAMRITTEEMAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 190,817 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-May-19	Arthurs,Durvin	0.0833333	65	5.4166645

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 18-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 18, 2019 12:10:35 AM	No	
20 - Miles			DARTHURS	May 18, 2019 12:10:35 AM	No	
30 - Kilometers			DARTHURS	May 18, 2019 12:10:35 AM	No	
40 - Hours			DARTHURS	May 18, 2019 12:10:35 AM	No	


Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	5.42
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	5.42
Work Order Footer		
	Work Order 52349776 Total	
	Parts:	1.96
	Labor:	162.50
	Labor Hours:	2.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	164.46



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52396219
Invoice No. 55345 - 52396219

Client Department:

Department: 55345M

Work Order Description

Starter

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 188,732 - DH

Chronology

Reported	May 2, 2019 2:51:11 PM	May 2, 2019 2:51:11 PM
Started	May 2, 2019 12:00:00 AM	
Completed	May 3, 2019 10:32:00 AM	May 3, 2019 10:32:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: vehicle won't start

Cause: bad starter

Correction: Replaced starter

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: SW Shop Work Order

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Delva, Terry	0.9	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 02-MAY-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	May 2, 2019 3:11:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	May 2, 2019 3:11:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	May 2, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:11:21 PM		
4 - Have you performed the proper LOTO?	Done		TDELVA	May 2, 2019 3:11:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	May 2, 2019 3:11:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	May 2, 2019 3:11:21 PM	No	
20 - Miles			TDELVA	May 2, 2019 3:11:21 PM	No	
30 - Kilometers			TDELVA	May 2, 2019 3:11:21 PM	No	
40 - Hours			TDELVA	May 2, 2019 3:11:21 PM	No	


Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.90
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52396219
Invoice No. 55345 - 52396219

Client Department:

Department: 55345M

Work Order Description

Starter

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 188,732 - DH

Activity Header

Activity: 15 032/000/000 CRANKING

Activity Note: Starter

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
02-May-19	DL3Z-11002-A	STARTER, E350, '14	1	133.95	133.95

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
02-May-19	Delva, Terry	1.35	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	133.95
Labor:	0.00
Labor Hours:	1.35
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	133.95

Work Order Footer

Work Order 52396219 Total

Parts:	133.95
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	133.95



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52275365
Invoice No. 55345 - 52275365

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 186,582 - DH

Chronology

Reported	Apr 16, 2019 1:38:50 PM	Apr 16, 2019 1:38:50 PM
Started	Apr 16, 2019 12:00:00 AM	
Completed	Apr 16, 2019 11:15:00 PM	Apr 16, 2019 11:15:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA SERVICE

CAUSE: PREVENTIVE MAINTENANCE

CORRECTION: PERFORM AND COMPLETED PMA SERVICE

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: VAMRITTEEMAL Performed on: 16-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,100 - Safety Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,170 - Check Fast Idle	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
10,190 - Check Reverse Warning System	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,100 - Check Parking Brake	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,150 - Perform Brake Test	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,170 - FRA Check Door Operation	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,240 - FRA Check Interior Lights	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,260 - Check Stop Request System	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
22,110 - Check Emergency Hatches	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
22,120 - Check All Safety Equipment	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,310 - Check Passenger Doors	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
33,100 - Check Lights and Reflectors	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,420 - Check Hood	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,130 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,140 - FRA Check Intake System	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,180 - FRA Check for Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
50,510 - Check Entire Steering System	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,630 - Check and Record Tread Depth	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,650 - Check Sidewall Wear	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,710 - Check Vibration Damper	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,730 - FRA Check Starter	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,770 - FRA Check Exhaust System	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,120 - Check Suspension Components	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,135 - Brake Rotor LF	39.82 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,137 - Brake Rotor LR	35.62 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,138 - Brake Rotor RR	35.63 Inch		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,150 - Check King Pins	-	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
80,810 - Completion of PMI Report	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52349720
Invoice No. 55345 - 52349720

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Replaced rear brakes		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	186,582 - DH

Chronology

Reported	Apr 16, 2019 10:28:04 PM	Apr 16, 2019 10:28:04 PM
Started	Apr 16, 2019 12:00:00 AM	
Completed	Apr 16, 2019 11:15:00 PM	Apr 16, 2019 11:15:00 PM
Down Time		

Work Order Notes

Line 10 Replaced rear brakes

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 16-APR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
20 - Miles			VAMRITTEEMAL	Apr 16, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:30:26 PM		
30 - Kilometers			VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	
40 - Hours			VAMRITTEEMAL	Apr 16, 2019 10:30:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52275365
Invoice No. 55345 - 52275365

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 186,582 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: VAMRITTEEMAL Performed on: 16-APR-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
101,000 - FRA Change Oil Filters	Yes		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
102,000 - FRA Drain Engine Oil	Yes		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
103,000 - FRA Check Transmission Fluid	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
104,000 - Lubricate Chassis	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
105,000 - Replace or Clean A/C Filters	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		VAMRITTEEMAL	Apr 16, 2019 10:27:57 PM	No	

Activity Sub Total

		Activity 20 Sub Total	
		Parts:	1.96
		Labor:	0.00
		Labor Hours:	1.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52349720
Invoice No. 55345 - 52349720

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Replaced rear brakes		Status:	40 - Closed (40)
Requested By:	VAMRITTEEMAL	Priority:	-
Created By:	VAMRITTEEMAL	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	186,582 - DH
Potential Warranty:	No		

Activity Header
Activity:20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Apr-19	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	1	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	1.00	Labor Hours:	1.00
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		47.81	

Work Order Footer		Work Order 52349720 Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	1.27	Labor Hours:	1.27
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		47.81	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52275365
Invoice No. 55345 - 52275365

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 186,582 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Apr-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 16-APR-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
20 - Miles			VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
30 - Kilometers			VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	
40 - Hours			VAMRITTEEMAL	Apr 16, 2019 9:56:00 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52275365 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.77
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52165553
Invoice No. 55345 - 52165553

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 182,563 - DH

Chronology

Reported	Mar 21, 2019 11:35:43 AM	Mar 21, 2019 11:35:43 AM
Started	Mar 21, 2019 12:00:00 AM	
Completed	Mar 22, 2019 12:16:00 AM	Mar 22, 2019 12:16:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Service

CORRECTION:Perform pmA Service

Oil filter B329 Qty1

Engine oil 5w20 qty 7 Qts

Air filter PA4075 Qty1

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-19	Gaspard,Ronald	1.6	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 21-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Mar 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:30:26 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:30:26 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Mar 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:30:26 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		RGASPARD	Mar 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:30:26 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Mar 21, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:30:26 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 21, 2019 11:30:26 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 21, 2019 11:30:26 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.60
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52165553
Invoice No. 55345 - 52165553

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 182,563 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Mar-19	B329	FILTER, OIL, SPIN-ON SEE P550965	1	1.96	1.96
21-Mar-19	PA4075	FILTER, AIR SEE P546597	1	5.28	5.28

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-19	Gaspard,Ronald	1.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 21-MAR-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 21, 2019 11:31:06 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 21, 2019 11:31:06 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 21, 2019 11:31:06 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 21, 2019 11:31:06 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 21, 2019 11:31:06 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 21, 2019 11:31:06 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 21, 2019 11:31:06 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 21, 2019 11:31:06 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	7.24
	Labor:	0.00
	Labor Hours:	1.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.24



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52165553
Invoice No. 55345 - 52165553

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 182,563 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
21-Mar-19	Gaspard,Ronald	0.25	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 21-MAR-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 21, 2019 11:31:52 PM	No	
20 - Miles			RGASPARD	Mar 21, 2019 11:31:52 PM	No	
30 - Kilometers			RGASPARD	Mar 21, 2019 11:31:52 PM	No	
40 - Hours			RGASPARD	Mar 21, 2019 11:31:52 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52165553 Total	
	Parts:	7.24
	Labor:	0.00
	Labor Hours:	2.93
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.24



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52224408
Invoice No. 55345 - 52224408

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Engine light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	181,463 - DH

Chronology		
Reported	Mar 5, 2019 2:38:53 PM	Mar 5, 2019 2:38:53 PM
Started	Mar 5, 2019 12:00:00 AM	
Completed	Mar 6, 2019 2:45:25 PM	Mar 6, 2019 2:45:25 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint:check engine light on

Cause: check computer system found cylinder 4 misfire

Correction:Replaced ignition coil and spark plug, retest system and road test vehicle ok at this time

Parts:
1 ignition coil e262
1 spark plug ap103

Activity Header	
Activity:5 999 TOTAL VEHICLE	
Activity Note: Personal Risk Assessment	
Reason for Repair:	05 Inspection, Routine
Work Accomplished:	06 Inspect
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	

Check List																				
5 Desc: Personal Risk Assessment																				
Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 05-MAR-19																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
20 - Miles			JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
30 - Kilometers			JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
40 - Hours			JAPEREZ	Mar 5, 2019 2:44:53 PM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 5 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>0.00</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.00</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>0.00</td> </tr> </tbody> </table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.00																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52224408
Invoice No. 55345 - 52224408

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Engine light on		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	181,463 - DH

Activity Header
Activity:15 033 IGNITION
Activity Note: Engine light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Mar-19	AP103	PLUG, SPARK	1	2.9	2.9
05-Mar-19	E262	COIL, IGNITION	1	34.73	34.73

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Mar-19	Perez,Javier	1.8333333	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	37.63
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	37.63

Work Order Footer	
Work Order 52224408 Total	
Parts:	37.63
Labor:	0.00
Labor Hours:	1.83
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	37.63



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52207571
Invoice No. 55345 - 52207571

Client Department:

Department: 55345M

Work Order Description

Weld rear end

Requested By: JAPEREZ

Created By: JAPEREZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 180,453 - DH

Chronology

Reported	Feb 27, 2019 1:38:25 PM	Feb 27, 2019 1:38:25 PM
Started	Feb 27, 2019 12:00:00 AM	
Completed	Feb 27, 2019 2:48:40 PM	Feb 27, 2019 2:48:40 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:weld rear end

Cause: while inspecting vehicle found rear differential left axle tube came out of original position

Correction:removed tires and U joints from spring suspension to reinstall axle tube to original position and proceed to weld axle tube

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 27-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
20 - Miles			JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
30 - Kilometers			JAPEREZ	Feb 27, 2019 1:48:15 PM	No	
40 - Hours			JAPEREZ	Feb 27, 2019 1:48:15 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52207571
Invoice No. 55345 - 52207571


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Weld rear end		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	180,453 - DH

Activity Header				
Activity: 15 022 AXLE, DRIVEN, REAR (POWER UNITS & TRAILERS)				
Activity Note: Weld rear end				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Feb-19	Perez,Javier	4.5	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	4.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 52207571 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	4.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52084014
Invoice No. 55345 - 52084014

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 178,500 - DH

Chronology

Reported	Feb 12, 2019 12:01:18 PM	Feb 12, 2019 12:01:18 PM
Started	Feb 12, 2019 12:00:00 AM	
Completed	Feb 12, 2019 11:30:00 PM	Feb 12, 2019 11:30:00 PM
Down Time		

Work Order Notes

Line 10 Perform PMC Service Change Oil & Filter. Lube all Pivoting Points. Check brakes Clean batteries.&Perform Transmission Service/ differential service

ATF Fluid Qty (9.0) Qt

Gear Oil (3.0) Qt

Oil 5W20QTY (7.0) Qt

Parts# B329 Qty (1)

Parts #20021 Qty (1)

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-19	Arthurs,Durvin	3.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 12-FEB-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,420 - Check Hood	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,133 - Brake Pad Thickness LR	9 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,134 - Brake Pad Thickness RR	9 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,135 - Brake Rotor LF	1.554 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,137 - Brake Rotor LR	1.654 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,138 - Brake Rotor RR	1.655 Inch		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Feb 12, 2019 11:15:02 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Feb 12, 2019 11:15:02 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		3.50
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52084014
Invoice No. 55345 - 52084014

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 178,500 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Feb-19	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27
12-Feb-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-19	Arthurs,Durvin	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM C						
Task: PM C SERVICE Performed by: DARTHURS Performed on: 12-FEB-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	NA	DARTHURS	Feb 12, 2019 11:17:04 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	Feb 12, 2019 11:17:04 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
302,000 - Check Toe-In and Record Reading	-	NA	DARTHURS	Feb 12, 2019 11:17:04 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	NA	DARTHURS	Feb 12, 2019 11:17:04 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	
305,000 - FRA Change Differential Fluid	Yes		DARTHURS	Feb 12, 2019 11:17:04 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	19.23
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52084014
Invoice No. 55345 - 52084014

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	178,500 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Feb-19	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 12-FEB-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
3 - Are you wearing the appropriate PPE?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
4 - Have you performed the proper LOTO?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 12, 2019 11:17:45 PM	No	
20 - Miles			DARTHURS	Feb 12, 2019 11:17:45 PM	No	
30 - Kilometers			DARTHURS	Feb 12, 2019 11:17:45 PM	No	
40 - Hours			DARTHURS	Feb 12, 2019 11:17:45 PM	No	

Activity Sub Total	Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.08
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52084014 Total	
	Parts:	19.23
	Labor:	0.00
	Labor Hours:	4.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52086879
Invoice No. 55345 - 52086879

Client Department:

Department: 55345M

Work Order Description

Radiator

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 174,288 - DH

Chronology

Reported	Jan 16, 2019 3:51:34 PM	Jan 16, 2019 3:51:34 PM
Started	Jan 16, 2019 12:00:00 AM	
Completed	Jan 21, 2019 1:12:31 PM	Jan 21, 2019 1:12:31 PM
Down Time		

Work Order Notes

Line 10 Replaced Radiator

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-19	Delva,Terry	0.9	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc:

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 16-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 16, 2019 3:54:18 PM	No	
20 - Miles			TDELVA	Jan 16, 2019	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:54:18 PM		
30 - Kilometers			TDELVA	Jan 16, 2019 3:54:18 PM	No	
40 - Hours			TDELVA	Jan 16, 2019 3:54:18 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.90
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52086879
Invoice No. 55345 - 52086879

Client Department:

Department: 55345M

Work Order Description

Radiator

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 174,288 - DH

Activity Header

Activity: 15 042 COOLING SYSTEM

Activity Note: Radiator

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Jan-19	1411886	RECEIVER/DEHYDRATOR, A/C	1	35.76	35.76
16-Jan-19	G1000382282CSF	RADIATOR, E450	1	195.92	195.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Jan-19	Delva, Terry	1.4833333	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	231.68
Labor:	0.00
Labor Hours:	1.48
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	231.68

Work Order Footer

Work Order 52086879 Total

Parts:	231.68
Labor:	0.00
Labor Hours:	2.38
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	231.68



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 52082351
Invoice No. 55345 - 52082351

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front Brakes Motor Mounts			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	174,288 - DH

Chronology

Reported	Jan 15, 2019 4:30:02 PM	Jan 15, 2019 4:30:02 PM
Started	Jan 15, 2019 12:00:00 AM	
Completed	Jan 16, 2019 11:34:03 AM	Jan 16, 2019 11:34:03 AM
Down Time		

Work Order Notes

Line 10 Replaced front brakes and caliper pin(1)
Replaced Motor mounts

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-19	8C2Z-2C150-C	PIN, CALIPER, BRAKE, DISC, FRONT SAME AS BKCOE10	1	19.81	19.81

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-19	Delva,Terry	1.75	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 15, 2019 4:55:10 PM	No	
20 - Miles			TDELVA	Jan 15, 2019 4:55:10 PM	No	
30 - Kilometers			TDELVA	Jan 15, 2019 4:55:10 PM	No	
40 - Hours			TDELVA	Jan 15, 2019 4:55:10 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	19.81
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	19.81



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 52082351
Invoice No. 55345 - 52082351

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Front Brakes Motor Mounts		Status:	40 - Closed (40)
Requested By:	TDELVA	Priority:	-
Created By:	TDELVA	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	174,288 - DH
Potential Warranty:	No		

Activity Header					
Activity:20 013/000/000 BRAKES					
Activity Note: Front Brakes					
Reason for Repair:		39 Natural Causes			
Work Accomplished:		03 Replace New			
Part Failure:		44 Worn			
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-19	8C2Z-2V001-D	PADS, BRAKE, DISC, FRONT	1	48.87	48.87
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
15-Jan-19	Delva, Terry	1.5833333	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:	48.87	
			Labor:	0.00	
			Labor Hours:	1.58	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	48.87	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 52082351
Invoice No. 55345 - 52082351

Client Department:
Department: 55345M
Work Order Description
Front Brakes Motor Mounts
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No
Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 174,288 - DH

Activity Header
Activity:30 040/000/000 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: Motor Mounts
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-19	5U9Z-6038-AA	MOUNT, ENGINE, RH	1	52	52
15-Jan-19	F7UZ-6038-EB	INSULATOR, SUPPORT, ENGINE, FRONT, LH	1	48.11	48.11

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-19	Delva, Terry	1.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 30 Sub Total	
Parts:	100.11
Labor:	0.00
Labor Hours:	1.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	100.11

Work Order Footer	
Work Order 52082351 Total	
Parts:	168.79
Labor:	0.00
Labor Hours:	4.40
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	168.79



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51986864
Invoice No. 55345 - 51986864

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	174,288 - DH

Chronology		
Reported	Jan 15, 2019 10:07:26 AM	Jan 15, 2019 10:07:26 AM
Started	Jan 15, 2019 12:00:00 AM	
Completed	Jan 16, 2019 9:00:00 AM	Jan 16, 2019 9:00:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: Service due

CORRECTION: Performed and completed pmA
Changed engine oil and replaced engine oil filter
Replaced rear AC filter

Activity Header						
Activity: 10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: A PM Level A						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
15-Jan-19	Delva,Terry	1.2333333	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 15-JAN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,420 - Check Hood	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,670 - Check Dual Mating With Square	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,132 - Brake Pad Thickness RF	4 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,135 - Brake Rotor LF	39.7 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,137 - Brake Rotor LR	38.7 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,138 - Brake Rotor RR	38.7 Inch		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,150 - Check King Pins	-	na	TDELVA	Jan 15, 2019 4:28:05 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jan 15, 2019 4:28:05 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51986864
Invoice No. 55345 - 51986864

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 174,288 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Jan-19	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-19	Delva,Terry	1.3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: TDELVA Performed on: 15-JAN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jan 15, 2019 4:28:59 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jan 15, 2019 4:28:59 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jan 15, 2019 4:28:59 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jan 15, 2019 4:28:59 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jan 15, 2019 4:28:59 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jan 15, 2019 4:28:59 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	TDELVA	Jan 15, 2019 4:28:59 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jan 15, 2019 4:28:59 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51986864
Invoice No. 55345 - 51986864

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 174,288 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Jan-19	Delva, Terry	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 15-JAN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 15, 2019 4:29:21 PM	No	
20 - Miles			TDELVA	Jan 15, 2019 4:29:21 PM	No	
30 - Kilometers			TDELVA	Jan 15, 2019 4:29:21 PM	No	
40 - Hours			TDELVA	Jan 15, 2019 4:29:21 PM	No	


Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 51986864 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.95
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52050869
Invoice No. 55345 - 52050869

Client Department:

Department: 55345M

Work Order Description

Scheduled

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 173,020 - DH

Chronology

Reported	Jan 7, 2019 12:33:01 PM	Jan 7, 2019 12:33:01 PM
Started	Jan 7, 2019 12:00:00 AM	
Completed	Jan 8, 2019 9:56:26 AM	Jan 8, 2019 9:56:26 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:fuel gauge bad reading

Cause: Flim bad. Normal wear

Correction:removed and replaced Flim.

Part. Flim

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 07-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
20 - Miles			RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
30 - Kilometers			RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	
40 - Hours			RAUODRIGUEZ	Jan 7, 2019 12:40:44 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52050869
Invoice No. 55345 - 52050869

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Scheduled		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	173,020 - DH

Activity Header
Activity:15 044 FUEL SYSTEM
Activity Note: Fuel gauge bad reading
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Jan-19	Rodriguez,Raul	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 52050869 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52052133
Invoice No. 55345 - 52052133

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Replaced 1 battery		Ford E450 Champion Challenger	
Requested By:	VAMRITTEEMAL	Status:	40 - Closed (40)
Created By:	VAMRITTEEMAL	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	173,020 - DH

Chronology		
Reported	Jan 7, 2019 3:48:20 PM	Jan 7, 2019 3:48:20 PM
Started	Jan 7, 2019 12:00:00 AM	
Completed	Jan 7, 2019 3:53:00 PM	Jan 7, 2019 3:53:00 PM
Down Time		

Work Order Notes

Line 10 Rear battery tested low
Replaced bad battery and swapped placement
No charging issues at this time

Activity Header				
Activity: 10 031/005/000 CHARGER, BATTERY, ON-BOARD, VEHICLES, PROPELLED, ELECTRICALLY				
Activity Note: Replaced 1 battery				
Reason for Repair:		05 Inspection, Routine		
Work Accomplished:		03 Replace New		
Part Failure:		43 Weak		
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Jan-19	AMRIT TEEMAL,VISHNU	0.75	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
		Activity 10 Sub Total		
		Parts:	0.00	
		Labor:	0.00	
		Labor Hours:	0.75	
		Sublet Parts:	0.00	
		Sublet Labor:	0.00	
		Activity Sub Total	0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52052133
Invoice No. 55345 - 52052133

Client Department:		Equipment No.:	4602-P
Department:	55345M	VIN:	1FDFE4FSXEDB17155
Work Order Description			Ford E450 Champion Challenger
Replaced 1 battery		Status:	40 - Closed (40)
Requested By:	VAMRITTEEMAL	Priority:	-
Created By:	VAMRITTEEMAL	Driver:	
Assigned To:		Phone:	
Class:	-	ETA:	
Arrangement:	Unassigned	Meter:	173,020 - DH
Potential Warranty:	No		

Activity Header
Activity:20 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Jan-19	AMRIT TEEMAL,VISHNU	0.2666666	0	0

Activity Sublet
No Data Available


Check List						
20 Desc: Task: PRA and Meter Readings Performed by: VAMRITTEEMAL Performed on: 07-JAN-19						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
3 - Are you wearing the appropriate PPE?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
4 - Have you performed the proper LOTO?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
20 - Miles			VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
30 - Kilometers			VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	
40 - Hours			VAMRITTEEMAL	Jan 7, 2019 3:52:31 PM	No	

Activity Sub Total	Activity 20 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.27
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 52052133 Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	1.02
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 52041381
Invoice No. 55345 - 52041381

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Lift SeatBelt			Ford E450 Champion Challenger
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	172,638 - DH

Chronology

Reported	Jan 3, 2019 11:13:53 AM	Jan 3, 2019 11:13:53 AM
Started	Jan 3, 2019 12:00:00 AM	
Completed	Jan 3, 2019 11:45:15 AM	Jan 3, 2019 11:45:15 AM
Down Time		

Work Order Notes

Line 10 Replaced Lift SeatBelt Assembly

Activity Header

Activity: 10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jan-19	31579KS	BELT, W/C	1	75.46	75.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva, Terry	0.3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 03-JAN-19

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	
3 - Are you wearing the appropriate PPE?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	
4 - Have you performed the proper LOTO?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jan 3, 2019 11:18:24 AM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			TDELVA	Jan 3, 2019 11:18:24 AM	No	
30 - Kilometers			TDELVA	Jan 3, 2019 11:18:24 AM	No	
40 - Hours			TDELVA	Jan 3, 2019 11:18:24 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	75.46
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	75.46



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 52041381
Invoice No. 55345 - 52041381

Client Department:
Department: 55345M
Work Order Description
Lift SeatBelt
Requested By: TDELVA
Created By: TDELVA
Assigned To:
Class: -
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: -
Driver:
Phone:
ETA:
Meter: 172,638 - DH

Activity Header Activity: 20 068/003/000 SYSTEM, HYDRAULIC, LIFTING/UNLOADING Activity Note: WheelChair Lift Reason for Repair: 05 Inspection, Routine Work Accomplished: 03 Replace New Part Failure: Activity Comments:				
Activity Parts No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
03-Jan-19	Delva,Terry	0.5666666	0	0
Activity Sublet No Data Available				
Activity Checklist No Data Available No Data Available				
Activity Sub Total				
			Activity 20 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.57
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 52041381 Total	
			Parts:	75.46
			Labor:	0.00
			Labor Hours:	0.87
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	75.46



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51995556
Invoice No. 55345 - 51995556

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	170,382 - DH

Chronology		
Reported	Dec 14, 2018 8:34:42 AM	Dec 14, 2018 8:34:42 AM
Started	Dec 14, 2018 12:00:00 AM	
Completed	Dec 14, 2018 10:10:27 AM	Dec 14, 2018 10:10:27 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:vehicle won't start

Cause: check computer system found code supply solenoid circuit open

Correction:follow diagrams and diagnostic repair found main relay pin connectors were loose causing not to send power to solenoid tight pin connector. Retest system vehicle start ok at this time

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 14-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
3 - Are you wearing the appropriate PPE?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
4 - Have you performed the proper LOTO?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
20 - Miles			JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
30 - Kilometers			JAPEREZ	Dec 14, 2018 8:44:59 AM	No	
40 - Hours			JAPEREZ	Dec 14, 2018 8:44:59 AM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51995556
Invoice No. 55345 - 51995556

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Vehicle wont start		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	170,382 - DH

Activity Header
Activity:15 030 ELECTRICAL GROUP
Activity Note: Vehicle wont start
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Dec-18	Perez,Javier	3.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	3.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 51995556 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	3.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51986863
Invoice No. 55345 - 51986863

Client Department:

Department: 55345M

Work Order Description

Needs rear brakes job

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 170,013 - DH

Chronology

Reported	Dec 12, 2018 12:29:55 AM	Dec 12, 2018 12:29:55 AM
Started	Dec 12, 2018 12:00:00 AM	
Completed	Dec 12, 2018 4:29:00 PM	Dec 12, 2018 4:29:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:needs rear brakes job

Cause: wear

Correction:Replaced rear brake pads and lube guide pins
Torque wheels 140 lbs second torque 140 lbs
Part number 8C2Z-2V200-C Qty1

Activity Header

Activity:10 999/999/999 TOTAL VEHICLE

Activity Note: PERSONAL RISK ASSESMENT

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-18	Gaspard,Ronald	0.1333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: PERSONAL RISK ASSESMENT

Check List						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-DEC-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 12, 2018 4:25:01 PM	No	
20 - Miles			RGASPARD	Dec 12, 2018 4:25:01 PM	No	
30 - Kilometers			RGASPARD	Dec 12, 2018 4:25:01 PM	No	
40 - Hours			RGASPARD	Dec 12, 2018 4:25:01 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:

Labor:

Labor Hours:

Sublet Parts:

Sublet Labor:

Activity Sub Total

0.00

0.00

0.13

0.00

0.00

0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51986863
Invoice No. 55345 - 51986863

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Needs rear brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	170,013 - DH

Activity Header
Activity:20 013/000/000 BRAKES
Activity Note:
Reason for Repair: 39 Natural Causes
Work Accomplished: 03 Replace New
Part Failure: 44 Worn
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Dec-18	8C2Z-2V200-C	PADS, BRAKE, DISC, REAR	1	47.81	47.81

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-18	Gaspard,Ronald	1.6666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	1.67	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	47.81

Work Order Footer		Work Order 51986863 Total	
Parts:	47.81	Labor:	0.00
Labor Hours:	1.80	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	47.81



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51910508
Invoice No. 55345 - 51910508

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 170,013 - DH

Chronology

Reported	Dec 11, 2018 1:46:37 PM	Dec 11, 2018 1:46:37 PM
Started	Dec 12, 2018 12:00:00 AM	
Completed	Dec 12, 2018 12:30:00 AM	Dec 12, 2018 12:30:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:Perform PMA Service

Oil filter B329 qty1

Engine oil 5W20Qty qty 7 Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-18	Gaspard,Ronald	1.5833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 12-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,100 - Safety Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,420 - Check Hood	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,133 - Brake Pad Thickness LR	4 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,134 - Brake Pad Thickness RR	4 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Dec 12, 2018 12:26:23 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Dec 12, 2018 12:26:23 AM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51910508
Invoice No. 55345 - 51910508

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 170,013 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Dec-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-18	Gaspard,Ronald	1.1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 12-DEC-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Dec 12, 2018 12:26:58 AM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Dec 12, 2018 12:26:58 AM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Dec 12, 2018 12:26:58 AM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Dec 12, 2018 12:26:58 AM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Dec 12, 2018 12:26:58 AM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Dec 12, 2018 12:26:58 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Dec 12, 2018 12:26:58 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Dec 12, 2018 12:26:58 AM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	1.10
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51910508
Invoice No. 55345 - 51910508

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 170,013 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Dec-18	Gaspard,Ronald	0.25	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-DEC-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Dec 12, 2018 12:27:25 AM	No	
20 - Miles			RGASPARD	Dec 12, 2018 12:27:25 AM	No	
30 - Kilometers			RGASPARD	Dec 12, 2018 12:27:25 AM	No	
40 - Hours			RGASPARD	Dec 12, 2018 12:27:25 AM	No	


Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.25
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 51910508 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.93
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51908121
Invoice No. 55345 - 51908121

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
6 TIRES REPLACED.		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	165,698 - DH

Chronology		
Reported	Nov 14, 2018 11:57:00 AM	Nov 14, 2018 11:57:00 AM
Started	Nov 14, 2018 12:00:00 AM	
Completed	Nov 14, 2018 11:18:00 PM	Nov 14, 2018 11:18:00 PM
Down Time		

Work Order Notes

Line 10 Complaint.front and rear tires near min. Specs.

Cause.normal wear

Correction. Removed and replaced all tires.


Parts. 6 tires

Activity Header					
Activity: 10 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS					
Activity Note: Needs 6 new tires					
Reason for Repair:		08 Preventive Maintenance			
Work Accomplished:		03 Replace New			
Part Failure:		99 Replaced Before Failure			
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	6	103.6	621.6
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
14-Nov-18	Rodriguez,Raul	1.5333333	0	0	
14-Nov-18	Gaspard,Ronald	3	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:	621.60	
			Labor:	0.00	
			Labor Hours:	4.53	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	

	Activity Sub Total	621.60



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51908121
Invoice No. 55345 - 51908121

Client Department:

Department: 55345M

Work Order Description

6 TIRES REPLACED.

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 165,698 - DH

Activity Header

Activity: 20 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc:

Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 10-DEC-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
20 - Miles			RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
30 - Kilometers			RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	
40 - Hours			RAUODRIGUEZ	Dec 10, 2018 1:35:33 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts: 0.00

Labor: 0.00

	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 51908121 Total	
	Parts:	621.60
	Labor:	0.00
	Labor Hours:	4.53
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	621.60



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51784945
Invoice No. 55345 - 51784945

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	165,698 - DH

Chronology		
Reported	Nov 13, 2018 12:59:17 PM	Nov 13, 2018 12:59:17 PM
Started	Nov 14, 2018 12:00:00 AM	
Completed	Nov 14, 2018 11:16:00 PM	Nov 14, 2018 11:16:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:Service

CORRECTION:Perform PmB Service
Oil filter B329 Qty1
Engine oil 5w20 qty 7 Qts

Activity Header						
Activity: 10 999 TOTAL VEHICLE						
Activity Note: Light Mediu Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
14-Nov-18	Gaspard,Ronald	1.5666666	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Mediu Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 14-NOV-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,633 - Tread Depth RRO	2 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,134 - Brake Pad Thickness RR	6 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Nov 14, 2018 4:31:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 14, 2018 4:31:24 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		1.57
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51784945
Invoice No. 55345 - 51784945

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 165,698 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Nov-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-18	Gaspard, Ronald	1.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: RGASPARD Performed on: 14-NOV-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 14, 2018 4:33:10 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Nov 14, 2018 4:33:10 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Nov 14, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				4:33:10 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Nov 14, 2018 4:33:10 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Nov 14, 2018 4:33:10 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51784945
Invoice No. 55345 - 51784945

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 165,698 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Nov-18	Gaspard,Ronald	0.3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-NOV-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 14, 2018 4:34:17 PM	No	
20 - Miles			RGASPARD	Nov 14, 2018 4:34:17 PM	No	
30 - Kilometers			RGASPARD	Nov 14, 2018 4:34:17 PM	No	
40 - Hours			RGASPARD	Nov 14, 2018 4:34:17 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 51784945 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.95
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51864714
Invoice No. 55345 - 51864714

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Lift is not working properly		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	162,987 - DH

Chronology		
Reported	Oct 31, 2018 1:23:31 PM	Oct 31, 2018 1:23:31 PM
Started	Oct 31, 2018 12:00:00 AM	
Completed	Nov 1, 2018 12:18:57 PM	Nov 1, 2018 12:18:57 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

Complaint:lift is not working properly

Cause: lift cylinder is leaking fluid and not hold (front cylinder)

Correction:removed and replaced bad cylinder with used good one, tested, all okay at this time. Lift cycles 13578.

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 31-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
20 - Miles			RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
30 - Kilometers			RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	
40 - Hours			RAUODRIGUEZ	Oct 31, 2018 1:34:55 PM	No	

Activity Sub Total

Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51864714
Invoice No. 55345 - 51864714

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Lift is not working properly		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	162,987 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Lift is not working properly
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
31-Oct-18	Rodriguez,Raul	2.3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	2.30
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 51864714 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	2.30
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51822118
Invoice No. 55345 - 51822118

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
55345 SPARK PLUG Propane BUSES		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	162,110 - DH

Chronology		
Reported	Oct 17, 2018 2:45:39 PM	Oct 17, 2018 2:45:39 PM
Started	Oct 17, 2018 12:00:00 AM	
Completed	Oct 17, 2018 2:56:00 PM	Oct 17, 2018 2:56:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Manufacturer recommended spark plug service by mileage

CAUSE:
Normal wear.

CORRECTION:
Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTSk
Qty 10 Boot
Qty 10 spark plug

Activity Header
Activity: 10 999/999/999 TOTAL VEHICLE
Activity Note: PERSONAL RISK ASSESMENT
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
10 Desc: PERSONAL RISK ASSESMENT
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 17-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
2 - If task requires lifting, are lifts secured, are jack stands used correctly?	-	na	RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
4 - Have you performed the proper LOTO?	Done		RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
20 - Miles			RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
30 - Kilometers			RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	
40 - Hours			RAUODRIGUEZ	Oct 17, 2018 2:56:33 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51822118
Invoice No. 55345 - 51822118

Client Department:

Department: 55345M

Work Order Description

55345 SPARK PLUG Propane BUSSES

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: -

Driver:

Phone:

ETA:

Meter: 162,110 - DH

Activity Header

Activity: 20 040/000/000 ENGINE/MOTOR SYSTEMS GROUP

Activity Note:

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 03 Replace New

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Oct-18	AP103	PLUG, SPARK	10	2.9	29
17-Oct-18	357006	BOOT, COIL-ON-PLUG, IGNITION	10	4.29	42.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
17-Oct-18	Rodriguez,Raul	3.1833333	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total

Parts:	71.90
Labor:	0.00
Labor Hours:	3.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	71.90

Work Order Footer

Work Order 51822118 Total

Parts:	71.90
Labor:	0.00
Labor Hours:	3.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	71.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51706695
Invoice No. 55345 - 51706695

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 160,852 - DH

Chronology

Reported	Oct 4, 2018 2:40:20 PM	Oct 4, 2018 2:40:20 PM
Started	Oct 4, 2018 12:00:00 AM	
Completed	Oct 5, 2018 8:15:00 AM	Oct 5, 2018 8:15:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:Service

CORRECTION:Perform pmA Service

Oil filter B329 Qty1

Engine oil 5w20 qty 7 Qts

Replaced maker lights

Fixed right rear tire

Torque wheels 140 lbs second torque 140 lbs

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-18	Gaspard,Ronald	2.25	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 04-OCT-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		RGASPARD	Oct 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				11:26:41 PM		
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:26:41 PM		
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate	No	na	RGASPARD	Oct 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
with a Yes or No)				11:26:41 PM		
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,614 - Air Pressure RRI	65 Pounds per		RGASPARD	Oct 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:26:41 PM		
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
70,780 - Check Driveline, U-joint and Slip	Done		RGASPARD	Oct 4, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Yokes				11:26:41 PM		
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 4, 2018 11:26:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 4, 2018 11:26:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51706695
Invoice No. 55345 - 51706695

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 160,852 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Oct-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-18	Gaspard, Ronald	1.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 04-OCT-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 4, 2018 11:27:25 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 4, 2018 11:27:25 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 4, 2018 11:27:25 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 4, 2018 11:27:25 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 4, 2018 11:27:25 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 4, 2018 11:27:25 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 4, 2018 11:27:25 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 4, 2018 11:27:25 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51706695
Invoice No. 55345 - 51706695

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 160,852 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Oct-18	Gaspard,Ronald	0.3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 04-OCT-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
1 - Are you properly trained to perform the task?	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
2 - If this repair requires a lift, is the vehicle properly secured on lift and util	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
3 - Are you wearing the appropriate PPE?	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
4 - Have you performed the proper LOTO?	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
5 - Are you aware of the potential risks of performing this repair?	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 4, 2018 11:27:57 PM	No	
20 - Miles			RGASPARD	Oct 4, 2018 11:27:57 PM	No	
30 - Kilometers			RGASPARD	Oct 4, 2018 11:27:57 PM	No	
40 - Hours			RGASPARD	Oct 4, 2018 11:27:57 PM	No	

Activity Sub Total

Activity 30 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.30
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00
Work Order Footer		
	Work Order 51706695 Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	3.63
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51616899
Invoice No. 55345 - 51616899

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 156,549 - DH

Chronology

Reported	Sep 10, 2018 3:15:22 PM	Sep 10, 2018 3:15:22 PM
Started	Sep 10, 2018 12:00:00 AM	
Completed	Sep 10, 2018 11:56:00 PM	Sep 10, 2018 11:56:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:Perform pmA Service

Oil filter B329 Qty1

Engine oil 5w20 qty 7 Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-18	Gaspard,Ronald	1.55	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 10-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 10, 2018 10:59:52 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 10, 2018 10:59:52 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51616899
Invoice No. 55345 - 51616899

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 156,549 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Sep-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-18	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 10-SEP-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 10, 2018 11:00:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 10, 2018 11:00:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 10, 2018 11:00:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 10, 2018 11:00:37 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 10, 2018 11:00:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 10, 2018 11:00:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 10, 2018 11:00:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 10, 2018 11:00:37 PM	No	

Activity Sub Total

		Activity 20 Sub Total	
		Parts:	1.96
		Labor:	0.00
		Labor Hours:	1.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51616899
Invoice No. 55345 - 51616899

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 156,549 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Sep-18	Gaspard, Ronald	0.2666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 10, 2018 11:01:06 PM	No	
20 - Miles			RGASPARD	Sep 10, 2018 11:01:06 PM	No	
30 - Kilometers			RGASPARD	Sep 10, 2018 11:01:06 PM	No	
40 - Hours			RGASPARD	Sep 10, 2018 11:01:06 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 51616899 Total

Parts:	1.96
Labor:	0.00
Labor Hours:	2.82

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51696767
Invoice No. 55345 - 51696767

Client Department:

Department: 55345M

Work Order Description

FRONT A/C NOT BLOWING COLD AIR

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 155,995 - DH

Chronology

Reported	Sep 6, 2018 11:11:00 PM	Sep 6, 2018 11:11:00 PM
Started	Sep 6, 2018 12:00:00 AM	
Completed	Sep 6, 2018 11:27:00 PM	Sep 6, 2018 11:27:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: FRONT A/C NOT BLOWING COLD AIR

Cause: FRONT A/C BLOWER MOTOR

Correction: REPLACE FRONT A/C BLOWER MOTOR, RESISTOR, MOTOR WHEEL, 2 BLOCK TERMINAL SINGLE POLE

PARTS# 3940905 QTY 2

AC2Z-19834-A WHEEL BLOWER MOTOR QTY 1

4C2Z-19A706-AA BLOWER MOTOR RESISTOR QTY 1

MM-840 OR XC2Z-19805-BA QTY 1

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Owens, Arthur	0.25	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Check List						
Task: PRA and Meter Readings Performed by: AOWENS Performed on: 06-SEP-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Sep 6, 2018 11:26:45 PM	No	
20 - Miles			AOWENS	Sep 6, 2018 11:26:45 PM	No	
30 - Kilometers			AOWENS	Sep 6, 2018 11:26:45 PM	No	
40 - Hours			AOWENS	Sep 6, 2018 11:26:45 PM	No	

Activity Sub Total	
Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.25
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51696767
Invoice No. 55345 - 51696767

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FRONT A/C NOT BLOWING COLD AIR		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	155,995 - DH

Activity Header
Activity: 15 001/000/000 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: REPLACE BLOWER MOTOR
Reason for Repair: 04 Driver's Report
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Sep-18	XC2Z-19805-BA	MOTOR, BLOWER SAME AS MM-840	1	60.66	60.66
06-Sep-18	AC2Z-19834-A	WHEEL, MOTOR, BLOWER	3	14.05	42.15
06-Sep-18	3940905	BLOCK, TERMINAL, BATTERY	2	10.66	21.32
06-Sep-18	AC2Z-19834-A	WHEEL, MOTOR, BLOWER	-2	14.05	-28.1

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Sep-18	Owens,Arthur	1.5	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	96.03
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	96.03

Work Order Footer	
Work Order 51696767 Total	
Parts:	96.03
Labor:	0.00
Labor Hours:	1.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	96.03



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51686754
Invoice No. 55345 - 51686754

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE ALTERNATOR, belt, pig tail		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	-
Assigned To:		Driver:	
Class:	-	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	155,538 - DH

Chronology

Reported	Sep 4, 2018 4:50:03 PM	Sep 4, 2018 4:50:03 PM
Started		
Completed	Sep 4, 2018 10:58:00 PM	Sep 4, 2018 10:58:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced alternator Per Carlos
Alternator was already removed
Final voltage 14.13 V.
Alternator Qty:1 part#GC2Z-10346-B
Pig tail Qty1 part#WPT-118
Serpentine Belt Qty:1 part#1360K6

Activity Header

Activity:10 999/999/999 TOTAL VEHICLE

Activity Note:

Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc:

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 04-SEP-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Sep 4, 2018 5:09:24 PM	No	
20 - Miles			CKARLENS	Sep 4, 2018 5:09:24 PM	No	
30 - Kilometers			CKARLENS	Sep 4, 2018 5:09:24 PM	No	
40 - Hours			CKARLENS	Sep 4, 2018 5:09:24 PM	No	

Activity Sub Total

Activity 10 Sub Total

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51686754
Invoice No. 55345 - 51686754

Client Department:
Department: 55345M **Equipment No.:** 4602-P
Work Order Description **VIN:** 1FDFE4FSXEDB17155
REPLACE ALTERNATOR, belt, pig tail Ford E450 Champion Challenger
Requested By: CKARLENS **Status:** 40 - Closed (40)
Created By: CKARLENS **Priority:** -
Assigned To: **Driver:**
Class: - **Phone:**
Arrangement: Unassigned **ETA:**
Potential Warranty: No **Meter:** 155,538 - DH

Activity Header
Activity: 20 031/000/000 CHARGING
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Sep-18	GC2Z-10346-B	ALTERNATOR, E450	1	450	450
04-Sep-18	1360K6	BELT, SERPENTINE, 6-RIB, 136.00" SAME AS 5061360	1	23.51	23.51
04-Sep-18	WPT118	PIGTAIL, SENSOR, CAM SAME AS 1U2Z-14S411-TA	1	36.57	36.57

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 20 Sub Total	
		Parts:	510.08
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	510.08

Work Order Footer		Work Order 51686754 Total	
		Parts:	510.08
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	510.08



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51498919
Invoice No. 55345 - 51498919

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 152,083 - DH

Chronology

Reported	Aug 10, 2018 1:38:53 PM	Aug 10, 2018 1:38:53 PM
Started		
Completed	Aug 13, 2018 8:49:00 AM	Aug 13, 2018 8:49:00 AM
Down Time		

Work Order Notes

Line 10 Tech performed PM-c

Parts used

Oil filter Qty1 part#329

Oil Qty:6.5

Transmission filter Qty1 part#20021

Transmission fluid Qts:10

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 12-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,140 - Check Service Brakes	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,260 - Check Stop Request System	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,420 - Check Hood	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,632 - Tread Depth LF	14 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,150 - Check King Pins	-	na	CKARLENS	Aug 12, 2018 3:20:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Aug 12, 2018 3:20:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51498919
Invoice No. 55345 - 51498919

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 152,083 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
12-Aug-18	20021	FILTER, TRANSMISSION 20021	1	17.27	17.27

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM C Task: PM C SERVICE Performed by: CKARLENS Performed on: 12-AUG-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	CKARLENS	Aug 12, 2018 3:11:32 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		CKARLENS	Aug 12, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				3:11:32 PM		
201,000 - Service Crankcase Breather	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	CKARLENS	Aug 12, 2018 3:11:32 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	CKARLENS	Aug 12, 2018 3:11:32 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	
305,000 - FRA Change Differential Fluid	Yes		CKARLENS	Aug 12, 2018 3:11:32 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	19.23
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51498919
Invoice No. 55345 - 51498919

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 152,083 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 12-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Aug 12, 2018 3:10:03 PM	No	
20 - Miles			CKARLENS	Aug 12, 2018 3:10:03 PM	No	
30 - Kilometers			CKARLENS	Aug 12, 2018 3:10:03 PM	No	
40 - Hours			CKARLENS	Aug 12, 2018 3:10:03 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer


Work Order 51498919 Total

Parts:	19.23
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	19.23



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51570493
Invoice No. 55345 - 51570493

Client Department:

Department: 55345M

Work Order Description

Front tire flat nail

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 151,140 - DH

Chronology

Reported	Aug 5, 2018 3:47:56 PM	Aug 5, 2018 3:47:56 PM
Started	Aug 5, 2018 12:00:00 AM	
Completed	Aug 5, 2018 3:53:00 PM	Aug 5, 2018 3:53:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Front Tire Flat

Cause: Both front tire worn L/F has A Nail

Correction: Mount& Balance both front tire.& Replace on Front.

Parts# 189752 Qty (2)

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 05-AUG-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Aug 5, 2018 3:49:29 PM	No	
20 - Miles			DARTHURS	Aug 5, 2018 3:49:29 PM	No	
30 - Kilometers			DARTHURS	Aug 5, 2018 3:49:29 PM	No	
40 - Hours			DARTHURS	Aug 5, 2018 3:49:29 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51570493
Invoice No. 55345 - 51570493

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Front tire flat nail		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	151,140 - DH

Activity Header
Activity: 15 018/000/000 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 03 Replace New
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Aug-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Aug-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	206.88

Work Order Footer	
Work Order 51570493 Total	
Parts:	206.88
Labor:	0.00
Labor Hours:	1.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	206.88



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51410167
Invoice No. 55345 - 51410167

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 147,683 - DH

Chronology

Reported	Jul 10, 2018 10:54:54 AM	Jul 10, 2018 10:54:54 AM
Started	Jul 10, 2018 12:00:00 AM	
Completed	Jul 10, 2018 10:59:00 PM	Jul 10, 2018 10:59:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: Perform pmA

CAUSE: Preventive Maintenance

CORRECTION: Tech Performed pmA

Oil filter Qty:1 part#329

Oil Qty:7qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-18	KARLENS,Cyrius	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 10-JUL-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,120 - FRA Check All Warning Lights and	Done		CKARLENS	Jul 10, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:50:00 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Jul 10, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:50:00 PM		
20,260 - Check Stop Request System	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,420 - Check Hood	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,442 - Freeze Point	Degree	NA	CKARLENS	Jul 10, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:50:00 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,615 - Air Pressure LRI	70 Pounds per		CKARLENS	Jul 10, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:50:00 PM		
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		CKARLENS	Jul 10, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:50:00 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Jul 10, 2018 10:50:00 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Jul 10, 2018 10:50:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51410167
Invoice No. 55345 - 51410167

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	147,683 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jul-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-18	KARLENS,Cyrius	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: CKARLENS Performed on: 10-JUL-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Jul 10, 2018 10:50:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Jul 10, 2018 10:50:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Jul 10, 2018 10:50:41 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51410167
Invoice No. 55345 - 51410167

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	147,683 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
10-Jul-18	KARLENS,Cyrius	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 10-JUL-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Jul 10, 2018 10:51:17 PM	No	
20 - Miles			CKARLENS	Jul 10, 2018 10:51:17 PM	No	
30 - Kilometers			CKARLENS	Jul 10, 2018 10:51:17 PM	No	
40 - Hours			CKARLENS	Jul 10, 2018 10:51:17 PM	No	


Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 51410167 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.33

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51491059
Invoice No. 55345 - 51491059

Client Department:

Department: 55345M

Work Order Description

Front Heather hose

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 147,338 - DH

Chronology

Reported	Jul 8, 2018 7:04:25 PM	Jul 8, 2018 7:04:25 PM
Started	Jul 8, 2018 12:00:00 AM	
Completed	Jul 8, 2018 7:20:00 PM	Jul 8, 2018 7:20:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint Front heather hose

Cause: Heather hose leaking

Correction: drain radiator Remove& Replace both front heather hose& Refill radiator.& Road test all is O/K.

Parts# BC2Z-18472-CA Qty (1)

Parts # BC2Z-18472-CA Qty (1)

Coolant Qty (3)Qt

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-JUL-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 8, 2018 7:19:53 PM	No	
20 - Miles			DARTHURS	Jul 8, 2018 7:19:53 PM	No	
30 - Kilometers			DARTHURS	Jul 8, 2018 7:19:53 PM	No	
40 - Hours			DARTHURS	Jul 8, 2018 7:19:53 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.08			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51491059
Invoice No. 55345 - 51491059

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front Heather hose		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	147,338 - DH

Activity Header
Activity: 15 042/000/000 COOLING SYSTEM
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 03 Replace New
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jul-18	BC2Z-18472-DA	TUBE, HEATER, WATER	1	20.48	20.48
08-Jul-18	BC2Z-18472-CA	TUBE, HEATER, WATER	1	22.22	22.22

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-18	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	42.70
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	42.70

Work Order Footer	
Work Order 51491059 Total	
Parts:	42.70
Labor:	0.00
Labor Hours:	1.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	42.70



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51426569
Invoice No. 55345 - 51426569

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Upper Glass housing		Ford E450 Champion Challenger	
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	144,442 - DH

Chronology		
Reported	Jun 13, 2018 5:02:18 PM	Jun 13, 2018 5:02:18 PM
Started	Jun 13, 2018 12:00:00 AM	
Completed	Jun 13, 2018 5:14:00 PM	Jun 13, 2018 5:14:00 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: Broken Glass

Cause: Normal wear

Correction:replaced broken glass

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
13-Jun-18	Delva,Terry	0.35	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 13-JUN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 13, 2018 5:08:28 PM	No	
20 - Miles			TDELVA	Jun 13, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				5:08:28 PM		
30 - Kilometers			TDELVA	Jun 13, 2018 5:08:28 PM	No	
40 - Hours			TDELVA	Jun 13, 2018 5:08:28 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.35
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51426569
Invoice No. 55345 - 51426569

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Upper Glass housing		Ford E450 Champion Challenger	
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	144,442 - DH

Activity Header
Activity: 15 999/999/999 TOTAL VEHICLE
Activity Note: Upper Glass hoising
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Jun-18	709770	PIVOT, HOUSING, GLASS, UPPER	1	31.75	31.75

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Jun-18	Delva, Terry	0.5333333	0	0

Activity Sublet
No Data Available

Activity Checklist							
Check List							
15 Desc: Upper Glass hoising							
Task: PRA and Meter Readings Performed by: TDELVA Performed on: 13-JUN-18							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 13, 2018 5:08:14 PM	No		
20 - Miles			TDELVA	Jun 13, 2018 5:08:14 PM	No		
30 - Kilometers			TDELVA	Jun 13, 2018 5:08:14 PM	No		
40 - Hours			TDELVA	Jun 13, 2018 5:08:14 PM	No		


Activity Sub Total		Activity 15 Sub Total	
Parts:	31.75	Parts:	31.75
Labor:	0.00	Labor:	0.00
Labor Hours:	0.53	Labor Hours:	0.53
Sublet Parts:	0.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total	31.75	Activity Sub Total	31.75

Work Order Footer		Work Order 51426569 Total	
Parts:	31.75	Parts:	31.75

	Labor:	0.00
	Labor Hours:	0.88
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	31.75



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51336457
Invoice No. 55345 - 51336457

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 143,520 - DH

Chronology

Reported	Jun 7, 2018 11:07:30 AM	Jun 7, 2018 11:07:30 AM
Started	Jun 8, 2018 12:00:00 AM	
Completed	Jun 8, 2018 12:03:07 PM	Jun 8, 2018 12:03:07 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: Preventive Maintenance

CORRECTION: Perform pmA Service lube all Pivoting Points cross rotate tires completed

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
08-Jun-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Pierre, Hubert J	5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 07-JUN-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,420 - Check Hood	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,150 - FRA Inspect Turbocharger	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jun 7, 2018 3:17:33 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jun 7, 2018 3:17:33 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	1.96
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51336457
Invoice No. 55345 - 51336457

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	143,520 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: HPIERRE Performed on: 08-JUN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jun 8, 2018 9:48:19 AM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jun 8, 2018 9:48:19 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jun 8, 2018 9:48:19 AM	No	

Activity Sub Total	
Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51336457
Invoice No. 55345 - 51336457

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	143,520 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Jun-18	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 08-JUN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jun 8, 2018 9:48:45 AM	No	
20 - Miles			HPIERRE	Jun 8, 2018 9:48:45 AM	No	
30 - Kilometers			HPIERRE	Jun 8, 2018 9:48:45 AM	No	
40 - Hours			HPIERRE	Jun 8, 2018 9:48:45 AM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 51336457 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	5.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51221024
Invoice No. 55345 - 51221024

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 139,350 - DH

Chronology

Reported	May 9, 2018 10:33:07 AM	May 9, 2018 10:33:07 AM
Started	May 9, 2018 12:00:00 AM	
Completed	May 9, 2018 11:04:00 PM	May 9, 2018 11:04:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMB Service

CAUSE: Service due by Mileage.

CORRECTION: Change Oil & Filter Lube all Pivoting Points. check Brakes Clean batteries. Replace drain plugs.

Parts # B329 Qty (1)

Oil 5W20 Qty (7.0) Qt

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,131 - Brake Pad Thickness LF	11 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,132 - Brake Pad Thickness RF	11 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,133 - Brake Pad Thickness LR	11 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,134 - Brake Pad Thickness RR	11 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,135 - Brake Rotor LF	1.556 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,136 - Brake Rotor RF	1.557 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,137 - Brake Rotor LR	1.643 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,138 - Brake Rotor RR	1.645 Inch		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 9, 2018 10:44:50 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 9, 2018 10:44:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51221024
Invoice No. 55345 - 51221024

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	139,350 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM B
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: B PM Level B
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
09-May-18	F75Z-6730-BA	PLUG, DRAIN, OIL, ENGINE, 3.0L	1	6.66	6.66
09-May-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM B Task: PM B SERVICE Performed by: DARTHURS Performed on: 09-MAY-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 9, 2018 10:46:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 9, 2018 10:46:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 9, 2018 10:46:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 9, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:46:13 PM		
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	
201,000 - Service Crankcase Breather	-	NA	DARTHURS	May 9, 2018 10:46:13 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		DARTHURS	May 9, 2018 10:46:13 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		DARTHURS	May 9, 2018 10:46:13 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		DARTHURS	May 9, 2018 10:46:13 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	8.62
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	8.62



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51221024
Invoice No. 55345 - 51221024

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 139,350 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-May-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-MAY-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 9, 2018 10:46:38 PM	No	
20 - Miles			DARTHURS	May 9, 2018 10:46:38 PM	No	
30 - Kilometers			DARTHURS	May 9, 2018 10:46:38 PM	No	
40 - Hours			DARTHURS	May 9, 2018 10:46:38 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 51221024 Total

Parts:	8.62
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	8.62



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51097962
Invoice No. 55345 - 51097962

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 135,248 - DH

Chronology

Reported	Apr 12, 2018 1:04:18 PM	Apr 12, 2018 1:04:18 PM
Started	Apr 12, 2018 12:00:00 AM	
Completed	Apr 12, 2018 11:13:00 PM	Apr 12, 2018 11:13:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:Perform pmA

CAUSE:Preventive Maintenance

CORRECTION: Tech Performed pmA

Parts used

Oil filter Qty:1 part#B329

Oil Qty:6qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrus	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: CKARLENS Performed on: 12-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,100 - Safety Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,140 - Check Service Brakes	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,160 - FRA Check Instruments and Horns	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,170 - Check Fast Idle	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,180 - Check Starter Protection Circuit	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
10,190 - Check Reverse Warning System	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,100 - Check Parking Brake	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,150 - Perform Brake Test	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,170 - FRA Check Door Operation	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,210 - Check Condition of Operator's Area	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,240 - FRA Check Interior Lights	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,260 - Check Stop Request System	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
22,110 - Check Emergency Hatches	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
22,120 - Check All Safety Equipment	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,310 - Check Passenger Doors	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,330 - Check Wheelchair Lift Operation	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,360 - Check for Physical Damage and Decals	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,380 - Check Exterior Compartment Doors	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
33,100 - Check Lights and Reflectors	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,420 - Check Hood	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		CKARLENS	Apr 12, 2018 9:47:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,130 - FRA Check Exhaust System	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,140 - FRA Check Intake System	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,180 - FRA Check for Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,190 - FRA Perform Battery Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
50,510 - Check Entire Steering System	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,620 - Check Valve Stems and Caps	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,630 - Check and Record Tread Depth	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,650 - Check Sidewall Wear	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,660 - Inspect for Cuts and Tears	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,670 - Check Dual Mating With Square	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,710 - Check Vibration Damper	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,730 - FRA Check Starter	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,770 - FRA Check Exhaust System	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,110 - FRA Check Fuel Tank	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,120 - Check Suspension Components	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,131 - Brake Pad Thickness LF	5 Inch	replace front Brakes pads	CKARLENS	Apr 12, 2018 9:47:41 PM	Yes	51220741
77,132 - Brake Pad Thickness RF	5 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,133 - Brake Pad Thickness LR	6 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,134 - Brake Pad Thickness RR	5 Inch	Replace Rear brakes pads	CKARLENS	Apr 12, 2018 9:47:41 PM	Yes	51220741
77,135 - Brake Rotor LF	39.8 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,136 - Brake Rotor RF	39.8 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,137 - Brake Rotor LR	41.8 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,138 - Brake Rotor RR	41.8 Inch		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,140 - FRA Check Brake Hoses	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,150 - Check King Pins	-	NA	CKARLENS	Apr 12, 2018 9:47:41 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
80,810 - Completion of PMI Report	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		CKARLENS	Apr 12, 2018 9:47:41 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 51220741
Invoice No. 55345 - 51220741

Client Department:

Department: 55345M

Work Order Description

FOLLOWUP-->51097962

Requested By: CKARLENS

Created By: CKARLENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 135,248 - DH

Chronology

Reported	Apr 12, 2018 9:47:28 PM	Apr 12, 2018 9:47:28 PM
Started	Apr 12, 2018 12:00:00 AM	
Completed	Apr 12, 2018 11:13:00 PM	Apr 12, 2018 11:13:00 PM
Down Time		

Work Order Notes

Line 10 Tech replaced front/Rear brakes and shifter cable

Front brakes Qty:1

Rear brakes Qty:1

Shifter cable Qty:1

Activity Header

Activity:10 013/000/000 BRAKES

Activity Note: Replace Rear brakes pads

Reason for Repair: 39 Natural Causes

Work Accomplished: 03 Replace New

Part Failure: 44 Worn

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-18	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.9	43.9

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrius	2	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	43.90
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	43.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51097962
Invoice No. 55345 - 51097962

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 135,248 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrius	2	0	0

Activity Sublet

No Data Available

Activity Checklist


Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: CKARLENS Performed on: 12-APR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
101,000 - FRA Change Oil Filters	Yes		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
102,000 - FRA Drain Engine Oil	Yes		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
103,000 - FRA Check Transmission Fluid	Done		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
104,000 - Lubricate Chassis	Done		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
105,000 - Replace or Clean A/C Filters	Done		CKARLENS	Apr 12, 2018 9:38:27 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	CKARLENS	Apr 12, 2018 9:38:27 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		CKARLENS	Apr 12, 2018 9:38:27 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	2.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 51220741
Invoice No. 55345 - 51220741

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP??->51097962		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	135,248 - DH

Activity Header					
Activity: 20 013/000/000 BRAKES					
Activity Note: replace front Brakes pads					
Reason for Repair: 39 Natural Causes					
Work Accomplished: 03 Replace New					
Part Failure: 44 Worn					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-18	BRSD1328	PADS, BRAKE, DISC, FRONT, DUTY, HEAVY, FORD SAME AS PFH132820	1	51.84	51.84
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
12-Apr-18	KARLENS,Cyrius	2	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 20 Sub Total		
			Parts:	51.84	
			Labor:	0.00	
			Labor Hours:	2.00	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	51.84	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51097962
Invoice No. 55345 - 51097962

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	135,248 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrus	0.2333333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 12-APR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 12, 2018 9:37:49 PM	No	
20 - Miles			CKARLENS	Apr 12, 2018 9:37:49 PM	No	
30 - Kilometers			CKARLENS	Apr 12, 2018 9:37:49 PM	No	
40 - Hours			CKARLENS	Apr 12, 2018 9:37:49 PM	No	


Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 51097962 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	4.23

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 51220741
Invoice No. 55345 - 51220741

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FOLLOWUP??->51097962		Ford E450 Champion Challenger	
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	135,248 - DH

Activity Header

Activity:30 027/000/000 TRANSMISSION, MAIN, AUTOMATIC

Activity Note: Replace Shifter Cable

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Apr-18	8C2Z-7E395-A	CABLE, SELECTOR, SHIFT	1	44.69	44.69

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrius	2	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available


No Data Available

Activity Sub Total

Activity 30 Sub Total	
Parts:	44.69
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	44.69



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 51220741
Invoice No. 55345 - 51220741

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
FOLLOWUP-->51097962			
Requested By:	CKARLENS	Status:	40 - Closed (40)
Created By:	CKARLENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	135,248 - DH

Activity Header
Activity:40 999/999/999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Apr-18	KARLENS,Cyrus	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
40 Desc: Task: PRA and Meter Readings Performed by: CKARLENS Performed on: 12-APR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		CKARLENS	Apr 12, 2018 9:56:18 PM	No	
20 - Miles			CKARLENS	Apr 12, 2018 9:56:18 PM	No	
30 - Kilometers			CKARLENS	Apr 12, 2018 9:56:18 PM	No	
40 - Hours			CKARLENS	Apr 12, 2018 9:56:18 PM	No	

Activity Sub Total	
Activity 40 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 51220741 Total	
Parts:	140.43
Labor:	0.00
Labor Hours:	6.33

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	140.43



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51164792
Invoice No. 55345 - 51164792

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Hard drive not working		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	133,480 - DH

Chronology		
Reported	Apr 2, 2018 11:32:54 AM	Apr 2, 2018 11:32:54 AM
Started	Apr 2, 2018 12:00:00 AM	
Completed	Apr 3, 2018 8:13:43 AM	Apr 3, 2018 8:13:43 AM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:
camera system is not working

Cause:
Hard driver is the defective

Correction:
Ordered a hard drive under warranty from Angel traxs

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 02-APR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Apr 2, 2018 11:44:16 AM	No	
20 - Miles			EDTORRES	Apr 2, 2018 11:44:16 AM	No	
30 - Kilometers			EDTORRES	Apr 2, 2018 11:44:16 AM	No	
40 - Hours			EDTORRES	Apr 2, 2018 11:44:16 AM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51164792
Invoice No. 55345 - 51164792

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Hard drive not working		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	133,480 - DH

Activity Header				
Activity:15 050 GROUP, ACCESSORIES				
Activity Note: Hard drive not working				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
02-Apr-18	Torres,Edwin	0.7333333	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.73
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 51164792 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.73
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51097928
Invoice No. 55345 - 51097928

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front Tire& Tag Light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	130,905 - DH

Chronology		
Reported	Mar 14, 2018 11:38:49 PM	Mar 14, 2018 11:38:49 PM
Started	Mar 14, 2018 12:00:00 AM	
Completed	Mar 15, 2018 12:02:00 AM	Mar 15, 2018 12:02:00 AM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: tires

Cause: Tire Worn

Correction: Mount&Balance front Tires.Rotate L/R To Front& New On L/R Remove& Replace Tag Light.
Parts# 189752 Qty (2)
Parts# 3975927 Qty (1)

Activity Header				
Activity:5 999 TOTAL VEHICLE				
Activity Note: Personal Risk Assessment				
Reason for Repair:		05 Inspection, Routine		
Work Accomplished:		06 Inspect		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	0.0833333	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
Check List				
5 Desc: Personal Risk Assessment				

Check List						
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-MAR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 14, 2018 11:40:25 PM	No	
20 - Miles			DARTHURS	Mar 14, 2018 11:40:25 PM	No	
30 - Kilometers			DARTHURS	Mar 14, 2018 11:40:25 PM	No	
40 - Hours			DARTHURS	Mar 14, 2018 11:40:25 PM	No	

Activity Sub Total	
Activity 5 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 51039947
Invoice No. 55345 - 51039947

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 130,905 - DH

Chronology

Reported	Mar 14, 2018 10:21:24 AM	Mar 14, 2018 10:21:24 AM
Started	Mar 14, 2018 12:00:00 AM	
Completed	Mar 15, 2018 12:02:00 AM	Mar 15, 2018 12:02:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil& Filter .Lube all Pivoting Points. check brakes .clean batteries

Parts# B329 Qty (1)

Oil 5W20 Qty (7) Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 14-MAR-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,420 - Check Hood	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,135 - Brake Rotor LF	1.557 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,136 - Brake Rotor RF	1.556 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,137 - Brake Rotor LR	1.645 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,138 - Brake Rotor RR	1.646 Inch		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	Mar 14, 2018 11:33:18 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	Mar 14, 2018 11:33:18 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		1.50
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51097928
Invoice No. 55345 - 51097928

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front Tire& Tag Light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	130,905 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace Tires
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Mar-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	103.44	206.88

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			206.88
Labor:			0.00
Labor Hours:			1.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			206.88



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 51039947
Invoice No. 55345 - 51039947

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 130,905 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Mar-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: DARTHURS Performed on: 14-MAR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	Mar 14, 2018 11:34:14 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	Mar 14, 2018 11:34:14 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	Mar 14, 2018 11:34:14 PM	No	

Activity Sub Total

	Activity 20 Sub Total	
	Parts:	1.96
	Labor:	0.00
	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51097928
Invoice No. 55345 - 51097928

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front Tire& Tag Light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	130,905 - DH

Activity Header
Activity:25 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Remove&Replace Tag Light
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	0.3333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.33
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 51097928 Total	
Parts:			206.88
Labor:			0.00
Labor Hours:			1.42
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			206.88



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 51039947
Invoice No. 55345 - 51039947

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	130,905 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Mar-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-MAR-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Mar 14, 2018 11:34:38 PM	No	
20 - Miles			DARTHURS	Mar 14, 2018 11:34:38 PM	No	
30 - Kilometers			DARTHURS	Mar 14, 2018 11:34:38 PM	No	
40 - Hours			DARTHURS	Mar 14, 2018 11:34:38 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 51039947 Total	
Parts:	1.96
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51042649
Invoice No. 55345 - 51042649

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C fans stay on after you shut vehicle off.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	127,227 - DH

Chronology		
Reported	Feb 15, 2018 8:17:26 AM	Feb 15, 2018 8:17:26 AM
Started	Feb 15, 2018 12:00:00 AM	
Completed	Feb 15, 2018 12:09:54 PM	Feb 15, 2018 12:09:54 PM
Down Time		

Work Order Notes

- Line 10 To file warranty be sure to do the following:
- 1) Enter a COMPLAINT statement for each activity.
 - 2) Enter CAUSE statement in the Notes field of each activity.
 - 3) Enter CORRECTION statement in the Comment section of each activity.
- =====

Complaint:
Rear A/C condenser fans stay on after you shut vehicle off.

Cause:
Rear fans circuit board.

Correction:
Complaint was verified by Carlos V.
Was not able to duplicate the complaint after the initial verification. I suspect the rear A/C condenser relay on the circuit board is getting stuck on the high voltage connection. Relays are soldered on, had to replaced the rear circuit board. Placed vehicle back in service and will monitor for future complaints.

Parts are under warranty.

Activity Header Activity: 5 999 TOTAL VEHICLE Activity Note: Personal Risk Assessment Reason for Repair: 05 Inspection, Routine Work Accomplished: 06 Inspect Part Failure: Activity Comments:
Activity Parts No Data Available
Activity Labor No Data Available
Activity Sublet No Data Available
Activity Checklist

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 15-FEB-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Feb 15, 2018 8:24:27 AM	No	
20 - Miles			EDTORRES	Feb 15, 2018 8:24:27 AM	No	
30 - Kilometers			EDTORRES	Feb 15, 2018 8:24:27 AM	No	
40 - Hours			EDTORRES	Feb 15, 2018 8:24:27 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51042649
Invoice No. 55345 - 51042649

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C fans stay on after you shut vehicle off.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	127,227 - DH

Activity Header				
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION				
Activity Note: Rear A/C fans stay on after you shut vehicle off.				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Feb-18	Torres,Edwin	0.9333333	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.93
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 51042649 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.93
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 50988870
Invoice No. 55345 - 50988870

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 126,799 - DH

Chronology

Reported	Feb 13, 2018 11:15:30 AM	Feb 13, 2018 11:15:30 AM
Started	Feb 13, 2018 12:00:00 AM	
Completed	Feb 13, 2018 11:58:00 PM	Feb 13, 2018 11:58:00 PM
Down Time		

Work Order Notes

Line 10 PMC
Service
Perform pmc Service
Oil filter B329 qty1
Engine oil 5w20 qty7 Qts
Transmission filter 20021 qty1
Transmission fluid 10 Qts
Gear oil 80w90 qty 5qts
Replaced AC filter
Replaced serpentine belt 5061360 qty1
Air filter PA4075 qty1

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Feb-18	Gaspard,Ronald	1.55	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 13-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,420 - Check Hood	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,635 - Tread Depth LRI	14 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,636 - Tread Depth LRO	14 32nds of an inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,137 - Brake Rotor LR	40 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,138 - Brake Rotor RR	40 Inch		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Feb 13, 2018 11:26:00 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Feb 13, 2018 11:26:00 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.55
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 50988870
Invoice No. 55345 - 50988870

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 126,799 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Feb-18	5061360	BELT, SERPENTINE, 6-RIB, 136.02"L X 0.82"W	1	26.47	26.47
13-Feb-18	PA4075	FILTER, AIR SEE P546597	1	5.25	5.25
13-Feb-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.96	1.96
13-Feb-18	20021	FILTER, TRANSMISSION 20021	1	17.04	17.04

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Feb-18	Gaspard,Ronald	3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM C						
Task: PM C SERVICE Performed by: RGASPARD Performed on: 13-FEB-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Feb 13, 2018 11:27:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Feb 13, 2018	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:27:17 PM		
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	Yes		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Feb 13, 2018 11:27:17 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Feb 13, 2018 11:27:17 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Feb 13, 2018 11:27:17 PM	No	
305,000 - FRA Change Differential Fluid	Yes		RGASPARD	Feb 13, 2018 11:27:17 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	50.72
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	50.72



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 50988870
Invoice No. 55345 - 50988870

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 126,799 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Feb-18	Gaspard, Ronald	0.2333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 13-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Feb 13, 2018 11:27:40 PM	No	
20 - Miles			RGASPARD	Feb 13, 2018 11:27:40 PM	No	
30 - Kilometers			RGASPARD	Feb 13, 2018 11:27:40 PM	No	
40 - Hours			RGASPARD	Feb 13, 2018 11:27:40 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.23
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer


Work Order 50988870 Total

Parts:	50.72
Labor:	0.00
Labor Hours:	4.78

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	50.72



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51035870
Invoice No. 55345 - 51035870

Client Department:

Department: 55345M

Work Order Description

Worn Tires

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 126,799 - DH

Chronology

Reported	Feb 11, 2018 5:21:38 PM	Feb 11, 2018 5:21:38 PM
Started	Feb 11, 2018 12:00:00 AM	
Completed	Feb 11, 2018 5:29:00 PM	Feb 11, 2018 5:29:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:

- 1) Enter a COMPLAINT statement for each activity.
- 2) Enter CAUSE statement in the Notes field of each activity.
- 3) Enter CORRECTION statement in the Comment section of each activity.

Complaint: tires

Cause: rear tire Worn

Correction: Mount&Balance all Rear Tires.

Parts#189752 Qty (4)

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-18	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 11-FEB-18

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Feb 11, 2018 5:26:20 PM	No	
20 - Miles			DARTHURS	Feb 11, 2018 5:26:20 PM	No	
30 - Kilometers			DARTHURS	Feb 11, 2018 5:26:20 PM	No	
40 - Hours			DARTHURS	Feb 11, 2018 5:26:20 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51035870
Invoice No. 55345 - 51035870

Client Department:

Department: 55345M

Work Order Description

Worn Tires

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 126,799 - DH

Activity Header

Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Replace rear Tires

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-18	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	4	103.44	413.76

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Feb-18	Arthurs,Durvin	2	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	413.76
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	413.76

Work Order Footer

Work Order 51035870 Total

Parts:	413.76
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	413.76



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 51005542
Invoice No. 55345 - 51005542

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Sun visor		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	124,223 - DH

Chronology		
Reported	Jan 23, 2018 9:48:12 PM	Jan 23, 2018 9:48:12 PM
Started	Jan 23, 2018 12:00:00 AM	
Completed	Jan 23, 2018 10:28:00 PM	Jan 23, 2018 10:28:00 PM
Down Time		

Work Order Notes

Line 10 To file warranty be sure to do the following:
1) Enter a COMPLAINT statement for each activity.
2) Enter CAUSE statement in the Notes field of each activity.
3) Enter CORRECTION statement in the Comment section of each activity.

=====

Complaint: sun Visor

Cause: Sun Visor Retainer missing.

Correction: Replace sun Visor Retainer.
Parts#3C2Z-5404132-AAB Qty (1)

Activity Header				
Activity:5 999 TOTAL VEHICLE				
Activity Note: Personal Risk Assessment				
Reason for Repair:		05 Inspection, Routine		
Work Accomplished:		06 Inspect		
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-18	Arthurs,Durvin	0.0833333	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
Check List				
5 Desc: Personal Risk Assessment				
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 23-JAN-18				

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 23, 2018 10:18:10 PM	No	
20 - Miles			DARTHURS	Jan 23, 2018 10:18:10 PM	No	
30 - Kilometers			DARTHURS	Jan 23, 2018 10:18:10 PM	No	
40 - Hours			DARTHURS	Jan 23, 2018 10:18:10 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 51005542
Invoice No. 55345 - 51005542

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Sun visor		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	124,223 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace sun visor retainer
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jan-18	3C2Z-5404132-AAB	CLIP, VISOR, SUN	1	5.87	5.87

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
23-Jan-18	Arthurs,Durvin	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			5.87
Labor:			0.00
Labor Hours:			0.17
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			5.87

Work Order Footer		Work Order 51005542 Total	
Parts:			5.87
Labor:			0.00
Labor Hours:			0.25
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			5.87



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 49393198
Invoice No. 55345 - 49393198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	122,730 - DH

Chronology		
Reported	Jan 11, 2018 2:54:17 PM	Jan 11, 2018 2:54:17 PM
Started	Jan 11, 2018 12:00:00 AM	
Completed	Jan 12, 2018 10:28:00 AM	Jan 12, 2018 10:28:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:Service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 Qts

Activity Header						
Activity: 10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
11-Jan-18	Gaspard,Ronald	1.5166666	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 11-JAN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Jan 11, 2018 11:21:03 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 11, 2018 11:21:03 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 49393198
Invoice No. 55345 - 49393198

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 122,730 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jan-18	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-18	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 11-JAN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 11, 2018 11:21:49 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 11, 2018 11:21:49 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 11, 2018 11:21:49 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 11, 2018 11:21:49 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Jan 11, 2018 11:21:49 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 11, 2018 11:21:49 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Jan 11, 2018 11:21:49 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Jan 11, 2018 11:21:49 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 49393198
Invoice No. 55345 - 49393198

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	122,730 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
11-Jan-18	Gaspard,Ronald	0.2	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 11-JAN-18						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 11, 2018 11:22:12 PM	No	
20 - Miles			RGASPARD	Jan 11, 2018 11:22:12 PM	No	
30 - Kilometers			RGASPARD	Jan 11, 2018 11:22:12 PM	No	
40 - Hours			RGASPARD	Jan 11, 2018 11:22:12 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.20
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 49393198 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.72

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 50963192
Invoice No. 55345 - 50963192

Client Department:

Department: 55345M

Work Order Description

Steering box Leaking

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 121,665 - DH

Chronology

Reported	Dec 23, 2017 12:13:01 AM	Dec 23, 2017 12:13:01 AM
Started	Dec 24, 2017 12:00:00 AM	
Completed	Dec 24, 2017 3:33:00 PM	Dec 24, 2017 3:33:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: Steering Box

CAUSE: Steering Box Leaking.

CORRECTION: Remove& Replace Steering Box ./Fill with P/S Fluid. Replace pitman arm& Nut
Parts#GU2Z3504ASUB Qty (1) under Warranty
Parts# HC2C-3504-AG Qty (1) under Warranty.
P/S Fluid Qty (1) Qt

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Dec-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Dec 24, 2017 3:23:41 PM	No	
20 - Miles			DARTHURS	Dec 24, 2017 3:23:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
30 - Kilometers			DARTHURS	Dec 24, 2017 3:23:41 PM	No		
40 - Hours			DARTHURS	Dec 24, 2017 3:23:41 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.08
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 50963192
Invoice No. 55345 - 50963192

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Steering box Leaking		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	121,665 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Remove& Replace Steering Box.				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Dec-17	Arthurs,Durvin	1	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.00
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 50963192 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.08
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 50951138
Invoice No. 55345 - 50951138

Client Department:

Department: 55345M

Work Order Description

Cameras not working

Requested By: JAPEREZ

Created By: JAPEREZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 120,983 - DH

Chronology

Reported	Dec 15, 2017 11:29:48 AM	Dec 15, 2017 11:29:48 AM
Started	Dec 15, 2017 12:00:00 AM	
Completed	Dec 15, 2017 1:54:00 PM	Dec 15, 2017 1:54:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: cameras not working

CAUSE:inspect cameras system found combination cable damage causing no power to camera system

CORRECTION: replace combination cable, retest system ok at this time

Parts:

1 combination cable under warranty

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: JAPEREZ Performed on: 15-DEC-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JAPEREZ	Dec 15, 2017 11:56:49 AM	No	
20 - Miles			JAPEREZ	Dec 15, 2017 11:56:49 AM	No	
30 - Kilometers			JAPEREZ	Dec 15, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				11:56:49 AM			
40 - Hours			JAPEREZ	Dec 15, 2017 11:56:49 AM	No		
Activity Sub Total				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 50951138
Invoice No. 55345 - 50951138

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Cameras not working		Ford E450 Champion Challenger	
Requested By:	JAPEREZ	Status:	40 - Closed (40)
Created By:	JAPEREZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	120,983 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Camera system not working
Reason for Repair: 38 Warranty
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-17	Perez,Javier	1.5	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 50951138 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 46125471
Invoice No. 55345 - 46125471

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 118,863 - DH

Chronology

Reported	Nov 24, 2017 5:10:33 PM	Nov 24, 2017 5:10:33 PM
Started	Nov 27, 2017 12:00:00 AM	
Completed	Nov 27, 2017 4:35:00 PM	Nov 27, 2017 4:35:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:Service

CORRECTION:perform PMA service

Oil filter B329 qty 1

Engine oil 5w20 qty 7 Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-17	Gaspard,Ronald	1.55	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 27-NOV-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,150 - Check King Pins	-	NA	RGASPARD	Nov 27, 2017 4:31:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 27, 2017 4:31:24 PM	No	
Activity Sub Total						
				Activity 10 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		1.55
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 46125471
Invoice No. 55345 - 46125471

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 118,863 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Nov-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-17	Gaspard, Ronald	1.0333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 27-NOV-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Nov 27, 2017 4:32:08 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Nov 27, 2017 4:32:08 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Nov 27, 2017 4:32:08 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Nov 27, 2017 4:32:08 PM	No	
104,000 - Lubricate Chassis	-	NA	RGASPARD	Nov 27, 2017 4:32:08 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Nov 27, 2017 4:32:08 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	RGASPARD	Nov 27, 2017 4:32:08 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Nov 27, 2017 4:32:08 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.03
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 46125471
Invoice No. 55345 - 46125471

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	118,863 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Nov-17	Gaspard,Ronald	0.1833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 27-NOV-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 27, 2017 4:32:30 PM	No	
20 - Miles			RGASPARD	Nov 27, 2017 4:32:30 PM	No	
30 - Kilometers			RGASPARD	Nov 27, 2017 4:32:30 PM	No	
40 - Hours			RGASPARD	Nov 27, 2017 4:32:30 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.18
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 46125471 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.77

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 43049824
Invoice No. 55345 - 43049824

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 114,469 - DH

Chronology

Reported	Oct 23, 2017 12:36:35 PM	Oct 23, 2017 12:36:35 PM
Started	Oct 24, 2017 12:00:00 AM	
Completed	Oct 24, 2017 5:36:00 PM	Oct 24, 2017 5:36:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:service

CORRECTION:perform pmB service

Oil filter B329 qty 1

Engine oil 5w20 qty 7 Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard,Ronald	1.5166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-OCT-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,631 - Tread Depth RF	3 32nds of an inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,632 - Tread Depth LF	4 32nds of an inch	needs 2 front tires	RGASPARD	Oct 24, 2017 4:11:34 PM	Yes	46119696
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,120 - Check Suspension Components	-	needs front shock absorbers	RGASPARD	Oct 24, 2017 4:11:34 PM	Yes	46119696
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 24, 2017 4:11:34 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 24, 2017 4:11:34 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.52
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 46119696
Invoice No. 55345 - 46119696

Client Department:

Department: 55345M

Work Order Description

Followup-----> needs 2 front tires and front shock absorbers

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 114,469 - DH

Chronology

Reported	Oct 24, 2017 4:11:34 PM	Oct 24, 2017 4:11:34 PM
Started	Oct 24, 2017 12:00:00 AM	
Completed	Oct 24, 2017 5:36:00 PM	Oct 24, 2017 5:36:00 PM
Down Time		

Work Order Notes

Line 10 Needs front tires and front shock absorbers

Wear

Replaced front tires and shock 2 top bushing

Mounted and balance tires

Torque wheels 140 lbs second torque 140 lbs

Part number tires 189752 qty 2

Shock part number 8C2Z-18124-D qty 2

Bushings part number 6C3Z-18197-AA qty 2

Activity Header

Activity: 10 017 TIRES, TUBES, LINERS & VALVES

Activity Note: needs 2 front tires

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Oct-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.17	210.34

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard, Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	210.34
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	210.34



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 43049824
Invoice No. 55345 - 43049824

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 114,469 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Oct-17	B329(F)	GOING OUT OF SERVICE SEE BALDWIN B329 IN THE FLEET ORG. FILTER, OIL, SPIN-ON	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard,Ronald	1.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: RGASPARD Performed on: 24-OCT-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Oct 24, 2017 4:12:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Oct 24, 2017 4:12:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Oct 24, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				4:12:31 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Oct 24, 2017 4:12:31 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Oct 24, 2017 4:12:31 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 46119696
Invoice No. 55345 - 46119696

Client Department:

Department: 55345M

Work Order Description

Followup-----> needs 2 front tires and front shock absorbers

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 114,469 - DH

Activity Header

Activity:20 016 SUSPENSION

Activity Note: needs front shock absorbers

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Oct-17	6C3Z-18197-AA	BUSHING, ABSORBER, SHOCK, FRONT, UPPER, ECONOLINE, '08	2	4.15	8.3
24-Oct-17	8C2Z-18124-D	ABSORBER, SHOCK, FRONT, E450, '08 SAME AS ASH1154	2	39.03	78.06

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available


No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	86.36
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	86.36



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 43049824
Invoice No. 55345 - 43049824

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	114,469 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard,Ronald	0.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-OCT-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 24, 2017 4:12:54 PM	No	
20 - Miles			RGASPARD	Oct 24, 2017 4:12:54 PM	No	
30 - Kilometers			RGASPARD	Oct 24, 2017 4:12:54 PM	No	
40 - Hours			RGASPARD	Oct 24, 2017 4:12:54 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.17
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 43049824 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.73

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 46119696
Invoice No. 55345 - 46119696

Client Department:

Department: 55345M

Work Order Description

Followup-----> needs 2 front tires and front shock absorbers

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 114,469 - DH

Activity Header

Activity: 30 016 SUSPENSION

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Oct-17	Gaspard, Ronald	0.0666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-OCT-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 24, 2017 4:18:05 PM	No	
20 - Miles			RGASPARD	Oct 24, 2017 4:18:05 PM	No	
30 - Kilometers			RGASPARD	Oct 24, 2017 4:18:05 PM	No	
40 - Hours			RGASPARD	Oct 24, 2017 4:18:05 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 46119696 Total	
Parts:	296.70
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	296.70



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 38208481
Invoice No. 55345 - 38208481

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	110,292 - DH

Chronology		
Reported	Sep 22, 2017 3:11:25 PM	Sep 22, 2017 3:11:25 PM
Started	Sep 22, 2017 12:00:00 AM	
Completed	Sep 22, 2017 11:35:00 PM	Sep 22, 2017 11:35:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service
Oil filter B329 qty 1
Engine oil 5w20 qty 7 qts

Activity Header						
Activity: 10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
22-Sep-17	Gaspard,Ronald	1.5	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 22-SEP-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,152 - Decelerometer Results Test 1	FEET	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,154 - Decelerometer Results Test 2	FEET	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,156 - Decelerometer Results Test 3	FEET	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,131 - Brake Pad Thickness LF	12 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,132 - Brake Pad Thickness RF	12 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 22, 2017 9:52:54 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 22, 2017 9:52:54 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 38208481
Invoice No. 55345 - 38208481

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 110,292 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
22-Sep-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A Task: PM A SERVICE Performed by: RGASPARD Performed on: 22-SEP-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 22, 2017 9:53:36 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 22, 2017 9:53:36 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 22, 2017 9:53:36 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 22, 2017 9:53:36 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 22, 2017 9:53:36 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 22, 2017 9:53:36 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 22, 2017 9:53:36 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 22, 2017 9:53:36 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 38208481
Invoice No. 55345 - 38208481

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 110,292 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Sep-17	Gaspard, Ronald	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 22-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 22, 2017 9:54:00 PM	No	
20 - Miles			RGASPARD	Sep 22, 2017 9:54:00 PM	No	
30 - Kilometers			RGASPARD	Sep 22, 2017 9:54:00 PM	No	
40 - Hours			RGASPARD	Sep 22, 2017 9:54:00 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 38208481 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 42188969
Invoice No. 55345 - 42188969

Client Department:

Department: 55345M

Work Order Description

Loose tie rod & Center Link

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 109,820 - DH

Chronology

Reported	Sep 14, 2017 7:03:25 PM	Sep 14, 2017 7:03:25 PM
Started	Sep 14, 2017 12:00:00 AM	
Completed	Sep 14, 2017 9:25:00 PM	Sep 14, 2017 9:25:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: tie rod& Center Link

CAUSE: center link& tie rod Loose

CORRECTION: remove& Replace .Center Link& Both outer tie rod.

Parts# 8C2Z-3A131-D Qty (1)

Parts#8C2Z-3A131-C Qty (1)

Parts#8C2Z-3304-C Qty (1) Line 20 UNIT WAS SENT TO CALLAGHAN TRUCK REPAIR FOR WHEEL ALIGNMENT.

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 14-SEP-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Sep 14, 2017 9:12:19 PM	No	
20 - Miles			DARTHURS	Sep 14, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:12:19 PM		
30 - Kilometers			DARTHURS	Sep 14, 2017 9:12:19 PM	No	
40 - Hours			DARTHURS	Sep 14, 2017 9:12:19 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.08
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 42188969
Invoice No. 55345 - 42188969

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Loose tie rod & Center Link		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	109,820 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Replace both outer tie rod & Center Link
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-17	8C2Z-3304-C	LINK, DRAG, STEERING	1	177.99	177.99

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-17	Arthurs, Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	177.99	Labor:	0.00
Labor Hours:	1.50	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		177.99	

Work Order Footer		Work Order 42188969 Total	
Parts:	177.99	Labor:	0.00
Labor Hours:	1.58	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		177.99	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 42062194
Invoice No. 55345 - 42062194

Client Department:

Department: 55345M

Work Order Description

Front brakes squeaks ,vehicle has a pulsation when apply brakes.

Requested By: JVARGASSANDOVAL

Created By: JVARGASSANDOVAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 109,799 - DH

Chronology

Reported	Sep 13, 2017 11:39:57 AM	Sep 13, 2017 11:39:57 AM
Started	Sep 13, 2017 12:00:00 AM	
Completed	Sep 13, 2017 2:45:52 PM	Sep 13, 2017 2:45:52 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: front brakes squeaks and has a pulsation when apply brakes.

CAUSE:normal wears.

CORRECTION: removed and replaced front pads,,removed and replaced front rotors,removed and replaced front wheel bearings and seals..removed and replaced left front sway bar bushing.adjust front wheel bearings,installed new cuter pins and grease bearings...torque front tires at 140 lbs...test drive vehicle to confirm repairs..Re torqued front tires at 140lbs...complete repair

Parts

Front rotors part # BRRF-115 qty 2

Front pads part # BRSD-1328 qty 1

Inner bearings part # TMLM102949 qty 2

Outer bearings part # TM15101 qty 2

Hub seal part # CR24000 qty 2

Sway bar bushing part # 8C2Z-5484-D. Qty 1

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist


Check List

5 Desc: Personal Risk Assessment

Check List						
Task: PRA and Meter Readings Performed by: JVARGASSANDOVAL Performed on: 13-SEP-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		JVARGASSANDOVAL	Sep 13, 2017 12:36:15 PM	No	
20 - Miles			JVARGASSANDOVAL	Sep 13, 2017 12:36:15 PM	No	
30 - Kilometers			JVARGASSANDOVAL	Sep 13, 2017 12:36:15 PM	No	
40 - Hours			JVARGASSANDOVAL	Sep 13, 2017 12:36:15 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:	0.00	
				Labor:	0.00	
				Labor Hours:	0.00	
				Sublet Parts:	0.00	
				Sublet Labor:	0.00	
				Activity Sub Total	0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 42062194
Invoice No. 55345 - 42062194

Client Department:
Department: 55345M
Work Order Description
Front brakes squeaks ,vehicle has a pulsation when apply brakes.
Requested By: JVARGASSANDOVAL
Created By: JVARGASSANDOVAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 109,799 - DH

Activity Header
Activity:15 013 BRAKES
Activity Note: Front brakes squeaks and has a pulsation when apply brakes
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Sep-17	BRRF115	ROTOR & HUB, BRAKE, DISC, FRONT, E350	2	109.66	219.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-17	Vargas Sandoval,Javier	1.7333333	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total

Activity 15 Sub Total
Parts: 219.32
Labor: 0.00
Labor Hours: 1.73
Sublet Parts: 0.00
Sublet Labor: 0.00
Activity Sub Total 219.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 42062194
Invoice No. 55345 - 42062194

Client Department:
Department: 55345M
Work Order Description
Front brakes squeaks ,vehicle has a pulsation when apply brakes.
Requested By: JVARGASSANDOVAL
Created By: JVARGASSANDOVAL
Assigned To:
Class: WO - WORK ORDER
Arrangement: Unassigned
Potential Warranty: No

Equipment No.: 4602-P
VIN: 1FDFE4FSXEDB17155
Ford E450 Champion Challenger
Status: 40 - Closed (40)
Priority: 1 - Low
Driver:
Phone:
ETA:
Meter: 109,799 - DH

Activity Header
Activity:25 018 WHEELS, RIMS, HUBS AND BEARINGS
Activity Note: Found front wheel bearings with little end play.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Sep-17	TMLM102949	BEARING, DIFFERENTIAL, CONE, ROLLER, TAPERED	2	6.95	13.9
13-Sep-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
13-Sep-17	TM15101	BEARING, WHEEL, OUTER, CONE, ROLLER, TAPERED	2	8.16	16.32
13-Sep-17	CR24000	SEAL, WHEEL, HUB, FRONT	2	7.64	15.28

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-17	Vargas Sandoval,Javier	1.9	0	0


Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 25 Sub Total	
Parts:			95.82
Labor:			0.00
Labor Hours:			1.90
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			95.82



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 42062194
Invoice No. 55345 - 42062194

Client Department:

Department: 55345M

Work Order Description

Front brakes squeaks ,vehicle has a pulsation when apply brakes.

Requested By: JVARGASSANDOVAL

Created By: JVARGASSANDOVAL

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 109,799 - DH

Activity Header

Activity:35 016 SUSPENSION

Activity Note: During inspection found wear front left sway bar bushing

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Sep-17	8C2Z-5484-D	BUSHING, BAR, SWAY, FRONT	1	7.14	7.14

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-17	Vargas Sandoval,Javier	0.7333333	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 35 Sub Total

Parts:	7.14
Labor:	0.00
Labor Hours:	0.73
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	7.14


Work Order Footer

Work Order 42062194 Total

Parts:	322.28
Labor:	0.00
Labor Hours:	4.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	322.28



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 35000229
Invoice No. 55345 - 35000229

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: TDELVA

Created By: TDELVA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 106,285 - DH

Chronology

Reported	Aug 4, 2017 11:45:37 AM	Aug 4, 2017 11:45:37 AM
Started	Aug 4, 2017 12:00:00 AM	
Completed	Aug 4, 2017 2:28:36 PM	Aug 4, 2017 2:28:36 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: preventive maintenance

CORRECTION: perform service lube all Pivot point cross tires completed

Part # oil filter b329 qty 1

Oil # 5W30 qts 6

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-17	Pierre, Hubert J	6	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 04-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,240 - FRA Check Interior Lights	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,420 - Check Hood	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,633 - Tread Depth RRO	9 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,635 - Tread Depth LRI	9 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,636 - Tread Depth LRO	9 32nds of an inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,134 - Brake Pad Thickness RR	4 Inch	need rear brake pads	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,135 - Brake Rotor LF	1.5 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,136 - Brake Rotor RF	1.5 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Aug 4, 2017 1:49:50 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Aug 4, 2017 1:49:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	6.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 35000229
Invoice No. 55345 - 35000229

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	106,285 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available


Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: HPIERRE Performed on: 04-AUG-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Aug 4, 2017 2:02:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Aug 4, 2017 2:02:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Aug 4, 2017 2:02:01 PM	No	

Activity Sub Total	
Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 35000229
Invoice No. 55345 - 35000229

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	106,285 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-17	Pierre,Hubert J	0.0833333	0	0


Activity Sublet
No Data Available

Activity Checklist							
Check List							
30 Desc: PRAMETER							
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 04-AUG-17							
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 4, 2017 2:02:23 PM	No		
20 - Miles			HPIERRE	Aug 4, 2017 2:02:23 PM	No		
30 - Kilometers			HPIERRE	Aug 4, 2017 2:02:23 PM	No		
40 - Hours			HPIERRE	Aug 4, 2017 2:02:23 PM	No		

Activity Sub Total		Activity 30 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.08
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 35000229
Invoice No. 55345 - 35000229


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	TDELVA	Status:	40 - Closed (40)
Created By:	TDELVA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	106,285 - DH

Activity Header															
Activity:40 999 TOTAL VEHICLE															
Activity Note:															
Reason for Repair:	08 Preventive Maintenance														
Work Accomplished:	A PM Level A														
Part Failure:	99 Replaced Before Failure														
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 40 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 40 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 40 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 35000229 Total</td></tr><tr><td>Parts:</td><td>1.92</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>6.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>1.92</td></tr></table>		Work Order 35000229 Total		Parts:	1.92	Labor:	0.00	Labor Hours:	6.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	1.92
Work Order 35000229 Total															
Parts:	1.92														
Labor:	0.00														
Labor Hours:	6.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	1.92														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 38207672
Invoice No. 55345 - 38207672

Client Department:

Department: 55345M

Work Order Description

Pma follow up need rear brake pads

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 106,285 - DH

Chronology

Reported	Aug 4, 2017 2:13:21 PM	Aug 4, 2017 2:13:21 PM
Started	Aug 4, 2017 12:00:00 AM	
Completed	Aug 4, 2017 2:28:00 PM	Aug 4, 2017 2:28:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: pm a follow need rear brake pads

CAUSE: below spect

CORRECTION: replace rear brake pads completed
Part# bred 1330 qty 1

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 04-AUG-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Aug 4, 2017 2:18:24 PM	No	
20 - Miles			HPIERRE	Aug 4, 2017 2:18:24 PM	No	
30 - Kilometers			HPIERRE	Aug 4, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				2:18:24 PM		
40 - Hours			HPIERRE	Aug 4, 2017 2:18:24 PM	No	
Activity Sub Total				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.08
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 38207672
Invoice No. 55345 - 38207672

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Pma follow up need rear brake pads		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	106,285 - DH

Activity Header
Activity:15 013/000 BRAKES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Aug-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Aug-17	Pierre,Hubert J	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	43.15	Labor:	0.00
Labor Hours:	2.00	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	43.15

Work Order Footer		Work Order 38207672 Total	
Parts:	43.15	Labor:	0.00
Labor Hours:	2.08	Labor Parts:	0.00
Sublet Parts:	0.00	Sublet Labor:	0.00
Sublet Labor:	0.00	Activity Sub Total	43.15



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 34879187
Invoice No. 55345 - 34879187

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 102,348 - DH

Chronology

Reported	Jun 30, 2017 12:35:23 PM	Jun 30, 2017 12:35:23 PM
Started	Jun 30, 2017 12:00:00 AM	
Completed	Jun 30, 2017 3:14:00 PM	Jun 30, 2017 3:14:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PM C Service

CAUSE: PM C Service Due

CORRECTION: PM C services completed

Engine oil changed and engine oil filter replaced

Transmission fluid changed and Transmission filter replaced

Differential fluid changed

Air filter replaced

Parts used # B329 Qty: 1

#20021 Qty: 1

PA4075 Qty: 1

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
30-Jun-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
30-Jun-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94
30-Jun-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-17	Delva, Terry	6	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: TDELVA Performed on: 30-JUN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,100 - Safety Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,140 - Check Service Brakes	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,170 - Check Fast Idle	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
10,190 - Check Reverse Warning System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,100 - Check Parking Brake	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,150 - Perform Brake Test	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,152 - Decelerometer Results Test 1	FEET	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,154 - Decelerometer Results Test 2	FEET	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,156 - Decelerometer Results Test 3	FEET	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,170 - FRA Check Door Operation	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		TDELVA	Jun 30, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:10:12 PM		
20,210 - Check Condition of Operator's Area	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,240 - FRA Check Interior Lights	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,260 - Check Stop Request System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
22,110 - Check Emergency Hatches	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
22,120 - Check All Safety Equipment	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,310 - Check Passenger Doors	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
33,100 - Check Lights and Reflectors	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,410 - FRA Check Engine	Done		TDELVA	Jun 30, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Compartment/Condition for Fire Risk				3:10:12 PM		
40,420 - Check Hood	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,130 - FRA Check Exhaust System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,140 - FRA Check Intake System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,180 - FRA Check for Leaks	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
50,510 - Check Entire Steering System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		TDELVA	Jun 30, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:10:12 PM		
60,611 - Air Pressure RF	65 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,630 - Check and Record Tread Depth	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,650 - Check Sidewall Wear	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,710 - Check Vibration Damper	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,730 - FRA Check Starter	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid	Done		TDELVA	Jun 30, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Leaks				3:10:12 PM		
70,750 - FRA Check Transmission for Leaks	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,770 - FRA Check Exhaust System	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,120 - Check Suspension Components	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,150 - Check King Pins	-	N/A	TDELVA	Jun 30, 2017 3:10:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
80,810 - Completion of PMI Report	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		TDELVA	Jun 30, 2017 3:10:12 PM	No	

Activity Sub Total

Activity 10 Sub Total Parts:	24.04

	Labor:	0.00
	Labor Hours:	6.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	24.04



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 34879187
Invoice No. 55345 - 34879187

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 102,348 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
30-Jun-17	Delva,Terry	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM C

Task: PM C SERVICE Performed by: TDELVA Performed on: 30-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
104,000 - Lubricate Chassis	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
201,000 - Service Crankcase Breather	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		TDELVA	Jun 30, 2017 3:14:41 PM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	TDELVA	Jun 30, 2017 3:14:41 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	TDELVA	Jun 30, 2017 3:14:41 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	
305,000 - FRA Change Differential Fluid	Yes		TDELVA	Jun 30, 2017 3:14:41 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 34879187
Invoice No. 55345 - 34879187

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 102,348 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: TDELVA Performed on: 30-JUN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		TDELVA	Jun 30, 2017 3:14:27 PM	No	
20 - Miles			TDELVA	Jun 30, 2017 3:14:27 PM	No	
30 - Kilometers			TDELVA	Jun 30, 2017 3:14:27 PM	No	
40 - Hours			TDELVA	Jun 30, 2017 3:14:27 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 34879187 Total

Parts:	24.04
Labor:	0.00
Labor Hours:	6.08
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	24.04



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34988163
Invoice No. 55345 - 34988163

Client Department:

Department: 55345M

Work Order Description

Check engine light is on P0751 transmission shift solenoid stuck OFF

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 101,774 - DH

Chronology

Reported	Jun 23, 2017 11:06:11 AM	Jun 23, 2017 11:06:11 AM
Started	Jun 23, 2017 12:00:00 AM	
Completed	Jun 23, 2017 11:58:30 AM	Jun 23, 2017 11:58:30 AM
Down Time		

Work Order Notes

Line 10 Transmission P0751

COMPLAINT:

Check engine light is on P0751 transmission shift solenoid stuck OFF

CAUSE:

Per FORD bulletin (TSB 16-0057) this transmission needs to be removed and rebuilt.

CORRECTION:

Removed transmission from vehicle and sent transmission to be repaired. Received transmission back from the transmission shop and installed transmission back onto vehicle with the original torque converter. Filled transmission with approximately 16qts of transmission fluid. Erased check engine light. Test drove and re-checked fluid level. Transmission is shifting properly and the check engine light did not come on.

PARTS

Qty 1 clutch cylinder # 7C3Z-7G387-B

Qty 1 Transmission filter 20021

Qty 1 F81Z-7A527-AA Clutch snap ring

Qty1 3C3Z-7G299-AA Planetary Gear Retainer

Qty 16qts of transmission oil.

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Aug-17	19180251	TRANSMISSION, REMANUFACTURED	1	337.31	337.31

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Check List						
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 23-JUN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jun 23, 2017 11:13:26 AM	No	
20 - Miles			EDTORRES	Jun 23, 2017 11:13:26 AM	No	
30 - Kilometers			EDTORRES	Jun 23, 2017 11:13:26 AM	No	
40 - Hours			EDTORRES	Jun 23, 2017 11:13:26 AM	No	

Activity Sub Total	Activity 5 Sub Total
	Parts: 337.31
	Labor: 0.00
	Labor Hours: 0.00
	Sublet Parts: 0.00
	Sublet Labor: 0.00
	Activity Sub Total 337.31



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34988163
Invoice No. 55345 - 34988163

Client Department:		
Department:	55345M	Equipment No.: 4602-P
Work Order Description		VIN: 1FDFE4FSXEDB17155
Check engine light is on P0751 transmission shift solenoid stuck OFF		Ford E450 Champion Challenger
Requested By:	EDITORRES	Status: 40 - Closed (40)
Created By:	EDITORRES	Priority: 1 - Low
Assigned To:		Driver:
Class:	WO - WORK ORDER	Phone:
Arrangement:	Unassigned	ETA:
Potential Warranty:	No	Meter: 101,774 - DH

Activity Header
Activity: 15 027 TRANSMISSION, MAIN, AUTOMATIC
Activity Note: Check engine light is on P0751 transmission shift solenoid stuck OFF
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-17	3C3Z-7G299-AA	RETAINER, GEAR, PLANETARY	1	9.46	9.46
23-Jun-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94
23-Jun-17	7C3Z-7G387-B	CYLINDER, CLUTCH, TRANSMISSION	1	77.72	77.72
23-Jun-17	F81Z-7A527-AA	RING, SNAP, CLUTCH, TRANSMISSION	1	2.53	2.53

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
23-Jun-17	Torres,Edwin	4.1166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	106.65
Labor:	0.00
Labor Hours:	4.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	106.65

Work Order Footer	
Work Order 34988163 Total	
Parts:	443.96
Labor:	0.00
Labor Hours:	4.12
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	443.96



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34984554
Invoice No. 55345 - 34984554

Client Department:

Department: 55345M

Work Order Description

Transmission

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 99 - Cancelled (99)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 101,703 - DH

Chronology

Reported	Jun 22, 2017 8:19:10 PM	Jun 22, 2017 8:19:10 PM
Started	Jun 22, 2017 12:00:00 AM	
Completed	Jun 22, 2017 10:44:00 PM	Jun 22, 2017 10:44:00 PM
Down Time		

Work Order Notes

Line 10 SAME REPAIRS ,LABOR ,AND COMMENTS AS W.O # 39488163

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 21-JUL-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 21, 2017 4:29:24 PM	No	
20 - Miles			DARTHURS	Jul 21, 2017 4:29:24 PM	No	
30 - Kilometers			DARTHURS	Jul 21, 2017 4:29:24 PM	No	
40 - Hours			DARTHURS	Jul 21, 2017 4:29:24 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34984554
Invoice No. 55345 - 34984554

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Transmission		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	99 - Cancelled (99)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	101,703 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Remove&Replace Transmission				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-Jun-17	Arthurs,Durvin	6.5	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	6.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 34984554 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	6.58
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 34787936
Invoice No. 55345 - 34787936

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Chronology

Reported	May 25, 2017 10:42:12 AM	May 25, 2017 10:42:12 AM
Started	May 25, 2017 12:00:00 AM	
Completed	May 25, 2017 11:10:00 PM	May 25, 2017 11:10:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA Service

CAUSE: Service due by Mileage

CORRECTION: Change Oil & Filter Lube all Pivoting Points, clean batteries ,check brakes,
Parts# B329 Qty (1)
Oil 5W20 Qty (7) Qts

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 25-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,120 - FRA Check All Warning Lights and	Done		DARTHURS	May 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				10:47:44 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,152 - Decelerometer Results Test 1	FEET	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
11,154 - Decelerometer Results Test 2	FEET	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
11,156 - Decelerometer Results Test 3	FEET	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:47:44 PM		
20,260 - Check Stop Request System	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,370 - Check Wiper Blade and Arm Condition	-	wiper blades	DARTHURS	May 25, 2017 10:47:44 PM	Yes	34879139
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
40,442 - Freeze Point	Degree	NA	DARTHURS	May 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			10:47:44 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,615 - Air Pressure LRI	65 Pounds per		DARTHURS	May 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			10:47:44 PM		
60,616 - Air Pressure LRO	65 Pounds per Square Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,631 - Tread Depth RF	5 32nds of an inch	Front tires	DARTHURS	May 25, 2017 10:47:44 PM	Yes	34879139
60,632 - Tread Depth LF	6 32nds of an inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		DARTHURS	May 25, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				10:47:44 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,135 - Brake Rotor LF	1.568 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,136 - Brake Rotor RF	1.567 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,137 - Brake Rotor LR	1.635 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,138 - Brake Rotor RR	1.637 Inch		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 25, 2017 10:47:44 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 25, 2017 10:47:44 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 34879139
Invoice No. 55345 - 34879139

Client Department:

Department: 55345M

Work Order Description

PMA Follow up>>>>>>Front tires&Wiper blades,

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Chronology

Reported	May 25, 2017 10:16:49 PM	May 25, 2017 10:16:49 PM
Started	May 25, 2017 12:00:00 AM	
Completed	May 25, 2017 11:10:00 PM	May 25, 2017 11:10:00 PM
Down Time		

Work Order Notes

Line 10 Mount&Balance front tires& Replace wiper blades, torque wheel to 140 Ft /lb,

Parts# 189752 Qty (2)

Parts# 3120 Qty (2)

Activity Header

Activity:10 002/035 WIPER & WASHER, WINDSHIELD

Activity Note: wiper blades

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-17	3120	BLADE, WIPER, WINDSHIELD, 20"	2	3.47	6.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	6.94
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	6.94



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 34787936
Invoice No. 55345 - 34787936

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist


Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: DARTHURS Performed on: 25-MAY-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 25, 2017 10:17:41 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 25, 2017 10:17:41 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 25, 2017 10:17:41 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 25, 2017 10:17:41 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 25, 2017 10:17:41 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 25, 2017 10:17:41 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 25, 2017 10:17:41 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 25, 2017 10:17:41 PM	No	

Activity Sub Total

		Activity 20 Sub Total	
		Parts:	1.92
		Labor:	0.00
		Labor Hours:	0.42
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 34879139
Invoice No. 55345 - 34879139

Client Department:

Department: 55345M

Work Order Description

PMA Follow up>>>>>>Front tires&Wiper blades,

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Activity Header

Activity:20 017 TIRES, TUBES, LINERS & VALVES

Activity Note: Front tires

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-May-17	189752	TIRE, LT225/75R16, TLBLPS115RE, TRANSFORCE HT 10PLY 1622575E, NEW	2	105.25	210.5

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 20 Sub Total	
Parts:	210.50
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	210.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 34787936
Invoice No. 55345 - 34787936

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 25-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 25, 2017 10:18:07 PM	No	
20 - Miles			DARTHURS	May 25, 2017 10:18:07 PM	No	
30 - Kilometers			DARTHURS	May 25, 2017 10:18:07 PM	No	
40 - Hours			DARTHURS	May 25, 2017 10:18:07 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 34787936 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	2.00

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 34879139
Invoice No. 55345 - 34879139

Client Department:

Department: 55345M

Work Order Description

PMA Follow up>>>>>Front tires&Wiper blades,

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 98,517 - DH

Activity Header

Activity:30 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note:

Reason for Repair: 01 Breakdown

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 25-MAY-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 25, 2017 10:25:53 PM	No	
20 - Miles			DARTHURS	May 25, 2017 10:25:53 PM	No	
30 - Kilometers			DARTHURS	May 25, 2017 10:25:53 PM	No	
40 - Hours			DARTHURS	May 25, 2017 10:25:53 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 34879139 Total	
Parts:	217.44
Labor:	0.00
Labor Hours:	1.17

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	217.44



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34813321
Invoice No. 55345 - 34813321

Client Department:

Department: 55345M

Work Order Description

W/C lift not working properly

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 96,143 - DH

Chronology

Reported	May 8, 2017 12:57:46 PM	May 8, 2017 12:57:46 PM
Started	May 8, 2017 12:00:00 AM	
Completed	May 8, 2017 3:51:00 PM	May 8, 2017 3:51:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:W/C lift not working

CAUSE:Broken IB up switch wire

CORRECTION:IB up Switch replacement

Complaint identified

IB up switch replaced

Lift is working ok.

Part used:

One (1) IB up switch #32519KS(under warranty).

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 08-MAY-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	May 8, 2017 1:20:21 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	May 8, 2017 1:20:21 PM	No	
30 - Kilometers			FSIMON	May 8, 2017 1:20:21 PM	No	
40 - Hours			FSIMON	May 8, 2017 1:20:21 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34813321
Invoice No. 55345 - 34813321

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
W/C lift not working properly		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	96,143 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-May-17	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 34813321 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34786479
Invoice No. 55345 - 34786479

Client Department:

Department: 55345M

Work Order Description

W/C LIFT INSPECTIONS

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 94,433 - DH

Chronology

Reported	Apr 25, 2017 8:08:00 AM	Apr 25, 2017 8:08:00 AM
Started	Apr 26, 2017 12:00:00 AM	
Completed	Apr 26, 2017 12:36:00 PM	Apr 26, 2017 12:36:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:W/C lift inspection

CAUSE:Preventive maintenance

CORRECTION:W/C lift inspection completion

W/C lift inspection completed

No part used

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 26, 2017 12:08:59 PM	No	
20 - Miles			FSIMON	Apr 26, 2017 12:08:59 PM	No	
30 - Kilometers			FSIMON	Apr 26, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				12:08:59 PM		
40 - Hours			FSIMON	Apr 26, 2017 12:08:59 PM	No	
Activity Sub Total				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34786479
Invoice No. 55345 - 34786479

Client Department:

Department: 55345M

Work Order Description

W/C LIFT INSPECTIONS

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 94,433 - DH

Activity Header

Activity: 15 055/023 LIFT, WHEELCHAIR, PASSENGER

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-17	Simon,Fritz	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

15 Desc:

Task: Braun Wheelchair Lift Inspection Performed by: FSIMON Performed on: 26-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100 - Record Lift Model in Notes	Done	NCL954FIB3454HB-2	FSIMON	Apr 26, 2017 12:35:17 PM	No	
200 - Record Serial # in Notes	Done	FA-00961	FSIMON	Apr 26, 2017 12:35:17 PM	No	
300 - Cycle Count	Cycles	6671	FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,000 - A - GENERAL INSPECTION	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,100 - Lift Battery, Circuit Breaker & Cable	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,200 - Lift Ground & Secondary Ground	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,300 - Vehicle Interlock Power	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,400 - Vehicle Interlock Prohibits Vehicle Movement	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,500 - Lift Door Condition	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
10,600 - Hand Pendant Codition/Function	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,700 - Inspect Mounting Components	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,000 - B - CYCLE CHECK	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,100 - General Operation Throug Comple Cycle	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,200 - Main, Handrail, OB & IB Bumper Adjustments	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,300 - Floor Level Adjustment	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,400 - Platform Angle Adjustment	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,500 - Outer Barrier Interlock	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,600 - Inner Barrier Interlock	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,700 - Threshold Warning Interlock	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,800 - 50 Pound Fold Interlock	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
20,900 - Platform Lights	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
21,000 - Anti-Skid	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
21,100 - Operation & Warning Decals	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
21,200 - Back Pump Handdle Location	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
21,300 - Manual Override/Back-up System Function	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,000 - C - MECHANICAL COMPONENTS	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,100 - Base Plate, Tower, Arm & Platform Welds	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,200 - Outer Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,300 - Inner Barrier Pins, Gas Springs & Fasteners	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,400 - Pivot Pin Fasteners	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,500 - Pivot Pins & Bushing Condition	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,600 - Handrails	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
30,700 - Lift-Tite System	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,000 - D - HYDRAULIC COMPONENT CHECKS	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,100 - Leaks	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,200 - Hoses & Harness Routing/Condition (pump,parallel-vertical arms,platform)	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,300 - Remove Pump Cover & Check Fluid Level	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,400 - Fluid Condition	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,500 - LiftPump Motor Cables/Connections	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	
40,600 - Lift Pump Harnesses/Fuses/Electrical Components	Done		FSIMON	Apr 26, 2017 12:35:17 PM	No	

Activity Sub Total

Activity 15 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 34786479 Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34787012
Invoice No. 55345 - 34787012

Client Department:

Department: 55345M

Work Order Description

Transmission check

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 94,579 - DH

Chronology

Reported	Apr 25, 2017 3:41:22 PM	Apr 25, 2017 3:41:22 PM
Started	Apr 26, 2017 12:00:00 AM	
Completed	Apr 26, 2017 8:29:00 AM	Apr 26, 2017 8:29:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Engine and wrench lights on

CAUSE:Faulty Transmission FT sensor

CORRECTION:Transmission FT sensor and harness replacement

Transmission FT sensor and harness replaced

Parts used:

One (1) FT sensor#BC3Z-7H141-A

One harness #4C3Z7G76-AA

One (1) trani filter #8C3Z-7A098-D

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-APR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 26, 2017 8:28:06 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Apr 26, 2017 8:28:06 AM	No	
30 - Kilometers			FSIMON	Apr 26, 2017 8:28:06 AM	No	
40 - Hours			FSIMON	Apr 26, 2017 8:28:06 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34787012
Invoice No. 55345 - 34787012

Client Department:

Department: 55345M

Work Order Description

Transmission check

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 94,579 - DH

Activity Header

Activity: 15

Activity Note:

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
26-Apr-17	8C3Z-7C155-A	GASKET, BODY, VALVE, TRANSMISSION, 5R110	1	10.63	10.63
26-Apr-17	BC3Z-7H141-A	SENSOR, TEMPERATURE, TRANSMISSION	2	11.83	23.66
26-Apr-17	4C3Z-7G276-AA	HARNESS, SOLENOID, INTERNAL, TRANSMISSION, 5R110W	1	114.91	114.91
26-Apr-17	20021	FILTER, TRANSMISSION 20021	1	16.94	16.94

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-17	Simon,Fritz	2	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	166.14
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	166.14

Work Order Footer

Work Order 34787012 Total

Parts:	166.14
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	166.14



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 34726727
Invoice No. 55345 - 34726727

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	94,579 - DH

Chronology		
Reported	Apr 25, 2017 9:15:13 AM	Apr 25, 2017 9:15:13 AM
Started	Apr 26, 2017 12:00:00 AM	
Completed	Apr 26, 2017 8:23:00 AM	Apr 26, 2017 8:23:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA

CAUSE:PMA service due

CORRECTION:PMA completion

PMA performed
Engine oil filter changed
Engine oil changed
Air filter replaced
Grease fittings lubricated

Materials used:
One(1) Engine oil filter B329
Six(6) quarts oil 5W20
One (1) Ai filter PA4075

F

Activity Header						
Activity: 10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
Booked Date	Part Number	Part Description	Quantity	Each	Extended	
25-Apr-17	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18	
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
26-Apr-17	Simon,Fritz	1	0	0		
Activity Sublet						
No Data Available						

Activity Checklist

Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 26-APR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,100 - Safety Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,140 - Check Service Brakes	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,170 - Check Fast Idle	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,100 - Check Parking Brake	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,150 - Perform Brake Test	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,152 - Decelerometer Results Test 1	FEET	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,154 - Decelerometer Results Test 2	FEET	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,156 - Decelerometer Results Test 3	FEET	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,210 - Check Condition of Operator's Area	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,240 - FRA Check Interior Lights	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,260 - Check Stop Request System	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,310 - Check Passenger Doors	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,420 - Check Hood	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,140 - FRA Check Intake System	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,150 - FRA Inspect Turbocharger	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
50,510 - Check Entire Steering System	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,631 - Tread Depth RF	7 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,632 - Tread Depth LF	7 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,633 - Tread Depth RRO	11 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,634 - Tread Depth RRI	11 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,635 - Tread Depth LRI	11 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,636 - Tread Depth LRO	11 32nds of an inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,710 - Check Vibration Damper	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,730 - FRA Check Starter	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,120 - Check Suspension Components	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,131 - Brake Pad Thickness LF	10 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,132 - Brake Pad Thickness RF	10 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,133 - Brake Pad Thickness LR	10 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,134 - Brake Pad Thickness RR	10 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,135 - Brake Rotor LF	40 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,136 - Brake Rotor RF	40 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,137 - Brake Rotor LR	40 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,138 - Brake Rotor RR	40 Inch		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,150 - Check King Pins	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	-	n/a	FSIMON	Apr 26, 2017 8:23:12 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
80,810 - Completion of PMI Report	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	Apr 26, 2017 8:23:12 AM	No	
Activity Sub Total			Activity 10 Sub Total			

	Parts:	5.18
	Labor:	0.00
	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	5.18



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 34726727
Invoice No. 55345 - 34726727

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 94,579 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Apr-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
26-Apr-17	Simon,Fritz	0.3	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: FSIMON Performed on: 26-APR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	Apr 26, 2017 7:53:59 AM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	Apr 26, 2017 7:53:59 AM	No	
102,000 - FRA Drain Engine Oil	No		FSIMON	Apr 26, 2017 7:53:59 AM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	Apr 26, 2017 7:53:59 AM	No	
104,000 - Lubricate Chassis	Done		FSIMON	Apr 26, 2017 7:53:59 AM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	Apr 26, 2017 7:53:59 AM	No	
107,000 - FRA Change Primary Fuel Filter	No		FSIMON	Apr 26, 2017 7:53:59 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		FSIMON	Apr 26, 2017 7:53:59 AM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	0.30
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 34726727
Invoice No. 55345 - 34726727

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	94,579 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 26-APR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 26, 2017 7:52:53 AM	No	
20 - Miles			FSIMON	Apr 26, 2017 7:52:53 AM	No	
30 - Kilometers			FSIMON	Apr 26, 2017 7:52:53 AM	No	
40 - Hours			FSIMON	Apr 26, 2017 7:52:53 AM	No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 34726727 Total	
		Parts:	7.10
		Labor:	0.00
		Labor Hours:	1.30
		Sublet Parts:	0.00
		Sublet Labor:	0.00

	Activity Sub Total	7.10



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34728675
Invoice No. 55345 - 34728675

Client Department:

Department: 55345M

Work Order Description

L turn signal out.

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 90,723 - DH

Chronology

Reported	Mar 27, 2017 9:48:04 AM	Mar 27, 2017 9:48:04 AM
Started	Mar 27, 2017 12:00:00 AM	
Completed	Mar 27, 2017 10:48:00 AM	Mar 27, 2017 10:48:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

L turn signal is out.

CAUSE:

Normal wear.

CORRECTION:

Replaced L turn signal bulb.

Parts

Qty 1 L turn signal bulb. 3157NA

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 27-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDITORRES	Mar 27, 2017 9:52:24 AM	No	
20 - Miles			EDITORRES	Mar 27, 2017 9:52:24 AM	No	
30 - Kilometers			EDITORRES	Mar 27, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				9:52:24 AM			
40 - Hours			EDTORRES	Mar 27, 2017 9:52:24 AM	No		
Activity Sub Total				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34728675
Invoice No. 55345 - 34728675

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
L turn signal out.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	90,723 - DH

Activity Header
Activity:15 034 LIGHTING SYSTEM
Activity Note: L turn signal is out.
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Mar-17	3157NA	LAMP, MINIATURE, WEDGE-MOUNT, AMBER SAME AS GE3157NA	1	0.85	0.85

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Mar-17	Torres,Edwin	0.3666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
	Activity 15 Sub Total
Parts:	0.85
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.85

Work Order Footer	
	Work Order 34728675 Total
Parts:	0.85
Labor:	0.00
Labor Hours:	0.37
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.85



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 34232312
Invoice No. 55345 - 34232312

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 90,723 - DH

Chronology

Reported	Mar 24, 2017 1:29:08 PM	Mar 24, 2017 1:29:08 PM
Started	Mar 24, 2017 12:00:00 AM	
Completed	Mar 24, 2017 5:34:00 PM	Mar 24, 2017 5:34:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMB

CAUSE:service

CORRECTION:perform PMB service

Oil filter B329 qty 1

Engine oil 5w20 qty 7 qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,420 - Check Hood	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,613 - Air Pressure RRO	65 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,614 - Air Pressure RRI	65 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,615 - Air Pressure LRI	65 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,616 - Air Pressure LRO	65 Pounds per Square Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,131 - Brake Pad Thickness LF	3 Inch	needs front brakes job	RGASPARD	Mar 24, 2017 4:58:17 PM	Yes	34726692
77,132 - Brake Pad Thickness RF	3 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Mar 24, 2017 4:58:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Mar 24, 2017 4:58:17 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34726692
Invoice No. 55345 - 34726692

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Followup-----> needs front brakes job		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	90,723 - DH

Chronology		
Reported	Mar 24, 2017 4:58:17 PM	Mar 24, 2017 4:58:17 PM
Started	Mar 24, 2017 12:00:00 AM	
Completed	Mar 24, 2017 5:34:00 PM	Mar 24, 2017 5:34:00 PM
Down Time		

Work Order Notes

Line 10 Needs front brakes job
Normal wear
Replaced front pads lubed guide pins
Torque wheels 140 lbs test drive second 140 lbs
Parts number BRSD1328 qty 1

Activity Header					
Activity: 10 013/001 BRAKES & DRUMS, FRONT					
Activity Note: needs front brakes job					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-17	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
24-Mar-17	Gaspard,Ronald	1	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts: 50.32		
			Labor: 0.00		
			Labor Hours: 1.00		
			Sublet Parts: 0.00		
			Sublet Labor: 0.00		
			Activity Sub Total 50.32		



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 34232312
Invoice No. 55345 - 34232312

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 90,723 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Mar-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: RGASPARD Performed on: 24-MAR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Mar 24, 2017 4:59:19 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Mar 24, 2017 4:59:19 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12	Done		RGASPARD	Mar 24, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
MONTH)				4:59:19 PM		
201,000 - Service Crankcase Breather	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Mar 24, 2017 4:59:19 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Mar 24, 2017 4:59:19 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34726692
Invoice No. 55345 - 34726692

Client Department:

Department: 55345M

Work Order Description

Followup-----> needs front brakes job

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 90,723 - DH

Activity Header

Activity: 20 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: Needs front brakes job

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Gaspard,Ronald	0.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: Needs front brakes job						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 24, 2017 5:05:05 PM	No	
20 - Miles			RGASPARD	Mar 24, 2017 5:05:05 PM	No	
30 - Kilometers			RGASPARD	Mar 24, 2017 5:05:05 PM	No	
40 - Hours			RGASPARD	Mar 24, 2017 5:05:05 PM	No	

Activity Sub Total

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 34726692 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.05

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	50.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 34232312
Invoice No. 55345 - 34232312

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	90,723 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Mar-17	Gaspard,Ronald	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-MAR-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Mar 24, 2017 4:59:44 PM	No	
20 - Miles			RGASPARD	Mar 24, 2017 4:59:44 PM	No	
30 - Kilometers			RGASPARD	Mar 24, 2017 4:59:44 PM	No	
40 - Hours			RGASPARD	Mar 24, 2017 4:59:44 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 34232312 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34630387
Invoice No. 55345 - 34630387

Client Department:

Department: 55345M

Work Order Description

Check bus for not cranking

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 87,444 - DH

Chronology

Reported	Feb 28, 2017 3:28:27 PM	Feb 28, 2017 3:28:27 PM
Started	Feb 28, 2017 12:00:00 AM	
Completed	Mar 1, 2017 8:43:00 AM	Mar 1, 2017 8:43:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT: Not cranking

CAUSE:Defective batteries

CORRECTION:Batteries replacement

Two batteries replaced

Materials used:

Two (2) batteries#MTP-24ZS

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 29-MAR-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 29, 2017 3:31:22 PM	No	
20 - Miles			FSIMON	Mar 29, 2017 3:31:22 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			FSIMON	Mar 29, 2017 3:31:22 PM	No	
40 - Hours			FSIMON	Mar 29, 2017 3:31:22 PM	No	
Activity Sub Total			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34630387
Invoice No. 55345 - 34630387

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check bus for not cranking		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	87,444 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Feb-17	MTP-24S	OUT OF SERVICE BATTERY	2	79.75	159.5

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Feb-17	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			159.50
Labor:			0.00
Labor Hours:			1.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			159.50

Work Order Footer		Work Order 34630387 Total	
Parts:			159.50
Labor:			0.00
Labor Hours:			1.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			159.50



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 34230499
Invoice No. 55345 - 34230499

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PMA Follow up need rear tires		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	86,036 - DH

Chronology		
Reported	Feb 16, 2017 2:07:33 PM	Feb 16, 2017 2:07:33 PM
Started	Feb 16, 2017 12:00:00 AM	
Completed	Feb 17, 2017 7:24:00 AM	Feb 17, 2017 7:24:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: PMA Follow up need rear tires

CAUSE: below spect

CORRECTION: mount and balance 4 tires completed
050017 qty 4

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-FEB-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 16, 2017 2:11:14 PM	No	
20 - Miles			HPIERRE	Feb 16, 2017 2:11:14 PM	No	
30 - Kilometers			HPIERRE	Feb 16, 2017 2:11:14 PM	No	
40 - Hours			HPIERRE	Feb 16, 2017 2:11:14 PM	No	

Activity Sub Total															
	<table><tr><td colspan="2">Activity 5 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 34230499
Invoice No. 55345 - 34230499

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
PMA Follow up need rear tires		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	86,036 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Feb-17	050017	OUT OF SERVICE TIRE, LT225/75R16, KRO5, KENDA	2	89.73	179.46

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Pierre,Hubert J	2	0	0
16-Feb-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	179.46	Labor:	0.00
Labor Hours:	2.08	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		179.46	

Work Order Footer		Work Order 34230499 Total	
Parts:	179.46	Labor:	0.00
Labor Hours:	2.08	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		179.46	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 32914529
Invoice No. 55345 - 32914529

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	86,036 - DH

Chronology		
Reported	Feb 16, 2017 9:41:12 AM	Feb 16, 2017 9:41:12 AM
Started	Feb 16, 2017 12:00:00 AM	
Completed	Feb 16, 2017 2:38:00 PM	Feb 16, 2017 2:38:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: PMA

CAUSE: preventive maintenance

CORRECTION: perform service lube all pivoting points cross rotate tires completed
Parts # B329 qty 1
Oil#5w20 qts 6

Activity Header
Activity:10 999 TOTAL VEHICLE
Activity Note: Light Medium Duty PMI
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Feb-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Pierre,Hubert J	5	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 16-FEB-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1500 Pounds per Square Inch	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,420 - Check Hood	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	need rear tires	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,133 - Brake Pad Thickness LR	12 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,134 - Brake Pad Thickness RR	12 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,135 - Brake Rotor LF	1.7 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,136 - Brake Rotor RF	1.7 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Feb 16, 2017 2:01:16 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Feb 16, 2017 2:01:16 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 32914529
Invoice No. 55345 - 32914529

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	86,036 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Pierre,Hubert J	0.4166666	0	0

Activity Sublet
No Data Available


Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: HPIERRE Performed on: 16-FEB-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 16, 2017 2:02:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 16, 2017 2:02:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 16, 2017 2:02:13 PM	No	

Activity Sub Total		Activity 20 Sub Total	
Parts:			0.00
Labor:			0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 32914529
Invoice No. 55345 - 32914529

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 86,036 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Feb-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 16-FEB-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 16, 2017 2:02:37 PM	No	
20 - Miles			HPIERRE	Feb 16, 2017 2:02:37 PM	No	
30 - Kilometers			HPIERRE	Feb 16, 2017 2:02:37 PM	No	
40 - Hours			HPIERRE	Feb 16, 2017 2:02:37 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 32914529 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	5.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 33095284
Invoice No. 55345 - 33095284

Client Department:

Department: 55345M

Work Order Description

Road call. Lift. Shocks. And micro switch.

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 83,556 - DH

Chronology

Reported	Jan 25, 2017 12:47:33 PM	Jan 25, 2017 12:47:33 PM
Started	Jan 25, 2017 12:00:00 AM	
Completed	Jan 30, 2017 8:34:00 AM	Jan 30, 2017 8:34:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT: ROADCALL

Driver called dispatch complaint that lift stopped working. Switched out vehicle with 4609 at the FAU BOCA campus, no clients were on board when I arrived.

CAUSE:

Inner bridge plate not working correctly due to bad shocks. Also, the switch actuator for the IB occupancy micro switch assembly is bent of specs.

CORRECTION:

Lift is under warranty, vehicle sent to Mobility Works for warranty repairs.

PARTS

Under warranty. Line 20 the following parts were replaced by mobility works front and rear fold arms kit.

plate ib occ stow microswitch part# 32514na-54 replaced by raul rodrigue part under warranty.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 27-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		EDITORRES	Jan 27, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				12:33:34 PM		
20 - Miles			EDTORRES	Jan 27, 2017 12:33:34 PM	No	
30 - Kilometers			EDTORRES	Jan 27, 2017 12:33:34 PM	No	
40 - Hours			EDTORRES	Jan 27, 2017 12:33:34 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 33095284
Invoice No. 55345 - 33095284

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Road call. Lift. Shocks. And micro switch.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,556 - DH

Activity Header
Activity: 15 050 GROUP, ACCESSORIES
Activity Note: Road. Lift issues.
Reason for Repair: 10 Road Call
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
25-Jan-17	Torres,Edwin	2.7166666	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.72
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 33095284 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.72
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 33066840
Invoice No. 55345 - 33066840

Client Department:

Department: 55345M

Work Order Description

Winding When Driving

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 83,350 - DH

Chronology

Reported	Jan 24, 2017 4:14:27 PM	Jan 24, 2017 4:14:27 PM
Started	Jan 24, 2017 12:00:00 AM	
Completed	Jan 24, 2017 5:05:00 PM	Jan 24, 2017 5:05:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: Winding Noise When driving

CAUSE:driving shaft support bearing bad

CORRECTION: Remove drive shaft to Remove& Replace support bearing,
Parts#E4TZ-4800-A Qty (1)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-17	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 24-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 24, 2017 4:17:26 PM	No	
20 - Miles			DARTHURS	Jan 24, 2017 4:17:26 PM	No	
30 - Kilometers			DARTHURS	Jan 24, 2017 4:17:26 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
40 - Hours			DARTHURS	Jan 24, 2017 4:17:26 PM	No															
Activity Sub Total			<table><tr><th colspan="2">Activity 5 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.08</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.08	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.08																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 33066840
Invoice No. 55345 - 33066840

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Winding When Driving		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,350 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Bad support bearing
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-17	E4TZ-4800-A	BEARING, SUPPORT, CENTER, DRIVESHAFT	1	53.55	53.55

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-17	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>53.55</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>53.55</td></tr></table>	Activity 15 Sub Total		Parts:	53.55	Labor:	0.00	Labor Hours:	1.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	53.55	
Activity 15 Sub Total															
Parts:	53.55														
Labor:	0.00														
Labor Hours:	1.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	53.55														

Work Order Footer															
<table><tr><th colspan="2">Work Order 33066840 Total</th></tr><tr><td>Parts:</td><td>53.55</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.58</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>53.55</td></tr></table>	Work Order 33066840 Total		Parts:	53.55	Labor:	0.00	Labor Hours:	1.58	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	53.55	
Work Order 33066840 Total															
Parts:	53.55														
Labor:	0.00														
Labor Hours:	1.58														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	53.55														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 33063006
Invoice No. 55345 - 33063006

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Driver side headlight is out		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,166 - DH

Chronology		
Reported	Jan 24, 2017 11:58:20 AM	Jan 24, 2017 11:58:20 AM
Started	Jan 24, 2017 12:00:00 AM	
Completed	Jan 24, 2017 2:10:00 PM	Jan 24, 2017 2:10:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT:
Driver side headlight is out

CAUSE:
Normal wear

CORRECTION:
Removed and replaced driver side headlight bulb

Part: 1 headlight bulb #83982

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 24-JAN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Jan 24, 2017 12:13:16 PM	No	
20 - Miles			RAURODRIGUEZ	Jan 24, 2017 12:13:16 PM	No	
30 - Kilometers			RAURODRIGUEZ	Jan 24, 2017 12:13:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RAURODRIGUEZ	Jan 24, 2017 12:13:16 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 33063006
Invoice No. 55345 - 33063006

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Driver side headlight is out		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,166 - DH

Activity Header
Activity:15 030 ELECTRICAL GROUP
Activity Note: Driver side headlight is out
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-17	83982	BULB, HALOGEN, 9008	1	9.64	9.64

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-17	Rodriguez,Raul	0.2333333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>9.64</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>9.64</td></tr></table>	Activity 15 Sub Total		Parts:	9.64	Labor:	0.00	Labor Hours:	0.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	9.64	
Activity 15 Sub Total															
Parts:	9.64														
Labor:	0.00														
Labor Hours:	0.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	9.64														

Work Order Footer															
<table><tr><th colspan="2">Work Order 33063006 Total</th></tr><tr><td>Parts:</td><td>9.64</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.23</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>9.64</td></tr></table>	Work Order 33063006 Total		Parts:	9.64	Labor:	0.00	Labor Hours:	0.23	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	9.64	
Work Order 33063006 Total															
Parts:	9.64														
Labor:	0.00														
Labor Hours:	0.23														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	9.64														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 33058679
Invoice No. 55345 - 33058679

Client Department:

Department: 55345M

Work Order Description

Tensioner bearing, rear brakes.

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 83,166 - DH

Chronology

Reported	Jan 24, 2017 6:54:51 AM	Jan 24, 2017 6:54:51 AM
Started	Jan 24, 2017 12:00:00 AM	
Completed	Jan 24, 2017 7:35:00 AM	Jan 24, 2017 7:35:00 AM
Down Time		

Work Order Notes

Line 10 Rear Brakes

COMPLAINT:

Change rear brakes

CAUSE:

Normal wear

CORRECTION:

Replaced rear brake pads. Replaced clips on caliper bracket. Applied anti-seize to pin slides. Applied liquid bolt lock to caliper bracket bolts. Torqued lug nuts to 140 lbs. test drove. Re torqued to 140 lbs.

Parts.

Qty 1 rear brake pads BRSD-1330 Line 20

Complaint.

Squeaking sound coming from engine compartment.

Found that the bearing from the driver side idler pulley and tensioner bearing has some play and are no longer feeling smooth when you spin them.

Parts


Qty 2 bearing 6203

Activity Header	
Activity: 5 999 TOTAL VEHICLE	
Activity Note: Personal Risk Assessment	
Reason for Repair:	05 Inspection, Routine
Work Accomplished:	06 Inspect
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 24-JAN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jan 24, 2017 7:07:54 AM	No	
20 - Miles			EDTORRES	Jan 24, 2017 7:07:54 AM	No	
30 - Kilometers			EDTORRES	Jan 24, 2017 7:07:54 AM	No	
40 - Hours			EDTORRES	Jan 24, 2017 7:07:54 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 33058679
Invoice No. 55345 - 33058679


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Tensioner bearing, rear brakes.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,166 - DH

Activity Header					
Activity:15 013 BRAKES					
Activity Note: Rear brakes are near minimum spec.					
Reason for Repair: 05 Inspection, Routine					
Work Accomplished:					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-17	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
24-Jan-17	Torres,Edwin	1.8666666	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 15 Sub Total		
			Parts:	43.15	
			Labor:	0.00	
			Labor Hours:	1.87	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	43.15	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 33058679
Invoice No. 55345 - 33058679

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Tensioner bearing, rear brakes.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	83,166 - DH

Activity Header
Activity:25 040 ENGINE/MOTOR SYSTEMS GROUP
Activity Note: There is a pulley making a squeaking sound
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
24-Jan-17	6203	BEARING, SHAFT, STEERING, POWER	2	2.54	5.08

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
24-Jan-17	Torres,Edwin	1.6833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 25 Sub Total</th></tr><tr><td>Parts:</td><td>5.08</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.68</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>5.08</td></tr></table>	Activity 25 Sub Total		Parts:	5.08	Labor:	0.00	Labor Hours:	1.68	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	5.08	
Activity 25 Sub Total															
Parts:	5.08														
Labor:	0.00														
Labor Hours:	1.68														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	5.08														

Work Order Footer															
<table><tr><th colspan="2">Work Order 33058679 Total</th></tr><tr><td>Parts:</td><td>48.23</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.55</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>48.23</td></tr></table>	Work Order 33058679 Total		Parts:	48.23	Labor:	0.00	Labor Hours:	3.55	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	48.23	
Work Order 33058679 Total															
Parts:	48.23														
Labor:	0.00														
Labor Hours:	3.55														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	48.23														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 32969403
Invoice No. 55345 - 32969403

Client Department:

Department: 55345M

Work Order Description

Check Batteries tray

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 82,607 - DH

Chronology

Reported	Jan 18, 2017 12:08:15 PM	Jan 18, 2017 12:08:15 PM
Started	Jan 18, 2017 12:00:00 AM	
Completed	Jan 18, 2017 12:56:00 PM	Jan 18, 2017 12:56:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Batteries tray moving in ant out its cage

CAUSE:Missing Spring

CORRECTION:Spring replacement

Complaint verified

A new spring installed

Batteries tray is ok

Part used:

One (1) spring (shop supply)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 18-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 18, 2017 12:23:59 PM	No	
20 - Miles			FSIMON	Jan 18, 2017 12:23:59 PM	No	
30 - Kilometers			FSIMON	Jan 18, 2017 12:23:59 PM	No	
40 - Hours			FSIMON	Jan 18, 2017 12:23:59 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 32969403
Invoice No. 55345 - 32969403

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Check Batteries tray		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	82,607 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
18-Jan-17	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 32969403 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 28841821
Invoice No. 55345 - 28841821

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 81,783 - DH

Chronology

Reported	Jan 10, 2017 11:47:21 AM	Jan 10, 2017 11:47:21 AM
Started	Jan 10, 2017 12:00:00 AM	
Completed	Jan 10, 2017 11:48:00 PM	Jan 10, 2017 11:48:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service

Oil filter B329 qty1

Engine oil 5w20 qty 7 qts

Drain plug oil F75Z-6730-BA qty 1

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-17	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 10-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,120 - FRA Check All Warning Lights and	Done		RGASPARD	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Alarms				11:18:17 PM		
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails	Done		RGASPARD	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
and Floor Covering				11:18:17 PM		
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,420 - Check Hood	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,461 - Refractometer Reading	Degree	na	RGASPARD	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:18:17 PM		
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:18:17 PM		
60,631 - Tread Depth RF	10 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,632 - Tread Depth LF	10 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,633 - Tread Depth RRO	6 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Jan 10, 2017	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:18:17 PM		
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,132 - Brake Pad Thickness RF	6 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,137 - Brake Rotor LR	32 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,138 - Brake Rotor RR	32 Inch		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Jan 10, 2017 11:18:17 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Jan 10, 2017 11:18:17 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 28841821
Invoice No. 55345 - 28841821

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 81,783 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
10-Jan-17	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92
10-Jan-17	F757-6730-BA	PLUG, DRAIN, OIL, ENGINE	1	6.66	6.66

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-17	Gaspard, Ronald	1.1666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: RGASPARD Performed on: 10-JAN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Jan 10, 2017 11:19:26 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Jan 10, 2017 11:19:26 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Jan 10, 2017 11:19:26 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Jan 10, 2017 11:19:26 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Jan 10, 2017 11:19:26 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Jan 10, 2017 11:19:26 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Jan 10, 2017 11:19:26 PM	No	
108,000 - Lube all pivoting	Done		RGASPARD	Jan 10, 2017 11:19:26	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Mechanisms				PM			
Activity Sub Total				Activity 20 Sub Total			
				Parts:		8.58	
				Labor:		0.00	
				Labor Hours:		1.17	
				Sublet Parts:		0.00	
				Sublet Labor:		0.00	
				Activity Sub Total		8.58	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 28841821
Invoice No. 55345 - 28841821

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 81,783 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Jan-17	Gaspard, Ronald	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 10-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Jan 10, 2017 11:19:48 PM	No	
20 - Miles			RGASPARD	Jan 10, 2017 11:19:48 PM	No	
30 - Kilometers			RGASPARD	Jan 10, 2017 11:19:48 PM	No	
40 - Hours			RGASPARD	Jan 10, 2017 11:19:48 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 28841821 Total

Parts:	8.58
Labor:	0.00
Labor Hours:	2.75

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	8.58



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 32794855
Invoice No. 55345 - 32794855

Client Department:

Department: 55345M

Work Order Description

Rear differential leaking

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 81,144 - DH

Chronology

Reported	Jan 4, 2017 2:59:12 PM	Jan 4, 2017 2:59:12 PM
Started	Jan 4, 2017 12:00:00 AM	
Completed	Jan 5, 2017 8:46:09 AM	Jan 5, 2017 8:46:09 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT: rear differential leaking

CAUSE: the gasket wear out

CORRECTION: remove rear differential cover clean reseal and add fluid , replace one passenger rear tire by a use one completed

Differential fluid # 3 quarts

Tire #use one

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-17	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 04-JAN-17

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 4, 2017 3:03:16 PM	No	
20 - Miles			HPIERRE	Jan 4, 2017 3:03:16 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
30 - Kilometers			HPIERRE	Jan 4, 2017 3:03:16 PM	No	
40 - Hours			HPIERRE	Jan 4, 2017 3:03:16 PM	No	
Activity Sub Total			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.08
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 32794855
Invoice No. 55345 - 32794855

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear differential leaking		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	81,144 - DH

Activity Header
Activity: 15 022 AXLE, DRIVEN, REAR (POWER UNITS & TRAILERS)
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-17	Pierre, Hubert J	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	3.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	3.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														

Work Order Footer															
<table><tr><th colspan="2">Work Order 32794855 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>3.08</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 32794855 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	3.08	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 32794855 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	3.08														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 32836526
Invoice No. 55345 - 32836526

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	81,144 - DH

Chronology		
Reported	Jan 4, 2017 10:18:35 PM	Jan 4, 2017 10:18:35 PM
Started	Jan 4, 2017 12:00:00 AM	
Completed	Jan 4, 2017 11:15:00 PM	Jan 4, 2017 11:15:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Rear A/C inop

CAUSE:high Side service valve leaking

CORRECTION: Remove&Replace high side service valve& Replace Orifice tube add4ozs oil evacuate /Recharge,
Freon 6.5 Lbs
Parts#YG380 Qty (1)

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
04-Jan-17	Arthurs,Durvin	0.0833333	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 04-JAN-17						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jan 4, 2017 10:19:43 PM	No	
20 - Miles			DARTHURS	Jan 4, 2017 10:19:43 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
30 - Kilometers			DARTHURS	Jan 4, 2017 10:19:43 PM	No		
40 - Hours			DARTHURS	Jan 4, 2017 10:19:43 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.08
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 32836526
Invoice No. 55345 - 32836526

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	81,144 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
04-Jan-17	YG380	TUBE, ORIFICE, A/C, E450, BLACK	1	4.26	4.26

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
04-Jan-17	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	4.26
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	4.26

Work Order Footer	
Work Order 32836526 Total	
Parts:	4.26
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	4.26



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 31813836
Invoice No. 55345 - 31813836

Client Department:

Department: 55345M

Work Order Description

Manufacturer recommended spark plug service by mileage

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 80,663 - DH

Chronology

Reported	Dec 27, 2016 9:59:23 AM	Dec 27, 2016 9:59:23 AM
Started	Dec 27, 2016 12:00:00 AM	
Completed	Dec 28, 2016 11:46:00 AM	Dec 28, 2016 11:46:00 AM
Down Time		

Work Order Notes

Line 10 Spark plug

COMPLAINT:

Manufacturer recommended spark plug service by mileage

CAUSE:

Normal wear.

CORRECTION:

Removed all spark plugs and spark plug boots. Replaced them with new spark plugs and spark plug boots. Applied dielectric grease to the the spring inside the spark plug boot.

PARTS

Qty 10 Boot WR-6128

Qty 10 spark plug SP521

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 28-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Dec 28, 2016 10:02:41 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			EDITORRES	Dec 28, 2016 10:02:41 AM	No	
30 - Kilometers			EDITORRES	Dec 28, 2016 10:02:41 AM	No	
40 - Hours			EDITORRES	Dec 28, 2016 10:02:41 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 31813836
Invoice No. 55345 - 31813836

Client Department:

Department: 55345M

Work Order Description

Manufacturer recommended spark plug service by mileage

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 80,663 - DH

Activity Header

Activity: 15 040 ENGINE/MOTOR SYSTEMS GROUP

Activity Note: Manufacturer recommended spark plug service by mileage

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Dec-16	SP521	PLUG, SPARK, 5.4L, FORD	-10	4.15	-41.5
28-Dec-16	SP521	PLUG, SPARK, 5.4L, FORD	10	4.15	41.5
28-Dec-16	WR6128	BOOT, PLUG, SPARK	10	5.28	52.8

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Dec-16	Torres, Edwin	3.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	94.30
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	94.30

Work Order Footer

Work Order 31813836 Total

Parts:	94.30
Labor:	0.00
Labor Hours:	3.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	94.30



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 29589326
Invoice No. 55345 - 29589326

Client Department:

Department: 55345M

Work Order Description

STEERING GEAR BOX BAD LEAK

Requested By: RAURODRIGUEZ

Created By: RAURODRIGUEZ

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 78,545 - DH

Chronology

Reported	Dec 8, 2016 11:56:28 AM	Dec 8, 2016 11:56:28 AM
Started	Dec 8, 2016 12:00:00 AM	
Completed	Dec 8, 2016 3:18:27 PM	Dec 8, 2016 3:18:27 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

STEERING GEAR BOX BAD LEAK

CAUSE:

Gear box defective

CORRECTION:

Removed and replaced gear box

PARTS: Under Warranty

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RAURODRIGUEZ Performed on: 08-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAURODRIGUEZ	Dec 8, 2016 12:09:18 PM	No	
20 - Miles			RAURODRIGUEZ	Dec 8, 2016 12:09:18 PM	No	
30 - Kilometers			RAURODRIGUEZ	Dec 8, 2016 12:09:18 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40 - Hours			RAURODRIGUEZ	Dec 8, 2016 12:09:18 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 29589326
Invoice No. 55345 - 29589326

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
STEERING GEAR BOX BAD LEAK		Ford E450 Champion Challenger	
Requested By:	RAUODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAUODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	78,545 - DH

Activity Header
Activity:15 015 STEERING
Activity Note: STEERING GEAR BOX BAD LEAK
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Dec-16	Rodriguez,Raul	1.1666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.17
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 29589326 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			1.17
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 29314466
Invoice No. 55345 - 29314466

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C check		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	78,260 - DH

Chronology		
Reported	Dec 5, 2016 3:40:46 PM	Dec 5, 2016 3:40:46 PM
Started	Dec 5, 2016 12:00:00 AM	
Completed	Dec 6, 2016 7:15:00 AM	Dec 6, 2016 7:15:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Rear A/C not blowing cold

CAUSE:Leaky high side valve fittings

CORRECTION:Leak repair

Complaint identified
Visual inspection performed and high side valve fittings found leaking
Orifice tube replaced
Leak repaired vacuum and leak test done and A/C system recharged
Rear A/C blowing cold

Part used
One(1) orifice tube #YG380

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List 5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-DEC-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Dec 5, 2016 3:52:07 PM	No	
20 - Miles			FSIMON	Dec 5, 2016 3:52:07 PM	No	
30 - Kilometers			FSIMON	Dec 5, 2016 3:52:07 PM	No	
40 - Hours			FSIMON	Dec 5, 2016 3:52:07 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 29314466
Invoice No. 55345 - 29314466

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C check		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	78,260 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Dec-16	YG-380	TUBE, ORIFICE, A/C	1	4.36	4.36

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Dec-16	Simon,Fritz	3	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			4.36
Labor:			0.00
Labor Hours:			3.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			4.36

Work Order Footer		Work Order 29314466 Total	
Parts:			4.36
Labor:			0.00
Labor Hours:			3.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			4.36



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 4



Work Order No. 27751945
Invoice No. 55345 - 27751945

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 77,714 - DH

Chronology

Reported	Nov 28, 2016 2:37:50 PM	Nov 28, 2016 2:37:50 PM
Started	Nov 29, 2016 12:00:00 AM	
Completed	Nov 29, 2016 1:54:00 PM	Nov 29, 2016 1:54:00 PM
Down Time		

Work Order Notes

Line 10 PMC
Preventive maintenance

Perform service lube all pivoting points cross rotate tires completed
Parts # B329 qty 1
Oil# 5w20 qts 6

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-16	Pierre, Hubert J	5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 29-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	1400 Pounds per Square Inch	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,162 - FRA Check/Record Water Temperature	190 Degree Fahrenheit	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,420 - Check Hood	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,631 - Tread Depth RF	12 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,632 - Tread Depth LF	12 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,633 - Tread Depth RRO	7 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,634 - Tread Depth RRI	7 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,635 - Tread Depth LRI	7 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,636 - Tread Depth LRO	7 32nds of an inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,135 - Brake Rotor LF	1.7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,136 - Brake Rotor RF	1.7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,137 - Brake Rotor LR	1.7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,138 - Brake Rotor RR	1.7 Inch		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Nov 29, 2016 7:32:35 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Nov 29, 2016 7:32:35 AM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	5.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 4



Work Order No. 27751945
Invoice No. 55345 - 27751945

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	77,714 - DH

Activity Header

Activity:20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-16	Pierre,Hubert J	0.3333333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM C						
Task: PM C SERVICE Performed by: HPIERRE Performed on: 30-NOV-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
107,000 - FRA Change Primary Fuel Filter	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Nov 30, 2016 7:09:27 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Nov 30, 2016 7:09:27 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Nov 30, 2016 7:09:27 AM	No	
305,000 - FRA Change Differential Fluid	No		HPIERRE	Nov 30, 2016 7:09:27 AM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.33
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 4



Work Order No. 27751945
Invoice No. 55345 - 27751945

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	77,714 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 29-NOV-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Nov 29, 2016 7:36:21 AM	No	
20 - Miles			HPIERRE	Nov 29, 2016 7:36:21 AM	No	
30 - Kilometers			HPIERRE	Nov 29, 2016 7:36:21 AM	No	
40 - Hours			HPIERRE	Nov 29, 2016 7:36:21 AM	No	

Activity Sub Total		Activity 30 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.08
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 4 of 4



Work Order No. 27751945
Invoice No. 55345 - 27751945

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	77,714 - DH

Activity Header
Activity:40 999 TOTAL VEHICLE
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: C PM Level C
Part Failure: 99 Replaced Before Failure
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
29-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.92	-1.92
30-Nov-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.92	-1.92

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Nov-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 40 Sub Total	
		Parts:	-3.84
		Labor:	0.00
		Labor Hours:	0.08
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	-3.84

Work Order Footer		Work Order 27751945 Total	
		Parts:	-1.92
		Labor:	0.00
		Labor Hours:	5.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	-1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27834602
Invoice No. 55345 - 27834602

Client Department:

Department: 55345M

Work Order Description

Heater covers check

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 74,511 - DH

Chronology

Reported	Oct 31, 2016 3:46:59 PM	Oct 31, 2016 3:46:59 PM
Started	Nov 1, 2016 12:00:00 AM	
Completed	Nov 1, 2016 11:25:00 AM	Nov 1, 2016 11:25:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Heater covers on the floor

CAUSE:Torn heater covers

CORRECTION:Heater covers reinstalled

Heater covers reinstalled

No parts used

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 01-NOV-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 1, 2016 9:34:02 AM	No	
20 - Miles			FSIMON	Nov 1, 2016 9:34:02 AM	No	
30 - Kilometers			FSIMON	Nov 1, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				9:34:02 AM		
40 - Hours			FSIMON	Nov 1, 2016 9:34:02 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27834602
Invoice No. 55345 - 27834602

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Heater covers check		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	74,511 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Nov-16	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 27834602 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27442522
Invoice No. 55345 - 27442522

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 73,291 - DH

Chronology

Reported	Oct 20, 2016 11:20:12 AM	Oct 20, 2016 11:20:12 AM
Started	Oct 20, 2016 12:00:00 AM	
Completed	Oct 21, 2016 12:26:00 AM	Oct 21, 2016 12:26:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION:perform pmA service

Oil filter B329 qty1

Engine oil 5w20 qty 7qts

Replaced rear tires by good used tires

Used tires LRI 8 . LRO 7

Used tires RRI 10 . RRO 10

Torque tires 140 lbs second torque 140 lbs

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Gaspard,Ronald	1.8833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive	Done		RGASPARD	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
On (In Lot) Inspection				11:21:39 PM		
10,100 - Safety Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:21:39 PM		
20,260 - Check Stop Request System	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,420 - Check Hood	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,442 - Freeze Point	Degree	na	RGASPARD	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Fahrenheit			11:21:39 PM		
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,611 - Air Pressure RF	70 Pounds per Square Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,612 - Air Pressure LF	70 Pounds per Square Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,615 - Air Pressure LRI	70 Pounds per		RGASPARD	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
	Square Inch			11:21:39 PM		
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,634 - Tread Depth RRI	2 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
70,790 - Check All Body Mounts and Chassis	Done		RGASPARD	Oct 20, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Frame				11:21:39 PM		
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,131 - Brake Pad Thickness LF	7 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,133 - Brake Pad Thickness LR	8 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,134 - Brake Pad Thickness RR	8 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Oct 20, 2016 11:21:39 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Oct 20, 2016 11:21:39 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	1.17
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27442522
Invoice No. 55345 - 27442522

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 73,291 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-16	Gaspard, Ronald	0.0666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 20-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 20, 2016 11:22:52 PM	No	
20 - Miles			RGASPARD	Oct 20, 2016 11:22:52 PM	No	
30 - Kilometers			RGASPARD	Oct 20, 2016 11:22:52 PM	No	
40 - Hours			RGASPARD	Oct 20, 2016 11:22:52 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer


Work Order 27442522 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	3.12

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27743471
Invoice No. 55345 - 27743471

Client Department:

Department: 55345M

Work Order Description

Tie down bagtorn

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 73,115 - DH

Chronology

Reported	Oct 19, 2016 11:01:11 PM	Oct 19, 2016 11:01:11 PM
Started	Oct 19, 2016 12:00:00 AM	
Completed	Oct 19, 2016 11:27:00 PM	Oct 19, 2016 11:27:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: tie down bag

CAUSE:Bag torn

CORRECTION: Remove& Replace tie down bag
Parts under warranty Qty (1)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Oct-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 19-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 19, 2016 11:02:34 PM	No	
20 - Miles			DARTHURS	Oct 19, 2016 11:02:34 PM	No	
30 - Kilometers			DARTHURS	Oct 19, 2016 11:02:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																					
40 - Hours			DARTHURS	Oct 19, 2016 11:02:34 PM	No																						
Activity Sub Total			<table><tr><td colspan="2">Activity 5 Sub Total</td><td></td></tr><tr><td>Parts:</td><td></td><td>0.00</td></tr><tr><td>Labor:</td><td></td><td>0.00</td></tr><tr><td>Labor Hours:</td><td></td><td>0.08</td></tr><tr><td>Sublet Parts:</td><td></td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td></td><td>0.00</td></tr><tr><td colspan="2">Activity Sub Total</td><td>0.00</td></tr></table>				Activity 5 Sub Total			Parts:		0.00	Labor:		0.00	Labor Hours:		0.08	Sublet Parts:		0.00	Sublet Labor:		0.00	Activity Sub Total		0.00
Activity 5 Sub Total																											
Parts:		0.00																									
Labor:		0.00																									
Labor Hours:		0.08																									
Sublet Parts:		0.00																									
Sublet Labor:		0.00																									
Activity Sub Total		0.00																									



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27743471
Invoice No. 55345 - 27743471

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Tie down bagtorn		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	73,115 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Tie down bag torn
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Oct-16	Arthurs,Durvin	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 27743471 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.08
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27725864
Invoice No. 55345 - 27725864

Client Department:

Department: 55345M

Work Order Description

Check engine for warning light on

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 72,619 - DH

Chronology

Reported	Oct 14, 2016 4:01:38 PM	Oct 14, 2016 4:01:38 PM
Started	Oct 17, 2016 12:00:00 AM	
Completed	Oct 18, 2016 7:14:00 AM	Oct 18, 2016 7:14:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Engine warning light on

CAUSE:Lean condition

CORRECTION: Clean and repair all connections related to lean condition cause

Complaint verified

Bus scanned code PO 174 found

All connections cleaned and repaired

Test drive performed (ok)

No part used

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 17-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 17, 2016 3:48:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			FSIMON	Oct 17, 2016 3:48:33 PM	No	
30 - Kilometers			FSIMON	Oct 17, 2016 3:48:33 PM	No	
40 - Hours			FSIMON	Oct 17, 2016 3:48:33 PM	No	
Activity Sub Total			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27725864
Invoice No. 55345 - 27725864

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check engine for warning light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	72,619 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
17-Oct-16	Simon,Fritz	2	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	2.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 27725864 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	2.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27611224
Invoice No. 55345 - 27611224

Client Department:

Department: 55345M

Work Order Description

Rear A/C hot air

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 71,815 - DH

Chronology

Reported	Oct 9, 2016 3:07:55 PM	Oct 9, 2016 3:07:55 PM
Started	Oct 9, 2016 12:00:00 AM	
Completed	Oct 9, 2016 3:22:00 PM	Oct 9, 2016 3:22:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: Rear A/C

CAUSE:Block Orifice Tube

CORRECTION: Evacuate &Remove Orifice tube & Replace/Recharge,Add (2)ozs Oil

Parts# Orifice tube blue no Parts#

Freon (4)Lbs

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 09-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Oct 9, 2016 3:09:49 PM	No	
20 - Miles			DARTHURS	Oct 9, 2016 3:09:49 PM	No	
30 - Kilometers			DARTHURS	Oct 9, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				3:09:49 PM			
40 - Hours			DARTHURS	Oct 9, 2016 3:09:49 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.08
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27611224
Invoice No. 55345 - 27611224

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear A/C hot air		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	71,815 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear A/C blowing hot Air
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
09-Oct-16	Arthurs,Durvin	2	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 27611224 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.08
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27575489
Invoice No. 55345 - 27575489

Client Department:

Department: 55345M

Work Order Description

Needs 2 front tires

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 71,815 - DH

Chronology

Reported	Oct 7, 2016 9:37:10 PM	Oct 7, 2016 9:37:10 PM
Started	Oct 7, 2016 12:00:00 AM	
Completed	Oct 7, 2016 10:28:00 PM	Oct 7, 2016 10:28:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: needs 2 front tires

CAUSE:wear

CORRECTION: 2 new tires mounted and balanced

Torque tires 140 lbs second torque 140lbs

Part number 192659 qty 2 bridgestone

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-16	Gaspard,Ronald	0.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 07-OCT-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Oct 7, 2016 9:38:48 PM	No	
20 - Miles			RGASPARD	Oct 7, 2016 9:38:48 PM	No	
30 - Kilometers			RGASPARD	Oct 7, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				9:38:48 PM			
40 - Hours			RGASPARD	Oct 7, 2016 9:38:48 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.05
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27575489
Invoice No. 55345 - 27575489

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Needs 2 front tires		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	71,815 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Oct-16	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	2	109.61	219.22

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Oct-16	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:	219.22	Labor:	0.00
Labor Hours:	1.00	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		219.22	

Work Order Footer		Work Order 27575489 Total	
Parts:	219.22	Labor:	0.00
Labor Hours:	1.05	Sublet Parts:	0.00
Sublet Labor:	0.00	Sublet Labor:	0.00
Activity Sub Total		219.22	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27447328
Invoice No. 55345 - 27447328

Client Department:

Department: 55345M

Work Order Description

Rear bumper on passenger side came off

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 69,365 - DH

Chronology

Reported	Sep 19, 2016 5:45:44 AM	Sep 19, 2016 5:45:44 AM
Started	Sep 19, 2016 12:00:00 AM	
Completed	Sep 19, 2016 9:06:00 AM	Sep 19, 2016 9:06:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

Rear bumper on passenger-side came off

CAUSE:

Vehicle involved in an accident

CORRECTION:

Reattached the rear bumper passenger side back onto the frame.

No parts used

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 19-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Sep 19, 2016 5:49:51 AM	No	
20 - Miles			EDTORRES	Sep 19, 2016 5:49:51 AM	No	
30 - Kilometers			EDTORRES	Sep 19, 2016 5:49:51 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																					
40 - Hours			EDTORRES	Sep 19, 2016 5:49:51 AM	No																						
Activity Sub Total			<table><tr><td colspan="2">Activity 5 Sub Total</td><td></td></tr><tr><td>Parts:</td><td></td><td>0.00</td></tr><tr><td>Labor:</td><td></td><td>0.00</td></tr><tr><td>Labor Hours:</td><td></td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td></td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td></td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td></td><td>0.00</td></tr></table>				Activity 5 Sub Total			Parts:		0.00	Labor:		0.00	Labor Hours:		0.00	Sublet Parts:		0.00	Sublet Labor:		0.00	Activity Sub Total		0.00
Activity 5 Sub Total																											
Parts:		0.00																									
Labor:		0.00																									
Labor Hours:		0.00																									
Sublet Parts:		0.00																									
Sublet Labor:		0.00																									
Activity Sub Total		0.00																									



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27447328
Invoice No. 55345 - 27447328

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear bumper on passenger side came off		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	69,365 - DH

Activity Header				
Activity: 15 174 BODY, BUS				
Activity Note: Rear bumper on passenger side came official				
Reason for Repair: 41 Abuse of Equipment				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
19-Sep-16	Torres,Edwin	0.8333333	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.83
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 27447328 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.83
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27382329
Invoice No. 55345 - 27382329

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 69,107 - DH

Chronology

Reported	Sep 14, 2016 2:53:06 PM	Sep 14, 2016 2:53:06 PM
Started	Sep 14, 2016 12:00:00 AM	
Completed	Sep 14, 2016 10:25:00 PM	Sep 14, 2016 10:25:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmA

CAUSE:service

CORRECTION: perform pmA service

Oil filter B329 qty 1

Engine oil 5w20 qty 7 qts

Air filter PA4075 qty 1

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Sep-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18
14-Sep-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-16	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 14-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,100 - Safety Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,631 - Tread Depth RF	6 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,632 - Tread Depth LF	5 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,633 - Tread Depth RRO	4 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,131 - Brake Pad Thickness LF	8 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,132 - Brake Pad Thickness RF	8 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,135 - Brake Rotor LF	36 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,136 - Brake Rotor RF	36 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,137 - Brake Rotor LR	38 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,138 - Brake Rotor RR	38 Inch		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 14, 2016 9:16:46 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 14, 2016 9:16:46 PM	No	

Activity Sub Total

Activity 10 Sub Total

Parts:	7.10
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	7.10



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27382329
Invoice No. 55345 - 27382329

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 69,107 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-16	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM A

Task: PM A SERVICE Performed by: RGASPARD Performed on: 14-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 14, 2016 9:18:31 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 14, 2016 9:18:31 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 14, 2016 9:18:31 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 14, 2016 9:18:31 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 14, 2016 9:18:31 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Sep 14, 2016 9:18:31 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Sep 14, 2016 9:18:31 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 14, 2016 9:18:31 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	1.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27382329
Invoice No. 55345 - 27382329

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	69,107 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
14-Sep-16	Gaspard,Ronald	0.0666666	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 14-SEP-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 14, 2016 9:18:55 PM	No	
20 - Miles			RGASPARD	Sep 14, 2016 9:18:55 PM	No	
30 - Kilometers			RGASPARD	Sep 14, 2016 9:18:55 PM	No	
40 - Hours			RGASPARD	Sep 14, 2016 9:18:55 PM	No	


Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 27382329 Total	
Parts:	7.10
Labor:	0.00
Labor Hours:	2.57

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	7.10



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27440076
Invoice No. 55345 - 27440076

Client Department:

Department: 55345M

Work Order Description

Replaced drivers side head light

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 68,888 - DH

Chronology

Reported	Sep 13, 2016 1:09:41 PM	Sep 13, 2016 1:09:41 PM
Started	Sep 13, 2016 12:00:00 AM	
Completed	Sep 14, 2016 8:57:00 AM	Sep 14, 2016 8:57:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT: road call. Drivers side head light out

CAUSE: light blow out

CORRECTION: Replace head light. Drivers side

Parts used. 1. Head light. 9008. Pig tail harness. 1. 891699

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-16	Capazzoli, Louis	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment


Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 13-SEP-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Sep 13, 2016 1:28:52 PM	No	
20 - Miles			LCAPAZZOLI	Sep 13, 2016 1:28:52 PM	No	
30 - Kilometers			LCAPAZZOLI	Sep 13, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				1:28:52 PM		
40 - Hours			LCAPAZZOLI	Sep 13, 2016 1:28:52 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.50
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27440076
Invoice No. 55345 - 27440076

Client Department:

Department: 55345M

Work Order Description

Replaced drivers side head light

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 68,888 - DH

Activity Header

Activity: 15 034 LIGHTING SYSTEM

Activity Note:

Reason for Repair: 10 Road Call

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Sep-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79
13-Sep-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
13-Sep-16	Capazzoli, Louis	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	13.20
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	13.20

Work Order Footer

Work Order 27440076 Total

Parts:	13.20
Labor:	0.00
Labor Hours:	0.58
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	13.20



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27408897
Invoice No. 55345 - 27408897

Client Department:

Department: 55345M

Work Order Description

bad tire

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 66,859 - DH

Chronology

Reported	Aug 29, 2016 12:50:31 PM	Aug 29, 2016 12:50:31 PM
Started	Aug 29, 2016 12:00:00 AM	
Completed	Aug 30, 2016 11:50:00 AM	Aug 30, 2016 11:50:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

Found inner tire on driver side with only 25psi.

CAUSE:

Tire had a nail in it.

CORRECTION:

Replaced tire with a used but in good condition tire with 4/32 of tread. Set psi to 70. Torqued lug nuts and test drove vehicle. Re-torqued lug nuts. Park at its designated parking spot.

No parts used.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment


Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 29-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Aug 29, 2016 1:54:17 PM	No	
20 - Miles			EDTORRES	Aug 29, 2016 1:54:17 PM	No	
30 - Kilometers			EDTORRES	Aug 29, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				1:54:17 PM			
40 - Hours			EDTORRES	Aug 29, 2016 1:54:17 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27408897
Invoice No. 55345 - 27408897

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
bad tire		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	Status:	40 - Closed (40)
Created By:	LCAPAZZOLI	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	66,859 - DH

Activity Header				
Activity: 15 017 TIRES, TUBES, LINERS & VALVES				
Activity Note: Found inner tire with only 25 psi.				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
29-Aug-16	Torres,Edwin	0.8166666	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.82
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 27408897 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.82
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27231246
Invoice No. 55345 - 27231246

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 64,794 - DH

Chronology

Reported	Aug 12, 2016 11:30:05 AM	Aug 12, 2016 11:30:05 AM
Started	Aug 12, 2016 12:00:00 AM	
Completed	Aug 12, 2016 10:38:00 PM	Aug 12, 2016 10:38:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:pmB

CAUSE:service

CORRECTION:perform pmB service

Oil filter B329 qty1

Engine oil 5w20 qty 7qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Mediu Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
12-Aug-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-16	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Mediu Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 12-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,420 - Check Hood	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,631 - Tread Depth RF	7 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,632 - Tread Depth LF	7 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,634 - Tread Depth RRI	6 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,636 - Tread Depth LRO	6 32nds of an inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,670 - Check Dual Mating With Square	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,135 - Brake Rotor LF	37 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,136 - Brake Rotor RF	37 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Aug 12, 2016 9:57:04 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Aug 12, 2016 9:57:04 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27231246
Invoice No. 55345 - 27231246

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 64,794 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-16	Gaspard,Ronald	1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM B

Task: PM B SERVICE Performed by: RGASPARD Performed on: 12-AUG-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Aug 12, 2016 9:58:00 PM	No	
105,000 - Replace or Clean A/C Filters	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	na	RGASPARD	Aug 12, 2016 9:58:00 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Aug 12, 2016 9:58:00 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Aug 12, 2016 9:58:00 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27231246
Invoice No. 55345 - 27231246

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	64,794 - DH

Activity Header

Activity:30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Aug-16	Gaspard,Ronald	0.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 12-AUG-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Aug 12, 2016 9:58:22 PM	No	
20 - Miles			RGASPARD	Aug 12, 2016 9:58:22 PM	No	
30 - Kilometers			RGASPARD	Aug 12, 2016 9:58:22 PM	No	
40 - Hours			RGASPARD	Aug 12, 2016 9:58:22 PM	No	

Activity Sub Total

Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 27231246 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.55

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27344532
Invoice No. 55345 - 27344532

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
ABS light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	62,883 - DH

Chronology		
Reported	Jul 27, 2016 2:50:47 PM	Jul 27, 2016 2:50:47 PM
Started	Jul 27, 2016 12:00:00 AM	
Completed	Jul 28, 2016 8:11:00 AM	Jul 28, 2016 8:11:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: ABS light on

CAUSE: Damaged Right front ABS sensor line

CORRECTION: Right front ABS sensor replacement

Complaint verified
Visual inspection performed
Right front ABS sensor line found broken
Right front ABS sensor replaced
Road test performed and ABS warning light cleared

Part used:
One (1) right ABS sensor#BC2Z-2C205-A

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 27-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jul 27, 2016 3:20:22 PM	No	
20 - Miles			FSIMON	Jul 27, 2016 3:20:22 PM	No	
30 - Kilometers			FSIMON	Jul 27, 2016 3:20:22 PM	No	
40 - Hours			FSIMON	Jul 27, 2016 3:20:22 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27344532
Invoice No. 55345 - 27344532

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
ABS light on		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	62,883 - DH

Activity Header
Activity:15 013 BRAKES
Activity Note: Brake light on
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-Jul-16	BC2Z-2C205-A	SENSOR, SPEED, WHEEL, REAR, LEFT	1	32.52	32.52

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Jul-16	Simon,Fritz	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>32.52</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>32.52</td></tr></table>		Activity 15 Sub Total		Parts:	32.52	Labor:	0.00	Labor Hours:	0.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	32.52
Activity 15 Sub Total															
Parts:	32.52														
Labor:	0.00														
Labor Hours:	0.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	32.52														

Work Order Footer															
<table><tr><th colspan="2">Work Order 27344532 Total</th></tr><tr><td>Parts:</td><td>32.52</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>32.52</td></tr></table>		Work Order 27344532 Total		Parts:	32.52	Labor:	0.00	Labor Hours:	0.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	32.52
Work Order 27344532 Total															
Parts:	32.52														
Labor:	0.00														
Labor Hours:	0.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	32.52														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27242278
Invoice No. 55345 - 27242278

Client Department:

Department: 55345M

Work Order Description

Rear ac vent is missing

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 61,272 - DH

Chronology

Reported	Jul 15, 2016 8:29:53 AM	Jul 15, 2016 8:29:53 AM
Started	Jul 15, 2016 12:00:00 AM	
Completed	Jul 18, 2016 8:02:00 AM	Jul 18, 2016 8:02:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

Missing 1 rear ac vent

CAUSE:

Someone pressed ac vent too hard which cause the vent to break apart.

CORRECTION:

Replaced A/C with a new A/C vent.

PARTS

Parts covered under warranty.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 15-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDITORRES	Jul 15, 2016 8:33:23 AM	No	
20 - Miles			EDITORRES	Jul 15, 2016 8:33:23 AM	No	
30 - Kilometers			EDITORRES	Jul 15, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				8:33:23 AM			
40 - Hours			EDITORRES	Jul 15, 2016 8:33:23 AM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27242278
Invoice No. 55345 - 27242278

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear ac vent is missing		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	61,272 - DH

Activity Header
Activity:15 050 GROUP, ACCESSORIES
Activity Note: Missing 1 rear ac vent
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
15-Jul-16	Torres,Edwin	0.3833333	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.38
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 27242278 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			0.38
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27240039
Invoice No. 55345 - 27240039

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE LEFT FRONT SIDE MARKER		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	61,091 - DH

Chronology		
Reported	Jul 13, 2016 8:57:23 PM	Jul 13, 2016 8:57:23 PM
Started	Jul 13, 2016 12:00:00 AM	
Completed	Jul 13, 2016 9:17:00 PM	Jul 13, 2016 9:17:00 PM
Down Time		

Work Order Notes

Line 10
COMPLAINT: LEFT FRONT SIDE MARKER OUT

CAUSE:BLOWN SIDE MARKER BULB

CORRECTION: REPLACE LEFT FRONT SIDE MARKER
PARTS: S 168 QTY 1

Activity Header Activity: 5 999 TOTAL VEHICLE Activity Note: Personal Risk Assessment Reason for Repair: 05 Inspection, Routine Work Accomplished: 06 Inspect Part Failure: Activity Comments:						
Activity Parts No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
13-Jul-16	Owens,Arthur	0.0333333	0	0		
Activity Sublet No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment Task: PRA and Meter Readings Performed by: AOWENS Performed on: 13-JUL-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 13, 2016 9:00:03 PM	No	
20 - Miles			AOWENS	Jul 13, 2016 9:00:03 PM	No	
30 - Kilometers			AOWENS	Jul 13, 2016 9:00:03 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
40 - Hours			AOWENS	Jul 13, 2016 9:00:03 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.03
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27240039
Invoice No. 55345 - 27240039

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE LEFT FRONT SIDE MARKER		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	61,091 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE LEFT FRONT SIDE MARKER
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-16	168	BULB, WEDGE, 12V/3CP	2	0.23	0.46

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
13-Jul-16	Owens,Arthur	0.0666666	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	0.46
Labor:	0.00
Labor Hours:	0.07
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.46

Work Order Footer	
Work Order 27240039 Total	
Parts:	0.46
Labor:	0.00
Labor Hours:	0.10
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.46



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27237284
Invoice No. 55345 - 27237284

Client Department:

Department: 55345M

Work Order Description

Check driver seat and rear tires

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,998 - DH

Chronology

Reported	Jul 12, 2016 11:42:01 AM	Jul 12, 2016 11:42:01 AM
Started	Jul 12, 2016 12:00:00 AM	
Completed	Jul 12, 2016 1:59:00 PM	Jul 12, 2016 1:59:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: check driver seat and rear tires

CAUSE:driver ripe

CORRECTION: replace driver seat cover and replace 2rear tires by 2 good use one completed
Part cover under warranty, seat cover

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 12-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jul 12, 2016 1:49:08 PM	No	
20 - Miles			HPIERRE	Jul 12, 2016 1:49:08 PM	No	
30 - Kilometers			HPIERRE	Jul 12, 2016 1:49:08 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
40 - Hours			HPIERRE	Jul 12, 2016 1:49:08 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.08
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27237284
Invoice No. 55345 - 27237284

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check driver seat and rear tires		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	60,998 - DH

Activity Header
Activity: 15 050/000 GROUP, ACCESSORIES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 14 Install
Part Failure: 00 No Failure
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
12-Jul-16	Pierre, Hubert J	2	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.00
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00

Work Order Footer		Work Order 27237284 Total	
Parts:			0.00
Labor:			0.00
Labor Hours:			2.08
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27233148
Invoice No. 55345 - 27233148

Client Department:

Department: 55345M

Work Order Description

Rear Brake

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,706 - DH

Chronology

Reported	Jul 8, 2016 4:09:29 PM	Jul 8, 2016 4:09:29 PM
Started	Jul 8, 2016 12:00:00 AM	
Completed	Jul 8, 2016 10:26:00 PM	Jul 8, 2016 10:26:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: Rear Brake Low/ uneven Wear,

CAUSE: Slide Pins Seize

CORRECTION: Clean Slide Pin/Lubricate with Grease and Replace Rear Pad,
Parts#BRSD1330 Rear Pads Qty (1)

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 08-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	Jul 8, 2016 4:12:14 PM	No	
20 - Miles			DARTHURS	Jul 8, 2016 4:12:14 PM	No	
30 - Kilometers			DARTHURS	Jul 8, 2016 4:12:14 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
40 - Hours			DARTHURS	Jul 8, 2016 4:12:14 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.08
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27233148
Invoice No. 55345 - 27233148

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Rear Brake		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	60,706 - DH

Activity Header
Activity:15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: Rear Brakes Low
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Jul-16	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
08-Jul-16	Arthurs,Durvin	1.5	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			43.15
Labor:			0.00
Labor Hours:			1.50
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			43.15

Work Order Footer		Work Order 27233148 Total	
Parts:			43.15
Labor:			0.00
Labor Hours:			1.58
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			43.15



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27138576
Invoice No. 55345 - 27138576

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,507 - DH

Chronology

Reported	Jul 5, 2016 12:46:00 PM	Jul 5, 2016 12:46:00 PM
Started	Jul 7, 2016 12:00:00 AM	
Completed	Jul 7, 2016 2:01:01 PM	Jul 7, 2016 2:01:01 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm -A inspection due

CAUSE: where

CORRECTION: Completed pm -A inspection. Replace oil and oil filter

Parts used 6 quarts oil 5 -w20. 1 oil filter Br329

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-16	Capazzoli, Louis	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 07-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,131 - Brake Pad Thickness LF	Inch	4 mm	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,132 - Brake Pad Thickness RF	Inch	4 mm	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	Yes	27231146
77,133 - Brake Pad Thickness LR	Inch	12 mm	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,134 - Brake Pad Thickness RR	Inch	12 mm	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,135 - Brake Rotor LF	Inch	40	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,136 - Brake Rotor RF	Inch	40	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,137 - Brake Rotor LR	Inch	40	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,138 - Brake Rotor RR	Inch	40	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Jul 7, 2016 12:56:40 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27138576
Invoice No. 55345 - 27138576

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,507 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-16	Capazzoli, Louis	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM A

Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 07-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Jul 7, 2016 12:57:20 PM	No	

Activity Sub Total


Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27138576
Invoice No. 55345 - 27138576

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	60,507 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 07-JUL-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jul 7, 2016 1:00:22 PM	No	
20 - Miles			LCAPAZZOLI	Jul 7, 2016 1:00:22 PM	No	
30 - Kilometers			LCAPAZZOLI	Jul 7, 2016 1:00:22 PM	No	
40 - Hours			LCAPAZZOLI	Jul 7, 2016 1:00:22 PM	No	


Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 27138576 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27231146
Invoice No. 55345 - 27231146

Client Department:

Department: 55345M

Work Order Description

Front Brake Job

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,507 - DH

Chronology

Reported	Jul 7, 2016 12:56:40 PM	Jul 7, 2016 12:56:40 PM
Started	Jul 7, 2016 12:00:00 AM	
Completed	Jul 7, 2016 2:00:00 PM	Jul 7, 2016 2:00:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brakes due to under specs. Parts used. 1 set of front brake pads. BRSD- 1228

Activity Header

Activity: 10 013/001 BRAKES & DRUMS, FRONT

Activity Note: 4 mm

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Jul-16	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-16	Capazzoli, Louis	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	50.32
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	50.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27231146
Invoice No. 55345 - 27231146

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Front Brake Job		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	Status:	40 - Closed (40)
Created By:	LCAPAZZOLI	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	60,507 - DH

Activity Header
Activity:20 013 BRAKES
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Jul-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Check List						
20 Desc: Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 07-JUL-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Jul 7, 2016 1:17:52 PM	No	
20 - Miles			LCAPAZZOLI	Jul 7, 2016 1:17:52 PM	No	
30 - Kilometers			LCAPAZZOLI	Jul 7, 2016 1:17:52 PM	No	
40 - Hours			LCAPAZZOLI	Jul 7, 2016 1:17:52 PM	No	

Activity Sub Total	
Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 27231146 Total	
Parts:	50.32
Labor:	0.00
Labor Hours:	1.58

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	50.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27228203
Invoice No. 55345 - 27228203

Client Department:

Department: 55345M

Work Order Description

REPLACE WHEELCHAIR BAG

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,221 - DH

Chronology

Reported	Jul 5, 2016 4:49:32 PM	Jul 5, 2016 4:49:32 PM
Started	Jul 5, 2016 12:00:00 AM	
Completed	Jul 5, 2016 6:27:00 PM	Jul 5, 2016 6:27:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: WHEEL CHAIR BAG RIP

CAUSE:NORMAL USAGE

CORRECTION: REPLACE WHEEL CHAIR BAG
PART WARRANTY

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Owens,Arthur	0.1	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: AOWENS Performed on: 05-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		AOWENS	Jul 5, 2016 6:26:31 PM	No	
20 - Miles			AOWENS	Jul 5, 2016 6:26:31 PM	No	
30 - Kilometers			AOWENS	Jul 5, 2016 6:26:31 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO																					
40 - Hours			AOWENS	Jul 5, 2016 6:26:31 PM	No																						
Activity Sub Total			<table><tr><td colspan="2">Activity 5 Sub Total</td><td></td></tr><tr><td>Parts:</td><td></td><td>0.00</td></tr><tr><td>Labor:</td><td></td><td>0.00</td></tr><tr><td>Labor Hours:</td><td></td><td>0.10</td></tr><tr><td>Sublet Parts:</td><td></td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td></td><td>0.00</td></tr><tr><td colspan="2">Activity Sub Total</td><td>0.00</td></tr></table>				Activity 5 Sub Total			Parts:		0.00	Labor:		0.00	Labor Hours:		0.10	Sublet Parts:		0.00	Sublet Labor:		0.00	Activity Sub Total		0.00
Activity 5 Sub Total																											
Parts:		0.00																									
Labor:		0.00																									
Labor Hours:		0.10																									
Sublet Parts:		0.00																									
Sublet Labor:		0.00																									
Activity Sub Total		0.00																									



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27228203
Invoice No. 55345 - 27228203

Client Department:

Department: 55345M

Work Order Description

REPLACE WHEELCHAIR BAG

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,221 - DH

Activity Header

Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER

Activity Note: REPLACE WHEEL CHAIR BAG

Reason for Repair: 05 Inspection, Routine

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Owens, Arthur	0.65	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.65
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 27228203 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.75
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27226933
Invoice No. 55345 - 27226933

Client Department:

Department: 55345M

Work Order Description

Passenger headlight is dim.

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 60,054 - DH

Chronology

Reported	Jul 5, 2016 7:19:08 AM	Jul 5, 2016 7:19:08 AM
Started	Jul 5, 2016 12:00:00 AM	
Completed	Jul 5, 2016 8:40:00 AM	Jul 5, 2016 8:40:00 AM
Down Time		

Work Order Notes

Line 10

Headlight Pigtail

COMPLAINT:

Passenger side headlight is out

CAUSE:

Pigtail harness is bad.

CORRECTION:

Replaced passenger side headlight and pigtail harness.

PARTS:

9008 headlight bulb qty 1

891699 headlight pigtail qty 1

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 05-JUL-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		EDITORRES	Jul 5, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
Personal Risk Assessment?				7:26:02 AM			
20 - Miles			EDITORRES	Jul 5, 2016 7:26:02 AM	No		
30 - Kilometers			EDITORRES	Jul 5, 2016 7:26:02 AM	No		
40 - Hours			EDITORRES	Jul 5, 2016 7:26:02 AM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27226933
Invoice No. 55345 - 27226933

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Passenger headlight is dim.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	60,054 - DH

Activity Header
Activity:15 030 ELECTRICAL GROUP
Activity Note: Passenger headlight is dim.
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
05-Jul-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.41	7.41
05-Jul-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
05-Jul-16	Torres,Edwin	0.6666666	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
Parts:			13.20
Labor:			0.00
Labor Hours:			0.67
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			13.20

Work Order Footer		Work Order 27226933 Total	
Parts:			13.20
Labor:			0.00
Labor Hours:			0.67
Sublet Parts:			0.00
Sublet Labor:			0.00
Activity Sub Total			13.20



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27203828
Invoice No. 55345 - 27203828

Client Department:

Department: 55345M

Work Order Description

Check bus for fuel odor

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 59,616 - DH

Chronology

Reported	Jun 20, 2016 3:22:50 PM	Jun 20, 2016 3:22:50 PM
Started	Jun 28, 2016 12:00:00 AM	
Completed	Jun 30, 2016 7:58:00 AM	Jun 30, 2016 7:58:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:Bus smelling fuel

CAUSE:Fuel Rail supply line leaking

CORRECTION:Replace fuel rail supply lines and fittings

Complaint verified

Fuel rail supply lines leaking

Fuel rail supply lines and fittings replaced by Damian (Creatives Bus Sales)

One rear condenser fan replaced

Parts used:

One (1) condenser fan(under warranty)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 28-JUN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jun 28, 2016 3:30:48 PM	No	
20 - Miles			FSIMON	Jun 28, 2016 3:30:48 PM	No	
30 - Kilometers			FSIMON	Jun 28, 2016 3:30:48 PM	No	
40 - Hours			FSIMON	Jun 28, 2016 3:30:48 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27203828
Invoice No. 55345 - 27203828

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check bus for fuel odor		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	59,616 - DH

Activity Header
Activity: 15
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Jun-16	Simon,Fritz	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 27203828 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 27186582
Invoice No. 55345 - 27186582

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Passenger side headlight out		Ford E450 Champion Challenger	
Requested By:	RAURODRIGUEZ	Status:	40 - Closed (40)
Created By:	RAURODRIGUEZ	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	58,617 - DH

Chronology		
Reported	Jun 14, 2016 7:03:29 AM	Jun 14, 2016 7:03:29 AM
Started	Jun 14, 2016 12:00:00 AM	
Completed	Jun 14, 2016 7:24:00 AM	Jun 14, 2016 7:24:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:
Passenger side headlight out

CAUSE:
Pigtail bad

CORRECTION:
Removed and replaced pigtail and bulb

Parts: 1 headlight bulb, # 9008
1 pigtail, # 891699

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair:		05 Inspection, Routine				
Work Accomplished:		06 Inspect				
Part Failure:						
Activity Comments:						
Activity Parts						
Booked Date	Part Number	Part Description	Quantity	Each	Extended	
14-Jun-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.14	7.14	
14-Jun-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79	
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
14-Jun-16	Rodriguez,Raul	0.5666666	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						

Check List																				
5 Desc: Personal Risk Assessment																				
Task: PRA and Meter Readings Performed by: RAUODRIGUEZ Performed on: 14-JUN-16																				
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
10 - Have you successfully completed the Personal Risk Assessment?	Done		RAUODRIGUEZ	Jun 14, 2016 7:11:01 AM	No															
20 - Miles			RAUODRIGUEZ	Jun 14, 2016 7:11:01 AM	No															
30 - Kilometers			RAUODRIGUEZ	Jun 14, 2016 7:11:01 AM	No															
40 - Hours			RAUODRIGUEZ	Jun 14, 2016 7:11:01 AM	No															
Activity Sub Total																				
			<table border="1"> <thead> <tr> <th colspan="2">Activity 5 Sub Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>12.93</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.57</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>12.93</td> </tr> </tbody> </table>				Activity 5 Sub Total		Parts:	12.93	Labor:	0.00	Labor Hours:	0.57	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	12.93
Activity 5 Sub Total																				
Parts:	12.93																			
Labor:	0.00																			
Labor Hours:	0.57																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	12.93																			
Work Order Footer																				
			<table border="1"> <thead> <tr> <th colspan="2">Work Order 27186582 Total</th> </tr> </thead> <tbody> <tr> <td>Parts:</td> <td>12.93</td> </tr> <tr> <td>Labor:</td> <td>0.00</td> </tr> <tr> <td>Labor Hours:</td> <td>0.57</td> </tr> <tr> <td>Sublet Parts:</td> <td>0.00</td> </tr> <tr> <td>Sublet Labor:</td> <td>0.00</td> </tr> <tr> <td>Activity Sub Total</td> <td>12.93</td> </tr> </tbody> </table>				Work Order 27186582 Total		Parts:	12.93	Labor:	0.00	Labor Hours:	0.57	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	12.93
Work Order 27186582 Total																				
Parts:	12.93																			
Labor:	0.00																			
Labor Hours:	0.57																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	12.93																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 27159740
Invoice No. 55345 - 27159740

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Help Desk		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	HD - HELP DESK	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	56,611 - DH

Chronology

Reported	May 26, 2016 10:43:00 AM	May 26, 2016 10:43:00 AM
Started	Jun 1, 2016 12:00:00 AM	
Completed	Jun 1, 2016 2:13:16 PM	Jun 1, 2016 2:13:16 PM
Down Time		

Work Order Notes

Line 10 I have a new Technician working for my Location. Technician needs a Username and Password in order to login in Infor.
I need assistance with this.

Activity Header

Activity: 10

Activity Note:

Reason for Repair:

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jun-16	Mark Bond	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 27159740 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27158174
Invoice No. 55345 - 27158174

Client Department:

Department: 55345M

Work Order Description

Hinge for driver door in not working properly.

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 56,288 - DH

Chronology

Reported	May 25, 2016 12:32:15 PM	May 25, 2016 12:32:15 PM
Started	May 25, 2016 12:00:00 AM	
Completed	May 25, 2016 1:43:00 PM	May 25, 2016 1:43:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

Hinge for driver door not working properly

CAUSE:

Bracket for Roller pin for the pin broke, which caused the pin and the roller to fall out of place.

CORRECTION:

Removed bad hinge and installed a new hinge.

PARTS:

Qty 1 Driver door hinge 6C2Z-1522810-A

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 25-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	May 25, 2016 12:38:16 PM	No	
20 - Miles			EDTORRES	May 25, 2016 12:38:16 PM	No	
30 - Kilometers			EDTORRES	May 25, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				12:38:16 PM			
40 - Hours			EDTORRES	May 25, 2016 12:38:16 PM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27158174
Invoice No. 55345 - 27158174

Client Department:

Department: 55345M

Work Order Description

Hinge for driver door in not working properly.

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 56,288 - DH

Activity Header

Activity: 15

Activity Note: Hinge for driver door in not working properly.

Reason for Repair: 39 Natural Causes

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-Jun-16	6C2Z-1522-810A	OUT OF SERVICE HINGE, DOOR, LOWER, LH, E450	1	46.61	46.61
25-May-16	6C2Z-1522-810A	OUT OF SERVICE HINGE, DOOR, LOWER, LH, E450	1	46.61	46.61

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
25-May-16	Torres,Edwin	1.15	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	93.22
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	93.22

Work Order Footer

Work Order 27158174 Total

Parts:	93.22
Labor:	0.00
Labor Hours:	1.15
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	93.22



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27138579
Invoice No. 55345 - 27138579

Client Department:

Department: 55345M

Work Order Description

Interior light

Requested By: DARTHURS

Created By: DARTHURS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 55,907 - DH

Chronology

Reported	May 22, 2016 3:06:15 PM	May 22, 2016 3:06:15 PM
Started	May 22, 2016 12:00:00 AM	
Completed	May 22, 2016 3:18:00 PM	May 22, 2016 3:18:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: interior Light

CAUSE:bulb blown

CORRECTION: Replace interior Light

Qty (1) Parts under Warranry

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment


Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 22, 2016 3:16:40 PM	No	
20 - Miles			DARTHURS	May 22, 2016 3:16:40 PM	No	
30 - Kilometers			DARTHURS	May 22, 2016 3:16:40 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO														
40 - Hours			DARTHURS	May 22, 2016 3:16:40 PM	No															
Activity Sub Total			<table><tr><th colspan="2">Activity 5 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.08</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>				Activity 5 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.08	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 5 Sub Total																				
Parts:	0.00																			
Labor:	0.00																			
Labor Hours:	0.08																			
Sublet Parts:	0.00																			
Sublet Labor:	0.00																			
Activity Sub Total	0.00																			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27138579
Invoice No. 55345 - 27138579


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Interior light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	55,907 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: One interior light out				
Reason for Repair: 05 Inspection, Routine				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-16	Arthurs,Durvin	0.5	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27138579
Invoice No. 55345 - 27138579

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Interior light		Ford E450 Champion Challenger	
Requested By:	DARTHURS	Status:	40 - Closed (40)
Created By:	DARTHURS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	55,907 - DH

Activity Header															
Activity:25 079 DEVICES, SAFETY/STABILITY, TRAILER															
Activity Note: One interior Light out															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 25 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 25 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 25 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 27138579 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.58</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 27138579 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.58	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 27138579 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.58														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27065894
Invoice No. 55345 - 27065894

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 55,907 - DH

Chronology

Reported	May 20, 2016 2:39:52 PM	May 20, 2016 2:39:52 PM
Started	May 22, 2016 12:00:00 AM	
Completed	May 22, 2016 3:06:00 PM	May 22, 2016 3:06:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:PMA Service

CAUSE:Due by Mileage

CORRECTION:Change Oil /Filter Lube All pivoting Points Clean Rear AC Filter Remove All wheel and check Brakes/ Repack both Front wheel bearing,
Parts B329 Oil Filter Qty (1)
Oil5w20 Qty (7) Qts

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
23-May-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-16	Arthurs,Durvin	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: DARTHURS Performed on: 22-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,100 - Safety Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,140 - Check Service Brakes	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,160 - FRA Check Instruments and Horns	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,170 - Check Fast Idle	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,180 - Check Starter Protection Circuit	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
10,190 - Check Reverse Warning System	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,100 - Check Parking Brake	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,150 - Perform Brake Test	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
11,170 - FRA Check Door Operation	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,210 - Check Condition of Operator's Area	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,240 - FRA Check Interior Lights	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,260 - Check Stop Request System	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
22,110 - Check Emergency Hatches	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
22,120 - Check All Safety Equipment	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,310 - Check Passenger Doors	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,360 - Check for Physical Damage and Decals	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,380 - Check Exterior Compartment Doors	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
33,100 - Check Lights and Reflectors	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,420 - Check Hood	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,130 - FRA Check Exhaust System	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,140 - FRA Check Intake System	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,150 - FRA Inspect Turbocharger	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,180 - FRA Check for Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,190 - FRA Perform Battery Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
50,510 - Check Entire Steering System	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,630 - Check and Record Tread Depth	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,634 - Tread Depth RRI	9 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,635 - Tread Depth LRI	6 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,636 - Tread Depth LRO	4 32nds of an inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,650 - Check Sidewall Wear	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,660 - Inspect for Cuts and Tears	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,670 - Check Dual Mating With Square	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,710 - Check Vibration Damper	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,730 - FRA Check Starter	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,770 - FRA Check Exhaust System	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,120 - Check Suspension Components	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,131 - Brake Pad Thickness LF	6 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,132 - Brake Pad Thickness RF	7 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,135 - Brake Rotor LF	1.596 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,136 - Brake Rotor RF	1.595 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,137 - Brake Rotor LR	1.418 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,138 - Brake Rotor RR	1.417 Inch		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,140 - FRA Check Brake Hoses	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
77,150 - Check King Pins	-	NA	DARTHURS	May 22, 2016 3:05:51 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done	Repack both front wheel bearing	DARTHURS	May 22, 2016 3:05:51 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
80,810 - Completion of PMI Report	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		DARTHURS	May 22, 2016 3:05:51 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27065894
Invoice No. 55345 - 27065894

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	55,907 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-May-16	Arthurs,Durvin	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: DARTHURS Performed on: 22-MAY-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		DARTHURS	May 22, 2016 2:54:13 PM	No	
101,000 - FRA Change Oil Filters	Yes		DARTHURS	May 22, 2016 2:54:13 PM	No	
102,000 - FRA Drain Engine Oil	Yes		DARTHURS	May 22, 2016 2:54:13 PM	No	
103,000 - FRA Check Transmission Fluid	Done		DARTHURS	May 22, 2016 2:54:13 PM	No	
104,000 - Lubricate Chassis	Done		DARTHURS	May 22, 2016 2:54:13 PM	No	
105,000 - Replace or Clean A/C Filters	Done		DARTHURS	May 22, 2016 2:54:13 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	NA	DARTHURS	May 22, 2016 2:54:13 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		DARTHURS	May 22, 2016 2:54:13 PM	No	

Activity Sub Total	
Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27065894
Invoice No. 55345 - 27065894

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 55,907 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-16	Arthurs,Durvin	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: DARTHURS Performed on: 22-MAY-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		DARTHURS	May 22, 2016 2:54:38 PM	No	
20 - Miles			DARTHURS	May 22, 2016 2:54:38 PM	No	
30 - Kilometers			DARTHURS	May 22, 2016 2:54:38 PM	No	
40 - Hours			DARTHURS	May 22, 2016 2:54:38 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 27065894 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27006613
Invoice No. 55345 - 27006613

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	51,701 - DH

Chronology		
Reported	Apr 19, 2016 9:46:51 AM	Apr 19, 2016 9:46:51 AM
Started	Apr 19, 2016 12:00:00 AM	
Completed	Apr 20, 2016 9:41:00 AM	Apr 20, 2016 9:41:00 AM
Down Time		

Work Order Notes

Line 10 PMC

Preventive maintenance

Perform service,lube all pivoting point and cross rotate front tires, perform transmission service and replace filter complete

Parts # oil filter #B329 qty 1

Oil# 6qrt

Transmission fluid #8/5qts

Transmission filter # ft -180-8c3z-7a098-d qty 1

Activity Header						
Activity:10 999 TOTAL VEHICLE						
Activity Note: Light Medium Duty PMI						
Reason for Repair: 08 Preventive Maintenance						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
19-Apr-16	Pierre,Hubert J	3	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
10 Desc: Light Medium Duty PMI						
Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 19-APR-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,100 - Safety Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,110 - FRA Check Drivers Pre-trip or	Done		HPIERRE	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
DVIR/EVIR & Authorization Forms				11:27:09 AM		
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,270 - Check Fare Box Mounting (If	-	N/A	HPIERRE	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Applicable)				11:27:09 AM		
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,420 - Check Hood	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,460 - Record Antifreeze Protection Level	-	N/A	HPIERRE	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Using Refractometer				11:27:09 AM		
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:27:09 AM		
60,630 - Check and Record Tread Depth	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,631 - Tread Depth RF	10 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,632 - Tread Depth LF	10 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Apr 19, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:27:09 AM		
77,120 - Check Suspension Components	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,131 - Brake Pad Thickness LF	8 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,132 - Brake Pad Thickness RF	8 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,133 - Brake Pad Thickness LR	7 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,134 - Brake Pad Thickness RR	7 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,135 - Brake Rotor LF	1.8 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,136 - Brake Rotor RF	1.8 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,137 - Brake Rotor LR	1.6 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,138 - Brake Rotor RR	1.6 Inch		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Apr 19, 2016 11:27:09 AM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Apr 19, 2016 11:27:09 AM	No	


Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	3.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27006613
Invoice No. 55345 - 27006613

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 51,701 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM C

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Pierre,Hubert J	1.0166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM C

Task: PM C SERVICE Performed by: HPIERRE Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
107,000 - FRA Change Primary Fuel Filter	-	N/A	HPIERRE	Apr 19, 2016 11:28:42 AM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	Yes		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
301,000 - Check and Lubricate Door Linkages	Done		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
302,000 - Check Toe-In and Record Reading	-	N/A	HPIERRE	Apr 19, 2016 11:28:42 AM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	N/A	HPIERRE	Apr 19, 2016 11:28:42 AM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		HPIERRE	Apr 19, 2016 11:28:42 AM	No	
305,000 - FRA Change Differential Fluid	No		HPIERRE	Apr 19, 2016 11:28:42 AM	No	


Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	1.02
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27006613
Invoice No. 55345 - 27006613

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 51,701 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
19-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 19-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 19, 2016 11:29:00 AM	No	
20 - Miles			HPIERRE	Apr 19, 2016 11:29:00 AM	No	
30 - Kilometers			HPIERRE	Apr 19, 2016 11:29:00 AM	No	
40 - Hours			HPIERRE	Apr 19, 2016 11:29:00 AM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 27006613 Total

Parts:	0.00
Labor:	0.00
Labor Hours:	4.10

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 27053037
Invoice No. 55345 - 27053037

Client Department:

Department: 55345M

Work Order Description

Check engine air filter

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 51,522 - DH

Chronology

Reported	Apr 15, 2016 1:48:45 PM	Apr 15, 2016 1:48:45 PM
Started	Apr 15, 2016 12:00:00 AM	
Completed	Apr 19, 2016 7:52:00 AM	Apr 19, 2016 7:52:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT: check engine air filter

CAUSE:air filter are dirty

CORRECTION: replace air filter complete
Part # air filter PA 4075 qty 1

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 18-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Apr 18, 2016 3:02:27 PM	No	
20 - Miles			HPIERRE	Apr 18, 2016 3:02:27 PM	No	
30 - Kilometers			HPIERRE	Apr 18, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				3:02:27 PM		
40 - Hours			HPIERRE	Apr 18, 2016 3:02:27 PM	No	
Activity Sub Total			Activity 5 Sub Total			
			Parts:		0.00	
			Labor:		0.00	
			Labor Hours:		0.08	
			Sublet Parts:		0.00	
			Sublet Labor:		0.00	
			Activity Sub Total		0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 27053037
Invoice No. 55345 - 27053037

Client Department:

Department: 55345M

Work Order Description

Check engine air filter

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 51,522 - DH

Activity Header

Activity: 15 999 TOTAL VEHICLE

Activity Note:

Reason for Repair: 05 Inspection, Routine

Work Accomplished: D PM Level D

Part Failure: 00 No Failure

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Apr-16	PA4075	OUT OF SERVICE DO NOT ORDER FILTER, AIR, PAPER SAME AS AF25590	1	5.18	5.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Apr-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total	
Parts:	5.18
Labor:	0.00
Labor Hours:	0.42
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	5.18



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 27053037
Invoice No. 55345 - 27053037


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Check engine air filter		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	51,522 - DH

Activity Header															
Activity: 25 041 INTAKE, AIR															
Activity Note: activity was created by mistake															
Reason for Repair: 05 Inspection, Routine															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 25 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 25 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 25 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 27053037 Total</td></tr><tr><td>Parts:</td><td>5.18</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.50</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>5.18</td></tr></table>		Work Order 27053037 Total		Parts:	5.18	Labor:	0.00	Labor Hours:	0.50	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	5.18
Work Order 27053037 Total															
Parts:	5.18														
Labor:	0.00														
Labor Hours:	0.50														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	5.18														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27043264
Invoice No. 55345 - 27043264

Client Department:

Department: 55345M

Work Order Description

External Fuel filter replacement

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 50,177 - DH

Chronology

Reported	Apr 8, 2016 12:15:38 PM	Apr 8, 2016 12:15:38 PM
Started	Apr 8, 2016 12:00:00 AM	
Completed	Apr 8, 2016 1:24:00 PM	Apr 8, 2016 1:24:00 PM
Down Time		

Work Order Notes

Line 10

COMPLAINT: External Fuel filter (service)

CAUSE:Preventive maintenance

CORRECTION:External Fuel filter replacement

Bus reaches the mileage for external fuel filter replacement

Fuel filter replaced

Part used

One (1) fuel filter replaced

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
08-Apr-16	Simon,Fritz	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 08-APR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Apr 8, 2016 12:26:36 PM	No	
20 - Miles			FSIMON	Apr 8, 2016 12:26:36 PM	No	
30 - Kilometers			FSIMON	Apr 8, 2016 12:26:36 PM	No	
40 - Hours			FSIMON	Apr 8, 2016 12:26:36 PM	No	

Activity Sub Total

Activity 5 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27043264
Invoice No. 55345 - 27043264

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
External Fuel filter replacement		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	50,177 - DH

Activity Header
Activity:15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 08 Preventive Maintenance
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
19-Sep-16	P11BB-9155-AB	FILTER, FUEL, ROUSH NO CROSS	1	78.94	78.94

Activity Labor
No Data Available

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	78.94
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	78.94

Work Order Footer		Work Order 27043264 Total	
		Parts:	78.94
		Labor:	0.00
		Labor Hours:	0.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	78.94



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 27008052
Invoice No. 55345 - 27008052

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Left headlight not glowing		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	47,445 - DH

Chronology		
Reported	Mar 18, 2016 8:03:17 AM	Mar 18, 2016 8:03:17 AM
Started	Mar 18, 2016 12:00:00 AM	
Completed	Mar 21, 2016 7:04:00 AM	Mar 21, 2016 7:04:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT:Left headlight not glowing

CAUSE:Burnt headlight socket and bulb

CORRECTION:Headlight bulb and connector replaced

Complaint verified
Headlight socket and bulb found burnt
Headlight socket and bulb replaced

Parts utilized
One (1)bulb 9008
One (1) headlight socket 891699

Activity Header
Activity: 5 999 TOTAL VEHICLE
Activity Note: Personal Risk Assessment
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:
Activity Parts
No Data Available
Activity Labor
No Data Available
Activity Sublet
No Data Available
Activity Checklist
Check List
5 Desc: Personal Risk Assessment
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 18-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Mar 18, 2016 8:16:47 AM	No	
20 - Miles			FSIMON	Mar 18, 2016 8:16:47 AM	No	
30 - Kilometers			FSIMON	Mar 18, 2016 8:16:47 AM	No	
40 - Hours			FSIMON	Mar 18, 2016 8:16:47 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 27008052
Invoice No. 55345 - 27008052

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Left headlight not glowing		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	47,445 - DH

Activity Header
Activity:15 034 LIGHTING SYSTEM
Activity Note:
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
18-Mar-16	891699	OUT OF SERVICE DISCONTINUED USE 892292 PIGTAIL, HEADLAMP, 9008	1	7.69	7.69
21-Mar-16	9008	BULB, HEADLAMP, HALOGEN, 12V	1	5.79	5.79

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
18-Mar-16	Simon,Fritz	0.4166666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 15 Sub Total</th></tr><tr><td>Parts:</td><td>13.48</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.42</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>13.48</td></tr></table>		Activity 15 Sub Total		Parts:	13.48	Labor:	0.00	Labor Hours:	0.42	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	13.48
Activity 15 Sub Total															
Parts:	13.48														
Labor:	0.00														
Labor Hours:	0.42														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	13.48														

Work Order Footer															
<table><tr><th colspan="2">Work Order 27008052 Total</th></tr><tr><td>Parts:</td><td>13.48</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.42</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>13.48</td></tr></table>		Work Order 27008052 Total		Parts:	13.48	Labor:	0.00	Labor Hours:	0.42	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	13.48
Work Order 27008052 Total															
Parts:	13.48														
Labor:	0.00														
Labor Hours:	0.42														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	13.48														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26885680
Invoice No. 55345 - 26885680

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 47,190 - DH

Chronology

Reported	Mar 16, 2016 3:09:45 PM	Mar 16, 2016 3:09:45 PM
Started	Mar 16, 2016 12:00:00 AM	
Completed	Mar 17, 2016 6:36:00 AM	Mar 17, 2016 6:36:00 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm A due

CAUSE: mil

CORRECTION: Replaced oil and oil filter

Parts used. 6 quarts oil. 5w-20. 1 oil filter B-329

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
17-Mar-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Capazzoli, Louis	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 16-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,633 - Tread Depth RRO	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,634 - Tread Depth RRI	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,635 - Tread Depth LRI	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,636 - Tread Depth LRO	8 32nds of an inch		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,131 - Brake Pad Thickness LF	Inch	9 mm	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,132 - Brake Pad Thickness RF	Inch	9 mm	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,133 - Brake Pad Thickness LR	Inch	10 mm	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,134 - Brake Pad Thickness RR	Inch	10 mm	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Mar 16, 2016 3:25:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26885680
Invoice No. 55345 - 26885680

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	47,190 - DH

Activity Header
Activity:20 999 TOTAL VEHICLE
Activity Note: PM A
Reason for Repair: 08 Preventive Maintenance
Work Accomplished: A PM Level A
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Capazzoli,Louis	0.5	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 16-MAR-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Mar 16, 2016 3:28:37 PM	No	

Activity Sub Total		Activity 20 Sub Total	
Parts:			0.00
Labor:			0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26885680
Invoice No. 55345 - 26885680

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	HPIERRE	Status:	40 - Closed (40)
Created By:	HPIERRE	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	47,190 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
16-Mar-16	Capazzoli,Louis	0.0833333	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
30 - Kilometers					No	
40 - Hours					No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 26885680 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.08
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26940431
Invoice No. 55345 - 26940431

Client Department:

Department: 55345M

Work Order Description

Front A/C only blowing out of defroster

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 45,650 - DH

Chronology

Reported	Mar 7, 2016 5:15:45 AM	Mar 7, 2016 5:15:45 AM
Started	Mar 7, 2016 12:00:00 AM	
Completed	Mar 7, 2016 8:15:00 AM	Mar 7, 2016 8:15:00 AM
Down Time		

Work Order Notes

Line 10

COMPLAINT:

Front A/C only blowing out of defroster

CAUSE:

Vacuum Reservoir and one way valve for front a/c vent system

CORRECTION: installed a new Vacuum Reservoir and one way valve for front a/c vent system

PARTS

YC2Z-19A566-AA qty 1 vacuum reservoir

D70Z-19A563-A qty 1 1 way suction valve

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 07-MAR-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Mar 7, 2016 5:26:28 AM	No	
20 - Miles			EDTORRES	Mar 7, 2016 5:26:28 AM	No	
30 - Kilometers			EDTORRES	Mar 7, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO	
				5:26:28 AM			
40 - Hours			EDTORRES	Mar 7, 2016 5:26:28 AM	No		
Activity Sub Total							
				Activity 5 Sub Total			
				Parts:			0.00
				Labor:			0.00
				Labor Hours:			0.00
				Sublet Parts:			0.00
				Sublet Labor:			0.00
				Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26940431
Invoice No. 55345 - 26940431

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Front A/C only blowing out of defroster		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	45,650 - DH

Activity Header
Activity: 15 001 AIR CONDITIONING, HEATING AND VENTILATION
Activity Note: Front A/C only blowing out of defroster
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
07-Mar-16	YC2Z-19A566-AA	RESERVOIR, VACUUM W/BRACKET	1	25.81	25.81
07-Mar-16	D7OZ-19A563-A	VALVE, SUCTION, A/C	1	4.9	4.9

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
07-Mar-16	Torres, Edwin	1.2666666	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	30.71
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	30.71

Work Order Footer	
Work Order 26940431 Total	
Parts:	30.71
Labor:	0.00
Labor Hours:	1.27
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	30.71



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26921315
Invoice No. 55345 - 26921315

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Check rear right end for noise		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	44,175 - DH

Chronology		
Reported	Feb 22, 2016 3:37:57 PM	Feb 22, 2016 3:37:57 PM
Started	Feb 22, 2016 12:00:00 AM	
Completed	Feb 24, 2016 7:29:00 AM	Feb 24, 2016 7:29:00 AM
Down Time		

Work Order Notes

Line 10
COMPLAINT: Right rear end noisy

CAUSE:Bent bracket

CORRECTION:Bracket fixed
Driver's complaint verified
Visual inspection performed
Rear bracket found rubbing against the drive shaft
Bracket fixed
Road test performed ok
Bus returned in service

No parts utilized

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair:		05 Inspection, Routine				
Work Accomplished:		06 Inspect				
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 22-FEB-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal	Done		FSIMON	Feb 22, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Risk Assessment?				4:14:12 PM		
20 - Miles			FSIMON	Feb 22, 2016 4:14:12 PM	No	
30 - Kilometers			FSIMON	Feb 22, 2016 4:14:12 PM	No	
40 - Hours			FSIMON	Feb 22, 2016 4:14:12 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26921315
Invoice No. 55345 - 26921315

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Check rear right end for noise		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	44,175 - DH

Activity Header				
Activity:15 014 FRAME				
Activity Note:				
Reason for Repair:		04 Driver's Report		
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
22-Feb-16	Simon,Fritz	0.5	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 26921315 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.50
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26742224
Invoice No. 55345 - 26742224

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 42,862 - DH

Chronology

Reported	Feb 10, 2016 2:14:50 PM	Feb 10, 2016 2:14:50 PM
Started	Feb 10, 2016 12:00:00 AM	
Completed	Feb 10, 2016 10:16:00 PM	Feb 10, 2016 10:16:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE:regular maintenance

CORRECTION: perform service, lube all pivoting point and rotate all tires completed

Parts #oil filter B329 qty1

Oil#5w20 qt6

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Feb-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Feb-16	Pierre,Hubert J	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 10-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	0 Pounds per Square Inch	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,162 - FRA Check/Record Water Temperature	0 Degree Fahrenheit	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,420 - Check Hood	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,633 - Tread Depth RRO	10 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,634 - Tread Depth RRI	10 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,635 - Tread Depth LRI	10 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,636 - Tread Depth LRO	10 32nds of an inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,135 - Brake Rotor LF	40 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,136 - Brake Rotor RF	40 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,137 - Brake Rotor LR	42 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,138 - Brake Rotor RR	42 Inch		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Feb 10, 2016 5:12:30 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Feb 10, 2016 5:12:30 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26742224
Invoice No. 55345 - 26742224

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 42,862 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Feb-16	Pierre,Hubert J	0.4166666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM A						
Task: PM A SERVICE Performed by: HPIERRE Performed on: 10-FEB-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Feb 10, 2016 5:13:14 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Feb 10, 2016 5:13:14 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Feb 10, 2016 5:13:14 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.42
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26742224
Invoice No. 55345 - 26742224

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: HPIERRE

Created By: HPIERRE

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 42,862 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
10-Feb-16	Pierre,Hubert J	0.0833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 10-FEB-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Feb 10, 2016 5:13:37 PM	No	
20 - Miles			HPIERRE	Feb 10, 2016 5:13:37 PM	No	
30 - Kilometers			HPIERRE	Feb 10, 2016 5:13:37 PM	No	
40 - Hours			HPIERRE	Feb 10, 2016 5:13:37 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer


Work Order 26742224 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26867189
Invoice No. 55345 - 26867189

Client Department:

Department: 55345M

Work Order Description

Driver complaint of lift issues

Requested By: RMANZINO

Created By: RMANZINO

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 41,047 - DH

Chronology

Reported	Jan 28, 2016 8:48:11 AM	Jan 28, 2016 8:48:11 AM
Started	Jan 28, 2016 12:00:00 AM	
Completed	Jan 28, 2016 10:11:00 AM	Jan 28, 2016 10:11:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: driver complaint of lift issues.

CAUSE: inspected lift and tested operation.

Could not replicate any issues.

CORRECTION: checked all adjustments of microswitches and all ok

Lubricated all moving parts for preventative maintenance.

Lift operates as intended and no issues could be replicated at this time.

Vehicle returned to service.

No parts used.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-16	Manzino, Robert C	0.1666666	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Check List						
Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 28-JAN-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Jan 28, 2016 9:02:15 AM	No	
20 - Miles			RMANZINO	Jan 28, 2016 9:02:15 AM	No	
30 - Kilometers			RMANZINO	Jan 28, 2016 9:02:15 AM	No	
40 - Hours			RMANZINO	Jan 28, 2016 9:02:15 AM	No	

Activity Sub Total	Activity 5 Sub Total
	Parts: 0.00
	Labor: 0.00
	Labor Hours: 0.17
	Sublet Parts: 0.00
	Sublet Labor: 0.00
	Activity Sub Total 0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26867189
Invoice No. 55345 - 26867189

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Driver complaint of lift issues		Ford E450 Champion Challenger	
Requested By:	RMANZINO	Status:	40 - Closed (40)
Created By:	RMANZINO	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	41,047 - DH

Activity Header				
Activity:15 999 TOTAL VEHICLE				
Activity Note: Driver complaint of lift issues				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
28-Jan-16	Manzino,Robert C	1	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.00
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 26867189 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	1.17
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26866675
Invoice No. 55345 - 26866675

Client Department:

Department: 55345M

Work Order Description

REPLACE BOTH FRONT HEADLIGHTS

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 41,047 - DH

Chronology

Reported	Jan 27, 2016 9:30:00 PM	Jan 27, 2016 9:30:00 PM
Started	Jan 27, 2016 12:00:00 AM	
Completed	Jan 27, 2016 11:20:00 PM	Jan 27, 2016 11:20:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: road called no light on the bus

CAUSE: both headlight out

CORRECTION: replaced both head light bulb completed

Parts #light bulb h13 qt 2

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-16	Pierre, Hubert J	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 27-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the	Done		HPIERRE	Jan 27, 2016	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
Personal Risk Assessment?				11:17:27 PM		
20 - Miles			HPIERRE	Jan 27, 2016 11:17:27 PM	No	
30 - Kilometers			HPIERRE	Jan 27, 2016 11:17:27 PM	No	
40 - Hours			HPIERRE	Jan 27, 2016 11:17:27 PM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.50
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26866675
Invoice No. 55345 - 26866675

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
REPLACE BOTH FRONT HEADLIGHTS		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	41,047 - DH

Activity Header
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER
Activity Note: REPLACE BOTH HEADLIGHT BULBS
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
28-Jan-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.41	7.41
05-Feb-16	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	7.41	7.41

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
27-Jan-16	Pierre, Hubert J	1.5	0	0

Activity Sublet
No Data Available


Activity Checklist
No Data Available
No Data Available

Activity Sub Total	
Activity 15 Sub Total	
Parts:	14.82
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	14.82

Work Order Footer	
Work Order 26866675 Total	
Parts:	14.82
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	14.82



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26634159
Invoice No. 55345 - 26634159

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 38,477 - DH

Chronology

Reported	Jan 6, 2016 2:52:29 PM	Jan 6, 2016 2:52:29 PM
Started	Jan 6, 2016 12:00:00 AM	
Completed	Jan 6, 2016 3:51:00 PM	Jan 6, 2016 3:51:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pm b

CAUSE: regular maintenance

CORRECTION: perform service lube all pivoting point cross rotate front tires completed

Parts # oil filter b329 qty 1

Oil #5w20 qt 6

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-16	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-16	Pierre, Hubert J	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: HPIERRE Performed on: 06-JAN-16

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,100 - Safety Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,140 - Check Service Brakes	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,160 - FRA Check Instruments and Horns	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,170 - Check Fast Idle	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,180 - Check Starter Protection Circuit	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
10,190 - Check Reverse Warning System	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,100 - Check Parking Brake	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,150 - Perform Brake Test	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,170 - FRA Check Door Operation	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,210 - Check Condition of Operator's Area	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,240 - FRA Check Interior Lights	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,260 - Check Stop Request System	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
22,110 - Check Emergency Hatches	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
22,120 - Check All Safety Equipment	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,310 - Check Passenger Doors	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,360 - Check for Physical Damage and Decals	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,380 - Check Exterior Compartment Doors	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
33,100 - Check Lights and Reflectors	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,420 - Check Hood	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,130 - FRA Check Exhaust System	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,140 - FRA Check Intake System	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,150 - FRA Inspect Turbocharger	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,180 - FRA Check for Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,190 - FRA Perform Battery Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
50,510 - Check Entire Steering System	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,630 - Check and Record Tread Depth	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,631 - Tread Depth RF	8 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,632 - Tread Depth LF	8 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,633 - Tread Depth RRO	12 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,634 - Tread Depth RRI	12 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,635 - Tread Depth LRI	12 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,636 - Tread Depth LRO	12 32nds of an inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,650 - Check Sidewall Wear	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,660 - Inspect for Cuts and Tears	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,670 - Check Dual Mating With Square	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,710 - Check Vibration Damper	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,730 - FRA Check Starter	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,770 - FRA Check Exhaust System	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,120 - Check Suspension Components	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,133 - Brake Pad Thickness LR	11 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,134 - Brake Pad Thickness RR	11 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,135 - Brake Rotor LF	36 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,136 - Brake Rotor RF	36 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,137 - Brake Rotor LR	44 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,138 - Brake Rotor RR	44 Inch		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,140 - FRA Check Brake Hoses	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,150 - Check King Pins	-	N/A	HPIERRE	Jan 6, 2016 3:21:24 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
80,810 - Completion of PMI Report	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		HPIERRE	Jan 6, 2016 3:21:24 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26634159
Invoice No. 55345 - 26634159

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 38,477 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM B

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-16	Pierre, Hubert J	0.45	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List						
20 Desc: PM B						
Task: PM B SERVICE Performed by: HPIERRE Performed on: 06-JAN-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
101,000 - FRA Change Oil Filters	Yes		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
102,000 - FRA Drain Engine Oil	Yes		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
103,000 - FRA Check Transmission Fluid	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
104,000 - Lubricate Chassis	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
105,000 - Replace or Clean A/C Filters	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	N/A	HPIERRE	Jan 6, 2016 3:22:17 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
201,000 - Service Crankcase Breather	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		HPIERRE	Jan 6, 2016 3:22:17 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		HPIERRE	Jan 6, 2016 3:22:17 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.45
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26634159
Invoice No. 55345 - 26634159

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	RGASPARD	Status:	40 - Closed (40)
Created By:	RGASPARD	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	38,477 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Jan-16	Pierre,Hubert J	0.05	0	0

Activity Sublet
No Data Available

Activity Checklist						
Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 06-JAN-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Jan 6, 2016 3:22:42 PM	No	
20 - Miles			HPIERRE	Jan 6, 2016 3:22:42 PM	No	
30 - Kilometers			HPIERRE	Jan 6, 2016 3:22:42 PM	No	
40 - Hours			HPIERRE	Jan 6, 2016 3:22:42 PM	No	

Activity Sub Total	
Activity 30 Sub Total	
Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer	
Work Order 26634159 Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	2.50

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26741588
Invoice No. 55345 - 26741588

Client Department:

Department: 55345M

Work Order Description

GEAR BOX LEAK

Requested By: CVERGARA

Created By: CVERGARA

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: Yes

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 38,379 - DH

Chronology

Reported	Jan 6, 2016 9:22:00 AM	Jan 6, 2016 9:22:00 AM
Started		
Completed	Jan 6, 2016 1:24:00 PM	Jan 6, 2016 1:24:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: P/Steering gear box leaking fluid

CAUSE:Normal wear

CORRECTION:Power steering gear box replacement

Power steering system visually inspected

Complaint verified

Power steering gear box replaced

Power steering fluid added to the system

P/S System bled

Test drive performed ok

Part utilized:

One (1) power steering gear box #AC2Z3504 A (under warranty)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 06-JAN-16						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Jan 6, 2016 10:19:31 AM	No	
20 - Miles			FSIMON	Jan 6, 2016 10:19:31 AM	No	
30 - Kilometers			FSIMON	Jan 6, 2016 10:19:31 AM	No	
40 - Hours			FSIMON	Jan 6, 2016 10:19:31 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts: 0.00			
			Labor: 0.00			
			Labor Hours: 0.00			
			Sublet Parts: 0.00			
			Sublet Labor: 0.00			
			Activity Sub Total 0.00			



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26741588
Invoice No. 55345 - 26741588

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
GEAR BOX LEAK		Ford E450 Champion Challenger	
Requested By:	CVERGARA	Status:	40 - Closed (40)
Created By:	CVERGARA	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	Yes	Meter:	38,379 - DH

Activity Header

Activity:15 015/003/001 HOUSING, GEAR, STEERING, RACK & PINION

Activity Note: p/s gear box leaking fluid

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 03 Replace New

Part Failure: 18 Leaking

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
06-Jan-16	AC2Z-3504-A	BOX, GEAR, STEERING, E450, '08-'10 REPLACED BY GU2Z-3504-A	1	469.28	469.28

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	469.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	469.28

Work Order Footer

Work Order 26741588 Total

Parts:	469.28
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	469.28



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26709430
Invoice No. 55345 - 26709430

Client Department:

Department: 55345M

Work Order Description

L Headlight/ both marker lights

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 36,742 - DH

Chronology

Reported	Dec 15, 2015 10:37:38 AM	Dec 15, 2015 10:37:38 AM
Started	Dec 15, 2015 12:00:00 AM	
Completed	Dec 15, 2015 12:07:00 PM	Dec 15, 2015 12:07:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:

L headlight and bad marker lights.

CORRECTION:

Replaced L headlight and both marker lights.

Parts qty 1 H13 headlight

Qty 2 #168 marker lights.

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: EDITORRES Performed on: 15-DEC-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDITORRES	Dec 15, 2015 10:51:05 AM	No	
20 - Miles			EDITORRES	Dec 15, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				10:51:05 AM		
30 - Kilometers			EDITORRES	Dec 15, 2015 10:51:05 AM	No	
40 - Hours			EDITORRES	Dec 15, 2015 10:51:05 AM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:		0.00
				Labor:		0.00
				Labor Hours:		0.00
				Sublet Parts:		0.00
				Sublet Labor:		0.00
				Activity Sub Total		0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26709430
Invoice No. 55345 - 26709430

Client Department:

Department: 55345M

Work Order Description

L Headlight/ both marker lights

Requested By: EDITORRES

Created By: EDITORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 36,742 - DH

Activity Header

Activity: 15 034/001/000 HEADLAMP

Activity Note: Left headlight/book with the lights

Reason for Repair: 39 Natural Causes

Work Accomplished: 03 Replace New

Part Failure: 02 Burned, Scorched, Melted, Blistered

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
15-Dec-15	H13	BULB, CAPSULE, HEADLAMP, HALOGEN	1	4.11	4.11
22-Dec-15	168	BULB, WEDGE, 12V/3CP	-1	0.23	-0.23
15-Dec-15	168	BULB, WEDGE, 12V/3CP	2	0.23	0.46

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Dec-15	Torres,Edwin	0.5666666	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 15 Sub Total

Parts:	4.11
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	4.11

Work Order Footer

Work Order 26709430 Total

Parts:	4.11
Labor:	0.00
Labor Hours:	0.57
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	4.11



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26551546
Invoice No. 55345 - 26551546

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 34,233 - DH

Chronology

Reported	Nov 24, 2015 3:56:05 PM	Nov 24, 2015 3:56:05 PM
Started	Nov 24, 2015 12:00:00 AM	
Completed	Nov 24, 2015 11:09:00 PM	Nov 24, 2015 11:09:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: pmA

CAUSE: service

CORRECTION: perform pmA service

Engine oil 5w20 qty6qts

Oil filter B329 qty1

Activity Header

Activity:10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
25-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Nov-15	Gaspard, Ronald	1.8833333	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 24-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,420 - Check Hood	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,630 - Check and Record Tread Depth	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,631 - Tread Depth RF	9 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,632 - Tread Depth LF	9 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,633 - Tread Depth RRO	13 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,634 - Tread Depth RRI	13 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,635 - Tread Depth LRI	13 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,636 - Tread Depth LRO	13 32nds of an inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,120 - Check Suspension Components	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,131 - Brake Pad Thickness LF	9 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,132 - Brake Pad Thickness RF	9 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,133 - Brake Pad Thickness LR	10 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,134 - Brake Pad Thickness RR	10 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,137 - Brake Rotor LR	34 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,138 - Brake Rotor RR	34 Inch		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Nov 24, 2015 11:04:15 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Nov 24, 2015 11:04:15 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.92
Labor:	0.00
Labor Hours:	1.88
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.92

Activity 20 Sub Total	
Parts:	0.00
Labor:	0.00

	Labor Hours:	0.72
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26551546
Invoice No. 55345 - 26551546

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 34,233 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
24-Nov-15	Gaspard,Ronald	0.05	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 24-NOV-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Nov 24, 2015 11:06:55 PM	No	
20 - Miles			RGASPARD	Nov 24, 2015 11:06:55 PM	No	
30 - Kilometers			RGASPARD	Nov 24, 2015 11:06:55 PM	No	
40 - Hours			RGASPARD	Nov 24, 2015 11:06:55 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.05
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 26551546 Total

Parts:	1.92
Labor:	0.00
Labor Hours:	2.65

	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.92



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26573140
Invoice No. 55345 - 26573140

Client Department:

Department: 55345M

Work Order Description

W/C lift repair

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 31,949 - DH

Chronology

Reported	Nov 5, 2015 10:45:13 AM	Nov 5, 2015 10:45:13 AM
Started	Nov 5, 2015 10:53:00 AM	
Completed	Nov 6, 2015 1:38:00 PM	Nov 6, 2015 1:38:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:W/C lift not working properly

CAUSE:Defective Inboard micro-switch

CORRECTION. Inboard micro-switch

W/C lift diagnosed

Driver's complaint verified

W/C lift tested

Inboard micro-switch found defective

No parts utilized

NB:W/C lift is under warranty,this vehicle needs to be sent to the vendor for lift repair.

Line 20 Installed new bridge plate up switch.

Tested and issue now resolved.

Part supplied by creative bus sales under warranty.

32519ks (1) qty - bridge plate up switch (no parts issued, covered by warranty)

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 05-NOV-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Nov 5, 2015 10:53:44 AM	No	
20 - Miles			FSIMON	Nov 5, 2015 10:53:44 AM	No	
30 - Kilometers			FSIMON	Nov 5, 2015 10:53:44 AM	No	
40 - Hours			FSIMON	Nov 5, 2015 10:53:44 AM	No	
Activity Sub Total						
				Activity 5 Sub Total		
				Parts:	0.00	
				Labor:	0.00	
				Labor Hours:	0.00	
				Sublet Parts:	0.00	
				Sublet Labor:	0.00	
				Activity Sub Total	0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26573140
Invoice No. 55345 - 26573140

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
W/C lift repair		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	31,949 - DH

Activity Header
Activity: 15 055 HANDLING, CARGO RESTRAINT & LIFT SYSTEM (POWER UNITS, TRAILERS)
Activity Note: Install new bridgeplate up switch
Reason for Repair: 04 Driver's Report
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
06-Nov-15	Manzino,Robert C	0.5	0	0
05-Nov-15	Simon,Fritz	0.9	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total		Activity 15 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.40
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 26573140 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	1.40
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26551508
Invoice No. 55345 - 26551508

Client Department:

Department: 55345M

Work Order Description

FTLM PMI_FOLLOWUP

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Chronology

Reported	Oct 20, 2015 2:24:40 PM	Oct 20, 2015 2:24:40 PM
Started	Oct 20, 2015 12:00:00 AM	
Completed	Oct 20, 2015 6:38:00 PM	Oct 20, 2015 6:38:00 PM
Down Time		

Work Order Notes

Line 10 Replaced all rear tires. Torque 140 ft pounds rd test torque 2 nd time

Parts used. Qty. 4 rear tires. Bridgestone. 192659

Activity Header

Activity: 10 017 TIRES, TUBES, LINERS & VALVES

Activity Note: needs all rear tires

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Oct-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	4	130.29	521.16
09-Dec-15	192659	TIRE, LT225/75R16, R500 HD, BSW, E/10PR, DURAVIS, BRIDGESTONE	-3	116.94	-350.82

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-15	Capazzoli, Louis	1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	170.34
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	170.34



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26551508
Invoice No. 55345 - 26551508


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
FTLMPMI_FOLLOWUP		Ford E450 Champion Challenger	
Requested By:	LCAPAZZOLI	Status:	40 - Closed (40)
Created By:	LCAPAZZOLI	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	29,962 - DH

Activity Header															
Activity:20 017 TIRES, TUBES, LINERS & VALVES															
Activity Note:															
Reason for Repair:	08 Preventive Maintenance														
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 20 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 20 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 20 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 26551508 Total</td></tr><tr><td>Parts:</td><td>170.34</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>170.34</td></tr></table>		Work Order 26551508 Total		Parts:	170.34	Labor:	0.00	Labor Hours:	1.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	170.34
Work Order 26551508 Total															
Parts:	170.34														
Labor:	0.00														
Labor Hours:	1.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	170.34														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 26551513
Invoice No. 55345 - 26551513

Client Department:

Department: 55345M

Work Order Description

FTLMPMI_FOLLOWUP

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Chronology

Reported	Oct 20, 2015 2:26:22 PM	Oct 20, 2015 2:26:22 PM
Started	Oct 20, 2015 12:00:00 AM	
Completed	Oct 20, 2015 6:31:00 PM	Oct 20, 2015 6:31:00 PM
Down Time		

Work Order Notes

Line 10 Replaced front brakes. Torque tires 140 ft pounds. Rd test. Torque 2 nd time

Parts used. Front brake pads. Qty 1. Brsd1328

Activity Header

Activity: 10 013/001 BRAKES & DRUMS, FRONT

Activity Note: needs front brakes

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Oct-15	BRSD-1328	PADS, BRAKE, DISC, FRONT	1	50.32	50.32

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-15	Capazzoli,Louis	1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	50.32

Work Order Footer


Work Order 26551513 Total

Parts:	50.32
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	50.32



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 26551514
Invoice No. 55345 - 26551514

Client Department:

Department: 55345M

Work Order Description

FTLMPMI_FOLLOWUP

Requested By: LCAPAZZOLI

Created By: LCAPAZZOLI

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Chronology

Reported	Oct 20, 2015 2:27:20 PM	Oct 20, 2015 2:27:20 PM
Started	Oct 20, 2015 3:00:00 PM	
Completed	Oct 20, 2015 6:21:00 PM	Oct 20, 2015 6:21:00 PM
Down Time		

Work Order Notes

Line 10 Completed rear brakes. Torque rear tires 140 ft pounds. Rd test torque 2 nd time

Parts used. rear brake pads. Brsd-1330

Activity Header

Activity: 10 013/002 REAR BRAKES & DRUMS

Activity Note: needs rear brakes

Reason for Repair: 08 Preventive Maintenance

Work Accomplished:

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
21-Oct-15	BRSD-1330	PADS, BRAKE, DISC, REAR, FORD SAME AS PFH133020	1	43.15	43.15

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-15	Capazzoli,Louis	1	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	43.15
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	43.15

Work Order Footer

Work Order 26551514 Total

Parts:	43.15
Labor:	0.00
Labor Hours:	1.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	43.15



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26470743
Invoice No. 55345 - 26470743

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Chronology

Reported	Oct 20, 2015 12:53:48 PM	Oct 20, 2015 12:53:48 PM
Started	Oct 20, 2015 12:00:00 AM	
Completed	Oct 20, 2015 2:52:00 PM	Oct 20, 2015 2:52:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT: perform. Pm. A.

CAUSE:

CORRECTION: replace oil and filter change

Parts used. 6 quarts oil. 5w-20. 1 oil filter b-329

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
20-Oct-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.82	1.82
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	-1	1.84	-1.84
17-Nov-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.92	1.92

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-15	Capazzoli, Louis	2	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: LCAPAZZOLI Performed on: 20-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,100 - Safety Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,140 - Check Service Brakes	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,160 - FRA Check Instruments and Horns	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,170 - Check Fast Idle	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,180 - Check Starter Protection Circuit	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
10,190 - Check Reverse Warning System	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,100 - Check Parking Brake	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,150 - Perform Brake Test	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,170 - FRA Check Door Operation	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,210 - Check Condition of Operator's Area	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,240 - FRA Check Interior Lights	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,260 - Check Stop Request System	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
22,110 - Check Emergency Hatches	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
22,120 - Check All Safety Equipment	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,310 - Check Passenger Doors	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,360 - Check for Physical Damage and Decals	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,380 - Check Exterior Compartment Doors	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
33,100 - Check Lights and Reflectors	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,420 - Check Hood	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,461 - Refractometer Reading	Degree Fahrenheit	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,130 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,140 - FRA Check Intake System	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,150 - FRA Inspect Turbocharger	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,180 - FRA Check for Leaks	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,190 - FRA Perform Battery Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
50,510 - Check Entire Steering System	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,620 - Check Valve Stems and Caps	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,630 - Check and Record Tread Depth	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,631 - Tread Depth RF	12 32nds of an inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,632 - Tread Depth LF	12 32nds of an inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,634 - Tread Depth RRI	3 32nds of an inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,635 - Tread Depth LRI	3 32nds of an inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch	needs all rear tires	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	Yes	26551508
60,640 - Check for Mismatched Tread or Casing Design	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,650 - Check Sidewall Wear	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,660 - Inspect for Cuts and Tears	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,670 - Check Dual Mating With Square	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,710 - Check Vibration Damper	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,730 - FRA Check Starter	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,770 - FRA Check Exhaust System	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,110 - FRA Check Fuel Tank	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,120 - Check Suspension Components	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,131 - Brake Pad Thickness LF	4 Inch	needs front brakes	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	Yes	26551513
77,132 - Brake Pad Thickness RF	4 Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,133 - Brake Pad Thickness LR	4 Inch	needs rear brakes	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	Yes	26551514
77,134 - Brake Pad Thickness RR	4 Inch		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,135 - Brake Rotor LF	Inch	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,136 - Brake Rotor RF	Inch	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,137 - Brake Rotor LR	Inch	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,138 - Brake Rotor RR	Inch	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,140 - FRA Check Brake Hoses	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,150 - Check King Pins	-	n/a	LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
80,810 - Completion of PMI Report	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		LCAPAZZOLI	Oct 20, 2015 2:51:50 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.90
Labor:	0.00
Labor Hours:	2.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26470743
Invoice No. 55345 - 26470743

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
20-Oct-15	Capazzoli, Louis	0.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM A

Task: PM A SERVICE Performed by: LCAPAZZOLI Performed on: 20-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
101,000 - FRA Change Oil Filters	Yes		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
102,000 - FRA Drain Engine Oil	Yes		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
103,000 - FRA Check Transmission Fluid	Done		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
104,000 - Lubricate Chassis	Done		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
105,000 - Replace or Clean A/C Filters	Done		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
107,000 - FRA Change Primary Fuel Filter	No	n/a	LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		LCAPAZZOLI	Oct 20, 2015 2:34:20 PM	No	

Activity Sub Total


Activity 20 Sub Total

Parts:	0.00
Labor:	0.00

	Labor Hours:	0.50
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26470743
Invoice No. 55345 - 26470743

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: RGASPARD

Created By: RGASPARD

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 29,962 - DH

Activity Header

Activity: 30 999 TOTAL VEHICLE

Activity Note: PRAMETER

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

30 Desc: PRAMETER

Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 20-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Oct 20, 2015 2:35:12 PM	No	
20 - Miles			LCAPAZZOLI	Oct 20, 2015 2:35:12 PM	No	
30 - Kilometers			LCAPAZZOLI	Oct 20, 2015 2:35:12 PM	No	
40 - Hours			LCAPAZZOLI	Oct 20, 2015 2:35:12 PM	No	

Activity Sub Total

Activity 30 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00

Work Order Footer

Work Order 26470743 Total

Parts:	1.90
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00

	Activity Sub Total	1.90



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 26538790
Invoice No. 55345 - 26538790

Client Department:

Department: 55345M

Work Order Description

Check wheel chair lift

Requested By: RMANZINO

Created By: RMANZINO

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 28,680 - DH

Chronology

Reported	Oct 9, 2015 2:18:07 PM	Oct 9, 2015 2:18:07 PM
Started	Oct 12, 2015 12:00:00 AM	
Completed	Oct 12, 2015 7:01:00 AM	Oct 12, 2015 7:01:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: driver complaint of wheel chair lift not working.

CAUSE: could not replicate issue but did lubricate all moving points, adjusted and checked all safety mechanisms.

CORRECTION: all ok at this time. Line 20 No parts used

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
12-Oct-15	Manzino,Robert C	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment


Task: PRA and Meter Readings Performed by: RMANZINO Performed on: 12-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RMANZINO	Oct 12, 2015 7:01:14 AM	No	
20 - Miles			RMANZINO	Oct 12, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				7:01:14 AM		
30 - Kilometers			RMANZINO	Oct 12, 2015 7:01:14 AM	No	
40 - Hours			RMANZINO	Oct 12, 2015 7:01:14 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			1.50
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00
Work Order Footer						
			Work Order 26538790 Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			1.50
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26517398
Invoice No. 55345 - 26517398

Client Department:

Department: 55345M

Work Order Description

Wheelchair lift check

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 2 - Medium

Driver:

Phone:

ETA:

Meter: 27,659 - DH

Chronology

Reported	Oct 2, 2015 11:35:13 AM	Oct 2, 2015 11:35:13 AM
Started		
Completed	Oct 2, 2015 11:54:00 AM	Oct 2, 2015 11:54:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:Wheelchair lift not going down.

CAUSE:

CORRECTION:lubrication of the wheelchair lift mechanism

Driver complaint verified

Wheelchair lift inspected visually.

All lift chair pivoting mechanisms lubricated

Lift chair working ok

No new part used

Activity Header

Activity:5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: FSIMON Performed on: 02-OCT-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Oct 2, 2015 11:41:01 AM	No	
20 - Miles			FSIMON	Oct 2, 2015 11:41:01 AM	No	
30 - Kilometers			FSIMON	Oct 2, 2015 11:41:01 AM	No	
40 - Hours			FSIMON	Oct 2, 2015 11:41:01 AM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.00
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26517398
Invoice No. 55345 - 26517398


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Wheelchair lift check		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	2 - Medium
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	27,659 - DH

Activity Header															
Activity:15 050 GROUP, ACCESSORIES															
Activity Note:															
Reason for Repair: 04 Driver's Report															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 26517398 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 26517398 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 26517398 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26257123
Invoice No. 55345 - 26257123

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 25,588 - DH

Chronology

Reported	Sep 15, 2015 3:42:56 PM	Sep 15, 2015 3:42:56 PM
Started	Sep 15, 2015 8:30:00 PM	
Completed	Sep 15, 2015 11:48:00 PM	Sep 15, 2015 11:48:00 PM
Down Time		

Work Order Notes

Line 10 Oil filter B329 qty 1

Engine oil 5w20 6 qts

Test drive torque tires 140lbs

Second torque 140lbs

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: Light Medium Duty PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
16-Sep-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.52	1.52

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-15	Gaspard,Ronald	3.08	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: Light Medium Duty PMI

Task: First Transit Light-Medium Duty PMI Performed by: RGASPARD Performed on: 15-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,100 - Safety Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,120 - FRA Check All Warning Lights and Alarms	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,140 - Check Service Brakes	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,160 - FRA Check Instruments and Horns	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,170 - Check Fast Idle	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,180 - Check Starter Protection Circuit	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
10,190 - Check Reverse Warning System	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,100 - Check Parking Brake	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,150 - Perform Brake Test	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	Pounds per Square Inch	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,162 - FRA Check/Record Water Temperature	Degree Fahrenheit	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,170 - FRA Check Door Operation	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,210 - Check Condition of Operator's Area	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,240 - FRA Check Interior Lights	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,250 - FRA Check Interior Electrical Panels	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,260 - Check Stop Request System	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
22,110 - Check Emergency Hatches	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
22,120 - Check All Safety Equipment	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,310 - Check Passenger Doors	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,340 - FRA Check Destination Sign and Run Box	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,360 - Check for Physical Damage and Decals	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,380 - Check Exterior Compartment Doors	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
33,100 - Check Lights and Reflectors	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,420 - Check Hood	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	No	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,442 - Freeze Point	Degree Fahrenheit	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,461 - Refractometer Reading	Degree Fahrenheit	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,130 - FRA Check Exhaust System	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,140 - FRA Check Intake System	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,150 - FRA Inspect Turbocharger	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,180 - FRA Check for Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,190 - FRA Perform Battery Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
50,510 - Check Entire Steering System	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,615 - Air Pressure LRI	70 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,620 - Check Valve Stems and Caps	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,630 - Check and Record Tread Depth	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,631 - Tread Depth RF	11 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,632 - Tread Depth LF	11 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,633 - Tread Depth RRO	5 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,634 - Tread Depth RRI	5 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,635 - Tread Depth LRI	4 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,636 - Tread Depth LRO	5 32nds of an inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,640 - Check for Mismatched Tread or Casing Design	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,650 - Check Sidewall Wear	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,660 - Inspect for Cuts and Tears	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,670 - Check Dual Mating With Square	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,710 - Check Vibration Damper	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,730 - FRA Check Starter	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,770 - FRA Check Exhaust System	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
70,790 - Check All Body Mounts and Chassis Frame	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,110 - FRA Check Fuel Tank	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	


Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
77,120 - Check Suspension Components	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,131 - Brake Pad Thickness LF	10 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,132 - Brake Pad Thickness RF	10 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,133 - Brake Pad Thickness LR	7 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,134 - Brake Pad Thickness RR	7 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,135 - Brake Rotor LF	38 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,136 - Brake Rotor RF	38 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,137 - Brake Rotor LR	30 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,138 - Brake Rotor RR	30 Inch		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,140 - FRA Check Brake Hoses	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,150 - Check King Pins	-	na	RGASPARD	Sep 15, 2015 11:35:12 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
80,810 - Completion of PMI Report	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		RGASPARD	Sep 15, 2015 11:35:12 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.52
Labor:	0.00
Labor Hours:	3.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.52



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26257123
Invoice No. 55345 - 26257123

Client Department:

Department: 55345M

Work Order Description

PM C

Requested By: FSIMON

Created By: FSIMON

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 25,588 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PMC

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: C PM Level C

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
15-Sep-15	Gaspard,Ronald	0.08	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PMC

Task: PM C SERVICE Performed by: RGASPARD Performed on: 15-SEP-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
101,000 - FRA Change Oil Filters	Yes		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
102,000 - FRA Drain Engine Oil	Yes		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
103,000 - FRA Check Transmission Fluid	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
104,000 - Lubricate Chassis	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
105,000 - Replace or Clean A/C Filters	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
107,000 - FRA Change Primary Fuel Filter	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
200,000 - "B" PMI SERVICING ITEMS (12 MONTH)	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
201,000 - Service Crankcase Breather	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
203,000 - FRA Change Automatic Transmission Fluid	No		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
204,000 - FRA Change Power Steering Fluid and Filter	No		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
205,000 - Complete Engine Diagnostics and Clear Codes when Completed	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
300,000 - "C" PMI SERVICING ITEMS (24 MONTH)	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
301,000 - Check and Lubricate Door Linkages	Done		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
302,000 - Check Toe-In and Record Reading	-	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
302,001 - Record Toe-In Reading	Inches, fraction-actual	na	RGASPARD	Sep 15, 2015 11:38:33 PM	No	
304,000 - 1st "C" PMI ONLY: Tune Up Per Engine Mfg's Specifications	No		RGASPARD	Sep 15, 2015 11:38:33 PM	No	
305,000 - FRA Change Differential Fluid	No		RGASPARD	Sep 15, 2015 11:38:33 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.08
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26257123
Invoice No. 55345 - 26257123

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM C		Ford E450 Champion Challenger	
Requested By:	FSIMON	Status:	40 - Closed (40)
Created By:	FSIMON	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	25,588 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: RGASPARD Performed on: 15-SEP-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		RGASPARD	Sep 15, 2015 11:43:21 PM	No	
20 - Miles			RGASPARD	Sep 15, 2015 11:43:21 PM	No	
30 - Kilometers			RGASPARD	Sep 15, 2015 11:43:21 PM	No	
40 - Hours			RGASPARD	Sep 15, 2015 11:43:21 PM	No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 26257123 Total	
		Parts:	1.52
		Labor:	0.00
		Labor Hours:	3.16
		Sublet Parts:	0.00
		Sublet Labor:	0.00

	Activity Sub Total	1.52



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26468674
Invoice No. 55345 - 26468674

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Install driver side step rail		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	25,588 - DH

Chronology		
Reported	Sep 15, 2015 8:37:37 PM	Sep 15, 2015 8:37:37 PM
Started	Sep 15, 2015 9:32:00 PM	
Completed	Sep 15, 2015 11:02:00 PM	Sep 15, 2015 11:02:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:

CAUSE:

CORRECTION: Line 20 Install driver side step rail completed

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
Booked Date	Technician	Hours	Shop Rate	Extended		
15-Sep-15	Pierre,Hubert J	1.43	0	0		
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: HPIERRE Performed on: 15-SEP-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		HPIERRE	Sep 15, 2015 11:01:42 PM	No	
20 - Miles			HPIERRE	Sep 15, 2015	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
				11:01:42 PM		
30 - Kilometers			HPIERRE	Sep 15, 2015 11:01:42 PM	No	
40 - Hours			HPIERRE	Sep 15, 2015 11:01:42 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			1.43
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26468674
Invoice No. 55345 - 26468674

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Install driver side step rail		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	25,588 - DH

Activity Header															
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER															
Activity Note: Install driver side step rail															
Reason for Repair: 38 Warranty															
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 26468674 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.43</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 26468674 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	1.43	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 26468674 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	1.43														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26293944
Invoice No. 55345 - 26293944

Client Department:

Department: 55345M

Work Order Description

Driver states that the wheel chair bag is broken

Requested By: AOWENS

Created By: AOWENS

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 23,719 - DH

Chronology

Reported	Aug 31, 2015 5:16:29 PM	Aug 31, 2015 5:16:29 PM
Started	Aug 31, 2015 7:31:00 PM	
Completed	Aug 31, 2015 7:40:00 PM	Aug 31, 2015 7:40:00 PM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:

CAUSE:

CORRECTION: Install wheel chair bag
Part under warranty

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-15	Capazzoli, Louis	0.02	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: LCAPAZZOLI Performed on: 31-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		LCAPAZZOLI	Aug 31, 2015 7:40:29 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20 - Miles			LCAPAZZOLI	Aug 31, 2015 7:40:29 PM	No	
Activity Sub Total						
			Activity 5 Sub Total			
			Parts:			0.00
			Labor:			0.00
			Labor Hours:			0.02
			Sublet Parts:			0.00
			Sublet Labor:			0.00
			Activity Sub Total			0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26293944
Invoice No. 55345 - 26293944

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Driver states that the wheel chair bag is broken		Ford E450 Champion Challenger	
Requested By:	AOWENS	Status:	40 - Closed (40)
Created By:	AOWENS	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	23,719 - DH

Activity Header				
Activity: 15 079 DEVICES, SAFETY/STABILITY, TRAILER				
Activity Note: Driver States that the wheel chair bag is broken				
Reason for Repair: 04 Driver's Report				
Work Accomplished:				
Part Failure:				
Activity Comments:				
Activity Parts				
No Data Available				
Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
31-Aug-15	Capazzoli,Louis	0.6	0	0
Activity Sublet				
No Data Available				
Activity Checklist				
No Data Available				
No Data Available				
Activity Sub Total				
			Activity 15 Sub Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.60
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00
Work Order Footer				
			Work Order 26293944 Total	
			Parts:	0.00
			Labor:	0.00
			Labor Hours:	0.62
			Sublet Parts:	0.00
			Sublet Labor:	0.00
			Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 26099196
Invoice No. 55345 - 26099196

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 21,134 - DH

Chronology

Reported	Aug 11, 2015 12:00:00 AM	Aug 11, 2015 12:00:00 AM
Started	Aug 11, 2015 11:36:00 AM	
Completed	Aug 11, 2015 3:23:00 PM	Aug 11, 2015 3:23:00 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

PMA performed

Engine oil filter changed

Qt.(1) #B329

Engine oil changed

Qt 6qts.#5W20

Two tires changed by used tires

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: LIGHT MEDIUM DUTY PMI

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
11-Aug-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.26	1.26

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
11-Aug-15	Simon,Fritz	2.62	0	0

Activity Sublet

No Data Available

Activity Checklist

Check List

10 Desc: LIGHT MEDIUM DUTY PMI

Task: First Transit Light-Medium Duty PMI Performed by: FSIMON Performed on: 11-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10,000 - SECTION 1 Preparation and Drive On (In Lot) Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,100 - Safety Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,110 - FRA Check Drivers Pre-trip or DVIR/EVIR & Authorization Forms	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,120 - FRA Check All Warning Lights and Alarms	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,130 - FRA Check Automatic Transmission Neutral Start Operation	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,140 - Check Service Brakes	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,150 - FRA Start Engine and Listen for Any Unusual Noises	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,160 - FRA Check Instruments and Horns	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,170 - Check Fast Idle	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,180 - Check Starter Protection Circuit	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
10,190 - Check Reverse Warning System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,100 - Check Parking Brake	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,110 - Check HVAC Switches and Other Controls	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,120 - FRA Inspect Windshields, Mirror and Sun Visor Condition	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,130 - FRA Check Wiper and Washer Operation	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,140 - Road Test: Check for Proper Operation	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,150 - Perform Brake Test	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,161 - FRA Check/Record Oil Pressure / @1500 rpm	40 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	Yes	
11,162 - FRA Check/Record Water Temperature	189 Degree Fahrenheit		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,170 - FRA Check Door Operation	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
11,180 - FRA Check Operation of All Other Accessories	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,000 - SECTION 2 Interior Circle Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,210 - Check Condition of Operator's Area	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,220 - Check Accelerator and Brake Pedals	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,230 - FRA Check Wiring Under Dash	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,240 - FRA Check Interior Lights	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
20,250 - FRA Check Interior Electrical Panels	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,260 - Check Stop Request System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,270 - Check Fare Box Mounting (If Applicable)	Done	n/a	FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,280 - Check Seats, Seat Belts, Hand Rails and Floor Covering	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
20,290 - Check for Physical Damage, Water Leaks, and Graffiti	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
22,100 - Check Emergency Windows and Glass Condition	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
22,110 - Check Emergency Hatches	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
22,120 - Check All Safety Equipment	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,000 - SECTION 3 Exterior Circle Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,310 - Check Passenger Doors	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,320 - Inspect Step-well and Hand Rails	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,330 - Check Wheelchair Lift Operation	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,340 - FRA Check Destination Sign and Run Box	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,350 - FRA Inspect Mirror and Mountings	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,360 - Check for Physical Damage and Decals	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,370 - Check Wiper Blade and Arm Condition	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,380 - Check Exterior Compartment Doors	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
30,390 - FRA Check Fuel Tank Cap	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
33,100 - Check Lights and Reflectors	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
33,110 - Check License Plate, Permits and State Inspection Decals	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,000 - SECTION 4 Engine Compartment Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,410 - FRA Check Engine Compartment/Condition for Fire Risk	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,420 - Check Hood	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,430 - Check Fan, Shroud and Radiator	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,440 - Test Coolant System Using Test Strips and Record Results	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,441 - Inhibitor Test Pass or Fail (Indicate with a Yes or No)	Yes		FSIMON	Aug 11, 2015 2:12:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
40,442 - Freeze Point	-40 Degree Fahrenheit		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,450 - FRA Check Coolant Recovery System Condition & for Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,460 - Record Antifreeze Protection Level Using Refractometer	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,461 - Refractometer Reading	-40 Degree Fahrenheit		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,470 - Pressure Test Cooling System and Check for Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,480 - FRA Check Coolant Hose Condition	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
40,490 - FRA Check Alternator Mount and Condition	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,100 - FRA Check Fuel Control and Transmission Connections	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,110 - FRA Check Master Cylinder Fluid Level	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,120 - FRA Check All Belts for Condition, Alignment and Tension	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,130 - FRA Check Exhaust System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,140 - FRA Check Intake System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,150 - FRA Inspect Turbocharger	Done	n/a	FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,160 - FRA Inspect Power Steering and Hydraulic Fluid	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,170 - FRA Check All Engine or Belt Driven Components	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,180 - FRA Check for Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,190 - FRA Perform Battery Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
44,200 - FRA Check Battery Box Corrosion, Cables and Hold-Downs	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
50,000 - SECTION 5 Steering System Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
50,510 - Check Entire Steering System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,000 - SECTION 6 Tires and Wheel Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,610 - FRA Check and Record Air Pressure	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,611 - Air Pressure RF	65 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,612 - Air Pressure LF	65 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,613 - Air Pressure RRO	70 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,614 - Air Pressure RRI	70 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
60,615 - Air Pressure LRI	70 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,616 - Air Pressure LRO	70 Pounds per Square Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,620 - Check Valve Stems and Caps	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,630 - Check and Record Tread Depth	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,631 - Tread Depth RF	13 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,632 - Tread Depth LF	13 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,633 - Tread Depth RRO	3 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	Yes	
60,634 - Tread Depth RRI	5 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,635 - Tread Depth LRI	5 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,636 - Tread Depth LRO	3 32nds of an inch		FSIMON	Aug 11, 2015 2:12:34 PM	Yes	
60,640 - Check for Mismatched Tread or Casing Design	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,650 - Check Sidewall Wear	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,660 - Inspect for Cuts and Tears	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,670 - Check Dual Mating With Square	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,680 - Check Wheels for Cracks and Loose Lugs	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
60,690 - Check Tires for Irregular or Alignment Wear	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
66,100 - FRA Check Outer Hubs for Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,000 - SECTION 7 Under Vehicle Inspection	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,710 - Check Vibration Damper	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,720 - Check Engine and Transmission Mounts	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,730 - FRA Check Starter	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,740 - FRA Check Bottom of Engine for Fluid Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,750 - FRA Check Transmission for Leaks	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,760 - FRA Check Differential Breather and Fluid	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,770 - FRA Check Exhaust System	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
70,780 - Check Driveline, U-joint and Slip Yokes	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
70,790 - Check All Body Mounts and Chassis Frame	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,100 - FRA Check Security, Integrity and Length of Ground Straps	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,110 - FRA Check Fuel Tank	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,120 - Check Suspension Components	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,130 - FRA Check Brake Pad Thickness and Rotor for Wear	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,131 - Brake Pad Thickness LF	.32 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,132 - Brake Pad Thickness RF	.32 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,133 - Brake Pad Thickness LR	.27 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,134 - Brake Pad Thickness RR	.27 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,135 - Brake Rotor LF	1.6 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,136 - Brake Rotor RF	1.6 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,137 - Brake Rotor LR	1.4 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,138 - Brake Rotor RR	1.4 Inch		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,140 - FRA Check Brake Hoses	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,150 - Check King Pins	Done	n/a	FSIMON	Aug 11, 2015 2:12:34 PM	No	
77,160 - FRA Check for Loose or Noisy Wheel Bearings	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
80,000 - SECTION 8 PMI Report Completion	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
80,810 - Completion of PMI Report	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
90,000 - SECTION 9 Completion of PMI	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	
90,910 - Vehicle Returned to predetermined location	Done		FSIMON	Aug 11, 2015 2:12:34 PM	No	

Activity Sub Total

Activity 10 Sub Total	
Parts:	1.26
Labor:	0.00
Labor Hours:	2.62
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.26



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 26099196
Invoice No. 55345 - 26099196

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 21,134 - DH

Activity Header

Activity: 20 999 TOTAL VEHICLE

Activity Note: PM A SERVICE

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

20 Desc: PM A SERVICE

Task: PM A SERVICE Performed by: FSIMON Performed on: 11-AUG-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
100,000 - "A" PMI SERVICING ITEMS	Done		FSIMON	Aug 11, 2015 2:12:01 PM	No	
101,000 - FRA Change Oil Filters	Yes		FSIMON	Aug 11, 2015 2:12:01 PM	No	
102,000 - FRA Drain Engine Oil	Yes		FSIMON	Aug 11, 2015 2:12:01 PM	No	
103,000 - FRA Check Transmission Fluid	Done		FSIMON	Aug 11, 2015 2:12:01 PM	No	
104,000 - Lubricate Chassis	Done		FSIMON	Aug 11, 2015 2:12:01 PM	No	
105,000 - Replace or Clean A/C Filters	Done		FSIMON	Aug 11, 2015 2:12:01 PM	No	
107,000 - FRA Change Primary Fuel Filter	Yes	n/a	FSIMON	Aug 11, 2015 2:12:01 PM	No	
108,000 - Lube all pivoting Mechanisms	Done		FSIMON	Aug 11, 2015 2:12:01 PM	No	

Activity Sub Total

Activity 20 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	0.00
Sublet Parts:	0.00

	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 26099196
Invoice No. 55345 - 26099196

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	21,134 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: FSIMON Performed on: 11-AUG-15						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		FSIMON	Aug 11, 2015 2:11:31 PM	No	
20 - Miles			FSIMON	Aug 11, 2015 2:11:31 PM	No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 26099196 Total	
		Parts:	1.26
		Labor:	0.00
		Labor Hours:	2.62
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.26



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26214220
Invoice No. 55345 - 26214220

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FD4E4FSXEDB17155
Ck. for ants		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	19,269 - DH

Chronology		
Reported	Jul 30, 2015 9:24:00 AM	Jul 30, 2015 9:24:00 AM
Started		
Completed	Jul 30, 2015 9:31:00 AM	Jul 30, 2015 9:31:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT:

CAUSE:

CORRECTION:

Activity Header						
Activity: 5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
Activity Sub Total						
				Activity 5 Sub Total		

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26214220
Invoice No. 55345 - 26214220

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Ck. for ants		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	19,269 - DH

Activity Header															
Activity: 15 000 CAB, CLIMATE CONTROL, INSTRUMENTS & AERODYNAMIC DEVICES															
Activity Note: Ck. for ants															
Reason for Repair:	04 Driver's Report														
Work Accomplished:															
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 26214220 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 26214220 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 26214220 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26212082
Invoice No. 55345 - 26212082

Client Department:

Department: 55345M

Work Order Description

Driver complains of ants inside vehicle.

Requested By: EDTORRES

Created By: EDTORRES

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 19,269 - DH

Chronology

Reported	Jul 29, 2015 11:30:57 PM	Jul 29, 2015 11:30:57 PM
Started		
Completed	Jul 30, 2015 12:20:00 AM	Jul 30, 2015 12:20:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().

If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: ants inside vehicle.

CAUSE:

CORRECTION: spoke to Ulysis from Moor Cars and he said he will have someone spray the vehicle for bugs.

Activity Header

Activity: 5 999 TOTAL VEHICLE

Activity Note: Personal Risk Assessment

Reason for Repair: 05 Inspection, Routine

Work Accomplished: 06 Inspect

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

No Data Available

Activity Sublet

No Data Available

Activity Checklist

Check List

5 Desc: Personal Risk Assessment

Task: PRA and Meter Readings Performed by: EDTORRES Performed on: 30-JUL-15

Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done		EDTORRES	Jul 30, 2015 12:19:31 AM	No	
20 - Miles			EDTORRES	Jul 30, 2015 12:19:31 AM	No	

Activity Sub Total

	Activity 5 Sub Total	
	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26212082
Invoice No. 55345 - 26212082

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Driver complains of ants inside vehicle.		Ford E450 Champion Challenger	
Requested By:	EDITORRES	Status:	40 - Closed (40)
Created By:	EDITORRES	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	19,269 - DH

Activity Header															
Activity: 15 050/000 GROUP, ACCESSORIES															
Activity Note: Driver complains of ants inside vehicle.															
Reason for Repair:	05 Inspection, Routine														
Work Accomplished:	14 Install														
Part Failure:	00 No Failure														
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
<table><tr><td colspan="2">Activity 15 Sub Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Activity 15 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 15 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
<table><tr><td colspan="2">Work Order 26212082 Total</td></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>		Work Order 26212082 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 26212082 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 2



Work Order No. 26118174
Invoice No. 55345 - 26118174

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
R & R FRONT TIRES 4602		Ford E450 Champion Challenger	
Requested By:	TSALCI	Status:	40 - Closed (40)
Created By:	TSALCI	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	18,023 - DH

Chronology		
Reported	Jul 1, 2015 12:00:00 AM	Jul 1, 2015 12:00:00 AM
Started	Jul 1, 2015 12:00:00 AM	
Completed	Jul 27, 2015 12:00:00 AM	Jul 27, 2015 12:00:00 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

COMPLAINT: FRONT TIRES WORN

CAUSE: NORMAL WEAR AND TEAR

CORRECTION: R & R FRONT TIRES

Activity Header						
Activity:5 999 TOTAL VEHICLE						
Activity Note: Personal Risk Assessment						
Reason for Repair: 05 Inspection, Routine						
Work Accomplished: 06 Inspect						
Part Failure:						
Activity Comments:						
Activity Parts						
No Data Available						
Activity Labor						
No Data Available						
Activity Sublet						
No Data Available						
Activity Checklist						
Check List						
5 Desc: Personal Risk Assessment						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	
Activity Sub Total						
					Activity 5 Sub Total	

	Parts:	0.00
	Labor:	0.00
	Labor Hours:	0.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 2



Work Order No. 26118174
Invoice No. 55345 - 26118174

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
R & R FRONT TIRES 4602		Ford E450 Champion Challenger	
Requested By:	TSALCI	Status:	40 - Closed (40)
Created By:	TSALCI	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	18,023 - DH

Activity Header
Activity:10 017 TIRES, TUBES, LINERS & VALVES
Activity Note:
Reason for Repair: 05 Inspection, Routine
Work Accomplished:
Part Failure:
Activity Comments:

Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
14-Jul-15	08404	TIRE, LT225/75R16, MICHELIN SEE ATTACHED DOCUMENT	2	234.08	468.16

Activity Labor				
Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-15	Gaspard,Ronald	1	0	0

Activity Sublet
No Data Available

Activity Checklist
No Data Available
No Data Available

Activity Sub Total															
<table><tr><th colspan="2">Activity 10 Sub Total</th></tr><tr><td>Parts:</td><td>468.16</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>468.16</td></tr></table>	Activity 10 Sub Total		Parts:	468.16	Labor:	0.00	Labor Hours:	1.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	468.16	
Activity 10 Sub Total															
Parts:	468.16														
Labor:	0.00														
Labor Hours:	1.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	468.16														

Work Order Footer															
<table><tr><th colspan="2">Work Order 26118174 Total</th></tr><tr><td>Parts:</td><td>468.16</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>1.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>468.16</td></tr></table>	Work Order 26118174 Total		Parts:	468.16	Labor:	0.00	Labor Hours:	1.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	468.16	
Work Order 26118174 Total															
Parts:	468.16														
Labor:	0.00														
Labor Hours:	1.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	468.16														



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 25958774
Invoice No. 55345 - 25958774

Client Department:

Department: 55345M

Work Order Description

PM A

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 16,461 - DH

Chronology

Reported	Jul 1, 2015 12:00:00 AM	Jul 1, 2015 12:00:00 AM
Started	Jul 1, 2015 12:00:00 AM	
Completed	Jul 3, 2015 12:02:31 PM	Jul 3, 2015 12:02:31 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-A SERVICE COMPLETED
REPLACE OIL FILTER
CHANGE ENGINE OIL

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: PM A INSPECTION

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
03-Jul-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.18	1.18

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
01-Jul-15	Gaspard,Ronald	1.5	0	0

Activity Sublet

No Data Available

Activity Checklist


No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	1.18
Labor:	0.00
Labor Hours:	1.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	1.18





Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 25958774
Invoice No. 55345 - 25958774

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	16,461 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 25958774 Total	
		Parts:	1.18
		Labor:	0.00
		Labor Hours:	1.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.18



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 25824395
Invoice No. 55345 - 25824395

Client Department:

Department: 55345M

Work Order Description

PM B

Requested By: DCARTER

Created By: DCARTER

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 11,959 - DH

Chronology

Reported	May 22, 2015 12:00:00 AM	May 22, 2015 12:00:00 AM
Started	May 22, 2015 12:00:00 AM	
Completed	May 27, 2015 9:59:07 AM	May 27, 2015 9:59:07 AM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION: Line 20 PM-B SERVICE PERFORM.

REPLACED OIL FILTER.

CHANGED ENGINE OIL.

WASHER FLUID ADDED.

ROTATE TIRES AND TORQUE TO SPEC.

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: PM B INSPECTION

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: B PM Level B

Part Failure:

Activity Comments:

Activity Parts

Booked Date	Part Number	Part Description	Quantity	Each	Extended
27-May-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.71	1.71

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
22-May-15	Gaspard,Ronald	3	0	0

Activity Sublet

No Data Available

Activity Checklist

No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts: 1.71

	Labor:	0.00
	Labor Hours:	3.00
	Sublet Parts:	0.00
	Sublet Labor:	0.00
	Activity Sub Total	1.71



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 25824395
Invoice No. 55345 - 25824395

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	11,959 - DH

Activity Header	
Activity:20 999 TOTAL VEHICLE	
Activity Note: PM B SERVICE	
Reason for Repair:	08 Preventive Maintenance
Work Accomplished:	B PM Level B
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
No Data Available	
No Data Available	
Activity Sub Total	
Activity 20 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 25824395
Invoice No. 55345 - 25824395

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM B		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	11,959 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available


Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 25824395 Total	
		Parts:	1.71
		Labor:	0.00
		Labor Hours:	3.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.71



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 25737581
Invoice No. 55345 - 25737581

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	7,213 - DH

Chronology		
Reported	Apr 12, 2015 12:00:00 AM	Apr 12, 2015 12:00:00 AM
Started	Apr 12, 2015 12:00:00 AM	
Completed	Apr 13, 2015 2:44:56 PM	Apr 13, 2015 2:44:56 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:


CAUSE:

CORRECTION: Line 20 PMB

Activity Header					
Activity:10 999 TOTAL VEHICLE					
Activity Note: PM A INSPECTION					
Reason for Repair: 08 Preventive Maintenance					
Work Accomplished: A PM Level A					
Part Failure:					
Activity Comments:					
Activity Parts					
Booked Date	Part Number	Part Description	Quantity	Each	Extended
13-Apr-15	B329	GOING OUT OF SERVICE DO NOT ORDER USE B329 IN THE FLEET ORG FILTER, OIL	1	1.63	1.63
Activity Labor					
Booked Date	Technician	Hours	Shop Rate	Extended	
12-Apr-15	Owens,Arthur	2.5	0	0	
Activity Sublet					
No Data Available					
Activity Checklist					
No Data Available					
No Data Available					
Activity Sub Total					
			Activity 10 Sub Total		
			Parts:	1.63	
			Labor:	0.00	
			Labor Hours:	2.50	
			Sublet Parts:	0.00	
			Sublet Labor:	0.00	
			Activity Sub Total	1.63	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 2 of 3



Work Order No. 25737581
Invoice No. 55345 - 25737581


Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	7,213 - DH

Activity Header	
Activity:20 999 TOTAL VEHICLE	
Activity Note: PM A SERVICE	
Reason for Repair:	08 Preventive Maintenance
Work Accomplished:	A PM Level A
Part Failure:	
Activity Comments:	
Activity Parts	
No Data Available	
Activity Labor	
No Data Available	
Activity Sublet	
No Data Available	
Activity Checklist	
No Data Available	
No Data Available	
Activity Sub Total	
Activity 20 Sub Total Parts: 0.00 Labor: 0.00 Labor Hours: 0.00 Sublet Parts: 0.00 Sublet Labor: 0.00 Activity Sub Total 0.00	



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 25737581
Invoice No. 55345 - 25737581

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
PM A		Ford E450 Champion Challenger	
Requested By:	DCARTER	Status:	40 - Closed (40)
Created By:	DCARTER	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	7,213 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 25737581 Total	
		Parts:	1.63
		Labor:	0.00
		Labor Hours:	2.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	1.63



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 3



Work Order No. 24687417
Invoice No. 55345 - 24687417

Client Department:

Department: 55345M

Work Order Description

--> Followup on WO 25661470

Requested By: DKNOTT

Created By: DKNOTT

Assigned To:

Class: WO - WORK ORDER

Arrangement: Unassigned

Potential Warranty: No

Equipment No.: 4602-P

VIN: 1FDFE4FSXEDB17155

Ford E450 Champion Challenger

Status: 40 - Closed (40)

Priority: 1 - Low

Driver:

Phone:

ETA:

Meter: 2,658 - DH

Chronology

Reported	Feb 18, 2015 12:00:00 AM	Feb 18, 2015 12:00:00 AM
Started	Feb 18, 2015 12:00:00 AM	
Completed	Mar 17, 2015 12:04:06 PM	Mar 17, 2015 12:04:06 PM
Down Time		

Work Order Notes

Line 10 COMPLAINT:

CAUSE:

CORRECTION:

Activity Header

Activity: 10 999 TOTAL VEHICLE

Activity Note: PM A INSPECTION

Reason for Repair: 08 Preventive Maintenance

Work Accomplished: A PM Level A

Part Failure:

Activity Comments:

Activity Parts

No Data Available

Activity Labor

Booked Date	Technician	Hours	Shop Rate	Extended
18-Feb-15	Owens, Arthur	2.5	0	0

Activity Sublet

No Data Available

Activity Checklist


No Data Available

No Data Available

Activity Sub Total

Activity 10 Sub Total

Parts:	0.00
Labor:	0.00
Labor Hours:	2.50
Sublet Parts:	0.00
Sublet Labor:	0.00
Activity Sub Total	0.00





Work Order
55345 - Palm Tran Connection
v 3.0
Activity 3 of 3



Work Order No. 24687417
Invoice No. 55345 - 24687417

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
--> Followup on WO 25661470		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	1 - Low
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	2,658 - DH

Activity Header
Activity:30 999 TOTAL VEHICLE
Activity Note: PRAMETER
Reason for Repair: 05 Inspection, Routine
Work Accomplished: 06 Inspect
Part Failure:
Activity Comments:

Activity Parts
No Data Available

Activity Labor
No Data Available

Activity Sublet
No Data Available

Check List						
30 Desc: PRAMETER						
Task: PRA and Meter Readings Performed by: Performed on:						
Inspection Item	RESULTS	Inspector's Note	Inspector	Date Inspected	Follow Up Needed	Follow Up WO
10 - Have you successfully completed the Personal Risk Assessment?	Done				No	
20 - Miles					No	

Activity Sub Total		Activity 30 Sub Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	0.00
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00

Work Order Footer		Work Order 24687417 Total	
		Parts:	0.00
		Labor:	0.00
		Labor Hours:	2.50
		Sublet Parts:	0.00
		Sublet Labor:	0.00
		Activity Sub Total	0.00



Work Order
55345 - Palm Tran Connection
v 3.0
Activity 1 of 1



Work Order No. 25661470
Invoice No. 55345 - 25661470

Client Department:

Department:	55345M	Equipment No.:	4602-P
Work Order Description		VIN:	1FDFE4FSXEDB17155
Followup to PM WO 24687417		Ford E450 Champion Challenger	
Requested By:	DKNOTT	Status:	40 - Closed (40)
Created By:	DKNOTT	Priority:	-
Assigned To:		Driver:	
Class:	WO - WORK ORDER	Phone:	
Arrangement:	Unassigned	ETA:	
Potential Warranty:	No	Meter:	2,658 - DH

Chronology		
Reported	Mar 5, 2015 12:00:00 AM	Mar 5, 2015 12:00:00 AM
Started		
Completed	Mar 17, 2015 11:57:59 AM	Mar 17, 2015 11:57:59 AM
Down Time		

Work Order Notes

Line 10 Have you completed a satisfactory Personal Risk Assessment? Yes() No ().
If the answer is NO stop what you are doing, complete an IP Safety Contact Slip and see your supervisor for further instructions.

=====

Activity Header															
Activity: 1															
Activity Note:															
Reason for Repair:	11 Routine														
Work Accomplished:	03 Replace New														
Part Failure:															
Activity Comments:															
Activity Parts															
No Data Available															
Activity Labor															
No Data Available															
Activity Sublet															
No Data Available															
Activity Checklist															
No Data Available															
No Data Available															
Activity Sub Total															
	<table><tr><th colspan="2">Activity 1 Sub Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Activity 1 Sub Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Activity 1 Sub Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														
Work Order Footer															
	<table><tr><th colspan="2">Work Order 25661470 Total</th></tr><tr><td>Parts:</td><td>0.00</td></tr><tr><td>Labor:</td><td>0.00</td></tr><tr><td>Labor Hours:</td><td>0.00</td></tr><tr><td>Sublet Parts:</td><td>0.00</td></tr><tr><td>Sublet Labor:</td><td>0.00</td></tr><tr><td>Activity Sub Total</td><td>0.00</td></tr></table>	Work Order 25661470 Total		Parts:	0.00	Labor:	0.00	Labor Hours:	0.00	Sublet Parts:	0.00	Sublet Labor:	0.00	Activity Sub Total	0.00
Work Order 25661470 Total															
Parts:	0.00														
Labor:	0.00														
Labor Hours:	0.00														
Sublet Parts:	0.00														
Sublet Labor:	0.00														
Activity Sub Total	0.00														