Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Total Hours: 130.45 **Labor: 9,360.80** **Parts: 4,842.24** **Comm: 482.83** **Charged: 14685.87**

Work Order: 1711171 **Meter:** 364 **In Date:** 11/13/2017 **Closed:** 11/13/2017
Problem: 1061 - Pre Delivery Inspection

Work Completed

- Pre Delivery Inspection

Hours: 2.00 Comm: 0.00 Labor: 120.00 Parts: 0.00 Total: 120.00

Work Order: 1803793 **Meter:** 2671 **In Date:** 04/11/2018 **Closed:** 04/16/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires.
- Shop Supplies

Parts Issued	Quantity
Napa Quart 5w30	6.00
Napagold Oil Filter	1.00
Used Fire X Refurbished	1.00
Floor Mat-2pc Rub Bk	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 225.00 Parts: 72.22 Total: 297.22

Work Order: 1810607 **Meter:** 3173 **In Date:** 10/15/2018 **Closed:** 10/18/2018
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and balance all four tires.
- Load test battery due to slow crank . Diagnose charge battery fully . Retest battery ok .
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w30	7.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
Ford Triton Pvc Swc	1.00
5w20 Engine Oil	7.00
Shop Supplies	1.00

Hours: 4.25 Comm: 0.00 Labor: 284.75 Parts: 77.70 Total: 362.45

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1901564 **Meter:** 8266 **In Date:** 02/11/2019 **Closed:** 02/20/2019
Problem: P.M. service and toolbox latch inop.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires . Nitrofill all.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 251.25 Parts: 43.32 Total: 294.57

Work Order: 1905684 **Meter:** 14590 **In Date:** 05/30/2019 **Closed:** 05/30/2019
Problem: 1 - Wash ticket(s) issued

Work Completed

- 1 - Wash ticket(s) issued

Hours: 0.00 Comm: 9.54 Labor: 0.00 Parts: 0.00 Total: 9.54

Work Order: 1905828 **Meter:** 14847 **In Date:** 06/03/2019 **Closed:** 06/18/2019
Problem: P.M. service and recall 18S27.

Work Completed

- P.m. service.
- Rotate and high speed balance all four tires . Nitrofill all.
- Transport to and from dealer for recall 18s27 .
- Test and replace both blown fuses for power oultlets . Retest for shorts.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Washer Fluid Concentr	1.00
20amp Mcase Fuse	2.00
Shop Supplies	1.00

Hours: 6.55 Comm: 0.00 Labor: 438.85 Parts: 32.76 Total: 471.61

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 1910448 **Meter:** 20240 **In Date:** 10/09/2019 **Closed:** 10/24/2019
Problem: PM Service.

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Rotate and balance all four tires . Nitrofill all.	5w20 Engine Oil	6.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 33.72 Total: 307.47

Work Order: 2001395 **Meter:** 26140 **In Date:** 02/10/2020 **Closed:** 02/20/2020
Problem: P.M. service and request spare key .

Work Completed	Parts Issued	Quantity
- P.m. service.	Napagold Oil Filter	1.00
- Hook up Ids to program new key to vehicle .	5w20 Engine Oil	6.00
- Replace cabin air filter and clean fresh air intake .	Washer Fluid Concentr	1.00
- Rotate and balance all four tires . Nitrofill all.	22" Wiper Blade	2.00
- Shop Supplies	Cabin Air Filter	1.00
	ford side key	1.00
	Shop Supplies	1.00

Hours: 5.25 Comm: 0.00 Labor: 383.25 Parts: 129.88 Total: 513.13

Work Order: 2003517 **Meter:** 28838 **In Date:** 04/07/2020 **Closed:** 04/15/2020
Problem: replace cracked windsheild

Work Completed	Parts Issued	Quantity
- set up re[airs & reasset	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 473.29 Labor: 73.00 Parts: 4.00 Total: 550.29

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2005944 **Meter:** 29059 **In Date:** 06/16/2020 **Closed:** 06/23/2020
Problem: Check engine light.

Work Completed

- Diagnose check engine light.p0316 & P0301.perform pinpoint test ans evap system bay test.replace defective purge solenoid.clear codes and retest.pass bay test.
- Shop Supplies

Parts Issued	Quantity
Purge Valve	1.00
Shop Supplies	1.00

Hours: 2.50 Comm: 0.00 Labor: 182.50 Parts: 53.85 Total: 236.35

Work Order: 2006607 **Meter:** 29595 **In Date:** 07/06/2020 **Closed:** 07/07/2020
Problem: Right rear tire low.

Work Completed

- Replace right rear tire and balance . Nitrofill all.
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00
265/70r17 Tire	1.00
Tire Disposal Fee	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 125.99 Total: 162.49

Work Order: 2007918 **Meter:** 31431 **In Date:** 08/11/2020 **Closed:** 08/17/2020
Problem: P.M. service.

Work Completed

- P.m. service.
- Rotate and balance all four tires . Nitrofill all and reset Tpms .
- Shop Supplies

Parts Issued	Quantity
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Cabin Air Filter	1.00
Napagold Air Filter	1.00
Used Fire X Refurbished	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 73.60 Total: 347.35

Palm Beach County Fleet Management Asset Maintenance History

10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2100020 **Meter:** 38732 **In Date:** 01/04/2021 **Closed:** 01/13/2021

Problem: P.M. service.

Work Completed	Parts Issued	Quantity
- Performed P.m. Service & Inspection	5w20 Engine Oil	7.00
- Performed Tire Rotation Balance On All 4 Wheels. Reset Tpms.	Napagold Oil Filter	1.00
- Removed Cabin Air Filter, Clean A/c Vents . Install New Filter And Check.	22" Wiper Blade	2.00
- Shop Supplies	Cabin Filter	1.00
	Shop Supplies	1.00

Hours: 4.25 Comm: 0.00 Labor: 310.25 Parts: 64.53 Total: 374.78

Work Order: 2102569 **Meter:** 42029 **In Date:** 03/08/2021 **Closed:** 03/10/2021

Problem: Right front tire going flat .

Work Completed	Parts Issued	Quantity
- Replace both front tires and balance . Nitro fill all.	265/70/17 Tire Grappler	2.00
- Shop Supplies	Shop Supplies	1.00
	Tire Disposal Fee	2.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 493.43 Total: 566.43

Work Order: 2103149 **Meter:** 42545 **In Date:** 03/22/2021 **Closed:** 03/23/2021

Problem: Had to jump start .

Work Completed	Parts Issued	Quantity
- Charge battery fully . Test battery and charging system . Battery failed load test . R&r defective battery . Hook up Ids to reset Bsm .	Battry Motorcraft	1.00
- Shop Supplies	Shop Supplies	1.00

Hours: 1.50 Comm: 0.00 Labor: 109.50 Parts: 192.82 Total: 302.32

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2104428 **Meter:** 44583 **In Date:** 04/21/2021 **Closed:** 04/29/2021
Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Replaced 2 tires. Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Performed full front end alignment. Road test .
- Shop Supplies

Parts Issued	Quantity
5w20 Engine Oil	7.00
Napagold Oil Filter	1.00
22" Wiper Blade	2.00
Steering Wheel Cover Large	1.00
265/70/17 Tire Grappler	2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours: 7.25 Comm: 0.00 Labor: 529.25 Parts: 552.79 Total: 1,082.04

Work Order: 2111341 **Meter:** 51874 **In Date:** 10/21/2021 **Closed:** 10/28/2021
Problem: P.M. Service

Work Completed

- Preventive Maint. Service
- Rotated and balanced all 4 tires. Nitrogen filled all tires.
- Replaced cabin filter. Cleaned debris from fresh air intake.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Cabin Filter	1.00
Shop Supplies	1.00

Hours: 4.25 Comm: 0.00 Labor: 310.25 Parts: 65.20 Total: 375.45

Work Order: 2203469 **Meter:** 57305 **In Date:** 03/30/2022 **Closed:** 04/05/2022
Problem: PM Service.

Work Completed

- Preventive Maint. Service
- Rotate and speed balance, nitro fill
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	7.00
Washer Fluid Concentr	1.00
22" Wiper Blade	2.00
Napagold Air Filter	1.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 40.79 Total: 314.54

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2205127 **Meter:** 58529 **In Date:** 05/12/2022 **Closed:** 05/12/2022
Problem: low tire pressure Right rear tire going flat .

Work Completed	Parts Issued	Quantity
- Repair right rear tire and balance . Reset Tpms and Nitro fill all.	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2210620 **Meter:** 63936 **In Date:** 10/17/2022 **Closed:** 10/24/2022
Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- rotate and balance all 4 tires nitro fill all	5w20 Engine Oil	7.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 37.84 Total: 311.59

Work Order: 2300968 **Meter:** 67789 **In Date:** 01/30/2023 **Closed:** 01/30/2023
Problem: screw on front left tire

Work Completed	Parts Issued	Quantity
- Repair left front tire and balance . Nitro fill all.	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2302242 **Meter:** 69219 **In Date:** 03/03/2023 **Closed:** 03/13/2023
Problem: PM Service.

Work Completed

- Perform Pm Service
- Replace rear brake pads, Service calipers, resurface brake rotors, Bleed brakes .road test.
- Battery failed load test, replace, service cable ends.hook up Ids to reset Bsm
- Diagnose engine misfire .perform ignition tune up. Replace spark plugs.and #3 coil and all spark plug boots
- Perform fuel injector flush, Decarb intake system. Service fuel system.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w30	6.00
22" Wiper Blade	2.00
Used Fire X Refurbished	1.00
Brake Fl-dot 3-4 32oz	1.00
Brake Pad	1.00
Intake Cleaner Kit	1.00
Battry Motorcraft	1.00
Spark Plug	6.00
Napa Quart 5w20	6.00
Ign Boot	6.00
Coil	1.00
Shop Supplies	1.00

Hours: 15.55 Comm: 0.00 Labor: 1,135.15 Parts: 454.68 Total: 1,589.83

Work Order: 2304441 **Meter:** 71615 **In Date:** 05/03/2023 **Closed:** 05/04/2023
Problem: flat tire Right rear

Work Completed

- Repair left rear tire, balance and nitro service
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2305149 **Meter:** 72441 **In Date:** 05/24/2023 **Closed:** 05/24/2023
Problem: nail in Left front tire

Work Completed

- Repair left front tire and balance . Nitro fill all and reset Tpms .
- Shop Supplies

Parts Issued	Quantity
Shop Supplies	1.00

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2307319 **Meter:** 74406 **In Date:** 07/25/2023 **Closed:** 08/03/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service completed
- replaced all 4 tires and balance . Nitro fill all.
- check,pin point test,found leaking water pump,sop and r&r defective waterpump ,thermostat housing ,oring gasket,,a/c and drive belt, flush coolant ,bleed and road test
- check and replced cabin a/c filter and clean fresh air intake
- check front pads,resurfaced both front brakes rotors,replaced pads,,calipers,,flush fluid,bleed,road test to verify normal operation
- completed front end alignment and road test
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Coolent	1.00
V Belt	1.00
Serpentine Belt	1.00
Gasket	1.00
Connection Assy	1.00
Water Pump	1.00
Brake Fl-dot 3-4 32oz	1.00
Bracketed Caliper	1.00
Bracketed Caliper	1.00
Brake Pad	1.00
265/70r17 Bfg Trail Terrain	4.00
Shop Supplies	1.00
Tire Disposal Fee	4.00

Hours: 17.55 Comm: 0.00 Labor: 1,281.15 Parts: 1,299.21 Total: 2,580.36

Work Order: 2311579 **Meter:** 79492 **In Date:** 11/17/2023 **Closed:** 11/30/2023
Problem: PM Service.

Work Completed

- Preventive Maint. Service completed
- balance and rotate all 4 tires . Nitro fill all.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Big G Degreaser 1 Gal	1.00
5w20 Engine Oil	6.00
22" Wiper Blade	2.00
Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 38.79 Total: 312.54

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2402653 **Meter:** 84401 **In Date:** 03/14/2024 **Closed:** 03/25/2024
Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation And Balance On All 4 Tires, Add Nitro Fill Reset Tpms.
- Driver Side Rear Taillight Assembly Damaged And Has Water Intrusion, Removed And Replaced Taillight Assembly, Modify For Strobes.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
Lamp Assy	1.00
Shop Supplies	1.00

Hours: 4.55 Comm: 0.00 Labor: 332.15 Parts: 122.01 Total: 454.16

Work Order: 2407260 **Meter:** 89483 **In Date:** 07/29/2024 **Closed:** 08/06/2024
Problem: PM Service.

Work Completed

- Performed P.m. Service & Inspection.
- Performed Tire Rotation Balance On All 4 Tires, Add Nitro Fill Reset Tpms.
- Removed And Replaced The Cabin Air Filter, Clean A/c Vents & Check.
- Performed Service On The Front Differential.
- Performed Service On The Rear Differential.
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
5w20 Engine Oil	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Cabin Air Filter	1.00
Dif Oil	1.00
Px Grey Rtv Silicone	1.00
Dif Oil	2.00
Non-chlor Brake Clnr	2.00
Shop Supplies	1.00

Hours: 7.25 Comm: 0.00 Labor: 529.25 Parts: 137.24 Total: 666.49

Palm Beach County Fleet Management Asset Maintenance History
10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2408083 **Meter:** 90272 **In Date:** 08/21/2024 **Closed:** 08/28/2024
Problem: flat tire right front

Work Completed	Parts Issued	Quantity
- Repair right front tire and balance . Nitro fill all and reset Tpms	Shop Supplies	1.00
- Shop Supplies		

Hours: 1.00 Comm: 0.00 Labor: 73.00 Parts: 2.65 Total: 75.65

Work Order: 2409242 **Meter:** 91819 **In Date:** 09/24/2024 **Closed:** 09/25/2024
Problem: screw in tire left front sidewall

Work Completed	Parts Issued	Quantity
- Replace left front tire and balance . Due to sidewall damage . Nitro fill all and reset Tpms	265/70r17 Bfg Trail Terrain	1.00
	Shop Supplies	1.00
- Shop Supplies	Tire Disposal Fee	1.00

Hours: 0.50 Comm: 0.00 Labor: 36.50 Parts: 188.10 Total: 224.60

Work Order: 2411677 **Meter:** 94654 **In Date:** 12/11/2024 **Closed:** 12/30/2024
Problem: PM Service.

Work Completed	Parts Issued	Quantity
- Preventive Maint. Service	Napagold Oil Filter	1.00
- Rotate and balance four tires. Nitro fill all tires .	5w20 Engine Oil	6.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Wiper Blade	2.00
	Shop Supplies	1.00

Hours: 3.75 Comm: 0.00 Labor: 273.75 Parts: 34.09 Total: 307.84

Palm Beach County Fleet Management Asset Maintenance History

10203952 2017 FORD F150 Pickup, 1/2 Ton, 4X4

Work Order: 2504454 **Meter:** 100865 **In Date:** 05/13/2025 **Closed:** 05/29/2025

Problem: PM Service

Work Completed

- perform Preventive Maint. Service
- mount 1 tire due to puncture, perform balance rotate and nitrofill, tpms relearn.
- Charge battery . Test battery . failed load test , replace battery . R&r battery perform bms reset
- Shop Supplies

Parts Issued	Quantity
Napagold Oil Filter	1.00
Napa Quart 5w20	6.00
Washer Fluid Concentr	1.00
Wiper Blade	2.00
Used Fire X Refurbished	1.00
265/70r17 Bfg Trail Terrain	1.00
Battry Motorcraft	1.00
Shop Supplies	1.00
Tire Disposal Fee	1.00

Hours: 6.25 Comm: 0.00 Labor: 456.25 Parts: 460.47 Total: 916.72

Work Order: 2507529 **Meter:** 103590 **In Date:** 08/12/2025 **Closed:** 08/13/2025

Problem: Transition Prep Charge

Work Completed

- Transition Prep Charge

Hours: 3.50 Comm: 0.00 Labor: 255.50 Parts: 0.00 Total: 255.50

Total Hours: 130.45 **Total Labor: 9,360.80** **Total Comm: 482.83** **Total Parts: 4,842.24**