

**Palm Beach County Fleet Management
Asset Maintenance History**

10171095 2008 STONE 125CM Concrete Mixer,Tow Behind

Workorder: 837191 **Meter:** 0 **In Date:** 03/26/2008 **Closed:** 03/26/2008
Problem: TRAVEL TIME

- Travel Time

Hours 0.10 Labor: 6.00 Parts: 0.00 Total: 6.00
:

Workorder: 837191 **Meter:** 0 **In Date:** 04/18/2008 **Closed:** 04/30/2008
Problem: P.M.

- Pm Service	Parts List	Qty
- Trailer Service	Shop Supplies	1.00
- Test Run	Air Filter	1.00
- Shop Supplies	15/40 Oil	2.00

Hours 5.00 Labor: 300.00 Parts: 58.66 Total: 358.66
:

Workorder: 936602 **Meter:** 0 **In Date:** 04/17/2009 **Closed:** 04/22/2009
Problem: P.M.-PARKED IN SPOT # 279

- Pm Service	Parts List	Qty
- Service Trailer	Shop Supplies	1.00
- Nitro 2 Tires	15/40 Oil	1.00

- Apply Asset Numbers
- Shop Supplies

Hours 6.50 Labor: 390.00 Parts: 4.57 Total: 394.57
:

Workorder: 1001974 **Meter:** 0 **In Date:** 02/24/2010 **Closed:** 03/18/2010
Problem: pm / repair as needed

- Pm	Parts List	Qty
- replaced throttle cable and adjust	Shop Supplies	1.00
- service trailer	46760 Seal	2.00
- remove engine to reinstall bearings and chain sprocket to shaft from engine to mixer barrel-reinstall engine and drive chain and sprockets and realign engine and test run	Air Filter	1.00
	15/40 Oil	1.00
- Shop Supplies	Throttle Cable	1.00

Hours 9.00 Labor: 540.00 Parts: 174.60 Total: 714.60
:

Workorder: 1005046 **Meter:** 0 **In Date:** 05/14/2010 **Closed:** 06/08/2010
Problem: sprocked drive missing

- R&r hood to replace sprocket on barrel and adj chain and test run	Parts List	Qty
	Shop Supplies	1.00
- Shop Supplies	Chain Sprocket	1.00

Hours 2.50 Labor: 150.00 Parts: 168.16 Total: 318.16
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1009448	Meter: 0	In Date: 08/31/2010	Closed: 09/07/2010
Problem: gear came off / see request			
- R&r engine hood to reinstall drive chain and gear from engine to barrel & adj chain and lock tite all set screws	Parts List		Qty
- R/r pull start and reinstall pull kudo and reinstall and tension springs	Shop Supplies		1.00
- r/r chain guard to reattach guard to mounting bracket and free up and lube drum release lever.			
- Shop Supplies			
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			
Workorder: 1103917	Meter: 0	In Date: 04/12/2011	Closed: 04/15/2011
Problem: pm service			
- Pm Service	Parts List		Qty
- Service Trailer	Shop Supplies		1.00
- Replace Asset's	46760 Seal		2.00
- R&r Eng Cover To Replace Bushings On Mounting Bolts	15/40 Oil		1.00
- Shop Supplies			
Hours 6.00	Labor: 360.00	Parts: 9.36	Total: 369.36
:			
Workorder: 1203990	Meter: 0	In Date: 04/27/2012	Closed: 05/04/2012
Problem: pm service/ lock mechanism loose			
- Pm Service	Parts List		Qty
- Service Trailer	Shop Supplies		1.00
- Repair chain guard and repalce retainer pin on wheel for tilt mechanism	46760 Seal		2.00
- Shop Supplies	15/40 Oil		1.00
Hours 6.00	Labor: 360.00	Parts: 9.63	Total: 369.63
:			
Workorder: 1303994	Meter: 0	In Date: 04/23/2013	Closed: 04/30/2013
Problem: PM			
- Pm	Parts List		Qty
- service trailer	Shop Supplies		1.00
- Shop Supplies			
Hours 5.00	Labor: 300.00	Parts: 2.00	Total: 302.00
:			
Workorder: 1403709	Meter: 0	In Date: 04/16/2014	Closed: 05/07/2014
Problem: pm/ check axle/ see notes			
- Pm	Parts List		Qty
- Service trailer	15-40 Oil		1.00
- Align eqpt to the center of frame to balance the axles	Blaster Penetrant		1.00
- Shop Supplies	Seal 1.250 1.979 .250		2.00
	Wd40 16oz		1.00
	Air Filter		1.00
	Shop Supplies		1.00
	Freight Charge		1.00
Hours 7.00	Labor: 420.00	Parts: 105.03	Total: 525.03
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505258 **Meter:** 0 **In Date:** 05/26/2015 **Closed:** 05/29/2015
Problem: pm service

	Parts List	Qty
- Pm		
- Service trailer	15-40 Oil	1.00
- Shop Supplies	Seal 1.250 1.979 .250	2.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 9.86
:		Total: 309.86

Workorder: 1605735 **Meter:** 0 **In Date:** 06/03/2016 **Closed:** 06/28/2016
Problem: pm service

	Parts List	Qty
- Pm		
- Service Trailer	fuel tank damper	4.00
- Repair and weld hood-replace latches	fuel shut off valve	1.00
- R&r Fuel tank repair fuel leak replace throttle cable, tank isolators	filter in tank	1.00
	o ring	1.00
- Shop Supplies	Rubber Latch	2.00
	Throttle Cable	1.00
	Napa Qt 15w40	1.00
	Seal 1.250 1.979 .250	2.00
	Gray Sea	1.00
	1cart Palladium 2 Grs	1.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 11.00	Labor: 660.00	Parts: 261.47
:		Total: 921.47