10181140 2011 FORD F350 Pickup, 1 Ton,4X4, 8Ft. Bed, Srw

| | _ | | | | | - , , - | , - | | |
|---------------------------|------------------------------|-----------------------|------------------------|---------|--------------|----------------|----------------|----------|------------|
| Workorder: Problem: | 1006942 Pre Delivery Ir | Meter: | 0 | | | In Date: | 07/01/2010 | Closed: | 07/01/2010 |
| - Pre Delivery | Inspection | | | | | | | | |
| | Hours : | s 2.00 | | Labor: | 120.00 | Parts: | 0.00 | Total: | 120.00 |
| Workorder: Problem: | 1007951 mount fire pun | Meter: | 333 | | | In Date: | 07/27/2010 | Closed: | 08/12/2010 |
| - fab, weld, cu | ut and mount fire | e pump | | | Parts Li | ist | | | Qty |
| - test run | | | | | Freight | | | | 1.00 |
| - Shop Suppli | es | | | | Shop Su | upplies | | | 1.00 |
| | | | | | T-1 Blac | k Paint Glo | SS | | 1.00 |
| | | | | | T-235 G | ray Primer | | | 2.00 |
| | | | | | T-4 Whi | te Paint | | | 2.00 |
| | | | | | Ltach Lo | ocking Pin | | | 4.00 |
| | Hours : | s 28.50 | | Labor: | 1,710.0 0 | Parts: | 114.16 | Total: | 1,824.16 |
| Workorder: Problem: | 1009630 Istall battery is | Meter: solator and | 915 I trailer plug. | | | In Date: | 09/02/2010 | Closed: | 09/13/2010 |
| | y isolator.fabric | | | | Parts Li | ist | | | Qty |
| disconnect to controller. | bed of truck.ins | tall trailer | connector and | d brake | Shop Su | 1.00 | | | |
| - Shop Suppli | oe. | | | | Connec | tors | | | 2.00 |
| - Shop Suppli | C 3 | | | | Cs4rv R | ed Cable #4 | 1 | | 4.00 |
| | | | | | Battery | Isolator 200 | Amp | | 1.00 |
| | | | | | 5404 Fe | male Conne | ector | | 1.00 |
| | | | | | Cs4rv R | ed Cable #4 | 1 | | 16.00 |
| | | | | | Cs4l Ca | ble #4 | | | 8.00 |
| | | | | | 4047 Br | ake Control | ler (use 5100) | | 1.00 |
| | Hours : | s 6.50 | | Labor: | 390.00 | Parts: | 339.69 | Total: | 729.69 |
| Workorder: Problem: | 1100406 P.M. Service. | Meter: | 4460 | | | In Date: | 01/11/2011 | Closed: | 01/13/2011 |
| - Perform pm | service. | | | | Parts Li | ist | | | Qty |
| - Fabricate ar | nd replace failed | d hitch pind | del pin with ne | ew. | Shop Su | upplies | | | 1.00 |
| - Rotate and I | palance all four | tires. | | | 1372 O | il Filter Frm | Ph2 Wix 513 | 372 | 1.00 |
| - Inspect and | perform power | winch ser | vice. | | Ca1026 | 2 Air Filter N | /Itc Fa1883 W | ix 49883 | 1.00 |
| - Shop Suppli | es | | | | 5w20 Er | ngine Oil | | | 7.00 |
| | | | | | 31-22 W | /iper Blades | 22" Wiper Bla | ade | 2.00 |
| | | | | | Used Fi | rex Refurbe | d Fire Extings | hers | 1.00 |
| | | | | | | Pintle Pin | J | | 1.00 |
| | Hours : | s 6.50 | | Labor: | 390.00 | Parts: | 47.43 | Total: | 437.43 |
| | | | | | | | | | |

| Workorder: Problem: | 1101789 extend elec | Meter: ctrical pigtail | 5120 | | In | n Date: | 02/15/2011 | Closed: | 02/25/20 |)11 |
|---|---------------------------|---------------------------|----------------------|------------|-------------------|--------------|----------------|-----------|----------|------|
| - Extend wire | harness and | d replace qui | ck conenct t | o longer | Parts List | | | | | Qty |
| size | | | | 3 | Shop Supp | olies | | | | 1.00 |
| - Shop Suppli | ies | | | | Sb350v Co | | | | | 2.00 |
| | | | | | Cs4l Cable | | | | | 3.00 |
| | | | | | Cs4rv Red | | 4 | | | 3.00 |
| | Ho | ours 1.00 | | Labor: | | | 46.46 | Total: | 106.46 | |
| Workorder: Problem: | 1102057 Replace tire | Meter: es with off ro | 5976 ad tires. | | In | n Date: | 02/22/2011 | Closed: | 03/15/20 | 011 |
| - Replace fou | | ew off road t | res asper re | equest and | | | | | | Qty |
| | | t complete | | | Shop Supp | | | | | 1.00 |
| - Perform who | J | it complete. | | | Tire Dispos | sal Fee | | | | 4.00 |
| - Shop Suppli | ies | | | | Wrangler N | /lt/r Tire | | | | 4.00 |
| | Ho : | ours 4.50 | | Labor: | 270.00 | Parts: | 1,130.44 | Total: | 1,400.44 | 4 |
| Workorder: Problem: | 1106951 Pm service | Meter: and cannot | 9735 out winch in | neutral. | In | n Date: | 06/30/2011 | Closed: | 07/20/20 | 011 |
| - Perform pm | service. | | | | Parts List | | | | | Qty |
| - Rotate and I | balance all fo | our tires. | | | Big G Degr | reaser St | ock# 4851800 | 002 | | 1.00 |
| - Inspect and | | | | | Shop Supp | olies | | | | 1.00 |
| planetarygear | | | | | 1372 Oil F | ilter Frm | n Ph2 Wix 51 | 372 | | 1.00 |
| Transport ve canister purge | | | | | 09997 Brake Clean | | | | | 1.00 |
| - Shop Suppli | | c with flow a | naci lactory | warranty. | 5w20 Engi | ne Oil | | | | 7.00 |
| опор оцррп | | | | | 31-22 Wipe | er Blades | s 22" Wiper Bl | ade | | 2.00 |
| | Ho : | ours 9.50 | | Labor: | 570.00 | Parts: | 40.56 | Total: | 610.56 | |
| Workorder: Problem: | 1201214 P.M. servic | Meter: | 15059 | | In | n Date: | 02/06/2012 | Closed: | 02/09/20 | 012 |
| - P.m. Service | Э. | | | | Parts List | | | | | Qty |
| - Replace mis | ssing tailgate | edge protec | tor moulding | g. | Shop Supp | olies | | | | 1.00 |
| - Inspect and | service wind | ch. | | | 1372 Oil F | ilter Frm | n Ph2 Wix 51 | 372 | | 1.00 |
| - Rotate and I | balance all ti | res. | | | Ca10262 A | Air Filter N | Mtc Fa1883 W | /ix 49883 | | 1.00 |
| - Shop Suppli | ies | | | | 5w20 Engi | ne Oil | | | | 7.00 |
| | | | | | Used Firex | Refurbe | d Fire Extings | shers | | 1.00 |
| | | | | | 31-22 Wipe | er Blades | s 22" Wiper Bl | ade | | 2.00 |
| | | | | | 7090blk Fr | t Floor M | ats (rubber Q | ueen) | | 1.00 |
| | | | | | Tailgate Mo | oulding | | | | 1.00 |
| | Ho | ours 5.25 | | Labor: | 315.00 | • | 146.42 | Total: | 461.42 | |
| Workorder: Problem: | 1202281 Left front til | Meter: re going flat. | 15797 | | In | n Date: | 03/06/2012 | Closed: | 03/08/20 | 012 |
| - Repair and I | | | | | Parts List | | | | | Qty |
| - Shop Suppli | | | | | Shop Supp | olies | | | | 1.00 |
| Shop Guppii | | ours 1.00 | | Labor: | | Parts: | 2.00 | Total: | 62.00 | |
| | : | | | | | | | . 5.611 | | |

| Workorder: | 1206435 | Meter: | 19686 | | | In Date: | 07/10/2012 | Closed: | 08/09/20 |)12 |
|--|-----------------------------|--------------------|------------------------|-----------|-----------|---------------|---------------|-------------|----------|------|
| Problem: | P.M. Service.C | check trar | ns,shifts hard | when hot. | | | | | | |
| - P.m. Service | Э. | | | | Parts Li | st | | | | Qty |
| - Inspect and | service winch. | | | | Shop Su | upplies | | | | 1.00 |
| - Rotate and I | palance all tires | | | | 1372 O | il Filter Frm | n Ph2 Wix 513 | 372 | 1.0 | |
| Transport vehicle to dealer for leaking rear axle seal and transmission shifting hard.(reflash). | | | | | 5w20 Er | ngine Oil | | | | 7.00 |
| - Shop Suppli | es | | | | | | | | | |
| | Hours : | 6.75 | | Labor: | 405.00 | Parts: | 22.07 | Total: | 427.07 | |
| Workorder: Problem: | 1207646 Install tool box | Meter: | 20052 | | | In Date: | 08/14/2012 | Closed: | 08/22/20 |)12 |
| - Fabricate m | ounting and inst | all tool bo | ox. | | Parts Li | st | | | | Qty |
| - Shop Suppli | es | | | | Shop Su | | 1.00 | | | |
| | | | | | Gas Lift | Support | | | | 2.00 |
| | | | | | 117 Use | d Tool Box | Weather Gua | rd Tool Box | | 1.00 |
| | Hours | 1.00 | | Labor: | 60.00 | Parts: | 154.97 | Total: | 214.97 | |
| Workorder: Problem: | 1302088 P.M. Service.F | Meter: ront end | 26103 shake very ba | ad. | | In Date: | 02/28/2013 | Closed: | 03/29/20 |)13 |
| - P.m. Service |) . | | | | Parts Li | st | | | | Qty |
| | and charging s | | | test | 5w20 Er | ngine Oil | | | | 7.00 |
| • | d test.replace d | | - | | 1372 Oi | | 1.00 | | | |
| Replace leal differential. | king right rear a | xle seal.c | heck and top | off | Used Fi | | 1.00 | | | |
| | tires,rotate and | l halance | all four | | 31-22 W | | 2.00 | | | |
| • | er/caster adjust | | | 1 | Battery (| | | 1.00 | | |
| | el alignment.tes | | riirigs.periorii | ı | Rear Se | al | | | | 1.00 |
| - Inspect and | service winch. | | | | Lt265/70 | Or17 Mt/r | | | | 2.00 |
| - Shop Suppli | es | | | | Slinger | | | | | 1.00 |
| | | | | | Caster-c | amber Bus | hing | | | 2.00 |
| | | | | | Ultra Gr | ey Rtv Silic | one | | | 1.00 |
| | | | | | Pedal Pa | ad | | | | 1.00 |
| | | | | | Shop Su | ıpplies | | | | 1.00 |
| | | | | | Tire Disp | oosal Fee | | | | 2.00 |
| | Hours | 13.50 | | Labor: | 810.00 | Parts: | 1,017.41 | Total: | 1,827.41 | l |
| Workorder: Problem: | 1303061 raise hitch ball | Meter: | 26386 | | | In Date: | 03/28/2013 | Closed: | 03/29/20 |)13 |
| - Raise Two E | Belt Hitches | | | | Parts Li | st | | | | Qty |
| - Shop Suppli | es | | | | Shop Su | ıpplies | | | | 1.00 |
| | Hours : | 3 1.00 | | Labor: | 60.00 | Parts: | 2.00 | Total: | 62.00 | |

| Workorder: 1310146 Meter: 32669 Problem: Pm service. | In Date: 10/08/2013 Closed: | 12/10/2013 |
|---|--|------------|
| - Perform pm service. | Parts List | Qty |
| - Install two new tires to the front wheels.nitrogen fill and | Tire Pressure Monitoring System Sensor (| 2.00 |
| balance all four. | 5w20 Engine Oil | 7.00 |
| Inspect and replace both failed tailgate support cables with new. | Napagold Oil Filter | 1.00 |
| - Test and replace failed left side cargo lamp bulb with new. | Napagold Air Filter | 1.00 |
| - Inspect and service power winch. | Wiper Blade | 2.00 |
| - Transport vehicle to and from dealer for replacing failed | Brake Cleaner | 1.00 |
| leaking front differential pinnion seal with new. | Lt265/70r17 | 2.00 |
| - Shop Supplies | Tr416 Valve Stem | 2.00 |
| | Cable Asy | 1.00 |
| | Cable Asy | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 9.75 Labor: | 585.00 Parts: 699.48 Total: | 1,284.48 |
| Workorder: 1401032 Meter: 34246 Problem: Install Fire Pump | In Date: 01/30/2014 Closed: | 02/10/2014 |
| - fab/weld new fire pump to truck | Parts List | Qty |
| - rewire battery isolator and make battery cables for fire | Cs2l Black Cable 2 Ga | 5.00 |
| pump | Cs2rv Red Cable 2 Gau | 5.00 |
| - test run | 40 60 Ros Core Sld1 | 1.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 25.50 Labor: | 1,530.0 Parts: 77.20 Total: 0 | 1,607.20 |

| Workorder: 1404438 Meter: 37818 | In Date: 05/06/2014 Closed: 05/20/2014 |
|---|--|
| Problem: Pm service and winch cable broken. | |
| - Perform pm service. | Parts List Qty |
| - Inspect and perform winch service replace damage winch | Winch Cable Fabrication 1.00 |
| cable and hook with new and secure cable to drum. | 2232 Brake Fluid Quar 2.00 |
| Inspect and perform rear differential service.replace failed right axle seal and o ring with new.remove parking brake | 5w20 Engine Oil 8.00 |
| shoes to clean and degrease backing plate. | Napagold Oil Filter 1.00 |
| - Perform front differential service. | Used Fire X Refurbished 1.00 |
| - Perform transfer case service. | Napagold Air Filter 1.00 |
| - Install new rear brake pads and resurface rear brake | Wiper Blade 2.00 |
| rotors.service calipers and flush brake fluid.automated bleed | Pintle Pin W/chain 1.00 |
| hydraulic system with scan tool and roadtest. | Clevis Slip Hook-bulk 1.00 |
| - Rotate and balance all four tires. | Seal 1.00 |
| - Shop Supplies | 75w140 Ford Axle Lube 4.00 |
| | Friction Modifier 2.00 |
| | Ptex Ultra Grey 3oz 1.00 |
| | Napa Gear 80w-90 Qt 3.00 |
| | Ford Transfer Case Fluid 2.00 |
| | Rear Pads 1.00 |
| | Washer Nozzle 2.00 |
| | Seal 1.00 |
| | Axle O Ring 1.00 |
| | Shop Supplies 1.00 |
| Hours 16.50 Labor: | 990.00 Parts: 772.90 Total: 1,762.90 |
| Workorder: 1411407 Meter: 42916 Problem: Pm service. | In Date: 11/17/2014 Closed: 12/04/2014 |
| - Pm service. | Parts List Qty |
| - Computer diagnose for check engine light on.code | Stg Wheel Cov - Ford 1.00 |
| P0528.test and replace defective electric fan clutch.clear | Fan Clutch 1.00 |
| code with scan tool and road test | 5w20 Engine Oil 8.00 |
| Inspect and service winch.replace cable end then secure cable to drum and respool. | Napagold Oil Filter 1.00 |
| - Rotate and balance all four tires. | Wiper Blade 2.00 |
| - Shop Supplies | Napagold Air Filter 1.00 |
| - Onop Supplies | Shop Supplies 1.00 |
| Hours 11.50 Labor: | 690.00 Parts: 322.57 Total: 1,012.57 |
| Workorder: 1505310 Meter: 48470 | In Date: 05/27/2015 Closed: 06/02/2015 |
| Problem: Move Hitch | |
| - adjust hitch | Parts List Qty |
| | |
| | Pintle Pin W/chain 1.00 |

| Problem: F | 1505532 Pm service.C | Meter: Check winch | 48983 cable.Vibration a | at high | | Date: | 06/02/2015 | Closed: | 06/18/20 |)15 |
|---|---|--|--|---------|--|---|----------------------------|---------|-------------------------------|---|
| - Pm service. | | | | | Parts List | | | | | Qty |
| - Replace front brake pads and two front calipers.resurface | | | | | Reman Bra | ke Calip | er | | | 1.00 |
| ront brake rotor | | | | | Reman Bra | • | | | | 1.00 |
| | ervice winch | .replace cal | ole and re spool | to | Disc Pads | • | | | | 1.0 |
| drum. | | | - (1 (1 1 1 | 1 | Lt265/70r1 | 7 | | | | 2.0 |
| - Check battery after recharge.re | | | attery failed loadt | est | 5w20 Engir | | | 8.0 | | |
| - Replace two tires.rotate and balance all four. | | | | | Napagold (| Dil Filter | | | 1.00 | |
| - Shop Supplies | | | | | Napagold A | Air Filter | | | | 1.0 |
| | | | | | Used Fire 2 | K Refurb | ished | | | 1.0 |
| | | | | | Wiper Blad | е | | | | 2.0 |
| | | | | | B Fluid Dot | 3-32oz | | | | 1.0 |
| | | | | | Battery | | | | | 1.0 |
| | | | | | Bulb | | | | | 1.0 |
| | | | | | Crane Cab | le Fabric | ation | | | 1.0 |
| | | | | | Clevis Slip | Hook-bu | lk | | | 1.0 |
| | | | | | Shop Supp | lies | | | | 1.0 |
| | | | | | Tire Dispos | al Fee | | | | 2.0 |
| | Hou | ırs 13.00 | La | abor: | 780.00 | Parts: | 1,448.75 | Total: | 2,228.75 | 5 |
| Problem: in Install Bed Slider Shop Supplies | der and Rea | | set 10164690 | | Parts List Shop Supp | lies | | | | Qt 1.0 |
| | Hou | ırs 4.00 | La | abor: | 240.00 | Parts: | 2.00 | Total: | 242 00 | |
| | : | | | | | | | | 242.00 | |
| | : 1509434 _eft brake lar | Meter: mp inop. | 51636 | | | Date: | 09/18/2015 | Closed: | 09/29/20 | 015 |
| Problem: L | _eft brake lar | mp inop. | | | | Date: | 09/18/2015 | Closed: | | |
| Problem: L | _eft brake lar | mp inop. | | | In | Date: | 09/18/2015 | Closed: | | 015 Qt : |
| Problem: L | _eft brake lar | mp inop. | amp bulb. | abor: | In Parts List | Date: | | | | Qt |
| Problem: L - Test and repla | Left brake lar ace defective Hou : 1512261 | mp inop. e left brake l | amp bulb. | abor: | Parts List Bulb 30.00 | | | | 09/29/20 | Qt 1.0 |
| Problem: L - Test and repla Workorder: 1 Problem: F | Left brake lar ace defective Hou : 1512261 | mp inop. e left brake l | amp bulb. | abor: | Parts List Bulb 30.00 | Parts: | 0.75 | Total: | 09/29/20 30.75 | Qt 1.0 |
| Problem: L - Test and repla Vorkorder: 1 Problem: F - Pm service. | Left brake lar ace defective Hou : 1512261 Pm service. | mp inop. e left brake I urs 0.50 Meter: | amp bulb. | abor: | Parts List Bulb 30.00 | Parts: | 0.75 | Total: | 09/29/20 30.75 | Qt 1.0 015 |
| Problem: L - Test and repla Vorkorder: 1 Problem: F - Pm service Perform transi | Left brake lar ace defective Hou : 1512261 Pm service. | mp inop. e left brake I urs 0.50 Meter: h.replace filt | amp bulb. La | abor: | Parts List Bulb 30.00 In | Parts: Date: | 0.75 | Total: | 09/29/20 30.75 | Qt 1.0 |
| Problem: L - Test and repla Vorkorder: 1 Problem: F - Pm service Perform transi - Rotate and ba - Found third br | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all four | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La | | Parts List Bulb 30.00 In Parts List 5w20 Engir Napagold (Napagold (| Parts: Date: ne Oil Dil Filter Air Filter | 0.75 | Total: | 09/29/20 30.75 | Qt 1.0 015 Qt 8.0 |
| Problem: L Test and repla Vorkorder: 1 Problem: F Pm service. Perform transi Rotate and ba Found third br parness for third | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all fourake lamp ind | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La 53029 er and refill fluid. | | Parts List Bulb 30.00 In Parts List 5w20 Engir Napagold (Napagold (22" Wiper B | Parts: Date: ne Oil Dil Filter Air Filter Blade | 0.75 | Total: | 09/29/20 30.75 | Qt 1.0 015 Qt 8.0 1.0 |
| Problem: L Test and repla Vorkorder: 1 Problem: F Pm service. Perform transi Rotate and ba Found third br parness for third | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all fourake lamp ind | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La 53029 er and refill fluid. | | Parts List Bulb 30.00 In Parts List 5w20 Engir Napagold (Napagold (22" Wiper E Macs Chair | Parts: Date: Dil Filter Air Filter Blade Cable I | 0.75 | Total: | 09/29/20 | Qt 1.0 O15 Qt 8.0 1.0 2.0 1.0 |
| Problem: L Test and repla Vorkorder: 1 Problem: F Pm service. Perform transi Rotate and ba Found third br parness for third | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all fourake lamp ind | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La 53029 er and refill fluid. | | Parts List Bulb 30.00 In Parts List 5w20 Engin Napagold A 22" Wiper B Macs Chain Brake Clea | Parts: Date: Dil Filter Air Filter Blade Cable I | 0.75 12/03/2015 _ube | Total: | 09/29/20 30.75 12/21/20 | Qtt 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 |
| Problem: L Test and repla Vorkorder: 1 Problem: F Pm service. Perform transi Rotate and ba Found third br parness for third | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all fourake lamp ind | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La 53029 er and refill fluid. | | Parts List Bulb 30.00 In Parts List 5w20 Engir Napagold (Napagold (22" Wiper E Macs Chair Brake Clea Syn-atf Tra | Parts: Date: Dil Filter Air Filter Blade n Cable I ner ns Fluid | 0.75 12/03/2015 _ube | Total: | 09/29/20 30.75 12/21/20 | Qtt 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 |
| Problem: L - Test and repla Norkorder: 1 Problem: F - Pm service Perform transi - Rotate and ba - Found third br narness for third | Left brake lar ace defective Hou : 1512261 Pm service. mission flush alance all fourake lamp ind | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. La 53029 er and refill fluid. | | Parts List Bulb 30.00 In Parts List 5w20 Engin Napagold A 22" Wiper B Macs Chain Brake Clea | Parts: Date: Dil Filter Air Filter Blade n Cable I ner ns Fluid | 0.75 12/03/2015 _ube | Total: | 09/29/20 30.75 12/21/20 | Qt 1.0 1.0 Qt 8.0 1.0 1.0 2.0 1.0 2.0.0 1.0 |
| Problem: L - Test and repla Workorder: 1 Problem: F - Pm service Perform transi - Rotate and ba | Left brake lare ace defective Hou: 1512261 Pm service. mission flush alance all four rake lamp ince brake lamp is | mp inop. e left brake I urs 0.50 Meter: h.replace filt ur tires. op.no wiring | amp bulb. 53029 er and refill fluid. .make up and refill. | wire | Parts List Bulb 30.00 In Parts List 5w20 Engir Napagold (Napagold (22" Wiper E Macs Chair Brake Clea Syn-atf Tra | Parts: Date: Dil Filter Blade Cable I ner ns Fluid er | 0.75 12/03/2015 _ube | Total: | 09/29/20 30.75 12/21/20 | Qt 1.0 1.0 Qt 8.0 1.0 1.0 2.0 1.0 2.0 2.0.0 |

:

| Workorder: Problem: | 1606745 P.M. Service | Meter: | 56535 | | I | n Date: | 07/01/2016 | Closed: | 07/12/2016 |
|---|---|---|---|---------------------|---|---|------------|---------|---|
| - P.m. Service | 9. | | | | Parts List | : | | | Qt |
| | st and inspect | cooling sys | tem.flush and | d refill | 5w20 Eng | ine Oil | | | 8.0 |
| system. | | | | | Napagold | Oil Filter | | | 1.00 |
| - | service winch. | | | | 22" Wiper | Blade | | | 2.00 |
| | balance all tire | S. | | | Used Fire | X Refurb | shed | | 1.00 |
| - Shop Suppli | ies | | | | Macs Cha | in Cable I | ₋ube | | 1.00 |
| | | | | | Ford Red | Antifreeze |) | | 2.00 |
| | | | | | Drain Plug | J | | | 1.00 |
| | | | | | Shop Supp | plies | | | 1.00 |
| | Hou | rs 8.00 | | Labor: | 480.00 | Parts: | 113.05 | Total: | 593.05 |
| Workorder: Problem: | 1613123 P.M. Service. | Meter: | 58505 | | | n Date: | 12/28/2016 | Closed: | 01/11/2017 |
| - P.m. Service | Э. | | | | Parts List | | | | Qt |
| - Inspect and | service winch. | diagnose a | and replace d | efective | 5w20 Eng | ine Oil | | | 8.0 |
| solenoid. | | | | | Napagold | Oil Filter | | | 1.00 |
| | rbag light.b001 | | | r&r | 22" Wiper | | 2.00 | | |
| _ | eplace defectiv o tires,rotate ar | • | • | | Used Fire X Refurbished Repl Solenoid Term Up Lt265/70r17 | | | | 1.00 |
| • | heel alignment | | | | | | | | 2.00 |
| - Shop Suppli | _ | test unive. | | | | | | | 2.00 |
| - Shop Suppli | 163 | | | | Cover And | d Sterring | Wieel | | 1.00 |
| | | | | | Shop Supp | plies | | | 1.00 |
| | | | | | Tire Dispo | sal Fee | | | 2.00 |
| | Нош | rs 12.75 | | Labor | 765.00 | Parts: | 846.00 | Total· | 1,611.00 |
| | | 10 12.70 | | Labor. | 703.00 | i arts. | 040.00 | rotar. | 1,011.00 |
| Workorder: Problem: | 1703274 Hard to get or | Meter: | 60773 nd clicking no | | | n Date: | 03/31/2017 | Closed: | 04/18/2017 |
| Problem: - Test dreive | : 1703274 Hard to get of for 4x4 concert | Meter: ut of 4x4 an | nd clicking no varify.replac | oise. ce leaking | | n Date: | | | |
| Problem: - Test dreive transmission p | : 1703274 Hard to get of for 4x4 concert oan gasket,rep | Meter: ut of 4x4 are n,unable to lace filter.fl | nd clicking no varify.replac | oise. ce leaking | I | n Date: | | | 04/18/2017 |
| Problem: - Test dreive transmission psystem.clean | : 1703274 Hard to get or for 4x4 concert pan gasket,rep fluid fom under | Meter: ut of 4x4 and an | nd clicking no varify.replac ush and refill | oise. ce leaking | l Parts List | n Date: | | | 04/18/2017 Qt |
| Problem: - Test dreive transmission psystem.clean to Diagnose in | : 1703274 Hard to get of for 4x4 concert pan gasket,repl fluid fom under op winch.repla | Meter: ut of 4x4 and an | nd clicking no varify.replac ush and refill | oise. ce leaking | Parts List | n Date: : : : : : : : : : : : : : : : : : : | 03/31/2017 | | 04/18/2017 Qty 1.00 |
| Problem: - Test dreive transmission psystem.clean | : 1703274 Hard to get of for 4x4 concert pan gasket,repl fluid fom under op winch.repla | Meter: ut of 4x4 and an | nd clicking no varify.replac ush and refill | oise. ce leaking | Parts List Transmiss trans pan | n Date: sion Filter gasket noid Term | 03/31/2017 | | 04/18/2017 Qty 1.00 |
| Problem: - Test dreive transmission psystem.clean to Diagnose in | : 1703274 Hard to get of for 4x4 concert pan gasket,repl fluid fom under op winch.repla | Meter: ut of 4x4 and an | nd clicking no varify.replac ush and refill | oise. ce leaking | Parts List Transmiss trans pan Repl Sole | n Date: sion Filter gasket noid Term ans Fluid | 03/31/2017 | | 04/18/2017 Qty 1.00 1.00 1.00 |

| Workorder: 1706502 Meter: 63609 Problem: P.M. Service. | | In Date: | 06/30/2017 | Closed: | 07/10/2017 |
|--|---------------------|--|------------------------------|----------|--|
| - P.m. service. | | Parts List | | | Qty |
| - Check starting and charging systems.battery failed | load | 5w20 Engine Oil | 8.00 | | |
| test.replace with new battery. | | Napagold Oil Filter | | | 1.00 |
| - Replace all six body mount bushings. | | 20" Wiper Blade | | | 2.00 |
| - Rotate and high speed balance all four tires. | | Used Fire X Refurb | | 1.00 | |
| - Shop Supplies | | Fire Ext Mount Stra | | 1.00 | |
| | | Napagold Air Filter | | | 1.00 |
| | | Stg Wheel Cov - Fo | ord | | 1.00 |
| | | Mac Wite Lithium G | ires | | 1.00 |
| | | Washer Fluid Conc | entr | | 1.00 |
| | | Battery | | | 1.00 |
| | | Body Mount Kit | | | 2.00 |
| | | Body Mount Kit | | | 4.00 |
| | | Shop Supplies | | | 1.00 |
| Hours 12.00 | Labor: | 720.00 Parts: | 799.64 | Total: | 1,519.64 |
| Workorder: 1800127 Meter: 67049 Problem: P.M. service. | | In Date: | 01/03/2018 | Closed: | 01/16/2018 |
| - P.m. Service. | | Parts List | | | Qty |
| - Replace dome lamp bulbs. | | 5w20 Engine Oil | | | 8.00 |
| - Replace two tires,rotate and balance all four. | | Name and Cit Filters | | | |
| | Napagold Oil Filter | | | 1.00 | |
| Complete wheel alignment.test drive. | | Washer Fluid Conc | entr | | 1.00 1.00 |
| Complete wheel alignment.test drive.Inspect and service winch. | | , , | entr | | |
| | | Washer Fluid Conc | | | 1.00 |
| - Inspect and service winch. | | Washer Fluid Conc 22" Wiper Blade | | | 1.00 2.00 |
| - Inspect and service winch. | | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw | | | 1.00 2.00 1.00 |
| - Inspect and service winch. | | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb | С | Sensor (| 1.00 2.00 1.00 3.00 |
| - Inspect and service winch. | | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 | С | Sensor (| 1.00 2.00 1.00 3.00 2.00 |
| - Inspect and service winch. | | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 Tire Pressure Moni | С | Sensor (| 1.00 2.00 1.00 3.00 2.00 |
| - Inspect and service winch. | Labor: | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 Tire Pressure Moni Shop Supplies Tire Disposal Fee | С | · | 1.00 2.00 1.00 3.00 2.00 2.00 1.00 |
| Inspect and service winch.Shop Supplies | Labor: | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 Tire Pressure Moni Shop Supplies Tire Disposal Fee | c toring System | · | 1.00 2.00 1.00 3.00 2.00 2.00 1.00 2.00 |
| - Inspect and service winch Shop Supplies Hours 8.75 : Workorder: 1800993 Meter: 67416 Problem: Left rear tire going flat. | Labor: | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 Tire Pressure Moni Shop Supplies Tire Disposal Fee 525.00 Parts: | c toring System 695.34 | Total: | 1.00 2.00 1.00 3.00 2.00 2.00 1.00 2.00 1,220.34 |
| - Inspect and service winch Shop Supplies Hours 8.75 : Workorder: 1800993 Meter: 67416 | Labor: | Washer Fluid Conc 22" Wiper Blade Ford Triton Pvc Sw Bulb Lt265/70r17 Tire Pressure Moni Shop Supplies Tire Disposal Fee 525.00 Parts: | c toring System 695.34 | Total: | 1.00 2.00 1.00 3.00 2.00 2.00 1.00 2.00 1,220.34 |

| Workorder: 1806014 Meter: 72050 Problem: PM Service | | | In Date: | 06/12/2018 | Closed: | 06/20/2018 | |
|---|--------|--|--------------|------------|---------|------------|--|
| - P.m. Service. | | Parts Li | st | | Qty | | |
| - Resurface front brake rotors,replace pads and | | Napagol | | 1.00 | | | |
| calipers.flush and bleed system. | | 5w20 Er | ngine Oil | 8. | | | |
| - Inspect and service winch. | | Napagol | d Air Filter | | 1.0 | | |
| - Replace worn out front bump stops. | | Used Fir | e X Refurbi | ished | | 1.00 | |
| - Rotate and balance titres. | | Ford Trit | on Pvc Swo | | 1.00 | | |
| - Shop Supplies | | Brake P | ads | | 1.00 | | |
| | | | or Brake Clr | nr | | 2.00 | |
| | | B Fluid [| Oot 3-32oz | | | 1.00 | |
| | | Remote | Ctrl Ser. Pa | | 1.00 | | |
| | | bumper L /f Caliper R /f Caliper | | | | 2.00 | |
| | | | | | | 1.00 | |
| | | | | | | 1.00 | |
| | | , | • | | | 2.00 | |
| | | 22" Wiper Blade Shop Supplies | | | | 1.00 | |
| Hours 10.50 | Labor: | 630.00 | • • | 466.15 | Total: | 1,096.15 | |
| Workorder: 1810757 Meter: 77068 | | | In Date: | 10/18/2018 | Closed: | 10/18/2018 | |
| Problem: Transition Prep Charge | | | | | | | |
| - Transition Prep Charge | | | | | | | |
| Hours 2.00 | Labor: | 134.00 | Parts: | 0.00 | Total: | 134.00 | |