10189465 2013 FORD F-250 Cage Truck, 3/4 Ton, Regular With A/C

	101894	465	2013 FOR	D F-250 Cage	e Truck,	3/4 Ton, Re	gular With A	/C		
Workorder:	1304861	Meter:	338			In Date:	05/15/2013	Closed:	05/15/2013	,
Problem:	1061 - Pre Deli	very Ins	pection							
- Pre Delivery	Inspection									
	Hours	4.00		Labor:	240.00	Parts:	0.00	Total:	240.00	
Moulsondon	1205270	Matau	1010			In Data:	05/04/0040	Classic	00/44/0040	
Workorder: Problem:	1305376 Towed in for No	Meter: o start.A	1912 bs and tra	ction control li	ights on.	In Date:	05/31/2013	Closed:	06/11/2013	
	ge drained batte				Parts L	ist			C	lty
system.test for discharged.	r draw.all check	out ok a	t this time.	battery was	Shop Si	upplies			1.	00
- Shop Suppli										
	Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1305463	Meter:	1185			In Date:	05/30/2013	Closed:	06/04/2013	;
Problem:	stuck in park/ se	erv adva	ince track	& brake light	on					
- Tow From: v	wallmart belvede	re and 4	41 To: lv	shop						
	Hours	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1306041	Meter:	3407			In Date:	06/17/2013	Closed:	07/05/2013	
Problem:	Check engine li	ight on.								
	iagnose for chec				Parts L	ist			C	lty
	I replace failed fu close to plastic c				Pipe Fu	ıel			1.	00
codes with Ids		quick dis	connect ei	bow.cieai	Shop Si	upplies			1.	00
- Shop Suppli										
	Hours :	2.50		Labor:	150.00	Parts:	197.96	Total:	347.96	
Workorder:	1306366	Meter:	3407			In Date:	06/25/2013	Closed:	07/05/2013	,
Problem:	Pm service.Fue	el cap wa	arning ligh	t on.Left top w	vork lamp	broken.				
- P.m. Service	Э.				Parts L	ist			C	lty
- Replace bro	ken left side wor	k lamp.			5w20 E	ngine Oil				00
- Rotate and I	balance all tires.				Napago	ld Oil Filter			1.	00
- Shop Suppli	es				Floor M	at-2pc Rub I	Вk		1.	00
					Work Lr	np			1.	00
					Shop Si	upplies			1.	00
	Hours	4.25		Labor:	255.00	Parts:	77.23	Total:	332.23	
Workorder:	1309203	Meter:	10			In Date:	09/10/2013	Closed:	09/19/2013	;
Problem:	P.M. service.									
- P.m. Service					Parts L					lty
- Rotate and I	balance all tires.				Napago	ld Oil Filter			1.	00
- Shop Suppli	es				5w20 E	ngine Oil			7.	00
					Used Fi	re X Refurbi	shed		1.	00
					Shop St	upplies			1.	00
	Hours	3.75		Labor:	225.00	Parts:	39.89	Total:	264.89	

Workorder: Problem:	1311870 Pm service.	Meter:	13507			In Date:	11/25/2013	Closed:	12/10/20	013
- P.m. Service	€.				Parts Lis	t				Qty
- Rotate and I	palance all tires	S.			5w20 Eng	ine Oil				7.00
- Complete w	heel alignment				Napagold					1.00
- Shop Suppli	_				Wiper Bla					2.00
111					Shop Sup					1.00
	Hour	rs 6.25		Labor:	375.00	•	32.38	Total:	407.38	
Workorder: Problem:	1402064 P.M. service a	Meter: and left firs	19967 st two cage d	loors loose		In Date:	03/03/2014	Closed:	03/13/20	014
- P.m. Service	€.				Parts Lis	t				Qty
- Replace two	tires,rotate an	ıd balance	all four.		5w20 Eng	jine Oil				7.00
- Shop Suppli	es				Napagold	Oil Filter				1.00
					Napagold	Air Filter				1.00
					Wd40 16	oz				1.00
					17963649	2 Lt245-7	′5r17			2.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	Hour :	rs 4.75		Labor:	285.00	Parts:	535.89	Total:	820.89	
Workorder: Problem:	1404575 Pm service.	Meter:	24290		l	In Date:	05/09/2014	Closed:	05/20/20	014
- Perform pm	service.				Parts Lis	t				Qty
	ew tires to the	front whee	ls.nitrogen fi	ill and	5w20 Eng	jine Oil				7.00
balance all fou					Napagold	Oil Filter				1.00
- Shop Suppli	es				Wiper Bla	de				2.00
					Washer F	1				1.00
					Stg Whee	l Cov - Fo	ord			2.00
					17963649	2 Lt245-7	′5r17			2.00
					Shop Sup	plies				1.00
					Tire Dispo	sal Fee				2.00
	Hour :	rs 4.75		Labor:	285.00	Parts:	558.44	Total:	843.44	
Workorder: Problem:	1407841 Pm service ar	Meter:	28977 ngine light o	·n.		In Date:	08/08/2014	Closed:	08/22/20	014
- Pm service.			· •		Parts Lis	t				Qty
	agnose for fue	l cap light	on.code P04	157.found	Pipe Fue					1.00
broken filler ne	eck vent hose.r r code with sca	replace fue	el filler tube		Washer F	Ί				1.00
assembly.clea					Used Fire		ished			1.00
-					Napagold	Oil Filter				1.00
- Rotate and I										
-					5w20 Eng	jine Oil				7.00
- Rotate and I					5w20 Eng Shop Sup					7.00 1.00

Workorder: Problem:	1408707 Fix front bun	Meter: nper.	29959			In Date:	08/29/2014	Closed:	09/02/2014
- Reinstall from	nt bumper va	lance.							
	Hou	urs 0.75		Labor:	45.00	Parts:	0.00	Total:	45.00
Workorder: Problem:	1412467 Pm service.	<b>Meter:</b> Towed in for	34245 no start.			In Date:	12/15/2014	Closed:	12/30/2014
- Pm service.					Parts L	ist			Qty
- Check batte				adtest	5w30 O	il			7.00
after recharge	•	•				ld Oil Filter			1.00
<ul> <li>Repair broke to connector.</li> </ul>	en wire for lef	t side work l	amp above ca	ige close	Wiper B	lade			2.00
- Rotate and b	nalance all fo	ur tires			Battery	65			1.00
- Shop Suppli		u			Shop S	upplies			1.00
опор обрри		urs 5.50		Labor:	330.00	Parts:	196.28	Total:	526.28
Workorder: Problem: - Tow From: 1 Shop	1412531 No start/PM 2038 Forest		34241 ellington FI To	o: Lv		In Date:	12/12/2014	Closed:	12/15/2014
СПОР	Hou	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1503929 Pm service.	Meter:	40742			In Date:	04/16/2015	Closed:	04/28/2015
- Pm service.					Parts L	ist			Qty
- Replace from				ke	kit brake	€			1.00
rotors.service system.roadte		h and bleed	brake		5w20 E	7.00			
- Rotate and b		ur tiros			Napago	1.00			
- Shop Suppli		ui iii63.			Napago	ld Air Filter			1.00
Shop Guppii	00				Wiper B				2.00
					Shop S				1.00
	Ho	urs 7.75		Labor:	465.00	Parts:	147.94	Total:	612.94

	1507292 Pm service 3	Meter:	46759 warm when stan	lina	In D	ate:	07/22/2015	Closed:	08/10/2015
- P.m. Service		and ac blows	wann when stair		arts List				Qt
		hlowing cold	l.replace defective		v20 Engine	Oil			7.0
			sh system.vacuum		apagold Oil		1.0		
and recharge s	system to spe	CS.			sed Fire X F		ished		1.0
- Replace two	tires,rotate a	nd balance	all four.		iper Blade	Coraro	101100		2.0
- Shop Supplie	es				B A/c Oil Un	niv W C	Ove		1.0
					q A-c Flush				1.0
					'9636492 Lt				2.0
					c Compress				1.0
					κ Pansion V				1.0
				Ac	cumulator				1.0
				R1	134a Lv Sho	op 1			3.0
					eal Kits	•			1.0
				Se	eal				1.0
				Sh	nop Supplie	s			1.0
				Tir	re Disposal	Fee			2.0
	Hou	ırs 9.75	La	or: 58	35.00 I	Parts:	1,176.24	Total:	1,761.24
	1508369 Right front tii	Meter: re flat.	47842		In D	ate:	08/20/2015	Closed:	08/25/2015
Problem: - Replace defetire.	Right front til	e flat.	47842 stem and balance		arts List		08/20/2015 toring System		08/25/2015 <b>Q</b> t 1.0
Problem: - Replace defe	Right front til	e flat.		Tir	arts List	Monit			Qı
Problem: - Replace defetire.	Right front tile ective right from es	e flat.	stem and balance	Tir	arts List re Pressure nop Supplie	Monit	toring System	Sensor (	<b>Q</b> 1 1.0
Problem: - Replace defetire Shop Supplie	Right front til ective right fro es Hou : 1511292	re flat. ont tire valve urs 1.00  Meter:	stem and balance	Tir Sh	arts List re Pressure nop Supplie	e Monit es Parts:	toring System	Sensor (	<b>Q</b> 1 1.0 1.0
Problem: - Replace defetire Shop Supplie	Right front til ective right fro es Hou : 1511292	re flat. ont tire valve urs 1.00  Meter:	e stem and balance La 52322	Tir Sh oor: 60	arts List re Pressure nop Supplie:	e Monit es Parts:	toring System 4.96	Sensor ( Total:	<b>Q</b> 1 1.0 1.0 64.96
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter	Right front tile ective right from the es  House 1511292 P.M. service	re flat. ont tire valve urs 1.00  Meter: and left from	La 52322 at tire going flat.	Tir Sh por: 60	re Pressure nop Supplie 0.00 I	e Monites Parts:	toring System 4.96	Sensor ( Total:	Q1 1.0 1.0 64.96
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge.	Right front tile ective right from the es  House 1511292 P.M. service ry and charging replace defective right from the expense of the expense	re flat. ont tire valve urs 1.00  Meter: and left from	La 52322 In tire going flat.	Tir Sh por: 60 Pa	re Pressure re Pressure nop Supplie: 0.00 I	e Monites Parts: Pate:	toring System 4.96	Sensor ( Total:	1.0 1.0 64.96 11/23/2015
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two	Right front tile ective right from the es  House 1511292 P.M. service Ty and charging replace defectives. rotate a	me flat.  In tire valve  In 1.00  Meter:  and left from  Ing system.bative battery  Ind balance a	La 52322 at tire going flat.	Tirr Shoor: 60  Pa  State Stat	re Pressure nop Supplie: 0.00 In D arts List	e Monites Parts: Pate:	toring System 4.96	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans	Right front tile ective right from the ective right from the estable of the extension of the extension fluid replace defectives. For the extension fluid replace defections and the extension fluid replace defections are extension fluid replaced from the extension fluid replaced	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Tir Shoor: 60 Pa St 5w Na Wi	re Pressure nop Supplie: 0.00 In D arts List v20 Engine apagold Oil	e Monites Parts: Pate:	toring System 4.96	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wo	re Pressure nop Supplies 0.00 In D arts List v20 Engine apagold Oil iper Blade	e Monites Parts: Pate: Oil Filter	4.96 11/04/2015	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Wi	In D  arts List v20 Engine apagold Oil iper Blade d40 16oz	e Monites Parts: Pate: Oil Filter	4.96 11/04/2015	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wo Ma Ba	re Pressure nop Supplies 0.00 In D  arts List v20 Engine apagold Oil iper Blade d40 16oz ac Wite Lith	e Monites Parts:  Oil Filter	4.96 11/04/2015	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wo Ma Ba 17	In D  arts List  one Supplies  one In D  arts List  v20 Engine apagold Oil iper Blade d40 16oz ac Wite Lith attery 65	e Monites Parts:  Oil Filter  hium G	4.96 11/04/2015 ares	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0 1.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wo Ma Ba 17 Sy	In D  Arts List  one Supplies  one Supplies  one In D  Arts List  v20 Engine  apagold Oil  iper Blade  d40 16oz  ac Wite Lith  attery 65	Monites Parts: Pate: Oil Filter hium G	4.96 11/04/2015 ares	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0 1.0 2.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wa Ba 177 Sy Bra	In D  In D	e Monites Parts: Pate: Oil Filter hium G t245-7 s Fluid	4.96 11/04/2015 ares	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0 1.0 2.0 18.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wo Ma Ba 17 Sy Bra	In D  In D	e Monites Parts: Pate: Oil Filter t245-7 6 Fluid er	4.96 11/04/2015 ares	Sensor ( Total:	Qf 1.0 1.0 64.96 11/23/2015 Qf 7.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0
Problem: - Replace defetire Shop Supplie  Workorder: Problem: - Pm service Check batter after recharge Replace two - Perform trans-	Right front tile ective right from the estrong House H	me flat.  ont tire valve  urs 1.00  Meter: and left from  ng system.bactive battery  nd balance at flush .repla	La 52322 at tire going flat.  attery failed loadte. all four. ace filter.and refill.	Past 5w Na Wi Wa Ba 17 Sy Bra Sh	In D  In D	e Monites Parts:  Pate:  Oil Filter  sit245-7 si Fluid er si Filter	4.96 11/04/2015 ares	Sensor ( Total:	Q1 1.0 1.0 64.96 11/23/2015 Q1 7.0 1.0 2.0 1.0 2.0 18.0 1.0

Workorder: Problem:	1600045 Power outlet a	Meter: and ciger li	54206 ght inop.			In Date:	01/04/2016	Closed:	01/20/20	16
	blace both fuses or short.ok at thes es		r outlet and o	cigarette	Parts List  Bp Fmx-lp F Mx Fuse  Shop Supplies					<b>Qty</b> 2.00 1.00
	Hours	s 0.75		Labor:	45.00	Parts:	11.30	Total:	56.30	
Workorder: Problem:	1602747 Pm service.	Meter:	57662			In Date:	03/16/2016	Closed:	03/23/20	16
- Pm service.					Parts L	ist				Qty
- Replace two	defective wind	lshield wa	sher nozzles		5w20 E	ngine Oil				7.00
	st and inspect o	ooling sys	tem.flush an	d refill	Napago	ld Oil Filter				1.00
coolant.					Napago	ld Air Filter				1.00
	ince and leak te n hose from eva				22" Wip	er Blade				2.00
	system.leak tes		Compressor	i.evacuate	Washer	Nozzle				2.00
- Rotate and I	oalance all four	tires.			Ford Re	ed Antifreeze	)			2.00
- Shop Suppli	es				R134a Lv Shop 1					3.00
					A/c Suc	tion Hose				1.00
					Shop St	upplies				1.00
	Hours :	s 9.75		Labor:	585.00	Parts:	272.77	Total:	857.77	
Workorder: Problem:	1604629 Right front tire	Meter: going flat	60443 and can not	lower spa	re tire.	In Date:	05/03/2016	Closed:	05/05/20	16
- Repair and I	palance right fro	ont tire.			Parts L	ist				Qty
- Shop Suppli	_				Shop Si	upplies				1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1604653 flat tire afterho	Meter: ours towed	60353 I in			In Date:	05/03/2016	Closed:	05/04/20	16
- Tow From: a	animal care To	: Iv shop								
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1605941 damage to rea	Meter: ar bumper	61298			In Date:	05/19/2016	Closed:	06/09/20	16
- damage to r	ear bumper									
	Hours	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	

Workorder: 16074 Problem: P.M.		<b>Meter:</b> nd right re	64150 ear tire flat sp	are on tru	ck.	In Date:	07/21/2016	Closed:	08/02/20	016
- P.m. Service.					Parts L	ist				Qty
- Inspect and service	e differen	tial.				ld Oil Filter				1.00
- Replace one tire,ro			all four.			ngine Oil				7.00
- Shop Supplies					22" Wip		2.00			
Chief Capphies					Washer			1.00		
						Ford Axle L				3.00
						Modifier	Lube			1.00
						492 Lt245-7	5r17			1.00
						ra Grey 3oz				1.00
						re X Refurbi				1.00
							isrieu			1.00
					Shop St					
	Harris	4.50		Laban		posal Fee	204.50	Tatal	004.50	1.00
	Hours	3 4.50		Labor:	270.00	Parts:	391.59	ı otal:	661.59	
Workorder: 16117 Problem: P.M.		Meter: PMS ligh	70347 t on.			In Date:	10/27/2016	Closed:	11/08/20	016
- P.m. Service.					Parts L	ist				Qty
- Replace two cargo	lamps.				Napago	ld Oil Filter				1.00
- Rotate and balance					22" Wip		2.00			
- Shop Supplies					Used Fi		1.00			
						ld Air Filter				1.00
					Work Lr					2.00
						ngine Oil				7.00
					Shop St	_				1.00
	Hours :	4.75		Labor:	285.00		102.88	Total:	387.88	1.00
Workorder: 1613 <sup>a</sup> Problem: no sta		Meter:	73156			In Date:	12/29/2016	Closed:	12/29/20	016
- Tow From: animal	care To:	lv								
	Hours :	0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: 1613 <sup>a</sup> Problem: Tow i		Meter:	74371			In Date:	12/29/2016	Closed:	01/25/20	017
- Recharge battery.t bad battery.	est batter	y and cha	arging system	n.replace	Parts Li Battery	ist				<b>Qty</b> 1.00
- Shop Supplies					Shop St	upplies				1.00
	Hours :	3 1.00		Labor:	•		126.43	Total:	186.43	1.00
Workorder: 17003 Problem: No sta		Meter:	73550			In Date:	01/09/2017	Closed:	01/10/20	017
- Tow From: Animal		: Lv shon								

Problem:	1702142 P.M. service a	Meter: and right #4	76688 4 kennel door	damaged		n Date:	03/01/2017	Closed:	03/16/2017
- P.m. Service.		J		J	Parts List	:			Qty
- Replace and		new tires.			5w20 Eng	ine Oil			7.00
- Replace left s			l ioints.		Napagold				1.00
- Resurface fro			•		22" Wiper				2.00
calipers.flush a					Washer Fl		entr		1.00
- Complete who	eel alignment	test drive.			17963649	2 Lt245-7	5r17		4.00
- Repair and a	djust damage	right rear of	door on cage.		Ball Joint				1.00
- Shop Supplie	es				Ball Joint				1.00
					Front Brak	ce Caliper			1.00
					Front Brak	ce Caliper			1.00
					kit brake	-			1.00
					B Fluid Do	t 3-32oz			1.00
					Non-chlor	Brake Cli	nr		1.00
					Shop Sup	plies			1.00
					Tire Dispo	sal Fee			4.00
	Hour	rs 14.65		Labor:	879.00	Parts:	1,452.64	Total:	2,331.64
	1704187 Missing fuel c	Meter: ap.Right si	78686 de running bo	ard brok		n Date:	04/26/2017	Closed:	05/11/2017
- Replace miss	sing fuel cap.				Parts List	:			Qty
- Replace brok	en right side i	running ho	ard						
OI		i ai ii iii ig bot	aiu.		Step Asy				1.00
<ul> <li>Shop Supplie</li> </ul>	_	ranning boo	aru.		Step Asy Cap Asy				•
- Shop Supplie	_	ruming boo	aru.			plies			1.00
- Shop Supplie	es	rs 1.20	aru.	Labor:	Cap Asy Shop Sup		485.27	Total:	1.00 1.00
Workorder:	es	rs 1.20 <b>Meter:</b>	81480	Labor:	Cap Asy Shop Sup 72.00		485.27 07/06/2017	Total:	1.00 1.00 1.00
Workorder:	Hour : 1706645 A/C blows wa	meter:	81480		Cap Asy Shop Sup 72.00	Parts:			1.00 1.00 1.00 557.27
Workorder: Problem: - Check perfor front and rear A	Hour : 1706645 A/C blows wa rmed.a/c perfo	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00	Parts:	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017
Workorder: Problem: - Check perfor front and rear A condensor, and	Hour : 1706645 A/C blows wa rmed.a/c perfo /c expandsion high side shre	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00	Parts:  n Date:  Core High	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 Qty
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00	Parts:  n Date:  Core High	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 <b>Qty</b> 1.00
Workorder: Problem: - Check perfor front and rear A condensor, and	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00  Parts List Ac Valve Of Freon Lv S	Parts:  n Date:  Core High	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 <b>Qty</b> 1.00 4.00
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00  Parts List Ac Valve C Freon Lv S Expension	Parts:  n Date:  Core High Shop 2  n Valve	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 <b>Qty</b> 1.00 4.00 1.00
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00  Parts List Ac Valve Of Freon Lv S Expension A/c Dryer	Parts:  n Date:  Core High Shop 2  n Valve	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 <b>Qty</b> 1.00 4.00 1.00
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Supp 72.00  Parts List Ac Valve ( Freon Lv S Expension A/c Dryer Rapid Sea	Parts:  n Date:  Core High Shop 2  n Valve  al Kit	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 <b>Qty</b> 1.00 4.00 1.00 1.00
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Sup 72.00  Parts List Ac Valve Of Freon Lv S Expension A/c Dryer Rapid Sea Valve Ass	Parts:  n Date:  Core High Shop 2  n Valve  al Kit y Kit	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 Qty 1.00 4.00 1.00 1.00 1.00
Workorder: Problem: - Check perfor front and rear A condensor,and and recharge a	Hour: 1706645 A/C blows warmed.a/c perfolyc expandsion high side shrond retest.	Meter: arm air. brmance te	81480 st .replace del d rear drier and	fective d	Cap Asy Shop Supp 72.00  Parts List Ac Valve ( Freon Lv S Expension A/c Dryer Rapid Sea Valve Ass A/c Seal K	Parts:  n Date:  Core High Shop 2  n Valve  al Kit y Kit	07/06/2017		1.00 1.00 1.00 557.27 07/31/2017 Qty 1.00 4.00 1.00 1.00 1.00

Workorder: 1709596 Meter: 84316 Problem: P.M. service.	In Date: 10/02/2017	Closed:	10/19/2017	
- P.m. service.	Parts List		Qty	
- Performance test for misfire.replace faulty ignition coil from	5w20 Engine Oil		7.00	
cylinder # one with new.replace sixteen spark plugs and eight	Napagold Oil Filter		1.00	
ignition wires worn.  - Load test battery and recharge due to weak start.replace	Stg Wheel Cov - Ford		1.00	
failed battery for bad cell with new.	Washer Fluid Concentr		1.00	
- Perform fuel injection clean and decarb intake system	Used Fire X Refurbished		1.00	
service.	22" Wiper Blade		2.00	
- Mount new power inverter behind passenger seat	Coil		1.00	
floor.fabericate wiring and install high amp circuit breaker inline.	Spark Plug		16.00	
- Rotate and balance four tires.	Espak Plug Wire		4.00	
- Shop Supplies	Espak Plug Wire		4.00	
	Battery		1.00	
	Intake Cleaner Kit		1.00	
	Injector Cleaner		1.00	
	Napagold Oil Filter		1.00	
	Cpi 1575 Inverter 1500 W		1.00	
	Cb185-100 Cir Brkr		1.00	
	Terminal		2.00	
	Cabl/lug		4.00	
	Bulk Battery Cable			
	Bulk Battery Cable		3.00	
	Fab Loom-split Poly		12.00	
	Shop Supplies		1.00	
Hours 17.25 Labor:	1,035.0 Parts: 823.46 0	Total:	1,858.46	
Workorder: 1802134 Meter: 91457 Problem: P.M. service and check tires.	In Date: 02/27/2018	Closed:	03/06/2018	
- P.m. service.	Parts List		Qty	
- Repair electrical wire on right alley work light .	5w20 Engine Oil	8.00		
- Repair left rear tire .balance and rotate all four tires.	Napagold Oil Filter		1.00	
- Shop Supplies	22" Wiper Blade		2.00	
	Drain Plug		1.00	
	Shop Supplies		1.00	
Hours 5.25 Labor:	315.00 Parts: 32.69	Total:	347.69	

Workorder: Problem:	1806159 PM Serv		Meter: neck AC,	97723 blow cool air r	not cold.		In Date:	06/15/2018	Closed:	06/27/20	)18	
- P.m. service	€.					Parts Li	st				Qty	
				e compressor		Napago		1.00				
				n valve .evacu	ılate and	5w20 Er	ngine Oil			7.00		
recharge syst					toot	Napago		1.00				
_	<ul> <li>Diagnose work light inop .repair broken wire and retest.</li> <li>Rotate and balance all four tires. Nitrogen fill tires.</li> </ul>							ished		1.00		
- Shop Suppl		ii ioui t	iies. Mili	ogen illi tires.		22" Wipe	er Blade			2.0		
- Shop Suppi	162					Non-chlo	or Brake Clr	nr			2.00	
						Pag Oil					1.00	
						Flush So	olvent				2.00	
						Seal Kits	8				1.00	
						Seal					1.00	
						Ex Pans	1.00					
				Kit O				1.00				
						accumu	lator				1.00	
						A/c Com	-			1.00		
						A/c Dryer					1.00	
						Shop Su	ıpplies				1.00	
		Hours :	13.25		Labor:	795.00	Parts:	676.46	Total:	1,471.46	5	
Workorder:	1810868	3	Meter:	103676			In Date:	10/22/2018	Closed:	10/24/20	)18	
Problem:	remove	dept de	ecals									
- remove dec	als					Parts Li			Qty			
- Shop Suppl	ies					Shop Supplies					1.00	
		Hours :	2.00		Labor:	134.00	Parts:	3.00	Total:	137.00		
Workorder:	1810936	3	Meter:	103346			In Date:	10/24/2018	Closed:	10/24/20	018	
Problem:	Transitio	n Prep	Charge									
- Transition P	rep Char	ge										
		Hours :	2.00		Labor:	134.00	Parts:	0.00	Total:	134.00		