

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 436217		Problem: WASH VEHICLE			
Meter Reading: 0		Labor		Parts	
In Date: 02/27/2004	Close Date: 02/27/2004	Hours	Description		Quantity
- Wash Vehicle		3.10			
- Pre-Delivery Inspection					
- Make Duplicate Keys For New Vehicle					
	Parts Charge: 0.00	Labor Charge:	155.00		
Workorder: 438355		Problem: TAG CHARGE			
Meter Reading: 11		Labor		Parts	
In Date: 03/17/2004	Close Date: 03/17/2004	Hours	Description		Quantity
- Vehicle Tag			VEHICLE TAG CHARGE		1.00
	Parts Charge: 51.85	Labor Charge:	0.00		
Workorder: 446656		Problem: MAKE AND APPLY DECALS			
Meter Reading: 1587		Labor		Parts	
In Date: 06/03/2004	Close Date: 06/03/2004	Hours	Description		Quantity
- Make And Apply Decals		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	50.00		
Workorder: 535976		Problem: P.M.SERVICE			
Meter Reading: 7696		Labor		Parts	
In Date: 02/11/2005	Close Date: 02/15/2005	Hours	Description		Quantity
- Pm Service.		2.00	SHOP SUPPLIES		1.00
- Shop Supplies			AF1519 AIR FILTER USE LAF1520 FRM CA8755A		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			10W30 MOTOR OIL		5.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
	Parts Charge: 31.84	Labor Charge:	100.00		

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 636070

Problem: P.M.SERVICE

Meter Reading: 15130	Labor	Parts		
In Date: 03/21/2006	Hours	Description	Quantity	
- Pm Service	2.00	1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00	
- Shop Supplies		10W30 MOTOR OIL	5.00	
		SHOP SUPPLIES	1.00	
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00	
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00	
		WD40 SPRAY LUBE STOCK# 405540002	1.00	
		31-22 WIPER BLADES 22" WIPER BLADE	2.00	
	Parts Charge:	Labor Charge:	54.85	100.00

Workorder: 644332

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts		
In Date: 08/07/2006	Hours	Description	Quantity	
- Tiresoles Of Broward Inc				
	Parts Charge:	Labor Charge:	0.00	0.00
		Commercial Charge:		88.12

Workorder: 644333

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts		
In Date: 08/07/2006	Hours	Description	Quantity	
- Tiresoles Of Broward Inc				
	Parts Charge:	Labor Charge:	0.00	0.00
		Commercial Charge:		54.00

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 649630

Problem: P.M. SERVICE.

Meter Reading: 18689	Labor	Parts	
In Date: 12/07/2006	Hours	Description	Quantity
- Pm Service	4.00	05023 BATTERY CLEANER	1.00
- Replace And Balance Two Tires.		05046 BATTERY PROTECTOR (CRC)	1.00
- Nitrogen Fill All Tires.		10W30 MOTOR OIL	6.00
- Shop Supplies		SHOP SUPPLIES	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		773430430 235/75R16 WRANGLER ST SL	2.00
		TIRE DISPOSAL FEE	2.00
Parts Charge:	243.05	Labor Charge:	55.00

Workorder: 732518

Problem: ABS PUMP RUNNING & LIGHT ON DASH

Meter Reading: 18711	Labor	Parts	
In Date: 01/08/2007	Hours	Description	Quantity
- Pickup And Deliver To Gmc For Abs Pump	1.50	SHOP SUPPLIES	1.00
- Cran Abs Sys For Codes,Disconnect Shorted & Abs Pump And Send To Dealer For Warranty.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	27.50

Workorder: 743411

Problem: P.M. SERVICE.

Meter Reading: 21269	Labor	Parts	
In Date: 08/30/2007	Hours	Description	Quantity
- Pm Service	4.50	10020 INJECTOR CLEANER DON'T REORDER	1.00
- Transmisson Sys Flush		10W30 MOTOR OIL	6.00
- High Speed Balance 4 Tires		SYN/ATF TRANS FLUID SYNTHETIC	12.00
- Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		05046 BATTERY PROTECTOR (CRC)	1.00
Parts Charge:	109.39	Labor Charge:	55.00

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 835852

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 26421 In Date: 03/20/2008	Close Date: 03/26/2008	Labor Hours	Description	Parts	Quantity
- Pm Service		11.30	10W30 MOTOR OIL		6.00
- A/C Blower Not Working On All Speeds.Diagnose Circuits.Replace Blower Resistor.			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Battery Failed Load Test. Ck Electrical System.Charging Rate At Spec. Replace Battery.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Replace One Tire.Repair 1 Tire(Nail) High Speed Balance 4 Tires.Fill W/Nitrogen.			BLOWER RESISTOR		1.00
- Replace Both Inner Tie Rods.Loose.Lube Intermediate Steering Shaft. Noisy.			GROUP 78 BATTERY (ACD 78PS)		1.00
- Perform Complete Wheel Alignment,Test Drive.			773430430 235/75R16 WRANGLER ST SL		1.00
- Shop Supplies			INNER TIE ROD		2.00
			SHOP SUPPLIES		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			TIRE DISPOSAL FEE		1.00
Parts Charge:		406.55	Labor Charge:		150.00

Workorder: 843519

Problem: P.M SERVICE,STROBES INOP

Meter Reading: 30437 In Date: 08/29/2008	Close Date: 09/05/2008	Labor Hours	Description	Parts	Quantity
- Pm Service		3.50	6678 AIR FILTER FRM CA8755A WIX 46678		1.00
- Strobe Lamps Not Working.Diagnose Circuits.Replace Fuse In Pdc. No Short Found.			10W30 MOTOR OIL		6.00
- Rotate & High Speed Balance 4 Tires,Fill W/Nitrogen			31-22 WIPER BLADES 22" WIPER BLADE		2.00
- Shop Supplies			15319477 FUSE 30 AMP GMC		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			SHOP SUPPLIES		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
Parts Charge:		52.68	Labor Charge:		60.00

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 846181

Problem: LEFT FRONT TIRE DAMAGE BEYOND REPAIRS

Meter Reading: 31685		Labor		Parts	
In Date: 10/27/2008	Close Date: 10/29/2008	Hours	Description	Quantity	
-	Install New Tire To Left Frt Wheel,Swap & Mount New Spare Tire To Right Front & Balance 3 Tires.Seure Spare To Rack.	2.00	773430430 235/75R16 WRANGLER ST SL		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		115.89	Labor Charge:		120.00

Workorder: 935073

Problem: P.M SERVICE

Meter Reading: 34552		Labor		Parts	
In Date: 03/12/2009	Close Date: 03/16/2009	Hours	Description	Quantity	
-	Pm Service	6.50	1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
-	Mount One New Tire.Balance 4,Nitro Fill.		10W30 MOTOR OIL		6.00
-	Complete Front End Alignment,Test Drive.		SHOP SUPPLIES		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			773430430 235/75R16 WRANGLER ST SL		1.00
Parts Charge:		136.31	Labor Charge:		390.00

Workorder: 942615

Problem: P.M service

Meter Reading: 39482		Labor		Parts	
In Date: 08/27/2009	Close Date: 09/03/2009	Hours	Description	Quantity	
-	P.M Service.	11.50	BLOWER RESISTOR		1.00
-	Mount Two New Tires, Rotate & Balance All Four Tires.		SYN/ATF TRANS FLUID SYNTHETIC		16.00
-	Test Starting & Charging System, Test & Replace Battery.		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		2.00
-	Trans Flush & Filter Change.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Pressure Test & Inspect Cooling System, Flush & Renew Coolant.		31-22 WIPER BLADES 22" WIPER BLADE		2.00
-	Diagnose A/C Blower Not Blowing On All Speeds, Trace Circuit, Replace Blower Resistor & Spline In New Connector.		SHOP SUPPLIES		1.00
-	Shop Supplies		WARRANTY BATTERY		1.00
			TIRE DISPOSAL FEE		2.00
			FT1217 TRANS FILTER ATP B-165 WIX DON'T USE		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			RESISTOR PIGTAIL		1.00
			10W30 MOTOR OIL		6.00
			183407418 P235/70R16 WRANGLER SR-A 104S		2.00
Parts Charge:		559.35	Labor Charge:		690.00

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1002877

Problem: P.M service, check side mirrors.

Meter Reading: 43938	Labor	Parts	
In Date: 03/22/2010	Hours	Description	Quantity
- P.M Service.	4.20	LS94 BULB SOCKET DRIVE LIGHT (ACD)	2.00
- Test & Replace Both Front Dtrl Bulbs & Wire In New Sockets.		SHOP SUPPLIES	1.00
		DRIVER SIDE MIRROR ASSY	1.00
- Replace Broken Driver Side Mirror Assembly.		4114K BULB (ACD)	2.00
- Shop Supplies		10W30 MOTOR OIL	6.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
Parts Charge:	196.83	Labor Charge:	252.00

Workorder: 1011075

Problem: P.M. Service.See note.

Meter Reading: 49145	Labor	Parts	
In Date: 10/07/2010	Hours	Description	Quantity
- Perform Pm Service.	6.50	TIRE DISPOSAL FEE	2.00
- Fabricate And Replace Failed Driver Door Hinge Bushings With New And Secure Head Liner.		SHOP SUPPLIES	1.00
		89025539 DOOR HINGE BUSHING KIT (GMC)	1.00
- Install Two New Tires To The Front Wheels,Nitrogen Fill And Balance All Four.		10W30 MOTOR OIL	6.00
		6678 AIR FILTER FRM CA8755A WIX 46678	1.00
- Shop Supplies		183407418 P235/70R16 WRANGLER SR-A 104S	2.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		31-22 WIPER BLADES 22" WIPER BLADE	2.00
		89025539 DOOR HINGE BUSHING KIT (GMC)	2.00
Parts Charge:	515.59	Labor Charge:	390.00

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1104325

Problem: Pm service also see notes on door and strobe lights.

Meter Reading: 53921	Labor	Parts	
In Date: 04/21/2011	Hours	Description	Quantity
- Perform Pm Service.	11.25	89025539 DOOR HINGE BUSHING KIT (GMC)	2.00
- Inspect And Replace Both Failed Serpentine Belts With New..		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		1522 OIL FILTER FRM PH3675/9837 WIX 51522	1.00
- Inspect And Remove Driver Door.Replace Failed Door Hinge Bushings And Pins With New Then Align To Open And Close.		FUSE	1.00
		K040378HD A/C BELT	1.00
		SHOP SUPPLIES	1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		K060923HD SERP BELT	1.00
		TIRE DISPOSAL FEE	2.00
- Inspect For Short Ciccuit.Repair Power Wiring Through Fire Wall And Replace Open 30 Amp Fuse With New.		10W30 MOTOR OIL	6.00
		183407418 P235/70R16 WRANGLER SR-A 104S	2.00
- Perform Wheel Alignment Complete.			
- Shop Supplies			
Parts Charge: 348.65		Labor Charge: 675.00	

Workorder: 1108786

Problem: Tailgate will not latch closed.

Meter Reading: 56476	Labor	Parts	
In Date: 08/18/2011	Hours	Description	Quantity
- Diagnose Tail Gate Latch Inop.Test And Replace Failed Tail Gate Handle With New And Adjust Linkages And Striker.	1.00	TAILGATE HANDLE	1.00
		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge: 26.10		Labor Charge: 60.00	

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1110299

Problem: Pm service also check driver door and wipers.

Meter Reading: 57589		Labor		Parts	
In Date: 09/27/2011	Close Date: 09/30/2011	Hours	Description	Quantity	
-	P.M. Service.	6.50	W/WASHER PUMP		1.00
-	Remove Left Door And Replace Hinge Pins And Bushings.Replace Washer Pump.		SHOP SUPPLIES		1.00
-	Rotate And Balance All Tires.		10W30 MOTOR OIL		6.00
-	Shop Supplies		1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
			31-22 WIPER BLADES 22" WIPER BLADE		2.00
			W/WASHER BOTTLE		1.00
			89025539 DOOR HINGE BUSHING KIT (GMC)		2.00
Parts Charge: 241.11		Labor Charge: 390.00			

Workorder: 1200024

Problem: No heat on left side of dash.

Meter Reading: 59936		Labor		Parts	
In Date: 01/03/2012	Close Date: 01/09/2012	Hours	Description	Quantity	
-	Diagnose A/C Electrical System.B0408.Perform Pin Point Test.Replace Left Side Blend Door Actuator.Clear Codes And Recalibrate Mode Doors.	3.00	SHOP SUPPLIES		1.00
-	Shop Supplies		TEMP. DOOR ACTUATOR		1.00
Parts Charge: 147.29		Labor Charge: 180.00			

Workorder: 1202189

Problem: Pm service.

Meter Reading: 61719		Labor		Parts	
In Date: 03/02/2012	Close Date: 03/15/2012	Hours	Description	Quantity	
-	P.M. Service.	4.00	SHOP SUPPLIES		1.00
-	Test Battery And Charging System.Replace Bad Battery.		10W30 MOTOR OIL		6.00
-	Rotate And Balance All Tires.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Shop Supplies		GROUP 78 BATTERY (ACD 78PS)		1.00
			1522 OIL FILTER FRM PH3675/9837 WIX 51522		1.00
Parts Charge: 140.46		Labor Charge: 240.00			

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1211391

Problem: Pm service.

Meter Reading: 64852		Labor		Parts	
In Date: 11/27/2012	Close Date: 12/13/2012	Hours	Description	Quantity	
-	Perform Pm Service.	9.50	10W30 MOTOR OIL	6.00	
-	Inspect And Replace Failed Short Power Steering Rack		GEAR ASS	1.00	
	And Pinnion Assembly With New.Had To Transfer Tie		BUMP STOPERS	2.00	
	Rods.Flush And Renew Power Steering Fluid.Replace		PH3675 OIL FILTER LBF	1.00	
	Failed Rear Suspension Bump Stops With New.		USED FIREX REFURBED F	1.00	
-	Rotate And Balance All Four Tires.		SHOP SUPPLIES	1.00	
-	Perform Wheel Alignment Complete.		61A P-STEERING FLUID	2.00	
-	Shop Supplies		31-22 WIPER BLADES 22	2.00	
Parts Charge:		369.31	Labor Charge:	570.00	

Workorder: 1211874

Problem: Headliner and seat damage.

Meter Reading: 64868		Labor		Parts	
In Date: 12/07/2012	Close Date: 01/08/2013	Hours	Description	Quantity	
-	Comercial Repairs.Repairing Damage Driver Seat And Headliner At Central Auto Trim Shop.	2.00	SHOP SUPPLIES	1.00	
-	Transport Vehicle To And From Central Auto Trim Shop For Repairing Damage Driver Seat And Head Liner.				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	120.00	Commercial Charge: 346.57

Workorder: 1301331

Problem: Right turnsignal and brake lamps inop.

Meter Reading: 65746		Labor		Parts	
In Date: 02/06/2013	Close Date: 02/08/2013	Hours	Description	Quantity	
-	Test And Replace Failed Right Brake Lamp Assembly With New.Fabricate New Lamp To Access And Install Strobe Lamp Bulb And Secure.	1.00	MINIATURE BULB	2.00	
			LAMP	1.00	
			SHOP SUPPLIES	1.00	
-	Shop Supplies		JB WELD KWIK WELD	1.00	
Parts Charge:		172.47	Labor Charge:	60.00	

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1306281

Problem: P.M. Service.

Meter Reading: 67275		Labor		Parts	
In Date: 06/24/2013	Close Date: 07/10/2013	Hours	Description	Quantity	
-	P.M. Service.	6.50	PADS		1.00
-	Resurface Rear Brake Rotors,Replace Rear Pads.Service And Lube Caliper.Flush And Bleed System And Test Drive.		BRAKE CLEANER		1.00
			REMAN BRAKE CALIPER		1.00
			REMAN BRAKE CALIPER		1.00
-	Rotate And Balance All Tires.		SHOP SUPPLIES		1.00
-	Shop Supplies		WIPER BLADE		2.00
			10W30 MOTOR OIL		6.00
			PH3675 OIL FILTER LBF		1.00
			REMAN BRAKE CALIPER		1.00
			REMAN BRAKE CALIPER		1.00
Parts Charge: 200.49		Labor Charge: 390.00			

Workorder: 1307262

Problem: Transition Prep Charge

Meter Reading: 67275		Labor		Parts	
In Date: 07/22/2013	Close Date: 07/22/2013	Hours	Description	Quantity	
-	Transition Prep Charge	2.00			
Parts Charge: 0.00		Labor Charge: 120.00			

Workorder: 1308647

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 67320		Labor		Parts	
In Date: 08/27/2013	Close Date: 08/27/2013	Hours	Description	Quantity	
-	1 - Detail Vehicle Wash Ticket(S) Issued				
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 97.92	

Workorder: 1401609

Problem: trailer plug not working

Meter Reading: 70177		Labor		Parts	
In Date: 02/19/2014	Close Date: 02/19/2014	Hours	Description	Quantity	
-	Repair Wire Harness For Trailer Plug	2.00			
Parts Charge: 0.00		Labor Charge: 120.00			

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1407073

Problem: pm

Meter Reading: 73515		Labor		Parts	
In Date: 07/17/2014	Close Date: 08/12/2014	Hours	Description	Quantity	
-	Pm	3.50	NAPAGOLD AIR FILTER		1.00
-	Replace 2 Tires Mount Balance Add N2		TIRE DISPOSAL FEE		2.00
			NAPAGOLD OIL FILTER		1.00
			10W30 BULK SR		6.00
			WIPER BLADE		2.00
			WASHER FL		1.00
			183407418 P235-70R16		2.00
Parts Charge: 435.29		Labor Charge: 210.00			

Workorder: 1500358

Problem: Check lights.

Meter Reading: 76546		Labor		Parts	
In Date: 01/12/2015	Close Date:	Hours	Description	Quantity	
-					
Parts Charge: 0.00		Labor Charge: 0.00			

Workorder: 1500616

Problem: P.M.SERVICE/ BATTERY

Meter Reading: 76607		Labor		Parts	
In Date: 01/16/2015	Close Date: 01/22/2015	Hours	Description	Quantity	
-	Pm	5.75	WASHER FL		1.00
-	Recharge And Ck Battery Replace Bad Battery		USED FIRE X REFURBISHED		1.00
-	Replace Both Rear Tires And Rotate To The Front		183407418 P235-70R16		2.00
-	Remove And Repair Leaking Washer Bottle Hose		BATTERY		1.00
-	Fill All Tires With Nitrogen		TIRE DISPOSAL FEE		2.00
			NAPAGOLD OIL FILTER		1.00
			10W30 BULK SR		6.00
Parts Charge: 542.32		Labor Charge: 345.00			

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1504529 **Problem:** p.m.service/no start

Meter Reading: 78507	Labor	Parts	
In Date: 05/04/2015	Hours	Description	
Close Date: 05/26/2015		Quantity	
- Pm	5.75	NAPAGOLD OIL FILTER	1.00
- Verify Left Rear Tail Light Out Replace Tail Light Bulb		10W30 BULK SR	6.00
- Wont Start Verify Dead Battery Recharge Battery Test		BULB	1.00
- Good Ck Charging Sys Found Bad Ign Switch		STG WHEEL COV - FORD	1.00
- Install Steering Wheel Cover		STG WHEEL COV - CHEVY	1.00
- Wont Start Verify Ign Staying On Replace Ignition		LOCK CYL	1.00
		RE-KEY LOCK	1.00
Parts Charge: 160.13		Labor Charge: 345.00	

Workorder: 1507207 **Problem:** PM

Meter Reading: 79103	Labor	Parts	
In Date: 07/20/2015	Hours	Description	
Close Date: 07/22/2015		Quantity	
- Pm	3.00	NAPAGOLD OIL FILTER	1.00
- Clean		10W30 BULK SR	6.00
Parts Charge: 22.08		Labor Charge: 180.00	

Workorder: 1512729 **Problem:** brake light out

Meter Reading: 82710	Labor	Parts	
In Date: 12/17/2015	Hours	Description	
Close Date: 12/29/2015		Quantity	
- Repair Rr Brake Light	0.50	BULB	1.00
Parts Charge: 0.75		Labor Charge: 30.00	

Workorder: 1600842 **Problem:** flat tire

Meter Reading: 83735	Labor	Parts	
In Date: 01/26/2016	Hours	Description	
Close Date: 01/28/2016		Quantity	
- Flat Tire Side Wall Damage Unable To Repair Replace Fr Tire	1.00	183407418 P235-70R16	1.00
		TIRE DISPOSAL FEE	1.00
Parts Charge: 198.94		Labor Charge: 60.00	

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1601898

Problem: PM

Meter Reading: 84585		Labor		Parts	
In Date: 02/23/2016	Close Date: 02/29/2016	Hours	Description	Quantity	
- Pm		8.50	USED FIRE X REFURBISHED		1.00
- Replace Both Front Running Light Socket And Replace Marker Light Bulbs			22" WIPER BLADE		2.00
			NAPAGOLD OIL FILTER		1.00
- Resurface Front Rotors Svc Calipers And Replac Epads			PIGTAILS SOCKETS		3.00
- Replace Wind Shield Washer Pump			LAMP		2.00
			W S WASH		1.00
			BULB		2.00
			BULB		2.00
			DISC BRAKE PADS		1.00
			WASHER FLUID CONCENTR		1.00
			10W30 BULK SR		6.00
			BULB		2.00
			LIGHT SOCKET		1.00
Parts Charge: 172.07		Labor Charge: 510.00			

Workorder: 1604401

Problem: Right rear tire flat.

Meter Reading: 85628		Labor		Parts	
In Date: 04/27/2016	Close Date: 04/29/2016	Hours	Description	Quantity	
- Repair And Balance Right Rear Tire.		1.00			
Parts Charge: 0.00		Labor Charge: 60.00			

Workorder: 1606998

Problem: 2 - Key(s) issued

Meter Reading: 87004		Labor		Parts	
In Date: 07/12/2016	Close Date: 07/12/2016	Hours	Description	Quantity	
- 2 - Key(S) Issued		0.60	DUPLICATE VEHICLE KEYS		2.00
Parts Charge: 6.00		Labor Charge: 36.00			

1/3/2017
12:17:41PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155203 2004 GMC 1500 Pickup, 1/2 Ton, W/Strobe System, V8

Workorder: 1611520

Problem: Transition Prep Charge

Meter Reading: 87629

Labor

Parts

In Date: 11/08/2016

Close Date: 11/08/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **5,663.64**

Total Labor Charges: **7,295.50**

Total Comm. Charges: **586.61**