10179596 2010 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Problem: Pre Delivery Inspection - Pre Delivery Inspection Hours 4.00 Education: Hours 6.50 Education: Hours 6	/14/2010	0	Closed:	07/12/2010	Date:	I		375	Meter: IVER	1007310 I FLASH CANCEI	
Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.01	Q					Parts List				eiver	- Reflash Can
Workorder: 1007322 Meter: 0 In Date: 07/13/2010 Closed: 07/7 Problem: Pre Delivery Inspection	1.0				ies	Shop Supp				S	- Shop Supplie
Problem: Pre Delivery Inspection - Pre Delivery Inspection Hours 4.00 Eabor: 240.00 Parts: 0.00 Total: 240 Workorder: 1101035 Meter: 4895 Problem: P.M. Service.Install vise. Parts Only (send to He Shop) Inspect and service crane. Rotate and balance all tires. Rotate and balance all tires. Rotate and balance all tires. Shop Supplies Rotate and balance all tires. Rotate Filter Frm Cs10263a Wix 33963 L0135-063 Lubriplate Chain&cable Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers Royolblk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Labor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 In Date: 02/03/2011 Closed: 02/04 Rotate	00	6	Total:	2.00	Parts:	60.00	Labor:		1.00	Hours :	
Workorder: 1101035 Meter: 4895 Problem: P.M. Service. Install vise. - Parts Clist Problem: P.M. Service orane Parts and balance all tires Shop Supplies - Shop Supplies - Shop Supplies - Rotate and balance all tires Shop Supplies - Shop Supplies - Shop Supplies - Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise - In Date: 01/27/2011 Closed: 02/0 Parts List - 101/27/2011 Closed: 02/0 Parts List - 01/27/2011 Closed: 02/0 Parts List - 101/27/2011 Closed: 02/0 Parts List - Shop Supplies	/13/2010	0	Closed:	07/13/2010	Date:	lı		0			
Workorder: 1101035 Meter: 4895 In Date: 01/27/2011 Closed: 02/07/2019 Problem: P.M. Service. Parts only(send to He Shop) Pm-22-a Additive Diesel Fuel (m/craft) Shop Supplies Shop Supplies Parts early literary Pm-22-a Additive Diesel Fuel (m/craft) Pm-22-a Additive Diesel Fuel (m/craft) Shop Supplies Pm-22-a Additive Diesel Fuel (m/craft) Pm-22-a Additive Diesel Fuel										nspection	- Pre Delivery
Problem: P.M. Service. - P.m. Service. - Parts only(send to He Shop) - Inspect and service crane. - Rotate and balance all tires. - Shop Supplies - Rotate and balance all tires. - Shop Supplies - Shop Supplies - Pm-22-a Additive Diesel Fuel (m/craft) - Shop Supplies - In Date: 02/03/2011 - Parts List - Fab / weld mounting bracket for vise - Shop Supplies - Parts List - Shop Supplies -	0.00	. 2	Total:	0.00	Parts:	240.00	Labor:		4.00	Hours 4	
Parts only(send to He Shop) Inspect and service crane. Rotate and balance all tires. Shop Supplies Pm-22-a Additive Diesel Fuel (m/craft) Shop Supplies Pilter Frm Ch9549 Wix 57312 Shop Supplies Pin Date: 02/03/2011 Closed: 02/05/2019 Shop Supplies Shop Supplies	/07/2011	0	Closed:	01/27/2011	Date:	lı		4895			
- Inspect and service crane Rotate and balance all tires Shop Supplies - Total: 962 - Shop Supplies - Rotate and balance all tires Rotate and balance all tires Total: 963 - Shop Supplies - Total: 962 - Shop Supplies - Shop Supplies - Shop Supplies	Q		Parts List								- P.m. Service
- Rotate and balance all tires. - Shop Supplies 3963 Fuel Filter Frm Cs10263a Wix 33963 L0135-063 Lubriplate Chain&cable Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Eabor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise 7312 Oil Filterfrm Ch9549 Wix 57312 3963 Fuel Filter Frm Cs10263a Wix 33963 L0135-063 Lubriplate Chain&cable Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Formula Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Fred Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 7090blk Frt Floor Mats (rubber Queen) 7090blk Frt Floor Mats (rubber Queen) 7090blk Frt	1.0		Pm-22-a Additive Diesel Fuel (m/craft)							nd to He Shop)	- Parts only(se
- Shop Supplies 3963 Fuel Filter Frm Cs10263a Wix 33963 L0135-063 Lubriplate Chain&cable Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Eabor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise Shop Supplies	1.0		Shop Supplies							ervice crane.	- Inspect and
L0135-063 Lubriplate Chain&cable Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Labor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise Parts List Shop Supplies	1.0		'312	h9549 Wix 57	terfrm C	7312 Oil F				alance all tires.	- Rotate and b
Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Labor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise Lube,03050crc 15/40 Oil Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) In Date: 02/03/2011 Closed: 02/03/2011 Parts List Shop Supplies	1.0	1	Nix 33963	m Cs10263a	Filter Fr	3963 Fue				S	- Shop Supplie
Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 Labor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise Used Firex Refurbed Fire Extingshers 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) In Date: 02/03/2011 Closed: 02/0 Parts List Shop Supplies	1.0		;	e Chain&cable							
7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) Hours 6.50 : Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise 7090blk Frt Floor Mats (rubber Queen) 66997 Combo Vise (rigid F-60) 1000 Parts: 572.31 Total: 962 In Date: 02/03/2011 Closed: 02/03 Parts List Shop Supplies	15.0					15/40 Oil					
Workorder: 1101352 Meter: 4895 Problem: install vise Meter: 4895 Problem: oscillation of the control of the co	1.0		ers	d Fire Extingsh	Refurbe	Used Fire					
Hours 6.50 Eabor: 390.00 Parts: 572.31 Total: 962 Workorder: 1101352 Meter: 4895 Problem: install vise - mount vise - fab / weld mounting bracket for vise Labor: 390.00 Parts: 572.31 Total: 962 In Date: 02/03/2011 Closed: 02/0 Parts List Shop Supplies	1.0		een)	ats (rubber Qu	Floor Ma	7090blk Fi					
: Workorder: 1101352 Meter: 4895 In Date: 02/03/2011 Closed: 02/0 Problem: install vise - mount vise Parts List - fab / weld mounting bracket for vise Shop Supplies	1.0			(rigid F-60)	bo Vise	66997 Cor					
Problem: install vise - mount vise - fab / weld mounting bracket for vise Parts List Shop Supplies	2.31	9	Total:	572.31	Parts:	390.00	Labor:		6.50	Hours (
- fab / weld mounting bracket for vise Shop Supplies	/04/2011	0	Closed:	02/03/2011	Date:	lı		4895	Meter:		
	Q					Parts List					- mount vise
	1.0				ies	Shop Supp			for vise	unting bracket fo	- fab / weld mo
- Shop Supplies 1/4x2x20 Steel Flat Bar	8.0			Bar	eel Flat	1/4x2x20				S	- Shop Supplie

Labor: 270.00

Parts: 12.27

Total: 282.27

Hours 4.50

Workorder: 1109295 Meter: 10348 Problem: P. M. SERVICE	In Date: 08/31/2011 Closed: 09/12/2011
- Performed P.m.	Parts List Qty
- Performed crane P.m.	13 Oz. Aero Kroil Aerosol Spray 1.00
- Repaired rear triple light assy.	Shop Supplies 1.00
- Unsiezed & lubed vise and hitch assy.	1259 Hydr Filter Lbf Frm P1653a Wix 51259 1.00
- Retightened body hold down.	7312 Oil Filterfrm Ch9549 Wix 57312 1.00
- Tire repair L/rear	3963 Fuel Filter Frm Cs10263a Wix 33963 1.00
- Unsiezed & lubed outrigger pins & extentions.	Ca10270 Air Filter Mtc Fa1886 Wix 49886 1.00
- Shop Supplies	15/40 Oil 16.00
	31-22 Wiper Blades 22" Wiper Blade 2.00
Hours 12.50 Labor:	750.00 Parts: 154.40 Total: 904.40
Workorder: 1202430 Meter: 15694 Problem: P.M. service.	In Date: 03/12/2012 Closed: 03/27/2012
- P.m. Service.	Parts List Qty
- Inspect and service crane.	Shop Supplies 1.00
- Replace and balance six tires.	7312 Oil Filterfrm Ch9549 Wix 57312 1.00
- Replace missing pintle pin.	3963 Fuel Filter Frm Cs10263a Wix 33963 1.00
- Replace camber/caster adjustment cam on both	Ca10270 Air Filter Mtc Fa1886 Wix 49886 1.00
sides.perform complete wheel alignment and test drive.	1259 Hydr Filter Lbf Frm P1653a Wix 51259 1.00
- Shop Supplies	Aw68 Hydro Fluid Hydraulic Oil 68 5.00
	15/40 Oil 16.00
	Used Firex Refurbed Fire Extingshers 1.00
	31-22 Wiper Blades 22" Wiper Blade 2.00
	Caster/ Camber Cams 2.00
	179636492 Lt245/75r17 Wrangler Sr-a E 6.00
	Tr416 Valve Stem 6.00
	Tire Disposal Fee 6.00
Haura 12 00	18410 Pintle Pin 1.00
Hours 12.00 Labor:	720.00 Parts: 1,364.21 Total: 2,084.21
Workorder: 1208146 Meter: 19340 Problem: P.M. service and install computer stand and rur	In Date: 08/29/2012 Closed: 09/28/2012 ns rough.
- P.m. Service.	Parts List Qty
- Test and replace five failed leds. in light bar.	Shop Supplies 1.00
- Inspect and service crane.	1259 Hydr Filter Lbf Frm P1653a Wix 51259 1.00
- Install costomer supplied computer stand.	7312 Oil Filterfrm Ch9549 Wix 57312 1.00
- Rotate and balance all six tires	3963 Fuel Filter Frm Cs10263a Wix 33963 1.00
- Shop Supplies	Aw68 Hydro Fluid Hydraulic Oil 68 4.00
5op - app5	15/40 Oil 15.00
	31-22 Wiper Blades 22" Wiper Blade 2.00
	31-22 Wiper Blades 22" Wiper Blade 2.00

Workorder: 1302762 Meter: 23277		lı	n Date:	03/20/2013	Closed:	03/28/2013
Problem: P.M. service and has to jump start in A/m.						
- Perform pm service.		Parts List				Qty
- Test starting and charging system.both batteries failed		15-40 Oil				15.00
loadtest after recharge.replace both failed batteries with n	new.	Napagold	Oil Filter			1.00
 Install new rear brake pads and resurface both rear rotors.service calipers and flush brake fluid.automated ble 	haa	31-22 Wip	er Blades	s 22		2.00
hydraulic system with scan tool.	ccu	3c3z9a343	Ba Seal	Kit		1.00
- Inspect and service hydraulic crane.		Used Firex	Refurbe	ed F		1.00
- Rotate and balance all six tires.		Battery 65				2.00
- Shop Supplies		Brake Pad				1.00
		1401 Brak				1.00
		Hydraulic I				1.00
		Aw68 Hyd		-		4.00
		Napagold		er		1.00
Hours 12.75 La	shor:	Shop Supp 765.00		486.35	Total	1.00
Hours 12.75 La	abor.	765.00	raits.	400.33	TOtal.	1,251.35
Workorder: 1306687 Meter: 26720 Problem: driver side rear tire flat		lt	n Date:	07/03/2013	Closed:	07/12/2013
- replace right rear outer tire damaged side wall		Parts List				Qty
- Shop Supplies		179636492	2 Lt245-7	75r17		1.00
		Shop Supp		1.00		
		Tire Dispos	sal Fee			1.00
Hours 1.00 La	abor:	60.00	Parts:	249.03	Total:	309.03
Workorder: 1308423 Meter: 28218		lı	n Date:	08/21/2013	Closed:	09/06/2013
Problem: P.M. service and check engine light on.						
- Perform pm service.		Parts List				Qty
 Install five new tires to wheels.nitrogen fill and balance six. 	all	Napagold	Oil Filter			1.00
- Inspect and service hydraulic crane.		15-40 Oil	15.00			
 Pressure test and inspect cooling system.replace failed 	l	Napagold	1.00			
radiator assembly,upper and lower radiator hoses with	-	Wiper Blace 179636492	2.00			
new.reverse flush and renew engine coolant.		Napa Tran	5.00 1.00			
- Perform wheel alignment complete.		Aw68 Hyd	10.00			
- Test and replace failed third brake lamp bulb with new.		Radiator	1.00			
 Computer diagnose for check engine light on.perform P software update aspertsb.clear codes with scan tool and 	cm	Top Radia	tor Hose			1.00
roadtest.		lower hose		1.00		
- Shop Supplies		Radiator H	lose		1.00	
		Coolant Fo	ord Gold			3.00
		Shop Supp	olies			1.00
		Tire Dispos				5.00
Hours 17.50 La	1,050.0	Parts:	2,520.29	Total:	3,570.29	

Workorder: Problem:	1312337 wont fuel	Meter:	31753			In Date:	12/11/2013	Closed:	12/18/2013
 - Ck Canceiver mileage error-remove canceiver and issue fuel card - Shop Supplies 					Parts Li Shop Su		Qty 1.00		
	Hours :	1.00		Labor:	60.00	Parts:	2.00	Total:	62.00
Workorder: Problem:	1312774 Towed in for br	Meter: ake fluid l	32181 ost.			In Date:	12/23/2013	Closed:	12/31/2013
 Replace both failed rear brake calipers and rotors with new.install new rear brake pads and both rear axle seals.flush brake fluid and bleed hydraulic system. Shop Supplies 					Parts Li Washer Brake P Brake R Brake C Brake C Napa O	ad otor aliper aliper			Qty 4.00 1.00 2.00 1.00 2.00
					Shop Su				1.00
	Hours :	6.50		Labor:	390.00	Parts:	589.28	Total:	979.28
	leaking brake fl 044 sw 1st dr b Hours	oca To: l	shop	Labor:	0.00	Parts:	0.00	Total:	0.00
	1403219 P.M. service ar		35535 nt headlight	inop.		In Date:	04/02/2014	Closed:	04/15/2014
Iamp assembly - Inspect and s hose under cra Also install nev - Replace brok	th bar and replay with new warra service hydrauling ane with new.replay hitch pindel pinden vise on rear	anty part. c crane.re blace brok n. bumper v	place failed l en switch wi	hydraulic	Fuel Filt Napago Wiper B Used Fi Aw68 H Napa Hy Pintle P hyd hos sb fitting Stg Whe 66997 C Switch	Dil Id Oil Filter er Ford Onl Id Air Filter lade re X Refurb ydro Fluid H ydraulic Filti in W/chain	ished Hydr r ord Rigid		15.00 1.00 1.00 1.00 2.00 1.00 1.00 1.00 1
	Hours	10.50		Labor:	Shop St 630.00		929.38	Total:	1.00 1,559.38

1404373 35535 In Date: Workorder: Meter: 04/16/2014 Closed: 05/07/2014 Problem: damage to rgt frt fender, hood, frt bumper, headlight bezel & rear bumper - damage to rgt frt fender, hood, frt bumper, headight bezel & rear bumper Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1409922 Meter: 40713 In Date: 10/02/2014 Closed: 10/14/2014 Problem: Pm service. Vice broken. - Pm service. **Parts List** Qty - Replace broken vise and secure to rear bumper.replace 15-40 Oil 15.00 broken hitch safety pindel pin. Napagold Oil Filter 1.00 - Replace front brake pads and both front calipers.resurface Fuel Filter Ford Only 1.00 front rotors.bleed system and road test. Wiper Blade 2.00 - Replace and balance six tires 66997 Combo Vise Rigid 1.00 - Replace broken clearance light bar above rear Reman Brake Caliper 1.00 bumper.fabricate wiring for power and ground. Reman Brake Caliper 1.00 - Inspect and service crane. **Brake Pads** 1.00 - Check starting and charging system.both batteries failed loadtest.replace both defective batteries. 1401 Brake Fluid Bra 1.00 - Complete front end alignment.and road test. 179636492 Lt245-75r17 6.00 - Shop Supplies 6 Inch Id Bar Kit 1.00 Napa Trans Filter 1.00 Pintle Pin W/chain 1.00 Battery 65 2.00 **Shop Supplies** 1.00 Tire Disposal Fee 6.00 Labor: 1,185.0 Hours 19.75 Parts: 2,910.77 Total: 4,095.77 0 Workorder: 1410429 Meter: 40714 In Date: 10/17/2014 Closed: 10/21/2014 Problem: bumper brackets

- fabricate brackets to hold bumper and weld **Parts List** Qty 1.00

- Shop Supplies Shop Supplies

> Hours 3.00 Labor: 180.00 Parts: 2.00 Total: 182.00

Workorder: 1503 Problem: Pm s		leter: 46344 r blades.	ļ	In Date:	04/17/2015	Closed:	04/30/2015
- Pm service.				Parts List			Qt
- Inspect and servic	e crane.			15-40 Oil			15.0
- Test and replace of	defective left	headlamp sea	al beam.	Napagold Oil Filter			1.0
- Inspect and replac				Fuel Filter Ford On	ly		1.0
mounts/insulators be				Wiper Blade			2.0
 Service transmissi 			nsmission fluid.	Napa Hydraulic Filt	r		1.0
- Rotate and balanc	e all six tires	S.		Halogen Lamp			1.0
- Shop Supplies				Syn-atf Trans Fluid	S		20.0
				Used Fire X Refurb	ished		1.0
				Insulator			2.0
				Insulator			2.0
				Bolt			6.0
				Aw68 Hydro Fluid I	Hydr		8.0
				Stg Wheel Cov - Fo	ord		1.0
				Shop Supplies			1.0
	Hours 1 ^r	1.00	Labor:	660.00 Parts:	535.00	Total:	1,195.00
Workorder: 1508 Problem: 1 - Ke		leter: 50857	,	In Date:	08/18/2015	Closed:	08/18/2015
- 1 - Key(s) issued				Doute Liet			Qt
• ()				Parts List			QI
				Duplicate Vehicle k	(eys		1.0
• • • • • • • • • • • • • • • • • • • •	Hours 0.	.30	Labor:	Duplicate Vehicle k	Keys 3.00	Total:	
Workorder: 1508	: 666 M	leter: 52750)	Duplicate Vehicle k	3.00	Total:	1.0
Workorder: 1508 Problem: P.M.	: 666 M	leter: 52750)	Duplicate Vehicle k 18.00 Parts:	3.00		21.00
Norkorder: 1508 Problem: P.M Pm service Replace rear brake	: 666 M service and e pads and r	leter: 52750 left front utility esurface rear) door will not cl	Duplicate Vehicle Marts: In Date: ose and water leak a	3.00		1.0 21.00 10/13/2015
Norkorder: 1508 Problem: P.M. - Pm service. - Replace rear brake ear calipers and flus	: 666 M service and e pads and resh brake fluic	leter: 52750 left front utility esurface rear d.	o door will not cl	Duplicate Vehicle k 18.00 Parts: In Date: ose and water leak a	3.00		1.0 21.00 10/13/2015 Qt
Norkorder: 1508 Problem: P.M Pm service Replace rear brakerear calipers and flusters.	: 666 M service and e pads and resh brake fluice both defec	leter: 52750 left front utility esurface rear d.	o door will not cl	Duplicate Vehicle Marts: In Date: ose and water leak at Parts List 15-40 Oil	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0
Workorder: 1508 Problem: P.M Pm service Replace rear brakerear calipers and flustereplace steering dangers.	: 666 M service and e pads and r sh brake fluice both defect pper.	leter: 52750 left front utility resurface rear d. ctive front show	o door will not cl rotors.service cks.also	In Date: ose and water leak a Parts List 15-40 Oil Napagold Oil Filter	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0
Workorder: 1508 Problem: P.M Pm service Replace rear brakerear calipers and fluster called the complete steering danter can be serviced.	: 666 M service and e pads and resh brake fluice e both defect nper. e lifting device	leter: 52750 left front utility resurface rear d. ctive front shocked ce crane.clear	o door will not cl rotors.service cks.also	Duplicate Vehicle Managold Oil Filter Duplicate Vehicle Managold Vehicle Managold Oil Filter Duplicate Vehicle Managold Veh	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0
Norkorder: 1508 Problem: P.M Pm service Replace rear brake ear calipers and fluster land replace steering dance are last of the compartments. Fabric compartments.	: 666 M service and e pads and resh brake fluid te both defect nper. e lifting devicting leaking v	leter: 52750 left front utility resurface rear d. ctive front shocked crane.clear water in	rotors.service cks.also	Duplicate Vehicle Marks: In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0
Workorder: 1508 Problem: P.M Pm service Replace rear brakerear calipers and fluster calipers and replace steering danter call and service case of crane mount compartments.fabrication door.	: 666 M service and e pads and resh brake fluid e both defect onper. e lifting devicting leaking verate and make	leter: 52750 left front utility resurface rear d. ctive front shocked ce crane.clear water in ke missing stri	rotors.service cks.also	Duplicate Vehicle Marks: In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0
Norkorder: 1508 Problem: P.M Pm service Replace rear braker calipers and fluster calipers and replace steering danter language of crane mount compartments.fabrication door Replace two tires.	: 666 M service and e pads and resh brake fluid te both defect nper. e lifting device ting leaking verate and make	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in ke missing stri alance all six.	rotors.service cks.also and reseal	In Date: In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0
Norkorder: 1508 Problem: P.M Pm service Replace rear brake ear calipers and fluster to the compact and service to the compa	: 666 M service and e pads and resh brake fluid te both defect the lifting devicting leaking vertex and make	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: In Date: ose and water leak a Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet	3.00 08/31/2015 at crane base. by entr Shoc		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0
Norkorder: 1508 Problem: P.M Pm service Replace rear brake ear calipers and flusteners and replace steering danteners of crane mount compartments.fabrication door Replace two tires.fabrications are place two tires.fabrications are placed two tires.fabrications are placed to the problem in the problem i	: 666 M service and e pads and resh brake fluid te both defect the lifting device ting leaking weate and make rotate and barrinspect and to corners ar	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: In Date: ose and water leak at the parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer	3.00 08/31/2015 at crane base.		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0
Norkorder: 1508 Problem: P.M Pm service Replace rear brakerear calipers and fluster and replace steering danter and service base of crane mount compartments.fabrication door Replace two tires.in a property lamps.two sight Led brake lamps.	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet S Steering Stabilizer Napa Hydraulic Filt	3.00 08/31/2015 at crane base. By entr Shoc r 75r17		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 1.0
Norkorder: 1508 Problem: P.M. - Pm service. - Replace rear brake ear calipers and flusted and replace steering danselected and service case of crane mount compartments.fabrication door. - Replace two tires.fabrication door. - Dismantle light base emergency lamps.two ight Led brake lampers.	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: In Date: ose and water leak at the parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer Napa Hydraulic Filt 179636492 Lt245-7	3.00 08/31/2015 at crane base. ly entr Shoc r 75r17		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 2.0
Norkorder: 1508 Problem: P.M. - Pm service. - Replace rear brake ear calipers and flusted and replace steering danselected and service case of crane mount compartments.fabrication door. - Replace two tires.fabrication door. - Dismantle light base emergency lamps.two ight Led brake lampers.	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer Napa Hydraulic Filt 179636492 Lt245-7 44202r Tail Light 4i	3.00 08/31/2015 at crane base. By entr Shoc r 75r17		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0
Workorder: 1508 Problem: P.M. - Pm service. - Replace rear brakerear calipers and flusterelace steering danseled as of crane mount compartments.fabrication door. - Replace two tires.fabrication door. - Dismantle light basemergency lamps.two in the compartments.fabrication door. - Perform front end	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: Ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer Napa Hydraulic Filter 179636492 Lt245-744202r Tail Light 4it Corner Led Module	3.00 08/31/2015 at crane base. ly entr Shoc r 75r17 n		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0 3.0
Norkorder: 1508 Problem: P.M. - Pm service. - Replace rear brake ear calipers and flusted and replace steering danselected and service case of crane mount compartments.fabrication door. - Replace two tires.fabrication door. - Dismantle light base emergency lamps.two ight Led brake lampers.	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer Napa Hydraulic Filte 179636492 Lt245-744202r Tail Light 4ic Corner Led Module Linear Strobe Modu Clr Rtv Silcn Seala	3.00 08/31/2015 at crane base. ly entr Shoc r 75r17 n		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0 3.0 2.0
Workorder: 1508 Problem: P.M. - Pm service. - Replace rear brakerear calipers and flus	: 666 M service and e pads and resh brake fluice e both defect onper. e lifting device ting leaking verate and make rotate and barrinspect and roto corners are	leter: 52750 left front utility resurface rear d. ctive front shock ce crane.clear water in the missing stri alance all six. d replace defer	rotors.service cks.also and reseal ker for left front	In Date: Ose and water leak at Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford On Wiper Blade Washer Fluid Cond Brake Pad Gas Grande Fleet Steering Stabilizer Napa Hydraulic Filt 179636492 Lt245-7 44202r Tail Light 4i Corner Led Module Linear Strobe Module	3.00 08/31/2015 at crane base. ly entr Shoc r 75r17 n		1.0 21.00 10/13/2015 Qt 15.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0 3.0 2.0 1.0

Workorder: Problem:	1603504 P.m. service.	Meter:	56022			In Date:	04/04/2016	Closed:	04/15/2016
- P.m. Service).			Parts Li	st			Qt	
- Inspect and	service crane.			15-40 C	Dil			15.00	
- Replace fou	r tires,rotate ar	nd balance	all six.		Napagol	d Oil Filter			1.00
- Shop Suppli	es				Fuel Filt	er Ford Onl	ly		1.00
					Led Sup	Mdl 44 42	Dio		1.00
					Napagol	d Air Filter			1.00
					. •	nain Cable	Lube		1.00
					1796364	92 Lt245-7	′5r17		4.00
					Napa Hy	draulic Filt	r		1.00
					Seal Kit				1.00
						/dro Fluid H	Hvdr		4.00
					Shop Su		.,		1.00
					•	osal Fee			4.00
	Houi	rs 7.50		Labor:	450.00		1,316.55	Total:	1,766.55
Workorder: Problem:	1610212 P.M. Service.	Meter: Dead batte	59170 ery.			In Date:	09/29/2016	Closed:	10/20/2016
- P.m. Service).				Parts Li	Qt			
	t and inspect				75w140	6.00			
upper radiator bypass.flush a			olant reservi	or and	Non-chlo		2.00		
• •		•			Egr Coo	1.00			
•	service rear di		anlaga hath k	acttorico	Degass	1.00			
	s and charging service crane.		epiace both t	Janenes.	Top Rac	1.00			
					Coolant	1.00			
- Replace left	•	4:			Halogen	1.00			
	oalance all six	tires.			Aw68 Hy		5.00		
- Shop Suppli	es				Napagol	d Oil Filter			1.00
					15-40 C)il			15.00
					20" Wipe	er Blade			2.00
					Fuel Filt	er Ford Onl	ly		1.00
						Ford Gold	•		3.00
					1at Synd	gear Oil 75-	.90		5.00
					Battery	,			2.00
					•	e Spray 12	07		1.00
					-	draulic Filt			1.00
					Shop Su		•		1.00
	Houi :	rs 15.00		Labor:	900.00		966.85	Total:	1,866.85
Workorder: Problem:	1613113 Washer inop.	Meter:	61297			In Date:	12/28/2016	Closed:	01/03/2017
- Replace bro	ken washer no	zzles.(p.m	. Service not	t due at	Parts Li	st			Qt
this time)		(Washer				2.00
Hours 0.50 Labor:							15.33	Total	45.33

Workorder: Problem:	1700216 Crane inop.	Meter:	61552			In Date:	01/09/2017	Closed:	03/20/201	17
- Diagnose in	op crane,turnta	ble gear,p	ins and bolts	sheared	Parts Li	st				Qty
off.r&r and diss-assemble crane and replace turntable						nt Base				1.00
	bleed hydraulio	c system.			Lock Nu	t				1.00
- Shop Suppli	es				Dowel P	in			;	3.00
					washer				;	3.00
					Screw				;	3.00
					Clr Rtv S	Silcn Sealan	nt			2.00
					Shop Su	pplies				1.00
					Freight (Charge				1.00
	Hours :	s 18.00		Labor:	1,080.0 0	Parts:	935.76	Total:	2,015.76	
Workorder: Problem:	1701114 repair chipped	Meter: I windshei	61297 ld			In Date:	02/02/2017	Closed:	02/14/201	7
- Set up repai	rs for windshiel	ld			Parts Li	st				Qty
- Shop Suppli	es				Shop Su	pplies				1.00
		s 1.00		Labor:	-	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1711304 P.M. service.	Meter:	61844			In Date:	11/16/2017	Closed:	11/29/201	17
- P.m. service) .				Parts Li	st				Qty
- Inspect and	service hoisting	g device,c	rane.		Napa Hy	draulic Filtr			•	1.00
- Rotate and I	high speed bala	ance all six	wheels.nitro	o fill	1cart Pa	lladium 2 G	rs		•	1.00
- Shop Suppli	es				15-40 C	Dil			19	5.00
					Napagol	d Oil Filter			•	1.00
					Fuel Filte	er Ford Only	y		•	1.00
					22" Wipe	er Blade			2	2.00
					Used Fir	e X Refurbi	shed			1.00
					ridgid vis	se handle			•	1.00
					Shop Su	pplies				1.00
	Hours :	s 6.50		Labor:	390.00	Parts:	241.87	Total:	631.87	
Workorder: Problem:	1711615 vise handle	Meter:	61658			In Date:	11/28/2017	Closed:	11/28/201	7
- weld vise ha	ındle				Parts Li	st				Qty
					010					1.00
- Shop Suppli	es				Shop Su	ipplies			•	1.00

Workorder: Problem:	1806530 P.M. service.	Meter:	62891			In Date:	06/26/2018	Closed:	07/03/2018	
- P.m. service).				Parts Li	st			Qty	
- Inspect and	service crane.				Napagol	d Oil Filter			1.00	
- Replace bot	h front bump s	tops.			15-40 C	Dil			15.00	
- Rottate and	high speed ba	lance all si	x tires.		20" Wipe	er Blade			2.00	
- Shop Suppli	es				Used Fir	e X Refurb	ished		1.00	
					Floor Ma	at-2pc Rub	Bk		1.00	
					Ford Tri	ton Pvc Sw	С		1.00	
					Macs Ch	nain Cable I	Lube		1.00	
					Napa Hy	1.00				
					Fuel Filt	1.00				
					bumper	2.00				
					Pedal Pa	1.00				
					Aw68 H	22.00				
					Shop Su	ıpplies		1.0		
	Houi	rs 7.30		Labor:	438.00	Parts:	282.52	Total:	720.52	
Workorder: Problem:	1901031 Transition Pre	Meter: ep Charge	67866			In Date:	01/29/2019	Closed:	01/29/2019	
- Transition P	rep Charge									
	Houi :	rs 2.00		Labor:	134.00	Parts:	0.00	Total:	134.00	