

**Palm Beach County Fleet Management
Asset Maintenance History**

10192689 2013 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4X4, Diesel

Workorder: 1307684 **Meter:** 1 **In Date:** 08/01/2013 **Closed:** 08/13/2013
Problem: install hitch ext

- parts only	Parts List	Qty
- Shop Supplies	Receiver Extension	1.00
	Ball Mount 3/4"	1.00
	Pin W/clip 5/8 For Hitch	2.00
	Shop Supplies	1.00
Hours 0.00	Labor: 0.00	Parts: 119.50
:		Total: 119.50

Workorder: 1307718 **Meter:** 1 **In Date:** 08/02/2013 **Closed:** 08/02/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection	Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
	:			

Workorder: 1309492 **Meter:** 5 **In Date:** 09/19/2013 **Closed:** 09/23/2013
Problem: leak under engine

- ck for leak-leaking coolant from drain cock engine, tightened cap and top off coolant level and burp system	Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
	:			

Workorder: 1407771 **Meter:** 780 **In Date:** 08/06/2014 **Closed:** 09/30/2014
Problem: pm/ trans/ brakes/ coolant/ see notes

- Pm Service	Parts List	Qty
- To Hector turf for warranty left axle, hub, bearing	Unitrac Fluid Pint Qty	2.00
- Replace r/side outer axle boot	Napagold Oil Filter	1.00
- Repair left rear brake light . Replace right rear brake light bulb	Fuel Filter	1.00
- Shop Supplies	Napagold Air Filter	1.00
	15-40 Oil	3.00
	L/f Inner Cv Boot	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 108.50
:		Total: 528.50

Workorder: 1409788 **Meter:** 780 **In Date:** 09/30/2014 **Closed:** 10/07/2014
Problem: commercial brake repair

- Commercial Repair	Parts List	Qty
- Shop Supplies	Comm Repair	1.00
	Shop Supplies	1.00
Hours 0.00	Labor: 0.00	Parts: 722.97
:		Total: 722.97

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1500661 **Meter:** 1074 **In Date:** 01/20/2015 **Closed:** 04/09/2015
Problem: install windshield kit

- Install windshield kit	Parts List	Qty
- Shop Supplies	Fold-down Windshield Kit	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 237.61
:		Total: 297.61

Workorder: 1502613 **Meter:** 1074 **In Date:** 03/12/2015 **Closed:** 04/09/2015
Problem: 4x4/ leak/ fuel gauge/ see 3 work requests

- Ck for stalling replaced fuel line and fuel filter	Parts List	Qty
- Replace frt and rear pads, replace 2 frt rotors	Fuel Line Hose	2.00
- Drive Train service	Fuel Filter	1.00
- Shop Supplies	Brake Rotor	2.00
	295 Rear Brake Pad Kit	2.00
	Mobil 424 Fluid	4.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 356.72
:		Total: 776.72

Workorder: 1502688 **Meter:** 1072 **In Date:** 03/16/2015 **Closed:** 04/03/2015
Problem: lr seal leaking/ rear bearings/ fl bearing

- To Hector Turf Lr Axle seal wheel bearings and rear end			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508702 **Meter:** 1416 **In Date:** 08/31/2015 **Closed:** 09/30/2015
Problem: PM/ GATE LATCH/ HORN/ RUSTED COOLANT PIPES

	Parts List	Qty
- Pm		
- Replace front and rear brake pads and rotors	Napa Qt 15w40	3.00
- Replace cooling system Pipes and coolant	Napagold Oil Filter	1.00
- Load tested and charged battery. Failed test and Replaced	Napagold Air Filter	1.00
- R&r Passenger front axle to replace ripped outer boot	Fuel Filter	1.00
- Ck Lights r/r Light was inop. replaced rear bulbs on both sides	Mobil 424 Fluid	4.00
	Brake Rotor	4.00
- Ck horn inop found faulty horn, replace horn and terminal end	295 Rear Brake Pad Kit	2.00
	Brake Cleaner	2.00
- Replaced front drive shaft	L/f Outer Cv Boot	1.00
- Wash vehicle and undercarriage to prep apply rust inhibitor and rubberized undercoating	Bulb	2.00
- Fabricate and repair r/r tailgate latch	Rubberized Undercoat	3.00
- Shop Supplies	Battery	1.00
	Coolant Pipes	1.00
	Peak Global	1.00
	Locknut	3.00
	Horn	1.00
	Ront Drive Shaft	1.00
	Horn	1.00
	Ront Drive Shaft	1.00
	Shop Supplies	1.00
	Freight Charge	1.00

Hours 20.00	Labor: 1,200.0	Parts: 1,463.09	Total: 2,663.09
:	0		

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1605071 **Meter:** 1946 **In Date:** 05/16/2016 **Closed:** 06/01/2016

Problem: brakes barely stop, parking brake wont stay disengaged

	Parts List	Qty
- Pm		
- Replace fr/pads, clean caliper sliding bolts and bracket	15-40 Oil	3.00
- replace calipers, bleed rear brakes	Napagold Oil Filter	1.00
- Replace pk brake cable	Napagold Air Filter	1.00
- Replace all tires	Mobil 424 Fluid	4.00
- Replace r/fr cv boot (outer)	295 Rear Brake Pad Kit	1.00
- Replace windshield clips	Caliper Rear Rh	1.00
- Replace right brake light bulb	25 X 11.00 X 12 Tire Kenda	4.00
- Shop Supplies	L/f Outer Cv Boot	1.00
	Bulb	1.00
	Brake Fl	1.00
	Fuel Filter	1.00
	L/f Inner Cv Boot	1.00
	Left Rear Caliper	1.00
	Left Parking Brake Cable	1.00
	Rh Parking Brake Cable	1.00
	Cable Main Pk Brk	1.00
	windshield clip	2.00
	Plug Oil Fill	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00

Hours 15.50
:

Labor: 930.00 Parts: 1,909.54

Total: 2,839.54

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1611608 **Meter:** 2326 **In Date:** 11/10/2016 **Closed:** 11/29/2016
Problem: pm/ tail and headlight/ tires/ clunk noise in front/ only one tire drives

	Parts List	Qty
- Pm		
- Replace front and rear brake pads and rotors	Napa Qt 15w40	3.00
- R&r rf axle to replace out Cv Boot	Napagold Oil Filter	1.00
- Replace front and rear drive shaft	Napagold Air Filter	1.00
- Replace front headlight bulbs	Napa Fuel Filter	1.00
- Replace rear tail light assemblies	Mobil 424 Fluid	4.00
- Replace rear tires	Blaster Penetrant	1.00
- Replace both rear wheel hubs assemblies, Lr wheel bearing	295 Rear Brake Pad Kit	2.00
	Brake Rotor	4.00
- Replace frt windshield mount	Non-chlor Brake Clnr	2.00
- Clean and apply rubberized undercoat to undercarriage	L/f Outer Cv Boot	1.00
- Shop Supplies	Bulb	2.00
	Led Rh S T T Lamp	2.00
	25 X 11.00 X 12 Tire Kenda	2.00
	Rubberized Undercoat	3.00
	Glos Blk	2.00
	Rear Propshaft	1.00
	Wheel Hub	2.00
	windshield clip	1.00
	Small Light Bulb	3.00
	Plug Oil Fill	1.00
	Bearings	1.00
	Lock Shield For Axle	2.00
	Non-chlor Brake Clnr	3.00
	propshaft	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 20.50	Labor: 1,230.00	Parts: 2,010.59
:	0	Total: 3,240.59

Workorder: 1612438 **Meter:** 2326 **In Date:** 12/05/2016 **Closed:** 12/08/2016
Problem: flat tire

	Parts List	Qty
- Repair R/f Tire		
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700778 **Meter:** 2433 **In Date:** 01/25/2017 **Closed:** 05/22/2017

Problem: check brakes, horn & hard to shift in gear, see Hank or Jeff to rate

	Parts List	Qty
- fabricate lower control arms and install	Nut	4.00
- replace horn and broken horn switch	Bolt	4.00
- clean, lube and adjust shifter assy	Horn	1.00
- clean and adjust brakes	Turn Signal Switch	1.00
- replace both rear axle hubs and bearings	Non-chlor Brake Clnr	2.00
- Shop Supplies	Washer	4.00
	Caliper Brake Front	2.00
	Brake FI	1.00
	Glos Blk	1.00
	Coupling	4.00
	Wheel Hub	2.00
	Bearings	2.00
	Non-chlor Brake Clnr	2.00
	Retaining Ring	2.00
	Shop Supplies	1.00

Hours 19.00
:

Labor: 1,140.0 Parts: 1,048.40
0

Total: 2,188.40

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1707984 **Meter:** 2533 **In Date:** 08/14/2017 **Closed:** 09/18/2017

Problem: pm service, no brakes, shifts hard, strg hard to lft, left turn lght out, eng stalls,

- Pm	Parts List	Qty
- r/r Frt Diff (locking Up) r/r both axle shafts (frozen in diff)	15-40 Oil	3.00
- r/r all brake cables and hardware	Napagold Oil Filter	1.00
- r/r coolant tubes and bleed sys	Napagold Air Filter	1.00
- R/r turn signal bulb and clean socket	Fuel Filter	1.00
- R/r passenger steering knuckles r/r steering rack and tie rod	Mobil 424 Fluid	3.00
- R/r drive betl	Non-chlor Brake Clnr	1.00
- r/r fuel filter head assembly	differential	1.00
- Shop Supplies	Front Halfshaft Awd	2.00
	Nut	2.00
	Brake Cable	1.00
	Left Parking Brake Cable	1.00
	Rh Parking Brake Cable	1.00
	Equalizer Rod	1.00
	Brake Return Spring	1.00
	Brckt Equalizer	1.00
	Coolant Pipes	1.00
	1gal Rtu Antifreeze	2.00
	Bulb	1.00
	Steering Rack	1.00
	Hex Nut	2.00
	Tie Rod End	2.00
	Lock Nut	2.00
	Belt	1.00
	Drag Link	2.00
	Caster Rh Upright	1.00
	Bolt	2.00
	Nut	2.00
	Tang Locking Washer	1.00
	Atf Plus 4	1.00
	Shop Supplies	1.00

Hours 16.50

:

Labor: 990.00 Parts: 3,580.07

Total: 4,570.07

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1711173 **Meter:** 2620 **In Date:** 11/13/2017 **Closed:** 12/08/2017

Problem: brakes not working, cart stalls, idle high, strg very stiff

- R/r drive and driving clutches	Parts List	Qty
- R/r master cylinder front/rear calipers and rotors bleed sys	Clutch Drive	1.00
- Shop Supplies	Driven Clutch	1.00
	Bolt	4.00
	Washer	4.00
	Brake Rotor	4.00
	Caliper Brake Front	2.00
	Left Rear Caliper	1.00
	Caliper Rear Rh	1.00
	295 Rear Brake Pad Kit	1.00
	Master Cylinder	1.00
	Filler Cap For Mc	1.00
	Brake Fl	2.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 2,427.26
:		Total: 2,787.26

Workorder: 1802673 **Meter:** 2785 **In Date:** 03/12/2018 **Closed:** 03/30/2018

Problem: service/ clutch slips/ e brake/ front hubs/ tail light/ see notes

- service	Parts List	Qty
- replace lr axle bearing, shaft and hub	Napagold Oil Filter	1.00
- replace all front upper and lower control arm bushings	15-40 Oil	3.00
- adjust parking brake	Mobil 424 Fluid	4.00
- remount left tail lamp assy	Bearings	1.00
- Shop Supplies	Wheel Hub	1.00
	Ring Retaining	1.00
	Axle Lh	1.00
	Upper Sleeve	4.00
	Lower Arm Bushing	4.00
	Lower Arm Sleeve	2.00
	Arm Bushing	8.00
	Bolt	2.00
	Flg Nut	2.00
	Shop Supplies	1.00
Hours 11.50	Labor: 690.00	Parts: 652.21
:		Total: 1,342.21

Workorder: 1803929 **Meter:** 2813 **In Date:** 04/16/2018 **Closed:** 04/23/2018

Problem: RR rim leaking/ bed inop

- install good wheels and tires from surplus asset	Parts List	Qty
- Shop Supplies	Rubberized Undercoat	1.00
	Jb Weld Kwik Weld	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 13.42
:		Total: 103.42

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1808833 **Meter:** 3033 **In Date:** 08/27/2018 **Closed:** 09/10/2018
Problem: pm/ rear bushings/ parking brake

	Parts List	Qty
- pm service		
- replace rear lateral link bushings	15-40 Oil	3.00
- replace rear brake pads, rotors and adjust parking brake	Napagold Oil Filter	1.00
- replace left rear axle hub	Napagold Air Filter	1.00
- wash and undercoat	Mobil 424 Fluid	4.00
- Shop Supplies	Arm Bushing	8.00
	Brake Rotor	2.00
	295 Rear Brake Pad Kit	1.00
	Wheel Hub	1.00
	Fuel Fil	1.00
	Inner Sleeve	4.00
	Shop Supplies	1.00
Hours 10.00	Labor: 600.00	Parts: 448.49
:		Total: 1,048.49

Workorder: 1812446 **Meter:** 3090 **In Date:** 12/06/2018 **Closed:** 12/21/2018
Problem: motor shuts off when driving/ P brake/ move shifter to get to start

	Parts List	Qty
- repair ignition switch and replace key		
- replace parking brake cable, lube and adjust others	Cable Main Pk Brk	1.00
- diagnose starting. R/r starter and rebuild	Diesel Key Set	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 4.50	Labor: 301.50	Parts: 63.20
:		Total: 364.70

Workorder: 1901176 **Meter:** 3090 **In Date:** 01/30/2019 **Closed:** 01/30/2019
Problem: Transition Prep Charge

- Transition Prep Charge		
Hours 2.00	Labor: 134.00	Parts: 0.00
:		Total: 134.00