



3/8/2019

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V022

In Date: 10/04/2005
Close Date: 10/07/2005

Meter Reading:

Problem?
o2 leak

Task performed:

Parts ----- Quantity

NO PARTS USED

Workorder: V128

In Date: 10/11/2005
Close Date: 10/13/2005

Meter Reading:

Problem?
BULB OUT IN LIGHT BAR REAR R-37

Task performed:

Parts ----- Quantity

6811831323068-1183132-30 LENS CLEAR 9E SERIES	1
98032R 41032-3 RED REFLECTOR OVAL REFLECTOR	3

Workorder: V676

In Date: 11/23/2005
Close Date: 12/15/2005

Meter Reading:

Problem?
REAR PT, LIGHT INOP, R-37

Task performed:

Parts ----- Quantity

NO PARTS USED

Workorder: V688

In Date: 11/28/2005
Close Date: 12/27/2005

Meter Reading:

Problem?
SIREN SPEAKER INOP, R/REAR LIGHT BULB IN LIGHT BAR INOP, R-37

Task performed:

Parts ----- Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V789

In Date: 12/05/2005

Meter Reading:

Close Date: 12/27/2005

Problem?

BRAKE LIGHT OUT R37

Task performed:

Parts	Quantity
01046139100EBULB STOP/TAIL	1
101291015434 LATCH TRIGGER S/O	1
1836267000VISOR RETRN	2
2220-145632-14 DRAWER SLIDE	2
H35DSN12BULB 35W DUAL FILAMENT DOME	1
H50SN12BULB	1
SLD5366HT4932-16 DRAWER SLIDE 16	2
STOPSN12BULB STOP/TAIL LIGHT	1

Workorder: V1203

In Date: 01/17/2006

Meter Reading:

Close Date: 01/24/2006

Problem?

FRONT A/C INOP, R-37

Task performed:

Parts	Quantity
H35SN12BULB	1

Workorder: V1290

In Date: 01/25/2006

Meter Reading:

Close Date: 02/01/2006

Problem?

R/REAR WHEEL COVER FELL OFF E-37

Task performed:

Parts	Quantity
620122SPOT LIGHT REMOTE	1
H6054USE CV TYPE SEALED BEAM	6



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1467

In Date: 02/10/2006

Meter Reading:

Close Date: 02/10/2006

Problem?

FRONT A/C INOP, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1281

In Date: 01/25/2006

Meter Reading:

Close Date: 02/14/2006

Problem?

REAR CABINET LOCK BROKEN TUMBLER FELL OFF R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V1483

In Date: 02/13/2006

Meter Reading:

Close Date: 02/23/2006

Problem?

P/SIDE RED MARKER LIGHT INOP, R-37

Task performed:

Parts

Quantity

HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING 1

HND5948TM22676-02 HANDLE DOOR ENTRY 1

V122XRCAN USE 46892-5 MARKER LIGHT 1

Workorder: V062

In Date: 10/05/2005

Meter Reading:

Close Date: 02/28/2006

Problem?

light bulb burned out in rear light bar R-37

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1793

In Date: 03/09/2006

Meter Reading:

Close Date: 03/15/2006

Problem?

CLEARANCE LIGHTS INOP, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2072

In Date: 04/03/2006

Meter Reading:

Close Date: 04/05/2006

Problem?

L/SIDE SCENE LIGHT COVER MISSING, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2188

In Date: 04/11/2006

Meter Reading:

Close Date: 04/21/2006

Problem?

HAZARDS & TURN SIGNALS INOP, L/SIDE REAR LIGHT NOT SPINNING R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2320

In Date: 04/21/2006

Meter Reading:

Close Date: 04/27/2006

Problem?

HANDLIGHT INOP, PIN MISSING, R-37

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2347

In Date: 04/24/2006

Meter Reading:

Close Date: 04/28/2006

Problem?

DIAMOND PLATE P/SIDE LOOSE, CHECK TIRES, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2481

In Date: 05/04/2006

Meter Reading:

Close Date: 05/09/2006

Problem?

CAB DOOR LATCH INOP, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2610

In Date: 05/15/2006

Meter Reading:

Close Date: 05/19/2006

Problem?

REAR ROTATOR IN LIGHT BAR INOP, R-37

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2568

In Date: 05/11/2006

Meter Reading: 68,550.00

Close Date: 05/22/2006

Problem?

B INSPECTION, R-37

Task performed:

See B Inspection pre-printed form

Parts	Quantity
01-0416333-00LIGHT ROTATOR	1
020383470CROLENS RED/C USE 4 SCREW LENS NOW	2
161657700065489 SHOCK REAR NEW RESCUE	2
203FFBEARING PULLEY	1
322502BULB PATIENT GH22	1
3911638PLUG OIL DRAIN C	1
3920773WASHER DRAIN PLUG	1
3959052PAN GASKET B ENGINE	1
508RED58EC20RU STROBE-RED SURFACE MOUNT	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
6808880023GRILLE FRTLNR. A17-14766-000	1
9550 BELT	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
CA8193AIR FILTER 46744 WIX	1
DOOR2LEXAN 14.5 X 8.5	1
DOOR5LEXAN 9 X 38 1/2 IN	1
EL12FLASHER ELECTRONIC	1
HLD3999GSS1715UV 30LB STRUT GAS	2
HLD44614446 1/4 LATCH	5
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SA66613SHOCK FRONT RESC	2
SWT5492744435 ACTUATOR-BLACK	2
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Vendor? VC-15214



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2644

In Date: 05/17/2006

Meter Reading:

Close Date: 06/09/2006

Problem?

REFLECTOR ON THE LOWER R/SIDE DOOR BROKEN, R-37

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V2941

In Date: 06/12/2006

Meter Reading:

Close Date: 06/13/2006

Problem?

REPLACE BATTERY SWITCH, R-32

Task performed:

Parts

Quantity

51-30219-1045 MASTER SWITCH 175 AMP

1

Workorder: V3149

In Date: 06/02/2006

Meter Reading:

Close Date: 06/26/2006

Problem?

frame rail cracked (outside agency-Freightliner trucks)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? FREI0006

Workorder: V3253

In Date: 07/01/2006

Meter Reading:

Close Date: 07/31/2006

Problem?

rear light bar reflector not spinning R37

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3671

In Date: 07/28/2006

Meter Reading:

Close Date: 08/18/2006

Problem?

repair marker lt r37

Task performed:

Parts

Quantity

4867JB320 UPGRADE ALTERNATOR

1

Workorder: V3896

In Date: 08/14/2006

Meter Reading:

Close Date: 08/18/2006

Problem?

on call check eng lt on r37

Task performed:

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

4

HP-31DBATTERY 950CCA HP-31D

4

Workorder: V3918

In Date: 08/14/2006

Meter Reading:

Close Date: 08/22/2006

Problem?

TOW VEHICLE FROM OVERLOOK RD TO THE SHOP, R-37 (SISTERS)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? SISTERS TOWING

Workorder: V3993

In Date: 08/18/2006

Meter Reading: 71,009.00

Close Date: 08/23/2006

Problem?

A INSPECTION, (OLD RESCUE R-37)

Task performed:

Parts

Quantity

322502BULB PATIENT GH22

3



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3951

In Date: 08/16/2006

Meter Reading:

Close Date: 08/24/2006

Problem?

A INSPECTION AND REPAIRS AS NEEDED R37

Task performed:

Parts	Quantity
B484RB484R REFLECT-RED	1
FS1269FUEL FILTER COMPLETE	1
SLD5366HT4932-16 DRAWER SLIDE 16	2

Workorder: V4915

In Date: 10/16/2006

Meter Reading: 71,014.00

Close Date: 11/01/2006

Problem?

B INSPECTION, R-37

Task performed:

1. PERFORM "B" INSPECTION
2. REPLACE LENS ON EMERGENCY LIGHTS.
3. R/R BATTERIES.
4. REPAIRED LIGHTS.
5. REPLACED HOLD OPENS ADJUSTED REAR DOOR SECURED DOOR LATCHES.
6. REPLACED BELTS AND TENDIONER.
7. SERVICED REAR DIFF
8. SERVICED AIR DRYER.
9. TORQUED U-BOLTS, REPLACED AIR BAGS.
10. R/R WIPERS.

Parts	Quantity
02034176800ADIVIDERS SUPER ADV. PLUS LT. BAR	1
16-15762-00016-19471-000 AIR BAG	2
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
38026169400BGASKET ENDCAP SUPER EDGE PLUS	3
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
68116169650CLENS RED SUPER ADV. PLUS LT. BAR 68-1	4
68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR	3
68118313250OBSOLETE REPLACE UNIT LENS RED 97 E S	1
91513AMBER LENS	2
9451BELT	1
9485BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
HLD374211 IN HOLD-OPEN 30LB	6
HLD39916USE EAA-8200-60 STRUT 60#	2
HP-31DBATTERY 950CCA HP-31D	4
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RK30063BOWL-PLASTIC RACOR FUEL FILTER	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V5439

In Date: 11/17/2006
Close Date: 11/20/2006

Meter Reading: 71,485.00

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR BACK FROM 21

Task performed:

1. "A" inspection

Parts

NO PARTS USED

Quantity

Workorder: V6100

In Date: 01/04/2007
Close Date: 01/17/2007

Meter Reading: 71,624.00

Problem?

A Inspection and needed repairs SR10 back from 47

Task performed:

- 1.A Inspection
- 2. Washers inop replaced washer pump assy
- 3. Engine hard starting inspected fuel system
- 4. Repaired several patient compartment door panals
- 5. Recharge a/c system in patient compartment
- 6. Replaced RRI tire

Parts

3941156CHECK VALVE ISB
 A2254926000WASHER PUMP W/GROMMET
 VBK-HBRACKET FOR WHEEL AIR EXTENSION

Quantity

1
1
2

Workorder: V6173

In Date: 01/09/2007
Close Date: 01/17/2007

Meter Reading: 71,624.00

Problem?

repair fuel system cummins power south

Task performed:

Repair fuel system Cummins Power South

Parts

NO PARTS USED

Quantity

Vendor? CUMMINS POWER SOUTH

Workorder: V6396

In Date: 01/22/2007
Close Date: 01/26/2007

Meter Reading: 71,982.00

Problem?

ON CALL R15 AIR LEAK

Task performed:

Parts

284358GOVERNOR D-2

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6550

In Date: 01/31/2007
Close Date: 02/01/2007

Meter Reading: 71,982.00

Problem?

a inspection and repairs as needed

Task performed:

- 1. A Inspection
- 2. Rear door latch loose secured latch
- 3. Panal loose secured loose panal

Parts

Quantity

NO PARTS USED

Workorder: V6831

In Date: 02/20/2007
Close Date: 02/21/2007

Meter Reading: 72,256.00

Problem?

ON CALL EMER. LTS NOT WORKING PROPERLY SR10 AT 42

Task performed:

Parts

Quantity

EL30213091-32 LOAD MANAGER

1

Workorder: V6832

In Date: 02/20/2007
Close Date: 02/26/2007

Meter Reading: 72,256.00

Problem?

EMRG. LTS. SHUTTING DOWN ON CALLS SR10 AT 42

Task performed:

RAN TRUCK FOR 1 HOUR- NO PROBLEM FOUND

Parts

Quantity

091-32R-12LOAD MANAGER

1

EL30213091-32 LOAD MANAGER

1

Workorder: V6890

In Date: 02/22/2007
Close Date: 02/27/2007

Meter Reading: 72,386.00

Problem?

Noticed 2 foot round spill on floor under engine compartment. SR10 AT 42

Task performed:

1. TRAVELED TO STN 42 FOR CALL OF POSSIBLE OIL LEAK. NONE FOUND, ADVISED D/O TO CONTACT SHOP IF OIL FOUND ON FLOOR OR LEVEL WAS BELOW DESIRED AMOUNT.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7003

In Date: 02/28/2007

Meter Reading: 7,213.00

Close Date: 03/23/2007

Problem?

Vehicle leaking engine oil out of bottom of engine. Also, there is no replacement oil in station. SR10 AT 42 A INSPECTION AND REPAIRS AS NEEDED

Task performed:

Task performed:	Parts	Quantity
1. A Inspection	A1834388002MOLD L/H	1
2. Replaced bulb in O2 comp	A1834388003MOLD R/H	1
3. Replaced and repaired loose and broken door latches	LTC594111656-16 LATCH R/H MEDIC MASTER	1
4. Check for oil leak none found	LTC594211657-16 LATCH L/H MEDIC MASTER	1
5. R&R 2 door moldings		
6. Secure drivers seat air switch		

Workorder: V7608

In Date: 04/09/2007

Meter Reading: 73,830.00

Close Date: 04/16/2007

Problem?

a inspection and repairs as needed sr 10 back from 19

Task performed:

Task performed:	Parts	Quantity
1. Repaired plexi glass door and handle in patient comp	091-3YWCOVER KUSSMAUL AUTO EJECT	1
2. Repaired rear door weather strip	2332920005SMASK LENS W/RST BUTTON VDO	1
3. Replaced instrument cluster glass	6808300074VENT A/C LH	1
4. Replaced kussmaul cover	6808300174VENT A/C RH	1

Workorder: V8144

In Date: 05/07/2007

Meter Reading: 74,250.00

Close Date: 05/15/2007

Problem?

A inspection and related repairs (back from sta 17)

Task performed:

Task performed:	Parts	Quantity
A-Inspection; road test	NO PARTS USED	
1. r-1 & rear pat comp door locks loose; chk/secure locking device.		
2. Start/run spare unit in yard		



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8083

In Date: 05/03/2007
Close Date: 05/18/2007

Meter Reading: 7,312.00

Problem?

request a third handlight charger in scba compartment.

Task performed:

At shop

Parts

Quantity

NO PARTS USED

Workorder: V9386

In Date: 07/17/2007
Close Date: 07/20/2007

Meter Reading: 74,250.00

Problem?

A inspection and related repairs (back from sta 81)

Task performed:

1. A INSP. AIR FILTER. ADD P/S FLUID.
2. CLEAN SHOP FLOOR.
3. MEETING ON NEW SHOP.
4. REPLACED HIGH HORN. CLEAN CONTACTS.
5. REMOVE LIGHT BAR LENSES & REPLACED ROTOR.
6. REPLACED R FRT MARKER BULB.
7. SECURE INNER FENDER SKIRT.

Parts

Quantity

01-0416333-00LIGHT ROTATOR

1

A0631117000HORN HIGH NEW # 06-52125-039

1

Workorder: V10308

In Date: 09/07/2007
Close Date: 09/25/2007

Meter Reading: 74,250.00

Problem?

ON CALL SR10 AT 33 TURBO HOSE BAD

Task performed:

Drove to STA 33, R/R Hose between Intake Manifold and Air Compressor.

Parts

Quantity

3944427INTAKE HOSE NEW #3949710

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V10444

In Date: 09/14/2007

Meter Reading: 74,615.00

Close Date: 09/27/2007

Problem?

a inspection and repairs as needed sr10 back from 17

Task performed:

1. A SERVICE, TOP OFF ALL FLUIDS.
2. FILL WASHER FLUID, REPLACE A/C CAPS AND VALVE CAPS.
3. REPLACE DOOR RUBBER.
4. INSTALLED REAR GLASS IN COMPARTMENT.

Parts	Quantity
16-31455533 CAP LOW SIDE BLUE	1
435 VALVE CAP	2
DOOR5LEXAN 9 X 38 1/2 IN	1
HNG5451HINGE - CHROME	1
MG-C23SPMGC23 GAUGE	1
S116BLO-GUN	1
S153BLOW GUN	1
S1815COUPLER MILTON	1
S448GAUGE TIRE TREAD DEPTH	1
S775COUPLER	3
S976GAUGE AIR USE S986	1

Workorder: V7074

In Date: 03/06/2007

Meter Reading: 73,182.00

Close Date: 10/15/2007

Problem?

A INSPECTION AND REPAIRS AS NEEDED SR10 BACK FROM 42

Task performed:

1. A Inspection
2. Repaired wiper nozzle
3. Repaired 2 patient compartment dome lights

Parts	Quantity
322502BULB PATIENT GH22	2
921LIGHT BULB	2
PVG-KITORING KIT	1
SPR-W58-1TEE PLASTIC	1

Workorder: V10734

In Date: 09/28/2007

Meter Reading: 7,357.00

Close Date: 10/22/2007

Problem?

AC IN FRONT CAB IS BLOWING HOT.... r23

Task performed:

drive to station. R/R heater a/c not cold. filled with freon. found leak at fitting. tighten. test ok.

Parts	Quantity
22-49905-000CABLE HEATER	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11601

In Date: 11/14/2007

Meter Reading: 75,000.00

Close Date: 12/04/2007

Problem?

b inspection and repairs as needed sr10 back from 23

Task performed:

- B-Inspection
- 2. R/R drvr seat swtches; brk pedal pad swtchs on dahs; fill washer tank
- 3. R/R Rear trans seal; R/R park brake asy; svc trans
- 4. R/R cab door ltches
- 5. R/R straps box handle & adj slides
- 6. Replc action area swtch; replc bulb; replc bulb in roof; rework bench ltch to work
- 7. Fuel leak #3 injector line; replc
- 8. Svc Air dryer
- 9. Replc belts j
- 10. door panels & ltches loose & msng screw; adj/tighten door panels

Parts

Quantity

18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
29526898 29548988 TRANS FILTER ALLISON	1
29546233SEAL TRANSMISSION	1
68129100826812910082 BRAKE PEDAL	1
921LIGHT BULB	2
9451BELT	1
9485BELT	1
98003RREFLECTOR RED 40132 GROTE	4
AEVDOOR LOCK BEZEL	1
BOS62221360026222207-001 W AIR SEAT	1
CA8193AIR FILTER 46744 WIX	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
LTC5993SSM1-63-8 LATCH STAINLESS	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT54913SW ROCKER SPST ON-OFF RED	1
SWT54924ACTUATOR-RED	1
SWT5492744435 ACTUATOR-BLACK	1

Workorder: V12351

In Date: 01/03/2008

Meter Reading: 7,508.00

Close Date: 01/09/2008

Problem?

backboard compartment door linkage retainer broke, unable to open door. I took the inside panel off to gain acces to linkage and need 2 plastic retainers to connect linkage to door latch. Jeff, 644-5651 R73

Task performed:

- 1. Repaired by Chris from Hallmark.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12378

In Date: 01/05/2008
Close Date: 01/09/2008

Meter Reading: 7,508.00

Problem?

need headset in rear box missing. R-73B

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|----------------------------------|---------------|-----------------|
| 1. Dropped off headset for R-73B | NO PARTS USED | |

Workorder: V12443

In Date: 01/08/2008
Close Date: 02/07/2008

Meter Reading: 7,508.00

Problem?

left rear turn signal out. r73

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|--|---------------|-----------------|
| | NO PARTS USED | |

Workorder: V12953

In Date: 01/31/2008
Close Date: 02/15/2008

Meter Reading: 7,629.00

Problem?

The rear light bar right side rotater lights light up but do not rotate. r73

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|-----------------------------------------------------|----------------------------|-----------------|
| 1. R & R two rotator on new light bar | 01-0416333-00LIGHT ROTATOR | 2 |
| 2. R & R strobe light in rear light bar | TURBO5TUBE - STROBE | 1 |
| 3. Go to St 74, check on equipment to see if all OK | | |

Workorder: V13541

In Date: 02/27/2008
Close Date: 02/29/2008

Meter Reading: 79,227.00

Problem?

repair stretcher at shop r73 emsar

Task performed:

- | | <u>Parts</u> | <u>Quantity</u> |
|----------------------------------------|---------------|-----------------|
| Repair stretcher at shop R73 - Emsar j | NO PARTS USED | |

Vendor? MEDCO EQPMT



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13749

In Date: 03/07/2008

Meter Reading: 79,755.00

Close Date: 03/13/2008

Problem?

A/C drain plugged, need bracket for patient suction in action area R73

Task performed:

Parts

Quantity

1. Cleared A/C drain
2. Ordered parts on WO 13750, Installed suction bracket (in patient compartment)

NO PARTS USED

Workorder: V14216

In Date: 04/01/2008

Meter Reading: 7,870.90

Close Date: 04/04/2008

Problem?

place bracket in backboard compartment to hold pike pole. sb7e at 73

Task performed:

Parts

Quantity

1. Install pike pole brackets

5269LPVM-5 SM MOUNT

2

Workorder: V14217

In Date: 04/01/2008

Meter Reading: 7,870.90

Close Date: 04/04/2008

Problem?

siren sounds like it is shorting out sb7 e at 73

Task performed:

Parts

Quantity

1. Install new siren head from coffee spill

NO PARTS USED

Workorder: V14499

In Date: 04/16/2008

Meter Reading:

Close Date: 04/23/2008

Problem?

Siren constantly turns off and on. Bad when crew is in with pt and siren turns on. Dangerous enroute code 3 when siren turns off. R-73

Task performed:

Parts

Quantity

1. SODA FOUND IN SIREN HEAD, CLEANED AND TESTED.

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V14589

In Date: 04/21/2008
Close Date: 05/02/2008

Meter Reading: 79,241.00

Problem?

A interior dome light is out in the pt compartment. r73

Task performed:

1. Repaired patient compartment light

Parts

Quantity

322502BULB PATIENT GH22

1

921LIGHT BULB

1

Workorder: V14841

In Date: 05/03/2008
Close Date: 05/12/2008

Meter Reading: 133,547.70

Problem?

LOOSE BELT CAUSING SQUEELING WHEN TRUCK ACCELERATES. R73 TRUCK VIBRATES/WOBBLES ON RIGHT FRONT SIDE WHEN DRIVING AT SPEED. TRIP BUTTON FOR ODOMETER DOES NOT WORK - CURRENTLY SHOWS KMs AS OPPOSED TO MILES.

Task performed:

1. Drive to Stn 73; chk for vibration & wobble; fnd L/R/l tire flat.
2. Tighten A/C belts
3. Rem dash cotnrol head & reset odometer to miles.
4. Drive to Stn73; R/R/ all belts & tensioner; test drive truck & c/o drive line. j

Parts

Quantity

39768315259022 GROOVED TENSIONER OLD#3936213

1

9451BELT

1

9485BELT

1

K080733BELT

1

Workorder: V15310

In Date: 05/24/2008
Close Date: 06/06/2008

Meter Reading: 80,448.00

Problem?

the rear a/c is leaking large amounts of water behiend the captians chair in the rescue just below the a/c unit in the pt compartmer R73

Task performed:

Drive to Stn73; Remount A/C drum hose. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15079

In Date: 05/14/2008
Close Date: 06/10/2008

Meter Reading: 83,374.00

Problem?

B inspection and repairs as needed r73

Task performed:

- B-Inspection
- 2. Broken bezel - R/R/ bezel
- 3. Tighten rear door latches
- 4. Replc washer on driver side.
- 5. Rem door panel & replc window molding.
- 6. Auto-eject inop; R/R/ asy & rewire/install btry charger LED.
- 7. R-windshield molding msng; install new molding. j

Parts

Quantity

0915520120AUTO EJECT 20 AERO OTL3925	1
15W40BSYN OIL BULK QTS	16
1829601001RHINGE PILLAR RESCUE	1
52-24WIPER BLADES ANCO 24	2
A1834388003MOLD R/H	1
AEVDOOR LOCK BEZEL	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SPRGW2612WASHER NOZZLE W/RELIEF	1

Workorder: V15312

In Date: 05/24/2008
Close Date: 06/10/2008

Meter Reading: 80,448.00

Problem?

the shore line does not work when plugged in on r-73

Task performed:

- 1. Shoreline has powier (110V); veh not lasting long enough to chk; Emergency calls went to STN72.
- 2. Started to C/O no power to charger; truck had go to training.
- 3. Shoreline get trip in box; troubleshoot; Fnd problem; rep. j

Parts

Quantity

NO PARTS USED

Workorder: V15314

In Date: 05/24/2008
Close Date: 06/10/2008

Meter Reading:

Problem?

action area lite in pt. compartment not working. R73

Task performed:

- 1. Installed new lights.
- 2. installed new overhead light, in dome, compartment.
- j

Parts

Quantity

322502BULB PATIENT GH22	2
-------------------------	---



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V14864

In Date: 05/05/2008
Close Date: 06/11/2008

Meter Reading: 133,547.00

Problem?

repair flat callaghan at sta 73

Task performed:

Repair flat Stn73 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V15560

In Date: 06/05/2008
Close Date: 06/16/2008

Meter Reading:

Problem?

a/c system just started to blow warm air. e73

Task performed:

1. Travel to St73 from St74.
2. Check A/C sys for cab; recharge sys term; now ok.
3. Chk A/C water drains in pat compt A/C - ok; clear on both sides. j

Parts

NO PARTS USED

Quantity

Workorder: V14919

In Date: 05/07/2008
Close Date: 06/17/2008

Meter Reading: 7,982.30

Problem?

The flashlight charger on R-73B is not charging the flashlight.

Task performed:

1. Both stream light bases are broken on power pin to light.
2. Travel to Stn; chk out ight; need parts at shop.
3. installed two charging bases in Rescue 73 for streamlight. j

Parts

NO PARTS USED

Quantity

Workorder: V15514

In Date: 06/03/2008
Close Date: 06/19/2008

Meter Reading:

Problem?

Rear A/C leaking into the pt compartment, and rear driver's side strobe not working. R-73

Task performed:

1. Rep drain to A/C.
2. Replc strobe light-bad; may need strobe part replaced. j

Parts

TURBO5TUBE - STROBE

Quantity

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15797

In Date: 06/17/2008

Meter Reading: 8,100.00

Close Date: 06/24/2008

Problem?

rt front scene light cover fell off en route to training R-73

Task performed:

drive to Stn; R/R lens & lite; test ok. j

Parts

Quantity

6811831323068-1183132-30 LENS CLEAR 9E SERIES

1

H50SN12BULB

1

Workorder: V15682

In Date: 06/11/2008

Meter Reading: 8,100.00

Close Date: 06/25/2008

Problem?

the a/c does not work when the unit is plugged in to shore line. The shore line has power and the charge light lights up on the rescue where the plug goes in.

Task performed:

1. Travel to Stn73 from Stn72.
2. Chk 110V A/C; veh has none.
3. Travel to CS from Stn73. j

Parts

Quantity

NO PARTS USED

Workorder: V15901

In Date: 06/23/2008

Meter Reading: 8,148.30

Close Date: 06/27/2008

Problem?

Goggle eye mirror needs to be replaced. R73

Task performed:

R/R mirror on R-door j

Parts

Quantity

980-412173 MIRROR 8 IN

1

Workorder: V15915

In Date: 06/23/2008

Meter Reading: 8,148.30

Close Date: 06/27/2008

Problem?

R73B Fisheye mirror on officer's side is broken. AC in patient compartment is leaking onto floor behind seat at head of stretcher.

Task performed:

Didn't find drains clogged; blew out anyways. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15859

In Date: 06/20/2008

Meter Reading: 8,148.30

Close Date: 07/01/2008

Problem?

Left side rear door of rescue will not close. It bounces back when attempt to close. It only becomes secure once the right side locking door is closed. It appears that the lower metal arm/catch will not grasp the n.pin R73

Task performed:

Parts

Quantity

1. disassemble L / R entry door, repair linkage to door and upper / lower latches.
2. travel from st 73 to c/s

NO PARTS USED

Workorder: V16047

In Date: 06/30/2008

Meter Reading: 8,179.20

Close Date: 07/14/2008

Problem?

Rear AC Leaking R73

Task performed:

Parts

Quantity

Check out - no leak at this time. Chk w/driver - no leak at this time. j

NO PARTS USED

Workorder: V16109

In Date: 07/02/2008

Meter Reading:

Close Date: 07/17/2008

Problem?

Interior Pt compartment high beam dome light out of service. R73

Task performed:

Parts

Quantity

Replace high light in rear compartment(1) H1, 12V, 27 watt. j

322502BULB PATIENT GH22

1

Workorder: V16155

In Date: 07/04/2008

Meter Reading: 85,722.00

Close Date: 07/17/2008

Problem?

left rear reverse light out R-73

Task performed:

Parts

Quantity

Replace light in left rear backup; 27W, 12V light off service truck. j

H27SN12BULB

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17512

In Date: 09/04/2008
Close Date: 09/29/2008

Meter Reading: 86,025.00

Problem?

COOLANT LEAK, SR-10

Task performed:

1. Rem blown radiator from truck; diss; reassemble radiator.
2. Trans fitting different; travel to Mako Hose for proper fitting.
3. Install radiator; fnd new brkt 5/8 taller; rem radiator & mod brackets; reinstall; run unit; no leaks.
4. Install new radiator cap.
5. install new T-stat.
6. Replc upper/lower radiator hose.
7. Fnd alt grd cable brkn; cut/crimp new ends.
8. Run unit; eng overheating; dia fault; traced to fan switch not engaging; fnd relay unplugged; plug in relay; unit still overheating & fan clutch not engaging.
9. Dia function or relay; fnd relay bad; rem/install new relay; operate unit; fan clutch engaging & temperature at normal range.
10. Road test unit; temp range 170-185 degrees; all working normal at this time; use manuel & diagnostic equipmt to make rep
11. Cln work area tools, eqpmt put away books. j

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB	1
05-17542-002HOSE UPPER RADIATOR	1
05-17544-002HOSE LOWER RADIATOR	1
1219360123-11276-041 RELAY VF28-35F14-Z05	1
39671953967195 THERMOSTAT ISB	1
PHT-B7596FL3S4917 RADIATOR	1

Workorder: V17682

In Date: 09/13/2008
Close Date: 09/29/2008

Meter Reading: 8,229.00

Problem?

VEHICLE OVERHEATED WHILE AT HOSPITAL, CHECK ENGINE LIGHT AND ALARM SOUNDING, TEMP OVER 200. SPARE RESCUE AT STA-39

Task performed:

Overheat, found fan clutch connection loose, secure and tie strap in place. Electrical connection loose.

Parts

Quantity

NO PARTS USED

Workorder: V16291

In Date: 07/10/2008
Close Date: 10/17/2008

Meter Reading:

Problem?

The A/C unit in the patient area in the rear of the rescue above the officers chair is leaking water inside of the unit. R73

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17689

In Date: 09/13/2008

Meter Reading: 86,025.00

Close Date: 01/01/2009

Problem?

ON CALL UNIT OVERHEARTING AT 39

Task performed:

Parts

Quantity

1on call rescue overheating check unit found wires bad to fan clutch repair wires recheck npf.

NO PARTS USED

Workorder: V20498

In Date: 01/23/2009

Meter Reading: 8,320.10

Close Date: 02/04/2009

Problem?

the siren turns on when the steering wheel is turning. R-25

Task performed:

Parts

Quantity

1- Drive to station, found short in steering wheel repairex

NO PARTS USED

Workorder: V20424

In Date: 01/17/2009

Meter Reading: 8,311.00

Close Date: 02/09/2009

Problem?

air leak under dash, ac not working, at st 25

Task performed:

Parts

Quantity

1. Ck for air leak; could not find air leak.
2. Ck cab A/C; fnd freon level low; lowside Schrader valve leaking; topped off A/C, j

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20882

In Date: 02/05/2009

Meter Reading: 87,253.60

Close Date: 02/26/2009

Problem?

C INSPECTION AND REPAIRS AS NEEDED SER4

Task performed:

- 1. C-Inspection
- 2. R/R btrys.
- 3. Ck air seat; fnd lines kinked & swtch inop; R/R swtch asy & lines; mnted swtch; ck opn-ck ok.
- 4. Door latches loose; tightened all latches; R/R (2) door latches; rem pat side door panels; rem door handle asy; R/R latch asy; reinstalled all parts; ck ok.
- 5. Rebuild air dryer; rem hoses/dryer; diss & cln dryer; rebuild dryer; rebuild purge evap & chk valve; reassemble all parts; installed dryer/hoses; _dryer.
- 6. Right rear marker on light bar out; rem lense; rep wires; ck opn; ck ok.
- 7. Torque all axle u-bolts.
- 8. Replc frnt/rear axle brakes; rem all wheels; rem frnt/rear calipers; R/R rear pads; R/R frnt calipers/pads; reinstall wheels; bled brakes.
- 9. replc rear axle shocks; R/R shocks.
- 10. Svc P/S sys; drained fluid; R/R filter & gsks; filled sys; ran/ck level; ck ok.
- 11. Pat A/C filter bad; fnd filtr moldy; replc filter; clnd evap & drain lies; ck ok.
- 12. Ck frnt end alignment; ck toe; fnd toed-in 1/4"; adj toe.
- 13. Ck pat dim lights; fnd light out; rem lense; rem light asy; rep connection; reassembled; ck ok.
- 14. Ck city horn; fnd horn/siren inop; rem horn button; rep connections; ck opn; ck ok; reinstalled button. j

Parts

Quantity

1500900017000USE 9 X 14 FILTER	1
15W40BSYN OIL BULK QTS	16
161657700065489 SHOCK REAR NEW RESCUE	2
AEVDOOR LOCK BEZEL	1
ASL4152092CALIPER F/R RESCUE 55314 NEW	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
BOS6222136002622207-001 W AIR SEAT	1
CA8193AIR FILTER 46744 WIX	1
E-600013-3052 NUT	5
HLD3999GSS1715UV 30LB STRUT GAS	4
HND5948TM22676-02 HANDLE DOOR ENTRY	1
HP-31DBATTERY 950CCA HP-31D	4
L1261F33585XE FUEL FILTER WIX	1
LTC594211657-16 LATCH L/H MEDIC MASTER	2
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
VML-T1279WASHER P/S	1

Workorder: V21064

In Date: 02/12/2009

Meter Reading: 87,253.60

Close Date: 02/28/2009

Problem?

replace 4 tires SER4 (outside agency-callaghan tire)

Task performed:

Replace (4) tires SER4 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20459

In Date: 01/20/2009
Close Date: 03/06/2009

Meter Reading: 87,012.50

Problem?

A/C INOP, R-25

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V21577

In Date: 03/05/2009
Close Date: 03/13/2009

Meter Reading: 9,288.00

Problem?

install repaired seat in unit at 25

Task performed:

Parts

Quantity

Drive to Strn; installed seat. j

NO PARTS USED

Workorder: V22734

In Date: 04/22/2009
Close Date: 04/22/2009

Meter Reading:

Problem?

FRONT A/C ONLY BLOWING HOT AIR sr at 39

Task performed:

Parts

Quantity

A/C warm; recharge sys & chkd for leaks. j

NO PARTS USED

Workorder: V22836

In Date: 04/27/2009
Close Date: 04/28/2009

Meter Reading: 87,808.40

Problem?

A INSPECTION (BACK FROM PALM SPRINGS)

Task performed:

Parts

Quantity

1. Start A-Inspection.
2. Complete A-Inspection
3. Rep sharps bio hazzard drawer; mod compt for new slides & replc plexi door.
4. Adj all door & compt strikers.
eto chk for intermittent alarm. j

2220-12USE 5632-12 DOOR SLIDE

2

DOOR2LEXAN 14.5 X 8.5

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25109

In Date: 07/28/2009

Meter Reading:

Close Date: 07/30/2009

Problem?

will not start (Special events unit)

Task performed:

Parts

Quantity

Drive to Stn; put charged (1) btry in morning; rem late in day; test ok. j

NO PARTS USED

Workorder: V26682

In Date: 10/05/2009

Meter Reading:

Close Date: 10/21/2009

Problem?

will not start....has been plugged in can you also check the shore line charging system ser4

Task performed:

Parts

Quantity

drive to Stn; hookup battery charger; go back later in day; unhook; test ok. j

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V26735

In Date: 10/07/2009

Meter Reading: 87,808.40

Close Date: 10/26/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED SE R4

Task performed:

- B-Service
- 2. Recovered, vac/recharged A/C sys(cab).
- 3. Replcd bulb for R/frt T-signal.
- 4. Replcd marker light asy on R/frt uppeer body.
- 5. Replc bulb in L2 dome light in pat compt.
- 6. Diss frt light bar to access peicer; cut out corroded connector & wire peicer direct; also replcd piecer bulb; reassembled light bar & tested.
- 7. Replcd wiper blades & cln debris frm windshld washer squirters.
- 8. Replcd L/R flag stickers on rear of body (faded).
- 9. Replc rear pat comp entry door latch(inner) & bezl; (brkn/crckd).
- 10. Rem inner door panel on pat compt side entry door; sec outter ltch & reassembled (loose/falling off).
- 11. Replcd both cab door trims (brkn).
- 12. Replcd driver's side door weatherstrip (ripped/torn).
- 13. Diss driver's seat belt asy & remntd properly (binding).
- 14. Replcd both door jam latches (bent).
- 15. Replcd accreditation stickers (faded/crck).
- 16. Lube/adj/tighten all door latches;; hold opens, door chks & strikers on cab/body.
- 17. painted fuel tank cap.
- 18. Installed "out of svc" stickers.
- 19. Replcd squad bench shocks. j

Parts

Quantity

15W40BSYN OIL BULK QTS	28
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
322502BULB PATIENT GH22	1
46892-546892-5 MARKER LAMP	1
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6806970098SEAL DOOR	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
HAN-1LBEZEL AND HANDLE	1
HLD3999GSS1715UV 30LB STRUT GAS	2
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
TURBO64STROBE TUBE	1

Workorder: V27012

In Date: 10/20/2009

Meter Reading: 87,808.40

Close Date: 11/02/2009

Problem?

check special events units at 25

Task performed:

- 1. Drive to Stn; no keys for one unit; have made; no power at all four outlets 110; called Bldg Mnt; start two units; run ok.
- 2. Drive to Stn; hookup btry chargers to unit that won't start; in morning come back at end of day; started units; test ok. j

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28394

In Date: 12/15/2009
Close Date: 01/05/2010

Meter Reading: 87,808.40

Problem?

batterys dead ser4

Task performed:

1. Travel
2. Replc btrys; cln term.
3. Chk btrty charging sys; fnd no power to charger & fnd brkr tripped; reset brkr.
4. Start & run all special event vehicles. j

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

4

HP-31DBATTERY 950CCA HP-31D

4

Workorder: V28499

In Date: 12/21/2009
Close Date: 01/05/2010

Meter Reading: 88,105.80

Problem?

BATTERY DEAD SE 3 AT 25

Task performed:

1. Chk cooling sys hoses & water pump; press tested; fnd no leak; was sent out for repair.
2. Chkd all SE trucks; all chkd fine. j

Vendor? FLORIDA DETROIT

Parts

Quantity

NO PARTS USED

Workorder: V33211

In Date: 06/28/2010
Close Date: 07/14/2010

Meter Reading: 89,168.00

Problem?

Special event rescue. Front head light out. There are black ant's through out the truck and the A/C is not working. This is the truck with the label "out of service" and is the most used truck for special events. Thank U SER4 at 25

Task performed:

1. Went to Stn25 frm 68; rem R/headlight; fnd plug pulled out of light; rep light/socket; rep headlight bucket & fnd wires clipped out of R/frnt t-signal; rep/rewired; ck lts; ck ok.
2. Fnd air horns inop; traced air supply line; rep line & ck ok.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33164

In Date: 06/26/2010

Meter Reading: 88,724.80

Close Date: 07/29/2010

Problem?

A/C does not blow cold SE R AT 25

Task performed:

1. Ck cab A/C; fnd hi-side hose bad; cond to dryer; R/R A/C hose & dryer; charge A/C; ck ok.
2. Ck pat A/C inop; fnd cond fan bad; R/R (2) condensor fans; ran/ck A/C; topped off unit; ran/ck ok. j

Parts

Quantity

60027FAN A/C COND 12IN 860026-2-W

2

716907-0610A DRYER

1

A2245296013A22-45296-013 HOSE A/C

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33881

In Date: 07/29/2010

Meter Reading: 89,340.00

Close Date: 08/27/2010

Problem?

C INSPECTION AND REPAIRS AS NEEDED SER4

Task performed:

Parts

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

C-Inspection

2. Rep R/rear outer tire flat; reinflate & chk for leaks; fnd bad valve core in extension hose; replc core & inflate to proper press; rechk leak-ok.
3. Btrys failed orig test-charge was low; charge btrys to 100% & retest using heavyloads on each btry; all passed.
4. Replc all (5) cab roof clearance light bulbs.
- 5.Replc both frnt fender t-signal light fixtures; also rep harnesses retainer clips.
6. Replc wiper blades.
7. Rep inner shaft of drivers mirror before adjustment/tightening.
8. Rep L/frnt corner of box clearance light & install proper color lens.
9. Replc both pat area bench seat lid hold open pistons.
10. L/rear interior shelf hanging down; had to rem slide attachment rails & rep slide nuts; reattach slides to walls; adj height of shelf & tighten secure.
11. Drivers seat slide lock doesnt lock seat in position; fnd a arm bent; straighten; works ok.
12. Replc btry charge indictor panel lights.
13. Svc trans.
14. Svc rear diff.
15. Svc air dryer.
16. Svc btry tray slides.
17. Replc all eng drive belts.
18. Door open alarm inop; status center works ok; diss ovrhd panel & trace wiring frm status center to LED light/buzzer; fnd bad connection; mk ness rep; now all works ok.
19. Replc eng oil pan gskt.
20. Rem frnt breather asy frm fnt cvr & rep; reassem breather & reinstall on frnt cvr; install new hose & down draft tube.
21. Rem turbo oil return tube & replc splice hose; reinstall tube.
22. Rear A/C blows only cool; set up A/C machine & chk charge - low; sniff for leaks; fnd only one in low side Shrader valve; recvr, replc shrader valve; evac/recharge; now blows cold - 41 degrees.
23. Frnt A/C blows warm air; recvr freon - only 2 oz; compressor frnt seal blown; replc compressor, expansion valve, hi-side hose (comp to cond) & lo-side hose (exp valve to comp); vac down & recharge sys; now blows cold 33 degrees.
24. Rem shelving frm pat area compt; rem left wall to gain access to exh vent blower; replc blower fan asy & reassem wall/shelving.
25. Tractor/ABS "light on" on instrument panel; hookup computer & chk codes; fnd (1) - R/rear sensor out ofut of range; push sensor all the way into exciter ring & test drive; now light out. ja

032-0116549297 BATTERY INDICATOR	2
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	16
1782684-0020SEAT BELT 3POINT WPB	1
194BULB	10
29526898 29548988 TRANS FILTER ALLISON	1
39034753903475 BREATHER GSK	1
39121833286499 HOSE OIL RETURN	1
3920773WASHER DRAIN PLUG	1
3959052PAN GASKET B ENGINE	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
532703-0602 COMPRESSOR U4735 4471	1
6808200020LIGHT ASSY. TURN SIGNAL	2
8201L17-3428 ESTER OIL E7	1
90-075-10HOSE	1
9451BELT	1
9485BELT	1
A2241331001HOSE A/C HIGH SIDE	1
A2241332084A2241332084 HOSE A/C LOW	1
CA8193AIR FILTER 46744 WIX	1
ELB56711446175 BLOWER 4 IN	1
HLD3999GSS1715UV 30LB STRUT GAS	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
U-24RWIPER REFILL	1
V122XARESCUES MARKER LIGHT	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V35468

In Date: 10/06/2010
Close Date: 12/22/2010

Meter Reading: 89,168.00

Problem?

CHECK UNIT FOR RAT DAMDGE AT 25

Task performed:

(1) TRAVELED TO ST25 TO CHECK FOR RAT DAMAGE IN UNIT. RAN AND CHECKED OUT OK. J.W.

Parts

Quantity

NO PARTS USED

Workorder: V37700

In Date: 01/10/2011
Close Date: 01/18/2011

Meter Reading: 89,168.00

Problem?

ON CALL WONT START SER 3

Task performed:

Travel to locn; veh started; restart veh sev times; NPF; crew already swapped into diff rescue; travel home. j

Parts

Quantity

NO PARTS USED

Workorder: V37727

In Date: 01/10/2011
Close Date: 02/01/2011

Meter Reading: 89,168.00

Problem?

INTERMITTENT NO START SER4

Task performed:

1. T-shoot inte4rmittent no start; cln/tightene all connections; chk volt drops; replc ign switch.
2. Go to J&J, PU solenoid; drop off at Cummins; go to Intl, PU R-14. j

Parts

Quantity

468438C91IGN SWITCH

1

Workorder: V37377

In Date: 02/07/2011
Close Date: 02/14/2011

Meter Reading:

Problem?

intermittant No-Start

Task performed:

T-shoot no start; fnd loose connector at solenoid; term spins; R/R solenoid; still missing; R/R starter; all ok. j

Parts

Quantity

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

1

ESX120105112STARTER RELAY ESX-120-105112

1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38325

In Date: 02/07/2011

Meter Reading: 89,168.00

Close Date: 02/14/2011

Problem?

ON CALL WONT START SER 2

Task performed:

Parts

Quantity

Drive to Stn25; C/O SER2 intermittant; no start; brought back to shop - swapped out. j

NO PARTS USED

Workorder: V41064

In Date: 06/02/2011

Meter Reading: 90,306.00

Close Date: 06/16/2011

Problem?

B INSPECTION AND REPAIRS AS NEEDED SE R

Task performed:

Parts

Quantity

- B-Service
- 2. Chk/replc light; strobe on left frnt side light out.
- 3. Top off all tires w/air.
- 4. Top off all fluids - (1) qt 15W40.
- 5. Top off washer fluid.
- 6. Makeup compt sign & installed.
- 7. Chk cab A/C sys & top off; Chk back A/C sys & top off.
- 8. Rep fuse/wiring to shoreline charger - ok.
- 9. Cln up truk & wax cab; buff out paint/lenses. j

15W40BSYN OIL BULK QTS	2
L PLACARDLARGE SIDE PLACARD	2
L PLACARD INSERTLARGE PLACARD INSERT CARD	2
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
TURBO5TUBE - STROBE	1

Workorder: V44477

In Date: 10/18/2011

Meter Reading:

Close Date: 10/31/2011

Problem?

R39 Asset #10132471 Side door of pt compartment does not open from inside the rescue. Sta 25.

Task performed:

Parts

Quantity

Rep side door that wld not open. j

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47144

In Date: 02/07/2012

Meter Reading: 91,000.00

Close Date: 02/29/2012

Problem?

C INSPECTION AND REPAIRS SE R3

Task performed:

Parts

Quantity



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

1. C-INSPECTION.
2. C-INSPECTION.
3. REPLACE REAR ROOF CLEARANCE LIGHTS. FILE AND CLEAN RUSTY BULB SOCKETS AND PROTECT WITH WD-40. REPLACED CRACKED LENS.
4. REPLACED WIPER BLADE REFILLS.
5. REPLACE REAR MARKER BULBS.
6. REMOVED DOUBLE SIDED TAPE FROM BODY AND INSTALL NEW PUB ED PLACKARD FRAME.
7. REPLACED O2 GAUGE.
8. REMOVE DRIVERS DOOR PANEL AND REPLACED DOOR TOP TRIM PIECE. REPLACE MISSING SCREW.
9. REMOVE WIPER BLADES AND WASHERS NOZZELS. CLEAN NOZZEL OPENINGS AND REINSTALL. ADJ SQUIRTERS.
10. CLEAN AND PAINT FUEL CAP.
11. TIGHTEN ALL COMPT DOOR PANEL SCREWS. REPLACE STRIPPED AND MISSING SCREWS. TIGHTEN DOOR HOLD OPENS.
12. REPLACED REAR PATIENT COMPT SWITCH ROCKERS.
- 13.REPLACE SQUAD BENCH SHOCKS.
14. GLUE PATIENT COMPT WINDOW HANDLE.
15. COOLANT SERVICE, PRESSURE CHECK SYSTEM OK.
16. POWER STEERING SERVICE.
17. REPLACE BATTERY SWITCH HANDLE SCREW AND TIGHTEN.
18. REPLACE AIR FILTER, CLEAN HOUSING AND DIRT ON GASKET.
19. REPAIR CONNECTIONS FOR L REAR CENTER PATIENT COMPART. LOW BEAM BULBS.
20. CHECK ABS CODE "LOW VOLTAGE". ERASED CODE BUT CODE CAME BACK. NEED TROUBLESHOOTING LOW VOLTAGE PERFORM VALVE INLET AND OUTLET ACTUATOR TEST OK.
21. REMOVE R/REAR TIRES INSPECT FRAME RAIL SPIBER CRACK, E. EKHRE RECOMEND CHANGING OUT CRACK AND WELD. REASSEMBLE FOR REPAIR.
22. REAR BUMPER PUSHED IN - REMOVED SUPPORT AND NUT/BOLTS - PUSH OUT BENT SUPPORT INSTALL METAL SHIM, DRILL AND SECURE SHIM PLATE, SECURE ALL NUTS AND BOLTS.
23. L-2 DOOR JAM - DRILL AND CUT OUT OLD LOCK ASSEMBLY - INSTALL NEW LOCK ASSEMBLY AND ADJUST PULL NODS.
24. L-2 DOOR SEAL MISSING - CLEAN SURFACE, CUT AND INSTALL NEW DOOR SEAL.
25. ABS SUPPLY POWER CODE VOLTAGE TO LOW - CHECK VOLTAGE. VOLTAGE SQUARE GOOD -

1875627DOOR HANDLE LOCKING	1
68118132150CLENS RED MAR.LIGHT SUPER ADV.LT.BA	1
A1834388002MOLD L/H	1
CA8193AIR FILTER 46744 WIX	1
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
L PLACARDLARGE SIDE PLACARD	1
L1261F33585XE FUEL FILTER WIX	1
MG-C23SPMGC23 GAUGE	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT5492744435 ACTUATOR-BLACK	2
U-24RWIPER REFILL	1
VML-S1414FILTER P/S	1



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

CLEAN CODE AND TEST DRIVE NO CODE REAPPEAR.

26. PRESSURE WASH ENGINE.

27. CHECKING ENGINE OIL LEAK - OPERATE ENGINE UNABLE TO DETERMINE LOCATION OF ORIGINAL LEAK - NO LEAK PRESENT AT THIS TIME.

28. LOOSE CABLE ALONG FRAME RAIL - SECURE CABLE.

29. INSTALL REPLACEMENT FIRE EXTINGUISHER.

Workorder: V47458

In Date: 02/21/2012

Meter Reading: 91,000.00

Close Date: 02/29/2012

Problem?

REPAIR FRAME RAIL

Task performed:

REPAIR FRAME RAIL.

Parts

NO PARTS USED

Quantity

Vendor? TOTAL TRUCK PARTS

Workorder: V49375

In Date: 05/15/2012

Meter Reading: 91,158.00

Close Date: 05/31/2012

Problem?

A inspectoin, check for cleanliness, if can be used as spare

Task performed:

1. A-INSPECTION.
2. INSTALL ALL BATTERIES.
3. INSTALL 4 DRAWER SLIDES HAD TO FACILITATE TO MAKE NEW SLIDES WORK.
4. INSTALL ALL INSIDE COMPARTMENT SHOCKS.

Parts

01-0862064-00SIREN FRONT SIDE 1
 BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF 4
 HLD3999GSS1715UV 30LB STRUT GAS 6
 HP-31DBATTERY 950CCA HP-31D 4
 SLD5366HT4932-16 DRAWER SLIDE 16 4
 SPR-W58-1TEE PLASTIC 1

Quantity

Workorder: V53772

In Date: 11/14/2012

Meter Reading: 92,441.50

Close Date: 12/06/2012

Problem?

B INSPECTION SER 3

Task performed:

B INSPECTION OIL CHANGE SERVICES

Parts

NO PARTS USED

Quantity

Vendor? OIL CHANGE SERVICES



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V54365

In Date: 12/11/2012

Meter Reading: 92,573.00

Close Date: 12/26/2012

Problem?

REPAIR REAR FLASHER SE R AT 25 CHECK OIL LEAK

Task performed:

PARTS BILLED ON V53629

Parts

Quantity

H35DSN12BULB 35W DUAL FILAMENT DOME

1

STOPSN12BULB STOP/TAIL LIGHT

1

TURBO5TUBE - STROBE

1

Workorder: V58141

In Date: 06/03/2013

Meter Reading: 93,207.40

Close Date: 06/03/2013

Problem?

won't start

Task performed:

WENT TO 25 FOUND BATT DEAD- R&R 4
BATT-STARTED AND CHECK OK RETURN HOME.

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

4

HP-31DBATTERY 950CCA HP-31D

4

Workorder: V60007

In Date: 08/23/2013

Meter Reading: 93,450.00

Close Date: 08/30/2013

Problem?

will not start...batt seem to be charged but nothing when turning key to start

Task performed:

TRAVEL TO 25 STARTED TRUCK SEVERAL TIMES
RAN FINE.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V61071

In Date: 10/07/2013

Meter Reading: 93,450.00

Close Date: 10/11/2013

Problem?

C inspection SER3

Task performed:

1. C INSPECTION.
2. REPLACE BOTH REAR UPPER MARKER LIGHT ASSEMBLIES.
3. TROUBLESHOOT L/R UPPER WARNING LIGHT INOP FOUND LIGHT FIXTURE OPEN, REPLACE LIGHT ASSEMBLY.
4. REPLACE BULBS IN R/F PATIENT COMP LIGHT, REPLACE WIPER BLADES.
5. TIGHTEN MIRRORS.
6. CHECK PATIENT A/C, INOP, FOUND WIRES FOR PRESSURE SWITCHES CUT. REPAIRED WIRES, VACUUM AND RECHARGE SYSTEM CHECK FOR LEAKS.
7. ADJUST AND LUBE REAR PATIENT COMP. LATCHES. DOORS WERE LOOSE.
8. TROUBLE SHOOT SHORELINE CHARGER INOP, KEEPS POPING BREAKER, FOUND 110V CONNECTION AT CHARGER LOOSE.
9. REMOVE ACCREDITATION DECALS.
10. REPAIR REAR STAIR CHAIR LATCH ASSEMBLY, DID NOT HAVE CORRECT HANDLE, MODIFY PARTS OFF OF PARTS TRUCK TO REPAIR HANDLE.
11. RESECURE PARKING BRAKE VALVE, LOOSE IN DASH.
12. TIGHTEN ALL EXHAUST CLAMPS.
13. TIGHTEN HUB CAPS, LOOSE AND NOISY.
14. TIGHTEN R/R RUB RAIL, LOOSE FROM DAMAGE
15. Q.A. INSPECTION.
16. TIE UP WIRE LOOMS HANGING DOWN ON BACK SIDE OF TRUCK.

Parts

Quantity

02038332800REFLECTOR	1
1501450007750USE 0775145	1
322502BULB PATIENT GH22	1
46892-546892-5 MARKER LAMP	2
52-24WIPER BLADES ANCO 24	2
906LIGHT BULB 12CP	1
KN20901KN20901 KNOB PARKING BRAK	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
R134AFREON LB	3
S3225PFUEL FILTER 33630 LFF5849	1

Workorder: V63631

In Date: 01/22/2014

Meter Reading: 93,450.00

Close Date: 03/05/2014

Problem?

REPLACE STARTER SE R 1 AT 25.

Task performed:

WILL REPAIR AT SHOP.

Parts

Quantity

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043	1
------------------------------------------------	---



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V63647

In Date: 01/23/2014

Meter Reading:

Close Date: 03/27/2014

Problem?

starter seems to be hanging up intermitly...i was able to reproduce it for ed he said needs new starter Starter Charged out on V636

Task performed:

1. MOVE VEH INTO SHOP, PUT VEH HOISTS DISCONNECT BATTERIES R&R STARTER RECONNECT BATTs AND TEST.
2. PACK UP OLD STARTER INTO BOX FROM NEW STARTER AND PLACE INTO CORE BIN. RESET STARTER OPERATION.
3. A-INSP.
4. R&R WIPER BLADES.
5. R&R LENS R&R BULB IN CAB DOME LT.
6. R&R LENS BULB PATIENT AREA CEILING LT.
7. L/R TURN SIG OU. NOT BULB, DIAGNOSE. R&R LIGHT ASSY PROBLEM IN WIRING. R&R ACCESS COVERS CHECK HARNESS AND CONNECTORS UNDER L/R OF VEH.
8. ON BOARD BATT CHARGER NOT WORKING. CHECK 12V AND 110V WIRING AND FUSES ETC. PROBLEM IN 110V SIDE. REPAIRED.
9. CHECK PATIENT A/C NO CLUTCH ENGAGE. DIAGNOSE ELECTRICAL SYSTEM. REPAIR CLUTCH GROUND CIRCUIT. RUN SYSTEM DISCH, EVAC AND RECHARGE SYSTEM WAS 1LB LOW ON FREON.

Parts

Quantity

1156BULB

1

52-24WIPER BLADES ANCO 24

2

Workorder: V68228

In Date: 07/28/2014

Meter Reading: 93,450.00

Close Date: 09/16/2014

Problem?

will not start

Task performed:

Jump started truck and charged batteries.

Parts

Quantity

NO PARTS USED

Workorder: V72290

In Date: 01/13/2015

Meter Reading: 94,000.00

Close Date: 01/16/2015

Problem?

Patient a/c inop

Task performed:

Travel to ST 17. Charged a/c system. Very low. System leaks.

Parts

Quantity

NO PARTS USED



3/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10132471

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V71629

In Date: 12/13/2014

Close Date: 02/24/2015

Meter Reading: 94,000.00

Problem?

B inspection SER3 OCS

Task performed:

B inspection

Parts

Quantity

L1261F33585XE FUEL FILTER WIX

1

PH8942FILTER OIL 57182 LFP3729

1

S3225PFUEL FILTER 33630 LFF5849

1

Vendor? OCS

Workorder: V73996

In Date: 03/18/2015

Close Date: 05/12/2015

Meter Reading:

Problem?

parking brake not engaging properly, sometimes transmission goes out of gear when stopped. SER AT 25

Task performed:

1. Parking brake valve exhaust line was clogged.
Cleaned out line and tested valve ok.

Parts

Quantity

NO PARTS USED



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

Asset: (10132471) 2000 - FREIGHTLINER FL60 Advanced Life Support Vehicle

10132471

CSHOP-2015-1336

Comments: SPEC EVENTS RESCUE AT 25 NOT STARTING, SHORELINE HAS POWER AND HAS BEEN PLUGGED IN SINCE LAST USED 2 WEEKS AGO

Date Opened 6-23-2015 Date Finished 6-23-2015 Meter 1 Reading: 94,432

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

CSHOP-2015-3464

Comments: DEAD BATTERY @25 PLUGGED NOT CHARGING?

Date Opened 10-16-2015 Date Finished 10-26-2015 Meter 1 Reading: 94,680

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
BATTERY

4 BATTERY; BATTERY 950CCA HP-31D
4 BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY

CSHOP-2016-2845

Date Opened 6-14-2016 Date Finished 6-29-2016 Meter 1 Reading: 94,993

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FUEL FILTER 33630 LFF5849
17 FLUID; SYN OIL BULK QTS
1 FILTER; 33585XE FUEL FILTER WIX
1 FILTER; AIR FILTER 46744 WIX
1 FILTER; FILTER OIL 57182 LFP3729

Asset Work Order History 10132471

CSHOP-2016-2851

Comments: **PM FOLLOW UPS**

Date Opened 6-14-2016

Date Finished

7-1-2016

Meter 1 Reading:

94,993

TASKS PERFORMED

Q PARTS

FUEL FILL BODY	1	REFLECTOR; REFLECTOR RED 40132 GROTE
EQUIPMENT MOUNTING BRACKETS	2	WIPER; WIPER BLADES ANCO 24
DOOR LATCH	1	WASHER; WASHER NOZZLE W/RELIEF
RADIO	1	DRAIN; 3959453S DRAIN KIT
WIPER BLADES	8	FLUID; COOLANT ANTIFREEZE GAL
WIPERS-WASHER	1	BULB; BULB
FUEL TANK	4	BATTERY; BATTERY 950CCA HP-31D
FUEL SYSTEM	4	BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY
COOLING SYSTEM	5	FLUID; ALLISON TRANS FLUID GAL
FAULT CODE	1	FILTER; 29548988 TRANS FILTER ALLISON
REPAIR FROM PM - DRY AIR CLEANER	1	BELT; BELT
PARK-CLEARANCE LIGHTS	1	BELT; BELT
BATTERY	1	BELT; BELT
ELECTRICAL	1	FREIGHTLINER; NEW# 3184640001 STEERING WHEEL
TRANSMISSION	1	FREIGHTLINER; PIN TURN SIGNAL STEERING WHEEL
REPAIR FROM PM - BELTS	1	FLUID; ALLISON TRANS FLUID GAL
STEERING WHEEL	1	FILTER; FILTER P/S
RESERVOIR	1	GASKET; GASKET P/S COVER
REPAIR FROM PM - DECALS/CLEANLINESS	1	DRYER; DRYER KIT
AIR DRIER	2	DRAIN; DRAIN COCK
AIR SYSTEM	1	TUBE; STROBE TUBE
STROBE LIGHTS	1	RELAY; RY48 RELAY
AIR HORN	2	HORN; KIT-AIR HORN-GROVER
DOOR HINGE-PINS-BUSHINGS	1	HORN; HORN HIGH NEW # 06-52125-039
DOOR	1	CAP; 5580 CAP-BLACK R134A
SEAT BELTS		
UPHOLSTERY		
INSTRUMENT CLUSTER		
INSTRUMENTS-GAUGES-WARNING &		
AIR CONDITIONING		

Asset Work Order History 10132471

CSHOP-2016-4854

Date Opened 10-11-2016 Date Finished 11-17-2016 Meter 1 Reading: 94,993

TASKS PERFORMED

ABS CODES
BLEED-FLUSH BRAKES
HOSES-LINES & FITTINGS (AIR &
BRAKES
AIR SYSTEM
BACK-UP ALARM

Q PARTS

1	BRAKE; BRAKE HOSE ASSY
1	BRAKE; BRAKE HOSE
2	NEWPART; HOSE HYDRAULIC
1	NEWPART; BRAKE HOSE DROP DOWN STERLING
1	ALARM; BACKUP ALARM ECCO 107 DEC
1	NEWPART; ABS MODULE HYD BRAKES
-1	EXHAUST; WRAP 2 IN WIDE
1	EXHAUST; WRAP 2 IN WIDE
1	NEWPART; BRAKE FLUID
2	GASKET; R002436 GASKET-REAR AXLE
2	CALIPER; CALIPER F/R RESCUE 55314 NEW
1	NEWPART; MASTER CYLINDER
2	SENSOR; ABS SENSOR FRONT OLD # S4410328130
2	CAP; 340-4065 CAP OIL STEMCO/CR
3	NUT; LUG NUT COVER PK10
3	NUT; LUG NUT COVER PK10
3	NUT; 13-3052 NUT
2	SEAL; SEAL
2	BRAKE; 141-70003 BRAKE CALIPER REAR ONLY MACHINED
2	SENSOR; R955342 SENSOR REAR ABS 4410328140
2	BRAKE; BRAKE PADS
2	SEAL; SEAL 34387
2	VALVE; VALVE LEVELIN

CSHOP-2017-1874

Comments: **WAS USED TO BILL GOLF CART TIRES**

Date Opened 3-28-2017 Date Finished 3-28-2017 Meter 1 Reading: 95,971

TASKS PERFORMED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

NO PARTS USED

CSHOP-2017-2339

Comments: **USE A FORM**

Date Opened 4-20-2017 Date Finished 5-20-2017 Meter 1 Reading: 95,997

TASKS PERFORMED

PM SERVICE B

NO PARTS USED

CSHOP-2017-3590

Date Opened 6-16-2017 Date Finished 6-17-2017 Meter 1 Reading: 95,971

TASKS PERFORMED

TRAVEL TO BE CHARGED TO WORK ORDER

NO PARTS USED

Asset Work Order History 10132471

CSHOP-2018-3715

Comments: **FOLLOW-UP REPAIRS**

Date Opened 7-2-2018

Date Finished

7-30-2018

Meter 1 Reading:

97,449

TASKS PERFORMED

Q PARTS

STORAGE CABINET EMERGENCY VEH
RADIATOR
ENGINE AND ACCESSORIES
LIGHTING SYSTEM
AIR CONDITIONING

3 9IP; M1-63-8 LATCH STAINLESS
1 2FL; RADCORE
1 9HY; HOSEFITTING
1 9HY; HOSE
1 NONSTOCK; FREIGHT CHARGE
1 9AP; CONDENSOR
1 9IP; 030602COMPRESSORU47354471
1 9HY; FITTING
1 TEM; EXPVALV
1 9HY; FITTING
1 TEM; STEELFILTERDRIER
2 9XX; 134A10194654
1 9HY; FITTING

CSHOP-2018-3716

Date Opened 7-2-2018

Date Finished

7-6-2018

Meter 1 Reading:

97,448

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

4 1AD; BATTERY31SERIES
20 4PC; 15W40PREMIUMBLUEOIL
1 FIL; NAPAGOLDOILFILTER
1 FIL; NAPAGOLDFUELFILTER
2 1AN; WIPERBLADE24IN

CSHOP-2018-4670

Date Opened 8-20-2018

Date Finished

9-4-2018

Meter 1 Reading:

97,449

TASKS PERFORMED

Q PARTS

BATTERY
TIRE

1 1AD; BATTERY
1 1AD; 65 SERIES BATTERY
1 1AD; 65 SERIES BATTERY

CSHOP-2018-4678

Date Opened 8-20-2018

Date Finished

8-20-2018

Meter 1 Reading:

97,449

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

Asset Work Order History 10132471

CSHOP-2018-5640

Comments: **SPECIAL EVENTS TRUCKS**

Date Opened 10-3-2018 Date Finished 11-7-2018 Meter 1 Reading: 97,449

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
FAULT CODE

CSHOP-2018-6361

Date Opened 11-8-2018 Date Finished 1-11-2019 Meter 1 Reading: 97,449

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR HORN

CSHOP-2018-6958

Comments: **DOOR HANDLES BROKEN**

Date Opened 12-7-2018 Date Finished 12-13-2018 Meter 1 Reading: 97,449

TASKS PERFORMED

NO PARTS USED

CHARGING SYSTEM
DOOR
