



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V269

In Date: 10/17/2005  
Close Date: 10/21/2005

Meter Reading: 25,295.00

### Problem?

110V A/C INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED

## Workorder: V271

In Date: 10/18/2005  
Close Date: 11/02/2005

Meter Reading:

### Problem?

R/SIDE AIR HORN INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED

## Workorder: V534

In Date: 11/02/2005  
Close Date: 12/22/2005

Meter Reading:

### Problem?

LIGHT OUT IN LIGHT BAR R35

Task performed:

Parts

Quantity

AS75600MONI-A01 O2 MINDER KIT

1

## Workorder: V1088

In Date: 01/03/2006  
Close Date: 01/09/2006

Meter Reading:

### Problem?

NEED WIPER BLADES, LIGHT OUT ON FRONT LIGHT BAR, R-35

Task performed:

Parts

Quantity

52-24WIPER BLADES ANCO 24

5

H20SN12H20SN12 BULB

4



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V1258

In Date: 01/23/2006

Meter Reading:

Close Date: 01/24/2006

#### Problem?

D/SIDE STROBE LIGHT INOP, R-35

#### Task performed:

Parts	Quantity
16450STARTER	1
TURBO5TUBE - STROBE	3

#### Workorder: V1316

In Date: 01/26/2006

Meter Reading: 29,771.00

Close Date: 02/22/2006

#### Problem?

B INSPECTION R35

#### Task performed:

See B Inspection pre-printed form

Parts	Quantity
012-5071-00-0KNOB DRAIN VALVE	1
05-17223-000CAP RADIATOR 10 LB	1
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
353R023HURST HOSE W/O SWIVEL	1
6807600070HANDLE DOOR EXT L/H	1
800405PURGE VALVE KIT	1
CH27007BUMPER DOOR	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

#### Workorder: V1764

In Date: 03/07/2006

Meter Reading:

Close Date: 03/17/2006

#### Problem?

FRONT A/C INOP, R-35

#### Task performed:

Parts	Quantity
NO PARTS USED	



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V1885

In Date: 03/17/2006

Meter Reading:

Close Date: 03/31/2006

#### Problem?

repair stretcher R19 (outside service-EMSAR MEDCO)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? MEDC0003

### Workorder: V1964

In Date: 03/27/2006

Meter Reading:

Close Date: 04/04/2006

#### Problem?

REAR A/C INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V1886

In Date: 03/16/2006

Meter Reading:

Close Date: 04/12/2006

#### Problem?

repair stretcher R35 (OUTSIDE VENDER MEDCO EMSAR)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? MEDC0003

### Workorder: V2166

In Date: 04/10/2006

Meter Reading:

Close Date: 04/14/2006

#### Problem?

OXYGEN GAUGE ON MAIN TANK INOP, R-35

Task performed:

Parts

Quantity

AS75600MONI-A01 O2 MINDER KIT

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V2268

In Date: 04/18/2006

Meter Reading:

Close Date: 04/25/2006

#### Problem?

PAT, COMPT, LIGHTS INOP, (2) SHORE LINE INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V2410

In Date: 04/28/2006

Meter Reading:

Close Date: 05/01/2006

#### Problem?

SIREN INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V2390

In Date: 04/26/2006

Meter Reading:

Close Date: 05/11/2006

#### Problem?

emergency repair stretcher- R35 (outside agency-emsar medco)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? MEDC0003

### Workorder: V2582

In Date: 05/12/2006

Meter Reading:

Close Date: 05/22/2006

#### Problem?

L/FRONT RED STROBE ON SIDE OF PAT. BOX INOP, R-35

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V3119

In Date: 06/02/2006

Meter Reading:

Close Date: 06/23/2006

#### Problem?

repair seat R35 (outside agency-Central auto trim)

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? CENT0002

#### Workorder: V3010

In Date: 06/16/2006

Meter Reading:

Close Date: 06/27/2006

#### Problem?

P/SIDE BOX DOOR HINGE ON TOP OF DOOR BROKEN, R-35

Task performed:

Parts

Quantity

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

1

#### Workorder: V3291

In Date: 07/05/2006

Meter Reading:

Close Date: 07/10/2006

#### Problem?

ON CALL OIL LEAK R35

Task performed:

Parts

Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

#### Workorder: V3491

In Date: 07/16/2006

Meter Reading:

Close Date: 07/17/2006

#### Problem?

TAILPIPE FALLEN OFF ON CALL R35

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V3324

In Date: 07/06/2006

Close Date: 07/27/2006

Meter Reading:

#### Problem?

OIL LEAK R35

Task performed:

Parts

Quantity

ELB56711446175 BLOWER 4 IN

1

SLD5366HT4932-16 DRAWER SLIDE 16

2

### Workorder: V3806

In Date: 08/07/2006

Close Date: 08/07/2006

Meter Reading:

#### Problem?

ON CALL R 35 INVOLVED IN ACCIDENT

Task performed:

Parts

Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V3817**

**In Date:** 08/07/2006

**Meter Reading:** 36,122.00

**Close Date:** 08/25/2006

**Problem?**

B INSPECTION AND REPAIRS AS NEEDED R35

**Task performed:**

ACIDENT DAMAGE RT REAR

Parts	Quantity
040444-01EXPANSION VALVE R-22	1
071601A07-0602A DRIER A/C 7118	2
107796DRYER KIT AD9 -NEW	1
12-2012AVALVE EXPANSION 1600 NEW # 12-0612A HOSE	1
18-29935-001RH DOOR LATCH NEW	1
2860528605 SPLICE HOSE 3/4"	1
52-24WIPER BLADES ANCO 24	2
5C-91345C-9134 LOUVER	1
91513AMBER LENS	2
9451BELT	1
9485BELT	1
98003RREFLECTOR RED 40132 GROTE	2
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
CH27007BUMPER DOOR	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HLD374211 IN HOLD-OPEN 30LB	2
HLD39914GSS7139UK STRUT 90#	2
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MISC PARTMISC PART	1
MK184HDBRAKE PADS	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	2



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V4276

In Date: 09/06/2006

Meter Reading: 25,092.00

Close Date: 09/08/2006

#### Problem?

A INSPECTION AND REPAIRS AS NEEDED R35

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V4302

In Date: 09/07/2006

Meter Reading: 36,189.00

Close Date: 09/08/2006

#### Problem?

ON CALL DOOR OPEN LT ON R35

#### Task performed:

#### Parts

#### Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

4

HP-31DBATTERY 950CCA HP-31D

4

#### Workorder: V4701

In Date: 10/02/2006

Meter Reading: 4,308.00

Close Date: 10/26/2006

#### Problem?

SIDE PT COMPARTMENT DOOR IS HARD TO OPEN AND CLOSE. R-35

#### Task performed:

#### Parts

#### Quantity

1. TRAVELED TO STN 35. GREASED TOP DOOR SPRINGS FOR DOOR.

NO PARTS USED

2. TRACED OUT PROBLEM WITH REAR LOAD LIGHTS AND FOUND BAD CONNECTION REPAIRED BAD CONNECTION.

#### Workorder: V5138

In Date: 10/29/2006

Meter Reading: 38,117.00

Close Date: 11/07/2006

#### Problem?

The patient compartment exhaust fan does not work (safety issue) The a/c in the patient compartment does not blow cold when plugged in to the shore line. The front grill and light bar have red lights out. R35

#### Task performed:

#### Parts

#### Quantity

1. recharge rear a/c (110 unit)

NO PARTS USED

2. repair emergency warning lights





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V5190

In Date: 10/31/2006

Meter Reading: 4,419.00

Close Date: 11/07/2006

#### Problem?

Pin & cotter pin holding right side equipment door latch missing. R35

#### Task performed:

#### Parts

#### Quantity

1. repair compartment door hold open assenbly

NO PARTS USED

#### Workorder: V4690

In Date: 10/02/2006

Meter Reading: 4,281.00

Close Date: 11/08/2006

#### Problem?

rear scene lights on r35 do not work and the rear flasher lights do not work. R35

#### Task performed:

#### Parts

#### Quantity

1. TRAVELED TO STN 74. R/R POWER PACK AND B STROBE LIGHTS FOUND SHORT IN ONE STROBE.

NO PARTS USED

#### Workorder: V5282

In Date: 11/07/2006

Meter Reading: 4,435.80

Close Date: 11/13/2006

#### Problem?

on board oxygen regulator valve won't seal to tank. R35

#### Task performed:

#### Parts

#### Quantity

1. TRAVELED TO STN 35. CHECKED FOR O2 LEAK FOUND NONE. INSTALLED NEW REGULATOR AND FITTING ABOUT 1 WEEK AGO.

01-0416333-00LIGHT ROTATOR

2

ELB56711446175 BLOWER 4 IN

1

#### Workorder: V5485

In Date: 11/22/2006

Meter Reading: 4,484.90

Close Date: 11/28/2006

#### Problem?

the right tail light assembly fell off and is hanging by the wires. R35

#### Task performed:

#### Parts

#### Quantity

1. TRAVELED TO STN 35. NUT SERTED TRUCK BODY AND INSTALLED LIGHT ASSEMBLY.  
2. INSTALLED BRAKE LIGHT BULB.

STOPSN12BULB STOP/TAIL LIGHT

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V5603

In Date: 11/29/2006

Meter Reading: 38,983.00

Close Date: 12/04/2006

#### Problem?

REPAIR STRETCHER AT STA 35 R35 MEDCO EQUIP.

#### Task performed:

Parts

Quantity

1. repair strecher on r35

NO PARTS USED

Vendor? MEDCO EQUIPMENT

#### Workorder: V5795

In Date: 12/13/2006

Meter Reading: 4,571.90

Close Date: 12/21/2006

#### Problem?

N2PU Diagnostic error on R35

#### Task performed:

Parts

Quantity

1. Installed new exhaust fan in rescue

NO PARTS USED

#### Workorder: V6082

In Date: 01/03/2007

Meter Reading: 4,639.50

Close Date: 01/08/2007

#### Problem?

one rotater light is out on the front light bar and also one is out on the rear light bar. R18

#### Task performed:

Parts

Quantity

1. R&R strobe light in light bar

NO PARTS USED

#### Workorder: V6060

In Date: 01/02/2007

Meter Reading: 40,022.00

Close Date: 01/23/2007

#### Problem?

flat repair r35 callaghan ent

#### Task performed:

Parts

Quantity

1. UNIT SENT TO CALLAGHAN FOR TIRE REPAIR.

NO PARTS USED

Vendor? CALLAGHAN TIRE



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V6592

In Date: 02/02/2007

Meter Reading: 41,289.00

Close Date: 02/06/2007

#### Problem?

High idle on Rescue will not come on. R35

#### Task performed:

Parts

Quantity

1. Found no problem with fast idle system works fine

NO PARTS USED

### Workorder: V6441

In Date: 01/24/2007

Meter Reading: 4,720.00

Close Date: 02/26/2007

#### Problem?

the front and rear light bar each have one rotator flashing light out. marker light out on cab, patient compartment has dome light out. action area in pt compartment has a light out. the rescue has a small oil leak. r35

#### Task performed:

Parts

Quantity

CHECK TRUCK-HAS BAD OIL LEAK-SWAP OUT

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V6675**

**In Date:** 02/08/2007

**Meter Reading:** 41,463.00

**Close Date:** 02/27/2007

**Problem?**

b inspection and repairs as needed r35

#### Task performed:

- B-Inspection
- 1. Svc rear axle
- 2. Replc oil pan gasket
- 3. Torque U-Bolts
- 4. Tighten exhaust pipe clamps
- 5. Svc dryer, rebuild purge valve
- 6. Svc batteries
- 7. Svc cooling system
- 8. Rep broken alt ground wire
- 9. Replc LF patient high beam bulb; dia actionary lite; fnd bad fixture; replc fixture;  
splice & protect wires; grind fixture flat
- 10. Rep door hold opens; missing 7 loose screws; replc cabinet door shocks & brackets.
- 11. Ck computer codes, trans codes, & ABS codes
- 12. Work on Sefac lifts; r/r plugs; swapout lifts/dia; swap back lifts & plugs.
- 13. Ck for O2 leak; replc fitting at tank connection.
- 14. Replc RF & LR rotator bulb; replc roof clearance & LF marker bulbs; replc map light assy; drill/rewire/rem frozen bolt.
- 15. Repair Kussmall battery charger
- 16. Install flag decals
- 17. replce wiper blades
- 18. replc horns; repair pigtail
- 19. replc all (6) tires.

#### Parts

#### Quantity

032-0116549297 BATTERY INDICATOR	1
107796DRYER KIT AD9 -NEW	1
322502BULB PATIENT GH22	1
3920773WASHER DRAIN PLUG	1
3959052PAN GASKET B ENGINE	1
5005037KIT MAINT. AD-9	1
52-24WIPER BLADES ANCO 24	2
680-10LAMERICAN FLAG W UV CLEAR LEFT	1
680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1
AS79934ACT AREA LIGHT	1
H50SN12BULB	2
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
LF18ESUSE LED MAP LIGHT	1
M54-13SPM5413 NIPPLE	1
PH8942FILTER OIL 57182 LFP3729	1
RP00126BRACKET - HOLD OPEN	1
S3225PFUEL FILTER 33630 LFF5849	1
SS-62NUT FOR M54-13 NIPPLE	1

**Workorder: V6749**

**In Date:** 02/14/2007

**Meter Reading:** 41,463.00

**Close Date:** 03/06/2007

**Problem?**

replace tires at callaghan ent r35

#### Task performed:

Replaced tires at Callaghan Ent

#### Parts

#### Quantity

NO PARTS USED

**Vendor?** CALLAGHAN ENT



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V7260

In Date: 03/19/2007

Meter Reading: 42,635.00

Close Date: 03/20/2007

#### Problem?

rear light bar has a rotator light out. The side patient compartment door latch is broken and is loose and does not latch in the correct position R35

#### Task performed:

#### Parts

#### Quantity

1. Repaired side entry door latch
2. Replaced bulb in rear light bar
3. Repaired door lock on cab door

NO PARTS USED

#### Workorder: V7411

In Date: 03/28/2007

Meter Reading: 4,937.30

Close Date: 04/03/2007

#### Problem?

the red emergency strobe lights on both sides of the box have a short and go on and off and do not stay on. rear light bar has a rotator light out, right side load light is out. R-35

#### Task performed:

#### Parts

#### Quantity

Replaced strobe bulbs

H50SN12BULB

3

TURBO5TUBE - STROBE

3

#### Workorder: V7661

In Date: 04/11/2007

Meter Reading: 43,622.00

Close Date: 04/16/2007

#### Problem?

repair broken stretcher (outside agency-medco emsar) R35

#### Task performed:

#### Parts

#### Quantity

Repaired broken stretcher Medco Equipment Repair

NO PARTS USED

Vendor? \*

#### Workorder: V7747

In Date: 04/16/2007

Meter Reading: 43,676.00

Close Date: 04/25/2007

#### Problem?

Driver side rear of Rescue truck, Airbag is not inflating. Truck sits uneven. r35

#### Task performed:

#### Parts

#### Quantity

Measured frame of truck to ground & checked ok; fnd rear bumper bent up.  
Adjusted rear door linkage due to hard to open.  
Recharged 110 A/C unit that was blowing warm.

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V7803

In Date: 04/18/2007

Meter Reading: 43,861.00

Close Date: 04/30/2007

### Problem?

the pt compartment side door metal rod that keeps the door from swinging open into the truck broke. r35

### Task performed:

Replace side entrance door;  
repaired 110 A/C-recharged

### Parts

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

### Quantity

2

## Workorder: V7856

In Date: 04/21/2007

Meter Reading: 43,970.00

Close Date: 04/30/2007

### Problem?

the rear a/c does not work when the unit is plugged into the shore line R-35

### Task performed:

Rep 110 outlet going to truck

### Parts

NO PARTS USED

### Quantity

## Workorder: V8179

In Date: 05/10/2007

Meter Reading: 44,501.00

Close Date: 05/31/2007

### Problem?

REAR DOME LIGHTS INOP, R-35

### Task performed:

Found bad connection in light  
Adj front air horns  
Checkd problem w/110 A/C; fnd unit low on charge;  
recharged

### Parts

NO PARTS USED

### Quantity

## Workorder: V8187

In Date: 05/10/2007

Meter Reading: 5,124.00

Close Date: 05/31/2007

### Problem?

Air horn not functioning properly. R-35

### Task performed:

Adjusted air horns

### Parts

NO PARTS USED

### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V8414

In Date: 05/24/2007

Meter Reading: 45,164.00

Close Date: 06/01/2007

#### Problem?

shoreline a/c not very cold R35

#### Task performed:

Parts

Quantity

1. Recharged A/C

NO PARTS USED

#### Workorder: V8109

In Date: 05/04/2007

Meter Reading: 44,501.00

Close Date: 06/05/2007

#### Problem?

windshield washer not working R-35

#### Task performed:

Parts

Quantity

1. repaired washer hose
2. repaired rear fold down step nut serted step

NO PARTS USED

#### Workorder: V8225

In Date: 05/12/2007

Meter Reading: 44,677.00

Close Date: 06/05/2007

#### Problem?

the rear a/c blows warm air when the truck is in the station plugged into the shore line. R-35

#### Task performed:

Parts

Quantity

1. Recharged rear110V A/C unit

NO PARTS USED

#### Workorder: V8228

In Date: 05/13/2007

Meter Reading: 5,138.20

Close Date: 06/05/2007

#### Problem?

Weather stripping around the glass on the rear patient compartment doors is coming apart. R-35

#### Task performed:

Parts

Quantity

1. Repaired weather stripping on rear window

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V8361

In Date: 05/22/2007

Meter Reading: 5,177.00

Close Date: 06/05/2007

#### Problem?

Re-charge shoreline A/C system;pt compartment A/C system only blowing hot air when plugged in. r35

#### Task performed:

#### Parts

#### Quantity

1. Rrepaired bad connection in 110V outlet plug
2. Readjusted left and right isde airhoses and repaired broken air line
3. Checked problem with siren head on left side found broken wire

NO PARTS USED

#### Workorder: V8684

In Date: 06/08/2007

Meter Reading: 45,606.00

Close Date: 06/19/2007

#### Problem?

pt compartment has a dome light out, rear a/c is out and blows warm air when the unit is plugged into the shoreline. Marker light is out on the cab. R35

#### Task performed:

#### Parts

#### Quantity

1. Checked rear 110 a/c and checked OK
2. Repaired bad connection on left side pt light
3. Repaired marker light clean socket for light bulb

NO PARTS USED

#### Workorder: V8222

In Date: 05/12/2007

Meter Reading: 44,677.00

Close Date: 06/26/2007

#### Problem?

front lightbar has a rotator light out. R-35

#### Task performed:

#### Parts

#### Quantity

1. Replaced bulb in rear Pt Compartment

322502BULB PATIENT GH22

2

#### Workorder: V8490

In Date: 05/30/2007

Meter Reading: 5,206.80

Close Date: 06/26/2007

#### Problem?

the front light bar has a rotator light out. The pt compartment has a dome light out. R35

#### Task performed:

#### Parts

#### Quantity

1. Replaced bulb in light bar
2. Traced out problem with door open light on - found battery tray switch off repaired switch
3. Adjusted A/C belts and repaired small leak in A/C system

H27SN12BULB

2





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V8732

In Date: 06/12/2007

Meter Reading: 5,261.90

Close Date: 06/29/2007

#### Problem?

replace stamp metal door latch on sheet compartment. R-35

#### Task performed:

1. Replaced latch

#### Parts

LTC1020606LATCH

#### Quantity

1

#### Workorder: V8993

In Date: 06/24/2007

Meter Reading: 5,313.70

Close Date: 07/06/2007

#### Problem?

Re-charge air conditioner and/or fix refrigerant leak. R35

#### Task performed:

1. 110 a/c compressor needs to be changed out

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V8931

In Date: 06/20/2007

Meter Reading: 5,290.00

Close Date: 07/16/2007

#### Problem?

Cracked front windshield r35

#### Task performed:

Replaced crack front windshield Safelite Glass

#### Parts

NO PARTS USED

#### Quantity

Vendor? SAFELITE GLASS

#### Workorder: V9276

In Date: 07/12/2007

Meter Reading: 46,807.00

Close Date: 07/17/2007

#### Problem?

The low voltage alarm is on and the rescue is only running at 12.9- 13.5 volts at high idle. This started at 0200 today. the rescue was fine with no problems prior to this morning. r35

#### Task performed:

1. TRAVEL TO 35. REPLACED DEFECTIVE ALTERNATOR.

#### Parts

4867JB320 UPGRADE ALTERNATOR

#### Quantity

2



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V9206

In Date: 07/08/2007

Meter Reading: 5,357.70

Close Date: 07/18/2007

#### Problem?

Driver side cab clearance light burned out. R-35

#### Task performed:

Rep marker light that had water in it

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V9505

In Date: 07/23/2007

Meter Reading: 5,379.00

Close Date: 07/30/2007

#### Problem?

When the rescue was parked on a hill the parking brake failed. The brake works fine on a level surface however on a hill the brake does not hold. r35

#### Task performed:

Adj parking brake & tested  
Load lights inop; rep bad ground

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V9684

In Date: 08/02/2007

Meter Reading: 47,479.00

Close Date: 08/10/2007

#### Problem?

ON CALL AIR LEAK R 35

#### Task performed:

Call out to STN35 to rep leak on rescue

#### Parts

#### Quantity

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

#### Workorder: V10338

In Date: 09/10/2007

Meter Reading: 5,379.70

Close Date: 09/26/2007

#### Problem?

Driver compartment door (airpack door) is not functioning properly. The spring loaded hinge has a broken bracket. This makes the door difficult to close. r35

#### Task performed:

1. DROVE TO STA 35, R/R SPRING ON DRIVER SIDE  
COMPARTMENT REAR DOOR.

#### Parts

#### Quantity

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V10391

In Date: 09/12/2007

Meter Reading: 5,379.00

Close Date: 09/27/2007

#### Problem?

right side hinge on the top of door in driver compartment is broken. r35

#### Task performed:

1. Replc hinge on L-1 compt
2. Chkd problem with 110 A/C unit; fnd A/C compressor NG

#### Parts

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

#### Quantity

1

#### Workorder: V10460

In Date: 09/15/2007

Meter Reading: 49,026.00

Close Date: 09/27/2007

#### Problem?

The a/c in the pt compartment is only blowing cool air not cold air. The temp in the rescue is 85 degrees. R35

#### Task performed:

Cleaned condenser fans & recharged sys

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V10461

In Date: 09/15/2007

Meter Reading: 5,379.70

Close Date: 09/27/2007

#### Problem?

The red stroblight on the passenger side box is shorted out, The red/amber strobe light on the left rear box is also shorted out. R3

#### Task performed:

replc strobe bulb in rear of truck

#### Parts

TURBO5TUBE - STROBE

#### Quantity

2

#### Workorder: V10617

In Date: 09/24/2007

Meter Reading: 49,248.00

Close Date: 09/27/2007

#### Problem?

A/C INOP, R-35

#### Task performed:

1. RECHARGED SYSTEM AND TESTED.

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V10645

In Date: 09/24/2007

Meter Reading: 5,379.00

Close Date: 10/01/2007

#### Problem?

The rescue is leaking oil. One quart a day has to be added. There is also a loose belt in the engine compartment. R-35

#### Task performed:

1. FOUND OIL FILTER LEAKING- REPAIRED
2. ADJUSTED AIR HORN
3. CHECKED PROBLEM WITH HORN BUTTON- FOUND BAD CONNECTION

#### Parts

39682023976511 OIL CAP ISL

#### Quantity

1

#### Workorder: V8050

In Date: 05/02/2007

Meter Reading: 5,095.50

Close Date: 10/15/2007

#### Problem?

Rear headset was replaced, but the person speaking into it, cant be heard from the crews upfront. Rear headset can hear the crew

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V10807

In Date: 10/03/2007

Meter Reading: 5,379.00

Close Date: 10/22/2007

#### Problem?

The rescue has an oil leak and has to have a quart of oil added every third day. Marker light out on cab, front grill red strobe light covers need to be replaced they are faded out and the lights are dim because of it. R45

#### Task performed:

1. found oil filter leaking. repaired.
2. adjusted air horns.
3. installed new marker lights. bulbs were needed.

#### Parts

194BULB

#### Quantity

10

#### Workorder: V7982

In Date: 04/28/2007

Meter Reading: 5,073.00

Close Date: 10/25/2007

#### Problem?

Reattach shoreline connection to ceiling R-35

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V11347

In Date: 10/31/2007

Meter Reading: 50,371.00

Close Date: 11/06/2007

#### Problem?

INSTALL FRAME RAIL L SERT PER CAMPAIN R35

#### Task performed:

1. perform frame rail campain per freightliner

#### Parts

25-SF350-000L-SERT REINFORCEMENT

#### Quantity

1

### Workorder: V10962

In Date: 10/11/2007

Meter Reading: 49,821.00

Close Date: 11/13/2007

#### Problem?

repair stretcher R35 (outside agency-medco equipt. repair)

#### Task performed:

Repair stretcher R35 - Medco Equipt

#### Parts

NO PARTS USED

#### Quantity

Vendor? MEDCO EQMPT



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V11306**

**In Date:** 10/29/2007

**Meter Reading:** 50,371.00

**Close Date:** 11/27/2007

**Problem?**

b inspection and repairs as needed r35

#### Task performed:

- B-Inspection
  - 10/29/07 1.5 hrs
  - 10/30/07 5.5 hrs total 7.0
- 2. Go to old shop for parts PU
- 3. Replc Front & Rear brakes
- 4. Sec right trans mnt loose
- 5. R/R rear door holdopn; R/R/ side door holdopn
- 6. R/R A/C compressor frnt AC; reinstall bolh vac sys and refill; test for leaks
  - 11/2/07 3.0 OT hrs
  - 11/5/07 1.0 hrs
  - 11/6/07 2.0 hrs
  - 11/2/07 3.0 OT hrs
  - 11/5/07 1.0 hrs
- 7. R/R park brake handle
- 8. R/R belts
- 9. R/R cab door latches & adj strikers; R/R/ inner door hndles for Pat compt doors & side door hndle
- 10. Replc swtch for btry drawer door alarm
- 11. Lube latch for lower rear compt door
- 12. Replc rear door window
- 13. Tighten all door ltches on body doors
- 14. Replc both seat belts in cab
- 15. Set/rem knob frm traffic advisor
- 16. Rear A/C inopp because bad pressure swtch on 110V A/C; rem swtch & bypass; none in stock
- 17. Replc stretcher ltch
- 18. Fnd pressure swtch leaking for 110V A/C; vac sys & recharged; chkd for leaks-ok
- 19. Replc electric transfer fuel pump
- 20. Svc P/S
- 21. Svc trans
- 22. Coolant lines going to air compressor leaking; replc seals on both lines j

#### Parts

#### Quantity

090-0278STRECHER BAR NEW	1
103899KNOB PARKING BRAKE	1
18-29935-001RH DOOR LATCH NEW	1
18-45484-000LATCH L/H	1
22512960001498 SWITCH BINA	1
29526898 29548988 TRANS FILTER ALLISON	1
3944427INTAKE HOSE NEW #3949710	1
39663983USE 3963983 WASHER-FUEL SYS.	6
39901054943048 FUEL PUMP ISB	1
532703-0602 COMPRESSOR U4735 4471	1
716907-0610A DRYER	1
9451BELT	1
9485BELT	1
AMH-1AMH-1 VALVE EXTENSION	1
CA8193AIR FILTER 46744 WIX	1
E-600013-3052 NUT	4
FG87904MFG3937557S FILTER P/S NEW STYLE	1
FGQ79699GASKET-P/S FILTER NEW STYLE	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD39917DC23-5011 50 # HOLD-OPEN RESCUE	2
HND59471514305 HANDLE CHROME L/H	1
IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OLD #	1
IMMF13225BELT SEAT PASS. IMMF11852 OLD #	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S1003-A3103015 SEAL	2
S3225PFUEL FILTER 33630 LFF5849	1
SWT54912SWITCH DOOR LGHT	2
SWT54930SWITCH DOOR	2



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V11654

In Date: 11/17/2007

Meter Reading: 50,773.00

Close Date: 11/29/2007

#### Problem?

R35 passenger (LT. side) door handle is not operating properly. Must pull too hard on door handle to be able to open door R35

#### Task performed:

Parts

Quantity

1. Readjusted door latch and lubed.

NO PARTS USED

#### Workorder: V11768

In Date: 11/26/2007

Meter Reading: 5,379.00

Close Date: 11/30/2007

#### Problem?

The driver side door is sticking and hard to open and close. The front red strobe light on the box passenger side has a short in it a needs a new bulb. the driver side front strobe light on the box is also out. R35

#### Task performed:

Parts

Quantity

1. Installed new bulb for left side strobe.
2. Adjusted drivers door latch and pass. side.
3. Remove rear step and reinstalled with new screws.

NO PARTS USED

#### Workorder: V11866

In Date: 12/03/2007

Meter Reading: 51,214.00

Close Date: 12/03/2007

#### Problem?

ON CALL R35 DOOR NOT CLOSING

#### Task performed:

Parts

Quantity

- Readj brkt for door that would not close j

NO PARTS USED

#### Workorder: V11735

In Date: 11/24/2007

Meter Reading: 5,379.20

Close Date: 12/19/2007

#### Problem?

Replace missing rear mud flap on passenger side. R35

#### Task performed:

Parts

Quantity

1. Repaired mud flap that was falling off.
2. Checked for air leaks found none.

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V11930

In Date: 12/05/2007

Meter Reading: 5,379.80

Close Date: 12/19/2007

#### Problem?

The jump seat in the pt compartment is torn in two places and the cushion is coming out. The driver side round mirror is rusted out and will not stay in one place. R35

#### Task performed:

1. Removed mirror and installed new one.

#### Parts

980-412173 MIRROR 8 IN

#### Quantity

2

#### Workorder: V12148

In Date: 12/19/2007

Meter Reading: 5,379.00

Close Date: 12/31/2007

#### Problem?

fuel guage light not working R-35

#### Task performed:

1. Checked fuel guage is at full mark, checked tank, tank at full removed sender from tank and tested ok, will monitor guage.
2. Rear entry door hard to open, readjusted door linkage.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V12229

In Date: 12/26/2007

Meter Reading: 6,056.00

Close Date: 01/04/2008

#### Problem?

The shore line does not work when plugged into the rescue. The shore line has power. The truck does not show any lights or any indication the shore line is plugged in. R35

#### Task performed:

1. Reset breaker for 110 A/C.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V6130

In Date: 01/07/2007

Meter Reading: 40,256.00

Close Date: 01/08/2008

#### Problem?

R35 radio/ headsets there is alot of static on the driver side and on the pasenger set the mic is off.

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V10856

In Date: 10/04/2007

Meter Reading: 5,379.00

Close Date: 01/15/2008

#### Problem?

EMSAR needs to be contacted to lubricate and/or inspect stretcher to correct "sticky" locking mechanisms. The stretcher is tagged and moved into the downstairs storage room. R35

#### Task performed:

Parts

Quantity

NO PARTS USED

### Workorder: V12492

In Date: 01/10/2008

Meter Reading: 52,530.00

Close Date: 01/17/2008

#### Problem?

REPAIR STRETCHER R35

#### Task performed:

Parts

Quantity

Repair stretcher R35 - EMSAR

j

NO PARTS USED

Vendor? EMSAR

### Workorder: V12493

In Date: 01/10/2008

Meter Reading: 52,530.00

Close Date: 01/17/2008

#### Problem?

REPAIR STRETCHER R35

#### Task performed:

Parts

Quantity

Repair stretcher R35 - EMSAR

j

NO PARTS USED

Vendor? EMSAR

### Workorder: V12627

In Date: 01/16/2008

Meter Reading: 52,798.00

Close Date: 01/28/2008

#### Problem?

repair flat tire r35

#### Task performed:

Parts

Quantity

Repair flat tire R35 - Callaghan

j

NO PARTS USED

Vendor? CALLAGHAN



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V12865

In Date: 01/28/2008

Meter Reading: 53,375.00

Close Date: 01/28/2008

#### Problem?

COMP OPEN LIGHT GOING OFF R35

#### Task performed:

1. R+R magnet on battery box for alarms.

#### Parts

SWT54930SWITCH DOOR

#### Quantity

1

### Workorder: V12556

In Date: 01/14/2008

Meter Reading: 52,742.00

Close Date: 02/04/2008

#### Problem?

ON CALL R35 ACCIDENT DAMAGE

#### Task performed:

1. damage to truck after accident
2. fabricated new tail pipe and installed on truck

#### Parts

20A-400CLAMP 4" 33969

#### Quantity

2

### Workorder: V12582

In Date: 01/14/2008

Meter Reading: 5,379.00

Close Date: 02/04/2008

#### Problem?

replace missing door stop on the oxygen compartment door, replace the missing reflective bumper on diamond plate step on drive side, replace severed shoreline cable/wire.r35

#### Task performed:

Rep broken Shoreline. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V12702

In Date: 01/19/2008

Meter Reading: 5,379.30

Close Date: 02/04/2008

#### Problem?

Main oxygen tank compartment door (driver side) missing exterior U-shaped door stop (locks door in open position). R35

#### Task performed:

Rep O2 door & installed new holdopn on door.  
j

#### Parts

DRC401202840048 DOOR GRABBER

#### Quantity

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V13161

In Date: 02/10/2008

Meter Reading: 5,379.70

Close Date: 03/03/2008

#### Problem?

TWO DOME LIGHTS IN THE PATIENT COMPARTMENT NOT WORKING. R35

#### Task performed:

1. replaced 2 pt lights in rear.
2. Auto eject inop, replaced unit and tested

#### Parts

#### Quantity

0915520120AUTO EJECT 20 AERO OTL3925

1

322502BULB PATIENT GH22

4

#### Workorder: V13444

In Date: 02/23/2008

Meter Reading: 54,313.00

Close Date: 03/13/2008

#### Problem?

driver interior door panel white safety light needs to be replaced. R35

#### Task performed:

1. Repaired driver's door light that was not working

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V13905

In Date: 03/17/2008

Meter Reading: 55,076.00

Close Date: 03/19/2008

#### Problem?

door open warnig lt on r35

#### Task performed:

1. Door open light on, traced out problem, found bad connection in switch.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V13972

In Date: 03/19/2008

Meter Reading: 5,579.00

Close Date: 04/02/2008

#### Problem?

Right rear back-up light and lens broken and needs replaced.

#### Task performed:

1. Rear backuo light, replaced light.
2. Truck leaning to the left. Adjusted rear air bags

#### Parts

#### Quantity

681181363356811813633S LENS CLEAR

2

6E0CX0RU60X000RR STROBE LIGHT

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V14073

In Date: 03/24/2008

Meter Reading: 5,579.00

Close Date: 04/02/2008

#### Problem?

The exterior door handle on the door to the patient compartment on the passenger's side of R35 broke in half. R35

#### Task performed:

1. Replaced side door handle on rescue

#### Parts

HND5948TM22676-02 HANDLE DOOR ENTRY

#### Quantity

1

#### Workorder: V14200

In Date: 03/31/2008

Meter Reading: 5,379.60

Close Date: 04/10/2008

#### Problem?

Temp gauge on the dash shows the engine coolant at 200. no fluid leaks noticed. knob for the radiant fluid show red fluid. R35

#### Task performed:

1. found no problem w/ temp. gauge.

#### Parts

05-17223-002RAD CAP 20 LB

ALA00350-50 EXTENDED LIFE COOLANT GAL

#### Quantity

2

3

#### Workorder: V14436

In Date: 04/13/2008

Meter Reading: 5,379.80

Close Date: 04/22/2008

#### Problem?

There is a screw in the passenger side front tire that is holding air. The back emergency light next to the door on the passenger side is not working. R35

#### Task performed:

1. Latch Broken - Removed med drawer latch and installed new one
2. Removed screw in tire and checked for leaks

#### Parts

LTC5993SSM1-63-8 LATCH STAINLESS

#### Quantity

2

#### Workorder: V14506

In Date: 04/16/2008

Meter Reading: 5,379.80

Close Date: 04/22/2008

#### Problem?

Biohazard compartment drawer latch broken and needs to be replaced. E-35

#### Task performed:

1. Strobe out in rear, installed new bulb and tested
2. Truck leaning, adjusted air bags and road tested

#### Parts

LTC5993SSM1-63-8 LATCH STAINLESS

#### Quantity

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V14507

In Date: 04/16/2008

Meter Reading: 5,379.80

Close Date: 04/22/2008

#### Problem?

Rear strobe light burned out on the rear light bar. E-35

#### Task performed:

1. Air Leak - Checked for Air Leaks, found four and repaired

#### Parts

TURBO5TUBE - STROBE

#### Quantity

2

### Workorder: V14562

In Date: 04/18/2008

Meter Reading: 5,379.80

Close Date: 04/30/2008

#### Problem?

Rescue 35 rear/top set of emergency lights, 2nd strobe light from left (driver side) out. Light needs to be replaced.

#### Task performed:

1. checked light found no lights out at this time.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V15198

In Date: 05/19/2008

Meter Reading: 5,379.70

Close Date: 06/02/2008

#### Problem?

R35 just went in for PM and the shoreline A/C is just blowing hot air.

#### Task performed:

recharged 110 A/C unit & tested. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V15309

In Date: 05/24/2008

Meter Reading: 5,379.70

Close Date: 06/02/2008

#### Problem?

Tires wearing unevenly on R35. Both front tires, inner tread wearing faster than outer tread. R35

#### Task performed:

Checked frnt tire; will monitor tire. j

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V14964

In Date: 05/09/2008

Meter Reading: 56,824.00

Close Date: 06/16/2008

#### Problem?

B inspection and repairs as needed r35

#### Task performed:

1. remove/replace batteries
2. replace bulbs in patient comp. and rear light bar.

Parts	Quantity
107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1156BULB	1
322502BULB PATIENT GH22	1
435 VALVE CAP	3
800405PURGE VALVE KIT	1
921LIGHT BULB	1
9670BELT WPB	1
9680BELT	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
DOOR5LEXAN 9 X 38 1/2 IN	1
H50SN12BULB	1
HP-31DBATTERY 950CCA HP-31D	4
K080816BELT WPB	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

#### Workorder: V15749

In Date: 06/14/2008

Meter Reading: 5,379.70

Close Date: 07/09/2008

#### Problem?

PT COMPARTMENT, OB CABINET LATCH IS BROKEN R35

#### Task performed:

1. replaced latch in rear pt compt.

Parts	Quantity
LTC5993SSM1-63-8 LATCH STAINLESS	1

#### Workorder: V15968

In Date: 06/25/2008

Meter Reading: 5,379.70

Close Date: 07/09/2008

#### Problem?

Excessive leaking from AC condensation drain on R35

#### Task performed:

1. repaired 90 for a/c drain that was leaking on floor.
2. adjusted air horns.

Parts	Quantity
NO PARTS USED	



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V16227

In Date: 07/08/2008

Meter Reading: 5,379.00

Close Date: 07/18/2008

#### Problem?

Rear A/C unit leaking excessive water inside the pt. compartment. r35

#### Task performed:

Parts

Quantity

find A/C leaking in compt; crew needs to leave at 70 degrees in rear box. j

NO PARTS USED

#### Workorder: V16235

In Date: 07/09/2008

Meter Reading: 5,379.70

Close Date: 07/22/2008

#### Problem?

replace front tires callaghan .

#### Task performed:

Parts

Quantity

Replace front tires - Callaghan j

NO PARTS USED

Vendor? CALLAGHAN

#### Workorder: V16449

In Date: 07/19/2008

Meter Reading: 5,379.00

Close Date: 07/25/2008

#### Problem?

Recently noticed the "engine hours" gauge no longer functions so when fueling the Rescue 35, the hours have been the same for several months now.

#### Task performed:

Parts

Quantity

1. No siren; replc both siren speakers & head.
  2. No fire; find siren shorted out; replcd siren speaker.
- j

01-0862064-00SIREN FRONT SIDE

1

SD-210RXSIREN DRIVER SMALL

3

#### Workorder: V16679

In Date: 07/29/2008

Meter Reading: 2,597.00

Close Date: 08/11/2008

#### Problem?

Mount Stryker Stretcher in Rescue 35. New stretcher has been delivered to Sta 35.

#### Task performed:

Parts

Quantity

1. Go to St35; mount striker in truck; remount all hooks ^ install floor hooks; train crew on use.
2. Go to ST41; remount rear hooks; R/R door shock.
3. Go back to St35; move hooks again, seal holes. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V16885

In Date: 08/07/2008

Meter Reading: 6,914.00

Close Date: 08/14/2008

#### Problem?

R35 REAR AC IN BOX NOT WORKING AT ALL.

#### Task performed:

Found breaker off; tested unit.

j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V16986

In Date: 08/12/2008

Meter Reading: 59,483.00

Close Date: 08/20/2008

#### Problem?

REPAIR STRETCHER AT STA 35 MEDCO EQUIP REPAIR

#### Task performed:

Repair stretcher at Stn35 - Medco

j

#### Parts

NO PARTS USED

#### Quantity

Vendor? MEDCO

#### Workorder: V16950

In Date: 08/10/2008

Meter Reading: 5,379.70

Close Date: 09/02/2008

#### Problem?

rear driver side scene light out R35

#### Task performed:

Chkd opn of auto-eject & fnd unit working. rep scene light.

j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V17234

In Date: 08/22/2008

Meter Reading: 5,379.70

Close Date: 09/02/2008

#### Problem?

Shore line still does not pop out when vehicle started. R35

#### Task performed:

Chkd opn of auto-eject plug & tested ok.

j

#### Parts

0915520120AUTO EJECT 20 AERO OTL3925

#### Quantity

1





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V17270

In Date: 08/24/2008

Meter Reading: 5,379.70

Close Date: 09/02/2008

#### Problem?

Running light on the roof on the officer side of rescue is not working R-35

#### Task performed:

#### Parts

#### Quantity

Traced out problem with marker lights & fnd bad connection in headliner. j

NO PARTS USED

#### Workorder: V17434

In Date: 09/01/2008

Meter Reading: 5,379.70

Close Date: 09/29/2008

#### Problem?

patient compartment not cooling when plugged in to shoreline; rear scene light still is burned out. R-35

#### Task performed:

#### Parts

#### Quantity

Recharged rear 110 ac and tested

18-45484-000LATCH L/H

2

Replaced bulb in rear spot light

H35SN12BULB

2

Driver door not closing, replaced door latch

#### Workorder: V17412

In Date: 08/31/2008

Meter Reading: 5,379.70

Close Date: 09/30/2008

#### Problem?

Rear scene light out. Rear AC inop while plugged into shore power outlet. R35

#### Task performed:

#### Parts

#### Quantity

Rear door hard to open, adjusted door linkage.

NO PARTS USED

#### Workorder: V17417

In Date: 08/31/2008

Meter Reading: 5,379.70

Close Date: 09/30/2008

#### Problem?

Driver's side headlamp out.R35

#### Task performed:

#### Parts

#### Quantity

Replaced headlight Bulb

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V17853

In Date: 09/22/2008

Meter Reading: 60,764.80

Close Date: 09/30/2008

#### Problem?

repair side door r47

#### Task performed:

disassemble door- adjust linkage-reassemble-test

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V17978

In Date: 09/27/2008

Meter Reading: 5,379.70

Close Date: 10/07/2008

#### Problem?

R35 needs oil added. R35

#### Task performed:

- 1- DROPPED OFFOILAT STATION.
- 2- INSTALLED NEW 110 OUTLET PLUG ON POWER CORD.
- 3- SIDE ENTRY DOOR SPRING MISSING PIN, INSTALLED NEW PIN.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V17979

In Date: 09/27/2008

Meter Reading: 5,379.70

Close Date: 10/07/2008

#### Problem?

Driver side rear stabilizer of tire pressure port broken on R35. Needs to be secured to the rim. This is a second request for fix. R3!

#### Task performed:

- 1- removed broken bracket for tire fill.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V18055

In Date: 10/01/2008

Meter Reading: 5,379.70

Close Date: 10/07/2008

#### Problem?

Shoreline plug shorting out; quick disconnect intermittently disconnecting causing wires to separate from plug connections. Metal bracket on rear wheel tire air line broken. r35

#### Task performed:

- 1- INSTALLED NEW 110 OUTLET ON POWER CORD AND TESTED.

#### Parts

5-20PH1PGK4 CONNECTOR 120V 20A FEMALE

2

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V18141

In Date: 10/06/2008

Meter Reading: 61,232.30

Close Date: 10/15/2008

#### Problem?

ROOF LEAK IN REAR BOX, R-35

#### Task performed:

1-Water leak in rear resealed roof seam.

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V15325

In Date: 05/26/2008

Meter Reading: 5,379.70

Close Date: 10/20/2008

#### Problem?

Truck returned from PM with Shoreline A/C not cooling patient compartment. R35

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V18541

In Date: 10/23/2008

Meter Reading: 61,771.00

Close Date: 10/28/2008

#### Problem?

REPLACE OIL CAP

#### Task performed:

Cleaned off eng of oil & installed new cap. j

#### Parts

39682023976511 OIL CAP ISL

#### Quantity

1

### Workorder: V19082

In Date: 11/14/2008

Meter Reading: 5,379.00

Close Date: 12/02/2008

#### Problem?

1)Driver side ext. horizontal compartment door hinge broken on left side. 2)A/C not working when truck plugged into shore line.  
3)Interior driver side compartment hinge not locking. (EKG battery compartment)

#### Task performed:

1. Air horns inop; adj air horns.
2. 110 A/C inop; recharged 110 A/C & repaired leak.
3. Compt hinge broken; replcd hinge.
4. EKG compt not latching; rep latch & adj brket. j

#### Parts

1094KIT-AIR HORN-GROVER

HLD44614446 1/4 LATCH

#### Quantity

2

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V19088

In Date: 11/15/2008

Meter Reading: 5,379.00

Close Date: 12/02/2008

#### Problem?

front top emergency light is not working. R-35

#### Task performed:

Parts

Quantity

Light out in light bar; chk lights; fnd no lights out. j

NO PARTS USED

### Workorder: V19098

In Date: 11/16/2008

Meter Reading: 5,379.00

Close Date: 12/02/2008

#### Problem?

front right head light is out. also one of the pt lights inside the rescue is out. R35

#### Task performed:

Parts

Quantity

1. Replaced headlight.

NO PARTS USED

2. Replaced pat lights in rear that were out. j

### Workorder: V19145

In Date: 11/18/2008

Meter Reading:

Close Date: 12/02/2008

#### Problem?

A light in the light bar is out and a dome light in the patient compartment is out. r35

#### Task performed:

Parts

Quantity

1. Rep lights in pat comp that were out.

NO PARTS USED

2. 110 A/C inop; recharged sys & rechkd. j



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V19507**

**In Date:** 12/04/2008

**Meter Reading:** 63,128.00

**Close Date:** 12/15/2008

**Problem?**

c inspection and repairs as needed )

#### Task performed:

- 1-C inspection.
- 2-Left front side strobe out, replaced strobe wired it, replaced 2 rubber grip nuts.
- 3-Box side molding door loose,tightenet trim. grip tape bad. replaced grip taped tightened door handle.
- 4-belt need change, remove old belt and fan connection. replaced 2 a/c belts andcheck. ok.

1/12/08

5. Fuel leak at rear of eng; rem trans; fill tube brkt asy; difficult access; tightened both ends of fitting; cnd; ran/ck for leaks; ck ok; reinstalled brkt.
6. Ck btry charger; chrgr wrkng; replcd/wire LED light panel; ck opn; ck ok.
7. Top rad hose loose; tied down hose & insulated; ck ok.
8. Exh manifold bolt/sleeve msng; replc msng bolt; tightened all exh manifold bolts; ck for leaks; ck ok.
9. Door latches loose; tightened all door catch latches.
10. Rt mudflap msng; cut new flap to fit; replcd mudflap.
11. R/R wiper blades.
12. Oil pan leaking; fnd bolts loose; tightened all bolts; ck ok.
13. Clamps brkn on trans lines & hoses; replcd clamps.
14. Rear bumper bent; loosened mnts; repositioned bumper; tightened bolts. j

#### Parts

#### Quantity

032-0116549297 BATTERY INDICATOR	1
15W40BSYN OIL BULK QTS	24
3944593EXH. MAN. BOLT	1
3945252SPACER EXH. MAN.	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
9451BELT	1
9485BELT	1
B2420LP-SMUD FLAP 24 X 24	1
CA8193AIR FILTER 46744 WIX	1
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Workorder: V19873**

**In Date:** 12/20/2008

**Meter Reading:** 63,585.40

**Close Date:** 12/31/2008

**Problem?**

shore line broke for the rescue, needs a plug replacement.

#### Task performed:

1. O2 leak; chkd for leaks; fnd main bottle leaking; swapped out bottle.
2. Replcd 110 plug for A/C j

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V19483

In Date: 12/03/2008

Meter Reading:

Close Date: 01/05/2009

#### Problem?

Upper rear corner driver side red flashing light burned out; front light bar spinning red light burned out. R-35

#### Task performed:

Replcd bulbs in emergency lights. j

Parts

Quantity

NO PARTS USED

#### Workorder: V19931

In Date: 12/23/2008

Meter Reading: 63,828.10

Close Date: 01/13/2009

#### Problem?

repair stretcher R35 (outside agency-medco equipment repairs)

#### Task performed:

REepair stretcher R35 - Medco Eqpmt j

Parts

Quantity

NO PARTS USED

Vendor? MEDCO

#### Workorder: V18547

In Date: 10/23/2008

Meter Reading: 61,771.00

Close Date: 01/14/2009

#### Problem?

REPLACE REAR TIRES R35 (outside agency-callaghan tire)

#### Task performed:

Replace rear tires R35 - Callaghan j

Parts

Quantity

NO PARTS USED

Vendor? CALLAGHAN

#### Workorder: V19465

In Date: 12/02/2008

Meter Reading: 63,128.30

Close Date: 01/14/2009

#### Problem?

REPAIR STRETCHER R35

#### Task performed:

Repair stretcher R35 - Medco j

Parts

Quantity

NO PARTS USED

Vendor? MEDCO



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V20290

In Date: 01/12/2009

Meter Reading: 5,379.00

Close Date: 01/26/2009

#### Problem?

pin on side patient compartment door hinge broken. R35

#### Task performed:

Parts

Quantity

1- Installed new pin for side entrance door.

NO PARTS USED

2- Installed 12 volt charger for dewalt battery.

### Workorder: V20067

In Date: 01/01/2009

Meter Reading: 63,896.30

Close Date: 01/27/2009

#### Problem?

red warning light is out on the front light bar. R35

#### Task performed:

Parts

Quantity

1- Light out in light bar, repaired bad connection.

NO PARTS USED

### Workorder: V20349

In Date: 01/14/2009

Meter Reading: 5,379.80

Close Date: 01/27/2009

#### Problem?

steering wheel was vibrating and making noise when making turns at slow speeds R35

#### Task performed:

Parts

Quantity

1- Steering fluid was low due to leak, repaired leak and road tested.

NO PARTS USED

### Workorder: V20554

In Date: 01/23/2009

Meter Reading: 5,379.70

Close Date: 02/13/2009

#### Problem?

Inside door handle to rear door on rescue is broken. Handle does not always open door. R35

#### Task performed:

Parts

Quantity

replaced door handle. j

AEVDOOR LOCK BEZEL

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V20410

In Date: 01/16/2009

Meter Reading: 5,379.70

Close Date: 02/18/2009

#### Problem?

Right scene light is out. This is the light towards the front of the box. r35

#### Task performed:

Drive to Stn; replc light on right side; scene light out on front H355N12. j

#### Parts

H35SN12BULB

#### Quantity

1

#### Workorder: V16781

In Date: 08/02/2008

Meter Reading: 5,379.70

Close Date: 03/02/2009

#### Problem?

driver side rear scene/back-up light on top light bar burned out. R-35

#### Task performed:

Rear A/C inop; replc blower motor.

#### Parts

65-72BXT65750 BATTERY

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

#### Quantity

2

2

#### Workorder: V16891

In Date: 08/07/2008

Meter Reading: 6,914.00

Close Date: 03/02/2009

#### Problem?

left top rear scene light is out in R35

#### Task performed:

Rear A/C inop; replc blower motor.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V18065

In Date: 10/01/2008

Meter Reading: 5,379.70

Close Date: 03/02/2009

#### Problem?

Replace pin on patient compartment side door. r35

#### Task performed:

1- BROKEN LATCH FOR DOOR/ REPAIRED LATCH FOR SIDE ENTREDOOR.

#### Parts

NO PARTS USED

#### Quantity





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V21096

In Date: 02/13/2009

Meter Reading: 5,379.80

Close Date: 03/05/2009

#### Problem?

One Of The Four Main Flashing/ Revolving Lights On The Front Lightbar Of R35 Is Out Of Service.

#### Task performed:

#### Parts

#### Quantity

1. Lights out in light bar; replcd ight in light bar.
2. Eng making noise; road tested & fnd no noise.
3. Rear A/C making noise; rep A/C fan that was making noise. j

NO PARTS USED

#### Workorder: V20019

In Date: 12/29/2008

Meter Reading: 5,379.70

Close Date: 03/06/2009

#### Problem?

Rescue involved in MVC with minor damage to driver side rear wheel trim and rear compartment scratching with minor damage to reflector strip and rubber cushion underneath compartment doors. R35 drivable and operational

#### Task performed:

#### Parts

#### Quantity

Oil at stn; dropped off oil. j

15W40QSYN OIL QT

12

#### Workorder: V16970

In Date: 08/11/2008

Meter Reading: 5,379.70

Close Date: 03/09/2009

#### Problem?

Shore line cord does not release from vehicle post starting vehicle. R-35

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V21424

In Date: 03/01/2009

Meter Reading: 5,379.70

Close Date: 03/26/2009

#### Problem?

Scene light on officer side is out R35

#### Task performed:

#### Parts

#### Quantity

Rep bad connection in scene light that was out. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V21765

In Date: 03/12/2009

Meter Reading: 5,379.80

Close Date: 03/26/2009

#### Problem?

Interior display above driver is showing "Diagnostic Error N2PH". Attempted to reset truck via battery switch and still returns. Passenger side scene light still out as well. R-35

#### Task performed:

#### Parts

#### Quantity

1. Svc call to Stn35; T-shoot screens; reset code; Ran/ck opn; ck ok; returned home.
2. Traced out problem from on-call with nodeipin-2; problem fnd scene light out; replcd bulb. j

NO PARTS USED

#### Workorder: V21921

In Date: 03/18/2009

Meter Reading: 5,379.70

Close Date: 03/27/2009

#### Problem?

Door ajar light inside rescue is flashing when all doors are closed. r35

#### Task performed:

#### Parts

#### Quantity

- Svc call to St35; cld not get alarm to go off; driver said pass door set off alarm; R/R door swtch; ck opn; j

91823SWITCH SWT5499 MED MASTER

1

#### Workorder: V21807

In Date: 03/15/2009

Meter Reading: 5,379.80

Close Date: 04/03/2009

#### Problem?

patient compartment shoreline a/c needs to be recharged (not cooling). r35

#### Task performed:

#### Parts

#### Quantity

- Recharged 110 A/C that was warm. j

NO PARTS USED

#### Workorder: V22323

In Date: 04/05/2009

Meter Reading: 5,379.60

Close Date: 04/17/2009

#### Problem?

Recharge patient compartment shoreline air conditioner (ALS drugs, plastic and rubber equipment sensitive to high heat while parked in hot bay). R35

#### Task performed:

#### Parts

#### Quantity

- coolant leak; watr pump leaking; sent to shop. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V22374

In Date: 04/07/2009

Meter Reading: 68,053.00

Close Date: 04/23/2009

#### Problem?

leaking red fluid R35

#### Task performed:

Coolant leak; sent to shop for repair. j

2. Water pump leaking; rem/install new water pump.

3. Tensioner going bad; rem/install new tensioner.

4. Dipstick rubber worn out; install new dipstick. j

#### Parts

#### Quantity

07-14488-000DIPSTICK

1

3286278WATER PUMP ISB

1

39768315259022 GROOVED TENSIONER OLD#3936213

1

#### Workorder: V22402

In Date: 04/08/2009

Meter Reading: 5,379.80

Close Date: 04/27/2009

#### Problem?

front passenger side scene light burned out again. R35

#### Task performed:

1. R/R right front scene light.

2. Cln work area & floor.

3. 110V A/C inop; fnd freon level low; clnd condensor; added freon to sys; ran/ck opn; ck ok. j

4. Light out; fnd b ad connection on relay & rep. j

#### Parts

#### Quantity

9EOCAOZUSCENE LIGHT

1

#### Workorder: V22649

In Date: 04/20/2009

Meter Reading: 68,547.80

Close Date: 04/28/2009

#### Problem?

REAR COMPARTMENT DOOR WILL NOT OPEN, R-35

#### Task performed:

Replace left rear door inside handle brkn; wld not open.

#### Parts

#### Quantity

HND5948TM22676-02 HANDLE DOOR ENTRY

1

#### Workorder: V22725

In Date: 04/22/2009

Meter Reading: 5,379.75

Close Date: 05/01/2009

#### Problem?

Left rear patient compartment door very difficult to open. r35

#### Task performed:

Rear door inop; rem rear door panel & rep door latch

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V23319

In Date: 05/17/2009

Meter Reading: 5,379.70

Close Date: 05/26/2009

#### Problem?

Sharps container drawer slides and plexiglass cover are broken. Please fix at your earliest convenience. Thanks, 35

#### Task performed:

1. Installed new glass over med.
2. Rep 110 A/C that needed a charge. j

#### Parts

DOOR2LEXAN 14.5 X 8.5

#### Quantity

1

#### Workorder: V23525

In Date: 05/26/2009

Meter Reading: 70,198.40

Close Date: 05/27/2009

#### Problem?

ENGINE OIL LEVEL LOW, R-35

#### Task performed:

- Go to Stn35; Chk eng low on oil;top off oil to (2) qts of oil. j

#### Parts

15W40QSYN OIL QT

#### Quantity

2

#### Workorder: V23425

In Date: 05/21/2009

Meter Reading: 8,080.50

Close Date: 06/01/2009

#### Problem?

air leak in air suspension line/system/valve. Thanks, r 35

#### Task performed:

- Air leak chkd for air leaks; fnd none at this time. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V23498

In Date: 05/23/2009

Meter Reading: 5,379.70

Close Date: 06/02/2009

#### Problem?

MULTIPLE DOOR AJAR ALARMS GOING OFF WITH ALL DOORS SECURED DURING WET WEATHER. DIFFICULT TO HEAR DISPATCH WHILE RESPONDING TO CALLS. R35

#### Task performed:

- Fnd water in connectors; rep/tested. j

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V23596

In Date: 05/27/2009

Meter Reading: 70,250.90

Close Date: 06/04/2009

#### Problem?

reprogram ecm oil prssure

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

Vendor? CUMMINS

#### Workorder: V23463

In Date: 05/21/2009

Meter Reading: 70,086.80

Close Date: 06/12/2009

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED R35

#### Task performed:

#### Parts

#### Quantity

B -Inspection	107796DRYER KIT AD9 -NEW	1
2. Pull wheels & chk all brakes; had Scotty double chk; ok at this time.	107800VALVE CHECK AD9	1
3. C/O charge up 100V A/C.	52-24WIPER BLADES ANCO 24	2
4. Chk for air leaks; replc air compressor line; air dryer quick connects & air tank drains.	800405PURGE VALVE KIT	1
5. Chk/charge cab A/C,	A1211593054HOSE DISCHG	1
6, R/R Air dryer.	AMH-1AMH-1 VALVE EXTENSION	1
7. R/R officers side seat belt. 8. Replcd L/R RLB rail.	E-600013-3052 NUT	4
9. R/R frnt shocks.	EXT4534RUBRAIL EXTRUSION PER FT	4
10. R/R wiper blades.	IMMF13225BELT SEAT PASS. IMMF11852 OLD #	1
11. Cln bay floor & work benches. j	L1261F33585XE FUEL FILTER WIX	1
	MFG9928PL17008 VERSACELL DECAL BACKING	4
	PH8942FILTER OIL 57182 LFP3729	1
	RBR7862GA48800 RUBRAIL INSET	4
	S3225PFUEL FILTER 33630 LFF5849	1
	SA66613SHOCK FRONT RESC	2

#### Workorder: V23724

In Date: 06/01/2009

Meter Reading: 5,379.60

Close Date: 06/19/2009

#### Problem?

Captain's chair in patient compartment screw fasteners poke into thighs while seated/ upholstery shot in front and rear (torn and damaged). r35

#### Task performed:

#### Parts

#### Quantity

Rem seat from spare rescue & installed in rescue 35. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V24046

In Date: 06/12/2009

Meter Reading: 70,672.70

Close Date: 07/06/2009

#### Problem?

Rescue plug end on side of box inop (shore line has power) R35

#### Task performed:

##### Parts

##### Quantity

1. Replcd auto-eject plug.
2. Air leak; fnd air leak at tank & rep. j

NO PARTS USED

### Workorder: V24136

In Date: 06/16/2009

Meter Reading: 5,379.60

Close Date: 07/06/2009

#### Problem?

Swing arm pin on patient compartment side door broken. R35

#### Task performed:

##### Parts

##### Quantity

- Replcd pin in side door that was brkn. j

HLD374211 IN HOLD-OPEN 30LB

2

### Workorder: V24249

In Date: 06/22/2009

Meter Reading: 5,379.70

Close Date: 07/06/2009

#### Problem?

Pt. compartment a/c not cooling below 80 degrees even after long time plugged in with doors closed. R35

#### Task performed:

##### Parts

##### Quantity

- Recharged sys; rep leak; cldd condensor fans & rep A/C fan switch. j

NO PARTS USED

### Workorder: V24324

In Date: 06/24/2009

Meter Reading: 5,379.70

Close Date: 07/06/2009

#### Problem?

pt. compartment a/c not cooling. Even when sitting in the bay in the shade plugged in with doors closed. r35

#### Task performed:

##### Parts

##### Quantity

1. Recharger 110 A/c unit.
2. Rear door not opening; rep door linkage. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V24227

In Date: 06/20/2009

Meter Reading: 5,379.60

Close Date: 07/08/2009

#### Problem?

slow air leak in suspension/air dump again. Thanks, R 35

#### Task performed:

Chkd for air leaks; rep where needed. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V24614

In Date: 07/07/2009

Meter Reading: 71,357.20

Close Date: 07/15/2009

#### Problem?

air dump leaks air R35

#### Task performed:

1. C/O air leak; bags leaking; also Murphy valve in dash unit; R/R bags & valve in dash replumb.
2. R/R dash light in gauge cluster. j

#### Parts

16-15762-00016-19471-000 AIR BAG  
4923090025DASH BULB VDO  
SU68088VALVE DUMP 310 HUMPHREY

#### Quantity

2  
1  
1

#### Workorder: V24602

In Date: 07/06/2009

Meter Reading: 5,379.70

Close Date: 07/17/2009

#### Problem?

shoreline r35

#### Task performed:

Shoreline operating normal at this time; cld not get it to fail. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V24646

In Date: 07/08/2009

Meter Reading: 5,379.70

Close Date: 07/17/2009

#### Problem?

airhorn on rescue not working r35

#### Task performed:

Travel to Stn; fnd air line to air solenoid disconnected & horn water gasket damage; correct all faults & adj horn.  
j

#### Parts

1094KIT-AIR HORN-GROVER

#### Quantity

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V24989

In Date: 07/22/2009

Meter Reading: 5,379.60

Close Date: 07/27/2009

#### Problem?

Poss. suspension problem. A lot of bouncing in front end. r35

#### Task performed:

#### Parts

#### Quantity

1. Rem frnt wheel; wheels are choppy; install new wheels.
2. Assist Mac w/frnt end set up.
3. Chk wheel alignment toe in out of specs; align wheels & test drive unit. j

NO PARTS USED

#### Workorder: V24990

In Date: 07/23/2009

Meter Reading: 5,379.60

Close Date: 07/27/2009

#### Problem?

hours meter broken/not functioning for over one year r35

#### Task performed:

#### Parts

#### Quantity

Hour meter inop; power going to hour meter; meter brkn; rem/install new hour meter; make tag for house to be added when rewinding unit \_\_\_\_\_.

8534203HRS METER 85342-03

1

#### Workorder: V24523

In Date: 07/02/2009

Meter Reading: 5,379.60

Close Date: 07/28/2009

#### Problem?

The air suspension still has a leak that is progressively getting worse. The air completely dumps when the vehicle is not started at approx. 3 hours. Thanks, R 35

#### Task performed:

#### Parts

#### Quantity

Chkd for air leaks & fnd none at this time. j

NO PARTS USED

#### Workorder: V25111

In Date: 07/28/2009

Meter Reading: 5,388.70

Close Date: 07/28/2009

#### Problem?

There is a loud noise coming from speaker in the patient compartment. Could be a short? R35

#### Task performed:

#### Parts

#### Quantity

pass on to radio shop

NO PARTS USED





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V25112

In Date: 07/28/2009

Meter Reading: 5,388.70

Close Date: 07/29/2009

#### Problem?

There is fluid coming from the engine compartment. It could be radiator fluid. It was low and needed to be filled. R35

#### Task performed:

#### Parts

#### Quantity

Fnd hose clamp loose; tightened clamp & clnd area of coolant. j

NO PARTS USED

#### Workorder: V25081

In Date: 07/27/2009

Meter Reading: 72,098.00

Close Date: 08/05/2009

#### Problem?

EMERGENCY LITES INOP, R-35

#### Task performed:

#### Parts

#### Quantity

1. Slides for med draw brkn.  
2. On-call; no emergency lights; rep connection on relay board. j

SLD5366HT4932-16 DRAWER SLIDE 16

4

#### Workorder: V25374

In Date: 08/06/2009

Meter Reading: 5,422.30

Close Date: 08/07/2009

#### Problem?

R35: Left front head light is not secure in frame. Water in fuel light is flashing in dash. Low voltage is flashing in scanner above drivers head.

#### Task performed:

#### Parts

#### Quantity

THIS TICKET WAS CLOSED OUT, THE REPAIRS AND PARTS WERE MADE ON W/O #25388

NO PARTS USED

#### Workorder: V25388

In Date: 08/07/2009

Meter Reading: 5,379.70

Close Date: 08/11/2009

#### Problem?

Left front headlight held in with duct tape. Low voltage alarm keeps going off, with -40 to -70 amps being shown with code 3 lights activated. Rear AC ducts possibly obstructed.

#### Task performed:

#### Parts

#### Quantity

1. Ck low voltage; rem cables & load test btry; ck ok; ck/tightened cable connections; take volt drops; Ck ok; R/R alt; cl nd alt pulley; installed pulley; ck opn.  
2. Rem left headlight asy; reinstalled adjuster screws/srping; reassembled ight; ck ok.  
3. Ck/adj headlights; ck ok. j

4867JB320 UPGRADE ALTERNATOR

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V25681

In Date: 08/21/2009

Meter Reading: 73,113.90

Close Date: 08/25/2009

#### Problem?

have added over 1 gallon to radiator daily-no leaks can be seen R35

#### Task performed:

#### Parts

#### Quantity

Filled rad; press cooling sys; cld not find external leak;  
relieved press; started/ran eng; combustion press going  
into cooling sys; send truck out to be rep. j

NO PARTS USED

#### Workorder: V25708

In Date: 08/22/2009

Meter Reading: 4,526.20

Close Date: 08/25/2009

#### Problem?

Spot light is broken on the top of R35. Broken off when it was hit by the bay door.

#### Task performed:

#### Parts

#### Quantity

Spotlight broke off by bay door; travel to shop for part;  
diss headliner to install roof top spotlight. j

SPT6008146SL LIGHT-REMOTE SPOT

1

#### Workorder: V25505

In Date: 08/13/2009

Meter Reading: 273.60

Close Date: 08/27/2009

#### Problem?

Low coolant. No coolant visible in reservoir window, some left in bottom of tank. No odor of coolant noted R-35

#### Task performed:

#### Parts

#### Quantity

1. Press tested sys; fnd no leaks.
2. 110 A/C warm; recharged sys. j

NO PARTS USED

#### Workorder: V25309

In Date: 08/05/2009

Meter Reading: 5,422.30

Close Date: 09/11/2009

#### Problem?

LEFT FRONT HEADLIGHT VERY LOOSE IN BRACKET. SCREWS POSSIBLY MISSING. R-35

#### Task performed:

#### Parts

#### Quantity

1. Headlight loose; rep light.
2. Coolant leak; rep hose clamps. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V25585

In Date: 08/17/2009

Meter Reading: 6,453.10

Close Date: 09/14/2009

#### Problem?

Coolant low, 1 1/2 gal of H2O added. Right rear scene light out. r35

#### Task performed:

1. Coolant; press tested unit; fnd no leaks.
2. Rear lens brkn;rep rear light. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V25689

In Date: 08/21/2009

Meter Reading: 73,113.90

Close Date: 09/14/2009

#### Problem?

repair engine (outside agency-cummins power southeast)

#### Task performed:

Repair engine - Cummins j

#### Parts

NO PARTS USED

#### Quantity

Vendor? CUMMINS

#### Workorder: V25917

In Date: 08/31/2009

Meter Reading: 102,127.10

Close Date: 09/14/2009

#### Problem?

A INSP. AND REPAIRS AS NEEDED AIR LEAKS

#### Task performed:

- A-Service
2. R/R dash panel
3. Cln off motor for oil leaks.
4. R/R frnt seats, ripped.
5. R/R both front corner light on front hood & lenses(2)
6. R/R side scene light.
7. Add coolant & chk for leaks-ok.
8. Add (2) qt of eng oil.
9. Installed bear brakes.
10. Light on action - R/R bulbs.
11. Rep wire in drivers door, light.
12. Add washer fluid; chk working.
13. Chk air leak & rep. j

#### Parts

12105QUICK DRAIN  
2332920005SMASK LENS W/RST BUTTON VDO  
4020362171 GRO LAMP DOME 4 IN  
91513AMBER LENS  
H50SN12BULB  
MK184HDBRAKE PADS

#### Quantity

1  
1  
1  
2  
1  
1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V26459

In Date: 09/25/2009

Meter Reading: 73,987.20

Close Date: 09/30/2009

#### Problem?

DOOR OPEN LIGHT ON, R-35

#### Task performed:

Door ajar lights on; rep bad switch. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V25745

In Date: 08/24/2009

Meter Reading: 102,127.10

Close Date: 10/14/2009

#### Problem?

replace bad compresor cummins power south

#### Task performed:

Replc bad compressor - Cummins Power j

#### Parts

NO PARTS USED

#### Quantity

Vendor? CUMMINS POWER

### Workorder: V26388

In Date: 09/22/2009

Meter Reading: 7,377.50

Close Date: 10/14/2009

#### Problem?

ON CALL R35 HEADLIGHTS 10-7

#### Task performed:

Headlights out; replcd headlights on left/right. j

#### Parts

NO PARTS USED

#### Quantity

### Workorder: V25942

In Date: 09/01/2009

Meter Reading: 102,127.10

Close Date: 10/15/2009

#### Problem?

REPAIR SEAT CENTRAL AUTO

#### Task performed:

Repair seat - Central Auto j

#### Parts

NO PARTS USED

#### Quantity

Vendor? CENTRAL AUTO



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V26797

In Date: 10/10/2009

Meter Reading: 5,683.50

Close Date: 10/21/2009

### Problem?

Shore line AC not blowing cold air. AC works with vehicle running. Fusebox checked, not popped. R35 ON CALL

### Task performed:

#### Parts

#### Quantity

1. L/F strobe(lens msg); installed new lens.
2. 110 A/C inop; low refrigerant; add (1) lb R22 & tightened shrader. j

NO PARTS USED

## Workorder: V26638

In Date: 10/02/2009

Meter Reading: 423.50

Close Date: 11/12/2009

### Problem?

Strobe light on top front light bar is no working. R35

### Task performed:

#### Parts

#### Quantity

1. Rep strobelight on top of eng.
2. Roof spotlight; rep connection on light. j

NO PARTS USED

## Workorder: V26804

In Date: 10/10/2009

Meter Reading: 5,683.50

Close Date: 11/12/2009

### Problem?

Left rear scene light out R35

### Task performed:

#### Parts

#### Quantity

1. left rear scene light out; rep brkn wire.
2. Rear door hard to open; readj door linkage.
3. Left headlight out; replcd headlight. j

NO PARTS USED

## Workorder: V26890

In Date: 10/14/2009

Meter Reading: 74,701.40

Close Date: 11/16/2009

### Problem?

replace 3 tires R35 loose wheels at vista (outside agency-callaghan tire)

### Task performed:

#### Parts

#### Quantity

Replace (3) tires R35, loose wheels - Callaghan

NO PARTS USED

Vendor? CALLAGHAN



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V27860**

In Date: 11/23/2009

Close Date: 01/13/2010

Meter Reading: 76,244.00

**Problem?**

COOLANT LEAK R35

**Task performed:**

Chkd for coolant leak; fnd none at this time. j

**Parts**

**Quantity**

05-17223-000CAP RADIATOR 10 LB

1

FSC17492134NC SW PARK BK SPADE TYPE CONNECTOR

1

VML-T1413T3248 SIGHT GLASS

1

VML-T1555SURGE TANK

1

**Workorder: V27685**

In Date: 11/16/2009

Close Date: 01/14/2010

Meter Reading: 618.00

**Problem?**

Please replace the strobe light bulb on the driver side front/top light bar. Thanks, R35

**Task performed:**

Rep rear strobe that was out. j

**Parts**

**Quantity**

NO PARTS USED

**Workorder: V27854**

In Date: 11/23/2009

Close Date: 01/14/2010

Meter Reading: 506.20

**Problem?**

The volume knob on the AM/FM radio disappeared recently and nobody seems to know where it went. Do you carry this or does t "radio shop" carry it? r35

**Task performed:**

Vol knob msng off radio; tried rep; will try to get part. j

2. install radio volume knob. j

**Parts**

**Quantity**

05-17223-000CAP RADIATOR 10 LB

1

52-24WIPER BLADES ANCO 24

2

6806970098SEAL DOOR

1

98003RREFLECTOR RED 40132 GROTE

1

A1834388002MOLD L/H

1

A1834388003MOLD R/H

1

FG-Q59278P/S GASKET

1

FG87904MFG3937557S FILTER P/S NEW STYLE

1

FGQ79699GASKET-P/S FILTER NEW STYLE

1

HAN-1LBEZEL AND HANDLE

1

PSO 09365838RADIO KNOB

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V27971

In Date: 11/28/2009

Meter Reading: 661.40

Close Date: 01/14/2010

#### Problem?

Light bar on R35 has one light out. Front light bar on drivers side.

#### Task performed:

Rep left frnt light lens. j

#### Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

#### Quantity

1

#### Workorder: V28093

In Date: 12/03/2009

Meter Reading: 5,936.90

Close Date: 01/15/2010

#### Problem?

Shore Power AC blowing hot, fuse reset with change in status. AC works OK with vehicle running. r35

#### Task performed:

Recharged 110 unit; unit was leaking; rep leak. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V28251

In Date: 12/10/2009

Meter Reading: 591.40

Close Date: 01/15/2010

#### Problem?

door hinge on the inside of side door leading into pt compartment is broken. R35

#### Task performed:

Replcd door spring. j

#### Parts

HLD374211 IN HOLD-OPEN 30LB

#### Quantity

1

#### Workorder: V28296

In Date: 12/12/2009

Meter Reading: 76,954.00

Close Date: 01/15/2010

#### Problem?

Cab a/c inop R35

#### Task performed:

Recharged cab A/C. j

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28431**

**In Date:** 12/17/2009

**Meter Reading:** 77,082.90

**Close Date:** 01/15/2010

**Problem?**

REPAIR PAITIENT LTS R35

**Task performed:**

Rep pat lights in rear that were out. j

Parts

Quantity

NO PARTS USED





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V28630**

**In Date:** 12/28/2009

**Meter Reading:** 77,598.00

**Close Date:** 02/05/2010


**Problem?**

C INSPECTION AND REPAIRS AS NEEDED R35 IS NOW A SPARE

**Task performed:**

Parts

Quantity



**\* ADVANCED LIFE SUPPORT VEHICLE**

1  
24  
1  
1  
1  
1  
1  
1  
1  
1  
1  
1  
1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

PSI.

32. L-4 compt ventilation duct damage; unable to get replacement; fab plate, cvr port. j

23. Action area drop dowqn pat hanging;

---

#### Workorder: V31016

In Date: 03/24/2010

Meter Reading: 78,346.90

Close Date: 03/24/2010

##### Problem?

front passenger headset talk box sticks in the talk position sr 13 at 17

##### Task performed:

Parts

Quantity

Contacted Steven Lee via email for repair 03/24

NO PARTS USED

---

#### Workorder: V31017

In Date: 03/24/2010

Meter Reading: 78,346.90

Close Date: 03/25/2010

##### Problem?

pt compartment radio has broken and missing home buttons. sr at 17

##### Task performed:

Parts

Quantity

Contacted Steven Lee via E mail 03/25

NO PARTS USED

---

#### Workorder: V30603

In Date: 12/28/2009

Meter Reading: 77,598.00

Close Date: 03/29/2010

##### Problem?

A inspection and repairs

##### Task performed:

Parts

Quantity

A-Inspection

H6054USE CV TYPE SEALED BEAM

1

2. Adj window washer squirters.

3. Replc L/headlight & installed spring & adj screws.

4. Tighten A/C belts.

5. Adj air press in all tires.

6. Chk codes; fnd error on node #1 pin L output 9 due to bad connectionfor LF hi-beam; rep connection. j



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V31015

In Date: 03/24/2010

Meter Reading: 78,346.90

Close Date: 04/20/2010

#### Problem?

front passenger seat loose moves front to back will not lock sr 13 at 17

#### Task performed:

#### Parts

#### Quantity

Went to Stn17; fnd seat not locking in place; rem seat cushion; rep spring & lock asy; ck opn; ck ok; reinstalled seat. j

NO PARTS USED

#### Workorder: V31052

In Date: 03/26/2010

Meter Reading: 78,346.90

Close Date: 04/20/2010

#### Problem?

HEAD LIGHTS NEED TO BE ADJUSTED. R17

#### Task performed:

#### Parts

#### Quantity

1. Adj headlites best as poss.
2. Fnd auto-eject inop; R/R auto-eject; ck opn; ck ok. j

0915520120AUTO EJECT 20 AERO OTL3925

1

#### Workorder: V31107

In Date: 03/29/2010

Meter Reading: 78,919.00

Close Date: 04/20/2010

#### Problem?

SPARE R17 SCENE LIGHTS WON'T COME ON ALL SHOW LOCKED ON DISPLAY HEAD,HEAD LIGHTS NEED ADJUSTMENT....CRS...

#### Task performed:

#### Parts

#### Quantity

Ck scene lites onging on/off w/switch; ck ok. j

NO PARTS USED

#### Workorder: V31734

In Date: 04/23/2010

Meter Reading: 79,012.50

Close Date: 04/27/2010

#### Problem?

A INSPECTION AND REPAIRS AS NEEDED SR13

#### Task performed:

#### Parts

#### Quantity

A-Inspection j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V31951

In Date: 05/03/2010

Meter Reading:

Close Date: 05/19/2010

Problem?

\*

#### Task performed:

#### Parts

#### Quantity

1. C/O tires; fnd R/R outer flat; let foreman know.
2. Assist w/swapout of truck.
3. Reseal tire & fill - chk. j

NO PARTS USED

#### Workorder: V32026

In Date: 05/05/2010

Meter Reading: 79,012.50

Close Date: 05/20/2010

Problem?

Front drivers side stobe cover is missing. Truck is spare rescue. R19

#### Task performed:

#### Parts

#### Quantity

1. Went to 19; R/R (1) cone rubber bumper on ram fan; R/R Hurst fee mnts; ck ok.
2. Went to 19; R/R R/hood lens on strobe; ck ok. j

02-0383470-CROBSOLETE LENS RED/CLEAR

1

07-0608A7160 DRIER A/C FRTLNR ABP-N83-319714

1

377R054FEET - HURST TOOL

1

FZ51368FEET RUBBER RAM-FAN

1

#### Workorder: V32105

In Date: 05/10/2010

Meter Reading: 79,012.50

Close Date: 05/20/2010

Problem?

Perform "A" service. Back from station 19.

#### Task performed:

#### Parts

#### Quantity

- A-Inspection
2. R/R lens; R/R gbulb center cab dome lite.
3. Rem black goo frm windshield.
4. R/R pass side cab door panel; cln/lube hinges; cln/lube door friction rod.
5. Tightene screws on center L/S compt hold opn.
6. Pos/adj fittings on P/S hose rubbin against another hose; also tightene loose fitting at pump.
7. Bench in pat compt brkn; fab a support; drill/bolt support; reglue brkn formica.
8. R/R R/S rear double door panels, window frame, grabrail, center panel & lock shroud; drill/replc defective nut sert; straighten bent locking latch lever; adj rods to upper/lower latches. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V32642

In Date: 06/04/2010 Meter Reading: 79,640.00  
Close Date: 06/18/2010

#### Problem?

ON CALL R34 HEADLIGHT 10-7

#### Task performed:

R/R R/front headlight 60541. j

#### Parts

H6054USE CV TYPE SEALED BEAM

#### Quantity

1

#### Workorder: V32885

In Date: 06/14/2010 Meter Reading: 79,856.30  
Close Date: 06/23/2010

#### Problem?

A INSPECTION AND REPAIRS AS NEEDED SR 13

#### Task performed:

A-Inspection.  
2. Air tires - low.  
3. Top off fluids - low.  
4. L/R marker inop; rep connection.  
5. pat compt R/R door hard to open; linkage binding; adj inner linkage; tightened/lubed latches.  
6. Hazmat/caginet drawers - sliders worn; replcd sliders & rep mntng; also had to adj height to get operational.  
7. Stretcher mnt inop; out of adj - adj, mnt & lubed.  
8. Mirros loose; tightend & adj.  
9. Sev pat compt door panels loose & msng screws; tightened & installed screws as needed. j

#### Parts

5632-1010 IN DRAWER SLIDES PR

SLD5366HT4932-16 DRAWER SLIDE 16

#### Quantity

2

2

#### Workorder: V33137

In Date: 06/25/2010 Meter Reading: 80,189.00  
Close Date: 06/29/2010

#### Problem?

front a/c inop a inpection R68

#### Task performed:

A-Inspection  
2. Chk A/C (frt); adj wtr valve & chk A/C gauge press;-ok; chk temp at register 39 degrees - OK. j

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V27173

In Date: 10/26/2009

Meter Reading: 528.10

Close Date: 07/13/2010

#### Problem?

voltage reading fine (+14.0) amps reading -37 to -38. The truck is running fine, don't know if this is a problem. Help. Thanks. r 35

#### Task performed:

Verified job j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V29932

In Date: 02/12/2010

Meter Reading: 77,943.00

Close Date: 07/13/2010

#### Problem?

N1PL Diagnostic Error on R45 Alpha

#### Task performed:

Verified job. j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V28947

In Date: 01/08/2010

Meter Reading: 77,598.00

Close Date: 08/12/2010

#### Problem?

check weld on frame for crack progression at fishplate (next B inspection) DEFERRED

#### Task performed:

DEFERED TO P.M

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V34082

In Date: 08/06/2010

Meter Reading: 81,048.00

Close Date: 08/26/2010

#### Problem?

A inspection and repairs (from 56)

#### Task performed:

- A-Inspection
2. Replc convex mirror, left side.
3. Replc right headlight.
4. Replc btrys.
5. Travel frm St81 to C/S; chk veh for oil leaks; raise veh; cln btm of eng trans & radiator; road test veh & chk for leaks.
6. Continue oil leaks repair & road testing until done; R/R fitting on trans cooler; cln/install thread seal; rep leak at fitting\_\_\_\_ surfaces; rep leak at P/S pump fitting.
7. Inspect rear brakes; enough lining left to not do brakes; show to Ed Ehrke; he agreed-no rear brakes at this time. ja

#### Parts

#### Quantity

980-412173 MIRROR 8 IN

1

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

4

H6054USE CV TYPE SEALED BEAM

1

HP-31DBATTERY 950CCA HP-31D

4

#### Workorder: V33626

In Date: 07/19/2010

Meter Reading: 80,256.30

Close Date: 09/08/2010

#### Problem?

SPARE RESCUE, DRIVER'S SIDE HEADLIGHT NEEDS TO BE REPLACED. sr at 56

#### Task performed:

1. Air leak; rep air leaks.
2. Replc lens on rear of rescue. j

#### Parts

#### Quantity

6EFLANGE600 CHROME FLANGE

4

H6054USE CV TYPE SEALED BEAM

4

#### Workorder: V34961

In Date: 09/15/2010

Meter Reading: 81,119.50

Close Date: 09/29/2010

#### Problem?

R/R tire flat R41 (outside agency-boulevard tire)

#### Task performed:

R/R tire flat R41 - Boulevard j

#### Parts

#### Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V34628

In Date: 08/31/2010

Meter Reading: 81,119.50

Close Date: 10/21/2010

#### Problem?

nail in left front tire AND over head spot lite not working r45

#### Task performed:

#### Parts

#### Quantity

1. check spot light, repaired bad ground on spotlight.  
jab
2. check a/c found 110a/c inop, reset breaker. jab

NO PARTS USED

#### Workorder: V35398

In Date: 10/04/2010

Meter Reading: 83,449.40

Close Date: 10/25/2010

#### Problem?

REPLACE TIRE BOULEVARD

#### Task performed:

#### Parts

#### Quantity

Replace tire - Boulevard j

NO PARTS USED

Vendor? BOULEVARD TIRE

#### Workorder: V35785

In Date: 10/19/2010

Meter Reading: 84,451.00

Close Date: 10/29/2010

#### Problem?

perform "b service.

#### Task performed:

#### Parts

#### Quantity

- B-Inspection
2. Sec all inner compt door skins.
3. Se all compt door latches.
4. Lube SCBA doors.
5. Replcd
6. Rem striker magnet & put in shop office for Tommy.
7. Topped off eng fluids.
8. Adj door linkage R-1 compt.
9. Replc wiper blades, washer tee & hose to arm.
10. Replc O2 light switch.
11. Rep grnd to clearance light.
12. Replc hi/lo dome bulbs.
13. Replc (4) rear tires.
14. Adj tire press.
15. Rep brkn wire to O2 light. j

15W40BSYN OIL BULK QTS  
322502BULB PATIENT GH22  
52-24WIPER BLADES ANCO 24  
921LIGHT BULB  
HLD374211 IN HOLD-OPEN 30LB  
L1261F33585XE FUEL FILTER WIX  
PH8942FILTER OIL 57182 LFP3729  
S3225PFUEL FILTER 33630 LFF5849  
SPR-W58-1TEE PLASTIC  
SWT5492744435 ACTUATOR-BLACK

28  
1  
2  
1  
1  
1  
1  
1  
1  
1



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V35833

In Date: 10/21/2010

Meter Reading: 80,189.00

Close Date: 11/05/2010

### Problem?

repair engine (head gasket leaking, front cover oil leak) (outside agency-cummins) SR13

### Task performed:

#### Parts

#### Quantity

Rep eng(head gskt leaking, frnt cvr oilleak - CUmmins  
j

NO PARTS USED

Vendor? CUMMINS

## Workorder: V35706

In Date: 10/17/2010

Meter Reading: 84,089.00

Close Date: 11/16/2010

### Problem?

med drawer out of alignment R41

### Task performed:

#### Parts

#### Quantity

1. repair med drawer that fell out.      jab

NO PARTS USED

## Workorder: V36599

In Date: 11/22/2010

Meter Reading: 84,646.00

Close Date: 11/30/2010

### Problem?

several strobes out R39 (on-call)

### Task performed:

#### Parts

#### Quantity

(1) TRAVELED TO ST39 TO REPAIR EMERGENCY STROBE LIGHTS ON R39. REPLACED BURN'T OUT BULBS. STROBE WORKING INTERMITTENTLY. CHECKED STROBE PACKS, ALL OPERATING NORMALLY. UNIT STILL IN SERVICE WITH ONLY ONE LIGHT OUT. OK.                      J.W.

TURBO5TUBE - STROBE

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V36700

In Date: 11/29/2010

Close Date: 12/03/2010

Meter Reading: 85,089.90

#### Problem?

on call eme lts 10-7 r39

#### Task performed:

(1) TRAVELED TO STATION 39 ON OT TO REPAIR EMERGENCY LIGHTS ON REAR OF R39. CHECKED SYSTEM AND FOUND A BAD CONNECTION ON THE POWER SUPPLY. REPAIRED CONNECTION AND ALL CHECKED OUT OK. J.W.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V36594

In Date: 11/21/2010

Close Date: 12/15/2010

Meter Reading: 84,646.00

#### Problem?

Right front strobe light not working. Spot light not working. sta R39

#### Task performed:

(1) TRAVELED TO STATION 39. STRETCHER BRACKET NOT HOLDING STRETCHER IN PLACE. READJUSTED THE STRETCHER LATCH. OK NOW. J.W.

#### Parts

6092036018J HOOK STRYKER

#### Quantity

1

#### Workorder: V34895

In Date: 09/12/2010

Close Date: 12/22/2010

Meter Reading: 81,770.00

#### Problem?

1. Rotating spot light is out. 2. Right rear red flashing light cover is missing. R41

#### Task performed:

(1) ROTATING SPOT LIGHT IS OUT.  
RIGHT REAR RED FLASHING LIGHT COVER IS MISSING. R41.  
REPAIRED ALL EMERGENCY LIGHTS THAT WERE OUT. J.W.

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V37219

In Date: 12/16/2010

Meter Reading: 85,995.70

Close Date: 01/11/2011

#### Problem?

Front driver side head light out... R39

#### Task performed:

1. Headlight inop; replc headlight.

2. Cab A/C inop, readj heater cable and teted. j

#### Parts

9007H9007 BULB ASSY

#### Quantity

1

#### Workorder: V37307

In Date: 12/20/2010

Meter Reading: 86,346.50

Close Date: 02/07/2011

#### Problem?

1. Receiving error message "Diagnostic Error Node 1 Pin L" on digital display. 2. Spotlight is inoperable. R39

#### Task performed:

replc headlight that was out. j

#### Parts

18753-0455H7935-1 SPOT LIGHT BULB SPT6008

#### Quantity

1

#### Workorder: V37737

In Date: 01/11/2011

Meter Reading: 88,029.80

Close Date: 02/08/2011

#### Problem?

Loose piece of metal strapping in back of truck. Got caught on pants last night. Partially secured needs permanant fix. R39

#### Task performed:

installed stainless steel plate in rear of rescue. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V37890

In Date: 01/19/2011

Meter Reading: 88,409.00

Close Date: 03/08/2011

#### Problem?

2 dome lights in pt compartment burned out on high and low

#### Task performed:

Replcd (4) bulbs in rea of rescue. j

#### Parts

322502BULB PATIENT GH22

#### Quantity

6



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V38733

In Date: 02/23/2011

Meter Reading: 90,596.00

Close Date: 03/09/2011

#### Problem?

REPLACE FRONT TIRES BOULEVARD

#### Task performed:

Replc frnt tires - Boulevard j

#### Parts

NO PARTS USED

#### Quantity

Vendor? BOULEVARD

#### Workorder: V38557

In Date: 02/16/2011

Meter Reading: 90,596.00

Close Date: 03/28/2011

#### Problem?

Runs rough eng R39

#### Task performed:

1. Test drove; fnd truk running 205 degrees; eng msng & white smoke out of exh; ck codes - no codes; fnd air clnr brkn; poss blown head gskt; swapped truck; fnd head gskt - ck ok.

2. Fnd turbo not spinning freely rem heat shed, clmps, hoses & lines; rem turbo; ordered part; replc turbo, gskts, drain hose; repos turbo; test drove; ck ok. j

#### Parts

3505300C1RELAY

#### Quantity

1

#### Workorder: V39387

In Date: 03/23/2011

Meter Reading: 91,739.90

Close Date: 03/28/2011

#### Problem?

Coolant leak is increasing in intensity. Having to add coolant daily. r39

#### Task performed:

sent to Cummins for repair. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V39369

In Date: 03/22/2011

Meter Reading: 91,524.00

Close Date: 03/30/2011

#### Problem?

UNIT OVERHEATING SR AT 35

#### Task performed:

1. Go to stn35 to replc electric fan clutch 10-7; overheating; rep - ok.

2. Assist replc fan clutch at Stn35. j

#### Parts

996019FAN CLUTCH 680-200-06-26

#### Quantity

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V38575**

**In Date:** 02/16/2011

**Meter Reading:** 90,662.00

**Close Date:** 04/08/2011

**Problem?**

**C INSPECTION AND REPAIRS R 39**

#### Task performed:

C-Service  
2. Fnd LRI tire flat; rem wheels; sprayed/rep leak on tire; replc lug nuts & reinstalled tires/hub cap.  
3. Fnd axle u-bolts loose; torq all bolts.  
4. Rebuild air dryer; rem lines/dryere; rebuilt dryer asy; installed. ran/chk opn; ck ok.  
5. Fnd soreline A/C inop; fnd fitting leaking; rep leak; vac/charge A/C; ran/ck ok.  
6. Fnd A/C inop; recvr freon; leak test sys; fnd leak at dryer switch; R/R exp. block/dryer; leak test; vac/charge; ck ok.  
7. Ck for air leaks; sprayed fittings/lines; fnd fitting leaking; rep/resealed; ran/ck ok.  
8. Rep btry box slides; clnd/lube slides; clnd/lube slides - ck ok; fnd btry charger inop; rem cvr/ R/R fuse; ran/ck ok. j  
9. Fnd inside compt shocks bad; R/R shocks on doors & squad bench - ck ok; R/R door time; R/R pat A/C filter.  
10. Fnd pat A/C inop; t-shoot/rep connection to compressor - ck ok.  
11. Fnd pat side door grip tape worn; R/R tape; rep door sill; fnd R-1 weatherstrip off; glued weatherstrip - ck ok.  
12. Fnd rad leaking - drained; rem hoses, lines, cables, brkts, condensor & rad; replc rad; reassem all parts; R/R hose clmps; ck for leaks; ck ok.  
13. Fnd axe nut loose; drilled/replc bolts; R/R SCBA bumper; tighten rear door grab handles.  
14. Fnd latches/nader pins loose; tighten/adj pins/latches; ck ok. j

#### Parts

#### Quantity

107796DRYER KIT AD9 -NEW	1
107800VALVE CHECK AD9	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
19282TAPE ANTI-SLIP PER FT 60FT ON ROLL	4
322502BULB PATIENT GH22	1
3802882RXTURBOHARGER	1
3818824TURBO NUT	4
39121833286499 HOSE OIL RETURN	2
3922794SEAL O RING	1
3931824SEAL	2
5264569DRAIN GASKET 3937706	2
716907-0610A DRYER	1
800405PURGE VALVE KIT	1
8201L17-3428 ESTER OIL E7	1
A0516058001F10 RESCUE C RADIATOR	1
A2245482000 12-0615A VALVE EXPANSION FTRLNR 1606	1
CH27007BUMPER DOOR	1
CLR9185209186-1500-20 MARKER LT.AMBER LED	1
DNEPG110286DNEPG110314 AIR CLEANER ASSY	1
E-600013-3052 NUT	4
GSS1717UL1717UL0270N 343/09 GAS SHOCK 60 LB	2
HLD3999GSS1715UV 30LB STRUT GAS	4
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RAIRK30880N122WSKL4000 SENSOR WATER IN FUEL	1
S3225PFUEL FILTER 33630 LFF5849	1
ZGG725028FLUID	1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V39643

In Date: 04/04/2011

Meter Reading: 92,054.90

Close Date: 04/13/2011

#### Problem?

ORDER PART FOR OVERHEAT PROBLEM R 39

#### Task performed:

Travel to stn; fan intermittent; got unit back to shop; fnd fan relay jumped; installed new relay fan; working properly now. j

#### Parts

1219360123-11276-041 RELAY VF28-35F14-Z05  
RSC-85927C1SENSOR COOLANT TANK LEVEL

#### Quantity

2  
1

#### Workorder: V39641

In Date: 04/04/2011

Meter Reading: 92,054.90

Close Date: 04/14/2011

#### Problem?

ON CALL R 39 OVERHEATING

#### Task performed:

Eng overheats; eng fan does not come on; poss alarm stat locked fan up; full time road tested; will order part Monday j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V39642

In Date: 04/04/2011

Meter Reading: 92,054.90

Close Date: 04/14/2011

#### Problem?

ON CALL R 39 WONT START

#### Task performed:

No start - starter solenoid bad; replc fire wall, mntd solenoid. j

#### Parts

ESX120105112STARTER RELAY ESX-120-105112

#### Quantity

1

#### Workorder: V39828

In Date: 04/11/2011

Meter Reading: 92,281.20

Close Date: 04/14/2011

#### Problem?

won't start (on-call)

#### Task performed:

Dia no start; fnd auto-eject malfunction; diss auto-eject.

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V39964

In Date: 04/17/2011

Meter Reading: 92,956.80

Close Date: 04/25/2011

#### Problem?

Shoreline auto-eject appears to have short. When plugged in smell of burning plastic is strong in the area. Plug has burned and discolored plastic and charring on contacts. R39

#### Task performed:

After getting back to stn, looked at auto-eject; to see if related to starter problem; auto-eject looks burnt; R/R auto-eject; chk wiring at starter relay. j

#### Parts

091-20WP-120AUTO EJECT

#### Quantity

1

#### Workorder: V40009

In Date: 04/19/2011

Meter Reading: 92,588.80

Close Date: 04/25/2011

#### Problem?

won't start R39

#### Task performed:

Wont start in Publix parking lot; drove to scene; starter faulty; R/R starter; took bak to stn. j

#### Parts

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

#### Quantity

1

#### Workorder: V39754

In Date: 04/06/2011

Meter Reading: 92,167.20

Close Date: 05/06/2011

#### Problem?

when a/c is one it sounds like the belt is sweaking. e39

#### Task performed:

Readj cab A/C belts. j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V39788

In Date: 04/08/2011

Meter Reading: 92,281.20

Close Date: 05/06/2011

#### Problem?

Engine misfires while idling. Increasing frequency. Truck idles up to overcome misfiring. sta39.

#### Task performed:

1. Replcd speed sensor & ran.
2. Rep rear door handle that was falling off. j

#### Parts

40020664921601 SENSOR CRANK POSITION

#### Quantity

1





3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V39827

In Date: 04/11/2011

Meter Reading: 92,281.20

Close Date: 05/06/2011

### Problem?

Auto eject innop sta39.

### Task performed:

1. Rep auto-eject wire & tested.
2. Chkd A/C & tested ok. j

### Parts

NO PARTS USED

### Quantity

## Workorder: V40152

In Date: 04/25/2011

Meter Reading: 93,631.70

Close Date: 05/09/2011

### Problem?

1. Driver's side fish-eye mirror is loose. R39 2. Loud humming noise noted from steering column area increasing frequency and intensity. Fluids are normal. Only happens at idle.

### Task performed:

Road tested truck; fnd no noise frm eng. j

### Parts

NO PARTS USED

### Quantity

## Workorder: V39879

In Date: 04/12/2011

Meter Reading: 92,588.80

Close Date: 05/13/2011

### Problem?

driver side headlight out r 39

### Task performed:

replcd headlight. j

### Parts

NO PARTS USED

### Quantity

## Workorder: V40455

In Date: 05/06/2011

Meter Reading: 94,381.00

Close Date: 06/03/2011

### Problem?

Need several patient compartment overhead lightbulbs replaced as they are burned out. Thanks R39

### Task performed:

1. Replc pat lights in rear.
2. A/C switch - replc switch in cab. j

### Parts

322502BULB PATIENT GH22

ABPN8332229011-3050 SWITCH BLOWER

### Quantity

2

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V40629

In Date: 05/16/2011

Meter Reading: 95,203.40

Close Date: 06/03/2011

#### Problem?

L reverse light out, Sta39.

#### Task performed:

#### Parts

#### Quantity

1. Replc reverse light & rep grnd wire.
2. Chkd 110 A/C & tested ok. j

NO PARTS USED

#### Workorder: V39152

In Date: 03/14/2011

Meter Reading: 90,854.30

Close Date: 06/09/2011

#### Problem?

Significant coolant leak noted under vehicle. During AM check coolant level noted to be low. Also slow oil leak noted under vehicle w/ normal oil levels. sta 39

#### Task performed:

#### Parts

#### Quantity

1. travel to sta 39
- 2 check for coolant leak, found water pump leaking, send to c/shop for repair
3. Wtr pump leaking; R/R wtr pump; pressure tested head gskt; has small leak; will reschedule repair at later date per Mike Lehan. j

3286278WATER PUMP ISB

1

#### Workorder: V40682

In Date: 05/18/2011

Meter Reading: 95,203.40

Close Date: 06/09/2011

#### Problem?

front cab air conditioning is blowing hot air R 39

#### Task performed:

#### Parts

#### Quantity

Recharged sys & chk for leaks. j

NO PARTS USED

#### Workorder: V40710

In Date: 05/19/2011

Meter Reading: 95,451.70

Close Date: 06/09/2011

#### Problem?

vista screen not working r39

#### Task performed:

#### Parts

#### Quantity

Chkd problem w/vista screen & fnd screen working. j

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V40737

In Date: 05/19/2011

Meter Reading: 95,506.90

Close Date: 06/09/2011

#### Problem?

Vibration and humming noise from steering column worsening. Entered previously. Sta 39.

#### Task performed:

road tested; fnd no noise frm steering column.

j

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V41147

In Date: 06/06/2011

Meter Reading: 96,447.70

Close Date: 06/23/2011

#### Problem?

A/C leak, power steering noise, air leak, reverse light out. Sta 39.

#### Task performed:

1. P/S - ck/noise; R/R P/S filter/fluid; cld not test drive.
  2. Backup light - R/R right backup light.
  3. Assist on evap - rep pat A/C.
  4. Rem pat compt evap unit - leaking; cln all reside out of A/C compt & pat compt frm wtr/coolant leakage.
  5. Replc compressor discharge line/hose - leaking.
  6. Installed new evap in pat compt unit; replc both expansion valves; replc both dryers; vac/recharge both sys; road test/rechkd A/C sys; working normally.
  7. Replc A/C vents in pat compt A/C access door - brkn.
- j

#### Parts

02028345000REFLECTOR  
040444-01EXPANSION VALVE R-22  
071601A07-0602A DRIER A/C 7118  
1501450007750USE 0775145  
68118358130600 SER OPTIC CLEAR  
A1211593054HOSE DISCHG  
EXV92812V EXPANSION VALVE  
FG87904MFG3937557S FILTER P/S NEW STYLE  
FGQ59267COVER GASKET STEERING  
H35SN12BULB  
HE50477VENT  
PROTO3EVAPORATOR HOSELINE

1  
1  
2  
1  
1  
1  
1  
1  
1  
1  
3  
1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V41364

In Date: 06/15/2011

Meter Reading: 96,669.00

Close Date: 06/24/2011

#### Problem?

B INSPECTION AND REPAIRS AS NEEDED R 39

#### Task performed:

- B-Inspection
2. R/R sharpies draw slides & cut out drain divider.
3. Tighten all exh hangers/bands.
4. R/R frnt/rear brake pads, rotors & wheel seals.
5. Chk for coolant leak, tighten all hose clamps.
6. R/R drag link.
7. R/R frnt hub cap seals leaking oil.
8. Quality check; test drove, chk brakes & noise in brake sys; ck ok. j

#### Parts

#### Quantity

1608340-4065 CAP OIL STEMCO/CR  
370047ASEAL 34387  
370150ASEAL  
5632-1010 IN DRAWER SLIDES PR  
A1414374000DRAG LINK RESCUE  
D6176M121-83014 ROTORS RESCUE  
E-2436R002436 GASKET-REAR AXLE  
L1261F33585XE FUEL FILTER WIX  
MK184HDBRAKE PADS  
PH8942FILTER OIL 57182 LFP3729  
S3225PFUEL FILTER 33630 LFF5849

1  
2  
2  
2  
1  
4  
2  
1  
2  
1  
1

#### Workorder: V41093

In Date: 06/03/2011

Meter Reading: 96,382.00

Close Date: 06/28/2011

#### Problem?

reported 5/16/11 not repaired to date, Sta 39. L reverse light out

#### Task performed:

- Rplaced bulb in light and repaired lewes  
repaired streacher latch and tested ak

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V41115

In Date: 06/05/2011

Meter Reading: 96,447.70

Close Date: 06/28/2011

#### Problem?

Rear AC drain line is not working. Water collects while plugged into shore line and spills in back of truck when truck moves. R39

#### Task performed:

- unit sent to shop ak

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V41637

In Date: 06/27/2011

Meter Reading: 97,045.40

Close Date: 08/08/2011

#### Problem?

Vibration/Humming noise in steering column has returned. Was recently out for repair of same. R 39

#### Task performed:

Parts

Quantity

check unit noise coming from suspension valve not steering column

NO PARTS USED

#### Workorder: V42055

In Date: 07/15/2011

Meter Reading: 98,176.80

Close Date: 08/08/2011

#### Problem?

Vibration and humming noise still present in steering column. Was in shop w/ some repairs made but problem not resolved. Sta 39

#### Task performed:

Parts

Quantity

road tested found noise from h block wrapped in brubber

NO PARTS USED

#### Workorder: V42761

In Date: 08/12/2011

Meter Reading: 100,152.80

Close Date: 08/12/2011

#### Problem?

door open light .

#### Task performed:

Parts

Quantity

r39 replaced door switch

NO PARTS USED

fire 2nd alarm

#### Workorder: V42196

In Date: 07/21/2011

Meter Reading: 98,587.80

Close Date: 08/25/2011

#### Problem?

Cab AC blowing warm air. Sta 39.

#### Task performed:

Parts

Quantity

readjusted heater cable and turned on a/c

NO PARTS USED

repaired stretcher latch and tested



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V42738

In Date: 08/11/2011

Meter Reading: 100,063.00

Close Date: 09/12/2011

#### Problem?

SECOND REQUEST- First entered 8/6 Request # P43825 Electronic oxygen guage on Main O2 coupling has loose wire. Multiple layers of tape have been added to to keep the wire in place and avoid loud audible alarm. Sta 39.

#### Task performed:

repalced o2 sencer and tested

#### Parts

#### Quantity

91823SWITCH SWT5499 MED MASTER

4

AST4000ASENSOR O2 REGULATOR

1

STOPSN12BULB STOP/TAIL LIGHT

1

### Workorder: V42943

In Date: 08/20/2011

Meter Reading: 100,805.00

Close Date: 09/12/2011

#### Problem?

Rear AC is flooding the back of the truck again. Water is running through the air intake and over the breaker panel for the shorelin R 39

#### Task performed:

unclogged drain and rechecked unit

#### Parts

#### Quantity

NO PARTS USED

repaired air ride seat that was leaking

### Workorder: V43592

In Date: 09/12/2011

Meter Reading: 102,252.50

Close Date: 09/16/2011

#### Problem?

engine has no power excessive smoke r 39

#### Task performed:

take sev long test drives; \_\_\_\_ complete & dia faulty injectors. j

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V42877

In Date: 08/17/2011

Meter Reading: 100,423.00

Close Date: 09/19/2011

#### Problem?

Strobe light out- rear lightbar R 39

#### Task performed:

repalced strobe light

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V43079

In Date: 08/26/2011

Meter Reading: 101,330.90

Close Date: 09/19/2011

#### Problem?

Second Request- First #p44137 entered 8/20/11 Rear AC is overflowing and flooding rear of truck, including breaker panel and connections for shore line and equipment. Mold smell in back of truck. Has occurred in past. Sta 39.

#### Task performed:

cleaned out a/c drain lines

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V43080

In Date: 08/26/2011

Meter Reading: 101,330.90

Close Date: 09/19/2011

#### Problem?

If possible we need motor oil delivered to the station. We have none and are several quarts low. Borrowed some from another station. Sta 39.

#### Task performed:

dropped off ok

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V43534

In Date: 09/09/2011

Meter Reading: 102,252.50

Close Date: 09/19/2011

#### Problem?

Engine smokes no power R39

#### Task performed:

go to jfk check out truck smoking look like injector or pump bad got it back to station bring --to shop for truck take to station

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V43709

In Date: 09/16/2011

Meter Reading: 102,252.50

Close Date: 09/19/2011

#### Problem?

A inspection.

#### Task performed:

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V43628

In Date: 09/13/2011

Meter Reading: 102,252.50

Close Date: 09/20/2011

#### Problem?

REPLACE INJECTORS CUMMINS POWER SOUTH.

#### Task performed:

Replc injectors - Cummins j

#### Parts

NO PARTS USED

#### Quantity

Vendor? CUMMINS

### Workorder: V43375

In Date: 09/01/2011

Meter Reading: 101,764.00

Close Date: 09/21/2011

#### Problem?

Driver's seatbelt is split and frayed. R 39

#### Task performed:

1. R/R driver seat belt w/new.
2. Replc (1) grille strobe light out; R/R rear scene light out.
3. Drive truck for hard shift; fast adapt trans trans; drive to reset shift; ok.
4. Cln out rear A/C drains; blow out. j

#### Parts

IMMF13224BELT SEAT DRIVER SIDE IMMF11851 OLD #

1

### Workorder: V43489

In Date: 09/07/2011

Meter Reading: 102,129.00

Close Date: 09/21/2011

#### Problem?

2qts oil low, leaked about 1 week, 500mi from PM Seatbelt still torn 1 strobe/1 scene light out Transmission shifting rough (worsening), Sta 39. Intermittent short in L front headlight, replaced last shift, problem yesterday

#### Task performed:

See WO 43375 I clsd on 9/21/11 j

#### Parts

15W40BSYN OIL BULK QTS

58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E

H35SN12BULB

1

1

1

### Workorder: V43490

In Date: 09/07/2011

Meter Reading: 102,129.00

Close Date: 09/21/2011

#### Problem?

Rear AC still leaking, repaired and problem returned. Door alarm sounds while truck is in park. Truck does not high idle at all. \*\*AT here--additional information about problems. Sta 39.

#### Task performed:

Coming to shop OOS per note on WO j

#### Parts

NO PARTS USED

#### Quantity





3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V42612

In Date: 08/06/2011

Meter Reading: 99,847.00

Close Date: 10/07/2011

### Problem?

Electronic guage on main O2coupling has a loose wire. Red wire is loose causing guage to read 0 and alarm to sound. Wire temporarily secured today. R 39

### Task performed:

Parts

Quantity

repaired air horn bracket that was falling off truck

NO PARTS USED

reinstalled tool in l1 compartment

repaired o2 line and tested

## Workorder: V43996

In Date: 09/28/2011

Meter Reading: 103,031.00

Close Date: 10/07/2011

### Problem?

Strobe light out. Far R on rear lightbar. Sta 39.

### Task performed:

Parts

Quantity

replaced light out and replaced

NO PARTS USED

## Workorder: V44268

In Date: 10/11/2011

Meter Reading: 104,060.80

Close Date: 10/14/2011

### Problem?

\*\*\*\*Saftey Problem\*\*\*\* Rear folding step is being held in place by 1 screw that is partially in place. Step moves freely on L side. P45325, P45303, and P45089 still not addressed. r 39

### Task performed:

Parts

Quantity

REPAIRED FOLDING STEP THAT WAS FALLING OFF

NO PARTS USED

## Workorder: V44171

In Date: 10/05/2011

Meter Reading: 103,576.40

Close Date: 10/21/2011

### Problem?

officer side compartment door, behind cab, will not open when handle is pulled. Sta 39.

### Task performed:

Parts

Quantity

adjusted door linkage and tested

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V44208

In Date: 10/07/2011

Meter Reading: 103,692.00

Close Date: 10/21/2011

#### Problem?

See wo P45089- Strobe light still out R39 Rear scene light out 1100 miles overdue for PM Transmission is shifting very rough again  
Was worked on and repair did not hold.

#### Task performed:

replaced strobe lights in rear

#### Parts

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

#### Quantity

2

fast adapted trans and road tested

#### Workorder: V44235

In Date: 10/08/2011

Meter Reading: 103,692.00

Close Date: 10/21/2011

#### Problem?

L headlight is dangling by wire. Diagnostic error N3PN. Rear dome light out. R39

#### Task performed:

repaired head light bracket

#### Parts

NO PARTS USED

#### Quantity

replaced dome lights

#### Workorder: V44251

In Date: 10/09/2011

Meter Reading: 103,933.00

Close Date: 10/21/2011

#### Problem?

left head light loose R 39

#### Task performed:

replaced head light

#### Parts

0621123000HEADLIGHT BRK.

#### Quantity

1

#### Workorder: V44378

In Date: 10/14/2011

Meter Reading:

Close Date: 10/26/2011

#### Problem?

Transmission reverted to very rough shifting. Consistent very hard shift between 2 and 3. Intermittent from N to 1 and 1 to 2. Station 3

#### Task performed:

PERFORM FAST ADAPTIVE RESET TO TRANS., TEST  
DRIVE VEHICLE UNTIL SHIFTS ARE SMOOTH

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V44816**

**In Date:** 10/31/2011

**Meter Reading:**

**Close Date:** 11/02/2011

**Problem?**

Transmission is shifting very rough into gear again. Rear scene light out. Rear suspension is rough. Truck rocks significantly with small bumps and strikes frame over large bumps or driveways. Sta 39.

**Task performed:**

1. Replc rear work light.
2. Adj rear air bags & test drive. j

**Parts**

**Quantity**

60F000RRLIGHT 600 SERIES

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V44386**

**In Date:** 10/14/2011

**Meter Reading:** 104,278.00

**Close Date:** 11/03/2011

**Problem?**

C INSPECTION AND REPAIRS R 39

**Task performed:**

Parts

Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

C INSPECTION	02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
C INSPECTION	1094KIT-AIR HORN-GROVER	2
	15W40BSYN OIL BULK QTS	17
SERVICE BATTERIES, FOUND BATTERIES BAD, REPLACED BATTERIES	29526898 29548988 TRANS FILTER ALLISON	1
	46455AIR FILTER MAGNETEK GEN	1
C INSPECTION	50R00FRRFLASHER RED LED FLANGED	1
	52-24WIPER BLADES ANCO 24	2
INSTALL ALL BULBS IN ROOF CLEARANCE LIGHTS	68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR	1
	9451BELT	1
RETIME WIPER ARMS	9485BELT	1
	98003RREFLECTOR RED 40132 GROTE	2
INSTALL NEW WIPER BLADES	A0516228002FAN STRAP	1
	A2241332084A2241332084 HOSE A/C LOW	1
SET VEHICLE ON JACK STANDS AND ASSIST JEFF WITH FRONT END CHECK OUT FOR ERATIC TIRE WARE	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	4
	FSC17492134NC SW PARK BK SPADE TYPE CONNECTOF	1
CHECK FRT END SUSPENSION AND WHEEL BEARING ADJ	HA141LIGHT RED WARNING	1
	HLD374211 IN HOLD-OPEN 30LB	1
REPLACE BELTS	HP-31DBATTERY 950CCA HP-31D	4
	ICC5ALLED CLEARANCE LIGHT AMBER	1
R&R COMPRESSOR, REMOVED BROKEN BOLT. RETIGHTEN BELTS	K080733BELT	1
	L1261F33585XE FUEL FILTER WIX	1
ADD WASHER FLUID AND SOLUTIONS	P111933351 FILTER	1
	PH3534OIL FILTER 51714 WIX	1
REPALCED R 1 COMPT. HOLD OPEN BRACKET, FILE SHARP EDGE ON BODY, DIASSEMBLE HOLD OPEN AND CUT FPRING TO SIZE	PH8942FILTER OIL 57182 LFP3729	1
	S3225PFUEL FILTER 33630 LFF5849	1
REPLACE R SIDE PATIENT COMPT HOLD OPEN BRACKET, LINK AND PIN	TRANSYNDALLISON TRANS FLUID GAL	6
LUBE ALL LATCHES AND HOLD OPENS		
TIGHTEN LOOSE L3 HINGE BRACKET BOLTS		
REPLACE L2 DOOR HOLD OPEN BRACKETS, LINKS, AND PINS ON BOTH INSIDE AND OUTSIDE DOORS		
REPAR SCBA DOOR LATCH, DISASSEMBLE, FOUND SPRING BOUND UP, STRAIGHTEN SPRING AND REASSEMBLE		
REPLACED L2 REFLECTOR AND REAR PATIENT COMPT REFLECTOR REPLACED MISSING BOLTS, DRILL OUT HOLES IN REFLECTORS		
REPLACED FRT TIRES AND WHEELS, AIRED ALL TIRES TO MANUFACTURES SPEC		



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

CHECK TOE ANGLE OK 0 DEGREES TO ONE SIXTENTH TOE IN

STRAIGHTEN BENT LICENSE PLATE AND HOLDER

TIGHTEN OIL PAN BOLTS

LUBE TRUCK

DISASSEMBLE FRONT LIGHTBAR TO INSTALL BUILT IN CLEARANCE LIGHT FIXTURE

INSTALL ASSET NUMBER ON WINDSHIELD

PAINT FUEL CAP

RAN CLUTCH STATIONARY BRACKET BROKEN, REMOVE OLD BRACKET ASSEMBLY AND INSTALL NEWER STYLE, MODIFICATION NECESSARY TO INSTALL NEWER STYLE

BUFF OUT ALL LIGHT LENSES ON VEHICLE, BRAKE, TAIL, TRUNK, BACK UP AND ALL EMER. LIGHTS, REMOVE LENS FROM LIGHT BAR TO BUFF OUT

SERV TRANS

DEGREASE MOTOR, TEST DRIVE VEHICLE AND RECHECK FOR OIL LEAKS, FOUND OIL PAN BOLT SEEPING, REMOVED BOLT, CLEAN AND APPLY SEALANT TIGHTEN

REMOVE WINDOW MOLDINGS FROM REAR DOORS AND CLEAN WINDOWS AND MOLDINGS, INSTALL MOLDINGS WITH GAP AT TOP

CHECK FRT A/C PRESSURES, RECOVER FREON, REPLACED SUCTION HOSE, VACUUM SYSTEM, CHARGE SYSTEM WITH FREON

ASSIST JEFF WITH OIL LEAK DIAGNOSTIC

VISTA SCREEN #3 BUTTON MISSING, CHECK ON PARTS FOR VISTA SCREEN #3 BUTTON, NO PARTS AVAILABLE, A COMPLETE NEW SCREEN CAN BE ORDERED BUT OLD SCREEN WORKS JUST FINE, THIS BUTTON IS NOT EVEN, CRITICAL TO ITS OPERATION

HIGH IDLE INOP, REPLACE PRESSURE SWITCH, TERMINAL BROKEN OFF

PARK BRAKE INDICATOR LIGHT INOP, CHECK OUT PROBLEM, INDICATOR LIGHT ITSELF NOT WORKING, REPLACE



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

LIGHT, ALSO FOUND NO POWER TO FROM PRESSURE SWITCH, SWITCH NG, REPLACE NOW OK

LOW PRESSURE INDICATOR LIGHT IN INSTRUMENT PANEL INOP, REMOVE INSTRUMENT CLUSTER, REMOVE BACK AND REPLACE BURNT OUT BULB, ALSO FOUND AIR LEAKING FROM AIR GAUGE FITTING, REPLACE WITH NEW FITTING

LOAD SHEDS #3 NODE, FOUND TAHT WITHOUT HIGH IDLE WORKING THAT NODE 3 WAS BEING SHED BECASUE OF INRPROPER VOLTAGE, AFTER HIGH IDEL FIXED THIS PROBLEM WENT AWAY

DOOR ALARM INOP, CHECK OUT PROBLEM WITH ALARM, REMOVE UPPER PANEL AND TEST LIGHT, LIGHT INOP, REPLACE LIGHT ASSEMBLY AND RETEST, NOW LIGH TON ALL THE TIME, FOUND TWO DOOR SWITCHES BAD, REPAIR BOTH AND RETEST NOW OK

ATTEMPT TO ADJ AIR HORNS, COULD NOT ADJ TO SOUND QUALITY, REBUILD BOTH AIR HORNS AND ADJ TO BEST SOUND QUALITY

ASSIST JEFF WITH AIR HORN REPAIR

---

#### Workorder: V45036

In Date: 11/08/2011      Meter Reading: 105,563.80  
Close Date: 11/09/2011

#### Problem?

Air leak.

#### Task performed:

Go to Stn36; air leak in rear air bag on left rear empty; leveling valve rod brkn; come to shop get parts & rep. j

#### Parts

#### Quantity

481-00-225334-751 VALVE HEIGHT CONTROL  
S4334010030LINK - FOR LEVELING VALVE

1  
1

---

#### Workorder: V44359

In Date: 10/13/2011      Meter Reading:  
Close Date: 11/14/2011

#### Problem?

R rear scene light out. Rear lightbar scene light intermittent, may be loose. Sta 39.

#### Task performed:

1. Rep all lights that were out.  
2. Rep rear step that was coming off. j

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V45098

In Date: 11/11/2011

Meter Reading:

Close Date: 11/21/2011

#### Problem?

Engine oil leaks slowly. 2drops over a 1hr period. May be leaking from the oil plug. R39

#### Task performed:

Parts

Quantity

Rep oil leak. j

NO PARTS USED

#### Workorder: V45274

In Date: 11/18/2011

Meter Reading: 106,165.00

Close Date: 11/21/2011

#### Problem?

A inspection.

#### Task performed:

Parts

Quantity

a inspection

NO PARTS USED

check cab a/c for leaks, tighten low side sch--dor valve,  
vaccum down and recharge

modify new squad bench latch, did not have right latch

tighten door latches

#### Workorder: V45142

In Date: 11/14/2011

Meter Reading: 106,109.50

Close Date: 12/05/2011

#### Problem?

Coolant leak

#### Task performed:

Parts

Quantity

REPAIRED COLLENT LEAK AND REPAIRED AIR  
LEAK.

NO PARTS USED

#### Workorder: V46405

In Date: 01/08/2012

Meter Reading: 106,767.80

Close Date: 01/23/2012

#### Problem?

The driver side rear scene light is not working. Sta 32

#### Task performed:

Parts

Quantity

REPAIRED ALL MELTED WIPES IN REAR LIGHT BAR  
AND TESTED.

NO PARTS USED





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V46582

In Date: 01/15/2012

Meter Reading: 107,319.30

Close Date: 01/23/2012

#### Problem?

Driver side headlight on the rescue is loose and sitting at an angle away from the truck, shining in the face of oncoming vehicles. sta 32

#### Task performed:

REPAIRED HEAD LIGHT.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V47076

In Date: 02/03/2012

Meter Reading: 108,502.00

Close Date: 02/06/2012

#### Problem?

A inspection.

#### Task performed:

1. A INSPECTION.
2. DIAGNOSE AND REPLACE REAR MARKER LIGHT AND REPAIR REAR STROBE LIGHT.

#### Parts

ICC5RLLED CLEARANCE LIGHT RED

1

#### Workorder: V47173

In Date: 02/08/2012

Meter Reading: 108,604.00

Close Date: 02/28/2012

#### Problem?

computer diagnostic error message. node 3 output 7 pin h registering sr at 22

#### Task performed:

CHECKED UNIT FOR PROBLEMS COULD NOT DUPLICATE.

#### Parts

6000000003NODE HERCULES V-MUX

1

#### Workorder: V47253

In Date: 02/12/2012

Meter Reading: 108,841.30

Close Date: 02/29/2012

#### Problem?

shore line is not maintaining contact in the plug of the truck, shore line does work, its the trucks connection that its not working. R22

#### Task performed:

REPLACED SHORELINE PLUG.

#### Parts

NO PARTS USED

#### Quantity



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V44822

In Date: 10/31/2011

Meter Reading: 104,889.60

Close Date: 03/09/2012

### Problem?

check and repair transmission r39

### Task performed:

#### Parts

#### Quantity

NO PARTS USED

## Workorder: V47524

In Date: 02/23/2012

Meter Reading: 108,928.70

Close Date: 03/27/2012

### Problem?

A inspection.

### Task performed:

#### Parts

#### Quantity

1. A-INSPECTION.
2. DIAGNOSTIC ERROR NODE 3 PIN H, RIGHT REAR SCENE LIGHT, TROUBLE SHOOT FOUND BAD CONNECTION GOING TO SCENE LIGHT.
3. ADJUST AIR BAGS.
4. PULL DOWN AND RE-CHARGE CAB A/C, REPLACE LOW SIDE SCHRODER VALVE.

68054400K0BEZEL HEADLIGHT

1

H35SN12BULB

1

## Workorder: V48103

In Date: 03/21/2012

Meter Reading: 108,928.70

Close Date: 03/27/2012

### Problem?

replace front tires

### Task performed:

#### Parts

#### Quantity

REPLACE FRONT TIRES.

NO PARTS USED

Vendor? BOULEVARD TIRE CENTE



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V48421

In Date: 04/04/2012

Meter Reading: 109,322.00

Close Date: 04/17/2012

### Problem?

A Inspection action area electrical and o2 panel has fallen and will not stay in place.

### Task performed:

1. A-INSPECTION.
2. R F MARKER IN/OP. REPLACED BULB.
3. O2 PANEL FALLING DOWN. MOVED LATCH CATCH ON RIGHT SIDE TO NEW POSITION. REPLACED LATCH ADJ BOLT TO LONGER ONE AND ADJ LATCHER.
4. LF AND RF VALVE STEM CORES LEAKING. REMOVE CORES TO CLEAN DEBRIS AND REINSTALL. AIR TIRES.
5. ADJUST AIR HORNS.

### Parts

### Quantity

NO PARTS USED

## Workorder: V48900

In Date: 04/25/2012

Meter Reading: 109,322.00

Close Date: 05/01/2012

### Problem?

REPLACE REAR TIRES SR 9

### Task performed:

REPLACE REAR TIRES SR 9

### Parts

### Quantity

NO PARTS USED

Vendor? ELPEX

## Workorder: V49544

In Date: 05/22/2012

Meter Reading: 109,322.00

Close Date: 05/29/2012

### Problem?

park brake won't hold - R18

### Task performed:

TRAVEL TO 18 ADJUST PARKING BRAKE CABLE.  
TEST VEHICLE ON INCLINE (OK) TRAVEL HOME.

### Parts

### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V49634

In Date: 05/25/2012

Meter Reading: 109,539.50

Close Date: 05/31/2012

#### Problem?

rear marker lights,break lights 10-7 r 18

#### Task performed:

TRAVEL TO 18 CHECKED LIGHTS ALL WORKING NO  
PROBLEM FOUND.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V50471

In Date: 06/29/2012

Meter Reading: 110,127.70

Close Date: 07/11/2012

#### Problem?

A INSPECTION SR4

#### Task performed:

1. A INSPECTION
2. REMOVE VISTA SCREEN, TAKE APART AND  
INSTALL NEW PUSH BUTTONS.
3. REPLACE REAR FLUORESCENT LIGHTS.
4. REMOVE SIDE PATIENT COMPARTMENT DOOR  
PANEL AND READJUST LATCH RODS.

#### Parts

0560-0987-00KEY CAPS VISTA 1

322502BULB PATIENT GH22

921LIGHT BULB

1

1

1

#### Workorder: V50673

In Date: 07/07/2012

Meter Reading: 110,416.60

Close Date: 07/13/2012

#### Problem?

Left headlight is out. We have no replacements at the station. R 43

#### Task performed:

REPAIRED SPARE HANDLIGHT THAT WAS OUT.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V50892

In Date: 07/16/2012

Meter Reading: 110,885.00

Close Date: 07/25/2012

#### Problem?

B INSPECTION SR 4

#### Task performed:

B INSPECTION OIL CHANGE SERVICES

#### Parts

NO PARTS USED

#### Quantity

Vendor? OIL CHANGE SERVICED



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V51044

In Date: 07/23/2012

Meter Reading: 110,885.00

Close Date: 07/27/2012

### Problem?

A inspection

### Task performed:

1. A-INSPECTION.
2. CHECK, VACUUM AND RECHARGE A/C.

### Parts

NO PARTS USED

### Quantity

## Workorder: V51118

In Date: 07/25/2012

Meter Reading: 110,885.00

Close Date: 08/08/2012

### Problem?

MAKE REPAIRS FROM B INSPECTION SR 4

### Task performed:

1. VERIFY COMPLAINTS ON B-INSPECTION AND LOOK OVER TRUCK.
2. CLEAR A/C DRAIN TUBE.
3. REMOVE A/C CONTROL PANEL DIAGNOSE BAD CONTROL PANEL AND REPLACE ALSO GREASE BLEND DOOR CABLES.
4. TEST COOLING SYSTEM TAKE ON LONG TEST DRIVE TRUCK NEVER RAN OVER 190.

### Parts

194BULB

ABPN83322930CONTROL HEAD AC/HEAT

IMMF13225BELT SEAT PASS. IMMF11852 OLD #

1

1

1

## Workorder: V51820

In Date: 08/22/2012

Meter Reading:

Close Date: 08/23/2012

### Problem?

Spare Rescue's MDT not connecting to server R37

### Task performed:

ITS WORK REQUEST MADE

### Parts

NO PARTS USED

### Quantity



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V52057**

**In Date:** 08/31/2012

**Meter Reading:** 111,483.80

**Close Date:** 09/12/2012

**Problem?**

A inspection

#### Task performed:

1. A INSP, FILL WASHER FLUID.
2. RATTLE DASH BOARD. TIGHTEN SCREWS. REPLACED STRIPED OUT SCREW WITH LARGER.
3. REAR PATIENT COMPT TRIM LOOSE ON COMPT AND MISSING LOWER TRIM PIECE. SECURE LOOSE TRIM W/ LONGER SCREWS AND ORDER TRIM PIECE.
4. BENCH SEAT LUTCH BROKEN. REMOVED LATCH FOUND PIN PULLED OUT. INSTALLED PINS WELD END OF PIN AND GRIND WELD RE-INSTALL LATCH ( NOTCH IN PARTS.
5. DIAGNOSE LFT STROBE INOP-FOUND BAD STROBE UNIT REPLACE STOPE.
6. DIAGNOSE AIR LEAK- FOUND BAD HORN SOLENOIID REPLACED SOLENOID. REPLACED WEATHER PACK CONNECTOR TESTED.
7. DIAGNOSE CITY HORNS INOP FOUND BAD HORNS REPLACED TEST OK.
8. DIAGNOSE R SROBE INOP-FOUND BAD STROBE UNIT REPLACED SROBE DRILL AND TAP THREADS FOR LENS TEST OK.
9. L-3 HINGE BOLTS STRIPPED OUT. DRILL OUT HOLES AND INSTALL NUT CERTS INSTALL NEW BOLTS AND TIGHTEN.
10. VEHICLE DIRTY INSIDE CLEANED INTERIOR.

#### Parts

#### Quantity

58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E 2  
A0631117000HORN HIGH NEW # 06-52125-039 1  
A0631117003HORN LOW NEW #06-52125-041 1  
HDY-H005700SOLENOID HORN AIR 1

**Workorder: V52330**

**In Date:** 09/12/2012

**Meter Reading:** 111,787.00

**Close Date:** 09/21/2012

**Problem?**

A INSPECTION AND NEEDED REPAIRS

#### Task performed:

1. A INSPECT
2. PULLED ALL 6 TIRES CHK BRAKE BRAKE LOOKS GOOD CHK TIRE AND FILL TO 105PSI AND PUT ALL 6 TIRES ON.
3. R&R WINDOW MOLDINGS.

#### Parts

#### Quantity

6809970086PLUG 2  
A1834388003MOLD R/H 1  
E-600013-3052 NUT 1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V52547

In Date: 09/21/2012

Meter Reading: 111,851.80

Close Date: 09/26/2012

#### Problem?

A INSPECTION AND NEEDED REPAIRS

#### Task performed:

1. A INSPECTION
2. FRT AND REAR PADS REPLACEMENT- SERV CALIPER SLIDES VERY RUSTY AND BINDING UP CALIPER.
3. REAR TIRES AND WHEEL EXTENSIONS-INOP AND KINKED BADLY-INSTALL NEW AIR EXTENSION KITS AND REPAIR SIMULATORS TO FIX WHEELS PROPERLY.

#### Parts

#### Quantity

359-5915359-5915 OIL PLUG

2

AMH-1AMH-1 VALVE EXTENSION

1

E-600013-3052 NUT

1

MK184HDBRAKE PADS

2

#### Workorder: V53490

In Date: 11/02/2012

Meter Reading:

Close Date: 11/14/2012

#### Problem?

Nail in tread of front tire, does not appear like its leaking. Have not removed the nail. R91

#### Task performed:

DRIVER PULLED NAIL NO LABOR.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V54179

In Date: 12/04/2012

Meter Reading: 115,391.00

Close Date: 12/05/2012

#### Problem?

A INSPECTION

#### Task performed:

1. CRANKS- NO START FIRST IN PARKING LOT REPLACE DRAIN VALVE WITH A SHREADER TYPE VALVE SO AIR TANKS CAN BE FILLED TO RELEASE PARKING BRAKE HOOK UP TOW STRAP AND PULL VEHICLE FROM LOT INTO SHOP- DIAGNOSE NO START PROBLEM- REPLACE FUEL LIFT PUMP. ALSO RESEAL FILTER HOUSING, LEAKING FROM THREE DIFFERENT AREAS. BLEED OUT AIR FROM SYSTEM, START AND LET RUN. ROAD TEST WAS OFF OIL RESIDUE AND FUEL FROM WIRING, HOSE ETC.
2. A INSP.
3. REPLACE BURNT OUT CENTER (YELLOW) STROBE IN REAR LT- BAR.
4. CUT AND MAKE UP NEW L/SIDE REAR MUD FLAP

#### Parts

#### Quantity

103385NDRAIN COCK

3

3926759-SDRAIN KIT

1

3963983WASHER SEAL ISB

8

39901054943048 FUEL PUMP ISB

1

684-4 VALVE - FILL AIR TANK

1

B2420LP-SMUD FLAP 24 X 24

1

L1261F33585XE FUEL FILTER WIX

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V55019

In Date: 01/12/2013

Meter Reading:

Close Date: 01/14/2013

#### Problem?

Front cab A/C not working.

#### Task performed:

A/C INOP, CONNECTOR TO CLUTCH LOOSE  
REPAIRED CAB A/C CONNECTOR NEED TO INSTALL  
RESISTOR TO GET HI SPEED FAN WORKING.

#### Parts

#### Quantity

87401RY-30T RELAY 5 PIN 12V

1

### Workorder: V55005

In Date: 01/11/2013

Meter Reading: 115,391.00

Close Date: 01/17/2013

#### Problem?

battery door sensor causing alarm to go off

#### Task performed:

TROUBLESHOOT FOUND SWITCH BROKEN MOUNT  
NEW SWITCH, BUT WAS WRONG, ORDER NEW  
SWITCH.

#### Parts

#### Quantity

03910030SWITCH COMPARTMENT DOORS

3

L PLACARDLARGE SIDE PLACARD

1

### Workorder: V55037

In Date: 01/14/2013

Meter Reading: 115,795.70

Close Date: 01/24/2013

#### Problem?

R300 cab a/c blower inop on high speed

#### Task performed:

TRAVEL TO STATION 30 REMOVED DASH AND  
REWIRED FAN SWITCH.

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V55270

In Date: 01/24/2013

Meter Reading: 116,229.20

Close Date: 01/24/2013

#### Problem?

Front cab a/c inop

#### Task performed:

REPLACED HI SPEED FAN RELAY.

#### Parts

#### Quantity

NO PARTS USED





3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55443**

**In Date:** 01/31/2013

**Meter Reading:**

**Close Date:** 02/01/2013

**Problem?**

Windshield window washer switch not working. Safety Concern. SR @ ST-30

**Task performed:**

TRAVEL TO 30 FOUND SWITCH BAD FOR WIPERS  
TRAVEL TO SHOP FOR PARTS RETURNED TO 30  
AND INSTALLED.

Parts

Quantity

064615900006-46159-001 SWITCH WIPER

1

**Workorder: V55509**

**In Date:** 02/04/2013

**Meter Reading:** 117,086.10

**Close Date:** 02/07/2013

**Problem?**

Wiring manifold in medical compartment over actionary will fall open during transports due to broken securing clip.

**Task performed:**

TRAVEL TO 30 REPAIRED LOOSE LATCH ON  
COMPARTMENT ABOVE ACTION AREA.

Parts

Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V55834**

**In Date:** 02/19/2013

**Close Date:** 03/08/2013

**Meter Reading:** 118,378.80


**Problem?**

C inspection R300

**Task performed:**

Parts

Quantity



**\* ADVANCED LIFE SUPPORT VEHICLE**

- 071601A07-0602A DRIER A/C 7118  
107796DRYER KIT AD9 -NEW  
1501450007750USE 0775145  
322502BULB PATIENT GH22  
60027FAN A/C COND 12IN 860026-2-W  
800405PURGE VALVE KIT  
CA8193AIR FILTER 46744 WIX  
CLR9185209186-1500-20 MARKER LT.AMBER LED  
DOOR 1017 X 35 X 3/16  
HLD3999GSS1715UV 30LB STRUT GAS  
L1261F33585XE FUEL FILTER WIX  
PH8942FILTER OIL 57182 LFP3729  
RKB5513COMPRESSOR A/C 115V R22  
S3225PFUEL FILTER 33630 LFF5849  
SWT54930SWITCH DOOR

[illegible]



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

20. ADJ PARKING BRAKE CABLE.

21. Q &A.

---

## Workorder: V56233

In Date: 03/07/2013

Meter Reading: 118,378.80

Close Date: 03/08/2013

### Problem?

replace plexi glass

### Task performed:

INSTALL PLEXI-GLASS. DRILL HOLES FOR  
MOUNTING SCREWS.

### Parts

NO PARTS USED

### Quantity

---

## Workorder: V46626

In Date: 01/17/2012

Meter Reading: 107,319.30

Close Date: 04/08/2013

### Problem?

Low oil level, officer side air horn not working, truck computer reading diagnostic error node 3. SR AT32

### Task performed:

1. REAR SCENE LIGHT OUT REPLACED.
2. ADJUSTED AIR HORN AND TESTED.

### Parts

NO PARTS USED

### Quantity

---

## Workorder: V55779

In Date: 02/14/2013

Meter Reading: 117,876.50

Close Date: 04/09/2013

### Problem?

mount fire extinguisher and misc equipment. R-300

### Task performed:

1. INSTALLED TOOL HOLDERS FOR CUTTERS  
HALIGAN TOOL BOLT CUTTERS AND HOOKS FOR  
GEAR. STILL NEED TO REPLACE EXTINGUISHER  
BRACKETS.
2. TRAVEL TO 30 MOUNTED SOME EQUIPMENT.  
NEEDED MORE BRACKETS WILL INSTALL.
3. FINISHED MOUNTING EQUIPMENT.

### Parts

5269LPVM-5 SM MOUNT

CYBS27299011 STRAP 36IN

6

3



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V56600

In Date: 03/23/2013

Close Date: 04/09/2013

Meter Reading: 119,429.80

#### Problem?

A-inspection

#### Task performed:

A-INSPECTION.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V55441

In Date: 01/31/2013

Close Date: 04/11/2013

Meter Reading:

#### Problem?

Problem with cab radio handset not cueing properly and wire exposed.

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V56702

In Date: 03/28/2013

Close Date: 04/16/2013

Meter Reading: 119,429.80

#### Problem?

WHEN AC UNIT IS ON IN ANY ON POSITION, IT'S BLOWING FROM HOT TO COLD BACK TO HOT IN THE FRONT CAB UNIT  
THIS TRUCK IS ONE OF THE SHOP SPARES THAT WE ARE USING DUE TO OUR TRUCK BEING IN THE SHOP. SR@93? r  
be getting picked up today and coming back to shop

#### Task performed:

UNABLE TO DUPLICATE COMPLAINT - BLOWER FAN  
ONLY OP ON LIGHT CHECK SYSTEM REPLACE  
RESISTER BLOCK NO CHANGE, CONTROLE PANEL  
OP. GOOD, WIRING PROPERLY INSTALLED,  
BLOWING COLD ON HIGH.

#### Parts

#### Quantity

ABPN83321070RESISTOR BLOWER

1

#### Workorder: V57908

In Date: 05/22/2013

Close Date: 05/30/2013

Meter Reading: 120,840.90

#### Problem?

LRO flat

#### Task performed:

#### Parts

#### Quantity

NO PARTS USED

Vendor? BOULEVARD TIRE



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V58546

In Date: 06/19/2013

Meter Reading: 120,840.90

Close Date: 06/24/2013

#### Problem?

Quality check

#### Task performed:

#### Parts

#### Quantity

QA, A-SERVICE CHECK OVER OK NEEDED DOME  
LIGHT REPAIR READY TO GO.

NO PARTS USED

#### Workorder: V59430

In Date: 07/30/2013

Meter Reading: 123,536.50

Close Date: 07/31/2013

#### Problem?

stretcher lock inop

#### Task performed:

#### Parts

#### Quantity

TRAVEL TO STATION 14 REPLACED STRETCHER  
LATCH.

090-0278STRECHER BAR NEW

1

#### Workorder: V59462

In Date: 07/31/2013

Meter Reading: 123,536.50

Close Date: 08/02/2013

#### Problem?

tranny dipstick missing r14

#### Task performed:

#### Parts

#### Quantity

TRAVEL TO 14 REPLACED BROKEN DIP STICK IN  
TRANS. HAD TO FISH OLD UNIT OUT FIRST.

07-14488-000DIPSTICK

1

#### Workorder: V59411

In Date: 07/29/2013

Meter Reading: 123,456.00

Close Date: 08/12/2013

#### Problem?

r41 rear a/c inop

#### Task performed:

#### Parts

#### Quantity

1. CLEAN REAR CONDENSER FANS AND TESTED.  
2. REPAIRED 110 A/C PLUG THAT WAS MELTED  
AND SHORTED OUT.

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V60490**

**In Date:** 09/13/2013

**Meter Reading:** 124,505.00

**Close Date:** 09/20/2013

**Problem?**

A-inspection

**Task performed:**

1. A-INSPECTION; TOP OFF ENGINE OIL; WINDSHIELD FLUID.
2. REAR LIGHT BAR MARKER LIGHT INOP - FOUND LED ASSEMBLY BLOWN - REMOVE HARDWARE REPLACEMENT LED ASSEMBLY.
3. GRILL MOUNT UNIT # HOLDER FALLING OFF - REMOVE CLEAN SURFACE APPLY NEW STRIP OF 2 SIDED TAPE AND MOUNT TO GRILL.
4. L/SIDE HEADLIGHT BEZEL FALLING OUT RETAINING PLUG MISSING INSTALL NEW RETAINING PLUG AND SECURE BEZEL.
5. PASS. WINDOW MOLDING BROKEN - REMOVE AND INSTALL NEW WINDOW MOLDING.
6. FRONT TIRES, NAIL AND WORN - ACQUIRE TO PREUSED TIRE FROM BLDG 3 INSTALL AND ROAD TEST.
7. A/C FAN INOP ON LOW AND MED - CHECK AND FOUND RESISTER LOW AND MED INOP REMOVE AND INSTALL NEW REOSTAT OPERATE NOW NO MEDIUM REMOVE CONTROLE SWITCH AND INSTALL NEW SWITCH FAULD CONTINUE. ADVISED TO PUT IN SERVICE BY FOREMAN S. REINES.

**Parts**

**Quantity**

11-06131229 RESISTER BLOWER	1
A1834388003MOLD R/H	1
ABPN8332229011-3050 SWITCH BLOWER	1
FAS212180402FAS21218040215 GROMET	1

**Workorder: V60787**

**In Date:** 09/25/2013

**Meter Reading:**

**Close Date:** 10/11/2013

**Problem?**

vibration when driving starts at 25mph . possible passenger side front shock blown. the shock is black on the lower half . ST30

**Task performed:**

1. TRAVEL TO STA 30 DRIVER COMPLAINT VIBRATION AT 45 AND 55 CHECKED FT TIRES OK. RF SHOCK 10-7 WILL REPLACE SHOCKS.
2. TRAVEL TO 30 REPLACED FT SHACKS.

**Parts**

**Quantity**

SA66613SHOCK FRONT RESC	2
-------------------------	---



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V61384

In Date: 10/19/2013

Meter Reading: 126,860.10

Close Date: 10/23/2013

#### Problem?

Driver side patient compartment front scene light out R300

#### Task performed:

DRIVER COMPLAINT SCENE LIGHT OUT REPLACED  
BULB IN SCENE LIGHT.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V61426

In Date: 10/21/2013

Meter Reading: 126,860.10

Close Date: 10/23/2013

#### Problem?

A/C inop

#### Task performed:

DRIVER COMPLAINT NO A/C FRONT OR REAR  
DIAGNOSE TRUCK FOUND REAR A/C CONDENSER  
CLOGGED CLEANED OUT WITH HOSE AND TESTED  
OK FRONT A/C NOT BLOWING CHECKED BLOWER  
SWITCH OK CHECKED FUSES AND RELAYS OK  
BLOWER MOTOR 10-7 RECEIVED UNIT FROM SHOP  
AND INSTALLED TESTED OK.

#### Parts

ABPN8330101701-0604 3924 BLOWER A/C BOA 85205000C

1

#### Workorder: V62616

In Date: 12/10/2013

Meter Reading: 127,699.50

Close Date: 12/16/2013

#### Problem?

Check over truck back from cummins.

#### Task performed:

1. C/O TRUCK FOUND DRAW ON FLOOR REAR  
DOOR LATCH INOP INNER WINDOW FRAMES LOOSE  
ALL DOOR LATCHES LOOSE, RESECURE WINDOW  
FAMES.
2. INSTALL NEW SLIDES, ADJUST SHARPESS  
DRAW.
3. INSTALL NEW DOOR LATCHES ON R/R LOWER  
L/R UPPER ADJUST RODS, REPLACE BAD  
NUTSERTS.

#### Parts

5632-1010 IN DRAWER SLIDES PR

2

LTC594211657-16 LATCH L/H MEDIC MASTER

1





3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V61773**

**In Date:** 11/04/2013

**Close Date:** 01/02/2014

**Meter Reading:** 127,699.50

**Problem?**

B inspection

#### Task performed:

1. B INSP.
2. BATTERIES- BATT HOLD DOWN BRACKET BROKEN- MAKE ALL NEW HOLD DOWN CLAMPS AND MODIFY BRACKET.
3. CHK FOR ROUGH RIDE 40 MPH- TEST DROVE OK
4. CHK A/C BLOWER FOUND BLOWER WORKS ON HIGH SPEED ONLY- REMOVED DASH PANEL.
5. CHK A/C BLOWER CONT- R&R BLOWER SWITCH- R&R BLOWER RESISTER- FOUND WIRING BAD- TROUBLESHOOT WIRING- REPAIRED AND REWIRE BLOWER CIRCUIT.
6. CHK A/C BLOWER CONT- R&R TERMINALS AT SW- REPLACED MISSING DASH SCREWS REASSEMBLE ALL PARTS CHK OK.
7. CHK WASTE DRAW- CHK OK- L-TURN OK CHK OIL LEAK CHK OK R&R WIPERS.
8. CHK BATT SLIDES- CLEANED AND LUBED SLIDES- CHK OK.
9. SERV- P/S DRAINED FLUID- R&R FILTER- R&R FLUID RAN ND CHK O.K.
10. REPLACE ALL BRAKE PADS- PUT TRUCK ON JACK STANDS.
11. REPLACE ALL BRAKES- REMOVED FRT WHEELS AND CALIPERS- R&R FRONT BRAKE PADS- REMOVED REAR WHEEL AND CALIPERS R&R REAR BRAKE PADS- TEST DROVE CHK OK.
12. Q.A INSPECTION- CHK OK.

#### Parts

#### Quantity

435 VALVE CAP	10
52-24WIPER BLADES ANCO 24	2
ABPN83321070RESISTOR BLOWER	1
ABPN8332229011-3050 SWITCH BLOWER	1
FG87904MFG3937557S FILTER P/S NEW STYLE	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1

**Workorder: V63263**

**In Date:** 01/09/2014

**Close Date:** 01/13/2014

**Meter Reading:**

**Problem?**

comp. 7 warning light shows door is ajar

#### Task performed:

CHECK ALL DOORS FOR ALARM OPERATION  
FOUND REAR BUMPER COMPARTMENT DOOR  
SENSOR SHORT OUT MAKING SYSTEM FAULTY AS  
#7 DOOR OPEN CUT AWAY SENSOR FOR DOOR  
BUMPER REPAIR CONNECTION ON DRIVER DOOR  
SENSOR TEST FOR OPERATION IS GOOD.

#### Parts

#### Quantity

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

## Workorder: V63347

In Date: 01/13/2014

Meter Reading: 128,118.90

Close Date: 01/15/2014

### Problem?

no rear a/c

### Task performed:

Parts

Quantity

REPAIR UNIT, CHECK FOUND A/C LOW ON REAR  
AND REPAIR FRONT A/C ALSO, HEATER VALVE ON  
MAKING HOT AIR.

NO PARTS USED

## Workorder: V64354

In Date: 02/19/2014

Meter Reading: 128,450.00

Close Date: 02/21/2014

### Problem?

Flat Repair Boluward

### Task performed:

Parts

Quantity

FLAT REPAIR BOULEVARD.

NO PARTS USED

Vendor? BOULEVARD TIRE

## Workorder: V64446

In Date: 02/21/2014

Meter Reading: 128,450.00

Close Date: 02/26/2014

### Problem?

A inspection

### Task performed:

Parts

Quantity

1. A INSP.
2. MIX AND FILL WASHER RESEVOIR.

NO PARTS USED

## Workorder: V64228

In Date: 02/14/2014

Meter Reading: 128,450.00

Close Date: 03/03/2014

### Problem?

Trake shakes at 60mph

### Task performed:

Parts

Quantity

TEST DRIVE TRUCK, REMOVE FRONT WHEELS,  
INSTALL NEW WHEELS ON FRONT. TEST DROVE  
OK.

NO PARTS USED



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V62376

In Date: 12/01/2013

Meter Reading:

Close Date: 03/21/2014

#### Problem?

check engine light on

#### Task performed:

DONE ON ANOTHER WORK ORDER.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V64719

In Date: 03/05/2014

Meter Reading:

Close Date: 03/28/2014

#### Problem?

R411 spare. Leaking alot of oil. Adding oil as needed.

#### Task performed:

CLEANED ALL OIL FROM BOOTOM OF TRUCK,  
CHECKED FOR LEAKS FOUND REAR MAIN OIL SEAL  
LEAKING SWAPED OUT TRUCK.

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V66270

In Date: 05/06/2014

Meter Reading: 128,887.90

Close Date: 05/13/2014

#### Problem?

QA rescue and check a/c, lights and tires

#### Task performed:

R&R HEAD LIGHT.

#### Parts

H6054USE CV TYPE SEALED BEAM

#### Quantity

1

#### Workorder: V66865

In Date: 05/30/2014

Meter Reading: 130,269.90

Close Date: 06/16/2014

#### Problem?

A inspection

#### Task performed:

- 1) perform A service.
- 2) replaced wiper blades.

#### Parts

52-24WIPER BLADES ANCO 24

#### Quantity

2



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V67349

In Date: 06/20/2014

Meter Reading: 130,576.30

Close Date: 07/07/2014

#### Problem?

A inspection

#### Task performed:

1. A - INSP AND AIR BAGS.
2. TRANNY OIL LEAKS.

#### Parts

16-15762-00016-19471-000 AIR BAG

#### Quantity

2

#### Workorder: V65942

In Date: 04/24/2014

Meter Reading: 128,887.90

Close Date: 07/08/2014

#### Problem?

repair oil leak

#### Task performed:

CK, OUT AT SHOP AT TIME OF SERVICE AND  
REPAIRED AT THAT TIME TICKET V67349

#### Parts

NO PARTS USED

#### Quantity

#### Workorder: V68846

In Date: 08/21/2014

Meter Reading: 132,147.70

Close Date: 10/15/2014

#### Problem?

B inspection SR4 by OCS

#### Task performed:

B inspection

#### Parts

L1261F33585XE FUEL FILTER WIX

PH8942FILTER OIL 57182 LFP3729

S3225PFUEL FILTER 33630 LFF5849

#### Quantity

1

1

1

Vendor? OCS

#### Workorder: V71855

In Date: 12/24/2014

Meter Reading: 160,106.30

Close Date: 01/07/2015

#### Problem?

Vehicle has weak batteries and need new ones. Must use charger to start vehicle even with being plugged in. Vehicle is also running high engine temperature when running.

#### Task performed:

Replaced batteries in ebola unit

#### Parts

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER

HP-31DBATTERY 950CCA HP-31D

#### Quantity

4

4



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

### 10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

#### Workorder: V72171

In Date: 01/09/2015

Meter Reading: 132,388.00

Close Date: 01/20/2015

#### Problem?

A inspection SR4

#### Task performed:

1. A Inspection.
2. Compartment infested with ants. Spray compartment with CR-2 roach and ant killer spray.
3. Windshield washer reservoir compartment latch missing. Install new latch and adjust locking mechanism
4. L-2 compartment extinguisher bracket mount loose. Remove to retap strip out screw holes. Remount and secure bracket mounts.
5. Spot light rotates but light not on. Remove assembly cover. Found loose connection to bulb. Secure connection and reassemble.
6. Air horn out of tune. Adjust air horn tone.

#### Parts

#### Quantity

HA49102C2-32-15 LATCH NON LOCKING

1

#### Workorder: V72914

In Date: 02/05/2015

Meter Reading:

Close Date: 02/13/2015

#### Problem?

While transporting patient, modular power to patient compartment was turning on and off on its own. There is also water pooling underneath the Officer's front seat.

#### Task performed:

Travel to ST 39. Check out mod power going off in rear of truck. Check out system nodes, Vista, wiring, etc. Test drive unit. No problem found/repared. Water leak on w/o #72900 possible short from water leaking on fuse panel from a/c drain.

#### Parts

#### Quantity

NO PARTS USED

#### Workorder: V72900

In Date: 02/05/2015

Meter Reading:

Close Date: 02/20/2015

#### Problem?

Reverse lights and back up alarm will not shut off. Remains on while driving and in park. Shop notified. R39

#### Task performed:

1. Travel to ST 39. Check out back-up alarm and lights stuck on. Check out nodes 15 ct. Found power from back-up lights switch on. Check cab fuse panel. Found water leaking on fuse panel shorting out relays. Pull a/c drain lines off and clear out lines. Blow out lines. Test. Clean out relays and fuse panel on truck. Test ok 2/5/15
2. Road tested and found no problem at this time 2/12/15.

#### Parts

#### Quantity

01-0285809-00C REFURB ONLY POWER SUPPLY KKKEPS

1

02038332800REFLECTOR

1

31-1631-16 WIPER BLADES

2



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

\* **ADVANCED LIFE SUPPORT VEHICLE**

### Workorder: V73257

In Date: 02/18/2015

Meter Reading:

Close Date: 03/09/2015

#### Problem?

While transporting patient, modular power to patient compartment was turning on and off on its own. There is also water pooling underneath the Officer's front seat.

#### Task performed:

Travel to ST 39. Check out mod power going off in rear of truck. Check out system nodes, Vista, wiring, etc. Test drive unit. No problem found/repared. Water leak on w/o #72900 possible short from water leaking on fuse panel from a/c drain.

1. REMOVED THRESHOLDS ON OFFICER DOOR ALONG WITH TRIM & FLOOR MAT. FOUND A/C DRAIN CLOGGED.

CLEANED AREA & REASSEMBLED

#### Parts

#### Quantity

NO PARTS USED

### Workorder: V72824

In Date: 02/02/2015

Meter Reading:

Close Date: 03/17/2015

#### Problem?

Driver's SIDE rear strobe out. Both rear corner strobes on rear light bar out. R39

#### Task performed:

1. Installed new strobe pack and tested.

#### Parts

#### Quantity

1876108C922511369C91 FUEL PUMP LOW PRESS

1

### Workorder: V73292

In Date: 02/20/2015

Meter Reading:

Close Date: 04/23/2015

#### Problem?

Pt compartment has section of wall falling down. Air horns do not work. Passenger door opens on it's own while vehicle is in motic SR@57

#### Task performed:

1. PASSENGER DOOR STRICKER AND NADER PIN ADJUST. CHECKED OK LUBED TESTED OK

2. ADJUST AIR HORNS-CHECKED OK

3. FABRICATED NEW BRACKETS FOR ACTION WALL INSTALLED TO SUPPORT WALL

4. Readjusted pass side door. Tested door several times and tested ok.

5. Repaired air horns and tested.

#### Parts

#### Quantity

01-0285809-00C REFURB ONLY POWER SUPPLY KKKEPS

1

RSR03ZCRLIGHT LED RED TIR3 SERIES

1



3/8/2019

# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

10142532

**\* ADVANCED LIFE SUPPORT VEHICLE**

**Workorder: V73939**

**In Date:** 03/17/2015

**Close Date:** 04/24/2015

**Meter Reading:** 133,557.40

**Problem?**

CAB & PAT A/C INOP

**Task performed:**

1. Drive to central shop swap out R45.

Parts

Quantity

NO PARTS USED



# Palm Beach County Fire Rescue

## Fleet Maintenance Asset History

Asset: (10142532) 2002 - AMERICAN LAFRAN FL60 Advanced Life Support Vehicle

10142532

### CSHOP-2015-1683

Comments: UNIT OVERHEATING, SPARE THAT R230 IS USING

Date Opened 7-10-2015

Date Finished 7-13-2015

Meter 1 Reading: 134,000

#### TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

### CSHOP-2015-1888

Comments: OIL LEAK AND OVERHEATING

Date Opened 7-21-2015

Date Finished 7-22-2015

Meter 1 Reading: 135,981

#### TASKS PERFORMED

NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? CUMMINS POWER SOUTH LLC

### CSHOP-2015-2303

Comments: B INSPECTION BY OCS

Date Opened 8-13-2015

Date Finished 8-18-2015

Meter 1 Reading: 135,990

#### TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1	PLUG; WASHER DRAIN PLUG
1	FILTER; FILTER OIL 57182 LFP3729
1	PLUG; OIL DRAIN PLUG CUMMINS
1	FILTER; 33585XE FUEL FILTER WIX
1	FILTER; FUEL FILTER 33630 LFF5849

VENDOR? OIL CHANGE SERVICES

### CSHOP-2015-2332

Comments: REPAIRS FROM B INSPECTION AND QUALITY CHECK

Date Opened 8-14-2015

Date Finished 8-18-2015

Meter 1 Reading: 135,990

#### TASKS PERFORMED

Q PARTS

DOMES LIGHTS  
TURN SIGNAL LIGHTS  
LIGHTING SYSTEM  
ABS COMPUTER CONTROLS  
DOOR PANEL  
SEAT FRONT  
QUALITY CHECK-REPAIRS  
AIR CONDITIONING

1	LIGHT; CLEAR UTILITY LED
2	FLOR LIGHT
1	REFLECTOR; REFLECTOR RED 40132 GROTE
1	BULB; BULB
1	SENSOR; ABS SENSOR FRONT OLD # S4410328130
1	SHOCK; 11 IN HOLD-OPEN 30LB
2	VENT; VENT A/C LH
1	VENT; VENT A/C RH



**Asset Work Order History 10142532**

**CSHOP-2015-3519**

Comments: **R19 CHECK ENGINE LIGHT**

Date Opened 10-20-2015 Date Finished 10-22-2015 Meter 1 Reading: 136,348

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
ENGINE AND ACCESSORIES

**CSHOP-2015-3662**

Comments: **SR @ ST18**

Date Opened 10-29-2015 Date Finished 10-29-2015 Meter 1 Reading: 136,348

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
SEAT FRONT

**Service Requests:**

10/29/2015 SERVICE REQUEST / 12: BROKEN / REPAIR  
MIC CABLE BROKEN AND WONT STAY PLUGGED INTO TRUCK RADIO

10/29/2015 SEATS / 12: BROKEN / REPAIR  
DRIVER SEAT BECOMES UNLOCKED AND MOVES FREELY WHILE DRIVING.

10/29/2015 SEATS / 12: BROKEN / REPAIR  
OFFICER SEAT IN BROKEN AND LEANS TO THE RIGHT TOWARDS THE DOOR.

**CSHOP-2015-3858**

Comments: **SPARE RESCUE @ ST18 OVERHEATING**

Date Opened 11-9-2015 Date Finished 11-9-2015 Meter 1 Reading: 137,113

**TASKS PERFORMED**

**Q PARTS**

SERPENTINE BELT

1 BELT; BELT

**CSHOP-2015-3880**

Comments: **SR @ ST18**

Date Opened 11-10-2015 Date Finished 11-16-2015 Meter 1 Reading: 137,370

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM

**Service Requests:**

11/10/2015 ENGINE / 12: BROKEN / REPAIR  
THERMOSTAT KEEPS GOING ABOVE 250 DEG AND COMING BACK SOWN TO 180 DEG MORE THAN THE LAST TIME THIS INCIDENT WAS REPORTED IE THIS PROBLEM IS HAPPENING MORE FREQUENTLY THAN NOT (WHILE SITTING AT LIGHTS & EXTENDED STAYS ON CALLS)

## Asset Work Order History 10142532

### CSHOP-2015-3954

Comments: **R18 FAULT CODE**

Date Opened 11-13-2015 Date Finished 11-16-2015 Meter 1 Reading: 137,370

#### TASKS PERFORMED

#### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
ELECTRICAL  
TRANSMISSION

#### **Service Requests:**

11/13/2015 ALARMS / 12: BROKEN / REPAIR  
DIAGNOSIS CODE N3PH

### CSHOP-2015-4118

Comments: **PARK BRAKE INOP @ST18**

Date Opened 11-23-2015 Date Finished 12-21-2015 Meter 1 Reading: 137,444

#### TASKS PERFORMED

#### Q PARTS

PARK BRAKE  
AIR BAG SYSTEM  
AIR HORN  
HOOD

2 BRAKE; 16-19471-000 AIR BAG  
1 BRAKE; CABLE PARKIN BRAKE ORS-15796705  
1 NEWPART; BRAKE ASSBLY  
1 SEAL; SEAL-TRANS. REAR  
2 HORN; KIT-AIR HORN-GROVER  
1 SOLENOID; SOLENOID HORN AIR  
2 CABLE; HOOD CABLE

### CSHOP-2015-4171

Comments: **REPAIR TRANS SEAL LEAKING**

Date Opened 11-25-2015 Date Finished 12-10-2015 Meter 1 Reading: 137,444

#### TASKS PERFORMED

#### NO PARTS USED

TRANSMISSION

### CSHOP-2015-4629

Date Opened 12-23-2015 Date Finished 1-14-2016 Meter 1 Reading: 137,889

#### TASKS PERFORMED

#### Q PARTS

COOLING SYSTEM

1 RELAY; 23-11276-041 RELAY VF28-35F14-Z05

## Asset Work Order History 10142532

### CSHOP-2015-4644

Comments: @41

Date Opened 12-28-2015 Date Finished 12-31-2015 Meter 1 Reading: 137,885

#### TASKS PERFORMED

#### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
QUARTZ LIGHT

#### Service Requests:

12/25/2015 LIGHTS / 10: BENT / ADJUST  
REAR PASSENGER SCENE LIGHT IS OUT.

12/25/2015 ALARMS / 10: BENT / ADJUST  
ERROR MESSAGE. DIAGNOSTIC ERROR ON NODE 3 PIN H

### CSHOP-2015-701

Comments: R244 CHECK ENGINE AND STOP ENGINE LIGHT

Date Opened 5-18-2015 Date Finished 5-22-2015 Meter 1 Reading: 133,975

#### TASKS PERFORMED

#### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
COOLING SYSTEM  
FAULT CODE

### CSHOP-2015-951

Comments: A-INSPECTION

Date Opened 6-2-2015 Date Finished 6-16-2015 Meter 1 Reading: 133,990

#### TASKS PERFORMED

A INSPECTION  
LIGHTING SYSTEM  
DOOR HANDLES INSIDE-OUTSIDE  
A/C LOW FREON

#### Q PARTS

2 REFLECTOR; STROBE LINEAR REFLECTOR 6ELTUBE  
1 HANDLE; HANDLE DOOR  
1 FAN; FAN A/C COND 12IN 860026-2-W  
1 FAN; 8 IN FAN COMPRESSOR HOSELINE  
1 SWITCH; 11-2630 SWITCH BINARY

### CSHOP-2016-1140

Comments: BRAKE LIGHTS INOP SR @39

Date Opened 3-9-2016 Date Finished 3-11-2016 Meter 1 Reading: 137,889

#### TASKS PERFORMED

LIGHTING SYSTEM

#### Q PARTS

1 SWITCH; SWITCH STOPLIGHT  
2 BULB; BULB STOP/TAIL LIGHT

## Asset Work Order History 10142532

### CSHOP-2016-1187

Comments: **ON-CALL R39 EMER LIGHTS OUT**

Date Opened 3-12-2016 Date Finished 3-15-2016 Meter 1 Reading: 138,435

#### TASKS PERFORMED

#### Q PARTS

STROBE LIGHTS

3 TUBE; TUBE - STROBE

#### **Service Requests:**

03/12/2016 LIGHTS / 12: BROKEN / INSPECT  
STATION 39 - BOTH GRILLE STROBES OUT, RIGHT FRONT FENDER STROBE OUT, BOTH REAR LOWER STROBES OUT.  
POSSIBLY BAD STROBE POWER SUPPLY.

### CSHOP-2016-1311

Comments: **SOME EMERGENCY LIGHTS INOP SR39**

Date Opened 3-18-2016 Date Finished 3-21-2016 Meter 1 Reading: 138,987

#### TASKS PERFORMED

#### Q PARTS

LIGHTING SYSTEM

1 ALTERNATOR; 320 UPGRADE ALTERNATOR  
1 PULLEY; PULLEY  
3 POWER SUPPLY; POWER SUPPLY KKKEPS

### CSHOP-2016-1328

Comments: **A INSPECTION**

Date Opened 3-21-2016 Date Finished 4-14-2016 Meter 1 Reading: 139,365

#### TASKS PERFORMED

#### Q PARTS

A INSPECTION  
SPOTLIGHT MOUNTING EQUIPMENT  
SIDE COMPARTMENT BODY  
HOSE UPPER  
REPAIR FROM PM - PATIENT COMPT  
PARK-CLEARANCE LIGHTS  
BELT  
FLUID  
AIR SYSTEM  
SAFTEY-EMERGENCY EQUIPMENT  
DOOR  
AIR CONDITIONING

1 FLUID; SYN OIL BULK QTS  
1 FLUID; ALLISON TRANS FLUID GAL  
1 LIGHT; LED CLEARANCE LIGHT RED  
1 HORN; HORN HIGH NEW # 06-52125-039  
1 HORN; HORN LOW NEW #06-52125-041  
1 RELAY; RY48 RELAY  
2 CAP; 16-3158 R12 CAP 1/4

#### **Service Requests:**

03/20/2016 A/C / 18: LEAKING / REPAIR  
SHORELINE A/C NOT WORKING. BLOWS HOT AIR.

## Asset Work Order History 10142532

### CSHOP-2016-1923

Date Opened 4-22-2016 Date Finished 4-26-2016 Meter 1 Reading: 139,646

REAR AC INOP.

#### TASKS PERFORMED

#### Q PARTS

ENGINE COOLANT TEMPERATURE SE  
SAFETY-EMERGENCY EQUIPMENT  
QUALITY CHECK-REPAIRS

2 WIPER; WIPER BLADE

---

### CSHOP-2016-2572

Comments: A INSPECTION SR4

Date Opened 5-27-2016 Date Finished 6-1-2016 Meter 1 Reading: 139,855

#### TASKS PERFORMED

#### Q PARTS

A INSPECTION  
STORAGE CABINET EMERGENCY VEH  
PARK-CLEARANCE LIGHTS  
HOSES-LINES & FITTINGS

1 SLIDE; 10 IN DRAWER SLIDES PR

---

### CSHOP-2016-2919

Comments: R-15 HEADLIGHT OUT

Date Opened 6-17-2016 Date Finished 6-21-2016 Meter 1 Reading: 139,976

#### TASKS PERFORMED

#### Q PARTS

HEADLIGHTS LOW BEAM

1 LIGHT; HEADLIGHT EXTRA BRIGHT

---

### CSHOP-2016-4017

Comments: C INSPECTION BY H2

Date Opened 8-16-2016 Date Finished 8-17-2016 Meter 1 Reading: 141,323

#### TASKS PERFORMED

#### Q PARTS

PM SERVICE C RESCUE

1 FILTER; FILTER OIL 57182 LFP3729  
1 FILTER; 33585XE FUEL FILTER WIX  
1 FILTER; FUEL FILTER 33630 LFF5849

---

### CSHOP-2016-4087

Comments: REPAIRS FROM PM

Date Opened 8-18-2016 Date Finished 8-18-2016 Meter 1 Reading: 141,323

#### TASKS PERFORMED

#### Q PARTS

A INSPECTION  
CHARGING SYSTEM  
AIR SYSTEM  
STROBE LIGHTS

1 POWER SUPPLY; POWER SUPPLY KKKEPS

---

**Asset Work Order History 10142532**

**CSHOP-2016-4434**

Comments: **ON-CALL SR4**

Date Opened 9-12-2016

Date Finished 9-13-2016

Meter 1 Reading: 142,193

**TASKS PERFORMED**

**Q PARTS**

AIR SYSTEM

2 SWITCH; 76072-15-DC SWITCH SW76072

**Service Requests:**

09/10/2016

AIR RIDE / 18: LEAKING / REPAIR  
AIR RIDE ISSUE. MASSIVE AIR LEAK

**CSHOP-2016-531**

Comments: **MED DRAWER ISSUE**

Date Opened 2-2-2016

Date Finished 2-2-2016

Meter 1 Reading: 138,020

**TASKS PERFORMED**

**Q PARTS**

DOOR LOCKS

1 SLIDE; HT4932-16 DRAWER SLIDE 16  
1 LATCH; M1-63-8 LATCH STAINLESS

**CSHOP-2016-536**

Comments: **SR-4 CUMMINS WORK**

Date Opened 2-3-2016

Date Finished 2-4-2016

Meter 1 Reading: 137,889

**TASKS PERFORMED**

**NO PARTS USED**

OIL

**VENDOR?** CUMMINS POWER SOUTH LLC

**CSHOP-2017-1074**

Date Opened 2-21-2017

Date Finished 2-28-2017

Meter 1 Reading: 143,050

**TASKS PERFORMED**

**Q PARTS**

BATTERY

4 1AD; BATTERY 31 SERIES

**CSHOP-2017-1719**

Date Opened 3-20-2017

Date Finished 4-25-2017

Meter 1 Reading: 146,874

**TASKS PERFORMED**

**Q PARTS**

PARK BRAKE

1 KNOB; KN20901 KNOB PARKING BRAK

## Asset Work Order History 10142532

### CSHOP-2017-1914

Date Opened 3-31-2017 Date Finished 4-27-2017 Meter 1 Reading: 146,874

#### TASKS PERFORMED

#### NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
REPAIR FROM PM - PARKING BRAKE

#### Service Requests:

03/31/2017 BRAKES / 18: LEAKING / REPAIR  
BRAKE ISSUES AIR BRAKES TAKE A WHILE TO RELEASE AFTER TRUCK SITS

### CSHOP-2017-1935

Date Opened 4-3-2017 Date Finished 4-5-2017 Meter 1 Reading: 145,829

#### TASKS PERFORMED

#### NO PARTS USED

BRAKE LIGHTS

#### Service Requests:

04/02/2017 LIGHTS / 23: NOT CONNECTED / REPAIR  
VEHICLE LIGHTS NOT WORKING, BRAKE LIGHTS NOT WORKING WHEN BRAKE PEDAL IS PRESSED

### CSHOP-2017-2057

Comments: **ON-CAL R230**

Date Opened 4-8-2017 Date Finished 4-10-2017 Meter 1 Reading: 146,195

#### TASKS PERFORMED

#### NO PARTS USED

STROBE LIGHTS

### CSHOP-2017-2059

Comments: **CK FOR NO BRAKE LIGHTS**

Date Opened 4-9-2017 Date Finished 4-20-2017 Meter 1 Reading: 146,874

#### TASKS PERFORMED

#### Q PARTS

BRAKE LIGHTS

1 FUSE; FUSE 20AMP  
1 RELAY; RELAY

**Asset Work Order History 10142532**

**CSHOP-2017-2096**

Date Opened 4-10-2017 Date Finished 4-27-2017 Meter 1 Reading: 146,910

**TASKS PERFORMED**

**Q PARTS**

QUALITY CHECK-REPAIRS  
A INSPECTION  
LIGHTING SYSTEM  
SUSPENSION  
MUD FLAP

1 LIGHT; 9186-1500-20 MARKER LT.AMBER LED  
1 LIGHT; 4 IN LIGHT  
2 TWD; AIR SPG  
1 FLAP; MUD FLAP 24 X 24

**Service Requests:**

04/10/2017 WINDOW / 12: BROKEN / REPAIR  
FRONT PASSENGER SIDE WIDOW OFF THE TRACK AND WON'T ROLL DOWN

**CSHOP-2017-2105**

Comments: **ROAD CALL STROBE LIGHTS ON BOX OUT**

Date Opened 4-10-2017 Date Finished 4-25-2017 Meter 1 Reading: 146,874

**TASKS PERFORMED**

**Q PARTS**

LIGHTING SYSTEM

2 9IP; DOME LIGHT BULBS  
1 9IP; POWER SUPPLY KKKEPS

**CSHOP-2017-2127**

Date Opened 4-12-2017 Date Finished 4-17-2017 Meter 1 Reading: 146,684

**TASKS PERFORMED**

**NO PARTS USED**

TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS

**Service Requests:**

04/10/2017 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
VEHICLE EMERGENCY LIGHTS NOT WORKING

**CSHOP-2017-2160**

Comments: **R230**

Date Opened 4-13-2017 Date Finished 4-17-2017 Meter 1 Reading: 146,684

**TASKS PERFORMED**

**NO PARTS USED**

AIR SYSTEM

**Service Requests:**

04/13/2017 AIR RIDE / 18: LEAKING / EXCHANGE - NEW  
AIR LEAK, TAKES SEVERAL MINUTES TO FILL AIR SUSPENSION



**Asset Work Order History 10142532**

**CSHOP-2017-2219**

Date Opened 4-17-2017 Date Finished 4-17-2017 Meter 1 Reading: 146,684

**TASKS PERFORMED**

**NO PARTS USED**

WAIT TIME TO BE CHARGED TO WORK ORDER  
TRAVEL TO BE CHARGED TO WORK ORDER  
STROBE LIGHTS  
DOOR

**Service Requests:**

04/14/2017 DOOR / 19: LOOSE / REPAIR  
VEHICLE DOORS

04/15/2017 SERVICE REQUEST / 12: BROKEN / EXCHANGE - USED  
SERVICE REQUEST FRONT EMERGENCY LIGHT COVERS ARE LOOSE

**CSHOP-2017-2220**

Comments: **ON-CALL R230 EMERGENCY LIGHTS OUT**

Date Opened 4-17-2017 Date Finished 4-19-2017 Meter 1 Reading: 146,874

**TASKS PERFORMED**

**Q PARTS**

STROBE LIGHTS

2 TUBE; TUBE - STROBE

**CSHOP-2017-2641**

Date Opened 5-5-2017 Date Finished 5-22-2017 Meter 1 Reading: 146,957

**TASKS PERFORMED**

**Q PARTS**

WIPER BLADES  
REPAIR FROM PM - POWER STEERING  
REPAIR FROM PM - BELTS  
REPAIR FROM PM - BRAKES  
CAB-INTERIOR ACCESSORIES  
AIR CONDITIONING

2 1AN; 22" WIPER BLADE  
1 FIL; POWER STEERING FILTER  
2 2IH; POWER STEERING FLUID 32OZ  
1 9IP; BELT  
1 9IP; BELT  
1 9IP; BLT  
10 NUT; 13-3052 NUT  
1 BRAKE; BRAKE PADS  
1 BRAKE; BRAKE PADS  
1 NEWPART; BRAKE FLUID  
2 5SC; ZICO STOPS BRACKETS  
3 5SC; ZICO RATCHET STRAP  
1 NONSTOCK; FREIGHT CHARGE

**Service Requests:**

05/05/2017 BODY / 19: LOOSE / REPAIR

## Asset Work Order History 10142532

### CSHOP-2017-2725

Date Opened 5-9-2017

Date Finished

5-19-2017

Meter 1 Reading:

146,957

#### TASKS PERFORMED

PM SERVICE B

#### Q PARTS

1 FIL; NAPAGOLD FUEL FILTER  
1 FIL; NAPAGOLD OIL FILTER  
2 NCB; SUPER K WASH CONCNTRT  
1 FIL; NAPAGOLD FUEL FILTER  
1 9IP; AIR FILTER 46744 WIX

### CSHOP-2017-412

Date Opened 1-18-2017

Date Finished

2-3-2017

Meter 1 Reading:

142,432

#### TASKS PERFORMED

A INSPECTION  
SIDE COMPARTMENT BODY  
FAULT CODE  
CHARGING SYSTEM  
HOOD LATCH  
A/C BELT FRONT A/C  
AIR CONDITIONING

#### Q PARTS

1 9IP; 9IP  
1 5TN; AUTO CHAGRE 2000  
1 9IP; PLASTIC HOOD LATCH  
1 9XX; 9XX

### CSHOP-2017-4180

Date Opened 7-18-2017

Date Finished

8-11-2017

Meter 1 Reading:

146,958

#### TASKS PERFORMED

WIPERS-WASHER  
FRONT SHOCKS- STRUTS

#### Q PARTS

2 1AN; 22`` WIPER BLADE  
2 2FL; SHOCK FRONT

### CSHOP-2017-5095

Comments: PATIENT A/C INOP AT ST30

Date Opened 8-29-2017

Date Finished

9-29-2017

Meter 1 Reading:

149,042

#### TASKS PERFORMED

AIR CONDITIONING

#### NO PARTS USED

## Asset Work Order History 10142532

### CSHOP-2017-5116

Comments: **SPARE RESCUE AT STATION 30**

Date Opened 8-30-2017 Date Finished 9-5-2017 Meter 1 Reading: 147,422

#### TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER  
TIRES ALL  
STROBE LIGHTS

#### **Service Requests:**

08/30/2017 LIGHTS / 38: SHORTED / INSPECT  
VEHICLE LIGHTS NOT WORKING DRIVERS SIDE EMERGENCY LIGHTS NOT FLASHING WHEN DRIVING CODE 3

08/31/2017 SERVICE REQUEST / 48: LOW PRESSURE / ADJUST  
SERVICE REQUEST- TIRE PRESSURE ON ALL 6 TIRES ARE LOW AT 95 PSI NEED TO BE AT 110

### CSHOP-2017-5171

Date Opened 9-4-2017 Date Finished 9-5-2017 Meter 1 Reading: 147,422

#### TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

#### **Service Requests:**

09/04/2017 A/C / 18: LEAKING / LUBRICATE  
A/C ISSUE. PATIENT COMPARTMENT IS VERY HOT. AIR IS BLOWING BUT VERY LITTLE AND NOT COLD.

### CSHOP-2017-7020

Date Opened 12-9-2017 Date Finished 12-14-2017 Meter 1 Reading: 149,042

#### TASKS PERFORMED

Q PARTS

BATTERY  
AIR CONDITIONING

3 9XX; 134A 10194654

### CSHOP-2018-1087

Date Opened 2-22-2018 Date Finished 2-28-2018 Meter 1 Reading: 149,112

#### TASKS PERFORMED

NO PARTS USED

PM SERVICE C RESCUE

## Asset Work Order History 10142532

### CSHOP-2018-1111

Comments: **PM FOLLOW UPS SCANNED TO WORK ORDER**

Date Opened 2-23-2018

Date Finished

6-14-2018

Meter 1 Reading:

150,106

PATIENT AC FILTER, AND 110 AC HOT

#### TASKS PERFORMED

BODY - EQUIPMENT TRANSPORT  
COOLING SYSTEM  
LIGHTING SYSTEM  
IGNITION SYSTEM  
AIR DRIER  
AIR CONDITIONING

#### Q PARTS

1	5AH; 11.25 DRAWER SLIDE (PR)
1	5EF; O23WRENCH
1	5TN; LEDLIGHTKIT
1	9IP; LIGHT BULB
2	8HD; 18 IN 15W BULB
1	9IP; BULB PATIENT GH22
4	1AD; BATTERY31SERIES
1	TWD; AD-9KIT
1	TWD; AD-9KIT MINOR
1	8HD; BREAKER
1	8GR; FILTER

#### **Service Requests:**

04/26/2018 LIGHTS / 49: CAN NOT DUPLICATE CONCERN / INSPECT  
VEHICLE LIGHT NOT WORKING. LEFT SIDE FRONT EMERGENCY LIGHT NOT WORKING

04/26/2018 SERVICE REQUEST / 19: LOOSE / REPAIR  
LEFT HEAD LIGHT FRAME BROKE

### CSHOP-2018-3949

Date Opened 7-12-2018

Date Finished

7-18-2018

Meter 1 Reading:

150,112

#### TASKS PERFORMED

QUALITY CHECK-REPAIRS  
STROBE LIGHTS  
A/C BELT FRONT A/C

#### Q PARTS

1	9HY; HOSEFITTINGS
1	BK; CLRRTVSILCNSEALANT
2	9IP; POWERSUPPLYKKKEPS

### CSHOP-2018-4049

Date Opened 7-18-2018

Date Finished

7-18-2018

Meter 1 Reading:

150,112

#### TASKS PERFORMED

QUALITY CHECK-REPAIRS  
LIGHTING SYSTEM

#### Q PARTS

1	2FL; LAMPASSYWSTUDS
---	---------------------

### CSHOP-2018-4189

Date Opened 7-26-2018

Date Finished

7-26-2018

Meter 1 Reading:

150,464

#### TASKS PERFORMED

DOOR

#### NO PARTS USED

## Asset Work Order History 10142532

### CSHOP-2018-4267

Comments: **AIR LEAK**

Date Opened 7-30-2018

Date Finished

8-2-2018

Meter 1 Reading:

150,954

#### TASKS PERFORMED

#### Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER  
AIR SYSTEM

1 BK; SWITCH  
1 2FL; SWITCH  
1 2FL; NORMCLSD2WIREPRESSW

### CSHOP-2018-4438

Date Opened 8-8-2018

Date Finished

8-10-2018

Meter 1 Reading:

151,496

#### TASKS PERFORMED

#### Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER  
WIPERS-WASHER  
DOOR

2 1AN; 22 WIPER BLADE

### CSHOP-2018-5253

Date Opened 9-14-2018

Date Finished

9-19-2018

Meter 1 Reading:

151,496

#### TASKS PERFORMED

#### NO PARTS USED

BATTERY

### CSHOP-2018-5492

Comments: **SPARE RESCUE AT 44**

Date Opened 9-26-2018

Date Finished

9-26-2018

Meter 1 Reading:

151,764

#### TASKS PERFORMED

#### NO PARTS USED

STRETCHER

#### Service Requests:

09/26/2018

HAZARD / 12: BROKEN / REPAIR

HAZARDOUS ISSUE CATCH HOOK FOR THE STRETCHER CAME OFF. IT WAS REPLACED BUT ITS STILL NOT CATCHING.

### CSHOP-2018-5645

Date Opened 10-4-2018

Date Finished

10-4-2018

Meter 1 Reading:

152,252

#### TASKS PERFORMED

#### NO PARTS USED

STRETCHER

## Asset Work Order History 10142532

### CSHOP-2018-5769

Date Opened 10-12-2018 Date Finished 12-11-2018 Meter 1 Reading: 156,424

#### TASKS PERFORMED

	Q	PARTS
LIGHTING SYSTEM	5	1WL; 600 SERIES RED LED WO FLANGE
TRANSMISSION	2	1WL; 900 SERIES SUPER RED LED
TIRES & WHEELS	2	LIT; BULB
BRAKES	1	1WL; 600 LIN SUPER LED FLASH
SAFTEY-EMERGENCY EQUIPMENT	2	LMP; BRITE LITE LAMP
HOSES-LINES & FITTINGS	3	MMM; ELECTRICAL TAPE
AIR CONDITIONING	1	2IH; BRAKE FLUID

#### Service Requests:

10/12/2018	LIGHTS / 12: BROKEN / EXCHANGE - NEW PASSENGER SIDE EMERGENCY GRILLE LIGHT NOT WORKING
10/12/2018	SERVICE REQUEST / 19: LOOSE / REPAIR AIR HORN IS NOT WORKING.
11/06/2018	LIGHTS / 12: BROKEN / EXCHANGE - NEW VEHICLE LIGHTS NOT WORKING - 2 SMALL RED EMERGENCY LIGHTS NEAR TOP LIGHT BAR NEAR ROOF IS NOT WORKING.
11/06/2018	LIGHTS / 12: BROKEN / EXCHANGE - NEW VEHICLE LIGHTS NOT WORKING - VEHICLE LIGHTS NOT WORKING - 2 SMALL RED EMERGENCY LIGHTS NEAR TOP LIGHT BAR NEAR ROOF ON THE BACK OF THE RESCUE IS NOT WORKING.

### CSHOP-2018-6616

Comments: **AT ST 44**

Date Opened 11-21-2018 Date Finished 11-21-2018 Meter 1 Reading: 156,019

#### TASKS PERFORMED

AIR HORN

#### NO PARTS USED

#### Service Requests:

11/20/2018	SERVICE REQUEST / 12: BROKEN / REPAIR AIR HORN DOES NOT WORK
------------	---

### CSHOP-2018-6711

Date Opened 11-27-2018 Date Finished 12-11-2018 Meter 1 Reading: 156,424

#### TASKS PERFORMED

	Q	PARTS
PM SERVICE B	2	1AN; WIPER BLADES
	1	FIL; NAPAGOLD FUEL FILTER
	-21	9OC; 15W40 OIL VAL DRUM S SHOP
	21	9OC; 15W40 OIL VAL DRUM S SHOP
	1	FIL; NAPAGOLD OIL FILTER
	21	FLUID; SYN OIL BULK QTS
	1	FIL; NAPAGOLD FUEL FILTER

## Asset Work Order History 10142532

### CSHOP-2018-6837

Date Opened 12-3-2018 Date Finished 12-3-2018 Meter 1 Reading: 156,424

#### TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR? DAN CALLAGHAN ENTERPRISES

### CSHOP-2019-150

Date Opened 1-9-2019 Date Finished 1-30-2019 Meter 1 Reading: 156,424

#### TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

PRE TRIP INSPECTION

POWER BOOSTER-HYDRO BOOST

1	1FG; CAP
1	2FL; SCREW
4	NOL; TRAN FLU QT DEXRON3I
1	2FL; VALVE
1	FIL; POWER STEERING FILTER
1	2FL; SERVICE KIT
1	2FL; GASKET

### RADIO-2018-501

Comments: REMOVE 10141708, INSTALL 10205599 INTO SR2 - 10142532

Date Opened 5-16-2018 Date Finished 5-16-2018 Meter 1 Reading: 0

#### TASKS PERFORMED

NO PARTS USED

MOBILE RELATED

#### Service Requests:

05/16/2018	RADIO / / REMOVE AND INSTALL NEW MOBILE RADIO INTO SPARE RESCUE 2
------------	--