

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 735146 **Problem:** WELD WINCH

Meter Reading: 313	Labor	Parts
In Date: 03/05/2007	Hours	Description
Close Date: 03/07/2007		Quantity
- Weld Winch Attachment Bolts.	1.00	SHOP SUPPLIES
- Shop Supplies		1.00
Parts Charge:	2.00	Labor Charge: 55.00

Workorder: 735164 **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts
In Date: 03/05/2007	Hours	Description
Close Date: 03/05/2007		Quantity
- Pre-Delivery Inspection	2.00	
Parts Charge:	0.00	Labor Charge: 110.00

Workorder: 737043 **Problem:** ORDER AND INSTALL FUEL TANK UNIT PER ESTIMATE

Meter Reading: 314	Labor	Parts
In Date: 04/11/2007	Hours	Description
Close Date: 04/23/2007		Quantity
- Ck Install Aux. Diesel Tank In Bed Of Truck,	9.00	FUEL/TANK 487000
Assemble,Instllgasboy Fuel Pump.		70064 PUMP FILTER DON'T REORDER
- Shop Supplies		TP-1993A-D DECAL DIESEL 1993
		3/4"X3/4"NIPPLE (VARIOUS)
		30055-20 CKT BREAKER 20 AMP
		504303-05 REBUILT DON'T REORDER
		50003 FILTER HEAD SINGLE 3/4" (CIM-TEK)
		FUEL/PUMP 001R
		SHOP SUPPLIES
		3/4" STREET ELBOW 90D GALVANIZED
Parts Charge:	1,326.80	Labor Charge: 495.00

Workorder: 740717 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts
In Date: 06/18/2007	Hours	Description
Close Date: 06/27/2007		Quantity
- Tiresoles Of Broward Inc		
Parts Charge:	0.00	Labor Charge: 0.00 Commercial Charge: 60.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 742490

Problem: LOW TIRE LIGHT ON

Meter Reading: 2910	Labor	Parts	
In Date: 08/02/2007	Hours	Description	Quantity
- Transport To Dealer For R/R Tpms Sensor Replacement Program Pu When Done.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	27.50

Workorder: 742866

Problem: CHECK DRIVELINE NOISE.

Meter Reading: 3268	Labor	Parts	
In Date: 08/20/2007	Hours	Description	Quantity
- Repair Catalytic Converter Shields & Reinstall Vehicle Rear Wiring Harness.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	55.00

Workorder: 745238

Problem: P.M SERVICE

Meter Reading: 4038	Labor	Parts	
In Date: 10/05/2007	Hours	Description	Quantity
- Pm Service	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Service Front Winch Lube And Inspect.		5W20 ENGINE OIL	7.00
- Shop Supplies		10020 INJECTOR CLEANER DON'T REORDER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	24.07	Labor Charge:	60.00

Workorder: 747987

Problem: CHECK LIGHTS & TRAILER PLUG

Meter Reading: 5994	Labor	Parts	
In Date: 11/30/2007	Hours	Description	Quantity
- Lights On Rear Of Truck Not Working.Diag Circuits.Trace Wiring.Repair Connector In Harness.Reroute And Secure Wiring As Needed	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 836601

Problem: P.M SERVICE

Meter Reading: 9397		Labor		Parts	
In Date: 04/04/2008	Close Date: 04/15/2008	Hours	Description	Quantity	
-	Pm Service	6.75	G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
-	Frt Drive Shaft Boot Torn.R&R Drive Shaft To Repl		DRIVESHAFT BOOT	1.00	
	Boot.Cleanout Excess Dirt.Relube Splines.		FRONT CLAMP	1.00	
-	Rotate High Speed Balance 4 Tires.Full W/Nitrogen.		REAR CLAMP	1.00	
-	Service Winch.		SHOP SUPPLIES	1.00	
-	Shop Supplies		05074 SILICONE SPRAY	1.00	
			CA8038 AIR FILTER LBF AF1300 WIX 46440	1.00	
			5W20 ENGINE OIL	7.00	
			31-20 WIPER BLADES 20" BLADE	2.00	
			1372 OIL FILTER FRM PH2 WIX 51372	1.00	
Parts Charge:		102.21	Labor Charge:	60.00	

Workorder: 837115

Problem: R/F TIRE BLOWN OUT

Meter Reading: 9444		Labor		Parts	
In Date: 04/17/2008	Close Date: 04/22/2008	Hours	Description	Quantity	
-	Right Frt Tire Damage Beyond Repairs Mount Spare Tire	1.50	TIRE	1.00	
	Fr Blkrim Tomatch Regular Wheel,New Tire Tospare		TIRE DISPOSAL FEE	1.00	
	Wheel Nitrogen Fill & Balance Both		SHOP SUPPLIES	1.00	
-	Shop Supplies				
Parts Charge:		193.35	Labor Charge:	30.00	

Workorder: 840722

Problem: L/F TIRE FLAT

Meter Reading: 11915		Labor		Parts	
In Date: 06/30/2008	Close Date: 07/02/2008	Hours	Description	Quantity	
-	Leak Test L/F Tire.Replace Cracked Leaking Valve Stem	2.00	SHOP SUPPLIES	1.00	
	Inspecall Other And Replace All 4 Valve Stems For				
	Cracks And Split.				
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	120.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 845147

Problem: P.M SERVICE

Meter Reading: 15290	Labor	Parts	
In Date: 10/03/2008	Hours	Description	
Close Date: 10/14/2008		Quantity	
- Pm Service	16.75	70064 PUMP FILTER DON'T REORDER	1.00
- Inspected Under Vehicle,Cleared Debris In Chassis & Infront End,Replaced Damaged Transmission Crossmember.Test Drive.		SHOP SUPPLIES	1.00
- Service Aux Fuel Tank.		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
- Resurface Rear Rotors,Replace Rear Pads,Service Parking Brkstest Drive.		09997 BRAKE CLEAN	1.00
- Ck Winch Operation,Would Not Pull In Cable.Diagnose Sys,Repl2 Defective Solinoids.Service Winch.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Hi Speed Balance 4 Tires,Nitrofill Tires.		31-20 WIPER BLADES 20" BLADE	2.00
- Complete Front End Alignment,Test Drive.		REAR BRAKE PAD SET	1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		E9TZ11450B SOLENOID STD SS598	2.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	-1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00
		5W20 ENGINE OIL	7.00
		CA8038 AIR FILTER LBF AF1300 WIX 46440	1.00
		TRANSMISSION CROSS MEMBER	1.00
		61A P/STEERING FLUID	1.00
Parts Charge:	809.66	Labor Charge:	150.00

Workorder: 845255

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	
In Date: 09/29/2008	Hours	Description	
Close Date: 10/06/2008		Quantity	
- Tiresoles Of Broward Inc			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	60.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 936781

Problem: P.M SERVICE,SEE NOTE

Meter Reading: 20210 In Date: 04/21/2009	Close Date: 04/30/2009	Labor Hours	Description	Parts	Quantity
- Pm Service		20.25	30055-30 30AMP CIRCUIT BREAKER		1.00
- Front Brake Machine Rotors New Pads Flush Fluid Lube Calipers Slide & Pins.			SHOP SUPPLIES		1.00
- R&R L. Front Door To Install New Arm Rest. Broken.			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
- Service External Fuel Tank.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Replace Damaged-Trans Cross Member,Transfer Case Shield,Front Skid Plate,Exhaust Sheild,Remove Lower Control Arms & Straighten Frame Align			5W20 ENGINE OIL		7.00
- R&R Front Drive Shaft & Replace Torn Flesc Boot On Shaft.			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
- Test Amp Drqw On Aux Fuel Pump Replace Circuit Breaker & Wire Off Battery. Repair On/Off Switch @ Pump.			FRONT DIFFERENTIAL SHAFT BOOT		1.00
- Rotate & High Speed Balance All 4 Tires.			FRONT BRAKE PAD SET		1.00
- Complete Front End Alignment.			DRIVER DOOR ARM REST		1.00
- Shop Supplies			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			60003 TANK CAP		1.00
			CATALYTIC CONVERTER HEAT SHIELD		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		-1.00
			24006 FUEL FILTER DIESEL AND GAS		1.00
			FRONT SKID PLATE		1.00
			HEAT SHIELD		1.00
			D3TZ2457B BRAKE PEDAL PAD		1.00
			CROSS MEMBER		1.00
			TRANSFER CASE CROSS MEMBER		1.00
	Parts Charge:	1,169.47	Labor Charge:	1,215.00	

Workorder: 943107

Problem: 4x4 not disengaging

Meter Reading: 23755 In Date: 09/10/2009	Close Date: 09/21/2009	Labor Hours	Description	Parts	Quantity
- To/From Dealer For 4X4 Inop. O/H Transfere Case, Replace Hub & 4X4 Indicator Switch. Perform Recall # 09L03 Valve Stems		2.50	4114K BULB (ACD)		1.00
- Check All Lights & Replace L/R Brake Light Bulb.			SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge:	4.94	Labor Charge:	90.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 947198

Problem: P.M service, see notes.

Meter Reading: 26401 In Date: 12/21/2009	Close Date: 01/20/2010	Labor Hours	Description	Parts	Quantity
- P.M Service.		13.45	THRUST BEARING		1.00
- Mount Two New Tires, Rotate & Balance All Four Tires.			117 USED TOOL BOX WEATHER GUARD TOOL BOX		1.00
- Service Aux Fuel Tank.			GASKET		1.00
- Fabricate & Install Tool Box In Bed.			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
- Pressure Test & Inspect Cooling System, Replace Damaged Lower Radiator Hose, Flush & Renew Coolant.			TIRE DISPOSAL FEE		2.00
- Service & Inspect Winch, Planetary Gear Section			CARRIER ASSEMBLY		1.00
- Destroyed, Overhaul Planetary Gear Section, Install New Hook On Cable.			LOWER RADIATOR HOSE		1.00
- Alignment.			5W20 ENGINE OIL		7.00
- Shop Supplies			SUN GEAR		1.00
			24006 FUEL FILTER DIESEL AND GAS		1.00
			3/4 90D ELBOW GALV. (VARIOUS)		1.00
			CARRIER ASSEMBLY		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			CARRIER ASSEMBLY		1.00
			WINCH HOOK CX06-7077		1.00
			SHOP SUPPLIES		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			758537188 235/75R17 WRGLR SILENT ARMOR 108T		2.00
			HEX SHAFT		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
	Parts Charge:	835.25	Labor Charge:	1,614.00	

Workorder: 1002021

Problem: Check vibration.

Meter Reading: 27256 In Date: 02/25/2010	Close Date: 03/01/2010	Labor Hours	Description	Parts	Quantity
- Mount Two New Tires, Rotate & Balance All Four Tires.		2.00	758537188 235/75R17 WRGLR SILENT ARMOR 108T		2.00
- Shop Supplies			TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
	Parts Charge:	323.73	Labor Charge:	120.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1003262

Problem: Check power steering leak.

Meter Reading: 28256 In Date: 03/31/2010	Close Date: 04/08/2010	Labor Hours	Description	Parts	Quantity
- Inspect & Replace Damaged Power Steering Rack & Pinion Unit, Refill & Bleed System, Realign Frontend & Test Drive.		13.70	R/F INNER CV BOOT CLAMP		1.00 1.00
- Replace Bent & Damaged Rear Transmission Support Crossmember, Straighten & Repair Mounting Plates.			61A P/STEERING FLUID CHASSIS GREASE		2.00 1.00
- Replace Bent Front Drive Shaft & Straighten Heat Shield, Remove R/F Half Shaft & Replace Torn Cv Boot.			SHOP SUPPLIES FRONT DRIVE SHAFT / 5L324A376A CLAMP		1.00 1.00 1.00
- Shop Supplies			AXLE NUT TRANS CROSSMEMBER / 6113Z6A023A RACK ASSEMBLY / 8L3Z3504DRM		1.00 1.00 1.00
Parts Charge:		1,693.57	Labor Charge:		762.00

Workorder: 1010593

Problem: P.M. Service..Check aux. pump.

Meter Reading: 33343 In Date: 09/27/2010	Close Date: 10/06/2010	Labor Hours	Description	Parts	Quantity
- P.M. Service.		13.25	MKD1012 BRAKE PADS		1.00
- Resurface Front And Rear Rotors.Replace Front And Rear Calipers And Brake Pads.Clean And Lube Slides,Flush And Bleed System.			SHOP SUPPLIES COVER WHEEL		1.00 1.00
- Check Aux. Fuel Pump Circuit. Replace Defective Circuit Breaker.			FRONT BRAKE CALIPER 09997 BRAKE CLEAN		1.00 1.00
- Inspect And Service Winch.			G10166 FUEL FILTER MTC FG1083 WIX 33243 FRONT BRAKE CALIPER		1.00 1.00
- Rotate And Balance All Tires.			5W20 ENGINE OIL 7090BLK FRT FLOOR MATS (RUBBER QUEEN)		7.00 1.00
- Shop Supplies			30055-30 30AMP CIRCUIT BREAKER 1372 OIL FILTER FRM PH2 WIX 51372 31-20 WIPER BLADES 20" BLADE MX1083 BRAKE PADS		1.00 1.00 2.00 1.00
			1401 BRAKE FLUID BRAKE FLUID USED FIREX REFURBED FIRE EXTINGSHERS CA8039 AIR FILTER LBF AF1615 WIX 46418		2.00 1.00 1.00
Parts Charge:		417.41	Labor Charge:		795.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1012459

Problem: Aux fuel pump slow to pump.

Meter Reading: 34551	Labor	Parts	
In Date: 11/05/2010	Hours	Description	Quantity
- Inspect And Service Auxiliary Fuel System.Replace Clogged Filter With New.	1.00	SHOP SUPPLIES 24006 FUEL FILTER DIESEL AND GAS	1.00 1.00
- Shop Supplies			
Parts Charge:	7.76	Labor Charge:	60.00

Workorder: 1101097

Problem: Towed in,P/S LEAK

Meter Reading: 36662	Labor	Parts	
In Date: 01/28/2011	Hours	Description	Quantity
- Replace Damaged Power Steering Cooler Line.Refill And Bleed System.Replace Oil Drain Deflector.	1.50	SHOP SUPPLIES COOLER LINE 61A P/STEERING FLUID DELECTOR	1.00 1.00 1.00 1.00
- Shop Supplies			
Parts Charge:	78.81	Labor Charge:	90.00

Workorder: 1101117

Problem: BROKEN POWER STEERING LINE

Meter Reading: 36609	Labor	Parts	
In Date: 01/28/2011	Hours	Description	Quantity
- From: Loxhtchee Slew-(B-Line Hwy 2 Mi W Of Pga-N-Side) To: Lv Shop			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	102.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1102049

Problem: Replace tires with off road tires.

Meter Reading: 38303 In Date: 02/22/2011	Close Date: 03/21/2011	Labor Hours	Description	Parts	Quantity
-	Install Four New Off Road Tires Asper Request.Nitrogen Fill And Balance All Four.	17.25	WRANGLER MT/R TIRE		4.00
-	Perform Pm Service.		TIRE DISPOSAL FEE		4.00
-	Inspect And Service Auxiliary Fuel Tank		REAR OUTER BEARING		2.00
-	Replace Left Front Axle Assemble.Replace Right Front Hub.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Replace Rear Axle Bearings.Serviceand Refill Rear Differential.		31-20 WIPER BLADES 20" BLADE		2.00
-	Replace Broken Tag Light.		SYN/ATF TRANS FLUID SYNTHETIC		16.00
-	Flush And Refill Transmission.		CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
-	Service And Refill Transfer Case.		5W20 ENGINE OIL		7.00
-	Complete Wheel Alignment.		SHOP SUPPLIES		1.00
-	Shop Supplies		75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)		2.00
			FRONT LIFT AXLE ASSEMBLY		1.00
			RIGHT FRONT HUB ASSEMBLY		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		5.00
			SEALS		2.00
			24006 FUEL FILTER DIESEL AND GAS		1.00
			F37Z13550AA TAG LIGHT (FORD)		1.00
			C8AZ19B546A ADDITIVE DIFFERENTIAL (MC XL-3)		1.00
Parts Charge:		1,847.27	Labor Charge:		1,035.00

Workorder: 1107292

Problem: Check axles and winch broken inop.

Meter Reading: 42113 In Date: 07/12/2011	Close Date: 07/28/2011	Labor Hours	Description	Parts	Quantity
-	Inspect And Replace Damage Left Front Axle Assembly With New.	6.00	WINCH M8000		1.00
-	Diagnose Winch Inop.Fabricate And Replace Failed Power Winch Assembly With New Due To Salt Water Damage.Fabricate And Mount Relay New Relay Control Box And Wiring Harness.		SHOP SUPPLIES		1.00
-	Shop Supplies		HALF SHAFT FRONT LEFT		1.00
Parts Charge:		1,351.52	Labor Charge:		360.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1107724

Problem: weld winch bolts

Meter Reading: 42113		Labor		Parts	
In Date: 07/22/2011	Close Date: 07/26/2011	Hours	Description		Quantity
- Weld Mounting Bolts For Winch		1.50	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 90.00			

Workorder: 1109701

Problem: Pm service.check ac,trailer plug and hub noises, see notes.

Meter Reading: 43761		Labor		Parts	
In Date: 09/12/2011	Close Date: 09/26/2011	Hours	Description		Quantity
- P.M. Service.		12.00	5W20 ENGINE OIL		7.00
- Test Battery And Charging System.Replace Bad Battery.			1372 OIL FILTER FRM PH2 WIX 51372		1.00
- Inspect And Service Auxillary Fuel Tank.			31-20 WIPER BLADES 20" BLADE		2.00
- Check Front Hubs.Replace Right Side Hub Assemble And Both Right And Left Vacuum Actuators.			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Check A/C System For Cooling Concern.Replace Fan Clutch And Belt Idler Pulley.			GROUP 59 BATTERY (MTC BXT 59)		1.00
- Inspect And Service Winch Assemble.			HUB		1.00
- Rotate And Balance All Tires.			HUB ACTUATORS		2.00
- Shop Supplies			FAN CLUTCH		1.00
			GROOVED IDLER PULLEY		1.00
			CA8039 AIR FILTER LBF AF1615 WIX 46418		1.00
			24006 FUEL FILTER DIESEL AND GAS		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 1,018.35		Labor Charge: 720.00			

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1200787

Problem: Ac inop.Winch will not go into neutral.

Meter Reading: 47076	Labor	Parts
In Date: 01/25/2012	Hours	Quantity
Close Date: 01/31/2012	Description	
- Diagnose Noise Squealing Noise Fron Engine Area.Replace Defective Belt Tensioner And Serpentine Belt.	9.50	ACCUMULATOR 1.00 SERPENTINE BELT 1.00 E8 A/C OIL R134A A/C OIL (TSI) 1.00
- Check A/C System.Replace Compressor,Accumulator And Orifice Tube.Evacuate And Recharge System.		BELT TENSIONER 1.00 R134A REFRIGERANT 2.00
- Dis-Assemble Winch And Clean A Lube Planetary Gears.Reseal Gear Case.Service Winch.		A/C COMPRESSOR 1.00 GASKET 1.00
- Shop Supplies		SHOP SUPPLIES 1.00 SEAL KIT 1.00 ORIFICE 1.00
Parts Charge: 661.28	Labor Charge: 570.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1202269

Problem: Check rear end noise and fluid leaks.

Meter Reading: 48230	Labor	Parts	
In Date: 03/06/2012	Hours	Description	Quantity
- P.M. Service.	24.25	31-20 WIPER BLADES 20" BLADE	2.00
- Resurface And Replace Front And Rear Brake Rotors.Replace Front And Rear Brake Pads.Service And Lube Calipers.Flush And Bleed System.		24006 FUEL FILTER DIESEL AND GAS	1.00
- Replace Damaged Right Front Axle Assemble.		82194 GRAY SILICONE (PERMATEX)	2.00
- Inspect And Service Aux. Fuel Tank.Inspect And Service Winch.		OIL SLINGER WASHER	1.00
- Diagnose Rear Axle Noise.Overhaul Differential.Replace Rinr And Pinion Gears And Carrier Bearing.Flush And Refill With New Fluid.Test Drive.		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00
- Rotate And Balance All Tires.		5W20 ENGINE OIL	7.00
- Shop Supplies		1401 BRAKE FLUID BRAKE FLUID	2.00
		C8AZ19B546A ADDITIVE DIFFERENTIAL (MC XL-3)	1.00
		TONE RING	1.00
		BEARING CUP	2.00
		RING AND PINION SET	1.00
		FLANGE	1.00
		DIFFERENTIAL CARRIER	1.00
		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
		BOLTS	10.00
		09997 BRAKE CLEAN	2.00
		SHOP SUPPLIES	1.00
		REAR PADS	1.00
		RF AXLE	1.00
		75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)	3.00
		FRONT PADS	1.00
		FRONT ROTORS	2.00
		REAR ROTORS	2.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		BEARING	2.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
Parts Charge:	1,959.78	Labor Charge:	1,455.00

Workorder: 1206290

Problem: Left front tire flat.Riding on spare.

Meter Reading: 51552	Labor	Parts	
In Date: 07/05/2012	Hours	Description	Quantity
- Repair Flat Left Front Tire.Nitrogen Fill And Balance Same.Remount Spare Tire To Rack.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1206753

Problem: belt broke

Meter Reading: 51910	Labor	Parts		
In Date: 07/19/2012	Hours	Description	Quantity	
- Tow From: 18051 Limestone Creek Rd, Jupiter Fl To: Vista Lv Shop				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 104.15

Workorder: 1206831

Problem: Towed in belt came apart.

Meter Reading: 52039	Labor	Parts		
In Date: 07/23/2012	Hours	Description	Quantity	
- Diagnose Belt Damage.Test And Replace Damage Fan Clutch,Idle Pulley And Serpentine Belt With New.				
	16.25	FAN CLUTCH	1.00	
		L/FRONT BRAKE CALIPER	1.00	
- Computer Diagnose For Check Engine Light .Pinpoint Test And Replace Failed Trottle Body Assembly With New And Clean Intake Ports.Clear Codes With Scan Tool And Road Test.				
		R/FRONT BRAKE CALIPER	1.00	
		1401 BRAKE FLUID BRAKE FLUID	1.00	
		FRONT BRAKE PAD SET	1.00	
		LOCK HUB VACUUM TUBE	1.00	
- Install New Front Brake Pads And New Front Brake Calipers.Resurface Both Front Brake Rotors And Flush Brake Fluid.Automated Bleed Hydraulic System With Scan Tool.				
		SHOP SUPPLIES	1.00	
		BELT	1.00	
		THROTTLE BODY	1.00	
		OUTER TIE ROD END	2.00	
		GROOVED IDLER PULLEY	1.00	
- Remove Left Lower Control Arm To Repair Bent Lower Control Arm Mounting Bracket.Replace Both Damage Outer Tie Rod Ends And Locking Hub Vacume Tubes.				
		09997 BRAKE CLEAN	1.00	
- Perform Wheel Alignment Complete.				
- Shop Supplies				
Parts Charge:	943.00	Labor Charge:	975.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1208338

Problem: P.M. service and 4 wheel drive inop.

Meter Reading: 53315	Labor	Parts	
In Date: 09/04/2012	Hours	Description	Quantity
- P.M. Service.	13.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Diagnose 4X4 Inop. Replace Failed lwe. Solenoid. Drain		CA8039 AIR FILTER LBF AF1615 WIX 46418	1.00
And Refill Front Differential.		24006 FUEL FILTER DIESEL AND GAS	1.00
- Replace And Balance All Four Tires.		IWE SOLENOID	1.00
- Replace Center Brake Lamp Lense.		TIRE LT245/70R17	4.00
- Inspect And Service Aux. Fuel Tank.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Inspect And Service Winch.		82194 GRAY SILICONE (PERMATEX)	1.00
- Complete Wheel Alignment. Test Drive.		SHOP SUPPLIES	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		THIRD BRAKE LIGHT ASSEMBLY	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)	2.00
Parts Charge:	1,315.98	Labor Charge:	795.00

Workorder: 1211292

Problem: Check over front end and wheel alignment.

Meter Reading: 54537	Labor	Parts	
In Date: 11/20/2012	Hours	Description	Quantity
- Inspect And Replace Failed Right Lower Balljoint With	5.50	JOINT ASSEMBLY	1.00
New. Fabricate And Repair Bent Crossmember With		CENTER CAP	1.00
Torch.		SHOP SUPPLIES	1.00
- Perform Wheel Alignment Complete.		NUT	1.00
- Shop Supplies			
Parts Charge:	118.02	Labor Charge:	330.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1305368

Problem: Pm service.Right front tire flat.

Meter Reading: 59144		Labor		Parts	
In Date: 05/31/2013	Close Date: 06/11/2013	Hours	Description		Quantity
-	P.M. Service.	7.25	31-20 WIPER BLADES 20		2.00
-	Inspect And Service Aux. Fuel System.		USED FIRE X REFURBISHED		1.00
-	Repair Right Front Tire.Rotate And Balance All Four.		BIGG DEGREASER		1.00
-	Replace Toolbox Lid Props.		TPMS8 STRAP TPS 17IN		1.00
-	Inspect And Service Winch.		NAPAGOLD FUEL FILTER		1.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			SHOP SUPPLIES		1.00
			PROP		1.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge: 283.40		Labor Charge: 435.00			

Workorder: 1308463

Problem: Check over and repair trailer plug receptacle and harness failed.

Meter Reading: 61836		Labor		Parts	
In Date: 08/21/2013	Close Date: 08/27/2013	Hours	Description		Quantity
-	Diagnose For Trailer Harness And Receptacle Inop.Test	1.50	SHOP SUPPLIES		1.00
	And Replace Failed Trailer Plug Receptacle With New		VINYL ELECTRICAL TAPE		1.00
	And Repair Faulty Wiring Harness.		5404 FEMALE CONNECTOR		1.00
-	Shop Supplies				
Parts Charge: 16.67		Labor Charge: 90.00			

Workorder: 1309574

Problem: Noise in front wheels when four wheel drive is selected.

Meter Reading: 63079		Labor		Parts	
In Date: 09/23/2013	Close Date: 09/30/2013	Hours	Description		Quantity
-	Test Drive And Diagnose Bad Front Axle.Replace Left	4.25	LINK KIT		2.00
	Front Axle Assemble.		NUT		2.00
-	Replace Front Sway Bar Linkages.		AXLE ASSEMBLY		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge: 558.97		Labor Charge: 255.00			

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1311491

Problem: P.M. service.

Meter Reading: 64634	Labor	Parts
In Date: 11/14/2013	Hours	Quantity
Close Date: 11/27/2013	Description	
- Perform Pm Service.	10.75	SHOP SUPPLIES 1.00
- Install New Rear Brake Pads And Resurface Both Rear Brake Rotors.Replace Both Failed Rear Calipers With New.Install New Rear Perking Brake Shoes.Flush Brake Fluid And Bleed System.		Caliper w/ Pads & Hdwr - R/Rr (Eclipse) 1.00 BATTERY 1.00 BRAKE PADS D1012 1.00 NAPAGOLD FUEL FILTER 1.00
- Test Starting And Charging System.Battery Failed Loadtest After Recharge.Replace Failed Battery With New.		5W20 ENGINE OIL 7.00 WIPER BLADE 2.00 NAPAGOLD FUEL FILTER 1.00 NAPAGOLD AIR FILTER 1.00
- Inspect And Service Auxiliary Fuel Tank.Replace Fuel Filter With New.		Caliper w/ Pads & Hdwr - L/Rr (Eclipse) 1.00
- Inspect And Service Power Winch.		REMAN BRAKE SHOES 1.00
- Shop Supplies		NAPAGOLD OIL FILTER 1.00
Parts Charge: 381.71	Labor Charge: 645.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1406798

Problem: Pm service.Winch inop.Transfer tank pump inop.

Meter Reading: 72012	Labor	Parts	Quantity
In Date: 07/10/2014	Hours	Description	Quantity
- P.M. Service.	19.25	WIPER BLADE	2.00
- Check Noise Coming From Engine Area.Replace Defective Belt Tensioner,And Three Idler Pulleys And Serpentine Belt.		IDLER PULLEY	2.00
- Replace Front Brake Rotors,And Brake Pads.Service And Lube Calipers.Flush And Bleed System And Test Drive.		5W20 ENGINE OIL	7.00
- Replace And Balance Four New Tires.Diagnose Tire Pressure Light.Replace Right Rear Pressure Sensor.		DR BLT TENSIONER ASSY	1.00
- Diagnose Inop Aux Fuel Pump.Replace Circuit Breaker And Inline Fuse Holder.Inspect And Service System.		USED FIRE X REFURBISHED	1.00
- Diagnose Inop Winch,Gears And Motor Rusted From Water Intrusion.Replace Winch.		TPMS SENSOR	1.00
- Complete Alignment.Test Drive.		VR8000 WINCH	1.00
- Shop Supplies		FUSE HOLDER	1.00
		LT245 70R17 KELLY MT/R	4.00
		NAPAGOLD FUEL FILTER	1.00
		IDLER PULLEY	1.00
		DRAIN PLUG	1.00
		BRAKE ROTOR ONLY	2.00
		STG WHEEL COV - FORD	1.00
		NAPAGOLD OIL FILTER	1.00
		WASHER FLUID CONCENTR	1.00
		NAPAGOLD FUEL FILTER	1.00
		NAPAGOLD AIR FILTER	1.00
		BRAKE PADS	1.00
		SHOP SUPPLIES	1.00
		BRAKE FLUID QT	1.00
		SERPENTINE BELT	1.00
		TIRE DISPOSAL FEE	4.00
		BRAKE CLEANER	1.00
Parts Charge:	2,756.95	Labor Charge:	1,155.00

Workorder: 1407160

Problem: weld winch bolts

Meter Reading: 71903	Labor	Parts	Quantity
In Date: 07/21/2014	Hours	Description	Quantity
- Weld Winch Bolts	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1410467

Problem: Check over for brake sticking.

Meter Reading: 75367 In Date: 10/20/2014	Close Date: 01/27/2015	Labor Hours	Description	Parts	Quantity
- Resurface Front Brake Rotors.Replace Front Pads And Calipers And Hoses.Flush And Bleed System.		25.25	5W20 ENGINE OIL		7.00
- Diagnose Noise Coming From Drivetrain.R&R Defective Transfer Case.Replace Front Drive Shaft 'U' Joints.			CLOCK SPRING		1.00
- Replace Failed Left Front Hub Assemble.			NAPAGOLD FUEL FILTER		1.00
- Diagnose Airbag Light. B2293.Perform Pin Point Test.Replace Defective Clock Spring.			SYN-ATF TRANS FLUID S		16.00
- P.M. Service.			SPARK PLUG		8.00
- Inspect And Service Aux. Fuel Tank.			HUB BEARING ASSEMBLY		1.00
- Service Transmission.Flush And Frefill System.			KA8A THROTTLE BODY- U		1.00
- Replace Eight Spark Plugs.			408 FUEL INJECTION CL		1.00
- Service And Clean Throttle Body.Flush Induction System.			OIL DRAIN PLUG		1.00
- Rotate And Balance All Tires.			SHOP SUPPLIES		1.00
- Shop Supplies			CENTER CAP		1.00
			Freight Charge		1.00
			FT1167 TRANS FILTER L		1.00
			SYN-ATF TRANS FLUID S		2.00
			Caliper w/ Hardware - Left Front (Eclips		1.00
			B FLUID DOT 3-32OZ		2.00
			NAPAGOLD OIL FILTER		1.00
			BRAKE CLEANER		1.00
			U-JOINT		2.00
			BRAKE HOSE		1.00
			DISC BRAKE PADS		1.00
			TRANSFER CASE ASM		1.00
			BRAKE HOSE		1.00
			Caliper w/ Hardware - Right Front (Eclip		1.00
			WIPER BLADE		2.00
	Parts Charge: 2,689.50	Labor Charge: 1,515.00			

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1506627

Problem: Pm service.Horn,left turnsignal inop.Ac not cold.

Meter Reading: 80519		Labor		Parts	
In Date: 07/01/2015	Close Date: 07/21/2015	Hours	Description		Quantity
-	Pm Service.	9.75	NAPAGOLD OIL FILTER		1.00
-	Replace Cracked Left Tail Lamp Assembly And One Bulb.		BULB		1.00
-	Inspect And Service Auxiliary Fuel Tank.		FAN CLUTCH		1.00
-	Perform Engine Coolant Flush And Refill System.		WIPER BLADE		2.00
-	Diagnose For Ac Air Not Cold.Replace Defective Cooling Fan Clutch Assembly.		USED FIRE X REFURBISHED		1.00
-	Inspect And Service Winch.		PEAK GLOBAL		2.00
-	Rotate And Balance Allfour Tires.		SHOP SUPPLIES		1.00
-	Shop Supplies		TAIL LAMP ASSY		1.00
			NAPAGOLD FUEL FILTER		1.00
			5W20 ENGINE OIL		7.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 424.04		Labor Charge: 585.00			

Workorder: 1508248

Problem: Exhaust damage and check engine light on.

Meter Reading: 81653		Labor		Parts	
In Date: 08/18/2015	Close Date: 08/25/2015	Hours	Description		Quantity
-	Computer Diagnose For Check Engine Light On..P2195.Repair Exhaust Pipe.Clear Code With Scan Tool And Retest Oxygen Sensors..Test Drive Vehicle.	3.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 180.00			

Workorder: 1509546

Problem: Power steering problem.Check engine light on.

Meter Reading: 82901		Labor		Parts	
In Date: 09/22/2015	Close Date: 09/30/2015	Hours	Description		Quantity
-	Diagnose Steering Binding.Replace Defective Intermeadiate Steering Shaft.	4.50	SHAFT ASSYM		1.00
-	Diagnose Check Engine Light.P0132,P2195.Perform Pin Point Test.Replace Oxygen Sensor,Sensor 1,Bank One.Clear Codes And Test Drive.		SHOP SUPPLIES		1.00
-	Shop Supplies		SENSOR		1.00
Parts Charge: 435.62		Labor Charge: 270.00			

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1510176

Problem: No start

Meter Reading: 82949	Labor	Parts
In Date: 10/06/2015	Hours	Description
Close Date: 10/07/2015	Quantity	
- Tow From: Coconut And Hamlin (Loxahatchee) To: Lv Shop		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 104.15

Workorder: 1510215

Problem: Towed in.No start.

Meter Reading: 83483	Labor	Parts
In Date: 10/08/2015	Hours	Description
Close Date: 10/26/2015	Quantity	
- Computer Diagnose For No Start.Code P0193.Test And Replace Defective Fuel Pump Assembly,Fuel Pump Driver Module,Fuel Rail Pressure Sensor And Fuel Filter.Clear Code And Retest.		
	6.00	SHOP SUPPLIES 1.00
		FUEL MOTULE 1.00
		GASKET 1.00
		SENSOR 1.00
- Shop Supplies		
		NAPAGOLD FUEL FILTER 1.00
		FUEL PUMP 1.00
Parts Charge: 751.97	Labor Charge: 360.00	

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1513038

Problem: Pm service.Check muffler.

Meter Reading: 85699	Labor	Parts	
In Date: 12/30/2015	Hours	Description	Quantity
- Pm Service.	15.75	DISC BRAKE PADS	1.00
- Check Battery And Charging System.Battery Failed		75W140 FORD AXLE LUBE	3.00
- Loadtest After Recharge.Replace Defective Battery.		PTEX ULTRA GREY 3OZ	1.00
- Replace Both Rear Brake Rotors. And Brake Pads.Service Calipers.		IDLER PULLEY	2.00
- Inspect And Service Auxiliary Fuel Tank.		SEAL ASY	1.00
- Perform Rear Differential Service.Replace Defective Rear Pinnion Seal And Crush Spacer.		KIT SPAC	1.00
- Replace Two Defective Serpentine Belt Idler Pulleys.		BRAKE CLEANER	1.00
- Inspect And Service Winch.		BRAKE ROTOR	2.00
- Rotate And Balance All Four Tires.		FRICTION MODIFIER	1.00
- Check And Reattache Exhaust Pipe To Clamp And Weld Prep.		SHOP SUPPLIES	1.00
- Shop Supplies		SPACER	1.00
		NAPAGOLD OIL FILTER	8.00
		5W20 ENGINE OIL	7.00
		NAPAGOLD FUEL FILTER	1.00
		BATTERY	1.00
		NAPAGOLD AIR FILTER	1.00
		20" WIPER BLADE	2.00
Parts Charge:	470.42	Labor Charge:	945.00

Workorder: 1601135

Problem: Enging misfires.Runs rough.

Meter Reading: 86028	Labor	Parts	
In Date: 02/02/2016	Hours	Description	Quantity
- Computer Diagnose For Check Engine Light On.Code P0303 And P0316.Pinpoint Test And Replace Defective #3 Ignition Coil.Clear Codes And Test Drive.	3.00	SHOP SUPPLIES	1.00
- Shop Supplies		FORD IGNITION COIL	1.00
Parts Charge:	70.75	Labor Charge:	180.00

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1605359

Problem: P.M. service and check engine light runs rough and at times will not crank on first try.

Meter Reading: 90383		Labor		Parts	
In Date: 05/24/2016	Close Date: 06/15/2016	Hours	Description		Quantity
-	P.M. Service.	11.50	ALTERNATOR		1.00
-	Diagnose Check Engine Light.P0302.Perform Pinpoint		LT245/70R17 M/T DESTINATION		2.00
-	Test.Replace #2 Coil.Clear Codes.		5W20 ENGINE OIL		7.00
-	Diagnose Starting System.Replace Defective Starter		FORD IGNITION COIL		1.00
-	Assemble.Horn Inop.Test And Replace Horn.		NAPAGOLD FUEL FILTER		1.00
-	Inspect And Service Aux Fuel System.		NAPAGOLD OIL FILTER		1.00
-	Replace Two Tires,Rotate And Balance All Four.		USED FIRE X REFURBISHED		1.00
-	Test Battery And Charging System,Below Specs.Replace		20" WIPER BLADE		2.00
-	Alternator Assemble.		brake pedal pad		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			STARTER MOTORCRAFT		1.00
			CENTER CAP		1.00
			HORN ASY		1.00
Parts Charge: 1,207.44		Labor Charge: 690.00			

Workorder: 1608435

Problem: P.M. Service.Check a/c,turn signals and cruise control operation.

Meter Reading: 92497		Labor		Parts	
In Date: 08/16/2016	Close Date:	Hours	Description		Quantity
-					
Parts Charge: 0.00		Labor Charge: 0.00			

Workorder: 1608824

Problem: check for intermittent no start

Meter Reading: 92996		Labor		Parts	
In Date: 08/24/2016	Close Date: 08/30/2016	Hours	Description		Quantity
-	Check Starting Replace Starter	2.50	SHOP SUPPLIES		1.00
-	Remove Tool Box To Transfer To New Vehicle		REMAN STARTER		1.00
-	Shop Supplies				
Parts Charge: 157.26		Labor Charge: 150.00			

1/3/2017
12:22:59PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169413 2007 FORD F150 Pickup, 1/2 Ton, 4X4, W/8 Ft Bed

Workorder: 1609109

Problem: Transition Prep Charge

Meter Reading: 92996

Labor

Parts

In Date: 08/31/2016

Close Date: 08/31/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **26,424.93**

Total Labor Charges: **19,933.50**

Total Comm. Charges: **430.30**