10169494 2007 FORD E350 Van, 1 Ton, Cargo, Shelves, For Locksmith

Problem:	741526 PRE-DELIVE	Meter: RY INSPE	0 CTION			In Date:	07/16/2007	Closed:	07/16/20	007
- Pre-delivery	Inspection									
	Hou :	rs 2.00		Labor:	110.00	Parts:	0.00	Total:	110.00	
Workorder: Problem:	833062 P.M SERVIC	Meter: E,CK WINI	2460 DSHIELD WA	ASHERS		In Date:	01/22/2008	Closed:	01/30/20	800
- Perform Pm	Service Comp	olete			Parts Li	st				Qty
• .	Balance All 4 T	ires To Co	rrect Vibratio	n Over	Shop Su	pplies				1.00
45mph	,				1372 Oi	I Filter Frm	Ph2 Wix 513	372		1.00
- Shop Suppli	es				5w20 En	igine Oil				7.00
	Hou :	rs 5.00		Labor:	300.00	Parts:	20.65	Total:	320.65	
Workorder: Problem:	840844 P.M SERVIC	Meter: E,SEE NO	4849 TE			In Date:	07/02/2008	Closed:	07/07/20	800
- Pm Service					Parts Li	st				Qty
	gh Speed Bala				Shop Su	pplies				1.00
•	ires.inspectr/f Tire For Lek,repair Tire W/patch.retest Ok.					Air Filter Lb	of Af1615 Wix	46418		1.00
- Shop Suppli	es				1372 Oi	I Filter Frm	Ph2 Wix 513	372		1.00
					G8018 F	uel Filter L	of G6593 Wix	33595		1.00
					5w20 En	ngine Oil				7.00
					31-20 W	iper Blades	20" Blade			2.00
	Hou :	rs 6.00		Labor:	360.00	Parts:	42.54	Total:	402.54	
Workorder: Problem:	848509 L/R TIRE FLA	Meter:	7745			In Date:	12/23/2008	Closed:	12/24/20	800
Danair I /ros	ar Tire.				Parts Li	st				04
 Repair L/rea 										Qty
- Repair L/rea					Shop Su	pplies				1.00
•	es	rs 1.00		Labor:	-	pplies Parts:	2.00	Total:	62.00	-
- Shop Suppli	es	Meter:	7893	Labor:	-		2.00	Total:	62.00	1.00
- Shop Suppli	Hou : 932288	Meter:	7893	Labor:	-	Parts:				1.00
- Shop Suppli Workorder: Problem: - Pm Service - Rotate And	Hou : 932288 PM SERVICE	Meter:			60.00 Parts Li	Parts: In Date: st pplies	01/05/2009	Closed:		1.00 009 Qty 1.00
- Shop Suppli Workorder: Problem: - Pm Service	Hou : 932288 PM SERVICE	Meter:			Parts Lis Shop Su 1372 Oi	Parts: In Date: st pplies I Filter Frm	01/05/2009 Ph2 Wix 51	Closed:		1.00 009 Qty 1.00 1.00
- Shop Suppli Workorder: Problem: - Pm Service - Rotate And	Hou : 932288 PM SERVICE	Meter:			Parts Lis Shop Su 1372 Oi G8018 F	Parts: In Date: st applies I Filter Frm	01/05/2009	Closed:		1.00 009 Qty 1.00 1.00
- Shop Suppli Workorder: Problem: - Pm Service - Rotate And	Hou : 932288 PM SERVICE	Meter:			Parts Li: Shop Su 1372 Oi G8018 F 5w20 En	Parts: In Date: st ppplies I Filter Frm fuel Filter Lingine Oil	01/05/2009 Depth of Ph2 Wix 513 Of G6593 Wix	Closed:		1.00 009 Qty 1.00 1.00 1.00 7.00
- Shop Suppli Workorder: Problem: - Pm Service - Rotate And	Hou : 932288 PM SERVICE	Meter:			Parts Li. Shop Su 1372 Oi G8018 F 5w20 En 31-20 W	Parts: In Date: st pplies I Filter Frm fuel Filter Lingine Oil iper Blades	01/05/2009 Ph2 Wix 513 of G6593 Wix 20" Blade	Closed: 372 33595		1.00 O09 Qty 1.00 1.00 1.00 7.00 2.00
- Shop Suppli Workorder: Problem: - Pm Service - Rotate And	932288 PM SERVICE	Meter:		en.	Parts Li. Shop Su 1372 Oi G8018 F 5w20 En 31-20 W	Parts: In Date: st pplies I Filter Frm fuel Filter Li gine Oil iper Blades ex Refurbe	01/05/2009 Depth of Ph2 Wix 513 Of G6593 Wix	Closed: 372 33595 hers		1.00 009 Qty 1.00 1.00 1.00 7.00

Workorder: Problem:	941047 P.M service	Meter: , check traile	11119 er plug		lı	n Date:	07/21/2009	Closed:	07/30/20	009
- P.m service					Parts List					Qty
- Trace short	in trailer plug	, repair traile	er plug conne	ector &	Shop Supp	plies				1.00
replace fuse.					1372 Oil F	Filter Frm	n Ph2 Wix 513	372		1.00
- Rotate & ba		tires.			5w20 Engi	ine Oil				7.00
- Shop Suppli	ies				Used Fire	x Refurbe	d Fire Extings	hers		1.00
	Ho:	urs 6.00		Labor:	360.00	Parts:	32.68	Total:	392.68	
Workorder: Problem:	945950 Battery goes	Meter: s dead.	13227		lı	n Date:	11/13/2009	Closed:	11/20/20	009
	Test battery and charging system.recharge and retest									Qty
•	attery, failed load test replace battery.					plies				1.00
- Test cig lighter circuit & replace blown fuse.					Group 65	Battery (r	ntc Bxt-65-850))		1.00
- Shop Suppli		4 = 0					100.10		0.4.0.4.0	
	Ho:	urs 1.50		Labor:	90.00	Parts:	129.43	Total:	219.43	
Workorder: Problem:	947051 ABS light on	Meter:	13659		lı	n Date:	12/15/2009	Closed:	12/31/20	009
- Diagnose Al	bsliht stays or	n.replace de	fective L/f sp	peed	Parts List					Qty
sensor.	•	n.replace de	fective L/f sp	peed	Parts List Shop Supp					Qty 1.00
sensor. - P.m. Service	Э.	·	fective L/f sp	peed	Shop Supp	plies	n Ph2 Wix 513	372		•
sensor P.m. Service - Rotate and I	e. balance all tir	es.	fective L/f sp	peed	Shop Supp 1372 Oil F	plies Filter Frm	n Ph2 Wix 513 of Af1615 Wix			1.00
sensor P.m. Service - Rotate and I - Complete w	e. balance all tir heel alignmer	es.	fective L/f sp	peed	Shop Supp 1372 Oil F	plies Filter Frm ir Filter Lt				1.00 1.00
sensor P.m. Service - Rotate and I	e. balance all tir heel alignmer	es.	fective L/f sp	peed	Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi	plies Filter Frm ir Filter Lt ine Oil				1.00 1.00 1.00
sensor P.m. Service - Rotate and I - Complete w	e. balance all tir heel alignmer	es.	fective L/f sp	peed	Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi 31-20 Wip	plies Filter Frm ir Filter Lt ine Oil er Blades	of Af1615 Wix			1.00 1.00 1.00 7.00
sensor P.m. Service - Rotate and I - Complete w	e. balance all tir heel alignmer ies	es.	fective L/f sp		Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi 31-20 Wip	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp	of Af1615 Wix s 20" Blade	46418	709.58	1.00 1.00 1.00 7.00 2.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli	e. balance all tir heel alignmer ies	es. nt. urs 9.50 Meter:	17112	Labor:	Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi 31-20 Wip Left Front 570.00	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp	of Af1615 Wix s 20" Blade beed Sensor	46418	709.58	1.00 1.00 1.00 7.00 2.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a	es. nt. urs 9.50 Meter:	17112	Labor:	Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi 31-20 Wip Left Front 570.00	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts: n Date:	of Af1615 Wix s 20" Blade beed Sensor 139.58	46418 Total:		1.00 1.00 1.00 7.00 2.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem:	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a	es. nt. urs 9.50 Meter: also see not	17112	Labor:	Shop Supp 1372 Oil F Ca8039 Ai 5w20 Engi 31-20 Wip Left Front 570.00	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts:	of Af1615 Wix s 20" Blade beed Sensor 139.58	46418 Total:		1.00 1.00 1.00 7.00 2.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem: - P.m. Service	e. balance all tir heel alignmer ies Ho : 1006492 Pm service a	es. nt. urs 9.50 Meter: also see note	17112 es on lighter	Labor:	Shop Supplement of Shop Shop Supplement of Shop Shop Supplement of Shop Shop Shop Shop Shop Shop Shop Shop	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts: n Date:	of Af1615 Wix s 20" Blade beed Sensor 139.58	Total:		1.00 1.00 1.00 7.00 2.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem: - P.m. Service - Flush and re	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a e. efill trans. sys:	es. nt. urs 9.50 Meter: also see note	17112 es on lighter	Labor:	Shop Supplement of the	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts: n Date:	of Af1615 Wix s 20" Blade beed Sensor 139.58	Total: Closed:		1.00 1.00 1.00 7.00 2.00 1.00 010 Qty 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem: - P.m. Service - Flush and re - Check cigar	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a e. efill trans. sys:	es. nt. urs 9.50 Meter: also see note	17112 es on lighter	Labor:	Shop Supplement of the	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts: n Date: plies Filter Frm el Filter L	of Af1615 Wix 6 20" Blade beed Sensor 139.58 06/21/2010	Total: Closed:		1.00 1.00 1.00 7.00 2.00 1.00 010 Qty 1.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem: - P.m. Service - Flush and re - Check cigar	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a e. efill trans. sys:	es. nt. urs 9.50 Meter: also see note	17112 es on lighter	Labor:	Shop Supplement of Shop Shop Supplement of Shop Shop Shop Shop Shop Shop Shop Shop	plies Filter Frm ir Filter Lt ine Oil er Blades Wheel Sp Parts: n Date: plies Filter Frm el Filter L ine Oil	of Af1615 Wix 6 20" Blade beed Sensor 139.58 06/21/2010 In Ph2 Wix 513 bf G6593 Wix	Total: Closed:	06/24/20	1.00 1.00 1.00 7.00 2.00 1.00 010 Qty 1.00 1.00
sensor P.m. Service - Rotate and I - Complete w - Shop Suppli Workorder: Problem: - P.m. Service - Flush and re - Check cigar	e. balance all tir heel alignmer ies Hot : 1006492 Pm service a e. efill trans. sys:	es. nt. urs 9.50 Meter: also see note	17112 es on lighter	Labor:	Shop Supplement of the state of	plies Filter Frm ir Filter Lk ine Oil er Blades Wheel Sp Parts: n Date: plies Filter Frm el Filter L ine Oil ans Fluid	of Af1615 Wix 6 20" Blade beed Sensor 139.58 06/21/2010 In Ph2 Wix 513 bf G6593 Wix	Total: Closed:	06/24/20	1.00 1.00 1.00 7.00 2.00 1.00 010 Qty 1.00 1.00 1.00 7.00

Workorder: Problem:	1013411 P.M. serv	Meter:	20261			In Date:	12/06/2010	Closed:	12/14/2010
- Perform pm		ioo ana oigoroi	io iigiitoi iiiopi		Parts L	iet			Qty
- Rotate and I		four tires			Shop St				1.00
		ioui tiles.					n Ph2 Wix 513	272	1.00
- Shop Suppli	U S					1.00			
							of Af1615 Wix	40418	
						ngine Oil	00" Di- 1-		7.00
						/iper Blades			2.00
	Houre 5.00						d Fire Extings		1.00
	H :	Hours 5.00		Labor:	300.00	Parts:	47.47	Total:	347.47
Workorder: Problem:	1100058 Flat tire o	Meter: n L/R	20387			In Date:	12/20/2010	Closed:	01/03/2011
- 429 Park Pla	ace (fac M	gmt Central)							
	H :	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1100060 TIRES	Meter:	20387			In Date:	12/23/2010	Closed:	01/03/2011
- 429 Park Pla	ace								
	H :	Hours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1105795 Pm service	Meter: ce and stalls se	23401 e notes.			In Date:	06/01/2011	Closed:	06/22/2011
- P.m. Service	Э.				Parts L	ist			Qty
- Replace and	d balance f	our tires.			Shop St	upplies			1.00
- Complete w	heel alignn	nent.			1372 O	1.00			
- Replace cer	nter brake l	ight bulb.			G8018 I	33595	1.00		
- Shop Suppli	es				5w20 Eı	ngine Oil			7.00
						_	d Fire Extings	hers	1.00
						/iper Blades	•		2.00
						•	5r16 Wrangle	r Sr-a F	4.00
						posal Fee	or ro rrraingle	. O. u _	4.00
						alve Stem			4.00
	H ·	Hours 8.75		Labor:	525.00		706.75	Total:	1,231.75
Workorder: Problem:	1108652 A/C inop,	Meter:	24345 utlet.			In Date:	08/16/2011	Closed:	08/22/2011
	·	nd leak test.rec		I	Parts L	ist			Qty
		ator,expansion			Shop St				1.00
with new.clear		ousing.vacume			•	Refrigerant			2.00
to specs.	41	•• •				Semgerani Sil R134a A	/c Oil (tei)		1.00
 Test power of and replace of 		it for power an	d ground.test f	or short			70 Oii (181)		1.00
		iui iiew.			•	ator Core			
- Shop Suppli	E2				Orfice T	upe			1.00
		January 7.05		ا ما ما	Dryer	D = -4-	202.00	T-4-1	1.00
	! :	Hours 7.25		Labor:	435.00	Parts:	393.06	ı otal:	828.06

	1112821 Meter:	26955	In Date	e: 12/05/2011	Closed:	12/15/201	1
	P.M. service and ciger li	gnter mop.					
- Perform pm s			Parts List				Qty
	alance all four tires.		Shop Supplies				.00
- Shop Supplie	S		1372 Oil Filter			.00	
			Ca8039 Air Filte		46418		.00
			5w20 Engine Oil				.00
			Syn/atf Trans Fl	•			.00
			31-20 Wiper Bla				2.00
			Used Firex Refu	•			.00
	Hours 5.00 :	Labor:	300.00 Pa	ts: 57.99	Total:	357.99	
Workorder:	1205274 Meter:	30380	In Date	e: 06/05/2012	Closed:	06/19/2012	2
Problem:	Pm service and request	for detail vehicle.					
- P.m. Service.			Parts List			(Qty
- Rotate and ba	alance all tires.		Big G Degrease	Stock# 485180	002	1	.00
- Shop Supplie	S		Shop Supplies			1	.00
			1372 Oil Filter	Frm Ph2 Wix 51	372	1	.00
			5w20 Engine Oil			7	.00
			31-20 Wiper Bla	des 20" Blade		2	2.00
	Hours 5.00	Labor:	300.00 Pa	rts: 38.48	Total:	338.48	
Problem:	1205630 Meter: 1 - Detail Vehicle Wash icle Wash Ticket(s) Issu	. ,	In Date	e: 06/13/2012	Closed:	06/13/2012	2
i Botan von	Hours 0.00	Labor:	0.00 Pa	rts: 0.00	Total:	0.00	
	:	Luboi.	0.00	10. 0.00	i otai.	0.00	
	1208632 Meter: Has to jump start all the	32246 time.	In Date	9: 09/11/2012	Closed:	09/17/2012	2
- Test starting a	and charging system.ba	ttery failed load test	Parts List			(Qty
	eplace failed battery wit		Shop Supplies				.00
- Shop Supplie	S		Group 65 Batter	/ (mtc Bxt-65-85	0)	1	.00
	Hours 1.00	Labor:	•	rts: 132.05	*	192.05	
	1211632 Meter: P.M. service and detail.	33558	In Date	e: 12/03/2012	Closed:	12/14/2012	2
- Perform pm s	ervice.		Parts List			(Qty
	alance all four tires.		5w20 Engine Oil				.00
- Shop Supplie	S		Ph2 Oil Filter Lb			1	.00
			31-20 Wiper Bla				2.00
			Used Firex Refu				.00
			G8018 Fuel Filte				.00
			Shop Supplies	01			.00
	Hours 5.00	Labor:		rts: 69.11	Total:	369.11	
	:						

Workorder: Problem:	1212089 1 - Detail Vehi	Meter: cle Wash	33558 Ticket(s) Iss	sued		In Date:	12/14/2012	Closed:	12/14/2012
- 1 - Detail Ve	hicle Wash Ticl	ket(s) Issu	ıed						
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder: Problem:	1305310 P.M. service.	Meter:	36484			In Date:	05/30/2013	Closed:	06/11/2013
- P.m. Service) .				Parts Li	st			Qt
- Repack and	and adjust fron	it wheel b	earings.		5w20 Er	ngine Oil			7.00
Rotate and balance all tires.					Napago	ld Oil Filter			1.00
- Shop Suppli	es				31-20 W	/iper Blades	20		2.00
					Washer	FI			1.00
					Shop Su	ıpplies			1.00
	Hours	s 6.00		Labor:	360.00	Parts:	39.85	Total:	399.85
Workorder:	1310804	Meter:	39263			In Date:	10/29/2013	Closed:	10/31/2013
Problem:	Rear cargo do	ors will no	t open from	outside.					
- Replace inor	o rear cargo do	or handle	assemble.		Parts Li	st			Qt
- Shop Suppli	es				doorhan	dle real			1.00
					Shop Su	upplies			1.00
	Hours :	s 1.00		Labor:	60.00	Parts:	144.43	Total:	204.43
Workorder: Problem:	1312128 Pm service.	Meter:	39732			In Date:	12/04/2013	Closed:	12/13/2013
- Perform pm	service.				Parts List (
•	ew tires to the f	ront whee	ls.nitrogen fi	ill and	5w20 Er	ngine Oil			7.00
balance all fou	r.		J			ld Oil Filter			1.00
- Inspect and	replace failed d	Iriver side	ac vent with	new.	20" Wip				2.00
- Perform whe	el alignment co	omplete.				re X Refurbi	ished		1.00
- Shop Suppli	es				Napago	ld Fuel Filte	r		1.00
					. •	192 Lt245-7			2.00
					a\c vent	louvre asy			1.00
					Shop Su	-			1.00
						oosal Fee			2.00
					THE DIS	Jusai i ee			2.0

- Computer diagnose for check engine light on pinpoint test and replace # 3 failed ignition coil with new.replace all eight spark plugs with new.clear codes with scan tool and roadtest Perform induction service and clean trottle body power flush all fuel injectors and fuel lines.clear codes with scan tool and roadtest Shop Supplies Hours 8.00 Labor: Hours 8.00 Labor: Workorder: 1405316 Problem: P.M. service and check for nails in tires. - P.m. Service Replace two tires, rotate and balance all four Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16 Tr416 Valve Stem	06/17/2014 Qty 7.00 1.00 1.00 2.00
and replace # 3 failed ignition coil with new.replace all eight spark plugs with new.clear codes with scan tool and roadtest. - Perform induction service and clean trottle body.power flush all fuel injectors and fuel lines.clear codes with scan tool and roadtest. - Shop Supplies - Shop Supplies - Hours 8.00 - Labor: Workorder: 1405316 - Problem: P.M. service and check for nails in tires. - P.m. Service Replace two tires, rotate and balance all four Shop Supplies - Shop Supplies - Parts List - Napagold Oil Filter - Napagold Fuel Filter - Used Fire X Refurbished - Wiper Blade - Mac Wite Lithium Gres - 179747492 Lt245-75r16	1.00 1.00 1.00 8.00 1.00 1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
Spark plugs with new.clear codes with scan tool and roadtest. - Perform induction service and clean trottle body.power flush all fuel injectors and fuel lines.clear codes with scan tool and roadtest. - Shop Supplies Hours 8.00 Hours 8.00 Eabor: Workorder: 1405316 Problem: P.M. service and check for nails in tires. - P.m. Service. - Replace two tires, rotate and balance all four. - Shop Supplies Parts List Sw20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 1.00 8.00 1.00 1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
Ferform induction service and clean trottle body.power flush all fuel injectors and fuel lines.clear codes with scan tool and roadtest. Saprk Plug Silicone Spray 10oz Shop Supplies Hours 8.00 Labor: 480.00 Parts: 186.07 Total: 6 Workorder: 1405316 Problem: P.M. service and check for nails in tires. P.m. Service. Replace two tires,rotate and balance all four. Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 8.00 1.00 1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
and roadtest Shop Supplies Hours 8.00 Labor: 480.00 Parts: 186.07 Total: 6 Workorder: 1405316 Problem: P.M. service and check for nails in tires. - P.m. Service Replace two tires,rotate and balance all four Shop Supplies Napagold Oil Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	8.00 1.00 1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
- Shop Supplies Hours 8.00 Labor: 480.00 Parts: 186.07 Total: 6 Workorder: 1405316 Problem: P.M. service and check for nails in tires. - P.m. Service Replace two tires, rotate and balance all four Shop Supplies Parts List Sw20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
Shop Supplies Hours 8.00 Labor: 480.00 Parts: 186.07 Total: 6 Workorder: 1405316 Problem: P.M. service and check for nails in tires. - P.m. Service Replace two tires,rotate and balance all four Shop Supplies Parts List Sw20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 666.07 06/17/2014 Qty 7.00 1.00 1.00 2.00
Hours 8.00 Labor: 480.00 Parts: 186.07 Total: 6 Workorder: 1405316 Meter: 42866 In Date: 06/02/2014 Closed: 06 Problem: P.M. service and check for nails in tires. Parts List - Replace two tires,rotate and balance all four Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	06/17/2014 Qty 7.00 1.00 1.00 2.00
Problem: P.M. service and check for nails in tires. - P.m. Service. - Replace two tires,rotate and balance all four. - Shop Supplies Parts List 5w20 Engine Oil Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	Qty 7.00 1.00 1.00 1.00 2.00
- P.m. Service Replace two tires,rotate and balance all four Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	7.00 1.00 1.00 1.00 2.00
- Replace two tires,rotate and balance all four. - Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	7.00 1.00 1.00 1.00 2.00
- Shop Supplies Napagold Oil Filter Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 1.00 1.00 2.00
Napagold Fuel Filter Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 1.00 2.00
Used Fire X Refurbished Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	1.00 2.00
Wiper Blade Mac Wite Lithium Gres 179747492 Lt245-75r16	2.00
Mac Wite Lithium Gres 179747492 Lt245-75r16	
179747492 Lt245-75r16	1.00
	2.00
	2.00
5068 Pentrating Oil	1.00
Shop Supplies	1.00
Tire Disposal Fee	2.00
Hours 6.00 Labor: 360.00 Parts: 527.84 Total: 8	887.84
	12/24/2014
Problem: Pm service.Power outlet inop.	
- Pm service. Parts List	Qty
- Replace rear brake pads and both rear calipers.resurface 5w20 Engine Oil	7.00
both rear brake rotors and bleed brake system.roadtest. Napagold Oil Filter	1.00
- Pressure test and inspect cooling system.reverse flush and Napagold Air Filter renew engine coolant.	1.00
- Rotate and balance all four tires. Wiper Blade	2.00
- Test power outlet inop and replace open 20 amps fuse.	1.00
- Shop Supplies B Fluid Dot 3-32oz	1.00
Peak Global	2.00
Loaded Cal	1.00
Loaded Cal	1.00
Brake Pads	1.00
Shop Supplies	1.00
Hours 11.50 Labor: 690.00 Parts: 340.66 Total: 1	1,030.66

Workorder: Problem:	1503892 Cigarette lig	Meter: hter inop.	48547			In Date:	04/15/2015	Closed:	04/30/20)15
- Test for sho	rt and replace	e open cigar	ette fuse.							
	Ho :	urs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	
Workorder: Problem:	1506180 Pm service.	Meter: Check ac air	49543 flow,powe	r outlet.batte	ery and o	In Date: driver side ar	06/19/2015 rm rest	Closed:	07/01/20)15
- P.m. Service	Э.				Parts L	.ist				Qty
- Test battery	and charging	g system.rep	lace bad ba	attery.	5w20 E	ngine Oil				7.00
- Replace left outlet fuse.						old Oil Filter oer Blade				1.00 2.00
	- Diagnose a/c blows only through defrost.replace vacuum ines,check valve and reservior.									1.00
•					Hide Av	way Strob				1.00
	Rotate and balance all tires.R&r drivedr door panel and fabricate and repair arm rest.						ished			1.00
- Shop Suppli	•				Wd40 1					1.00
						r Fluid Conce	entr			1.00
					Valve A					1.00
						n Resevoir				1.00
	Ho	urs 9.75		Labor:	Shop S 585.00	• •	277.61	Total:	862.61	1.00
Workorder: Problem:	1600044 Pm service.	Meter:	51405			In Date:	01/04/2016	Closed:	01/20/20)16
- Pm service.					Parts L	.ist				Qty
- Check and r			lamp bulbs	also .	5w20 E	ngine Oil				7.00
replace cigare	_	_			Napago	old Oil Filter				1.00
- Rotate and b		ur tires.			Napago	old Fuel Filte	r			1.00
- Shop Suppli	es				20" Wip	er Blade				2.00
					Bigg De	egreaser				1.00
					Bulb					2.00
					Ring					1.00
					Shop S					1.00
	Ho :	urs 6.00		Labor:	360.00	Parts:	56.80	Total:	416.80	
Workorder: Problem:	1601491 Rear door w	Meter: vill not open.l	51788 Difficult to f	uel vehicle.		In Date:	02/11/2016	Closed:	02/24/20)16
- Inspect and cargo door late			door and ri	ght front	Parts L		ontrol			Qty
- Inspect cani			tion.replace	canister		tch remote co	UNTION			1.00
vent solenoid					Remote	e Canister				1.00
1						tor Assembly	ı,			1.00
- Shop Suppli	es				Shop S	-	y			1.00
	Ho :	urs 5.00		Labor:	300.00	• •	375.20	Total:	675.20	1.00

Workorder: Problem:	1606769 P.M. service	Meter: and cigar li	53923 ghter inop a	and detail.	In	Date:	07/05/2016	Closed:	07/18/2016
- P.m. Service			- ·		Parts List				Qt
- Check and re	eplace power	outlet fuse.	i		5w20 Engir	ne Oil			7.0
- Rotate and b	-				Napagold C				1.0
- Shop Suppli					20" Wiper E		2.0		
					Used Fire X		ished		1.0
					Drain Plug				1.0
					Shop Suppl	lies			1.0
	Hou	urs 5.50		Labor:	330.00		48.65	Total:	378.65
Workorder: Problem:	1606944 1 - Detail Ve	Meter:	53758 Ticket(s) Iss	sued	In	Date:	07/11/2016	Closed:	07/11/2016
- 1 - Detail Ve		` '	ıed						
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1700979	Meter:	56527		In	Date:	01/31/2017	Closed:	02/23/2017
	DM contino	and book d	oor inop.po	wer outlet in	nop, noise fr	om unde	er van while dr	iving.	
Problem:	F.IVI. SETVICE	and back u							
- P.m. Service		and back d	7		Parts List				Qt
- P.m. Service - Replace leal	e. king front sho	cks.			Cover				1.0
- P.m. Service - Replace leal - Replace rea	e. king front sho r cargo door u	cks. upper and lo	ower latch		Cover 5w20 Engir				1.0 7.0
- P.m. Service - Replace leal - Replace rea assembly.repla	e. king front sho r cargo door u ace lighter so	cks. upper and lo cket.replace	ower latch e left visor re		Cover 5w20 Engir Napagold C	Dil Filter			1.0 7.0 1.0
- P.m. Service - Replace leal	e. king front sho r cargo door u ace lighter so ont brake roto	cks. upper and lo cket.replace ors,replace p	ower latch e left visor re		Cover 5w20 Engir Napagold C Napagold F	Dil Filter Fuel Filte	r		1.0 7.0 1.0 1.0
- P.m. Service - Replace leal - Replace rea assembly.repla - Resurface fr	e. king front sho r cargo door u ace lighter so ont brake roto and bleed sys	cks. upper and lo cket.replace ors,replace p stem.	ower latch e left visor re		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E	Dil Filter Tuel Filte Blade			1.0 7.0 1.0 1.0 2.0
- P.m. Service - Replace leal - Replace rea assembly.repla - Resurface fr calipers.flush a	e. king front sho r cargo door u ace lighter so ont brake roto and bleed sys d balance four	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu	Dil Filter Tuel Filte Blade Iid Conce			1.0 7.0 1.0 1.0 2.0 1.0
- P.m. Service - Replace leal - Replace rea assembly.repla - Resurface fr calipers.flush a	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock	Dil Filter Fuel Filte Blade Iid Conco ks	entr		1.0 7.0 1.0 1.0 2.0 1.0 2.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra	Dil Filter Fuel Filte Blade Iid Conco ks ke Calip	entr er		1.0 7.0 1.0 1.0 2.0 1.0 2.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra	Dil Filter Fuel Filte Blade Iid Conco ks ke Calip ke Calip	entr er		1.0 7.0 1.0 1.0 2.0 1.0 2.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot	Dil Filter Fuel Filte Blade iid Conco ks ke Calip ke Calip 3-32oz	entr er er		1.0 7.0 1.0 1.0 2.0 1.0 2.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E	Dil Filter Fuel Filte Blade Iid Conco ks ke Calip ke Calip 3-32oz Brake Clr	entr er er		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16	Dil Filter Fuel Filte Blade Iid Conco ks ke Calip ke Calip 3-32oz Brake Clr	entr er er		1.0 7.0 1.0 1.0 2.0 1.0 2.0 1.0 1.0 4.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring	Dil Filter Fuel Filte Blade Iid Conco ks ke Calip ke Calip 3-32oz Brake Clr	entr er er		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket	Dil Filter Tuel Filte Blade Iid Conce ks ke Calip ke Calip 3-32oz Brake Clr	entr er er nr		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch	Dil Filter Fuel Filte Blade Iid Conce ks ke Calip ke Calip 3-32oz Brake Clr 6	entr er er nr		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch Door Handl	Dil Filter Fuel Filte Blade Iid Conce ks ke Calip ke Calip 3-32oz Brake Clr 6	entr er er nr		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0 4.0 1.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch Door Handl Brake Pad	Dil Filter Fuel Filte Blade Iid Conce ks ke Calip ke Calip 3-32oz Brake Clr 6	entr er er nr		1.0 7.0 1.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 1.0
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch Door Handl Brake Pad Retainer	Dil Filter Fuel Filte Blade Iid Conce ks ke Calip ke Calip 3-32oz Brake Clr 6	entr er er nr		1.0 7.0 1.0 1.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch Door Handl Brake Pad Retainer Bulb	Dil Filter Fuel Filte Blade Iid Conce Iks Ike Calip	entr er er nr		1.0 7.0 1.0 1.0 1.0 2.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1
- P.m. Service - Replace lead - Replace rea assembly.repla - Resurface fr calipers.flush a - Replace and	e. king front sho r cargo door u ace lighter so ront brake rote and bleed sys d balance four heel alignmer	cks. upper and locket.replace ors,replace petem. r new tires.	ower latch e left visor re pads and		Cover 5w20 Engir Napagold C Napagold F 20" Wiper E Washer Flu Front Shock Reman Bra Reman Bra B Fluid Dot Non-chlor E Lt245 75r16 Ring Socket Door Latch Door Handl Brake Pad Retainer	Dil Filter Fuel Filte Blade iid Conce ks ke Calip ke Calip 3-32oz Brake Clr W/cable e W/cab	entr er er nr		1.0 7.0 1.0 1.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1.0 1

Workorder: Problem:	1708715 PM Service,	Meter: Cigarette li	59733 ghter does't w	ork, Deta		In Date:	09/01/2017	Closed:	09/18/20	017
- P.m. service		5		,	Parts Lis	st				Qty
- Check elect	rical circuit an	d replace b	lown fuse and		luminous					1.00
cigarette lighte		•			5w20 Eng	gine Oil				7.00
- Rotate and	high speed ba	lance all fo	ur tires.		Napagold Oil Filter					1.00
- Shop Suppl	ies				20" Wipe					2.00
					•	X Refurbi	ished			1.00
					Elemenet	t				1.00
					Ring					1.00
					Base Asy	1				1.00
					Shop Sup					1.00
	Hou	ırs 6.00		Labor:	360.00		107.54	Total:	467.54	
Workorder: Problem:	1708928 1 - Detail Ve	Meter: hicle Wash	59628 Ticket(s) Issu	ed		In Date:	09/18/2017	Closed:	09/18/20	017
- 1 - Detail Ve	hicle Wash T	cket(s) Issu	ıed							
	Ηοι :	ırs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1709428 Check engin	Meter: e light on .	59897			In Date:	09/27/2017	Closed:	09/28/20	017
P0304,p0316. codes and ret	est .reset Kam	int test.r&r	open coil # 4.	Clear	Parts Lis Ford Ignit Shop Sup	tion Coil				Qty 1.00 1.00
		ırs 1.70		Labor:	102.00	Parts:	71.21	Total:	173.21	
Workorder: Problem:	1804545 P.M. service	Meter: and check	62903 for nails in tire	es.		In Date:	05/01/2018	Closed:	05/09/20	018
- P.m. service) .				Parts Lis	st				Qty
- Replaced w	orn out serper	ntine belt.			5w20 Eng	gine Oil				7.00
		ce and rota	ite all four tires	3.	_					1.00
Nitrogen fill tir					20" Wipe	r Blade				2.00
- Shop Suppl	ies				Serpentin	ne Belt				1.00
					Napagolo	Oil Filter				1.00
					Shop Sup	oplies				1.00
	Ηοι :	ırs 7.00		Labor:	420.00	Parts:	64.16	Total:	484.16	
Workorder: Problem:	1808158 Had to jump	Meter: start.	62924			In Date:	08/08/2018	Closed:	08/09/20	018
- Charge batt		battery , fa	iled load test .	. R&r	Parts Lis	st				Qty
	•	ernator has	s bad diodes .	R&r	Battery	. Natari	£4			1.00
defective alter						r Motorcraf	I			1.00
- Shop Suppl	ies				Shop Sup	opiies				1.00
-	Ηου :	ırs 2.60		Labor:	156.00	Parts:	429.94	Total:	585.94	

Workorder: 1808268 62924 Meter: In Date: 08/03/2018 Closed: 08/13/2018 Problem: NO START - Tow From: 2300 Vista Pkwy-entrance To: Lv Shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 1811353 Meter: 63231 In Date: 11/02/2018 **Closed:** 11/15/2018 Problem: PM Service, 45 mph trucks makes noise, Intermittant crank no start. - P.m. service. Test drive vehicle for noise concern ,only **Parts List** Qty heard road noise. Test starting and charging system serval Napa Quart 5w20 6.00 times. Could not dupicate concern. Napagold Oil Filter 1.00 - Replace left cracked brake light lens and install strobe bulb 20" Wiper Blade 2.00 in new lens. Used Fire X Refurbished 1.00 - Rotate and balance all four tires. Nitrofill all . Lamp Assembly 1.00 - Shop Supplies **Shop Supplies** 1.00 Hours 5.50 Labor: 368.50 Parts: 96.08 Total: 464.58 Workorder: 1902912 **Closed:** 03/15/2019 Meter: 64653 In Date: 03/15/2019 Problem: Transition Prep Charge - Transition Prep Charge

Labor: 134.00

Hours 2.00

Parts: 0.00

Total: 134.00