10179592 2010 FORD F350 Utility Body, 1 Ton

Workorder: Problem: - Pre Delivery	1003881 Pre Delivery I	Meter: Inspection	0			In Date:	04/15/2010	Closed:	04/15/2	040
- Pre Delivery	/ Inspection					iii Date.	04/13/2010	Ciosea.	04/15/2	010
	•									
	Hou :	rs 4.00		Labor:	240.00	Parts:	0.00	Total:	240.00	
Workorder: Problem:	1012001 Pm service.	Meter:	4801			In Date:	10/26/2010	Closed:	11/03/2	010
- Perform pm	service.				Parts Li	st				Qty
	nce light bar in	op.test and	l repair	failed ground	Pm-22-a	Additive D	iesel Fuel (m/	craft)		1.00
wire for light b					Shop Su	ıpplies				1.00
	balance all six	tires			Fuel Filt	er				1.00
- Shop Suppl	ies				7312 O	il Filterfrm C	Ch9549 Wix 5	7312		1.00
					15/40 C	Dil				15.00
					7090blk	Frt Floor M	ats (rubber Q	ueen)		1.00
					Used Fi	ex Refurbe	d Fire Extings	shers		1.00
	Hou	rs 6.50		Labor:	390.00	Parts:	182.97	Total:	572.97	
Workorder: Problem:	1012323 REFLASH CA	Meter: ANCEIVER	4801 SPOT	212		In Date:	11/02/2010	Closed:	11/03/2	010
- Reflash Car	nceiver and rep	rogram			Parts Li	st				Qty
- Shop Suppl	ies				Shop Su	ıpplies				1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1104810 1 - Key(s) iss	Meter: ued	8276			In Date:	05/05/2011	Closed:	05/05/2	011
- 1 - Key(s) is	sued				Parts Li	st				Qty
					Duplicat	e Vehicle K	eys			1.00
	Hou	rs 0.20		Labor:	12.00	Parts:	3.00	Total:	15.00	
Workorder: Problem:	1104878 Pm service	Meter:	8681			In Date:	05/09/2011	Closed:	05/18/2	011
- P.m. Servic	e.				Parts Li	st				Qty
	balance all tire	S.			Shop Su	ıpplies				1.00
- Rotate and					7242 0	:	N. O. T. AO NA!' 5			
Rotate andShop Suppl					7312 U	ıı Fiiteririn C	Ch9549 Wix 5	7312		1.00
							use Cs1026			1.00 1.00
						3 Fuel Filter				

Workorder: Problem:	1112035 Pm service	Meter:	15438			In Date:	11/09/2011	Closed:	11/21/20	011
- Perform pm	service.				Parts Li	ist				Qty
- Repair flat ri	ght rear tire.nit	rogen fill a	nd balance a	ll four.	Pm-22-a Additive Diesel Fuel (m/craft)					1.00
- Shop Supplies					Shop Su	upplies				1.00
					7312 O	il Filterfrm C	Ch9549 Wix 5	7312		1.00
					3963 F	uel Filter Fr	m Cs10263a	Wix 33963		1.00
					15/40 C	Dil				15.00
					Used Fi	rex Refurbe	d Fire Extings	shers		1.00
					31-22 W	iper Blades	22" Wiper Bl	ade		2.00
	Hour :	s 6.00		Labor:	360.00	Parts:	126.81	Total:	486.81	
Workorder:	1204068	Meter:	21728			In Date:	04/30/2012	Closed:	05/16/20)12
Problem:	P.M. service a	and check	engine light o	n.						
- P.m. Service	э.				Parts Li	ist				Qty
- Replace and	d balance six tir	es.			Shop Supplies					1.00
	and charging s				Ca10270 Air Filter Mtc Fa1886 Wix 49886					1.00
•	oad test.replace			S.	7312 Oil Filterfrm Ch9549 Wix 57312					1.00
•	heel alignment	test drive.			3963 Fuel Filter Frm Cs10263a Wix 33963					1.00
- Shop Suppli	es				15/40 C	Dil				15.00
					31-22 W	iper Blades/	22" Wiper Bl	ade		2.00
					Group 6	5 Battery (r	ntc Bxt-65-850	0)		2.00
					1796364	492 Lt245/7	5r17 Wrangle	r Sr-a E		6.00
						posal Fee				6.00
						alve Stem				6.00
	Hour :	s 11.50		Labor:	690.00	Parts:	1,524.34	Total:	2,214.34	1
Workorder:	1205839	Meter:	22845			In Date:	06/20/2012	Closed:	06/27/20)12
Problem:	Check engine	light on.								
	ehicle to dealer				Parts Li	ist				Qty
	242b,p0703.9e	egr temp so	ensor,est. ser	nsor)	Shop St	upplies				1.00
- Shop Suppli		- 0.00		Laban	400.00	Danta	0.00	Tatal	400.00	
	Hour :	s 2.00		Labor:	120.00	Parts:	2.00	i otai:	122.00	
Workorder: Problem:	1206084 wont fuel	Meter:	23040			In Date:	06/28/2012	Closed:	06/29/20)12
- Repair Conr	nections at Can	ceiver rem	nove Canceiv	er	Parts Li	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	Hour	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	

Workorder: Problem:	1211337 Pm service.	Meter:	28901		In	Date:	11/26/2012	Closed:	12/13/20	012
- P.m. Service	e.				Parts List					Qty
	st inspect cooli			ıg	15-40 Oil					15.00
	s.flush and refil	٠.			Oil Filter Fuel Filter Used Firex Refurbed F					1.00
 Blower not of defective blow 	operating on al	l speeds.di	agnose and re	eplace						1.00
		tiras								1.00
Rotate and balance all six tires.Shop Supplies					Radiator Ho	ose				1.00
опор оцррп	103				lower hose					1.00
					Antifreeze I	Ext-life				2.00
					resistor					1.00
					Stg Wheel	Cov - Fo	ord			1.00
					Shop Supp	lies				1.00
	Hou	rs 9.50		Labor:	570.00	Parts:	346.99	Total:	916.99	
Workorder: Problem:	1303245 Pm service a	Meter: nd check e	32783 ngine light on,	no powe		Date:	04/03/2013	Closed:	04/15/20	J13
Problem: - Perform pm - Computer d and replace fa Tsb# 12-7-7.re	Pm service a service. iagnose for chailed brake prese eprogram Pcm balance all six ies	nd check e eck engine ssure switc with latest tires.	ngine light on, light on.pinpo h with new.pe	int test rform date.	r. Parts List 15-40 Oil Napagold C Napagold F 31-22 Wipe Pedal Pad Switch Shop Supp	Dil Filter Fuel Filte er Blades lies	r s 22			Qty 15.00 1.00 1.00 2.00 1.00 1.00
Problem: - Perform pm - Computer d and replace fa Tsb# 12-7-7.re - Rotate and I - Shop Suppli	Pm service a service. iagnose for chailed brake prese eprogram Pcm balance all six ies	nd check e eck engine ssure switc with latest	ngine light on, light on.pinpo h with new.pe	int test rform date.	r. Parts List 15-40 Oil Napagold C Napagold F 31-22 Wipe Pedal Pad Switch	Dil Filter Fuel Filte er Blades lies	r	Total:	651.22	Qty 15.00 1.00 2.00 1.00 1.00
Problem: - Perform pm - Computer d and replace fa Tsb# 12-7-7.re - Rotate and I - Shop Suppli	Pm service a service. iagnose for chailed brake prese eprogram Pcm balance all six ies	eck engine ssure switch with latest tires. rs 8.50 Meter:	ngine light on, light on.pinpo h with new.pe	int test rform date.	r. Parts List 15-40 Oil Napagold C Napagold F 31-22 Wipe Pedal Pad Switch Shop Supp 510.00	Dil Filter Fuel Filte er Blades lies	r s 22			Qty 15.00 1.00 2.00 1.00 1.00 1.00
Problem: - Perform pm - Computer d and replace fa Tsb# 12-7-7.re - Rotate and l - Shop Suppli Workorder: Problem:	Pm service a service. iagnose for chailed brake preseprogram Pcm balance all six ies Hou : 1307471 1 - Key(s) iss	eck engine ssure switch with latest tires. rs 8.50 Meter:	ngine light on, light on.pinpo h with new.pe calibration up	int test rform date.	r. Parts List 15-40 Oil Napagold C Napagold F 31-22 Wipe Pedal Pad Switch Shop Supp 510.00	Dil Filter Fuel Filte er Blades Iies Parts:	r 5 22 141.22	Total:	651.22	Qty 15.00 1.00 2.00 1.00 1.00 1.00
Problem: - Perform pm - Computer d and replace fa Tsb# 12-7-7.re - Rotate and I - Shop Suppli	Pm service a service. iagnose for chailed brake preseprogram Pcm balance all six ies Hou : 1307471 1 - Key(s) iss	eck engine ssure switch with latest tires. rs 8.50 Meter:	ngine light on, light on.pinpo h with new.pe calibration up	int test rform date.	r. Parts List 15-40 Oil Napagold C Napagold F 31-22 Wipe Pedal Pad Switch Shop Supp 510.00	Dil Filter Fuel Filte er Blades lies Parts:	r 3 22 141.22 07/25/2013	Total:	651.22	Qty 15.00 1.00 2.00 1.00 1.00 1.00

Workorder: 1400874 Meter: 42523 Problem: P.M. Service.	In Date: 01/27/2014 Closed:	02/19/2014
- P.m. Service.	Parts List	Qty
- Resurface rear brake rotors,replace rear brake pads.service	15-40 Oil	15.00
and lube rear calipers,flush and bleed system and test drive.	Napagold Oil Filter	1.00
- Replace two tires,rotate and balance all six.	Fuel Filter Ford Only	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Napagold Air Filter	1.00
	Washer FI	1.00
	Wiper Blade	2.00
	Brake Pad	1.00
	1401 Brake Fluid Bra	1.00
	179636492 Lt245-75r17	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.50 Labor:	690.00 Parts: 779.99 Total:	1,469.99
Workorder: 1407657 Meter: 45660	In Date: 08/04/2014 Closed:	08/19/2014
Problem: Pm service.		
	Parts List	Qty
Problem: Pm service.	Parts List Napagold Oil Filter	Qty 1.00
Problem: Pm service Perform pm service.		-
Problem: Pm service Perform pm service Rotate and balance all six tires.	Napagold Oil Filter	1.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack.	Napagold Oil Filter 15-40 Oil	1.00 15.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack.	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only	1.00 15.00 1.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack.	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr	1.00 15.00 1.00 1.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack. - Shop Supplies	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr Ladder Rack Shop Supplies	1.00 15.00 1.00 1.00 1.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack. - Shop Supplies	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr Ladder Rack Shop Supplies	1.00 15.00 1.00 1.00 1.00 1.00
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack. - Shop Supplies Hours 9.50 Eabor: Workorder: 1410991 Meter: 47647 Problem: Dead battery - Test both batteries and charging system.replace both bad	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr Ladder Rack Shop Supplies 570.00 Parts: 751.28 Total:	1.00 15.00 1.00 1.00 1.00 1.00 1,321.28
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack. - Shop Supplies Hours 9.50 Labor: : Workorder: 1410991 Meter: 47647 Problem: Dead battery - Test both batteries and charging system.replace both bad batteries.	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr Ladder Rack Shop Supplies 570.00 Parts: 751.28 Total: In Date: 11/03/2014 Closed:	1.00 15.00 1.00 1.00 1.00 1.00 1,321.28
Problem: Pm service. - Perform pm service. - Rotate and balance all six tires. - Install new ladder rack. - Shop Supplies Hours 9.50 Eabor: Workorder: 1410991 Meter: 47647 Problem: Dead battery - Test both batteries and charging system.replace both bad	Napagold Oil Filter 15-40 Oil Fuel Filter Ford Only Washer Fluid Concentr Ladder Rack Shop Supplies 570.00 Parts: 751.28 Total: In Date: 11/03/2014 Closed: Parts List	1.00 15.00 1.00 1.00 1.00 1.00 1,321.28 11/10/2014

Workorder: 1501240 Meter: 50220 Problem: Pm service.	In Date: 02/03/2015 Closed: 02/19/2015
- Pm service.	Parts List Qty
- Inspect and replace two worn /noisy front body to chasis	15-40 Oil 15.00
mount/insulators.	Napagold Oil Filter 1.00
- Replace four tires.rotate and balance all six.	Fuel Filter Ford Only 1.00
- Inspect and replace defective left rear Led turnsignal lamp assembly.	3c3z9a343a Seal Kit 1.00
- Complete front end alignment.test drive.	Wiper Blade 2.00
- Shop Supplies	Lt245 75r17 M/s2 Tire 4.00
Chop Supplies	Used Fire X Refurbished 1.00
	Led Sup Mdl 44 42 Dio 1.00
	Seal Kit 1.00
	Insulator 2.00
	Insualtor 2.00
	Shop Supplies 1.00
	Tire Disposal Fee 4.00
Hours 12.00 Labor :	720.00 Parts: 1,692.00 Total: 2,412.00
Workorder: 1507599 Meter: 52990 Problem: P.M. service and right front tire going flat.	In Date: 07/30/2015 Closed: 08/14/2015
- Pm service.	Parts List Qty
- Repair right front tire.rotate and balance all six.	15-40 Oil 15.00
- Shop Supplies	Napagold Oil Filter 1.00
	Fuel Filter Ford Only 1.00
	Wiper Blade 2.00
	Washer Fluid Concentr 1.00
	Shop Supplies 1.00
Hours 6.50 Labor	390.00 Parts: 150.76 Total: 540.76

 Perform transmission fluid flush and refill. Replace both headlamp assembly seal beams due to water condensation also check and replace two defective tail light assemblies. Check and replace broken engine oil dip stick tube. Replace two front tires.rotate and balance all six. Shop Supplies 	Parts List 15-40 Oil Napagold Oil Filter Fuel Filter Ford Only Used Fire X Refurbished Napagold Air Filter 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio Lt245 75r17 M/s2 Tire	Qty 15.00 1.00 1.00 1.00 2.00 2.00 2.00 2.00
 Replace both headlamp assembly seal beams due to water condensation also check and replace two defective tail light assemblies. Check and replace broken engine oil dip stick tube. Replace two front tires.rotate and balance all six. Shop Supplies 	Napagold Oil Filter Fuel Filter Ford Only Used Fire X Refurbished Napagold Air Filter 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	1.00 1.00 1.00 1.00 2.00 20.00 2.00
condensation also check and replace two defective tail light assemblies. - Check and replace broken engine oil dip stick tube. - Replace two front tires.rotate and balance all six. - Shop Supplies Shop Supplies	Fuel Filter Ford Only Used Fire X Refurbished Napagold Air Filter 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	1.00 1.00 1.00 2.00 20.00 2.00
- Check and replace broken engine oil dip stick tube Replace two front tires.rotate and balance all six Shop Supplies Shop Supplies	Used Fire X Refurbished Napagold Air Filter 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	1.00 1.00 2.00 20.00 2.00
- Check and replace broken engine oil dip stick tube Replace two front tires.rotate and balance all six Shop Supplies S H	Napagold Air Filter 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	1.00 2.00 20.00 2.00
- Replace two front tires.rotate and balance all six Shop Supplies S H	. 22" Wiper Blade Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	2.00 20.00 2.00
- Shop Supplies S	Syn-atf Trans Fluid S Halogen Lamp Led Sup Mdl 44 42 Dio	20.00 2.00
H L	Halogen Lamp Led Sup Mdl 44 42 Dio	2.00
L	Led Sup Mdl 44 42 Dio	
	•	2.00
	L t2/15 75r17 M/c2 Tira	
L	LIZAJ IJITI W/3Z TIIG	2.00
E	Engine Oil Tube	1.00
E	Engine Oil Tube Motorcraft	1.00
S	Shop Supplies	1.00
Т	Tire Disposal Fee	2.00
Hours 11.50 Labor: 6	690.00 Parts: 1,158.12 Total:	1,848.12
Workorder: 1609687 Meter: 61928	In Date: 09/16/2016 Closed:	09/27/2016
Problem: P.M. service and install steering wheel cover.		
- P.m. Service.	Parts List	Qty
1 3 7	15-40 Oil	15.00
replace coolant hose to Egr cooler.flush and refillcooling system.	Napagold Oil Filter	1.00
- Rotate and balance all six tires.	Fuel Filter Ford Only	1.00
- Shop Supplies	20" Wiper Blade	2.00
V	Washer Fluid Concentr	1.00
S	Stg Wheel Cov - Ford	1.00
C	Coolant Ford Gold	3.00
D	Degass Bottle Hose	1.00
H	Hose Clm	1.00
S	Shop Supplies	1.00
Hours 8.50 Labor: 5	510.00 Parts: 269.09 Total:	779.09

Workorder: 1704090 Meter: 66996 Problem: P.M. service.	In Date: 04/24/2017	Closed: 05/11/2017
- P.m. Service.	Parts List	Q
- Test batteries and charging system.replace both bad	15-40 Oil	15.0
batteries.	Napagold Oil Filter	1.0
- Replace two tires,rotate and balance all four.	22" Wiper Blade	2.0
- Replace four worn out body mounts.	White Lithium Grease	1.0
- Replace leaking rear axle seals.inspect and service rear differential.	Used Fire X Refurbished	1.0
- Replace burned out rear lamps.replace center brake lamp	Pedal Pad	1.0
bulbs.	Fuel Filter Ford Only	1.0
- Pressure test and inspect cooling system.replace leaking	Battery	2.0
upper radiator hose and bypass hose to coolant	179636492 Lt245-75r17	2.0
reservoir.flush and refill cooling system.	Body Mount Kit	4.0
Replace lower intercooler hose.Complete wheel alignment.test drive.	75w140 Ford Axle Lube	3.0
- Shop Supplies	Napa Oil Seal	2.0
- Shop Supplies	Ptex Ultra Grey 3oz	1.0
	Friction Modifier	2.0
	4 Led S T T Lamp	2.0
	Intercooler Hose	1.0
	Stg Wheel Cov - Ford	1.0
	Top Radiator Hose	1.0
	Degass Bottle Hose	1.0
	Coolant Ford Gold	1.0
	Shop Supplies	1.0
Hours 24.50 Labor:	Tire Disposal Fee	2.0
Hours 24.50 Labor.	1,470.0 Parts: 1,718.34 0	Total: 3,188.34
Workorder: 1711579 Meter: 70850 Problem: P.M. service .	In Date: 11/27/2017	Closed: 12/07/2017
- P.m. service.	Parts List	Q
- Removed and replaced rear marker light on three light bar	Napagold Oil Filter	1.0
	15-40 Oil	15.0
- Removed and replaced front brake pads and calipers	22" Wiper Blade	2.0
.resurface front rotors and bleed and flush brake system.test drive .	Fuel Filter Ford Only	1.0
- Replace two worn tires and repair right front tire .rotate and	M C Lamp	1.0
balance all six tires .nitrofill.	Brake Pads	1.0
- Shop Supplies	Reman Brake Caliper	1.0
	Reman Brake Caliper	1.0
	179636492 Lt245-75r17	2.0
	B Fluid Dot 3-32oz	1.0
	Non-chlor Brake Clnr	1.0
	Seal Kit	1.0
	Shop Supplies	1.0
	Tire Disposal Fee	2.0
Hours 12.30 Labor:	738.00 Parts: 900.36	Total: 1,638.36

Workorder: 1805958 Meter: 75633 Problem: P.M. Service.	In Date: 06/11/2018 Closed:	06/20/2018	
- P.m. Service.	Parts List	Qty	
- Replace defective blower resistor.	Napagold Oil Filter	1.00	
- Replace worn out front bump stoppers.	15-40 Oil	15.00	
- Replace cargo lamp bulbs.	Mac Wite Lithium Gres	1.00	
- Repair left front tire,rotate and balance all six.	Wd40 Spr	1.00	
- Complete wheel alignment.test drive.	Fuel Filter Ford Only	1.00	
- Shop Supplies	20" Wiper Blade	2.00	
	Blower Resistor	1.00	
	bumper	2.00	
	Bulb	1.00	
	Used Fire X Refurbished	1.00	
	Shop Supplies	1.00	
Hours 11.00 Labor:	660.00 Parts: 228.28 Total:	888.28	
Workorder: 1900976 Meter: 80558 Problem: P.M. service.	In Date: 01/25/2019 Closed:	02/07/2019	
- P.m. service.	Parts List	Qty	
- Replace two tires .rotate and balance all six tires . Nitrofill	15-40 Oil	15.00	
all.	Napagold Oil Filter	1.00	
- R&r worn bumper stops .	Washer Fluid Concentr	1.00	
- Perform complete four wheel alignment and test drive.	20" Wiper Blade	2.00	
- Shop Supplies	Fuel Filter Ford Only	1.00	
	Lt245/75r17 Mich Defend Ltx	2.00	
	Bumper	2.00	
	Shop Supplies	1.00	
	Tire Disposal Fee	2.00	
Hours 9.50 Labor:	636.50 Parts: 752.04 Total:	1,388.54	
Workorder: 1903543 Meter: 81319 Problem: Transition Prep Charge	In Date: 04/02/2019 Closed:	04/02/2019	
- Transition Prep Charge			
3			