# 10181152 2011 FORD F250 Pickup, 3/4 Ton

		10	101132	20111 010	7 1 230 1	ickup, 3/4	1011			
Workorder: Problem:	1007586 Pre Delivery In	Meter: nspection	0			In Date:	07/19/2010	Closed:	07/19/2	010
- Pre Delivery	/ Inspection									
	Hour :	s 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1007652 new key	Meter:	306			In Date:	07/20/2010	Closed:	07/23/2	010
- Cut 2 keys &	& program				Parts Li	ist				Qty
- Shop Suppli	ies				164-r04	75 Ign Key	2010-earlier (d	don't Reorde	er)	1.00
					164-r80	40 Ignition I	Key 2011- Nev	wer (ford)		2.00
					Shop Su	upplies				1.00
	Hour :	s 1.00		Labor:	60.00	Parts:	69.95	Total:	129.95	
Workorder: Problem:	1100831 P.M. Service	Meter:	4849			In Date:	01/21/2011	Closed:	01/28/2	011
- P.m. Service	э.				Parts Li	ist				Qty
- Rotate and I	balance all tires	S.			Shop Su	upplies				1.00
- Shop Suppli	ies				1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
					61a P/st	teering Fluid	t			1.00
						ngine Oil				7.00
	Hour :	s 3.00		Labor:	180.00	Parts:	21.70	Total:	201.70	
Workorder: Problem:	1107143 Pm service.	Meter:	9564			In Date:	07/06/2011	Closed:	07/19/2	011
- Perform pm	service.				Parts Li	ist				Qty
- Rotate and I	balance all four	tires.			Shop Supplies					1.00
- Shop Suppli	ies						n Ph2 Wix 51	372		1.00
					5w20 Er	ngine Oil				7.00
						/iper Blades				2.00
							d Fire Extings			1.00
	Hour :	s 3.75		Labor:	225.00	Parts:	45.38	Total:	270.38	
Workorder: Problem:	1200145 P.M. service a	Meter: and wiper l	14948 olades com	ning apart.		In Date:	01/05/2012	Closed:	01/19/2	012
- Perform pm	service.				Parts Li	ist				Qty
	olace failed left	signal lam	p bulb with	n new.	Shop Supplies					1.00
- Rotate and I	balance all four	tires.			1372 O	il Filter Frm	n Ph2 Wix 51	372		1.00
- Shop Suppli	ies				5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
					3157 Ta	ail Light Bulb	os			1.00
	Hour	s 4.25		Labor:	255.00	Parts:	33.34	Total:	288.34	
	•									

Workorder: 1202379 Meter: 16883 Problem: Right rear tire flat.	In Date: 03/08/2012 Closed: 03/12	/2012	
- Repair and balance right rear tire.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 1.00 Labor:	60.00 Parts: 2.00 Total: 62.00		
Workorder: 1206240 Meter: 20406 Problem: P.M. service.	In Date: 07/02/2012 Closed: 07/26	/2012	
- Perform pm service.	Parts List	Qty	
- Install four new tires.nitrogen fill and balance all four.	Shop Supplies	1.00	
- Inspect and repair left side tool box linkage and replace	1372 Oil Filter Frm Ph2 Wix 51372	1.00	
bushing.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00	
- Test starting and charging system.battery failed load test after recharge.replace failed battery with new.	5w20 Engine Oil	7.00	
- Perform wheel alignment complete.	Used Firex Refurbed Fire Extingshers	1.00	
- Shop Supplies	D3tz2457b Brake Pedal Pad	1.00	
5 - 1 - 5 11 - 5	Group 65 Battery (mtc Bxt-65-850)	1.00	
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00	
	Tire Disposal Fee	4.00	
Hours 8.75 Labor:	525.00 Parts: 924.92 Total: 1,449	.92	
Workorder: 1212157 Meter: 25086  Problem: Left front tire has nail.Oil light comes on.	In Date: 12/18/2012 Closed: 12/19	/2012	
Troblem. Left from the flas flan. On light comes on.			
- Repair and balance left front tire.	Parts List	Qty	
-	Parts List Valve	<b>Qty</b> 1.00	
- Repair and balance left front tire.		-	
- Repair and balance left front tire.	Valve Shop Supplies	1.00	
<ul><li>Repair and balance left front tire.</li><li>Shop Supplies</li></ul>	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11	1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor:  Workorder: 1305218 Meter: 29808	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11	1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift a	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds reqeust 2 spare keys.	1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service.	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds requust 2 spare keys.  Parts List	1.00 1.00 /2013	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds reqeust 2 spare keys.  Parts List 5w20 Engine Oil	1.00 1.00 /2013 <b>Qty</b> 7.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds request 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter	1.00 1.00 /2013 <b>Qty</b> 7.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift a  - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-21-13.	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds reqeust 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished	1.00 1.00 /2013 <b>Qty</b> 7.00 1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-21-13 Rotate an balance all four tire.	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds request 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished Stg Wheel Cov - Ford	1.00 1.00 /2013 <b>Qty</b> 7.00 1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift a  - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-21-13.	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds request 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished Stg Wheel Cov - Ford Floor Mat-2pc Rub Bk	1.00 1.00 /2013 <b>Qty</b> 7.00 1.00 1.00 1.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-21-13 Rotate an balance all four tire.	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds reqeust 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished Stg Wheel Cov - Ford Floor Mat-2pc Rub Bk 31-20 Wiper Blades 20	1.00 1.00 /2013 <b>Qty</b> 7.00 1.00 1.00 1.00 2.00	
- Repair and balance left front tire Shop Supplies  Hours 1.00 Labor: :  Workorder: 1305218 Meter: 29808 Problem: P.M. service and tail light inop and hard shift at - P.m. Service Replace left rear signal light bulb Cut and reprogram new Pats key per request Test drive vehicle for harsh shift concern at low speeds.reprogram Pcm with updated calibration per Tsb 10-21-13 Rotate an balance all four tire Shop Supplies	Valve Shop Supplies 60.00 Parts: 15.37 Total: 75.37  In Date: 05/28/2013 Closed: 06/11 low speeds request 2 spare keys.  Parts List 5w20 Engine Oil Napagold Oil Filter Used Fire X Refurbished Stg Wheel Cov - Ford Floor Mat-2pc Rub Bk 31-20 Wiper Blades 20 Bulb	1.00 1.00 1.00 72013 Qty 7.00 1.00 1.00 1.00 2.00 1.00 2.00 1.00	

Problem:	1310314 P.M. service	Meter:	35589		In Dat	te:	10/11/2013	Closed:	10/29/2013
- P.m. Service	<del>)</del> .				Parts List				Qty
- Replace thre	e tool box lid	props.			5w20 Engine Oi	il			7.00
- Replace cen	ter brake ligh	t bulb.			Napagold Oil Fi	ilter			1.00
- Rotate and b	- Rotate and balance all tires.					ilter			1.00
- Shop Supplie	es				Wiper Blade				2.00
					Lift Support Uni	iv			2.00
					Ball Joint Stud				1.00
					Lift Support Uni	iv			2.00
					Support				4.00
					Shop Supplies				1.00
	Hou	ırs 5.25		Labor:	315.00 Pa	arts:	325.30	Total:	640.30
Workorder: Problem: - damage to fr	•	·	40752		In Dat	ie.	04/14/2014	Closed:	05/07/2014
		ırs 0.00		Labor:	0.00 Pa	arts:	0.00	Total:	0.00
Workorder: Problem:	: 1405166 P.M. service	Meter:	41436		0.00 Pa		0.00	Total:	0.00
Problem:	P.M. service	Meter:	41436 jump start in A						06/11/2014
Problem: - P.m. Service	P.M. service	Meter: and had to	jump start in A	/M.	In Dat	te:			
Problem: - P.m. Service	P.M. service  and charging	Meter: and had to system.cha	jump start in A	/M.	In Date Parts List 5w20 Engine Oi	te:			06/11/2014 <b>Qty</b> 7.00
Problem: - P.m. Service - Test battery	P.M. service e. and charging d test.replace	Meter: and had to system.cha defective b	jump start in A	/M.	In Date Parts List 5w20 Engine Oi Napagold Oil Fi	te:			06/11/2014 Qty 7.00 1.00
Problem: - P.m. Service - Test battery battery,fail load	P.M. service e. and charging d test.replace I balance four	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	In Date Parts List 5w20 Engine Oi	t <b>e:</b> vil	05/28/2014		06/11/2014 <b>Qty</b> 7.00
Problem: - P.m. Service - Test battery battery,fail load - Replace and	P.M. service e. and charging d test.replace I balance four neel alignmen	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	In Date  Parts List  5w20 Engine Oi  Napagold Oil Fil  Wiper Blade	t <b>e:</b> ill ilter	05/28/2014		06/11/2014 Qty 7.00 1.00 2.00
Problem: - P.m. Service - Test battery battery,fail load - Replace and - Complete wh	P.M. service e. and charging d test.replace I balance four neel alignmen	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	Parts List 5w20 Engine Oi Napagold Oil Fi Wiper Blade Used Fire X Ref Bat Term Protect	t <b>e:</b> ill ilter	05/28/2014		06/11/2014 Qty 7.00 1.00 2.00 1.00 1.00
Problem: - P.m. Service - Test battery battery,fail load - Replace and - Complete wh	P.M. service e. and charging d test.replace I balance four neel alignmen	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	Parts List 5w20 Engine Oi Napagold Oil Fi Wiper Blade Used Fire X Ref	te: vil ilter efurbi	05/28/2014 shed		06/11/2014 Qty 7.00 1.00 2.00 1.00
Problem: - P.m. Service - Test battery battery,fail load - Replace and - Complete wh	P.M. service e. and charging d test.replace I balance four neel alignmen	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	Parts List 5w20 Engine Oi Napagold Oil Fil Wiper Blade Used Fire X Ref Bat Term Protect Battery 65 179636492 Lt24	te: vil ilter efurbi	05/28/2014 shed		06/11/2014 Qty 7.00 1.00 2.00 1.00 1.00 4.00
Problem: - P.m. Service - Test battery battery,fail load - Replace and - Complete wh	P.M. service e. and charging d test.replace I balance four neel alignmen	Meter: and had to system.cha defective b new tires.	jump start in A arge and retest attery.	/M.	Parts List 5w20 Engine Oi Napagold Oil Fi Wiper Blade Used Fire X Ref Bat Term Protect Battery 65	te: oil ilter octor 45-79	05/28/2014 shed		06/11/2014 Qty 7.00 1.00 2.00 1.00 1.00

Workorder: 1500375 Meter: 47901 Problem: Pm service.Check engine light on.	In Date: 01/12/2015 Closed: 0	01/28/2015
<ul> <li>P.m. Service.</li> <li>Diagnose check engine light.p0455.test and replace dfective fuel cap.reprogram Pcm with updated calibrationclear codes.</li> <li>Replace right rear signal light bulb.</li> <li>Resurface front and rear brake rotors,replace brake pads.service and lube calipers.flush and bleed systen.</li> <li>Rotate and balance all tires.</li> <li>Shop Supplies</li> </ul>	Parts List 5w20 Engine Oil Napagold Oil Filter Wiper Blade Bulb Pads Rear Pads B Fluid Dot 3-32oz Brake Cleaner Cap Asy Reman Brake Caliper	Qty 7.00 1.00 2.00 1.00 1.00 1.00 1.00 1.00 1
Hours 14.25 Labor:	Reman Brake Caliper Shop Supplies 855.00 Parts: 367.16 Total: 1	1.00 1.00 1,222.16
Workorder: 1511876 Meter: 57422 Problem: Pm service.	In Date: 11/20/2015 Closed: 1	12/09/2015
<ul> <li>- Pm service.</li> <li>- Check and replace damage rear bumper cover due to broken clips.also replace hitch pintle pin.</li> <li>- Replace and balance all four tires.</li> <li>- Diagnose for noise and replace one defective ignition wire and spark plug for #1 cylinder on exhaust side.</li> <li>- Complete front end alignment and test drive.</li> <li>- Shop Supplies</li> </ul>	Parts List  5w20 Engine Oil  Napagold Oil Filter  Napagold Air Filter  Used Fire X Refurbished  Bigg Degreaser  Wiper Blade  Real Bumper Cover  Pintle Pin W/chain  179636492 Lt245-75r17  Wire Assy  Spark Plug  Shop Supplies  Tire Disposal Fee	Qty 7.00 1.00 1.00 1.00 1.00 2.00 1.00 4.00 1.00 1.00 4.00 4.00 4.00
Hours 10.25 Labor:		1,913.37

Workorder:	1607339	Meter:	62508		ı	n Date:	07/19/2016	Closed:	07/29/2016
Problem:	P.M. service	e and wipers	stay on and n	eed spar	e key.				
- P.m. Service	e.				Parts List	t			Qty
			in point test ar	nd	5w20 Eng		7.00		
replace defect					Napagold	Oil Filter			1.00
- Service tran			-		20" Wiper	Blade			2.00
	- Pressure test and inspect cooling system.flush and refill system.						ished		1.00
-	worn out cah	/chasis mou	nts		Stg Whee	l Cov - Fo	ord		1.00
•	<ul><li>Replace six worn out cab/chasis mounts.</li><li>Cut and program spare key.</li></ul>								1.00
- Rotate and	•	-			Transmiss	sion Filter			1.00
- Shop Suppli		00.			Syn-atf Tr	ans Fluid	S		20.00
оттор образ					Ford Red		Э		2.00
					Body Mou	nt Kit			2.00
					Body Mou				4.00
					Ford Igniti	•	lank		1.00
					Shop Sup	•			1.00
	Ho :	urs 17.25		Labor:	1,035.0 0	Parts:	831.46	Total:	1,866.46
Workorder: Problem:	1609151 Airbag light	Meter: on.	63289		I	n Date:	09/01/2016	Closed:	09/21/2016
- Diagnose ai	irhaa liaht h0(	101 u3003 na	erform pinpoin	ıt.	Parts List				Qty
test.r&r defec					Housing A				1.00
- Shop Suppli					Shop Sup		1.00		
	Но	urs 3.00		I abor	180.00	•	194.69	Total·	374.69
	:								
Workorder: Problem:	1611294 Has to jump	Meter: start in A.M	64049 . and arcing n	near coils		n Date: ng rough.	11/01/2016	Closed:	11/14/2016
- Test battery	and charging	g system.rep	lace bad batte	ery.	Parts List	:			Qty
- Diagnose ro	ough idle.repl	ace spark plu	igs and two		Battery 65	1.00			
coils.replace p	olug wires.cle	ar codes.			Battery	1.00			
	I clean throttle	e body and ir	nduction syste	m.flush	Spark Plug	g			16.00
injectors.	:				Coil Asy				2.00
- Shop Suppl	ies				Intake Cleaner Kit				1.00
					Injector CI	eaner			1.00
					Wire Assy	,			8.00
					Shop Sup	plies			1.00
	Ho :	urs 8.00		Labor:	480.00	Parts:	744.04	Total:	1,224.04
Workorder:	•								
	1612923	Meter:	64540		I	n Date:	12/02/2016	Closed:	12/19/2016
Problem:			64540 & right front f	ender	I	n Date:	12/02/2016	Closed:	12/19/2016
Problem: - Damage to	Damage to	front bumper	· & right front f	ender	I	n Date:	12/02/2016	Closed:	12/19/2016
Workorder:	Ho :	urs 8.00		Labor:	Injector Cl Wire Assy Shop Sup	eaner plies	744.04	Total:	1.00 8.00 1.00

Workorder: Problem:	1702661 P.M. service	Meter: and check	66294 engine light o	n.		In Date:	03/15/2017	Closed:	03/29/20	017
- P.m. Service	e.				Parts Lis	t				Qty
- Replace wo		lid shocks.			5w20 Eng					8.00
- Diagnose ch			erform pin po	int	Napagold					1.00
test.replace de	efective purge	e valve and f			Used Fire		ished			1.00
and perform e		-			20" Wiper	Blade				2.00
- Replace and		trailer plu					1.00			
- Inspect and					75w140 F		Lube			3.00
- Rotate and I					Friction M	lodifier				2.00
- Shop Suppli	es				Ptex Ultra	Grey 3oz	<u>z</u>			1.00
					Non-chlor	•				1.00
					Cap Asy					1.00
					Purge Va	lve				1.00
					Support					4.00
					Shop Sup	plies				1.00
	Ho	urs 9.00		Labor:	540.00		382.37	Total:	922.37	
Workorder: Problem:	1705165 Left brake lig	Meter: ght inop.	68043		l	In Date:	05/25/2017	Closed:	05/31/20	017
- Replace blo	wn left brake	light bulb.			Parts Lis	t				Qty
					Bulb					1.00
	Ho:	urs 0.50		Labor:	30.00	Parts:	0.78	Total:	30.78	
Workorder: Problem:	1705948 1 - Key(s) is	Meter: sued	68209		I	n Date:	06/15/2017	Closed:	06/15/20	017
- 1 - Key(s) is	sued				Parts Lis	t				Qty
- 3 (- ) -					Duplicate		(evs			1.00
	Ho	urs 0.30		Labor:	18.00		•	Total:	21.00	
Workorder:	1709238	Meter:	70422			In Date:	09/22/2017	Closed:	10/11/20	017
		Loud sound	under bed of	truck, Tra	•					
- P.m. service					Parts List C					
- Replace bot	h rear shocks	s due to worr	n out bushing	s with	3					7.00
new. - Replace def	octive trailer	connector di	ie to water co	rrosion						1.00
and rewire.	ective trailer t	comector at	ie io water co	11031011	Washer Fluid Concenti					1.00
- Replace fail	ed radio due	to no display	and sound.		22" Wiper					2.00
- Rotate and I					Shock Ab					2.00
- Shop Suppli					trailer plu					1.00
					Vinyl Elec	trical Tap	е			1.00
					Radio					1.00
					010	mlinn				1.00
		urs 6.50			Shop Sup 390.00	•	326.33		716.33	1.00

Workorder:	1800789	Meter:	72530			In Date:	01/23/2018	Closed:	01/25/2	018
Problem:	Left rear signa	ıl inop								
- Replace left	rear tail light bu	ulb and so	cket.retest.		Parts L					Qty
						TI Lgt Sock	et			1.00
		0.50			Bulb	Б. /	7.00	<b>.</b>	07.00	1.00
	Hours :	s 0.50		Labor:	30.00	Parts:	7.32	i otai:	37.32	
Workorder:	1805545 P.M. Service.L	Meter:	76018			In Date:	05/31/2018	Closed:	06/14/2	018
- P.m. service					Parts L	ist				Qty
	our tires .high s	sneed hal:	ance and nitro	ngen fill		Sensor Tir	e Pr			1.00
all tires.	our theo inight	speca ban		gori illi		ld Oil Filter	011			1.00
- Replace bot	h front bump st	ops.			. •	ngine Oil				7.00
- Test and rep	lace tag light b	ulbs.				ld Air Filter				1.00
- Perform fron	it end alignmen	t.				Fluid Conc				1.00
- Shop Suppli	es				Bumper		O. I.			2.00
					•	re X Refurb	ished			1.00
						Miniatures	.0.100			2.00
						ton Pvc Sw	С			1.00
					Pedal P					1.00
						er Blade				2.00
					Shop Su					1.00
					•	5r17 Tire				4.00
					Tire Dis	posal Fee				4.00
	Hours :	s 8.25		Labor:	495.00	•	785.17	Total:	1,280.1	7
Workorder:	1806910	Meter:	76596			In Date:	07/06/2018	Closed:	07/18/2	018
Problem:	replace rear gl	lass								
- set up repair	rs & reasett				Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	Hours	s 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder:	1811966 P.M. service a	Meter:	79611			In Date:	11/26/2018	Closed:	12/05/2	018
- P.m. service			ono nam.		Parte I	ict				Qty
	ance test . Che	rk for leek	s Recover fr	eon	Parts List					1.00
	and recharge to			GOII .	Napagold Oil Filter Napa Quart 5w20					7.00
	palance all four	-	-		•	er Blade				2.00
- Shop Suppli	es					v Shop 2				2.00
						gel Ac Stop	l k			1.00
					Shop St	•	LIX			1.00
	Hours	s 6.15		Labor:	412.05	• •	99.90	Total:	511.95	1.00

Workorder: 1903026 Meter: 82364 Problem: Wont start in the morning, Check front end s		03/22/2019
- Test battery and charging system.replace bad battrery.	Parts List	Qty
- Test drive truck for front end shaking complaint.replace	Coil	1.00
both front shocks.	Gas Grande Fleet Shoc	2.00
- Diagnose ticking noise underhood, ignition coil arcing.replace defective coil.	Battery	1.00
- Shop Supplies	Coil	1.00
	Shop Supplies	1.00
Hours 4.00 Labo	or: 268.00 Parts: 546.29 Total: 8	314.29
<b>Workorder:</b> 1905894 <b>Meter:</b> 83922	In Date: 06/04/2019 Closed: 0	06/13/2019
Problem: P.M. Serevice.		
- P.m. service.	Parts List	Qty
- R&i broken pintle pin.	Napagold Oil Filter	1.00
- Replace both rear missing bump stops .	5w20 Engine Oil	7.00
- Test strobe lights . Repair ground circuit for rear strobe	Used Fire X Refurbished	1.00
lights and retest.	22" Wiper Blade	2.00
- Rotate and high speed balance all four tires . Nitrofill all.	Washer Fluid Concentr	1.00
- Shop Supplies	oil auto	1.00
	Pintle Pin W/clip	1.00
	Real Suspension Bumpstops	2.00
	Shop Supplies	1.00
Hours 4.95 Labor:	or: 331.65 Parts: 137.97 Total: 4	69.62
Workorder: 1907679 Meter: 84393 Problem: Transition Prep Charge	In Date: 07/24/2019 Closed: 0	07/24/2019
- Transition Prep Charge		
Hours 2.00 Labo	or: 134.00 Parts: 0.00 Total: 1	34.00