

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 744262	Problem: PRE-DELIVERY INSPECTION				
Meter Reading: 0		Labor		Parts	
In Date: 09/18/2007	Close Date: 09/18/2007	Hours	Description		Quantity
- Pre-Delivery Inspection		2.00			
	Parts Charge: 0.00	Labor Charge:	110.00		

Workorder: 744628	Problem: MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER				
Meter Reading: 0		Labor		Parts	
In Date: 09/26/2007	Close Date: 09/26/2007	Hours	Description		Quantity
- Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable.		0.01			
	Parts Charge: 0.00	Labor Charge:	0.55		

Workorder: 744800	Problem: MAKE & APPLY DECALS. CHECK FLUIDS, BELTS, AND OPER				
Meter Reading: 0		Labor		Parts	
In Date: 09/28/2007	Close Date: 09/28/2007	Hours	Description		Quantity
- Make & Apply Decals. Check Fluids, Belts, And Operation As Applicable.		1.00			
	Parts Charge: 0.00	Labor Charge:	55.00		

Workorder: 744961	Problem: 9950				
Meter Reading: 0		Labor		Parts	
In Date: 10/01/2007	Close Date: 10/31/2007	Hours	Description		Quantity
- Lubed Complete Attach To 10164900		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge:	60.00		

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 745195		Problem: BLADES			
Meter Reading: 0		Labor		Parts	
In Date: 10/05/2007	Close Date: 10/15/2007	Hours	Description		Quantity
-	Replace Blades	3.00	SHOP SUPPLIES		1.00
-	Test Run		W45327 BLADE JOHN DEERE MX5		2.00
-	Shop Supplies				
Parts Charge: 58.65		Labor Charge: 30.00			
Workorder: 748185		Problem: 2 SETS OF BLADES			
Meter Reading: 0		Labor		Parts	
In Date: 12/06/2007	Close Date: 12/07/2007	Hours	Description		Quantity
-	Parts For Leighton		W45327 BLADE JOHN DEERE MX5		4.00
Parts Charge: 113.29		Labor Charge: 0.00			
Workorder: 832207		Problem: REPLACE SKIDS			
Meter Reading: 0		Labor		Parts	
In Date: 01/02/2008	Close Date: 01/15/2008	Hours	Description		Quantity
-	Replace Skids W/Woods Skids Cutoff Old Skids,Weld In Studs Install Woods Skids,Fabricate And Weld In Skid Stops.	8.00	SHOP SUPPLIES		1.00
			1/4X1X1X20 ANGLE		12.00
			TAIL WHEEL SUPPORT AW26200		1.00
-	Replace Tail Wheel Yoke.Cutoff Old Grind Smooth.Install New Yoke,Weld In Shaft.		PAINT TY25624		1.00
			57353 SKID WOODS BB6000		2.00
-	Shop Supplies				
Parts Charge: 476.20		Labor Charge: 120.00			
Workorder: 834619		Problem: 9950			
Meter Reading: 0		Labor		Parts	
In Date: 02/25/2008	Close Date: 02/26/2008	Hours	Description		Quantity
-	Lubed Complete.Ck Gear Box Oil Attended To 10164900	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00			

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 836101

Problem: REPAIR TAIL WHEEL

Meter Reading: 1428		Labor		Parts	
In Date: 03/27/2008	Close Date: 04/21/2008	Hours	Description		Quantity
-	Replace Tail Wheel Fork	2.00	WHEEL		1.00
-	Cut Off Fork And Reweld To Arm		SUPPORT		1.00
-	Shop Supplies		NUT		1.00
			SHOP SUPPLIES		1.00
			SCREW		1.00
			SPACER		1.00
			WASHER		1.00
Parts Charge: 470.12		Labor Charge: 60.00			

Workorder: 839625

Problem: MOWER CLUTCH BAD

Meter Reading: 1428		Labor		Parts	
In Date: 06/06/2008	Close Date: 06/18/2008	Hours	Description		Quantity
-	R/R Pto Shaft-Replace Worn Out-Overheated Clutch Assembly & Adj Tension	2.50	CLUTCH		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
-	Test Run				
Parts Charge: 419.08		Labor Charge: 30.00			

Workorder: 842944

Problem: TAG WHEEL

Meter Reading: 1428		Labor		Parts	
In Date: 08/18/2008	Close Date: 08/21/2008	Hours	Description		Quantity
-	Weld Wheel Mount Assy.Install Complete Assy To Mower Deck.	5.50	24H1433 WASHER TAIL WHEEL (JOHN DEERE)		1.00
-	To Clintmoore Sub Station.		AW26200 WHEEL SUPPORT (JOHN DEERE)		1.00
-	Shop Supplies		AW30454 BEAM TAIL WHEEL (JOHN DEERE)		1.00
			W39491 SPACER TAIL WHEEL (JOHN DEERE)		1.00
			57353 SKID WOODS BB6000		2.00
			19M7639 WHEEL BOLT (JOHN DEERE)		1.00
			SHOP SUPPLIES		1.00
			AW30714 TIRE/WHEEL ASSY (JOHN DEERE)		1.00
Parts Charge: 776.04		Labor Charge: 120.00			

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 843789

Problem: DRIVESHAFT

Meter Reading: 1428	Labor	Parts	
In Date: 09/04/2008	Hours	Description	Quantity
- Repair Drive Shaft	2.00	DRIVE SHAFT	1.00
- To South Srwkry Road		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	879.73	Labor Charge:	90.00

Workorder: 843943

Problem: MOWER DECK CLUTCH BAD

Meter Reading: 1428	Labor	Parts	
In Date: 09/09/2008	Hours	Description	Quantity
- Replace Clutch And Adj.	1.50	CLUTCH	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	443.98	Labor Charge:	90.00

Workorder: 846578

Problem: FORK

Meter Reading: 1428	Labor	Parts	
In Date: 10/31/2008	Hours	Description	Quantity
- Wheel Fork Lube.Replace Fork And Tail Wheel Support	6.00	24H1433 WASHER TAIL WHEEL (JOHN DEERE)	1.00
Lube.		SHOP SUPPLIES	1.00
- To Lox Road And To Clintmoore Sub Station.		AW26200 WHEEL SUPPORT (JOHN DEERE)	1.00
- Shop Supplies			
Parts Charge:	148.90	Labor Charge:	240.00

Workorder: 932154

Problem: 2 SETS OF BLADES

Meter Reading: 1428	Labor	Parts	
In Date: 01/02/2009	Hours	Description	Quantity
- Supply Blades	0.50	W45327 BLADE JOHN DEERE MX5	4.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	119.50	Labor Charge:	30.00

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 934934	Problem: 9950			
Meter Reading: 1428		Labor	Parts	
In Date: 03/10/2009	Close Date: 03/12/2009	Hours	Description	Quantity
- Lubed Complete.Ck Gear Box Oil Attached To 10164900		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 935910	Problem: SKID			
Meter Reading: 1428		Labor	Parts	
In Date: 04/01/2009	Close Date: 04/17/2009	Hours	Description	Quantity
- Skids For Mowing Crew		0.50	SHOP SUPPLIES	1.00
- Shop Supplies			FRT SEAT	1.00
			WOODS SKID	2.00
	Parts Charge: 654.29	Labor Charge: 30.00		

Workorder: 938998	Problem: 9950			
Meter Reading: 1428		Labor	Parts	
In Date: 06/15/2009	Close Date: 06/17/2009	Hours	Description	Quantity
- Lubed Complete Ck Gear Box Oil.Attached To 10164900		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge: 60.00		

Workorder: 940123	Problem: repair the drive shaft			
Meter Reading: 1		Labor	Parts	
In Date: 07/02/2009	Close Date: 09/15/2009	Hours	Description	Quantity
- Rebuild Clutch Assembly R&R Drive Shaft		7.00	CLUTCH DISC	2.00
- Miner Rd. Twice			CLUTCH PLATE	1.00
- Weld And Install Flag			SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 126.47	Labor Charge: 420.00		

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 944084 **Problem:** rebuild/replace tail wheel

Meter Reading: 1	Labor	Parts
In Date: 10/02/2009	Hours	Description
Close Date: 11/02/2009		Quantity
- Replace Hub Assy	1.00	AW30713 WHEEL HUB (JOHN DEERE)
- Shop Supplies		SHOP SUPPLIES
Parts Charge:	58.01	Labor Charge: 60.00

Workorder: 945583 **Problem:** 9950

Meter Reading: 1	Labor	Parts
In Date: 11/02/2009	Hours	Description
Close Date: 11/03/2009		Quantity
- On Site Lube	1.00	SHOP SUPPLIES
- Shop Supplies		
Parts Charge:	2.00	Labor Charge: 60.00

Workorder: 1001279 **Problem:** south

Meter Reading: 1	Labor	Parts
In Date: 02/04/2010	Hours	Description
Close Date: 02/23/2010		Quantity
- Repalce Chains And Guard	5.00	SHOP SUPPLIES
- Fm To Lantana F.S. And System 3		REAR SHIELD ASSY
- Shop Supplies		
Parts Charge:	229.83	Labor Charge: 180.00

Workorder: 1002219 **Problem:** pm

Meter Reading: 1	Labor	Parts
In Date: 03/03/2010	Hours	Description
Close Date: 03/04/2010		Quantity
- Pm Deck	5.00	AW30454 BEAM TAIL WHEEL (JOHN DEERE)
- Replace Blades		24H1433 WASHER TAIL WHEEL (JOHN DEERE)
- R&R Tail Wheel Forklift		AW26200 WHEEL SUPPORT (JOHN DEERE)
- Weld Repair Fork To Arm		SHOP SUPPLIES
- Shop Supplies		W45327 BLADE JOHN DEERE MX5
Parts Charge:	389.94	Labor Charge: 300.00

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1005900	Problem: mower deck flag			
Meter Reading: 0		Labor	Parts	
In Date: 06/04/2010	Close Date: 06/16/2010	Hours	Description	Quantity
<hr/>				
- Replace Slow Moving Flag		0.30		
	Parts Charge: 0.00	Labor Charge:	18.00	

Workorder: 1006999	Problem: gearbox broken			
Meter Reading: 0		Labor	Parts	
In Date: 07/02/2010	Close Date: 07/15/2010	Hours	Description	Quantity
<hr/>				
- Replaced Damaged Gear Box, Fill W/Fluid And Reinstall Stump Jumper.		3.00	SHOP SUPPLIES	1.00
			GEAR BOX ASSY	1.00
- Clean Deck				
- Shop Supplies				
	Parts Charge: 1,228.32	Labor Charge:	180.00	

Workorder: 1011426	Problem: 9950			
Meter Reading: 0		Labor	Parts	
In Date: 10/15/2010	Close Date: 10/18/2010	Hours	Description	Quantity
<hr/>				
- On Site Lube		1.00	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge:	60.00	

Workorder: 1011784	Problem: blades			
Meter Reading: 0		Labor	Parts	
In Date: 10/21/2010	Close Date: 10/22/2010	Hours	Description	Quantity
<hr/>				
- Replace Blades		3.50	SHOP SUPPLIES	1.00
- Fm To Hypo.			W38054 BLADE BOLT JOHN DEERE	2.00
- Shop Supplies			W45327 BLADE JOHN DEERE MX5	2.00
			W50958 BLADE LOCKNUT JOHN DEERE	2.00
	Parts Charge: 175.71	Labor Charge:	210.00	

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1101134

Problem: 9103

Meter Reading: 0	Labor	Parts	
In Date: 01/31/2011	Hours	Description	Quantity
- Pm Service	7.30	8610 SAFETY FLAG (PAR-AIDE)	1.00
- Replace Blades		W45327 BLADE JOHN DEERE MX5	2.00
- Clean Deck And Touch Up Paint		57353 SKID WOODS BB6000	2.00
- Replace Skids		W50958 BLADE LOCKNUT JOHN DEERE	2.00
- Replace Flag		SHOP SUPPLIES	1.00
- Shop Supplies		W38054 BLADE BOLT JOHN DEERE	2.00
		W38627 BLADE WASHER JOHN DEERE MX5	2.00
		GREASE NLGI 2	1.00
Parts Charge:	692.55	Labor Charge:	438.00

Workorder: 1109975

Problem: pm servie

Meter Reading: 0	Labor	Parts	
In Date: 09/19/2011	Hours	Description	Quantity
- Pm Service	2.00	75W140 GEAR LUBE SYNTHETIC (MC XY75W140QL)	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		GEARBOX DIPSTICK	1.00
Parts Charge:	53.96	Labor Charge:	120.00

Workorder: 1200740

Problem: 9103

Meter Reading: 0	Labor	Parts	
In Date: 01/24/2012	Hours	Description	Quantity
- Pm Service	5.20	SHOP SUPPLIES	1.00
- Replace Blades		W45327 BLADE JOHN DEERE MX5	2.00
- Wash Deck		W50958 BLADE LOCKNUT JOHN DEERE	2.00
- Replace Pto Shaft		W38054 BLADE BOLT JOHN DEERE	2.00
- Shop Supplies		W38627 BLADE WASHER JOHN DEERE MX5	2.00
		DRIVESHAFT	1.00
Parts Charge:	1,405.99	Labor Charge:	312.00

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1204880		Problem: blades	
Meter Reading: 0		Labor	Parts
In Date: 05/25/2012	Close Date: 05/30/2012	Hours	Description
			Quantity
- Secure Parts For Dept		0.50	W45327 BLADE JOHN DEERE MX5
- Shop Supplies			SHOP SUPPLIES
	Parts Charge: 95.35	Labor Charge: 30.00	2.00
			1.00

Workorder: 1206615		Problem: 9950	
Meter Reading: 0		Labor	Parts
In Date: 07/16/2012	Close Date: 07/17/2012	Hours	Description
			Quantity
- On Site Lube		1.00	SHOP SUPPLIES
- Shop Supplies			
	Parts Charge: 2.00	Labor Charge: 60.00	1.00

Workorder: 1206654		Problem: blades	
Meter Reading: 0		Labor	Parts
In Date: 07/17/2012	Close Date: 07/24/2012	Hours	Description
			Quantity
- Secure Blades For Department		0.50	SHOP SUPPLIES
- Shop Supplies			W45327 BLADE JOHN DEERE MX5
	Parts Charge: 95.35	Labor Charge: 30.00	1.00
			2.00

Workorder: 1209871		Problem: 9950	
Meter Reading: 0		Labor	Parts
In Date: 10/15/2012	Close Date: 10/23/2012	Hours	Description
			Quantity
- On Site Lube		1.00	SHOP SUPPLIES
- Shop Supplies			
	Parts Charge: 2.00	Labor Charge: 60.00	1.00

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1209945		Problem: Blades			
Meter Reading: 0		Labor		Parts	
In Date: 10/17/2012	Close Date: 10/18/2012	Hours	Description		Quantity
- Secure Parts		0.50	W45327 BLADE JOHN DEE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 104.72		Labor Charge: 30.00			
Workorder: 1211259		Problem: 9950			
Meter Reading: 0		Labor		Parts	
In Date: 11/20/2012	Close Date: 11/28/2012	Hours	Description		Quantity
- On Site Lube		1.00	75W140 GEAR LUBE SYNT		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge: 47.30		Labor Charge: 60.00			
Workorder: 1211719		Problem: change mower head gear lube			
Meter Reading: 0		Labor		Parts	
In Date: 12/04/2012	Close Date: 12/05/2012	Hours	Description		Quantity
- Change Gear Lube And Reseal Box Lube Charged To Wo 1211719		4.00	SHOP SUPPLIES		1.00
- To Ibis					
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 240.00			

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1303191

Problem: 9103

Meter Reading: 0		Labor	Parts	
In Date: 04/02/2013	Close Date: 04/23/2013	Hours	Description	Quantity
- Pm Service		12.50	BRACE	2.00
- Replace Blades			BRACE	2.00
- Replace Flag, Pole, Lift Arms, Tail Wheel, Beam, Fork			SCREW	2.00
And Braces			NUT	4.00
- Shop Supplies			AW30714 TIRE-WHEEL AS	1.00
			AW26200 WHEEL SUPPORT	1.00
			AW30454 BEAM TAIL WHE	1.00
			A31869 LOCKNUT JOHN D	3.00
			CAP SCREW	2.00
			19M7639 WHEEL BOLT JO	1.00
			W45327 BLADE JOHN DEE	2.00
			W38054 BLADE BOLT JOH	2.00
			SHOP SUPPLIES	1.00
			12345841 GEAR OIL SYN	2.00
			W50958 BLADE LOCKNUT	2.00
			W38627 BLADE WASHER J	2.00
			W39491 SPACER TAIL WH	1.00
			730-079 FLAG STAFF PA	1.00
			BUSHING	4.00
			WHEEL WASHER	1.00
			8610 SAFETY FLAG PAR-	1.00
	Parts Charge: 1,642.31	Labor Charge: 750.00		

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1306045

Problem: pto shaft

Meter Reading: 0		Labor		Parts	
In Date: 06/18/2013	Close Date: 07/24/2013	Hours	Description		Quantity
-	Repair 2 Pto Shafts	6.00	WHEEL WASHER		1.00
-	Replace Rear Wheel		SHOP SUPPLIES		1.00
-	Weld Fork To Trailer Arm Via Washer		WHEEL SUPPORT		1.00
-	Shop Supplies		SHIELD		2.00
			CHAIN LINK		2.00
			TAIL WHEEL		1.00
			OUTER TUBE		2.00
			LOCKING BEARING		1.00
			SAFETY SHIELD		2.00
			INNER TUBE		2.00
			CAP		2.00
			SHIELD		4.00
Parts Charge: 1,513.91		Labor Charge: 360.00			

Workorder: 1309684

Problem: needs blades/ pto shaft

Meter Reading: 0		Labor		Parts	
In Date: 09/25/2013	Close Date: 10/18/2013	Hours	Description		Quantity
-	Parts Only	2.00	U-JOINT		1.00
-	Replace Clutch And Ujoint		W45327 BLADE JOHN DEE		2.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			CLUTCH ASSY		1.00
Parts Charge: 747.54		Labor Charge: 120.00			

Workorder: 1309765

Problem: flag pole

Meter Reading: 0		Labor		Parts	
In Date: 09/26/2013	Close Date: 10/03/2013	Hours	Description		Quantity
-	Replace Flag Pole And Replair Chain Guard	3.50	8610 SAFETY FLAG PAR-		1.00
-	To Dubois Park		FLAG POLE		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
Parts Charge: 60.79		Labor Charge: 210.00			

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1310508

Problem: broken tail wheel

Meter Reading: 0	Labor	Parts	
In Date: 10/18/2013	Hours	Description	Quantity
- Disassemble For Weld Repair	2.00	WHEEL SUPPORT	1.00
- Weld Repair		WHEEL WASHER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	171.96	Labor Charge:	120.00

Workorder: 1311189

Problem: Weld Cracks

Meter Reading: 0	Labor	Parts	
In Date: 11/04/2013	Hours	Description	Quantity
- Install Flag Pole And Weld Cracks In Mower Deck	2.00	FLAG POLE FIBERGLASS 7	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		RED FLAG	1.00
Parts Charge:	59.21	Labor Charge:	120.00

Workorder: 1311860

Problem: 9950

Meter Reading: 0	Labor	Parts	
In Date: 11/25/2013	Hours	Description	Quantity
- On Site Lube	2.00	SHOP SUPPLIES	1.00
- To Library On Orange Blvd.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1401077

Problem: pm service

Meter Reading: 0 In Date: 01/31/2014	Close Date: 03/24/2014	Labor Hours	Description	Parts	Quantity
- Pm		14.50	SHOP SUPPLIES		1.00
- R&R Blades			12345841 GEAR OIL SYN		3.00
- R&R Front Chain Gaurd Assembly. R&R Rear Chain			WHEEL SUPPORT		1.00
Links Cut By Hand. Weld Pivot Wheel Mount			W50958 BLADE LOCKNUT		2.00
- R&R Skids			W45327 BLADE JOHN DEE		2.00
- Test Run			678131 1-4IN GRADE 4		36.00
- Shop Supplies			W38627 BLADE WASHER J		2.00
			SAFETY GUARD		1.00
			SKID SHOE		2.00
			W38054 BLADE BOLT JOH		2.00
Parts Charge: 1,262.12		Labor Charge: 870.00			

Workorder: 1404796

Problem: Tail Wheel

Meter Reading: 0 In Date: 05/15/2014	Close Date: 06/11/2014	Labor Hours	Description	Parts	Quantity
- Install Tail Wheel		5.00	SHOP SUPPLIES		1.00
- Onsite Lube			WHEEL WASHER		1.00
- To Jupiter Yard			WASHER		1.00
- Shop Supplies			WHEEL SUPPORT		1.00
			24H1433 WASHER TAIL W		1.00
			TAIL WHEEL		1.00
Parts Charge: 363.27		Labor Charge: 300.00			

Workorder: 1412080

Problem: 9950

Meter Reading: 0 In Date: 12/02/2014	Close Date: 12/03/2014	Labor Hours	Description	Parts	Quantity
- Onsite Lube		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

1/3/2017
4:30:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171034 2007 JOHN DEERE MX5 Mower, 5 Ft. Lift Type Rotary

Workorder: 1611394

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/03/2016	Hours	Description	
- Transition Prep Charge	2.00		
Parts Charge: 0.00	Labor Charge: 0.00		

Total Parts Charges:	15,106.39	Total Labor Charges:	7,143.55	Total Comm. Charges:	0.00
----------------------	------------------	----------------------	-----------------	----------------------	-------------