

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1001592	Problem: Pre Delivery Inspection			
Meter Reading: 0	Labor	Parts		
In Date: 02/12/2010	Close Date: 02/12/2010	Hours	Description	Quantity
- Pre Delivery Inspection		2.00		
Parts Charge:	0.00	Labor Charge:	120.00	

Workorder: 1101299	Problem: pm service			
Meter Reading: 84	Labor	Parts		
In Date: 02/02/2011	Close Date: 02/09/2011	Hours	Description	Quantity
- Pm Service		5.00	SHOP SUPPLIES	1.00
- Wash			OIL FILTER	1.00
- Shop Supplies			6438 AIR FILTERFRM CA9550 WIX 46438	1.00
			15/40 OIL	4.00
Parts Charge:	32.21	Labor Charge:	300.00	

Workorder: 1200946	Problem: pm service			
Meter Reading: 172	Labor	Parts		
In Date: 01/30/2012	Close Date: 02/08/2012	Hours	Description	Quantity
- Pm Service		6.50	SHOP SUPPLIES	1.00
- Wash			BLADE BOLTS	3.00
- Replace Three Blades Sys			OIL FILTER	1.00
- Shop Supplies			BLADES	3.00
			6438 AIR FILTERFRM CA9550 WIX 46438	1.00
			15/40 OIL	4.00
Parts Charge:	144.24	Labor Charge:	390.00	

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1301016

Problem: PM / Rear tire leaks

Meter Reading: 350	Labor	Parts	
In Date: 01/29/2013	Hours	Description	Quantity
- Pm	9.50	OIL FILTER PH7317	1.00
- R/R Front Caster Wheel Asm		GROUP 26 BATTERY ACD	1.00
- R/R 3 Blades		Freight Charge	1.00
- R/R Battery		AW68 HYDRO FLUID HYDR	4.00
- Hyd Service		NAPAGOLD FUEL FILTER	1.00
- R/R Tire Clean Bead Area, R/R Valve Stem		NAPA HYDRAULIC FILTR	1.00
- Shop Supplies		ROTARY BLADE	3.00
		NAPAGOLD AIR FILTER	1.00
		15-40 OIL	4.00
		15-6.00X6 RIBBED TIRE	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	873.17	Labor Charge:	570.00

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1307901

Problem: PM see request

Meter Reading: 395 In Date: 08/07/2013	Close Date: 08/29/2013	Labor Hours	Description	Parts	Quantity
- Pm		12.00	FUEL CAP		2.00
- Replace Two Deck Belts And Readjust			15-40 OIL		4.00
- Wash Eqpt			BOLT RETURN, NEUTRAL		2.00
- Replace Caster Wheels			NAPAGOLD FUEL FILTER		1.00
- Replace Starter-Replace Both Ign Sys Safety Switch			SHOP SUPPLIES		1.00
- Fix Steering Replace Broken Links Readjust Both			SHAFT		2.00
Steering Arms And Pump			V-BELT		1.00
- Replace Fuel Pump Repalce 2 Fuel Lines Caps Add Inline			BRAKE CLEANER		1.00
Fuel Filter Due To Dirt			GAUGE OIL		1.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			SHAFT,ROLLER		1.00
			Freight Charge		1.00
			NAPAGOLD AIR FILTER		1.00
			SWITCH		2.00
			FUEL PUMP		1.00
			NAPAGOLD FUEL FILTER		1.00
			GUIDE		1.00
			DECK ROLLER		2.00
			Freight Charge		1.00
			STARTER ASSY		1.00
			BOLT		2.00
			ROLLER		1.00
			V-BELT		1.00
	Parts Charge: 1,568.61	Labor Charge: 720.00			

Workorder: 1401181

Problem: 9950

Meter Reading: 406 In Date: 02/04/2014	Close Date: 02/06/2014	Labor Hours	Description	Parts	Quantity
- On Site Lube And Remover Covers To Blow Out Radiator		4.00	SHOP SUPPLIES		1.00
- Fm To Riverbend			WD40 16OZ		1.00
- Shop Supplies			1CART PALLADIUM 2 GRS		1.00
	Parts Charge: 15.67	Labor Charge: 240.00			

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1403545

Problem: Onsitelube

Meter Reading: 409	Labor	Parts	
In Date: 04/10/2014	Hours	Description	Quantity
- Onsite Lube	2.00	SHOP SUPPLIES	1.00
- Blow Out Radiator			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1404684

Problem: Onsite Lube

Meter Reading: 409	Labor	Parts	
In Date: 05/13/2014	Hours	Description	Quantity
- Onsite Lube	4.00	SHOP SUPPLIES	1.00
- Blow Out Coolers			
- To Riverbend			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	240.00

Workorder: 1405442

Problem: Onsite Lube

Meter Reading: 414	Labor	Parts	
In Date: 06/03/2014	Hours	Description	Quantity
- Onsite Lube. Blow Off Deck	2.50	SHOP SUPPLIES	1.00
- Blow Out Radiator			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	150.00

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1408798

Problem: pm service

Meter Reading: 424 In Date: 09/02/2014	Close Date: 09/25/2014	Labor Hours	Description	Parts	Quantity
- Pm Service		11.00	SHOP SUPPLIES		1.00
- Hyd Service			NAPAGOLD FUEL FILTER		1.00
- R/R 3 Blades			KEY SWITCH ASSY		1.00
- R/R Bearings And Races R/F Caster Wheel			SPACER		2.00
- R/R Chute And Hardware			NAPAGOLD OIL FILTER		1.00
- R/R Both Deck Tensioners Pulleys			STOP SOLENOID		1.00
- Wash Mud, Debris And Grass Off Deck And Engine Compartment			SEAL		2.00
- Diag. Stalling R/R Key Switch Shutdown Solenoid			NAPAGOLD FUEL FILTER		1.00
- Shop Supplies			TORSION SPRING		1.00
			SPACER		1.00
			IDLER PULLEY		1.00
			AW68 HYDRO FLUID HYDR		4.00
			BEARING		2.00
			NAPAGOLD AIR FILTER		1.00
			RUBBER DEFLECTOR ASSY		1.00
			15-40 OIL		4.00
			SCREW		1.00
			FRONT CASTER SPACER		1.00
			IDLER PULLEY		1.00
			NAPA HYDRAULIC FILTR		1.00
			SCREW		1.00
			ROTARY BLADE		3.00
	Parts Charge:	967.49	Labor Charge:	660.00	

Workorder: 1500373

Problem: replace dryrot tire (tire only)

Meter Reading: 437 In Date: 01/12/2015	Close Date: 01/15/2015	Labor Hours	Description	Parts	Quantity
- Replace Tire And Valve Stem		1.00	TIRE DISPOSAL FEE		1.00
- Shop Supplies			24X12.00-12 TURF TRAC 6P TIRE		1.00
			SHOP SUPPLIES		1.00
	Parts Charge:	195.75	Labor Charge:	60.00	

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1500811

Problem: NEEDS TIRE/ (tire only)

Meter Reading: 437	Labor	Parts	
In Date: 01/23/2015	Hours	Description	Quantity
- Replace Tire	1.00	TIRE DISPOSAL FEE	1.00
- Shop Supplies		24X12.00-12 TURF TRAC 6P TIRE	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	195.75	Labor Charge:	60.00

Workorder: 1509350

Problem: pm service/ fan belt

Meter Reading: 479	Labor	Parts	
In Date: 09/16/2015	Hours	Description	Quantity
- Pm	8.50	NAPAGOLD AIR FILTER	1.00
- Replace Parking Brake Caliers And Pads		NAPAGOLD OIL FILTER	1.00
- Replace Fan Belt Worn		AW68 HYDRO FLUID HYDR	4.00
- Adjust Steering Linkage		LEFT BRAKE CALIPER	1.00
- Shop Supplies		NAPA GAL 15W40	1.00
		NAPAGOLD FUEL FILTER	1.00
		RIGHT BRAKE CALIPER	1.00
		SHOP SUPPLIES	1.00
		BRAKE CLEANER	1.00
		V-BELT	1.00
		NAPA HYDRAULIC FILTR	1.00
		NAPAGOLD FUEL FILTER	1.00
Parts Charge:	551.76	Labor Charge:	510.00

1/3/2017
4:31:46PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10180781 2010 TORO 7210 Mower, 72" Riding, Ztr, Side Discharge

Workorder: 1606225 **Problem:** pm/ dead battery/ alternator noise/ see notes

Meter Reading: 492		Labor	Parts	
In Date: 06/17/2016	Close Date: 07/26/2016	Hours	Description	Quantity
- Pm Service		22.00	NAPAGOLD AIR FILTER	1.00
- Hydraulic Service			BRAKE CLEANER	1.00
- Test And Replace Failed Battery			AW68 HYDRO FLUID HYDR	4.00
- Replace Deck Belts And Adjust Alt Belt			V-BELT	1.00
- Service Pto Gear Box			15-40 OIL	7.00
- R/R Deck Control Lever, Free Up, Clean And Lube			V-BELT	1.00
- Adjust Steering Control Levers For Creep			NAPAGOLD FUEL FILTER	1.00
- Diag. And Replace Righjt Side Safety Switch Steering			SWITCH	1.00
- Diag. And Replace Seat Safety Switch And Seat Bottom			NAPA HYDRAULIC FILTR	1.00
- Diag. Time Deck Lift Mech. R/R Inspect Control Valve.			NAPAGOLD OIL FILTER	1.00
- Adjust Deck			NAPA GAL 15W40	4.00
- Shop Supplies			NAPA GAL 15W40	4.00
			1QT SYNGEAR OIL 75-90	1.00
			SHOP SUPPLIES	1.00
			BATTERY	1.00
			BOTTOM CUSHION KIT	1.00
			BAIL SWITCH	1.00
			NAPA QT 15W40	4.00
	Parts Charge:	756.25	Labor Charge:	1,320.00

Workorder: 1612443 **Problem:** Transition Prep Charge

Meter Reading: 513		Labor	Parts	
In Date: 12/05/2016	Close Date: 12/05/2016	Hours	Description	Quantity
- Transition Prep Charge		2.00		
	Parts Charge:	0.00	Labor Charge:	120.00

Total Parts Charges:	5,306.90	Total Labor Charges:	5,580.00	Total Comm. Charges:	0.00
----------------------	-----------------	----------------------	-----------------	----------------------	-------------