10193108 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 745401 Meter: In Date: 10/10/2007 Closed: 10/10/2007 Problem: PRE-DELIVERY INSPECTION - Pre-delivery Inspection Labor: 120.00 Parts: 0.00 Total: 120.00 Hours 2.00 Workorder: 746836 Meter: 332 In Date: 11/06/2007 Closed: 11/07/2007 Problem: INSTALL TOOL BOX - Install Toolbox In Back Of Bed. **Parts List** Qty - Shop Supplies **Shop Supplies** 1.00 Tbsd72lp Tool Box (united Welding) 1.00 Hours 1.00 Labor: 60.00 Parts: 429.20 Total: 489.20 838034 Workorder: Meter: 5581 In Date: 05/05/2008 Closed: 05/08/2008 Problem: P.M SERVICE - Pm Service **Parts List** Qty - Rotate And High Speed Balance 4 Tires.refill W/nitrogen **Shop Supplies** 1.00 - Shop Supplies 1372 Oil Filter Frm Ph2 Wix 51372 1.00 G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00 5w20 Engine Oil 7.00 Hours 3.75 Labor: 225.00 Parts: 35.99 Total: 260.99 Workorder: 839608 Meter: 0 In Date: 05/08/2008 Closed: 06/06/2008 Problem: MURPHYS PAINT & BODY SHOP - Murphys Paint & Body Shop Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00 Workorder: 844990 10/01/2008 Closed: 10/03/2008 Meter: 11479 In Date: Problem: P.M. SERVICE*CHECK LITES - P/m Service **Parts List** Qty - L/r Stop Lite Inop R&r Bulb Check Op/ok **Shop Supplies** 1.00 - Shop Supplies Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00 1372 Oil Filter Frm Ph2 Wix 51372 1.00 3243 Fuel Filter Use Mtc Fg1083 1.00 5w20 Engine Oil 7.00 1.00 Used Firex Refurbed Fire Extingshers

Labor: 183.00

Parts: 83.99

Total: 266.99

Hours 3.05

Workorder: Problem:	936225 P.M. SERVIO	Meter:	16641			In Date:	04/08/2009	Closed:	04/28/20	009
- P/m Service					Parts Lis	t				Qty
- Shop Suppli	es				Shop Sup	plies				1.00
					1372 Oil	Filter Frm	n Ph2 Wix 51	372		1.00
					5w20 Eng	gine Oil				7.00
					31-20 Wip	per Blades	s 20" Blade			2.00
					Air Fresh	ener				1.00
	Hou :	ırs 2.75		Labor:	165.00	Parts:	54.01	Total:	219.01	
Workorder: Problem:	946115 P.M. service	Meter:	22985			In Date:	11/17/2009	Closed:	11/18/20	009
- P/m. Service	Э				Parts Lis	t				Qty
- Shop Suppli	es				Shop Sup	plies				1.00
					1372 Oil	Filter Frm	n Ph2 Wix 510	372		1.00
							e Mtc Fg1083			1.00
					Ca10262	Air Filter I	Mtc Fa1883 W	/ix 49883		1.00
					5w20 Eng					7.00
							ed Fire Extings			1.00
	Hou :	irs 2.75		Labor:	165.00	Parts:	100.90	Total:	265.90	
Workorder: Problem:	1003605 WILL NOT S	Meter: TART	25152			In Date:	04/07/2010	Closed:	04/08/20	010
- Check Starte	er Problum &	Charging S	System Bad I	Battery.	Parts Lis	t				Qty
- R & R Batte	ry.				Shop Sup	plies				1.00
- Shop Suppli	es				Group 65	Battery (r	ntc Bxt-65-850	0)		1.00
	Hou :	ırs 1.50		Labor:	90.00	Parts:	133.82	Total:	223.82	
Workorder: Problem:	1004892 PM SERVICI	Meter:	26024			In Date:	05/12/2010	Closed:	05/20/20	010
- pm service .					Parts Lis	t				Qty
- test drive .					Shop Sup	plies				1.00
- Shop Suppli	es				1372 Oil	Filter Frm	n Ph2 Wix 510	372		1.00
					5w20 Eng	gine Oil				7.00
					31-20 Wip	per Blades	s 20" Blade			2.00
					Air Fresh	ener				1.00
	Hou	ırs 3.25		Labor:	195.00	Parts:	56.86	Total:	251.86	

	1013741 pm service.	Meter:	29268			In Date:	12/14/2010	Closed:	01/05/2	011
- pm service					Parts Lis	t				Qty
- dismount & n	nount & ballar	nce tires ./ o	commercial i	repair	Shop Sup	plies				1.00
- Shop Supplie				•		•	n Ph2 Wix 513	372		1.00
					5w20 Eng	jine Oil				7.00
							d Fire Extings	hers		1.00
							s 20" Blade			2.00
					Tires / Lt2	245/75r-17	,			4.00
					Tire Fee					4.00
	Hou :	rs 3.05		Labor:	183.00	Parts:	809.85	Total:	992.85	
	1106906	Meter:	31639			In Date:	06/29/2011	Closed:	07/11/2	011
Problem:	pm service									
- Pm Service					Parts Lis	t				Qty
- test drive					Shop Sup	plies				1.00
- Shop Supplie	es				1372 Oil	Filter Frm	n Ph2 Wix 513	372		1.00
					3243 Fue	l Filter Us	e Mtc Fg1083			1.00
					Ca10262	Air Filter I	Mtc Fa1883 W	ix 49883		1.00
					5w20 Eng	gine Oil				7.00
					5lb Firex	Abc Stock	# 340280001			1.00
					31-20 Wip	oer Blades	s 20" Blade			2.00
	Hou :	rs 3.25		Labor:	195.00	Parts:	106.67	Total:	301.67	
	1200073 Pm Service	Meter:	33034			In Date:	01/03/2012	Closed:	02/07/2	012
- pm service					Parts Lis	t				Qty
- throttle body	service				Shop Sup	plies				1.00
- rotate & bala	nce tires				1372 Oil Filter Frm Ph2 Wix 51372					1.00
- seal left door	/ weather sea	al			5w20 Engine Oil					7.00
pick up at deShop Supplie		ty			31-20 Wi	oer Blades	s 20" Blade			2.00
		rs 6.75		Labor:	405.00	Parts:	45.53	Total:	450.53	
Workorder: Problem:	1212182 Pm service	Meter:	35857			In Date:	12/19/2012	Closed:	12/26/2	012
- Pm service					Parts Lis	t				Qty
- Rotate and b	alance tires				Used Fire		ed F			1.00
- Test drive					Napa Qua					7.00
- Shop Supplie	es				Ph2 Oil F		h			1.00
					31-20 Wi	oer Blades	s 20			2.00
					Ford Fuel					1.00
					Shop Sup	plies				1.00

Workorder: Problem:	1306047 Pm service	Meter:	38261		I	n Date:	06/18/2013	Closed:	06/25/201	13
- Pm service.					Parts List					Qty
- Rotate and I	palance tires.				Napa Qua					7.00
- Test drive.					Napagold					1.00
- Shop Suppli	es				31-20 Wip		s 20		:	2.00
					Washer Fl					1.00
					Napagold	Fuel Filte	er			1.00
					Shop Sup	plies				1.00
	Hou	rs 4.25		Labor:	255.00	Parts:	50.68	Total:	305.68	
Workorder: Problem:	1401022 Pm service.	Meter:	41657		I	n Date:	01/30/2014	Closed:	02/10/201	14
- Pm service.					Parts List	:				Qty
- Replace floo	or mats. Replac	ce asset #'s	S.		Napa Qua	rt 5w20			-	7.00
- Rotate and b	palance tires.				Napagold	Oil Filter				1.00
- Test drive.					Napagold	Fuel Filte	er			1.00
- Shop Suppli	es				Wiper Blad	de			:	2.00
					Used Fire	X Refurb	ished			1.00
					Floor Mat-	2pc Rub	Bk			1.00
					Shop Sup	plies				1.00
	Hou	rs 5.25		Labor:	315.00	Parts:	93.25	Total:	408.25	
Workorder: Problem:	1401463 LR brake ove	Meter: r heating.	41773		I	n Date:	02/13/2014	Closed:	02/21/201	14
- Replace seiz	zed calipers pa	ads and rot	ors.		Parts List	:				Qty
- Test drive.					Disc Brake	e Pads				1.00
- Shop Suppli	es				Reman Br	ake Calip	per			1.00
					Reman Br	ake Calip	per			1.00
					Brake Rot	or			2	2.00
					1401 Bral	ke Fluid E	3ra		:	2.00
					Shop Sup	plies				1.00
	Hou	rs 4.50		Labor:	270.00	Parts:	500.09	Total:	770.09	
Workorder: Problem:	1404667 Vehicle shake	Meter:	44806		ı	n Date:	05/13/2014	Closed:	05/21/201	14
	re. Tire plys se	eperating o	n tire. No si	dewall	Parts List	:				Qty
damage noted					17963649	2 Lt245-7	75r17			1.00
- Inspect front	end.				Shop Sup	plies				1.00
- Test drive.					Tire Dispo	sal Fee				1.00
- Shop Suppli		rs 2.00		Labor:	120.00	Parts:	247.77	Total·	367.77	
	1.154				5.55			. Juli.		

Workorder: 1405773 Meter: 45798 Problem: Replace LF tire.		lı	n Date:	06/12/2014	Closed:	06/23/2014
- Lf tire separating in tread and sidewall area. Repla	ce tire.	Parts List				Qty
- Test drive. Reset tpms light.		17963649	2 Lt245-7	′5r17		1.00
- Shop Supplies		Shop Supp	olies			1.00
		Tire Dispo				1.00
Hours 1.50 :	Labor:			247.77	Total:	337.77
Workorder: 1406766 Meter: 46469 Problem: Pm service. Check tires.		lı	n Date:	07/09/2014	Closed:	07/15/2014
- Pm service.		Parts List				Qty
- Rotate and balance tires.		Napa Qua	rt 5w20			7.00
- Replace two tires. Tread plys separating.		Napagold	Oil Filter			1.00
- Test drive.		Napagold	Air Filter	•		1.00
- Shop Supplies		Wiper Blad	de			2.00
		Washer Fl	uid Conc	entr		1.00
		Lt245/75r1	7 Hanko	ok Tire		2.00
		Shop Supp	olies			1.00
		Tire Dispo	sal Fee			2.00
Hours 6.25	Labor:	375.00	Parts:	606.44	Total:	981.44
Workorder: 1411334 Meter: 51216 Problem: Pm service.		l:	n Date:	11/13/2014	Closed:	12/09/2014
- Pm service		Parts List				Qty
- Check engine light on. Check dtc's. Replace shorte	ed Rf Abs	Brake Clea	aner			2.00
sensor.		Syn-atf Tra	ans Fluid	S		7.00
- Trans service.		5w20 Oil E	Bulk			7.00
- Battery failed load test. Replace battery.		Napagold	Oil Filter			1.00
- Check charging system.		Wiper Blad	de			2.00
- Shop Supplies		Washer Fl	uid Conc	entr		1.00
		Used Fire	X Refurb	ished		1.00
		Sensor As	y			1.00
		Trans Pan	Gasket			1.00
		Trans Filte	er			1.00
		Battery				1.00
		Shop Supp	olies			1.00
Hours 8.75	Labor:	525.00	Parts:	391.54	Total:	916.54

Workorder: 15066 Problem: Pm s		Meter:	59366			In Date:	07/06/2015	Closed:	07/07/2015	5
- Pm service.					Parts Lis	t			(Qty
- Rotate and balanc	e tires.				5w20 Oil	Bulk				.00
- Test drive.					Napagolo	Oil Filter			1	.00
- Shop Supplies						Fuel Filte	er		1	.00
						Air Filter			1	.00
					Wiper Bla				2	2.00
					Shop Sup	plies			1	.00
	Hours	s 4.25		Labor:	255.00	-	48.47	Total:	303.47	
Workorder: 15120		Meter:	64198			In Date:	12/16/2015	Closed:	12/21/2015	5
Problem: Pm s	ervice,cn	еск ргаке	S.							
- Pm service.					Parts Lis	t			(Qty
- Rotate and balanc	e tires.				5w20 Oil	Bulk			7	7.0 0
- Test drive 2x's.					Napagolo	Oil Filter			1	.00
- Abs light on. Chec			1233 presei	nt. Cler	20" Wipe	r Blade			2	2.00
dtc's. Replace If whe	el speed	sensor.			Napagolo	Fuel Filte	er		1	.00
- Shop Supplies					Mac Wite	Lithium G	Bres		1	.00
					Sensor A	sy			1	.00
					Shop Sup	plies			1	.00
	Hours :	5.75		Labor:	345.00	Parts:	119.26	Total:	464.26	
Workorder: 16062	272	Meter:	69317			In Date:	06/20/2016	Closed:	06/28/2016	6
Problem: Pm s	ervice.									
- Pm service.					Parts Lis	t			(Qty
- Replace front tires					5w20 Oil	Bulk			7	7.00
- Replace worn out	cab mour	nts.			Napagolo	Oil Filter			1	.00
- Replaced leaking	schocks.				Napagolo	Air Filter	•		1	.00
- Rotate and balanc	e tires.				17963649	92 Lt245-7	75r17		2	2.00
- Replace leaking a/			r and orifice	tube.	20" Wipe	r Blade			2	2.00
Evacuate and refill a	/c system	۱.			Napagolo	Fuel Filte	er		1	.00
- Test drive.					Body Mo	unt Kit			2	2.00
- Shop Supplies					Body Mo	unt Kit			4	1.00
					Gas Gran	de Fleet S	Shoc		2	2.00
					Reflex Tr	uck Shock	(2	2.00
					New Com	pressor			1	.00
					Accumula	ator			1	.00
					Orifice Tu	ıbe			1	.00
					Pahokee	Shop Fre	on		2	2.00
					Shop Sup	plies			1	.00
					Tire Disp				2	2.00
	Hours :	s 17.75		Labor:	1,065.0 0		1,815.18	Total:	2,880.18	

Problem: Flat tire Repair Lf tire. Relearn Tpms sensors. Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 93 Workorder: 1705291 Problem: Pm service. Pm service. Pm service. Rotate and balance tires. Replace shorted marker light and Hmsl bulbs. Replace worn front brake pads. Replace missing tailgate trim. Test drive. Check a/c per customer complaint. No problem found. Shop Supplies Hours 9.75 Labor: 585.00 Parts List Napagold Oil Filter Washer Fluid Concentr Cover Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8-1	12/01/201	16
- Replace both Rear Tires - Replace both rear lights on cab - Road Test - Ropaloe both rear lights on cab - Road Test - Ropaloe both rear lights on cab - Road Test - Shop Supplies - Shop Supplies - Road Test - Shop Supplies - Road Test - Shop Supplies - Road Test - Road Tire Disposal Filter - Used Fire X Refurbished - Napagold Full Filter - Used Fire X Refurbished - Napagold Full Filter - Top Supplies - Tire Disposal Fee - Hours 5.25 - Labor: 315.00 - Parts: 565.85 - Total: 8i - Road Test - Ro		Qty
Replace both rear lights on cab Road Test Road		7.00
- Road Test - Shop Supplies - Hours 5.25 - Labor: 315.00 - Parts: 565.85 - Total: 8: Workorder: 1701665 - Meter: 78544 - Problem: Flat tire - Repair Lf tire Releam Tpms sensors Shop Supplies - Hours 1.50 - Labor: 90.00 - Parts: 2.00 - Total: 9: Workorder: 1705291 - Problem: Pm service Pm service Pm service Pm service Pm service Pm service Replace shorted marker light and Hmsl bulbs Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace worn front b	1	1.00
- Shop Supplies	2	2.00
Used Fire X Refurbished Napagold Fuel Filter 179636492 Li245-75r17 Shop Supplies Tire Disposal Fee Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 8: Workorder: 1701665 Problem: Flat tire Repair Lf tire Relearn Tpms sensors. Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 9: Workorder: 1705291 Meter: 81596 Problem: Pm service. Parts List Rotate and balance tires. Replace shorted marker light and Hmsl bulbs. Replace missing tailgate trim. Replace missing tailgate trim. Test drive. Check a/c per customer complaint. No problem found. Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 9: Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch. Low pressure switch not working correctly. Replace low pressure switch. Low pressure switch. Low pressure switch not working correctly. Replace low pressure switch. Low pressure switch. Low pressure switch not working correctly. Replace low pressure switch. Low pressure switch. Low pressure switch. Low pressure switch not working correctly. Replace low pressure switch. Low pressure switch. Low pressure switch. Low pressure switch not working correctly. Replace low pressure switch.	1	1.00
Napagold Fuel Filter 179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 8: Workorder: 1701665 Meter: 78544 In Date: 02/16/2017 Closed: 0: Problem: Flat tire - Repair Lf tire - Relearn Tpms sensors. Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 9: Problem: Pm service Pm service Pm service Pm service Rotate and balance tires Rotate and balance tires Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Problem: No a/c. Check brakes: - A/c compressor not engaging. Check a/c system operation. Low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Shop Supplies - Shop Supplies - Wire Assy - A/c Switch	1	1.00
179636492 Lt245-75r17 Shop Supplies Tire Disposal Fee Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 8i Froblem: Flat tire Parts List Parts List Parts List Problem: Problem: Phouse 1.50 Labor: 90.00 Parts: 2.00 Total: 9i Problem: Pm service Parts List Part	1	1.00
Shop Supplies Tire Disposal Fee Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 8: Workorder: 1701665 Meter: 78544 Problem: Flat tire Repair Lf tire Repair Lf tire Releam Tpms sensors. Shop Supplies - Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 9: Workorder: 1705291 Meter: 81596 In Date: 05/30/2017 Closed: 0: Problem: Pm service Pm service Pm service Parts List - Replace shorted marker light and Hmsl bulbs Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies - Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8: Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Problem: No a/c. Check brakes A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Shop Supplies - Shop Supplies - Shop Supplies - A/c Switch - Shop Supplies - Replace low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Shop Supplies - Shop Supplies - A/c Switch	1	1.00
Tire Disposal Fee Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 88 Workorder: 1701665 Problem: Flat tire Repair Lf tire. Releam Tpms sensors. Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 98 Workorder: 1705291 Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 98 Workorder: 1705291 Problem: Pm service. Parts List Replace shorted marker light and Hmsl bulbs. Replace shorted marker light and Hmsl bulbs. Replace shorted marker light and Hmsl bulbs. Replace missing tailgate trim. Test drive. Check a/c per customer complaint. No problem found. Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 88 Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found. L' brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Shop Supplies - Shop Supplies - Check for Abs or A/c dtc's. None found L' brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Shop Supplies - Shop Supplies - Check for Abs or A/c dtc's. None found L' brake dragging. Caliper not releasing. Replace front calipers switch - Shop Supplies - Shop Supplies - Check for Abs or A/c dtc's. None found L' brake dragging. Caliper not releasing. Replace front calipers switch - Shop Supplies - Shop Supplies - Wire Assy - A/c Switch	2	2.00
Hours 5.25 Labor: 315.00 Parts: 565.85 Total: 8t	1	1.00
Workorder: 1701665 Meter: 78544 In Date: 02/16/2017 Closed: 0. Problem: Flat tire - Repair Lf tire Relearn Tpms sensors Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 9. Problem: Pm service Pm service Pm service Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8. Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Problem: No a/c. Check brakes A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch not working correctly. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies - Test drive Shop Supplies	2	2.00
Problem: Flat tire Repair Lf tire. Parts List Releam Tpms sensors. Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 9: Workorder: 1705291 Meter: 81596 In Date: 05/30/2017 Closed: 06 Problem: Pm service. Pm service. Parts List Replace and balance tires. Sw20 Oil Bulk Replace worn front brake pads. 20" Wiper Blade Replace missing tailgate trim. Washer Fluid Concentr Moulding Check a/c per customer complaint. No problem found. Cover Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8: Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Problem: No a/c. Check brakes. Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch - Li brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. Wire Assy - A/c Switch	80.85	
- Relearn Tpms sensors Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 90.00 Problem: 1705291 Meter: 81596 Problem: Pm service. - Pm service Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8. Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies A/c Switch)2/21/201	17
- Shop Supplies Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 92 Workorder: 1705291 Meter: 81596 Problem: Pm service. - Pm service Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 2.00 Parts List - Cover - Pads - Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8 Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies		Qty
Hours 1.50 Labor: 90.00 Parts: 2.00 Total: 99.00 Problem: 1705291 Meter: 81596 Problem: Pm service. - Pm service Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 99.00 Parts: 2.00 Total: 99.00 Parts: 2.00 Problem: 05/30/2017 Closed: 07 Parts List Sw20 Oil Bulk Napagold Oil Filter Washer Fluid Concentr Moulding Cover Pads Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 89.00 Parts: 259.81 Problem: No a/c. Check brakes A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies	1	1.00
: Workorder: 1705291 Meter: 81596 In Date: 05/30/2017 Closed: 06 Problem: Pm service. - Pm service Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies - Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8. Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 11 Workorder: 1709473 Neter: 85275 In Date: 09/28/2017 Closed: 11 - Check for Abs or A/c dtc's. None found Lif brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies - Caliper w/ Hardware - Left Front (eclips) - Disc Brake Pads - Pressure Switch - Wire Assy - A/c Switch		
Problem: Pm service. - Pm service Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8- Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Lubor pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies A/c Switch	2.00	
- Rotate and balance tires Replace shorted marker light and Hmsl bulbs Replace worn front brake pads Replace missing tailgate trim Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies - Hours 9.75 - Labor: - Moulding - Cover - Shop Supplies - Hours 9.75 - Labor: - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies - Sw20 Oil Bulk - Napagold Oil Filter - 20" Wiper Blade - Washer Fluid Concentr - Moulding - Cover - Pads - Shop Supplies - In Date: 09/28/2017 Closed: 11 - Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads - Pressure Switch - Pressure Switch - Vire Assy - A/c Switch	06/15/201	17
Replace shorted marker light and Hmsl bulbs. Replace worn front brake pads. Replace missing tailgate trim. Washer Fluid Concentr Test drive. Check a/c per customer complaint. No problem found. Shop Supplies Hours 9.75 Labor: Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch. Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies A/c Switch Napagold Oil Filter 20" Wiper Blade Washer Fluid Concentr Moulding Cover Pads Shop Supplies In Date: 09/28/2017 Closed: 11 Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch		Qty
- Replace worn front brake pads Replace missing tailgate trim Test drive Check a/c per customer complaint. No problem found Shop Supplies - Hours 9.75 - Labor: - S85.00 - Parts: 259.81 - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies - 20" Wiper Blade - Washer Fluid Concentr - Moulding - Cover - Pads - Shop Supplies - Pads - Shop Supplies - In Date: 09/28/2017 Closed: 10 - Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips) - Disc Brake Pads - Pressure Switch - Wire Assy - A/c Switch	7	7.00
- Replace missing tailgate trim. - Test drive. - Check a/c per customer complaint. No problem found. - Shop Supplies - Hours 9.75 - Labor: - Workorder: 1709473 - Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch. - Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies Washer Fluid Concentr Moulding Cover Pads Shop Supplies In Date: 09/28/2017 Closed: 10 Parts List Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch	1	1.00
- Test drive. - Check a/c per customer complaint. No problem found Shop Supplies - Hours 9.75 - Labor: - Set drive. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies - Moulding - Cover - Pads - Shop Supplies - In Date: 09/28/2017 Closed: 10 - Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch - Test drive Shop Supplies - Moulding - Cover - Pads - Shop Supplies - In Date: 09/28/2017 Closed: 10 - Caliper w/ Hardware - Right Front (eclips Disc Brake Pads Pressure Switch - Vire Assy - A/c Switch	2	2.00
- Check a/c per customer complaint. No problem found Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8- Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch Check for Abs or A/c dtc's. None found Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system Test drive Shop Supplies Parts List Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy - Shop Supplies	1	1.00
- Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8-259.81 Workorder: 1709473 Meter: 85275 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch. - Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Pads Shop Supplies In Date: 09/28/2017 Closed: 10 Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch	1	1.00
Shop Supplies Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8-259.81 Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 19/28/2017 Clos	1	1.00
Hours 9.75 Labor: 585.00 Parts: 259.81 Total: 8. Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 19/28/2017 Closed		1.00
Workorder: 1709473 Meter: 85275 In Date: 09/28/2017 Closed: 10 Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch. - Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies		1.00
Problem: No a/c. Check brakes. - A/c compressor not engaging. Check a/c system operation. Low pressure switch not working correctly. Replace low pressure switch. - Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Parts List Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch	344.81	
Low pressure switch not working correctly. Replace low pressure switch. - Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Caliper w/ Hardware - Right Front (eclip Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch	0/05/201	17
pressure switch. - Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Caliper w/ Hardware - Right Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch		Qty
- Check for Abs or A/c dtc's. None found. - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Caliper w/ Hardware - Left Front (eclips Disc Brake Pads Pressure Switch Wire Assy A/c Switch	1	1.00
 - Lf brake dragging. Caliper not releasing. Replace front calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Disc Brake Pads Pressure Switch Wire Assy A/c Switch 	1	1.00
calipers and pads. Fill and bleed brake system. - Test drive. - Shop Supplies Pressure Switch Wire Assy A/c Switch	1	1.00
- Test drive. Wire Assy - Shop Supplies A/c Switch	1	1.00
Griop Gappines	1	1.00
Shop Supplies	1	1.00
	1	1.00
Hours 6.00 Labor: 360.00 Parts: 295.88 Total: 69		

:

Workorder: Problem:	1711948 Pm service.	Meter:	86885		I	n Date:	12/06/2017	Closed:	12/12/2017
- Pm service.					Parts List				Qty
- Front headli	ghts full of wa	ter. Replace	ed front head	dlights.	5w20 Oil E	Bulk			14.00
- Replace wo	rn ball joints o	n pass side.	i		Napagold	Oil Filter			2.00
- Rotate and	balance tires.				Napagold	Fuel Filte	er		2.00
- Test drive.					Napagold	Air Filter	r		2.00
- Shop Suppli	ies				20" Wiper	Blade			4.00
					Used Fire	X Refurb	oished		2.00
					13 Oz Aer	o Kroil			2.00
					Halogen L	.amp			4.00
					Lower Bal	l Joint			1.00
					Upper Bal	l Joint			1.00
					Shop Sup	plies			1.00
	Hou :	ırs 6.75		Labor:	405.00	Parts:	253.07	Total:	658.07
Workorder: Problem:	1802594 Check A/C	Meter:	89264		I	n Date:	03/08/2018	Closed:	03/15/2018
	ystem. Evap c		Replace ev	ap core.	Parts List	:			Qty
	refill a/c syste				Evapotato	r Core			1.00
-	roded battery	noid down.			Tube Filte	r			1.00
- Clean vehic	ie.				Accumula				1.00
- Test drive.					Flush Solv				1.00
- Shop Suppli	ies				Freon Pah	okee Sh	op		2.00
					Spacer				1.00
					Shop Sup	plies			1.00
	Hou :	ırs 11.50		Labor:	690.00	Parts:	447.73	Total:	1,137.73
Workorder: Problem:	1805061 A/C not work	Meter:	91485		I	n Date:	05/16/2018	Closed:	05/17/2018
	ystem. Replac			tube	Parts List				Qty
fitting. Evacua		ge a/c syste	m.		Freon Pah	okee Sh	op		1.00
- Pm service.					Napagold	Oil Filter			1.00
-	rn serpentine	belt.			5w20 Oil E	Bulk			7.00
- Rotate and	balance tires.				20" Wiper	Blade			2.00
- Test drive.	•				Washer Fl	uid Conc	entr		1.00
- Shop Suppli	ies				Napagold	Fuel Filte	er		1.00
					V-ribbed E	Belt			1.00
					Shop Sup	plies			1.00
	Hou	ırs 7.25		Labor:	435.00	Parts:	88.43	Total:	523.43

Workorder:	1807013		eter:	93273			In Date:	07/10/2018	Closed:	07/17/20	018
Problem:	A/C not	working.									
				d and installed	d new	Parts Lis	st				Qty
dryer. Evacua		cnarge a/c	syste	·m.		Accumul	ator				1.00
- Shop Suppli	ies					Cap And	Valve Kit				1.00
						•	Seal Green	ı			2.00
						Shop Su	pplies				1.00
		Hours 2.5	50		Labor:	150.00	Parts:	101.06	Total:	251.06	
Workorder: Problem:	1807484 Running		eter:	93316 er.			In Date:	07/23/2018	Closed:	08/02/20	018
-	sing under	r Ioad. Rep	olaced	l all spark plug	s to	Parts Lis	st				Qty
correct.			<i></i> 5			Spark Pl	ug				8.00
	wipers no	t turning o	ff. Re _l	placed wiper s	switch.	Spark Pl	ug				8.00
- Test drive.						Switch					1.00
- Shop Suppl	ies					Shop Su	pplies				1.00
		Hours 4.0	00		Labor:	240.00	Parts:	348.74	Total:	588.74	
Workorder: Problem:	1808300 Running		eter:	93575			In Date:	08/13/2018	Closed:	08/23/20	018
- Maf sensor	not readir	ng properly	/. Rep	lace sensor.		Parts Lis	st				Qty
- Replace cat	. converte	er assy.				Maf Sens	sor				1.00
- Test drive 2	x's.					Cat Conv	V				1.00
_	ne light or	n. Check a	nd cle	ar dtc's. Dtc P	o430	Shop Su	pplies				1.00
present.	•					Freight C	Charge				1.00
- Shop Suppl	ies	Hours 5.0	00		Labor:	300.00	Parts:	1,150.72	Total:	1,450.72	2
	10100=	:									
Workorder: Problem:	1812650 Pm serv		eter:	95852			In Date:	12/12/2018	Closed:	12/17/20	J18
- Pm service.						Parts Lis	st				Qty
- Clean thrott	le body.					Napagol	d Oil Filter				1.00
- Rotate and	balance ti	res.				5w20 Oil	Bulk				7.00
- Replace sho	orted Rr ta	aillight bulb	ο.			Washer	Fluid Conc	entr			1.00
- Test drive.						20" Wipe	er Blade				2.00
- Shop Suppli	ies					Napagol	d Air Filter				1.00
						Used Fir	e X Refurb	ished			1.00
						Clean-r-c	carb 20oz				1.00
						Shop Su	pplies				1.00
		Hours 5.7	75		Labor:	385.25	Parts:	59.87	Total:	445.12	
		:									

Workorder: Problem:	1903352 Flat tire.	Meter:	97691			In Date:	03/27/2019	Closed:	04/03/20	019
- Repair Rf tir	e.				Parts Li	st				Qty
•	s have excess	ive play. R	eplace worn fi	ront	Сар					2.00
wheel bearing	s and hub sea	ıls.			Wheel S	eal - Front	Wheel			2.00
- Shop Suppli	ies				Napa Be	earing Cup				2.00
					Wheel B	earing Con	e - Inner - Fro	nt Wheel		2.00
					Napa Be	aring Cup				2.00
					Napa Be	aring Cone	:			2.00
					Race					2.00
					Race					2.00
					Shop Su	pplies				1.00
	Hou :	rs 3.50		Labor:	234.50	Parts:	365.88	Total:	600.38	
Workorder: Problem:	1905735 Won't start.	Meter:	98503			In Date:	05/30/2019	Closed:	06/03/20	019
- Battery faile	d load test. Re	eplace batte	erv.		Parts Li	st				Qty
- Shop Suppli		.,			Battery					1.00
					Shop Su	pplies				1.00
	Hou	rs 1.00		Labor:			128.01	Total:	195.01	
Workorder:	1910260	Meter:	100233			In Date:	10/03/2019	Closed:	10/15/20	019
Problem:	Pm service.									
Problem: - Pm service.	Pm service.				Parts Li	st				Qty
- Pm service.	Pm service.				Parts Li 5w20 Oi					Qty 7.00
- Pm service.	ssing hub cap.				5w20 Oi					-
- Pm service. - Replace mis	ssing hub cap.				5w20 Oi Napagol	l Bulk				7.00
Pm service.Replace misRotate and I	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol	l Bulk d Air Filter				7.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol	l Bulk d Air Filter d Oil Filter Fluid Conce				7.00 1.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol Washer 20" Wipe	l Bulk d Air Filter d Oil Filter Fluid Conce	entr			7.00 1.00 1.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol Washer 20" Wipe Napagol	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade	entr r			7.00 1.00 1.00 1.00 2.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol Washer 20" Wipe Napagol	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte	entr r			7.00 1.00 1.00 1.00 2.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires.				5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r			7.00 1.00 1.00 1.00 2.00 1.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires. ies	ırs 4.75		Labor:	5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir Cover	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r	Total:	485.57	7.00 1.00 1.00 1.00 2.00 1.00 1.00
Pm service.Replace misRotate and ITest drive.	ssing hub cap. balance tires. ies		101127	Labor:	5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir Cover Shop Su	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r ished	Total:	485.57	7.00 1.00 1.00 2.00 1.00 1.00 1.00
- Pm service Replace mis - Rotate and the rest drive Shop Suppli	ssing hub cap. balance tires. ies Hou :	rs 4.75 Meter:	101127	Labor:	5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir Cover Shop Su	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r ished 138.82			7.00 1.00 1.00 2.00 1.00 1.00 1.00
- Pm service Replace mis - Rotate and the rest drive Shop Suppli	ssing hub cap. balance tires. ies Hou : 1912660 Transition Presented to the presented to	rs 4.75 Meter:	101127	Labor:	5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir Cover Shop Su	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r ished 138.82			7.00 1.00 1.00 2.00 1.00 1.00 1.00
- Pm service Replace mis - Rotate and the rest drive Shop Suppli	House tires. House tires. House tires. Tansition Process	rs 4.75 Meter:	101127		5w20 Oi Napagol Napagol Washer 20" Wipe Napagol Used Fir Cover Shop Su	I Bulk d Air Filter d Oil Filter Fluid Conce er Blade d Fuel Filte e X Refurbi	entr r ished 138.82 12/10/2019	Closed:		7.00 1.00 1.00 2.00 1.00 1.00 1.00