# 10183716 2011 FORD RANGER Pickup, Compact

					- '	-				
Workorder: Problem:	1101642 Pre Delive	Meter: ry Inspection	0			In Date:	02/11/2011	Closed:	02/11/20	011
- Pre Delivery	Inspection									
	H- :	ours 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1107818 P. M. SER	Meter: VICE.	4729			In Date:	07/26/2011	Closed:	07/29/20	011
- P. M. Servic	e.				Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
					1348 Oi	l Filter Frm	Ph3614 Wix	51348		1.00
					5w20 E	ngine Oil				5.00
	H- :	ours 2.00		Labor:	120.00	Parts:	28.78	Total:	148.78	
Workorder: Problem:	1112695 R/FRONT	<b>Meter:</b> TIRE DAMAC	6789 SE			In Date:	11/30/2011	Closed:	12/09/20	011
- C/c: Right fr	ont tire dam	aged. Verify	complaint, s	wap bad	Parts L	ist				Qty
tire to spare. F drive to clear		ılance, add N	2. Rotate to	rear. Test	Shop St	upplies				1.00
- Shop Suppli	es									
	H- :	ours 2.00		Labor:	120.00	Parts:	2.00	Total:	122.00	
Workorder: Problem:	1201523 P. M. SER	Meter: VICE	7775			In Date:	02/15/2012	Closed:	02/17/20	012
- P. M. Servic	e.				Parts L	ist				Qty
- Nail in front	left tire, disn	nount, patch,	mount, bala	ance, &	Shop St	upplies				1.00
add N2.					3424 Fu	ıel Filter Frr	n 3424 Wix 3	3424		1.00
- Shop Suppli	es				1348 Oi	l Filter Frm	Ph3614 Wix	51348		1.00
					5w20 E	ngine Oil				5.00
	H- :	ours 3.00		Labor:	180.00	Parts:	30.72	Total:	210.72	
Workorder:	1205756	Meter:	10549			In Date:	06/18/2012	Closed:	06/27/20	012
Problem:	replace cra	acked windsh	eild & rgt do	or glass						
- Set up Wind	ow repair re	easset and ch	eck		Parts L	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	H- :	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1205766 Vandelism	Meter:	10500			In Date:	06/18/2012	Closed:	06/18/20	012
- Tow From: 4	1200 Comm	unity Dr, Wpb	- To: Body	Shop						
		ours 0.00	•	Labor:	0.00	Parts:	0.00	Total:	0.00	
	:	0.00								

Workorder: Problem:	1211544 pm	Meter:	14868			In Date:	11/30/2012	Closed:	12/19/2	012
- pm					Parts Lis	st				Qty
- Shop Suppli	es				Filter					1.00
					Napa Qu	art 5w20				5.00
					Shop Su					1.00
	H	ours 2.00		Labor:	120.00		25.70	Total:	145.70	
Workorder: Problem:	1300588 left rear tu	<b>Meter:</b> rn signal	15889			In Date:	01/16/2013	Closed:	01/18/20	013
- replace both	rear brake	light bulbs			Parts Lis	st				Qty
- Shop Suppli		J			Miniature	e Bulb				2.00
G.:. OF Gupp					Shop Su					1.00
	н	ours 1.00		Labor:		Parts:	3 44	Total·	63.44	
	:	1.00		Labor.	00.00	i arto.	0.11	i otai.	00.11	
Workorder: Problem:	1300811 nail in l/fro	Meter: nt tire	16217			In Date:	01/24/2013	Closed:	01/25/20	013
- ck flat tire di	smount pat	ch mount bala	nce add n2		Parts Lis	st				Qty
- Shop Suppli					Shop Su	pplies				1.00
		ours 1.00		Labor:	•	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1302043 accident to	Meter:	17267			In Date:	02/27/2013	Closed:	02/27/2	013
- Tow From: I		sts off of 44 ju	ıst s of Palme	etto park						
	H :	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1302593 damage to	<b>Meter:</b> frt bumper, h	17267 ood & grille			In Date:	02/28/2013	Closed:	03/15/2	013
- damage to f	rt bumper. h	nood & arille								
	•	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:	1305250	Meter:	17335			In Date:	05/29/2013	Closed:	05/31/2	013
Problem:	Had to jum	np start.								
- Recharge ba	attewry and	test battery a	nd charging		Parts Lis	st				Qty
system.battery				tery.		9 Battery M	c			1.00
- Shop Suppli	es				Shop Su	•				1.00
	н	ours 1.00		Labor:	-		131.35	Total·	191.35	1.00
	• • •	23.200			55.50	. 4.10.		i otai.	. 5	

Workorder:	1305263	Meter:	17335			In Date:	05/29/2013	Closed:	05/31/2	013
Problem:	turn signal	ls dont work	on both sides	front and b	oack					
- Check and r	eplace bad	right front st	robe light with	n wire	Parts Lis	Qty				
harness.	anal not wa	rking Varify	aanaara narf	orm	Vtx609c l		1.00			
- C/s: Turn signal not working. Verify concern, perform pinpoint test and found hazard light switch sticking. Remove & lube switch.				Shop Sup	oplies				1.00	
- Shop Suppli	es									
	H :	lours 3.25		Labor:	195.00	Parts:	125.24	Total:	320.24	
Workorder:	1308535	Meter:	21859			In Date:	08/23/2013	Closed:	08/30/2	013
Problem:	pm, tires,	windshield w	per blades ba	ack signal l	ight out br	ake light o	ut too			
- p.m.service					Parts Lis	st				Qty
- R&r Front A	nd Rear Tir	es.			Napagolo	d Fuel Filte	r			1.00
- Repair R/rea	_					d Oil Filter				1.00
- Shop Suppli	es				Napa Qua					5.00
					Wiper Bla					2.00
						18 P225-70	Or15			4.00
					Bulb	ممانمه				1.00
					Shop Sup Tire Dispo					1.00 4.00
	н	lours 4.50		Lahor:	270.00		682.21	Total:	952.21	4.00
	:	10010 4.00		Labor.	270.00	i dito.	002.21	Total.	302.21	
Workorder: Problem:	1311340 rear light o	Meter: change	23643			In Date:	11/07/2013	Closed:	11/14/2	013
- left rear bral	ke light repa	airs			Parts Lis	st				Qty
					Bulb					1.00
	H :	lours 0.50		Labor:	30.00	Parts:	0.99	Total:	30.99	
Workorder: Problem:	1403301 pm	Meter:	27647			In Date:	04/04/2014	Closed:	04/25/2	014
- pm					Parts Lis	st				Qty
- verify needs			nt brake pads	s turn	Napa Qua	art 5w20				5.00
rotors svc cali		n			. •	Oil Filter				1.00
- Shop Suppli	es				Washer F	-				1.00
					Disc Brak					1.00
	•				Shop Sup	•				1.00
	: :	lours 5.00		Labor:	300.00	Parts:	98.65	l otal:	398.65	
Workorder: Problem:	1405278 Clicking no	Meter: oise in steerir	29584 ng column.			In Date:	05/30/2014	Closed:	06/11/2	014
- Diagnose no	oise in steer	ring column.r	eplace defect	ive shift	Parts Lis	st				Qty
lock actuator a		oushings.			F3tz7l278	Ba Bushing	յ Sh			2.00
- Shop Suppli	es				Solenoid					1.00
					Shop Sup	oplies				1.00
	Н	lours 2.50		Labor:	150.00	Parts:	65.27	Total:	215.27	

Workorder: Problem:	1405516 1 - Detail Vehi	Meter: cle Wash	29338 Ticket(s) Issu	ıed		In Date:	06/04/2014	Closed:	06/04/20	014
- 1 - Detail Ve	hicle Wash Tic	ket(s) Issu	ied							
	Hours :	s 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1411142 PM	Meter:	36905			In Date:	11/06/2014	Closed:	11/18/20	014
- pm					Parts Li	st				Qty
- verify needs	4 tires replace	4 tires			Napagol	d Fuel Filte	r			1.00
- rr I rear tail li	ight bulb				Napagol	d Oil Filter				1.00
- Shop Suppli	es				Napa Qu	uart 5w20				5.00
					Wiper Bl	lade				2.00
					Washer	FI				1.00
					1834824	118 P225-70	)r15			4.00
					Bulb					1.00
					Shop Su	ıpplies				1.00
					Tire Disp	osal Fee				4.00
	Hours :	s 4.25		Labor:	255.00	Parts:	677.92	Total:	932.92	
Workorder: Problem:	1501175 dead battery	Meter:	41869			In Date:	02/02/2015	Closed:	02/09/20	015
- recharge and	d ck battery fou	ınd bad ba	ttery replace	battery	Parts Li	st				Qty
- recharge and	•	ınd bad ba	ittery replace	battery	Parts Li Battery	st				-
_	•	ınd bad ba	attery replace	battery						1.00
_	es	und bad ba	ittery replace	battery  Labor:	Battery Shop Su	ıpplies	103.00	Total:	148.00	1.00
- Shop Suppli	es	s 0.75	45033	Labor:	Battery Shop Su	ıpplies	103.00	Total:	148.00	1.00
- Shop Suppli	es Hours : 1503618	s 0.75	45033	Labor:	Battery Shop Su	pplies Parts: In Date:				1.00 1.00
- Shop Suppli Workorder: Problem: - pm	es Hours : 1503618	s 0.75  Meter: wing hard	45033 in high , light	Labor:	Battery Shop Su 45.00	pplies Parts: In Date:				Qty 1.00 1.00 015 Qty 1.00
- Shop Supplication  Workorder: Problem: - pm - replace left a	Hours : 1503618 pm, ac not blo	s 0.75  Meter: wing hard	45033 in high , light	Labor:	Shop Su 45.00 Parts Li Napagol	pplies Parts: In Date:				1.00 1.00 015
- Shop Supplie  Workorder: Problem: - pm - replace left a - resurface from	Hours : 1503618 pm, ac not blo	s 0.75  Meter: wing hard ower ball justing	45033 in high , light pints replace front	Labor:	Shop Su 45.00 Parts Li Napagol	pplies Parts: In Date: st d Oil Filter uart 5w20				1.00 1.00 015 Qty 1.00 5.00
- Shop Supplied  Workorder: Problem: - pm - replace left at a resurface from resurface rear - ck ac not blood.	Hours : 1503618 pm, ac not blo and right front keepent rotor svc call rotors svc call pwing hard on h	Meter: wing hard ower ball judgers and reading to person of the person o	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Battery Shop Su 45.00  Parts Li Napagol Napa Qu Washer	pplies Parts: In Date: st d Oil Filter uart 5w20				1.00 1.00 015 Qty 1.00
- Shop Supplication  Workorder: Problem:  - pm - replace left at a control of the	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cal rotors svc calip owing hard on h	Meter: wing hard ower ball judgers and reading to perform ap clean e	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Battery Shop Su 45.00  Parts Li Napagol Napa Qu Washer	pplies Parts: In Date: st d Oil Filter uart 5w20 Fl d Air Filter				1.00 1.00 015 Qty 1.00 5.00 1.00
- Shop Supplication  Workorder: Problem:  - pm - replace left and resurface from resurface rearesurface reare	Hours : 1503618 pm, ac not blo and right front keepen trotor svc calipowing hard on hund clogged everake light and de	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Washer Napagol	Ipplies Parts: In Date: st d Oil Filter Jart 5w20 Fl d Air Filter all Joint				1.00 1.00 015 Qty 1.00 5.00 1.00
- Shop Supplication  Workorder: Problem:  - pm - replace left at a control of the	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cali rotors svc cali owing hard on h und clogged ever ake light and de ront and left rea	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Washer Napagol Lower B	Ipplies Parts: In Date: st d Oil Filter Jart 5w20 Fl d Air Filter all Joint	04/08/2015			1.00 1.00 1.00 015 Qty 1.00 5.00 1.00 2.00
- Shop Supplied  Workorder: Problem: - pm - replace left at a resurface from resurface rear - ck ac not bloom inspect sys fou - repair 3rd br	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cali rotors svc cali owing hard on h und clogged ever ake light and de ront and left rea	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Washer Napagol Lower B	Ipplies Parts: In Date: st d Oil Filter Juart 5w20 FI d Air Filter all Joint d ke Pad Set	04/08/2015			1.00 1.00 1.00 015 Qty 1.00 5.00 1.00 2.00 1.00
- Shop Supplication  Workorder: Problem:  - pm - replace left at a control of the	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cali rotors svc cali owing hard on h und clogged ever ake light and de ront and left rea	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Napa Qu Washer Napagol Lower B Disc Pac Disc Bra Brake Ci	Ipplies Parts: In Date: st d Oil Filter Juart 5w20 FI d Air Filter all Joint d ke Pad Set	04/08/2015			1.00 1.00 1.00 015 015 015 1.00 1.00 1.0
- Shop Supplication  Workorder: Problem:  - pm - replace left at a control of the	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cali rotors svc cali owing hard on h und clogged ever ake light and de ront and left rea	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Napa Qu Washer Napagol Lower B Disc Pac Disc Bra Brake Ci B Fluid I	Ipplies Parts: In Date: st d Oil Filter Lart 5w20 Fl d Air Filter all Joint d lke Pad Set	04/08/2015			1.00 1.00 1.00 015 Qty 1.00 5.00 1.00 2.00 1.00
- Shop Supplie  Workorder: Problem: - pm - replace left a - resurface from resurface rear - ck ac not blooming pect sys four repair 3rd bring repair right from the supplies of the supplies o	Hours : 1503618 pm, ac not blo and right front lo ont rotor svc cali rotors svc cali owing hard on h und clogged ever ake light and de ront and left rea	Meter: wing hard ower ball judipers and realight performance one light	45033 in high , light pints replace front eplace rear parm sys pressr	Labor: pads ads	Parts Li Napagol Napa Qu Washer Napagol Lower B Disc Pac Disc Bra Brake Ci B Fluid I	Ipplies Parts: In Date:  st d Oil Filter Lart 5w20 Fl d Air Filter all Joint d lke Pad Set leaner Dot 3-32oz Brake Lube	04/08/2015			1.00 1.00 1.00 015 Qty 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: 150785. Problem: pm, hea		51701	In Date:	08/05/2015	Closed:	08/11/2015		
- P.m.service.			Parts List			Qi	ty	
- C/c Head Light Out.			Napagold Fuel Filte		1.0	-		
Repair Head Light.			Napagold Oil Filter			1.00		
- Replace Two Tires, F	Rotate To Front.		Napa Quart 5w20			5.00		
- Shop Supplies			Wiper Blade			2.0	00	
			Washer Fluid Cond	entr		1.0	00	
			Halogen Capsule			1.0	00	
			183482418 P225-7	'0r15		2.0	00	
			Shop Supplies			1.0	00	
			Tire Disposal Fee			2.0	00	
	Hours 4.00	Labor:	240.00 Parts:	359.00	Total:	599.00		
Workorder: 151258 Problem: flat tire	1 Meter:	57832	In Date:	12/14/2015	Closed:	12/17/2015		
- ck flat tire verify fl tire	sidewall damag	ge replace tire mount	Parts List			Qt	ty	
balance add n2			183482418 P225-7	'0r15		1.0	Э0	
- Shop Supplies			Shop Supplies			1.0	Э0	
	Hours 1.00	Labor:	60.00 Parts:	143.56	Total:	203.56		
Workorder: 1513013 Problem: PM, RR		58471 FT TAIL LIGHT NEED	In Date: REPLACE, CK ENG	12/29/2015 SNE LIGHT ON	Closed:	01/15/2016		
- pm			Parts List			Qt	ty	
- repair left rear brake	light		Napagold Oil Filter			1.0	-	
- replace brake pedal of			Napa Quart 5w20			5.0	00	
wheel bearings grease	seal and brake	pads	Washer Fluid Cond	entr		1.0	00	
- replace both rear tire	s and rotate to tl	ne front	Bulb			1.0	00	
- ck engine light is on		odes test drive was	Pedal Pad			1.0	00	
inable to verify concern	l		Disc Brake Pads			1.0	00	
- Shop Supplies			Brake Rotor Hub			2.0	00	
			Tappered Bearing	Set		2.0	00	
			Tappered Bearing	Set		2.0	00	
			Napa Oil Seal			2.0	00	
			B Fluid Dot 3-32oz			1.0	00	
			183482418 P225-7	'0r15		2.0	00	
			Shop Supplies			1.0	00	
			Tire Disposal Fee			2.0	00	
	Hours 9.50	Labor:	570.00 Parts:	589.20	Total:	1,159.20		

<b>Workorder:</b> 1604112 <b>Meter:</b> 63923	In Date: 04/19/2016	Closed:	05/06/2016			
Problem: Pm service.Headlamp inop.Strobe light switch	n broken.					
- Pm service.	Parts List		Qty			
- Replace strobe light switch and blown fuse.	Napagold Oil Filter					
- Repaired right front headlight and rear tag lamps.	Napa Quart 5w20		5.00			
- Replace both rear shocks.	Washer Fluid Concentr		1.00			
- Balance and rotate all tires.	18" wiper blades		2.00			
- Shop Supplies	Universal Switch		1.00			
	Atc-15 Fuse		1.00			
	Halogen Capsule		1.00			
	Bulb		2.00			
	Sensa-trac Lt Truck S		2.00			
	Rear Shock		2.00			
	Sensa-trac Lt Truck S		2.00			
	Shop Supplies		1.00			
Hours 6.75 Labo	: 405.00 Parts: 350.30	Total:	755.30			
Workorder: 1608277 Meter: 68487 Problem: Pm service.Left front tire flat.	<b>In Date:</b> 08/11/2016	Closed:	08/17/2016			
- P.m.service	Parts List		Qty			
- Repair R/front Tire	18" wiper blades		2.00			
- Repair Hazard Lights	Pedal Pad		1.00			
- Shop Supplies	Napagold Air Filter		1.00			
	Napagold Fuel Filter		1.00			
	Washer Fluid Concentr		1.00			
	Napagold Oil Filter		1.00			
	Napa Quart 5w20		5.00			
	Shop Supplies		1.00			
Hours 4.00 Labo	: 240.00 Parts: 51.17	Total:	291.17			
•						
: Workorder: 1612089 Meter: 73998 Problem: DEAD BATTERY	In Date: 11/28/2016	Closed:	11/30/2016			
		Closed:	11/30/2016 <b>Qt</b> y			
Problem: DEAD BATTERY		Closed:				
Problem: DEAD BATTERY - C/c Dead Battery. C/k Charging System Good. Test Battery.	y <b>Parts List</b>	Closed:	Qty			

<b>In Date:</b> 01/11/2017 m.	Closed:	02/13/2017
Parts List Napagold Oil Filter Napa Quart 5w20 Washer Fluid Concentr 18" wiper blades Syn Atf Bulk South Blend Door Acuator 183482418 P225-70r15 Brake Pad brake Pad Non-chlor Brake Clnr		Qty 1.00 5.00 1.00 2.00 2.00 1.00 4.00 1.00 1.00 1.00
Insulator Front Shocks Vtx609c Led Strobe Cl Shop Supplies Tire Disposal Fee 1,065.0 Parts: 979.84	Total:	2.00 1.00 1.00 4.00 2,044.84
0 In Date: 06/29/2017	Closed:	07/10/2017
Parts List  5w20 Engine Oil  Lock Key  Napagold Oil Filter  18" wiper blades  Washer Fluid Concentr  Napagold Fuel Filter  Shop Supplies		Qty 5.00 1.00 1.00 2.00 1.00 1.00 1.00
, ,,	Total:	254.44
	Parts List Napagold Oil Filter Napa Quart 5w20 Washer Fluid Concentr 18" wiper blades Syn Atf Bulk South Blend Door Acuator 183482418 P225-70r15 Brake Pad brake Pad Non-chlor Brake Clnr Insulator Front Shocks Vtx609c Led Strobe Cl Shop Supplies Tire Disposal Fee 1,065.0 Parts: 979.84 0  In Date: 06/29/2017  Parts List 5w20 Engine Oil Lock Key Napagold Oil Filter 18" wiper blades Washer Fluid Concentr Napagold Fuel Filter Shop Supplies	Parts List Napagold Oil Filter Napa Quart 5w20 Washer Fluid Concentr 18" wiper blades Syn Atf Bulk South Blend Door Acuator 183482418 P225-70r15 Brake Pad brake Pad Non-chlor Brake Clnr Insulator Front Shocks Vtx609c Led Strobe Cl Shop Supplies Tire Disposal Fee 1,065.0 Parts: 979.84 Total: 0 In Date: 06/29/2017 Closed:  Parts List 5w20 Engine Oil Lock Key Napagold Oil Filter 18" wiper blades Washer Fluid Concentr Napagold Fuel Filter Shop Supplies