Workorder:	745352	Meter:				In Date:	10/09/2007	Closed:	10/09/20	007
		VERY INSPI	ECTION							
- Pre-delivery						_				
	H :	ours 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	837213 P.M.SERV	Meter:	1644			In Date:	04/18/2008	Closed:	04/25/20	008
- Pm Service					Parts Li	st				Qty
- Vacuum 4 T	ires & Add I	Nitrogen			Shop Su	upplies				1.00
- Shop Suppli	es				1372 Oi	il Filter Frm	n Ph2 Wix 513	372		1.00
					5w20 Er	ngine Oil				7.00
					10020 Ir	njector Clea	ner Don't Reo	rder		1.00
	H	ours 3.75		Labor:	225.00	Parts:	43.00	Total:	268.00	
Workorder: Problem:	847548 P.M.SERV	Meter:	4201			In Date:	12/01/2008	Closed:	12/04/20	800
- Pm Service					Parts Li	st				Qty
- Lube Winch	& Cable As	sv: Free Rol	lers		Shop Su					1.00
- File Hinges		•		,	•	••	n Ph2 Wix 513	372		1.00
- Shop Suppli		Ū			5w20 Er					8.00
						Igine On				
						iper Blades	s 20" Blade			2.00
	H	ours 6.00		Labor:		iper Blades	3 20" Blade 54.86	Total:	414.86	2.00
Workorder: Problem:	: 935481	Meter:			31-20 W 360.00	iper Blades		Total: Closed:	414.86 04/09/20	
Problem:	: 935481 NAIL IN R/	<b>Meter:</b> REAR TIRE			31-20 W 360.00	/iper Blades Parts: In Date:	54.86			
Problem: - Replace Tai	: 935481 NAIL IN R/ Igate Switch	Meter: REAR TIRE	,BROKEN LI	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b>	/iper Blades Parts: In Date: st	54.86			
Problem: - Replace Tai - Remove Scr	935481 NAIL IN R/ Igate Switch rew In R/r T	Meter: REAR TIRE	,BROKEN LI	IFT BED SV	31-20 W 360.00 VITCH	/iper Blades Parts: In Date: st	54.86			009 <b>Qty</b> 1.00
Problem: - Replace Tai	: 935481 NAIL IN R/ Igate Switch rew In R/r T es	Meter: REAR TIRE	,BROKEN LI	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b> Shop Su Switch	/iper Blades Parts: In Date: st upplies	54.86	Closed:		009 <b>Qty</b> 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder:	: 935481 NAIL IN R/ Igate Switch rew In R/r T es	Meter: (REAR TIRE n ire; Test For ours 1.25 Meter:	,BROKEN LI	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b> Shop Su Switch	/iper Blades Parts: In Date: st upplies	54.86 03/23/2009	Closed:	04/09/20	009 <b>Qty</b> 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder:	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411	Meter: (REAR TIRE n ire; Test For ours 1.25 Meter:	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b> Shop Su Switch	/iper Blades Parts: In Date: st upplies Parts: In Date:	54.86 03/23/2009 99.50	Closed: Total:	04/09/20	009 <b>Qty</b> 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem:	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00	/iper Blades Parts: In Date: st upplies Parts: In Date: st	54.86 03/23/2009 99.50	Closed: Total:	04/09/20	009 <b>Qty</b> 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.servico	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00 Parts Li Shop Su	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies	54.86 03/23/2009 99.50	Closed: Total: Closed:	04/09/20	009 Qty 1.00 1.00 009 Qty
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,0	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service clean socker lift gate	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00 Parts Li Shop Su 1372 Oi	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies il Filter Frm	54.86 03/23/2009 99.50 07/07/2009	Closed: Total: Closed:	04/09/20	009 Qty 1.00 1.00 009 Qty 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,c - service hyd.	i 935481 NAIL IN R/ Igate Switch rew In R/r T es H 940411 p.m.servico clean socker lift gate winch rolle	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e t	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00 Parts Li Shop Su 1372 Oi G10166	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies il Filter Frm Fuel Filter	54.86 03/23/2009 99.50 07/07/2009	Closed: Total: Closed: 372 /ix 33243	04/09/20	009 <b>Qty</b> 1.00 1.00 009 <b>Qty</b> 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,c - service hyd. - freed&lubed	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service clean socker lift gate winch rolle	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e t	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00 Parts Li Shop Su 1372 Oi G10166	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies il Filter Frm Fuel Filter I 2 Air Filter I	54.86 03/23/2009 99.50 07/07/2009 07/07/2009	Closed: Total: Closed: 372 /ix 33243	04/09/20	009 <b>Qty</b> 1.00 1.00 009 <b>Qty</b> 1.00 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,c - service hyd. - freed&lubed - install no sm	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service clean socker lift gate winch rolle	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e t	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b> Shop Su Switch 75.00 <b>Parts Li</b> Shop Su 1372 Oi G10166 Ca10262 5w20 Er	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies il Filter Frm Fuel Filter 2 Air Filter I ngine Oil	54.86 03/23/2009 99.50 07/07/2009 07/07/2009	Closed: Total: Closed: 372 /ix 33243	04/09/20	009 <b>Qty</b> 1.00 1.00 009 <b>Qty</b> 1.00 1.00 1.00 1.00 1.00 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,c - service hyd. - freed&lubed - install no sm	: 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service clean socker lift gate winch rolle	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e t	,BROKEN LI Leak-none F	IFT BED SV	31-20 W 360.00 VITCH <b>Parts Li</b> Shop Su Switch 75.00 <b>Parts Li</b> Shop Su 1372 Oi G10166 Ca10262 5w20 Er 1066 W	/iper Blades Parts: In Date: st upplies Parts: In Date: st upplies il Filter Frm Fuel Filter 2 Air Filter I ngine Oil	54.86 03/23/2009 99.50 07/07/2009 07/07/2009 07/07/2009 07/07/2009 07/07/2009	Closed: Total: Closed: 372 /ix 33243	04/09/20	009 <b>Qty</b> 1.00 1.00 009 <b>Qty</b> 1.00 1.00
Problem: - Replace Tai - Remove Scr - Shop Suppli Workorder: Problem: - p.m.service - R & R bulb,c - service hyd. - freed&lubed - install no sm	i 935481 NAIL IN R/ Igate Switch rew In R/r T es H : 940411 p.m.service clean socker lift gate winch rolle noking deca es	Meter: /REAR TIRE ire; Test For ours 1.25 Meter: e t	,BROKEN LI Leak-none F	IFT BED SV Found Labor:	31-20 W 360.00 VITCH Parts Li Shop Su Switch 75.00 Parts Li Shop Su 1372 Oi G10166 Ca10262 5w20 Er 1066 W 31-20 W	/iper Blades Parts: In Date: st upplies Parts: In Date: In Date: st upplies il Filter Frm Fuel Filter I fuel Filter I ngine Oil /hite Lithium /iper Blades agner Bulb	54.86 03/23/2009 99.50 07/07/2009 07/07/2009 07/07/2009 07/07/2009 07/07/2009	Closed: Total: Closed: 72 /ix 33243 /ix 49883	04/09/20	009 Qty 1.00 1.00 009 Qty 1.00 1.00 1.00 8.00 1.00

Workorder: 1000333 Meter: 10024 Problem: P. M. SERVICE	In Date: 01/08/2010 Closed: 01/26/2010
- P. M.	Parts List Q
- Winch service.	Shop Supplies 1.
- Service power tailgate.	1372 Oil Filter Frm Ph2 Wix 51372 1.
- Verify right rear tail light out. Remove lens assy, R/r tailligh	G10166 Fuel Filter Mtc Fg1083 Wix 33243
bulb.	5w20 Engine Oil 8.
- Verify, front left strobe light out. Remove lens assy. R/r	3157 Tail Light Bulbs 1.
strobe light bulb.	Ha238c Strobe Bulb Use Whelen #s30hac 1.
- Shop Supplies Hours 7.50 Labor	450.00 Parts: 103.03 Total: 553.03
: Workorder: 1007666 Meter: 12819	In Date: 07/20/2010 Closed: 07/27/2010
Problem: P. M. SERVICE	
- P. M. Service.	Parts List Q
- Checked strobe operation, checked coil pach, R&r bulb.	Shop Supplies 1.
- R&r bulb.	1372 Oil Filter Frm Ph2 Wix 51372
- Freed siezed winch rollers & lubed.	5w20 Engine Oil 8.
- Checked left gate operation, lubed adjusted hinge points.	Used Firex Refurbed Fire Extingshers 1.
- Installed "how's my driving" sticker.	Ha238c Strobe Bulb Use Whelen #s30hac 1.
- Shop Supplies	3156 Wagner Bulb 1.
Hours 8.25 Labor	495.00 Parts: 98.72 Total: 593.72
Workorder: 1011853 Meter: 14464 Problem: P. M. Service, & Strobe light on the driver's si	In Date: 10/22/2010 Closed: 10/28/2010 de in the front is not working.
- P. M. service.	Parts List Q
- Replace left front strobe light bulb. Replace 3rd brake light	Shop Supplies 1.
bulb.	1372 Oil Filter Frm Ph2 Wix 51372 1.
- Service winch.	
	G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.
- Service tail gate lift.	G10166 Fuel Filter Mtc Fg1083 Wix 33243         1.           Ca10262 Air Filter Mtc Fa1883 Wix 49883         1.
- Service tail gate lift. - Shop Supplies	-
-	Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.
-	Ca10262 Air Filter Mtc Fa1883 Wix 498831.5w20 Engine Oil8.
-	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.         5w20 Engine Oil       8.         1066 White Lithium (crc 05037)       1.
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.4         5w20 Engine Oil       8.4         1066 White Lithium (crc 05037)       1.4         31-20 Wiper Blades 20" Blade       2.4
- Shop Supplies Hours 7.00 Labor :	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.         5w20 Engine Oil       8.         1066 White Lithium (crc 05037)       1.         31-20 Wiper Blades 20" Blade       2.         Ha238c Strobe Bulb Use Whelen #s30hac       1.
- Shop Supplies Hours 7.00 Labor : Workorder: 1014155 Meter: 16029 Problem: FRONT RIGHT HEAD LIGHT OUT - C/c: F/r headlight out. Remove headlight assy, R&r bulb	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.1         5w20 Engine Oil       8.1         1066 White Lithium (crc 05037)       1.1         31-20 Wiper Blades 20" Blade       2.1         Ha238c Strobe Bulb Use Whelen #s30hac       1.1         420.00       Parts: 111.44       Total: 531.44         In Date:       12/29/2010       Closed:       12/30/2010         Parts List       Q
- Shop Supplies Hours 7.00 Labor : Workorder: 1014155 Meter: 16029 Problem: FRONT RIGHT HEAD LIGHT OUT - C/c: F/r headlight out. Remove headlight assy, R&r bulb assy, & readjust.	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.1         5w20 Engine Oil       8.1         1066 White Lithium (crc 05037)       1.1         31-20 Wiper Blades 20" Blade       2.1         Ha238c Strobe Bulb Use Whelen #s30hac       1.1         420.00       Parts: 111.44       Total: 531.44         In Date:       12/29/2010       Closed:       12/30/2010         Parts List       Q       1.1       1.1         Shop Supplies       1.1       1.1       1.1
- Shop Supplies Hours 7.00 Labor : Workorder: 1014155 Meter: 16029 Problem: FRONT RIGHT HEAD LIGHT OUT	Ca10262 Air Filter Mtc Fa1883 Wix 49883       1.1         5w20 Engine Oil       8.1         1066 White Lithium (crc 05037)       1.1         31-20 Wiper Blades 20" Blade       2.1         Ha238c Strobe Bulb Use Whelen #s30hac       1.1         420.00       Parts: 111.44       Total: 531.44         In Date:       12/29/2010       Closed:       12/30/2010         Parts List       Q

Workorder: 1104243 Meter: 17515 Problem: P. M. SERVICE	In Date: 04/19/2011 Closed:	04/28/2011
- P. M. Service	Parts List	Qty
- Replace 4 tires & fill with Nitrogen.	Shop Supplies	1.00
- Service winch.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Service tail gate lift.	5w20 Engine Oil	8.00
- Shop Supplies	Used Firex Refurbed Fire Extingshers	1.00
	Lt265/70r17 121/118s Sr-a Tire	4.00
	Waste Fee	4.00
	Tire Disposal Fee	4.00
Hours 8.00 Labor	480.00 Parts: 801.32 Total	: 1,281.32
Workorder:         1111908         Meter:         21301           Problem:         P. M. SERVICE	In Date: 11/04/2011 Closed:	11/15/2011
- P. M. Service.	Parts List	Qty
- Repaired socket for tail light. R&r bulb center brake.	Shop Supplies	1.00
- Repaired connection to coil pack.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Serviced power tail gate.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Unsiezed & lube rollers.	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
- Shop Supplies	5w20 Engine Oil	8.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 8.00 Labor	480.00 Parts: 62.81 Total	: 542.81
Workorder:1113579Meter:22812Problem:Driver's side seat belt latch will not work	In Date: 12/30/2011 Closed:	01/27/2012
- Transport & pick up vehicle at dealer. Defective driver's	Parts List	Qty
side seat belt buckle. - Shop Supplies	Shop Supplies	1.00
	120.00 Parts: 2.00 Total	: 122.00
Workorder:1203084Meter:24872Problem:won't start sometimes	In Date: 03/30/2012 Closed:	04/03/2012
- test charging and starting sys battery failed load test after	Parts List	Qty
recharge replace battery with new	Shop Supplies	1.00
- Shop Supplies	Group 65 Battery (mtc Bxt-65-850)	1.00
Hours 1.00 Labor	60.00 Parts: 127.23 Total	: 187.23

	1204053 pm svc, trucl	Meter: k wont start	25694 ,check all ligh	nts, dead	battery, to	In Date:	04/30/2012	Closed:	05/09/20	12
- pm	-		-		Parts Li	st				Qty
- replace both	n rear brake lig	ght bulbs			Shop Su	upplies				1.00
- service pow	er tail gate	-			1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- service winc	- service winch					Fuel Filter	Mtc Fg1083 W	/ix 33243		1.00
- repair right front tire repair left rear tire					5w20 Er	ngine Oil				8.00
- ck truck wont start scan and was unable to communicate					1066 W	hite Lithium	(crc 05037)			1.00
with pcm perform pin point test and found fuse #71misisng replace fuse clear codes and test drive					Used Fi	rex Refurbe	d Fire Extings	hers		1.00
- Shop Suppli					31-20 W	/iper Blades	20" Blade			2.00
- Shop Suppli	162				3157 Ta	il Light Bulb	S			2.00
	Hou	urs 12.00		Labor:	720.00	Parts:	68.16	Total:	788.16	
	1204055 dead battery			. 40000		In Date:	04/30/2012	Closed:	04/30/20	12
- Tow From: 1 jog road delra		cess road b	oca raton To	5: 13026						
	Hou :	urs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder:										
	1204804 Won't start, s	Meter: sounds like s	25802 starter. Cont	act phone	# 954-79	In Date: 93-3076. DC	05/22/2012 D-19931, tow 1	Closed: to SR Shop.	05/22/20	12
	Won't start, s	sounds like s	starter. Cont	•	# 954-79				05/22/20	12
Problem: - Tow From: \$	Won't start, s Sunoco, Jog F	sounds like s	starter. Cont	•			D-19931, tow 1			12
Problem: - Tow From: S Shop Workorder:	Won't start, s Sunoco, Jog F	sounds like s Rd. & Yamat urs 0.00 Meter:	o, Boca Rato	on To: Sr		93-3076. DC	D-19931, tow 1	to SR Shop.		
Problem: - Tow From: S Shop Workorder: Problem: - Ck no start,	Won't start, s Sunoco, Jog F Hou : 1204806 Towed in, wo perform pinpo	sounds like s Rd. & Yamat urs 0.00 <b>Meter:</b> on't start (c/o pint & found	starter. Conta o, Boca Rato 25888 :: starter) bad starter. F	n To: Sr Labor:	0.00 Parts Li	93-3076. DC Parts: In Date: st	0.00	to SR Shop. Total:	0.00	
Problem: - Tow From: S Shop Workorder: Problem: - Ck no start, left front tire, for - Repair weat	Won't start, s Sunoco, Jog F Hou : 1204806 Towed in, wo perform pinpo ender well & r her strip for bo	sounds like s Rd. & Yamat urs 0.00 <b>Meter:</b> on't start (c/o point & found replace start	25888 c: starter) bad starter. Fer.	n To: Sr Labor:	0.00	93-3076. DC Parts: In Date: st	0.00	to SR Shop. Total:	0.00	12 Qty
Problem: - Tow From: S Shop Workorder: Problem: - Ck no start, left front tire, for	Won't start, s Sunoco, Jog F Hou : 1204806 Towed in, wo perform pinpo ender well & r her strip for bo	sounds like s Rd. & Yamat urs 0.00 <b>Meter:</b> on't start (c/o point & found replace start	25888 c: starter) bad starter. Fer.	n To: Sr Labor:	0.00 Parts Li Shop Su	93-3076. DC Parts: In Date: st	0.00	Total:	0.00	12 <b>Qty</b> 1.00

- replace left front head light bulb 1372 Oil Filter 1 - replace ight rear brake light Napa Quart 5w20 6 - replace deking right rear axle seal and axle ring seal Miniature Bulb 1 - replace leaking right rear axle seal and axle ring seal Miniature Bulb 1 - replace leaking right rear axle seal and axle ring seal Miniature Bulb 1 - replace right rear pakr brake shoes 1265 70:17 Sra 4 - svc winch 874ke Shoes 1 - svc tail gate and repair tail gate cable Rear 5 - svc winch 85 W 140 Drum South 2 - svc bulpes Rear Seal 4 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 4 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 4 - fill tires risk light bulb Reter: 39582 In Date: 09/20/2013 Closed: 09/25/201 Problem: repair left rear brake light - - repair left rear brake light bulb Parts List Bulb 1 - repair left rear brake light not space 1 - worthy robite pin or hitch pin install new pin and pintle - worthy robite spin left rear brake light not space 1 - swc and test power tail gate mount - - swo and test power tail gate mount - - shop Supplies - - fours 7.25 Labor: 43:00 Parts: 89.53 Total: 524.53 - repair spin se - - fours 7.25 Labor: 43:00 Parts: 89.53 Total: 524.53 - repair and rewire wire harness for right rear trailer brake Bulb - - repair and rewire wire harness for right rear trailer brake Bulb - - repair and rewire wire harness for right rear trailer brake Bulb - - repair and rewire wire harness for right rear trailer brake Shop Supplies - - Shop Supplies - - replace right rear brake light bulb replace tag light bulb - - repair and rewire wire harness for right rear trailer brake Shop Supplies - - replace right rear brake light bulb replace tag light bulb - - replace right rear brake light bulb replace tag light bulb - - replace right rear brake light bulb replace tag light bulb - - r	Workorder: 130	0899 <b>Meter:</b> 32	2443		In Date:	01/25/2013	Closed:	02/12/20	013
- replace left front head light bulb - replace right rear brake light - replace right rear brake light - replace right rear brake light - replace right rear brake shoes - replace right rear pakr brake shoes - replace right rear pakr brake shoes - replace right rear pakr brake shoes - svc winch - svc tail gate and repair tail gate cable - svc winch - svc tail gate and repair tail gate cable - flitt trees vitake light - flut trees vitake light - repair left rear brake light bulb - repair left rear brake light bulb mush guard - svc winch wrap cable lube rollers tighten brush guard - svc winch wrap cable lube rollers tighten brush guard - shop Supplies - replace right rear brake light turm signal not working - replace right rear brake light fught turm signal not working - replace right rear brake light bulb replace tag light bulb - repair and rewire wire harness for right rear trailer brake - shop Supplies - shop Supplies - shop Supplies	Problem: PM	FRONT HEAD LIGHT	, BACK BRAKE LIG	GHT , PUL	L CORD F	OR LIFT GAT	E		
- replace right rear brake light	- pm			Parts Lis	st				Qty
- replace 4 tires Halogen Lamp 1 - replace leaking right rear axle seal and axle ring seal Miniature Bulb 1 - replace leaking right rear axle seal and axle ring seal Miniature Bulb 1 - replace right rear park brake shoes L1265 70r17 Sr-a 4 - svc vinch Brake Cleaner 1 - svc tail gate and repair tail gate cable Reman Brake Shoes 1 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 1 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 1 - Hours 15.00 Labor: 900.00 Parts: 1,123.71 Total: 2,023.71 Workorder: 1309535 Meter: 39582 In Date: 09/20/2013 Closed: 09/25/201 Problem: repair left rear brake light - repair left rear brake light bulb Parts List Bulb 1 - repair left rear brake light bulb Parts List 1 - verify no pintle pin or hitch pin install new pin and pintle Napagold Cul Filter 1 - svc winch wrap cable lube rollers tighten brush guard mounting bolts - svc winch wrap cable lube rollers tighten brush guard mounting bolts - Shop Supplies 1 - Shop Supplies - Labor: 435.00 Parts: 89.53 Total: 524.53 Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/201 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and rewire wire harness for right rear trailer brake light bulb - repair and r	- replace left front	head light bulb		1372 Oil Filter					1.00
- replace leaking right rear axle seal and axle ring seal Miniture Bulb 1 - replace right rear pakr brake shoes Lt265 70:17 Sr-a 4 - svc winch Brake Cleaner 1 - svc ail gate and repair tail gate cable Reman Brake Shoes 1 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 1 - fill tires with nitrogen 85 W 140 Drum South 2 - Shop Supplies Rear Seal 1 - fill tires with nitrogen 900.00 Parts: 1,123.71 Total: 2,023.71 - T	- replace right rear	<sup>·</sup> brake light		Napa Quart 5w20					8.00
- replace right rear pake brokes bloes L1265 70r17 Sr-a 4 4 - svo winch Brake Cleaner 1 - svo tail gate and repair tail gate cable Reman Brake Shoes 1 - svo tail gate and repair tail gate cable Reman Brake Shoes 1 - store tail gate and repair tail gate cable Reman Brake Shoes 1 - store tail gate and repair tail gate cable Reman Brake Shoes 1 - store tail gate and repair tail gate cable Reman Brake Shoes 1 - store St	- replace 4 tires			Halogen	Lamp				1.00
- svc winch - svc kinch - svc	- replace leaking r	ight rear axle seal and a	ixle ring seal	Miniature	e Bulb				1.00
- svc tail gate and repair tail gate cable - fill titres with nitrogen -	- replace right rear	pakr brake shoes		Lt265 70	r17 Sr-a				4.00
- fill tires with nitrogen - fill tires with nitrogen - Shop Supplies - Shop Supplies - Shop Supplies - Hours 15.00 - Labor: - Hours 15.00 - Labor: - 1009/20/2013 - Trie Disposal Fee - 4 - Trie Dispose - Trie D	- svc winch			Brake Cl	eaner				1.00
- Shop Supplies Rear Seal 1 Axle O Ring 1 Shop Supplies 1 Tire Disposal Fee 4 Hours 15.00 Labor: 900.00 Parts: 1,123.71 Total: 2,023.71 Total: 30.99 Total: 50 Total: 524.53 Total: 524.53 Total: 524.5	- svc tail gate and	repair tail gate cable		Reman E	Brake Shoe	S			1.00
Axle O Ring 1 Shop Supplies 1 Tire Disposal Fee 4 Hours 15.00 Labor: 900.00 Parts: 1,123.71 Total: 2,023.71 Problem: repair left rear brake light repair left rear brake light 0 Parts List 0 Problem: pm p	- fill tires with nitro	gen		85 W 140	0 Drum So	uth			2.00
Shop Supplies       1         Tire Disposal Fee       4         Tire Disposal Fee       4         Hours 15.00       Labor:       900.00       Parts:       1,123.71       Total:       2,023.71         Workorder:       1309535       Meter:       39582       In Date:       09/20/2013       Closed:       09/25/201         Problem:       repair left rear brake light bulb       Parts List       5       09/23/2013       Closed:       10/04/201         Hours 0.50       Labor:       30.00       Parts:       0.99       Total:       30.99         *       Hours 0.50       Labor:       30.00       Parts:       0.9/23/2013       Closed:       10/04/201         Problem:       pm       Parts List       1       10/04/201       1	- Shop Supplies			Rear Sea	al				1.00
Tire Disposal Fee Hours 15.00 Labor: 900.00 Parts: 1,123.71 Total: 2,023.71 Workorder: 1309535 Meter: 39582 Problem: repair left rear brake light - repair left rear brake light bulb Hours 0.50 Labor: 30.00 Parts: 0.99 Total: 30.99 Workorder: 1309619 Meter: 39582 In Date: 09/23/2013 Closed: 10/04/201 Problem: pm - pm - pm - pm - pm - pm - pm - pm - yerify no pintle pin or hitch pin install new pin and pintle Napagold Fuel Filter - verify no pintle pin or hitch pin install new pin and pintle - svc and test power tail gate - svc and test power tail gate - svc and test power tail gate - svc inch wrap cable lube rollers tighten brush guard mounting bolts - Shop Supplies Workorder: 1400949 Meter: 43546 Hours 7.25 Labor: 435.00 Parts List - repair and rewire wire harness for right rear trailer brake Ight - Shop Supplies				Axle O R	ling				1.00
Hours 15.00Labor:900.00Parts:1,123.71Total:2,023.71Workorder:1309535Meter:39582In Date:09/20/2013Closed:09/25/201Problem:repair left rear brake lightParts ListBulb1- repair left rear brake light bulbParts List50.00Parts:0.99Total:30.99Workorder:1309619Meter:39582In Date:09/23/2013Closed:10/04/201Problem:pm-Parts List111- verify no pintle pin or hitch pin install new pin and pintleNapagold Fuel Filter11- verify no pintle pin or hitch pin install new pin and pintleNapagold Fuel Filter11- svc and test power tail gateNapa Quart 5w2022- svc winch wrap cable lube rollers tighten brush guard31-20 Wiper Biades 2022mounting boltsUsed Fire X Refurbished11- Shop Supplies1Used Fire X Refurbished1Hours 7.25Labor:435.00Parts:89.53Total:Morkorder:1400949Meter:43546In Date:01/29/2014Closed:02/10/201Problem:hazzard, brake light, right turn signal not workingParts List11- repair and rewire wire harness for right rear trailer brakeBulb11- repair and rewire wire harness for right rear trailer brakeBulb1- repair and rewire wire harness for right rear tra				Shop Su	pplies				1.00
Workorder:       1309535       Meter:       39582       In Date:       09/20/2013       Closed:       09/25/201         Problem:       repair left rear brake light       Parts List       0				Tire Disp	osal Fee				4.00
Problem:       repair left rear brake light         - repair left rear brake light bulb       Parts List         Bulb       1         Hours 0.50       Labor:         :       0.00         Problem:       pm         - prm       Parts List         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Fuel Filter         1       Napagold Fuel Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Fuel Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Fuel Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Oil Filter       1         - svc winch wrap cable lube rollers tighten brush guard       31-20 Wiper Blades 20       2         mounting bolts       31-20 Wiper Blades 20       2         - Shop Supplies       Used Fire X Refurbished       1         In Date:       01/29/2014       Closed:       02/10/201         Mark Wite Lithium Gres       1       1       2560 Hitch Pin-clip       1         Mark Wite Lithium Gres       1       1       254.53       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1 <t< td=""><td></td><td>Hours 15.00</td><td>Labor:</td><td>900.00</td><td>Parts:</td><td>1,123.71</td><td>Total:</td><td>2,023.7</td><td>1</td></t<>		Hours 15.00	Labor:	900.00	Parts:	1,123.71	Total:	2,023.7	1
- repair left rear brake light bulb Parts List Bulb 1 Hours 0.50 Labor: 30.00 Parts: 0.99 Total: 30.99 Workorder: 1309619 Meter: 39582 In Date: 09/23/2013 Closed: 10/04/201 Problem: pm - pm - ym - ver pin tich pin install new pin and pintle - ver and test power tail gate Napa Quart 5w20 6 - svc winch wrap cable lube rollers tighten brush guard - svc and test power tail gate Napa Quart 5w20 6 - svc winch wrap cable lube rollers tighten brush guard - Shop Supplies 1 - Shop Supplies 1 - replace right rear trake light, right turn signal not working - - replace right rear brake light, right turn signal not working - - replace right rear brake light, hight turn signal not working - - shop Supplies 1 - shop Supplies 1 - replace right rear brake light bulb replace tag light bulb - - replace right - - rep			9582		In Date:	09/20/2013	Closed:	09/25/20	013
Bulb       1         Hours 0.50       Labor: 30.00       Parts: 0.99       Total: 30.99         Workorder:       1309619       Meter: 39582       In Date: 09/23/2013       Closed: 10/04/201         Problem: pm       Parts List       Napagold Full Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Full Filter       1         Napagold Full Filter       1       Napagold Full Filter       1         - svc and test power tail gate       Napa Quart 5w20       2         - svc winch wrap cable lube rollers tighten brush guard       31-20 Wiper Blades 20       2         - Shop Supplies       Used Fire X Refurbished       1         - Shop Supplies       Used Fire X Refurbished       1         Hours 7.25       Labor:       435.00       Parts: 89.53       Total: 524.53         Workorder:       1400949       Meter: 43546       In Date:       01/29/2014       Closed:       02/10/201         Problem:       hazzard, brake light, right turn signal not working       1       1       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1 <td< td=""><td>Problem: repa</td><td>air left rear brake light</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	Problem: repa	air left rear brake light							
Hours 0.50 :Labor: 30.00Parts: 0.99Total: 30.99Workorder:1309619Meter: 39582In Date: 09/23/2013Closed: 10/04/201Problem:pmParts List10/04/201- verify no pintle pin or hitch pin install new pin and pintleNapagold Fuel Filter1- verify no pintle pin or hitch pin install new pin and pintleNapagold Fuel Filter1- svc and test power tail gateNapa Quart 5w208- svc and test power tail gateNapa Quart 5w202- svc winch wrap cable lube rollers tighten brush guard mounting bolts31-20 Wiper Blades 202- Shop SuppliesUsed Fire X Refurbished1Pintle Pin W/chain12560 Hitch Pin-clip1Morkorder:1400949Meter: 43546In Date: 01/29/2014Closed: 02/10/201Problem:hazard, brake light, right turn signal not workingParts List1- replace right rear brake light bulb replace tag light bulbParts List1- replar and rewire wire harness for right rear trailer brakeBulb1- Shop Supplies1551- shop Supplies1551- replar and rewire wire harness for right rear trailer brakeBulb1- shop Supplies155- shop Supplies15- shop Supplies1- shop Supplies1- shop Supplies1- shop Supplies1- shop Supplies1- shop Supplies1 </td <td>- repair left rear br</td> <td>ake light bulb</td> <td></td> <td>Parts Lis</td> <td>st</td> <td></td> <td></td> <td></td> <td>Qty</td>	- repair left rear br	ake light bulb		Parts Lis	st				Qty
i:       In Date:       09/23/2013       Closed:       10/04/201         Problem:       pm       Parts List       In Date:       09/23/2013       Closed:       10/04/201         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Fuel Filter       1       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Oil Filter       1         - svc and test power tail gate       Napa Quart 5w20       8         - svc winch wrap cable lube rollers tighten brush guard mounting bolts       31-20 Wiper Blades 20       2         - Shop Supplies       Used Fire X Refurbished       1         - Shop Supplies       Used Fire X Refurbished       1         - Hours 7.25       Labor:       435.00       Parts: 89.53       Total:       524.53         - replace right rear brake light, right turn signal not working       -       In Date:       01/29/2014       Closed:       02/10/201         - repair and rewire wire harness for right rear trailer brake       Bulb       1       Shop Supplies       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       Shop Supplies       1				Bulb					1.00
Problem: pm       Parts List       1         - pm       Napagold Fuel Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Fuel Filter       1         - verify no pintle pin or hitch pin install new pin and pintle       Napagold Oil Filter       1         - svc and test power tail gate       Napa Quart 5w20       2         - svc winch wrap cable lube rollers tighten brush guard mounting bolts       31-20 Wiper Blades 20       2         - shop Supplies       Washer Fl       1         - Shop Supplies       Used Fire X Refurbished       1         - Burs 7.25       Labor       435.00       Parts: 89.53       Total:       524.53         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1         - sh		Hours 0.50	Labor:	30.00	Parts:	0.99	Total:	30.99	
- verify no pintle pin or hitch pin install new pin and pintle lube hitch repair license plate mount - svc and test power tail gate - svc winch wrap cable lube rollers tighten brush guard mounting bolts - Shop Supplies - Shop Supplies - Shop Supplies - Hours 7.25 - Hours 0.1/29/2014 -		9619 <b>Meter:</b> 39	9582		In Date:	09/23/2013	Closed:	10/04/20	013
lube hitch repair license plate mount       Napagold Oil Filter       1         - svc and test power tail gate       Napa Quart 5w20       8         - svc winch wrap cable lube rollers tighten brush guard       31-20 Wiper Blades 20       2         mounting bolts       31-20 Wiper Blades 20       2         - Shop Supplies       Used Fire X Refurbished       1         Pintle Pin W/chain       1       2560 Hitch Pin-clip       1         Mac Wite Lithium Gres       1       Mac Wite Lithium Gres       1         Shop Supplies       Hours 7.25       Labor:       435.00       Parts: 89.53       Total:       524.53         Workorder:       1400949       Meter:       43546       In Date:       01/29/2014       Closed:       02/10/201         Problem:       hazzard, brake light, right turn signal not working       -       -       -       -         - repair and rewire wire harness for right rear trailer brake       Bulb       1       1       -         - shop Supplies       -       -       -       -       -       -         - repair and rewire wire harness for right rear trailer brake       Bulb       1       -       -       -         - Shop Supplies       -       -       -       -       <	- pm			Parts Lis	st				Qty
- svc and test power tail gate Napa Quart 5w20 8 - svc winch wrap cable lube rollers tighten brush guard 31-20 Wiper Blades 20 2 Washer Fl 1 - Shop Supplies Used Fire X Refurbished 1 Pintle Pin W/chain 1 2560 Hitch Pin-clip 1 Mac Wite Lithium Gres 1 Shop Supplies 1 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 : Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/201 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb Parts List 9 - repair and rewire wire harness for right rear trailer brake 1 light Shop Supplies 1			v pin and pintle	Napagolo	d Fuel Filte	r			1.00
- svc winch wrap cable lube rollers tighten brush guard mounting bolts - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/201- Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb - repair and rewire wire harness for right rear trailer brake light - Shop Supplies - Shop Supplies - Shop Supplies - Shop Supplies - repair and rewire wire harness for right rear trailer brake light - Shop Supplies - Shop Supplies		•		Napagolo	d Oil Filter				1.00
mounting bolts Vasher Fl 1 - Shop Supplies Vasher Fl 1 - Shop Supplies Vasher Fl 1 Used Fire X Refurbished 1 Pintle Pin W/chain 1 2560 Hitch Pin-clip 1 Mac Wite Lithium Gres 1 Shop Supplies 1 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 : Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/201 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb Parts List 0 - repair and rewire wire harness for right rear trailer brake 8 In Date: 01/29/2014 Closed: 02/10/201 Problem: hazzard, brake light bulb replace tag light bulb 1 - repair and rewire wire harness for right rear trailer brake 8 Bulb 1 Shop Supplies 1	•	•		Napa Qu	art 5w20				8.00
- Shop Supplies Washer Fl 1 Used Fire X Refurbished 1 Pintle Pin W/chain 1 2560 Hitch Pin-clip 1 Mac Wite Lithium Gres 1 Shop Supplies 1 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 : Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/2014 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb Parts List 9 - repair and rewire wire harness for right rear trailer brake 8 light Shop Supplies 1		able lube rollers tighten	brush guard	31-20 Wi	iper Blades	s 20			2.00
Used Fire X Returbished 1 Pintle Pin W/chain 1 2560 Hitch Pin-clip 1 Mac Wite Lithium Gres 1 Shop Supplies 1 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 : Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/201 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light, bulb replace tag light bulb Parts List 0 - repair and rewire wire harness for right rear trailer brake Bulb 1 light Shop Supplies 1	-			Washer I	FI				1.00
2560 Hitch Pin-clip 1 Mac Wite Lithium Gres 1 Shop Supplies 1 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 : Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/2014 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb - repair and rewire wire harness for right rear trailer brake Bulb 1 Shop Supplies 1	- Onop Oupplies			Used Fire	e X Refurbi	ished			1.00
Mac Wite Lithium Gres 1 Shop Supplies 7 Hours 7.25 Labor: 435.00 Parts: 89.53 Total: 524.53 Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/2014 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb - repair and rewire wire harness for right rear trailer brake Bulb - shop Supplies 1				Pintle Pir	n W/chain				1.00
Shop Supplies       1         Hours 7.25       Labor: 435.00       Parts: 89.53       Total: 524.53         Workorder: 1400949       Meter: 43546       In Date: 01/29/2014       Closed: 02/10/2014         Problem: hazzard, brake light, right turn signal not working       - replace right rear brake light bulb replace tag light bulb       Parts List       0         - replace right rear brake light bulb replace tag light bulb       Parts List       0       0         - repair and rewire wire harness for right rear trailer brake light       Bulb       1         Shop Supplies       1       Shop Supplies       1				2560 Hite	ch Pin-clip				1.00
Hours 7.25       Labor: 435.00       Parts: 89.53       Total: 524.53         Workorder: 1400949       Meter: 43546       In Date: 01/29/2014       Closed: 02/10/2014         Problem: hazzard, brake light, right turn signal not working       - replace right rear brake light bulb replace tag light bulb       Parts List       - repair and rewire wire harness for right rear trailer brake       - Shop Supplies       1				Mac Wite	e Lithium G	res			1.00
: Workorder: 1400949 Meter: 43546 In Date: 01/29/2014 Closed: 02/10/2014 Problem: hazzard, brake light, right turn signal not working - replace right rear brake light bulb replace tag light bulb Parts List - repair and rewire wire harness for right rear trailer brake Bulb 11 light Shop Supplies 1				Shop Su	pplies				1.00
Problem:       hazzard, brake light, right turn signal not working         - replace right rear brake light bulb replace tag light bulb       Parts List       0         - repair and rewire wire harness for right rear trailer brake light       Bulb       1         - Shop Supplies       1       1		Hours 7.25	Labor:	435.00	Parts:	89.53	Total:	524.53	
<ul> <li>repair and rewire wire harness for right rear trailer brake</li> <li>light</li> <li>Shop Supplies</li> </ul>				ng	In Date:	01/29/2014	Closed:	02/10/20	014
<ul> <li>repair and rewire wire harness for right rear trailer brake</li> <li>light</li> <li>Shop Supplies</li> </ul>	- replace right rear	· brake light bulb replace	e tag light bulb	Parts Lis	st				Qty
- Shop Supplies				Bulb					1.00
	light	5		Shop Su	pplies				1.00
Hours 3.50 Labor: 210.00 Parts: 2.99 Total: 212.99	and adduice	Hours 3.50	Labor:	210.00	Parts:	2.99	Total:	212.99	

Workorder: Problem:	1403257 pm	Meter:	44328			In Date:	04/03/2014	Closed:	04/08/20	)14
- pm					Parts Lis	st				Qty
- svc winch					Napagol	d Oil Filter				1.00
- svc power ta	ail gate				Napa Qu	art 5w20				8.00
- repair rr tire	mount balanc	e add n2			Washer	FI				1.00
- Shop Suppli	ies				Macs Ch	ain Cable I	ube			1.00
					Shop Su	pplies				1.00
	Hou :	irs 5.75		Labor:	345.00	Parts:	45.32	Total:	390.32	
Workorder: Problem:	1403670 replace bulb	Meter: tag	44414			In Date:	04/15/2014	Closed:	04/21/20	)14
- repair tag lig	ght									
	Hou	ırs 0.50		Labor:	30.00	Parts:	0.00	Total:	30.00	
	1406215 ROAD CALL	<b>Meter:</b> , FLAT TIR	45641 E			In Date:	06/25/2014	Closed:	06/26/20	)14
Problem: - ck raod call	ROAD CALL to flat tire insta	, FLAT TIR	E	unt	Parts Lis		06/25/2014	Closed:	06/26/20	
Problem: - ck raod call	ROAD CALL to flat tire insta	, FLAT TIR	E	unt	Parts Lis Lt265 70	st	06/25/2014	Closed:	06/26/20	Qty
Problem: - ck raod call balance add n - travel fromt	ROAD CALL to flat tire insta 2 sr shop to 441	, FLAT TIR all spare rr	E two tires mou			<b>st</b> r17 Sr-a	06/25/2014	Closed:	06/26/20	<b>Qty</b> 2.00
- ck raod call balance add n	ROAD CALL to flat tire insta 2 sr shop to 441	, FLAT TIR all spare rr	E two tires mou		Lt265 70 Shop Su	<b>st</b> r17 Sr-a	06/25/2014	Closed:	06/26/20	<b>Qty</b> 2.00 1.00
Problem: - ck raod call balance add n - travel fromt	ROAD CALL to flat tire insta 2 sr shop to 441 ies	, FLAT TIR all spare rr	E two tires mou	r flat tire	Lt265 70 Shop Su	<b>st</b> r17 Sr-a pplies posal Fee	06/25/2014 510.48		06/26/20 660.48	<b>Qty</b> 2.00 1.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder:	ROAD CALL to flat tire insta 2 sr shop to 441 ies	, FLAT TIR all spare rr and yama urs 2.50 Meter:	E two tires mou to rd to repair 47264	r flat tire	Lt265 70 Shop Su Tire Disp	<b>st</b> r17 Sr-a pplies posal Fee				<b>Qty</b> 2.00 1.00 2.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder: Problem:	ROAD CALL to flat tire insta 2 sr shop to 441 ies Hou : 1408143	, FLAT TIR all spare rr and yama irs 2.50 <u>Meter:</u> EAR TIRE	E two tires mou to rd to repain 47264 FLAT	r flat tire Labor:	Lt265 70 Shop Su Tire Disp	st r17 Sr-a pplies bosal Fee Parts: In Date:	510.48	Total:	660.48	<b>Qty</b> 2.00 1.00 2.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder: Problem:	ROAD CALL to flat tire insta 2 sr shop to 441 ies Hou : 1408143 TOW IN/ R/R	, FLAT TIR all spare rr and yama irs 2.50 <u>Meter:</u> EAR TIRE	E two tires mou to rd to repain 47264 FLAT	r flat tire Labor:	Lt265 70 Shop Su Tire Disp 150.00	st r17 Sr-a pplies bosal Fee Parts: In Date:	510.48	Total:	660.48	<b>Qty</b> 2.00 1.00 2.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder: Problem: - repair right r	ROAD CALL to flat tire insta 2 sr shop to 441 ies Hou 1408143 TOW IN/ R/F rear tire dismo	, FLAT TIR all spare rr and yama irs 2.50 <u>Meter:</u> EAR TIRE	E two tires mou to rd to repain 47264 FLAT	r flat tire Labor:	Lt265 70 Shop Su Tire Disp 150.00 Parts Lis Shop Su	st r17 Sr-a pplies bosal Fee Parts: In Date:	510.48 08/15/2014	Total: Closed:	660.48	<b>Qty</b> 2.00 1.00 2.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder: Problem: - repair right r	ROAD CALL to flat tire insta 2 sr shop to 441 ies Hou : 1408143 TOW IN/ R/F rear tire dismo ies Hou : 1408525	, FLAT TIR all spare rr and yama irs 2.50 <u>Meter:</u> EAR TIRE unt patch n	E two tires mou to rd to repain 47264 FLAT	r flat tire Labor: e add n2	Lt265 70 Shop Su Tire Disp 150.00 Parts Lis Shop Su	st pplies posal Fee Parts: In Date: st pplies	510.48 08/15/2014	Total: Closed:	660.48 08/19/20	<b>Qty</b> 2.00 1.00 2.00 014 <b>Qty</b> 1.00
Problem: - ck raod call balance add n - travel fromt - Shop Suppli Workorder: Problem: - repair right r - Shop Suppli Workorder: Problem:	ROAD CALL to flat tire insta 2 sr shop to 441 ies Hou : 1408143 TOW IN/ R/F rear tire dismo ies Hou : 1408525	, FLAT TIR all spare rr and yama ars 2.50 <b>Meter:</b> EAR TIRE unt patch n ars 1.00 <b>Meter:</b>	E two tires mou to rd to repain 47264 FLAT nount balance 47453	r flat tire Labor: e add n2 Labor:	Lt265 70 Shop Su Tire Disp 150.00 Parts Lis Shop Su	st r17 Sr-a pplies bosal Fee Parts: In Date: st pplies Parts:	510.48 08/15/2014 2.00	Total: <b>Closed:</b> Total:	660.48 08/19/20 62.00	Qty 2.00 1.00 2.00 014 Qty 1.00

Workorder: Problem:	1408540 pm, left tail l	<b>Meter:</b> ight , tag ligh	47551 nt and cover		In [	Date:	08/26/2014	Closed:	09/15/20	14
- pm					Parts List					Qty
-	s 2 tires mour	nt balance ad	dd n2 rotate to	o front	179535492 L	_t265-7	0r17			2.00
•	and tag light re				Napagold Fu	el Filte	r			1.00
bracket		-	-	-	Napagold Oi	I Filter				1.00
- svc winch					Napa Quart &	5w20				8.00
- svc power li	iftgate				Wiper Blade					2.00
- Shop Suppl	lies				Washer Fl					1.00
					License Brac	ket W/	light			1.00
					Bulb					2.00
					Macs Chain	Cable I	_ube			1.00
					Shop Supplie	es				1.00
					Tire Disposa	l Fee				2.00
	Ho	urs 7.25		Labor:	435.00	Parts:	620.48	Total:	1,055.48	
Workorder:	1409816	Meter:	47996		In [	Date:	09/30/2014	Closed:	10/09/20	14
Problem:	making strai	-	-	()	Devis L'at					0.
Problem: - ck making s bad cat conve - transport an converter	strange noise erter nd pick up veh	verify custoi	mer concern f		Parts List Shop Supplie	es				-
Problem: - ck making s bad cat conve - transport an	strange noise erter nd pick up veh lies	verify custoi	mer concern f	at		es Parts:	2.00	Total:	182.00	-
Problem: - ck making s bad cat conve - transport an converter - Shop Suppl Workorder:	strange noise erter nd pick up veh lies Ho : 1411238	verify custoin iicle at deale urs 3.00 Meter:	er deffective ca	at Labor:	Shop Supplie 180.00	Parts: Date:	2.00	Total: Closed:	182.00 12/04/20	1.00
Problem: - ck making s bad cat conve - transport an converter - Shop Suppl Workorder: Problem: - replace dam	strange noise erter nd pick up veh lies Ho : 1411238 cable broke nage trailer fe	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00	Parts: Date:				1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dam away brake co	strange noise erter nd pick up veh lies Ho : 1411238 cable broke nage trailer fe ontroller on da	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In E connectiond e	Parts: Date: elec	11/10/2014			<b>Qty</b> 1.00 14 <b>Qty</b> 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brob	strange noise erter nd pick up veh lies Ho : 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List	Parts: Date: elec n Socke	11/10/2014			1.00 14 <b>Qty</b>
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brol - replace brol	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Conr	Parts: <b>Date:</b> elec n Socke	11/10/2014			1.00 14 <b>Qty</b> 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brob	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Conr Brake Contr	Parts: Date: elec n Socke ol pe	11/10/2014			1.00 14 14 1.00 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brological - replace brological	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In E connectiond of Parts List Female Conr Brake Contr Electrical Tap	Parts: Date: elec n Socke ol pe ectors	11/10/2014			1.00 14 <b>Qty</b> 1.00 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brol - replace brol	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Contr Brake Contr Electrical Taj 12-10 Conne	Parts: Date: elec n Socke ol pe ectors	11/10/2014			1.00 14 <b>Qty</b> 1.00 1.00 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brological - replace brological	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Conr Brake Contr Electrical Tap 12-10 Conne Atm-25 Fuse	Parts: Date: elec ol pe ectors	11/10/2014 et			1.00 14 <b>Qty</b> 1.00 1.00 2.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brological - replace brological	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Contr Brake Contr Brake Contr Electrical Taj 12-10 Conne Atm-25 Fuse Bulb	Parts: Date: elec ol pe ectors e onn - Y	11/10/2014 et			1.00 14 14 1.00 1.00 1.00 1.00 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brol - replace brol	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Conr Brake Contr Electrical Tap 12-10 Conne Atm-25 Fuse Bulb 12-10 Butt C Cable Releas	Parts: Date: elec ol pe ectors onn - Y se Kit	11/10/2014 et			1.00 14 <b>Qty</b> 1.00 1.00 2.00 1.00
Problem: - ck making s bad cat conver- - transport and converter - Shop Suppl Workorder: Problem: - replace dama away brake co - replace brol - replace brol	strange noise erter nd pick up veh lies 1411238 cable broke nage trailer fe ontroller on da ken lift gate ca	verify custoin iicle at deale urs 3.00 <b>Meter:</b> on the backs male connect	49186 side of lift gate	at Labor: e replace	Shop Supplie 180.00 In C connectiond of Parts List Female Conr Brake Contr Electrical Taj 12-10 Conne Atm-25 Fuse Bulb 12-10 Butt C	Parts: Date: elec ol pe ectors e onn - Y se Kit es	11/10/2014 et			1.00 14 14 1.00 1.00 1.00 1.00 1.00 1.00

Workorder: Problem:	1412115 misfiring	Meter:	49421			In Date:	12/03/2014	Closed:	12/29/20	014
- ck misfiring found #1 coil test drive		ound po301 pe coil with good			Parts Lis Shop Sup	-				<b>Qty</b> 1.00
- test drive 2 this time	times total s	90 miles unab	le to verify co	oncern at						
- Shop Suppl	ies									
	ŀ	lours 4.00		Labor:	240.00	Parts:	2.00	Total:	242.00	
Workorder: Problem:	1502226 pm	Meter:	51024			In Date:	03/03/2015	Closed:	03/13/20	015
- pm					Parts Lis	st				Qty
- svc winch					Napagolo	d Air Filter				1.00
- service pow	ver tail gate				Napagolo	d Oil Filter				1.00
- replace third	d brake ligh	t bulb			Napa Qua	art 5w20				8.00
- Shop Suppl	ies				Shop Sup	oplies				1.00
	F	lours 5.25		Labor:	315.00	Parts:	43.99	Total:	358.99	
Workorder: Problem:	1505485 while drivi	Meter: ng with trailer	52119 hook up the	trans was		In Date:	06/01/2015	Closed:	06/09/20	)15
Problem:	while drivi ving with tra scan for coc ern at this ti	ng with trailer iler transmissi les perform sy	hook up the	g test		st	06/01/2015	Closed:	06/09/20	Qty
Problem: - ck while driv drive vehicle s to verify conce	while drivi ving with tra scan for coc ern at this ti ies	ng with trailer iler transmissi les perform sy	hook up the	g test as unable	slipping Parts Lis	st			06/09/20	Qty
Problem: - ck while drive drive vehicles to verify conce - Shop Suppl Workorder:	while drivi ving with tra scan for coo ern at this ti ies <u>F</u> 1505544	ng with trailer iler transmissi les perform sy me	hook up the	g test as unable	slipping <b>Parts Lis</b> Shop Sup 120.00	st oplies				<b>Qty</b> 1.00
Problem: - ck while drive drive vehicle s to verify conce - Shop Suppl Workorder: Problem:	while drivi ving with tra scan for coo ern at this ti ies H 1505544 transmissi	ng with trailer iler transmissi les perform sy me Hours 2.00 <b>Meter:</b>	hook up the ion is slipping is test and wa	g test as unable Labor:	slipping <b>Parts Lis</b> Shop Sup 120.00	st oplies Parts:	2.00	Total:	122.00	<b>Qty</b> 1.00
Problem: - ck while drive drive vehicle s to verify conce - Shop Suppl Workorder: Problem:	while drivi ving with tra scan for coc ern at this ti ies <u>1505544</u> transmissi 9400 w palr	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem	hook up the ion is slipping is test and wa	g test as unable Labor:	slipping <b>Parts Lis</b> Shop Sup 120.00	st oplies Parts:	2.00 06/01/2015	Total:	122.00	<b>Qty</b> 1.00
Problem: - ck while drive drive vehicles to verify conce - Shop Suppl Workorder: Problem: - Tow From: Workorder:	while drivi ving with tra scan for coc ern at this ti ies 1505544 transmissi 9400 w palr <u>+</u> 1509114	ng with trailer iler transmissi des perform sy me Hours 2.00 <b>Meter:</b> ion problem netto pk rd To	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00	st oplies Parts: In Date: Parts: In Date:	2.00 06/01/2015 0.00 09/11/2015	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	<b>Qty</b> 1.00
Problem: - ck while drive drive vehicles to verify conce - Shop Suppl Workorder: Problem: - Tow From: Workorder:	while drivi ving with tra scan for coc ern at this ti ies 1505544 transmissi 9400 w palr <u>+</u> 1509114	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00	st oplies Parts: In Date: Parts: RE EVERY	2.00 06/01/2015 0.00 09/11/2015	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	<b>Qty</b> 1.00
Problem: - ck while drive drive vehicles to verify conce - Shop Supple Workorder: Problem: Workorder: Problem:	while drivi ving with tra scan for coc ern at this ti ies 1505544 transmissi 9400 w palr <u>+</u> 1509114	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00 MAKE SUF Parts Lis	st oplies Parts: In Date: Parts: RE EVERY	2.00 06/01/2015 0.00 09/11/2015 THINGIN WC	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	<b>Qty</b> 1.00
Problem: - ck while drive drive vehicles to verify conce - Shop Supple Workorder: Problem: Workorder: Problem: - pm	while drivi ving with tra scan for coc ern at this ti ies 1505544 transmissi 9400 w palr H 1509114 P.M.SERV	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00 MAKE SUF Parts Lis Napagolo	st oplies Parts: In Date: Parts: RE EVERY	2.00 06/01/2015 0.00 09/11/2015 THINGIN WC	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	<b>Qty</b> 1.00 015 015 <b>Qty</b>
Problem: - ck while driv drive vehicles to verify conce - Shop Suppl Workorder: Problem: - Tow From: : Workorder: Problem: - pm - svc winch	while drivi ving with tra scan for coo ern at this ti ies 1505544 transmissi 9400 w palr 1509114 P.M.SERV ail gate	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00 MAKE SUF Parts Lis Napagolo	st oplies Parts: In Date: Parts: RE EVERY St d Fuel Filte d Oil Filter	2.00 06/01/2015 0.00 09/11/2015 THINGIN WC	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	Qty 1.00 015 015 015 015 015 015 015 015 015 0
Problem: - ck while drive drive vehicle s to verify conce - Shop Supple Workorder: Problem: Workorder: Problem: - pm - svc winch - svc power tagget	while drivi ving with tra scan for coo ern at this ti ies 1505544 transmissi 9400 w palr 1509114 P.M.SERV ail gate	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00 MAKE SUF Parts Lis Napagolo Napagolo	st oplies Parts: In Date: Parts: RE EVERY St J Fuel Filte d Gil Filter art 5w20	2.00 06/01/2015 0.00 09/11/2015 THINGIN WC	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	<b>Qty</b> 1.00 015 015 <b>Qty</b> 1.00
Problem: - ck while drive drive vehicle s to verify conce - Shop Supple Workorder: Problem: Workorder: Problem: - pm - svc winch - svc power tagget	while drivi ving with tra scan for coo ern at this ti ies 1505544 transmissi 9400 w palr 1509114 P.M.SERV ail gate	ng with trailer iler transmissi les perform sy me lours 2.00 <b>Meter:</b> ion problem netto pk rd To lours 0.00 <b>Meter:</b>	hook up the ion is slipping is test and wa 52032 b: sr shop del 53559	y test as unable Labor: Iray Labor:	slipping Parts Lis Shop Sup 120.00 0.00 MAKE SUF Parts Lis Napagolo Napagolo Napagolo	st oplies Parts: In Date: Parts: Parts: In Date: RE EVERY St d Fuel Filter art 5w20 ade	2.00 06/01/2015 0.00 09/11/2015 THINGIN WC	Total: Closed: Total: Closed:	122.00 06/02/20 0.00 09/18/20	Qty 1.00 015 015 015 1.00 1.00 8.00

Palm Beach	<b>County Fleet</b>	Management
Asset	Maintenance	History

Problem: A	511378 VC INOP.	Meter:	54253		l	n Date:	11/05/2015	Closed:	11/30/20	)15
- ck noise from	ac found bad	ac comp	ressor and leak	ina	Parts List					Qty
hight side hose	evac remove	fan shrou	d right fonrt fend	der will	Tube Asy					1.00
replace ac comp			•		New Com	oressor				1.00
hose from comp - Shop Supplies		ale rechai	ige and ck for le	ans	Orifice Tub					1.00
- Shop Supplies	5				Rapid Sea	l Kit			1.00	
					Accumulat					1.00
					E8 A/c Oil		)ve			1.00
					South Reg		•			2.00
					Hose Asse					1.00
					v belt	Sinory				1.00
					Shop Sup	olies				1.00
	Hours	s 9.00		Labor.	540.00		772.19	Total	1,312.19	
	:	5 0.00		Lubol.	040.00	i uno.	_		-	
Workorder: 1 Problem: p	602721 om	Meter:	55944		I	n Date:	03/15/2016	Closed:	03/23/20	)16
- pm					Parts List					Qty
- repaired scoke	et assy for ligh	nt			Napagold	Oil Filter				1.00
- strobes inop c			ower circuits fue	se	Napa Qua	rt 5w20				8.00
blown repaired s	-				20" Wiper	Blade				2.00
<ul> <li>serviced winch</li> </ul>	hand freed up	rollers			Washer Fl	uid Conc	entr			1.00
- serviced powe	er fail gate and	l adj links			Napagold	Air Filter				1.00
- Shop Supplies	5				Used Fire	X Refurb	ished			1.00
					Shop Sup	olies				1.00
					Onop Oup					
	Hours	s 9.25		Labor:	555.00		68.86	Total:	623.86	
	Hours : 603381 engine light is	Meter:	56253 is sputtering	Labor:	555.00		68.86 03/31/2016	Total: Closed:	623.86 04/13/20	
	: 603381 engine light is	Meter: on and it	is sputtering	Labor:	555.00	Parts: n Date:				
Problem: e - Check engine P0316.pinpoint t	: 603381 engine light is light on.scan test.replace al	Meter: on and it test.code I spark pl	is sputtering P0301 and ugs and ignition		555.00	Parts: n Date:				)16
Problem: e - Check engine P0316.pinpoint t coils.clear codes	: 603381 engine light is light on.scan test.replace al s.extra labour	Meter: on and it test.code I spark pl	is sputtering P0301 and ugs and ignition		555.00 In Parts List Spark Plug	Parts: n Date:				016 <b>Qty</b> 8.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder	: engine light is light on.scan test.replace al s.extra labour r heads.	Meter: on and it test.code I spark pl for extrac	is sputtering P0301 and ugs and ignition sting two broken	n I spark	555.00	Parts: n Date:				016 <b>Qty</b> 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder - Perform induc	: engine light is light on.scan test.replace al s.extra labour r heads.	Meter: on and it test.code I spark pl for extrac	is sputtering P0301 and ugs and ignition sting two broken	n I spark	555.00 In Parts List Spark Plug Intake Cle Coil	Parts: n Date: g aner Kit				016 <b>Qty</b> 8.00 1.00 8.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder - Perform induc injectors	: 603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning,	Meter: on and it test.code I spark pl for extrac trottle boo	is sputtering P0301 and ugs and ignition sting two broken	n I spark	555.00	Parts: n Date: g aner Kit				016 <b>Qty</b> 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder - Perform induc injectors - Test drive befo	: l603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n	Meter: on and it test.code I spark pl for extrac trottle boo	is sputtering P0301 and ugs and ignition sting two broken	n I spark	555.00 In Parts List Spark Plug Intake Cle Coil	Parts: n Date: g aner Kit				016 <b>Qty</b> 8.00 1.00 8.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes olugs in cylinder - Perform induc njectors - Test drive befo	: l603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n	Meter: on and it test.code I spark pl for extrac trottle boo	is sputtering P0301 and ugs and ignition ting two broken dy cleaning and	n spark flush	555.00 In Parts List Spark Plug Intake Cle Coil	Parts: n Date: aner Kit		Closed:		016 Qty 8.00 1.00 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes olugs in cylinder - Perform induc njectors - Test drive befor - Shop Supplies	: l603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n	Meter: on and it test.code I spark pl for extrac trottle boo	is sputtering P0301 and ugs and ignition ting two broken dy cleaning and	n spark flush	555.00 Parts List Spark Plug Intake Cle Coil Shop Supp 600.00	Parts: n Date: aner Kit	03/31/2016	Closed:	04/13/20	016 Qty 8.00 1.00 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes olugs in cylinder - Perform induc njectors - Test drive befo - Shop Supplies	: 603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n s Hours : 1603784	Meter: on and it test.code I spark pl for extract trottle boo repairs. a 10.00 Meter:	is sputtering P0301 and ugs and ignition cting two broken dy cleaning and	flush Labor:	555.00 In Parts List Spark Plug Intake Cle Coil Shop Supp 600.00	Parts: n Date: aner Kit plies Parts:	03/31/2016 762.01	Closed: Total:	04/13/20	016 Qty 8.00 1.00 8.00 1.00
Problem: e - Check engine P0316.pinpoint to coils.clear codes olugs in cylinder - Perform induc njectors - Test drive befor - Shop Supplies Morkorder: 1 Problem: F - Replace dama	: 1603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n s Hours : 1603784 Replace trailer fem	Meter: on and it test.code Il spark pl for extract trottle boo repairs. s 10.00 Meter: plug con	is sputtering P0301 and ugs and ignition tring two broken dy cleaning and 56427 nector and hitch	flush Labor:	555.00 In Parts List Spark Plug Intake Cle Coil Shop Supp 600.00	Parts: n Date: aner Kit olies Parts: n Date:	03/31/2016 762.01	Closed: Total:	04/13/20	016 Qty 8.00 1.00 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes olugs in cylinder - Perform induc injectors - Test drive befor - Shop Supplies Workorder: 1 Problem: F - Replace dama rewire.replace p	: 1603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n s Hours : 1603784 Replace trailer age trailer fem intle pin.	Meter: on and it test.code Il spark pl for extract trottle boo repairs. s 10.00 Meter: plug con	is sputtering P0301 and ugs and ignition tring two broken dy cleaning and 56427 nector and hitch	flush Labor:	555.00 In Parts List Spark Plug Intake Cle Coil Shop Supp 600.00	Parts: n Date: aner Kit olies Parts: n Date:	03/31/2016 762.01	Closed: Total:	04/13/20	016 Qty 8.00 1.00 8.00 1.00
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder - Perform induc injectors - Test drive befor - Shop Supplies Workorder: 1 Problem: F - Replace dama	: 1603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n s Hours : 1603784 Replace trailer age trailer fem intle pin.	Meter: on and it test.code Il spark pl for extract trottle boo repairs. s 10.00 Meter: plug con	is sputtering P0301 and ugs and ignition tring two broken dy cleaning and 56427 nector and hitch	flush Labor:	555.00 In Parts List Spark Plug Intake Cle Coil Shop Supp 600.00 In pin. Parts List	Parts: n Date: aner Kit olies Parts: n Date:	03/31/2016 762.01	Closed: Total:	04/13/20	016 Qty 8.00 1.00 1.00 016 Qty
Problem: e - Check engine P0316.pinpoint t coils.clear codes plugs in cylinder - Perform induc injectors - Test drive befor - Shop Supplies Workorder: 1 Problem: F - Replace dama rewire.replace p	: 1603381 engine light is light on.scan test.replace al s.extra labour heads. tion cleaning, ore and after n s Hours : 1603784 Replace trailer age trailer fem intle pin.	Meter: on and it test.code Il spark pl for extract trottle boo repairs. s 10.00 Meter: plug con	is sputtering P0301 and ugs and ignition tring two broken dy cleaning and 56427 nector and hitch	flush Labor:	555.00 In Parts List Spark Plug Intake Cle Coil Shop Supp 600.00 In pin. Parts List trailer plug	Parts: n Date: aner Kit olies Parts: n Date:	03/31/2016 762.01	Closed: Total:	04/13/20	016 Qty 8.00 1.00 8.00 1.00

Palm Beach County Fleet Management	
Asset Maintenance History	

Workorder: Problem:	1608552 Right tail lam	Meter: p inop.	57832			In Date:	08/17/2016	Closed:	08/24/2	016
- Replace Def	ective R/tail Li	aht Bulb.			Parts Li	ist				Qty
		0			Bulb					1.00
	Hou :	rs 0.25		Labor:	15.00	Parts:	0.78	Total:	15.78	
Workorder: Problem:	1609662 Leaking trans	Meter:	58225 lid.Right front	t turnsigna	I light inc	In Date:	09/15/2016	Closed:	09/26/2	016
- Clean and re	-		-	•	Parts Li	-				Qty
luid.						or Brake Clr	٦r			1.00
- Replace righ	nt front signal l	amp bulb.			Bulb					1.00
- Shop Suppli	es				Shop Su	upplies				1.00
	Hou	rs 1.25		Labor:		Parts:	5.59	Total:	80.59	
Workorder:	. 1609750	Meter:	58442			In Date:	09/19/2016	Closed:	10/18/2	016
Problem:	PM Service.T	owed in fo	r no crank,nc	o start.						
- Pm service.					Parts Li	ist				Qty
	perform pin po	oint test and	d found bad		Napago	ld Oil Filter				1.00
starter.replace					Napa Q	uart 5w20				8.00
	h and replace	hook.			20" Wip	er Blade				2.00
- Service pow	•				Washer	Fluid Conce	entr			1.00
- Rotate and b						ld Fuel Filte				1.00
- Shop Suppli	es					e Lithium G				1.00
						ld Air Filter				1.00
					Reman					1.00
						lip Hook-bu	lk			1.00
		7.00		1 - 1	Shop Su		040.05	<b>T</b> . ( . )	000.05	1.00
	Hou :	rs 7.00		Labor:	420.00	Parts:	210.35	i otal:	630.35	
Workorder: Problem:	1609943 No start	Meter:	58225			In Date:	09/19/2016	Closed:	09/23/2	016
- Tow From: 1 13026 South J			Boca Raton	To:						
	Hou	rs 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00	
Workorder: Problem:	1612587 Left rear tire f	Meter: lat.Ticking	59186 noise in engi	ine.		In Date:	12/08/2016	Closed:	02/13/2	017
					Parts Li	ist				Qty
	ective hydrauli			arms.	Rocker	Arm Assy				2.00
replace12 defe			nen fill all		Valva C	over Gaske	t			1.00
eplace12 defe - Repair left re		lance.nitro	gorr ini an.				· ·			
replace12 defe - Repair left re		lance.nitro	gori in an.		Lifter		L			
replace12 defe - Repair left re		lance.nitro					L			12.00 12.00
- Diagnose fo replace12 defe - Repair left re - Shop Suppli		lance.nitro	gori ini ani.		Lifter	alve	L.			12.00

Workorder: Problem:	1701268 Dead battery	Meter:	59186			In Date:	02/07/2017	Closed:	02/13/2017
- Test starting and charging system.replace bad battery.						st			Qty
- Shop Supplies					Battery				1.00
					Shop Su	upplies			1.00
	Hou :	rs 0.75		Labor:	45.00	Parts:	126.43	Total:	171.43
Workorder: Problem:	1703432 PM Service	Meter:	60118			In Date:	04/06/2017	Closed:	04/27/2017
- P.m.service					Parts Li	st			Qty
- A/ Blower Resister Module Diagnosed And Replaced					Napagold Oil Filter				1.00
- Mount And Balance 4 Tires					Napa Quart 5w20				8.00
- Front Brake Job And Resurface Rotors.					22" Wiper Blade				2.00
- Service Rear Tail Gate Lift And Repair Latch Release					Washer Fluid Concentr				1.00
Cable. - Service Winch - Shop Supplies					Used Fire X Refurbished				1.00
					Blower Resistor				1.00
					179535492 Lt265-70r17				4.00
					Brake P	ads			1.00
					Shop Su	upplies			1.00
					Tire Dis	oosal Fee			4.00
	Hou :	rs 13.50		Labor:	810.00	Parts:	1,242.87	Total:	2,052.87
Workorder: Problem:	1704324 Brake pedal f	Meter: ade.	60291			In Date:	04/28/2017	Closed:	05/15/2017
<ul> <li>Diagnose and replace brake master cylinder.flush and bleed brake hydraulic system.replace brake pedal pad.test drive before and after repairs.</li> <li>Fabricate and repair wiring for trailer connector harness.</li> <li>Shop Supplies</li> </ul>					Parts Li	st			Qty
					Us 440 Series Lamp				1.00
					Pedal P	ad		1.00	
					Master Cylinder Motorcraft B Fluid Dot 3-32oz				1.00
									1.00
						or Brake Clr	٦r		1.00
						Shop Supplies			1.00
	Hou :	rs 3.50		Labor:	210.00		254.38	Total:	464.38
	1711955	Meter:	63099			In Date:	12/06/2017	Closed:	12/06/2017
	Transition Pre	ep Charge							
Workorder: Problem: - Transition P	Transition Pre	ep Charge							