10179155 2009 FORD F350 Utility Body, 1 Ton, W/ Tow Pkg

| Problem: PRE-DELIVERY INSPECTION  - Pre-delivery Inspection  Hours 4.00 :  Workorder: 937656 Meter: 33 Problem: INSTALL VISE  - Fabricate Aluminum Vise Mount.install And Paint Mount And Vise.  Hours 10.00 Labor: 600.00 Parts: 0.00 Parts: 0.5/12/2009  In Date: 05/12/2009 Country Inspection Parts List 1/4x4x12 Alum Plate 5052 66997 Combo Vise (rigid F-60) Hours 10.00 Labor: 600.00 Parts: 572.58   | closed:         | 05/11/20<br>240.00<br>05/18/20<br>1,172.58 | 009<br><b>Qty</b><br>20.00<br>1.00 |
|---|-----------------|--|------------------------------------|
| Hours 4.00  | Closed:  Total: | 05/18/20                                   | <b>Qty</b><br>20.00<br>1.00        |
| :  Workorder: 937656  | Closed:  Total: | 05/18/20                                   | <b>Qty</b><br>20.00<br>1.00        |
| Problem: INSTALL VISE  - Fabricate Aluminum Vise Mount.install And Paint Mount And Vise.  Hours 10.00 Labor: 600.00 Parts: 572.58  Workorder: 938025 Meter: 33 In Date: 05/20/2009 Combo Make 2 SPARE KEYS  - Out 2 New Spare Keys  Parts List  | Total:          |  | <b>Qty</b><br>20.00<br>1.00        |
| And Vise.    1/4x4x12 Alum Plate 5052   66997 Combo Vise (rigid F-60)     Hours 10.00   Labor: 600.00   Parts: 572.58     Workorder: 938025   Meter: 33   In Date: 05/20/2009   Composite of the problem: MAKE 2 SPARE KEYS     - Out 2 New Spare Keys   Parts List   |                 |  | 20.00                              |
| ## Hours 10.00   Labor: 600.00   Parts: 572.58    ## Workorder: 938025   Meter: 33   In Date: 05/20/2009   Composition of the part of the |                 |  | 1.00                               |
| Hours 10.00 Labor: 600.00 Parts: 572.58  Workorder: 938025 Meter: 33 Problem: MAKE 2 SPARE KEYS  - Out 2 New Spare Keys  Parts List   |                 | 1,172.58                                   |                                    |
| : Workorder: 938025 Meter: 33 In Date: 05/20/2009 Comproblem: MAKE 2 SPARE KEYS  - Out 2 New Spare Keys Parts List  |                 | 1,172.58                                   | 3                                  |
| Problem: MAKE 2 SPARE KEYS  - Out 2 New Spare Keys  Parts List  | losed:          |  |                                    |
|   |                 | 05/26/20                                   | 009                                |
|   |                 |  | Qty                                |
|   |                 |  | 1.00                               |
| Hours 1.00 Labor: 60.00 Parts: 2.00   | Total:          | 62.00                                      |                                    |
| Workorder:         945644         Meter:         2000         In Date:         11/04/2009         C           Problem:         P. M. Service  | losed:          | 11/17/20                                   | 009                                |
| - P.m.service Parts List  |                 |  | Qty                                |
| - Retighten Body Hold Downs Shop Supplies   |                 |  | 1.00                               |
| - Free & Lube Siezed Vise 7312 Oil Filterfrm Ch9549 Wix 5733  | 12              |  | 1.00                               |
| - Repair Ground For Body Light Cs10263 Fuel Filter (use Cs10263a)   | )               |  | 1.00                               |
| - Repair Connection Atcoil Pachfor Strobes 15/40 Oil  |                 |  | 15.00                              |
| - Shop Supplies 31-22 Wiper Blades 22" Wiper Blade  | •               |  | 2.00                               |
| Hours 7.00 Labor: 420.00 Parts: 151.29  | Total:          | 571.29                                     |                                    |
| Workorder: 1001496 Meter: 3982 In Date: 02/10/2010 C  | losed:          | 02/22/20                                   | 010                                |
| - Replace pintal pin. Parts List  |                 |  | Qty                                |
| 18411 Pintal Pin, 2 3/4" New # 6606   | 3               |  | 1.00                               |
| Hours 0.25 Labor: 15.00 Parts: 1.33 :   | Total:          | 16.33                                      |                                    |
|   | losed:          | 03/15/20                                   | 010                                |
| Problem: CANCEIVER PROBLEM  |                 |  | Qty                                |
| Problem: CANCEIVER PROBLEM  - repair and program canceiver  Parts List  |                 |  |                                    |
|   |                 |  | 1.00                               |

| Workorder:<br>Problem:                   | 1005994<br>NEEDS PINT             | Meter:<br>LE PIN | 6313            |           |                    | In Date:       | 06/08/2010     | Closed:   | 06/09/2 | 010          |
|--|-----------------------------------|------------------|-----------------|-----------|--------------------|----------------|----------------|-----------|---------|--------------|
| - R&r pintle pi                          | in.                               |                  |                 |           | Parts Li           | st             |                |           |         | Qty          |
|  |                                   |                  |                 |           | 18410 P            | intle Pin      |                |           |         | 1.00         |
|  | Hour                              | rs 0.25          |                 | Labor:    | 15.00              | Parts:         | 1.98           | Total:    | 16.98   |              |
| Workorder:<br>Problem:                   | 1007031<br>P. M. SERVIC           | Meter:           | 7354            |           |                    | In Date:       | 07/06/2010     | Closed:   | 07/08/2 | 010          |
| - P. M. Servic                           | e.                                |                  |                 |           | Parts Li           | st             |                |           |         | Qty          |
| - Repaired gr                            | ounds to two b                    | ody lights.      |                 |           | Shop Su            | ıpplies        |                |           |         | 1.00         |
| - Checked str                            | obe light op. F                   | R&r bulb.        |                 |           | 7312 O             | il Filterfrm C | Ch9549 Wix 5   | 7312      |         | 1.00         |
| - Retightened                            | body hold dov                     | vns.             |                 |           | Cs1026             | 3 Fuel Filter  | use Cs1026     | 3a )      |         | 1.00         |
| - Unsiezed &                             | lube vise & ho                    | ok.              |                 |           | Ca1027             | 0 Air Filter N | ∕ltc Fa1886 W  | /ix 49886 |         | 1.00         |
| - Shop Suppli                            | es                                |                  |                 |           | 15/40 C            | Dil            |                |           |         | 15.00        |
|  |                                   |                  |                 |           | 1066 W             | hite Lithium   | (crc 05037)    |           |         | 1.00         |
|  |                                   |                  |                 |           | 31-22 W            | iper Blades/   | 22" Wiper Bl   | ade       |         | 2.00         |
|  |                                   |                  |                 |           | Used Fi            | rex Refurbe    | d Fire Extings | hers      |         | 1.00         |
|  |                                   |                  |                 |           | Ha238c             | Strobe Bulk    | Use Whelen     | #s30hac   |         | 1.00         |
|  | Hour                              | rs 8.00          |                 | Labor:    | 480.00             | Parts:         | 279.34         | Total:    | 759.34  |              |
| Workorder:<br>Problem:                   | 1008772<br>Needs a pinta          | Meter:<br>al pin | 8479            |           |                    | In Date:       | 08/16/2010     | Closed:   | 08/17/2 | 010          |
| - Replace pin                            | tal pin.                          |                  |                 |           | Parts Li           | st             |                |           |         | Qty          |
|  |                                   |                  |                 |           | 18411 P            | intal Pin, 2   | 3/4" New # 66  | 6063      |         | 1.00         |
|  | Hour<br>:                         | s 0.25           |                 | Labor:    | 15.00              | Parts:         | 1.32           | Total:    | 16.32   |              |
| Workorder:<br>Problem:                   | 1100695<br>P. M. SERVIC           | Meter:<br>CE     | 14187           |           |                    | In Date:       | 01/19/2011     | Closed:   | 01/31/2 | 011          |
| - P. M. Servic                           | e                                 |                  |                 |           | Parts Li           | st             |                |           |         | Qty          |
| - Repaired op                            | en to body ligh                   | ıt. R&r bul      | b for clip ligh | t.        | Shop Su            | upplies        |                |           |         | 1.00         |
|  | vitch operation.                  |                  | coil pack, rep  | paired    | 7312 O             | il Filterfrm C | Ch9549 Wix 5   | 7312      |         | 1.00         |
| _  | s from drivers                    |                  |                 |           | 3963 Fu            | uel Filter Fr  | m Cs10263a     | Wix 33963 |         | 1.00         |
|  | lubed vise & h                    |                  |                 |           | Ca1027             | 0 Air Filter N | ∕ltc Fa1886 W  | /ix 49886 |         | 1.00         |
| •  | body hold dov                     | vns.             |                 |           | 15/40 C            | Dil            |                |           |         | 16.00        |
| - Shop Suppli                            | es                                |                  |                 |           | 31-22 W            | iper Blades    | 22" Wiper Bl   | ade       |         | 2.00         |
|  | Hour<br>:                         | s 8.50           |                 | Labor:    | 510.00             | Parts:         | 145.26         | Total:    | 655.26  |              |
| Workorder:                               | 1104496                           | Meter:           | 17545           |           |                    | In Date:       | 04/27/2011     | Closed:   | 04/29/2 | 011          |
| Problem:                                 | Install comput                    | ter stand.P      | arts on floor   | in truck. |                    |                |                |           |         |              |
|  | start.recharge<br>ce defective ba |                  |                 |           | Parts Li           |                |                |           |         | Qty          |
| <ul> <li>Fabricate ar wiring.</li> </ul> |                                   |                  |                 |           | Shop Su<br>Group 6 |                | ntc Bxt-65-850 | 0)        |         | 1.00<br>2.00 |
| ···                                      |                                   | Sai compu        |                 | •         | Croup o            | 5 Dattery (II  | = 7.11 00 00.1 | - /       |         |              |
| - Shop Suppli                            |                                   | Sai compu        |                 |           | Croup o            | 5 Dattery (II  | 27.1. 00 00.   | - /       |         |              |

| Workorder: 1106602 Meter: 19161 Problem: P. M. SERVICE  | In Date: 06/22/2011 Closed: 06/29/201       |
|---|---|
| - Performed P.m.  | Parts List                                  |
| - Repaired grounds to two body lights. Repaired connection  |   |
| to one tail light.  | 7312 Oil Filterfrm Ch9549 Wix 57312 1       |
| - Repaired connection to one front strobe light. R&r bulb for   | r 3963 Fuel Filter Frm Cs10263a Wix 33963 1 |
| one rear strobe also.   | Ca10270 Air Filter Mtc Fa1886 Wix 49886     |
| - Unsiezed & lubed vise & hook.   | 15/40 Oil 16                                |
| - Retightened body hold downs.  | 31-22 Wiper Blades 22" Wiper Blade 2        |
| - R&r and balanced two tires.   | Used Firex Refurbed Fire Extingshers 1      |
| - Repaired Lr tire.   | Ha238c Strobe Bulb Use Whelen #s30hac 1     |
| - Shop Supplies   | 179636492 Lt245/75r17 Wrangler Sr-a E 2     |
|   | Tire Disposal Fee 2                         |
| Hours 11.50 Lab   | r: 690.00 Parts: 561.91 Total: 1,251.91     |
| Workorder: 1113093 Meter: 25495 Problem: P. M. Servide, need rear tire, & adj panel loc   | In Date: 12/13/2011 Closed: 12/19/201       |
| - Performed P.m.  |   |
| - R&r and balanced 4 tires.   | Parts List Shop Supplies 1                  |
| - Tire repair right rear.   | 7312 Oil Filterfrm Ch9549 Wix 57312         |
| •   | 3963 Fuel Filter Frm Cs10263a Wix 33963     |
| <ul><li>Checked bulb &amp; pack, repaired connector to rear strobe.</li><li>Repaired ground for running lights. R&amp;r bulb to clip.</li></ul> | Ca10270 Air Filter Mtc Fa1886 Wix 49886     |
| - Batts failed load. Recharged batts & retested, passed.  | 15/40 Oil 16                                |
| - Vise & hook siezed, unsiezed & lubed both.  | 31-22 Wiper Blades 22" Wiper Blade 2        |
| - Retightened hold downs.   | 179636492 Lt245/75r17 Wrangler Sr-a E 4     |
| - Readjusted urility body thru lock & door latches.   | Tire Disposal Fee 4                         |
| - Shop Supplies   | The Disposal Fee                            |
| Hours 13.50 Lab   | r: 810.00 Parts: 937.38 Total: 1,747.38     |
| Workorder: 1201762 Meter: 27318 Problem: CHECK ENGINE LIGHT   | In Date: 02/23/2012 Closed: 03/09/2013      |
| - Transport & pick up vehicle at dealer for warranty repair. (defective #6 injector).   | Parts List                                  |
| - Dealer to replace defective #6 injector.  | Shop Supplies 1                             |
| •   |   |
| - Dealer performed recall # 11b23b, reporgram control modules.  |   |
| - Shop Supplies   |   |
| Hours 1.50 Lab  | r: 90.00 Parts: 2.00 Total: 92.00           |
| Workorder: 1203317 Meter: 28175 Problem: r/rear outer tire flat   | In Date: 04/09/2012 Closed: 04/13/2013      |
| - repair rr outer tire  | Parts List                                  |
| - Shop Supplies   | Shop Supplies 1                             |
| Hours 1.00 Lab  | r: 60.00 Parts: 2.00 Total: 62.00           |
|   |   |

| Workorder:<br>Problem:                                | 1205895<br>pm                     | Meter:             | 31506         |             |           | In Date:       | 06/21/2012     | Closed:   | 06/29/2 | 012   |
|---|-----------------------------------|--------------------|---------------|-------------|-----------|----------------|----------------|-----------|---------|-------|
| - pm  |                                   |                    |               |             | Parts Li  | ist            |                |           |         | Qty   |
| -   | unds for two lig                  | hts repair         | ed tag light  |             | Shop Su   | upplies        |                |           |         | 1.00  |
| - frt strobes iv                                      | vop ck coil pack                  | switch ar          | nd wiring re  | moved       | 7312 O    | il Filterfrm C | Ch9549 Wix 5   | 7312      |         | 1.00  |
|   | t bezel assy rr l                 |                    | ove strobe    | out ck bulb | 3963 F    | uel Filter Fr  | m Cs10263a     | Wix 33963 |         | 1.00  |
|   | ired wiring in fra                |                    | tootod acca   | J           | Ca1027    | 0 Air Filter N | Mtc Fa1886 W   | ix 49886  |         | 1.00  |
|   | ad recharged b<br>bed vis and hoo |                    | iesied good   | 1           | 15/40 C   | Dil            |                |           |         | 16.00 |
|   |                                   | ĸ                  |               |             | 1066 W    | /hite Lithium  | (crc 05037)    |           |         | 1.00  |
| - tighten bady  |                                   |                    |               |             | 31-22 W   | /iper Blades   | 22" Wiper Bl   | ade       |         | 2.00  |
| <ul><li>repaired Ir til</li><li>Shop Suppli</li></ul> |                                   |                    |               |             | Used Fi   | rex Refurbe    | d Fire Extings | hers      |         | 1.00  |
| - Shop Suppli   | <b>C</b> 3                        |                    |               |             | Ha238c    | Strobe Bulk    | Use Whelen     | #s30hac   |         | 2.00  |
|   | Hours<br>:                        | s 11.50            |               | Labor:      | 690.00    | Parts:         | 246.24         | Total:    | 936.24  |       |
| Workorder:<br>Problem:                                | 1207435<br>TOW IN,L/FR0           | Meter:<br>ONT TIRE | 33575<br>FLAT |             |           | In Date:       | 08/08/2012     | Closed:   | 08/09/2 | 012   |
|   | tire remove disr                  | mount pate         | ch mount ba   | alance add  | Parts Li  | ist            |                |           |         | Qty   |
| n2  |                                   |                    |               |             | Shop St   | upplies        |                |           |         | 1.00  |
| - Shop Suppli   |                                   |                    |               |             |           | _              |                |           |         |       |
|   | Hours<br>:                        | s 1.00             |               | Labor:      | 60.00     | Parts:         | 2.00           | Total:    | 62.00   |       |
| Workorder:<br>Problem:                                | 1207541<br>driver front tire      | Meter:             | 33575         |             |           | In Date:       | 08/10/2012     | Closed:   | 08/10/2 | 012   |
| - Tow From: 2   | 201 brittney e ki                 | ngs point          | delray To:    | sr shop     |           |                |                |           |         |       |
|   | Hours<br>:                        | s 0.00             |               | Labor:      | 0.00      | Parts:         | 0.00           | Total:    | 0.00    |       |
| Workorder: Problem:                                   | 1208805<br>need pintle pir        | Meter:             | 35286         |             |           | In Date:       | 09/17/2012     | Closed:   | 09/19/2 | 012   |
| - replace pintl                                       | e pin                             |                    |               |             | Parts Li  | ist            |                |           |         | Qty   |
|   | ·                                 |                    |               |             | 18411 F   | Pintal Pin, 2  | 3/4" New # 66  | 8063      |         | 1.00  |
|   | Hours                             | s 0.25             |               | Labor:      | 15.00     | Parts:         | 1.31           | Total:    | 16.31   |       |
| Workorder:<br>Problem:                                | 1211887<br>P.M.SERVICE            | Meter:             | 38160         |             |           | In Date:       | 12/10/2012     | Closed:   | 12/19/2 | 012   |
| - pm  |                                   |                    |               |             | Parts Li  | ist            |                |           |         | Qty   |
| - repaired gro  | und for rear ligh                 | nts                |               |             | Oil Filte | r              |                |           |         | 1.00  |
| •   | ired connection                   |                    | :             |             | Napago    | ld Air Filter  |                |           |         | 1.00  |
| - unsiezed an   | d lubed vise an                   | d hook             |               |             | Napago    | ld Fuel Filte  | r              |           |         | 1.00  |
| - repaired left                                       | rear tire                         |                    |               |             | 15w40 E   | Bulk South F   | Reg            |           |         | 16.00 |
| - tightened ho  | ld downs                          |                    |               |             | 31-22 W   | /iper Blades   | 22             |           |         | 2.00  |
| - Shop Suppli   | es                                |                    |               |             | Used Fi   | rex Refurbe    | d F            |           |         | 1.00  |
|   |                                   |                    |               |             | Shop Su   | upplies        |                |           |         | 1.00  |
|   | Hours                             | s 8.50             |               | Labor:      | 510.00    | Parts:         | 180.43         | Total:    | 690.43  |       |

| Workorder: 1304084 Me<br>Problem: pm                                     | eter: 43704             |            | I           | n Date:     | 04/24/2013 | Closed: | 04/30/2013 |
|--|-------------------------|------------|-------------|-------------|------------|---------|------------|
| - pm   |                         |            | Parts List  | t           |            |         | Qty        |
| - center stop light out replaced bu                                      | ulb repaired socket     | to clip    | Napagold    | Oil Filter  |            |         | 1.00       |
| light  | •                       | •          | Napagold    |             | er         |         | 1.00       |
| - repaired connection at coil pack                                       | (                       |            | Napagold    |             |            |         | 1.00       |
| - unsiezed and lubed vise and ho   | ook                     |            | 31-22 Wip   |             | s 22       |         | 2.00       |
| - tightened body hold downs  |                         |            | 15w40 Bu    |             |            |         | 16.00      |
| - repaired rr tire   |                         |            | Shop Sup    |             | 3          |         | 1.00       |
| <ul><li>straightened frt bumper and reir</li><li>Shop Supplies</li></ul> | nstalled air dam an     | d cover    |             |             |            |         |            |
| Hours 10   | 0.00                    | Labor:     | 600.00      | Parts:      | 140.87     | Total:  | 740.87     |
| Workorder: 1308372 Me<br>Problem: pm                                     | eter: 48980             |            | I           | n Date:     | 08/20/2013 | Closed: | 08/27/2013 |
| - pm   |                         |            | Parts List  | t           |            |         | Qty        |
| - repaired grounds to running ligh                                       | nts repaired open to    | tail light | Napagold    | Air Filter  |            |         | 1.00       |
| - repaired r rear tire   |                         |            | Napagold    | Oil Filter  |            |         | 1.00       |
| - reanchor stabilazion mounts  |                         |            | Napagold    | Fuel Filte  | er         |         | 1.00       |
| - rr and balanced 4 tires  |                         |            | 15w40 Bu    | lk South I  | Reg        |         | 16.00      |
| - rr frt strobe bulb repaired wire to                                    | o rear strobe socke     | t          | Wiper Bla   | de          |            |         | 2.00       |
| - unseized and lubed vis and hoo   | ok                      |            | 05046 Ba    | ttery Prote | ect        |         | 1.00       |
| - adj rear tail gate striker and hind                                    | dge assy                |            | Mac Wite    | Lithium G   | Gres       |         | 1.00       |
| - Shop Supplies  |                         |            | 17963649    | 2 Lt245-7   | ′5r17      |         | 4.00       |
|  |                         |            | Hide Awa    | y Strob     |            |         | 1.00       |
|  |                         |            | Shop Sup    | plies       |            |         | 1.00       |
|  |                         |            | Tire Dispo  | sal Fee     |            |         | 4.00       |
| Hours 11   | .50                     | Labor:     | 690.00      | Parts:      | 1,186.30   | Total:  | 1,876.30   |
| Workorder: 1401535 Me<br>Problem: pm                                     | eter: 56632             |            | ı           | n Date:     | 02/18/2014 | Closed: | 02/26/2014 |
| - pm   |                         |            | Parts List  | t           |            |         | Qty        |
| - repaired grounds for body lights                                       | rr bulbs for clip lig   | ht         | Napagold    | Air Filter  |            |         | 1.00       |
| - repaired wiring through frame ra                                       | ail for rear strobe lig | ght        | Napagold    | Oil Filter  |            |         | 1.00       |
| - repaired shock mount straighter  | ned and reinstall sh    | nock       | Fuel Filter | Ford Onl    | ly         |         | 1.00       |
| - rr and balanced two tires  |                         |            | 15w40 Bu    | lk South I  | Reg        |         | 16.00      |
| - repaired rr tire   |                         |            | Wiper Bla   | de          |            |         | 2.00       |
| - removed door panel and adjuste   | ed track assy           |            | Used Fire   | X Refurb    | ished      |         | 1.00       |
| - Shop Supplies  |                         |            | Washer F    | I           |            |         | 1.00       |
|  |                         |            | 17963649    | 2 Lt245-7   | '5r17      |         | 2.00       |
|  |                         |            | Shop Sup    | plies       |            |         | 1.00       |
|  |                         |            | Tire Dispo  | sal Fee     |            |         | 2.00       |
|  |                         |            |             |             |            |         |            |

| Workorder:                    | 1405258                                    | Meter:         | 60334                |             |           | In Date:      | 05/29/2014 | Closed: | 06/04/20 | )14   |
|-------------------------------|--|----------------|----------------------|-------------|-----------|---------------|------------|---------|----------|-------|
| Problem:                      | had to jump                                | start          |                      |             |           |               |            |         |          |       |
| - batt failed lo              | ad recharged                               | batt and re    | tested fail ag       | ain rr batt | Parts Li  | ist           |            |         |          | Qty   |
| and checked of                | charge rate of                             | c ps11.8 269   | oca reaplac          | e batt      | Battery   |               |            |         |          | 2.00  |
| aces hg50p d<br>hg20p dtc ake |  | 10.62 bad o    | cell replace b       | att aces    | Shop Su   | upplies       |            |         |          | 1.00  |
| - Shop Suppli                 | •  |                |                      |             |           |               |            |         |          |       |
| - опор оцррп                  |  | urs 2.00       |                      | I ahor      | 120.00    | Parts:        | 241.22     | Total:  | 361.22   |       |
|                               | :  | ui3 2.00       |                      | Labor.      | 120.00    | i aits.       | 271.22     | rotai.  | 301.22   |       |
| Workorder:                    | 1405754                                    | Meter:         | 60667                |             |           | In Date:      | 06/11/2014 | Closed: | 06/18/20 | )14   |
| Problem:                      | broke down                                 | no brakes n    | o ac                 |             |           |               |            |         |          |       |
| - rr engine idle              |  |                |                      | remove      | Parts Li  | ist           |            |         |          | Qty   |
| pieces of brok                | en belt repair                             | wiring for so  | ensor                |             | Belt Ter  | sioner        |            |         |          | 1.00  |
| - rr all belts                |  | _              |                      |             | Idler Pu  | lley          |            |         |          | 1.00  |
| - removed wir                 | _  | ess for ac     |                      |             | Idler Pu  | lley Smooth   |            |         |          | 1.00  |
| - Shop Suppli                 | es   |                |                      |             | A/c Belt  |               |            |         |          | 1.00  |
|                               |  |                |                      |             | Drive Be  | elt           |            |         |          | 1.00  |
|                               |  |                |                      |             | Belt Ter  | sioner        |            |         |          | 1.00  |
|                               |  |                |                      |             | Shop St   | upplies       |            |         |          | 1.00  |
|                               | Hou  | urs 13.00      |                      | Labor:      | 780.00    | Parts:        | 389.48     | Total:  | 1,169.48 | 3     |
| - Tow From: b                 | 1405805<br>no start no b<br>pitterbush and |                | 60638<br>ynton beach | To: sr      |           | In Date:      | 06/11/2014 | Closed: | 06/12/20 | )14   |
| shop                          | Hou<br>:                                   | urs 0.00       |                      | Labor:      | 0.00      | Parts:        | 0.00       | Total:  | 0.00     |       |
| Workorder:                    | 1406226                                    | Meter:         | 60947                |             |           | In Date:      | 06/25/2014 | Closed: | 06/26/20 | )14   |
| Problem:                      | wont fuel                                  |                |                      |             |           |               |            |         |          |       |
| - Test and rer                | nove canceiv                               | er issue fue   | l card               |             | Parts Li  | ist           |            |         |          | Qty   |
| - Shop Suppli                 | es   |                |                      |             | Shop St   | upplies       |            |         |          | 1.00  |
|                               | Hou  | urs 1.00       |                      | Labor:      | 60.00     | Parts:        | 2.00       | Total:  | 62.00    |       |
| Workorder:<br>Problem:        | 1407415<br>pm                              | Meter:         | 63238                |             |           | In Date:      | 07/29/2014 | Closed: | 08/07/20 | )14   |
| - pm                          |  |                |                      |             | Parts Li  | ist           |            |         |          | Qty   |
| - repaired wir                | ing in bacinet                             | for lights     |                      |             | Napago    | ld Oil Filter |            |         |          | 1.00  |
| - repaired wir                | ing to control                             | for strobe lig | ght                  |             | Fuel Filt | er Ford Onl   | y          |         |          | 1.00  |
| - repaired lr ti              | _  | ·              |                      |             | Napago    | ld Air Filter |            |         |          | 1.00  |
| - adj striker la              | tches for tail                             | gate           |                      |             |           | Bulk South F  | Reg        |         | •        | 16.00 |
| - Shop Suppli                 |  | =              |                      |             | Wiper B   |               | -          |         |          | 2.00  |
|                               |  |                |                      |             | Shop Su   |               |            |         |          | 1.00  |
|                               | Hou<br>:                                   | urs 8.00       |                      | Labor:      | 480.00    |               | 185.54     | Total:  | 665.54   |       |

| Workorder:<br>Problem:       | 1412746<br>p.m.service                               | Meter:                       | 68800            |                |              | In Date:     | 12/22/2014 | Closed: | 12/31/2014 |
|------------------------------|--|------------------------------|------------------|----------------|--------------|--------------|------------|---------|------------|
| - pm                         |  |                              |                  |                | Parts Lis    | st           |            |         | Qty        |
| - repaired op                | en in cabinet f                                      | or tunning li                | ghts             |                | Napagolo     | d Air Filter |            |         | 1.00       |
| - rr strobe bu               | lb and repaire                                       | d connectio                  | n                |                | Napagolo     | d Oil Filter |            |         | 1.00       |
| - unsiezed ar                | nd lubed hook  | and vise                     |                  |                | Fuel Filte   | er Ford Onl  | у          |         | 1.00       |
| - rr tire                    |  |                              |                  |                | Wiper Bla    | ade          |            |         | 2.00       |
| - tire repair l              | rear   |                              |                  |                | Used Fire    | e X Refurbi  | ished      |         | 1.00       |
| - frt brakes co              | omplete  |                              |                  |                | Hide Awa     | ay Strob     |            |         | 1.00       |
|                              | att and tray ren                                     |                              |                  | ipe and        | 1796364      | 92 Lt245-7   | 5r17       |         | 1.00       |
| •                            | voir to access                                       | nose and r                   | r hoses          |                | Brake Pa     | ads          |            |         | 1.00       |
| - coolant serv               |  |                              |                  |                | B Fluid D    | ot 3-32oz    |            |         | 1.00       |
| - Shop Suppl                 | lies   |                              |                  |                | Brake Cl     | eaner        |            |         | 1.00       |
|                              |  |                              |                  |                | Curved F     | Radiator Ho  | se         |         | 1.00       |
|                              |  |                              |                  |                | Curved F     | Radiator Ho  | ose        |         | 1.00       |
|                              |  |                              |                  |                | Coolant I    | Ford Gold    |            |         | 4.00       |
|                              |  |                              |                  |                | Napakoo      | l            |            |         | 2.00       |
|                              |  |                              |                  |                | 15w40 B      | ulk South F  | Reg        |         | 16.00      |
|                              |  |                              |                  |                | Shop Su      | pplies       |            |         | 1.00       |
|                              |  |                              |                  |                | Tire Disp    | osal Fee     |            |         | 1.00       |
|                              | Ηοι<br>:   | urs 21.50                    |                  | Labor:         | 1,290.0<br>0 | Parts:       | 802.74     | Total:  | 2,092.74   |
| Workorder:<br>Problem:       | 1500403<br>CK ENGINE                                 | <b>Meter:</b><br>LIGHT ON    | 70243<br>I       |                |              | In Date:     | 01/12/2015 | Closed: | 01/22/2015 |
| - installed lap              | top checked  | for codes p2                 | 2610 u2023 p     | 0605           | Parts Lis    | st           |            |         | Qty        |
| po488 follow open and icp of | chart procedur<br>ck pin chart for<br>connections ar | res corrupte<br>pin point te | d soft ware rest | eprogram<br>ed | Shop Su      |              |            |         | 1.00       |
| - Shop Suppl                 |  |                              |                  |                |              |              |            |         |            |
|                              | Hou<br>:   | ırs 6.50                     |                  | Labor:         | 390.00       | Parts:       | 2.00       | Total:  | 392.00     |
| Workorder:<br>Problem:       | 1501635<br>ck engine lig                             | <b>Meter:</b><br>ht on       | 71346            |                |              | In Date:     | 02/13/2015 | Closed: | 02/24/2015 |
| - ck engine li               | ght is on scan                                       | found code                   | po488 poe2       | perform        | Parts Lis    | st           |            |         | Qty        |
| pinpoint test a              | and found bad  |                              |                  |                | Housing      |              |            |         | 1.00       |
| plate and clea               |  |                              |                  |                | exhaust      | sensor       |            |         | 3.00       |
|                              | point test for c<br>erature senso<br>ear code        |                              |                  |                | Shop Su      |              |            |         | 1.00       |
| - clean regior               | n system and   | reset sys                    |                  |                |              |              |            |         |            |
| - test drive af              | -  | •                            |                  |                |              |              |            |         |            |
| - Shop Suppl                 | •  |                              |                  |                |              |              |            |         |            |
|                              |  | ırs 12.50                    |                  | Labor:         | 750.00       | Parts:       | 582.17     | Total:  | 1,332.17   |
|                              | :  |                              |                  |                |              |              |            |         |            |

| Problem: PM  | 74881               | Ir                     | Date:      | 04/24/2015 | Closed:  | 04/30/2015   |
|--|---------------------|------------------------|------------|------------|----------|--------------|
| - pm   |                     | Parts List             |            |            |          | Qty          |
| - repaired grounds for two lights  |                     | Napagold A             | Air Filter |            |          | 1.00         |
| - repaired and replaced socket for bulb in                                 | nstalled new strobe | Napagold (             | Oil Filter |            |          | 1.00         |
| bulb   |                     | Fuel Filter            | Ford On    | ly         |          | 1.00         |
| - unsiezed lubed vise  |                     | 15w40 Bull             | k South    | Reg        |          | 16.00        |
| <ul> <li>rr rear brakes cleaned off shell rock from parts</li> </ul>       | m compartment       | Wiper Blad             | le         |            |          | 2.00         |
| - rr and balanced four tires   |                     | Hide Away              | Strob      |            |          | 1.00         |
| - repaired If tire   |                     | Brake Pad              |            |            |          | 1.00         |
| - repaired and adj latch on utility door                                   |                     | B Fluid Do             |            |            |          | 1.00         |
| - dropped skid plate and tank to repair he                                 | ose leak            | Brake Clea             |            |            |          | 1.00         |
| - Shop Supplies  |                     | 179636492              |            | 75r17      |          | 4.00         |
|  |                     | Shop Supp              |            |            |          | 1.00         |
| H 00 50  | 1 -1 -              | Tire Dispos            |            | 4 070 50   | <b>T</b> | 4.00         |
| Hours 20.50<br>:   | Labo                | r: 1,230.0<br>0        | Parts:     | 1,372.50   | i otai:  | 2,602.50     |
| Workorder: 1504699 Meter: 7  | 75146               | Ir                     | Date:      | 05/08/2015 | Closed:  | 05/26/2015   |
| - rr rad retrofitted napa rad  |                     | Parts List             |            |            |          | Qty          |
| - coolant svc  |                     | Complete F             | Radiator   |            |          | 1.00         |
| - Shop Supplies  |                     | Coolant Fo             | rd Gold    |            |          | 4.00         |
|  |                     | Napakool               |            |            |          | 2.00         |
|  |                     | Shop Supp              | olies      |            |          | 1.00         |
| Hours 11.00  | Labo                | r: 660.00              | Parts:     | 795.19     | Total:   | 1,455.19     |
| Workorder: 1510749 Meter: 8 Problem: pm, steerihg wheel                    | 31110               | lr                     | Date:      | 10/23/2015 | Closed:  | 10/29/2015   |
| - pm   |                     | Parts List             |            |            |          | Qty          |
| - repaired ground for running lights                                       |                     | Fuel Filter            | Ford On    | ly         |          | 1.00         |
| - rr strobe bulb and repaired connections                                  | i                   | Napagold A             | Air Filter |            |          | 1.00         |
| - repaired rr tire   |                     | Napagold (             | Oil Filter |            |          | 1.00         |
| - unsiezed and lubed vise and hook   |                     | 15w40 Bull             | k South    | Reg        |          | 16.00        |
| - removed door panel and adj and lubed assy installed steering wheel cover | regulator and track | Wiper Blad Used Fire 2 |            | oished     |          | 2.00<br>1.00 |
| - Shop Supplies  |                     | Stg Wheel              | Cov - Fo   | ord        |          | 1.00         |
|  |                     | Hide Away              |            |            |          | 1.00         |
|  |                     | •                      |            |            |          |              |
|  |                     | Shop Supp              | olies      |            |          | 1.00         |

| Workorder: 1604366 Meter: 88297 Problem: Pm service.   | In Date: 04/26/2016 Closed: 04/29/2016     |
|--|--|
| - Pm service.  | Parts List Qty                             |
| - Repaired grounds to light.   | Napagold Oil Filter 1.00                   |
| - Repaired connections to strobe lights.   | Napagold Air Filter 1.00                   |
| - R&r and balance two tires.   | Fuel Filter Ford Only 1.00                 |
| - Repaired right rear tire.  | 15w40 Bulk South Reg 16.00                 |
| - Unsiezed and lube hitch.   | 22" Wiper Blade 2.00                       |
| - Shop Supplies  | 179636492 Lt245-75r17 4.00                 |
|  | Shop Supplies 1.00                         |
|  | Tire Disposal Fee 2.00                     |
| Hours 9.00 Labo  | r: 540.00 Parts: 1,191.69 Total: 1,731.69  |
| Workorder: 1607002 Meter: 90478  Problem: Coolant leak and check Ac.   | In Date: 07/12/2016 Closed: 07/28/2016     |
| - C/c coolant leak.pressure test cooling system and found  | Parts List Qty                             |
| leaking radiator.replace defective radiator.   | Body Mount Kit 2.00                        |
| - C/c check ac.perform system pressure test and found low  | Body Mount Kit 4.00                        |
| freon.check and found leaking schrader valves.evacuate an replace both schrader valves.recharge system and recheck | Complete Radiator 1.00                     |
| for leaks.   | Coolant Ford Gold 4.00                     |
| - Replace body mounts.   | Valve Core 1.00                            |
| - Shop Supplies  | Ac Valve Core High 1.00                    |
|  | South Region R134a 3.00                    |
|  | E8 A/c Oil Univ W Dye 1.00                 |
|  | Shop Supplies 1.00                         |
| Hours 19.75 Labo   | r: 1,185.0 Parts: 1,351.87 Total: 2,536.87 |

| Workorder:<br>Problem:   | 1610430<br>: PM Service.   | Meter: 93 Wont start inte  | 3894<br>rmittently.       |        |   | In Date:  | 10/05/2016                               | Closed: | 10/28/2016  |
|--|--|--|---------------------------|--------|---|---|--|---------|---|
| - P.m.service  | е  |  |                           |        | Parts Lis   | st  |  |         | Qty   |
|  |  | itch,ignition Sw   | itch And Code             | е То   | Napagolo  | d Oil Filter  |  |         | 1.00  |
| Vin. R/r Start   |  |  |                           |        | . •   | r Ford Onl  | ly                                       |         | 1.00  |
| - Repair Tag   | Light And L/fr   | ont Signal Ligh  | ıt.                       |        | 15w40 B   | ulk South I   | Reg                                      |         | 16.00   |
| - Repair Both  | h Head Lights  |  |                           |        | Wd40 16   | oz Aero C   | an                                       |         | 1.00  |
| - Clean Batte  | ery Terminals <i>i</i>   | And R/r Both B   | atteries.                 |        | Washer F  | Fluid Conc  | entr                                     |         | 1.00  |
| - R/r Both W   | /washer Nozzl  | es.  |                           |        | 22" Wipe  | r Blade   |  |         | 2.00  |
| - Shop Supp  | lies   |  |                           |        | Ignition S  | Switch  |  |         | 1.00  |
|  |  |  |                           |        | Bulb  |   |  |         | 1.00  |
|  |  |  |                           |        | Starter M   | lotor Crf   |  |         | 1.00  |
|  |  |  |                           |        | Ingition L  | .ock  |  |         | 1.00  |
|  |  |  |                           |        | Halogen   | Lamp  |  |         | 2.00  |
|  |  |  |                           |        | Battery   |   |  |         | 2.00  |
|  |  |  |                           |        | Battery C   | Cleaner   |  |         | 1.00  |
|  |  |  |                           |        | Bat Term  | Protector   |  |         | 1.00  |
|  |  |  |                           |        | Washer N  | Nozzle  |  |         | 2.00  |
|  |  |  |                           |        | Used Fire   | e X Refurb  | ished                                    |         | 1.00  |
|  |  |  |                           |        | Shop Sup  | pplies  |  |         | 1.00  |
|  | Ho   | urs 14.75  | L                         | _abor: | 885.00  | Parts:  | 935.38                                   | Total:  | 1,820.38  |
| Workorder:   | 1700697  | Meter: 9   | 7963                      |        |   | In Date:  | 01/24/2017                               | Closed: | 01/31/2017  |
| Problem:   | : Ckeck for oi   | l leak.  |                           |        |   | in Date.  | 01/24/2017                               | Cioseu. | 01/31/2017  |
| - Repair leak  | king transmissi  | l leak.<br>on cooler line.c  | clean oil spill a         | and    | Parts Lis   |   | 01/24/2017                               | Ciosea. | Qty   |
| - Repair leak<br>refill transmis   | king transmissi<br>ssion oil level.  |  | clean oil spill a         | and    | Parts Lis   |   | 01/24/2017                               | Ciosea. | <b>Qty</b><br>4.00  |
| - Repair leak  | king transmissi<br>ssion oil level.  |  | clean oil spill a         | and    | Parts Lis   | st  | 01/24/2011                               | Closeu. | <b>Qty</b><br>4.00<br>2.00  |
| - Repair leak<br>refill transmis   | king transmissi<br>ssion oil level.<br>Ilies   | on cooler line.c   | clean oil spill a         | and    | Parts Lis   | st<br>Bulk South  | 01/24/2011                               |         | <b>Qty</b><br>4.00<br>2.00<br>1.00  |
| - Repair leak<br>refill transmis   | king transmissi<br>ssion oil level.<br>Ilies   |  |                           |        | Parts Lis<br>Syn Atf B<br>Coupler   | st<br>Bulk South  | 50.87                                    |         | <b>Qty</b><br>4.00<br>2.00  |
| - Repair leak<br>refill transmis   | king transmissi<br>ssion oil level.<br>Ilies   | on cooler line.c   |                           |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00  | st<br>Bulk South  |  |         | <b>Qty</b><br>4.00<br>2.00<br>1.00  |
| - Repair leak<br>refill transmis<br>- Shop Supp<br>Workorder:  | king transmissi<br>ssion oil level.<br>slies<br>Ho<br>:  | on cooler line.durs 1.50  Meter: 10                                    | L                         |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00  | st<br>Bulk South<br>pplies<br>Parts:  | 50.87                                    | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87   |
| - Repair leak<br>refill transmis<br>- Shop Supp<br>Workorder:  | king transmissi<br>ssion oil level.<br>olies  Hotel 1703824  P.M.SERVIO                                    | on cooler line.durs 1.50  Meter: 10                                    | L                         |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00  | st<br>Bulk South<br>pplies<br>Parts:  | 50.87                                    | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87   |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service  | king transmissi<br>ssion oil level.<br>blies  Hotel 1703824  P.M.SERVIO                                    | on cooler line.durs 1.50  Meter: 10                                    | L<br>00822                |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00  | st<br>Bulk South<br>pplies<br>Parts:  | 50.87                                    | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87   |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n                            | king transmissi<br>ssion oil level.<br>blies Hotel: 1703824 : P.M.SERVIC                                   | on cooler line.durs 1.50  Meter: 10                                    | 00822<br>Dos              |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00  | st Bulk South pplies Parts: In Date: st   | 50.87                                    | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87   |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/i - Mount 4 Tir              | king transmissi<br>ssion oil level.<br>blies  Hotel 1703824  P.M.SERVICE rear And R/fromose, Rotated A     | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp               | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe   | st Bulk South pplies Parts: In Date: st   | 50.87                                    | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017   |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/i - Mount 4 Tir              | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F  | st Bulk South pplies Parts: In Date: st d Oil Filter or Blade   | 50.87<br>04/14/2017<br>entr              | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00  |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F Fuel Filte   | st Bulk South pplies Parts: In Date: d Oil Filter or Blade Fluid Conc   | 50.87<br>04/14/2017<br>entr              | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00                                  |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F Fuel Filte Napagolo  | st Bulk South pplies Parts: In Date: d Oil Filter or Blade Fluid Concer Ford Onle   | 50.87<br>04/14/2017<br>entr              | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00                                  |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F Fuel Filte Napagolo  | st Bulk South pplies Parts: In Date: If Blade Fluid Concer Ford Onled Air Filter ulk South I                                      | 50.87<br>04/14/2017<br>entr              | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00<br>1.00                          |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F Fuel Filte Napagolo 15w40 Bi Hide Awa  | st Bulk South pplies Parts: In Date: If Blade Fluid Concer Ford Onled Air Filter ulk South I                                      | 50.87<br>04/14/2017<br>entr<br>ly<br>Reg | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00<br>1.00<br>16.00                 |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis Syn Atf B Coupler Shop Sup 90.00  Parts Lis Napagolo 22" Wipe Washer F Fuel Filte Napagolo 15w40 Bi Hide Awa  | st Bulk South pplies Parts: In Date: In Date: In Blade Fluid Concer Ford Onled Air Filter ulk South I                             | 50.87<br>04/14/2017<br>entr<br>ly<br>Reg | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00<br>1.00<br>1.00<br>2.00          |
| - Repair leak refill transmis - Shop Supp  Workorder:  Problem: - P.m.service - Replace L/n - Mount 4 Tir - Clean Dies | king transmissission oil level. blies Horis 1703824 : P.M.SERVIC e rear And R/fromose, Rotated August 1988 | on cooler line.cours 1.50  Meter: 10  CE  nt Strobe Lamp nd Balanced 6 | L<br>00822<br>os<br>Tires |        | Parts Lis<br>Syn Atf B<br>Coupler<br>Shop Sup<br>90.00<br>Parts Lis<br>Napagolo<br>22" Wipe<br>Washer F<br>Fuel Filte<br>Napagolo<br>15w40 Bu<br>Hide Awa<br>17963649 | st Bulk South pplies Parts: In Date: In Date: In Blade Fluid Concer Ford Onled Air Filter ulk South Italy Strob 92 Lt245-7 pplies | 50.87<br>04/14/2017<br>entr<br>ly<br>Reg | Total:  | Qty<br>4.00<br>2.00<br>1.00<br>140.87<br>04/27/2017<br>Qty<br>1.00<br>2.00<br>1.00<br>1.00<br>16.00<br>2.00<br>4.00 |

Workorder: 1707282 104142 In Date: 07/25/2017 **Closed:** 07/27/2017 Meter: Problem: BOLT IN R/REAR TIRE - Repair and balance right rear outer tire. **Parts List** Qty 1.00 - Shop Supplies **Shop Supplies** Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00 Workorder: 1709954 Meter: 107528 In Date: 10/12/2017 Closed: 10/24/2017 Problem: PM Service - Pm Service **Parts List** Qty - Rotate and balance all six tires. Napagold Oil Filter 1.00 - Shop Supplies 15w40 Bulk South Reg 16.00 22" Wiper Blade 2.00 Amber Marker Lamp 2.00 Def Fluid 2.5 1.00 **Shop Supplies** 1.00

Hours 5.00 Labor: 300.00 Parts: 125.41 Total: 425.41

**Workorder:** 1800079 **Meter:** 109298 **In Date:** 01/03/2018 **Closed:** 01/03/2018

Problem: Transition Prep Charge

- Transition Prep Charge

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00

٠