

**Palm Beach County Fleet Management
Asset Maintenance History**

10189879 2013 FORD ESCAPE Suv, Mid Size

Workorder: 1305437 **Meter:** 6 **In Date:** 06/03/2013 **Closed:** 06/03/2013
Problem: 1061 - Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 1305636 **Meter:** 6 **In Date:** 06/06/2013 **Closed:** 06/24/2013
Problem: Install lightbar

- Fabricate and install new light bar with wiring and control switch.

Parts List
Ltbar 48 14led Qty 1.00

- Install new fire extinguisher with bracket.

Switch Box Qty 1.00

- Shop Supplies

Silicone Clear Permatex Qty 1.00

Used Fire X Refurbished Qty 1.00

Custom Bracket Fire Ex Qty 1.00

Shop Supplies Qty 1.00

Hours 8.50 Labor: 510.00 Parts: 2,333.44 Total: 2,843.44
:

Workorder: 1311772 **Meter:** 9395 **In Date:** 11/21/2013 **Closed:** 11/27/2013
Problem: Pm service and flat tire.Riding on spare tire.

- P.m. Service.

Parts List

- Repair right front tire,rotate and balance all four.

5w20 Engine Oil Qty 6.00

- Shop Supplies

Napagold Oil Filter Qty 1.00

Shop Supplies Qty 1.00

Hours 4.00 Labor: 240.00 Parts: 20.96 Total: 260.96
:

Workorder: 1311828 **Meter:** 9043 **In Date:** 11/21/2013 **Closed:** 11/22/2013
Problem: flat tire, put spare on or tow to vista

- Tow From: Us1 & Indiantown Rd Mobil gas station

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1401302 **Meter:** 16786 **In Date:** 02/07/2014 **Closed:** 02/19/2014
Problem: Pm service.

- P.m. Service.

Parts List

- Rotate and balance all tires.

5w20 Engine Oil Qty 6.00

- Shop Supplies

Napagold Oil Filter Qty 1.00

Shop Supplies Qty 1.00

Hours 3.00 Labor: 180.00 Parts: 20.96 Total: 200.96
:

Workorder: 1403345 **Meter:** 20322 **In Date:** 04/04/2014 **Closed:** 04/15/2014
Problem: Hard starting vehicle after running for while. Seat adjusting lever inop

- Transport vehicle to and from dealer for replacing failed fuel pump assembly with new under factor warranty.

Parts List
Shop Supplies Qty 1.00

- Shop Supplies

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1405524	Meter: 23969	In Date: 06/05/2014	Closed: 06/10/2014
Problem: P.M. service.			
- P.m. Service.	Parts List		Qty
- Replace and balance four new tires.	5w20 Engine Oil		6.00
- Complete wheel alignment.test drive.	Napagold Oil Filter		1.00
- Shop Supplies	Washer Fl		1.00
	Accufit Beam		2.00
	Used Fire X Refurbished		1.00
	Blade		1.00
	P235 55r17 Assur Tour		4.00
	Shop Supplies		1.00
	Tire Disposal Fee		4.00
Hours 6.50	Labor: 390.00	Parts: 1,001.59	Total: 1,391.59
:			

Workorder: 1407659	Meter: 32297	In Date: 08/04/2014	Closed: 09/15/2014
Problem: Right rear tire flat.Pm service and safety recalls 14S03 and 14S04			
- Pm service.	Parts List		Qty
- Repair one flat tire.rotate and balance all four.	5w20 Engine Oil		6.00
- Transport vehicle to and from dealer for safety recalls 14s03 and 14s04 Inspecting all four door handles and reprogram restraints control module.	Napagold Oil Filter		1.00
	Accufit Beam		2.00
	Blade		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 6.00	Labor: 360.00	Parts: 70.97	Total: 430.97
:			

Workorder: 1411662	Meter: 39135	In Date: 11/18/2014	Closed: 11/25/2014
Problem: Left rear tire flat.			
- Repair left rear tire flat and balance .	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

Workorder: 1411982	Meter: 39716	In Date: 12/01/2014	Closed: 12/12/2014
Problem: P.M. service and right front marker light inop .			
- Pm service.	Parts List		Qty
- Check and diagnose electrical circuit for right front parking lamp inop.replace defective bulb.	5w20 Engine Oil		6.00
	Napagold Oil Filter		1.00
- Inspect and roadtest vehicle for growling noise in front end while driving when turning left or right.disassemble and replace both left and right defective front wheel bearings.	Accufit Beam		2.00
	Blade		1.00
- Rotate and balance all four tires.	Washer Fluid Concentr		1.00
- Shop Supplies	Bulb		1.00
	Bering		2.00
	Shop Supplies		1.00
Hours 7.10	Labor: 426.00	Parts: 233.78	Total: 659.78
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1501377	Meter: 45938	In Date: 02/05/2015	Closed: 02/19/2015
Problem: Pm service.			
- Pm service.		Parts List	Qty
- Rotate and balance all four tires.		5w20 Engine Oil	6.00
- Shop Supplies		Napagold Oil Filter	1.00
		Stg Wheel Cov - Ford	1.00
		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 39.62	Total: 219.62
:			
Workorder: 1501875	Meter: 46232	In Date: 02/23/2015	Closed: 02/26/2015
Problem: Towed in for no start.			
- Test starting and charging system.battery failed loadtest after recharge.replace defective battery.		Parts List	Qty
- Shop Supplies		Bxt96r 59	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 145.27	Total: 205.27
:			
Workorder: 1502091	Meter: 46232	In Date: 02/21/2015	Closed: 02/26/2015
Problem: TOW IN FOR REPAIR			
- Tow From: 12800 Hagen Ranch Rd To: Fleet N0rth			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1502291	Meter: 47454	In Date: 03/04/2015	Closed: 03/09/2015
Problem: Towed in for left rear tire flat.			
- Replace and balance one damage tire.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		P235/55r17 Tire	1.00
Hours 0.50	Labor: 30.00	Parts: 151.99	Total: 181.99
:			
Workorder: 1502381	Meter: 46940	In Date: 03/03/2015	Closed: 03/05/2015
Problem: Flat tire			
- Tow From: Haverhill Park 5470 Belvdere To: Fleet North			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1502698	Meter: 49090	In Date: 03/16/2015	Closed: 03/26/2015
Problem: Driver window inop.Set up light bar to operate emergency lights with no alley lights on.			
- Diagnose for driver window inop,falls into door.inspect and replace defective driver door window regulator assembly.		Parts List	Qty
- Rewire light bar controller so alley lights are not on with flashing lights.		5w20 Engine Oil	6.00
- Shop Supplies		Napagold Oil Filter	1.00
		Bering	1.00
		Accufit Beam	2.00
		Regulator	1.00
		Silicone Spray 10oz	1.00
		Vinyl Electrical Tape	1.00
		Shop Supplies	1.00
Hours 2.25	Labor: 135.00	Parts: 202.69	Total: 337.69
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1505770 **Meter:** 56509 **In Date:** 06/09/2015 **Closed:** 06/22/2015
Problem: Pm service.Light bar inop.Driver door handle and wiper blades.Safety recall #14S21

- Pm service.	Parts List	Qty
- Inspect -check and diagnose emergency lighting box intermittent operation.replace defective control box.install drivers door pull handle trim-missing.	P235 55r17 Assur Tour	2.00
- Replace two tires.rotate and balance all four.	Interior Door Handle	1.00
- Perform complete front end alignment.	Tire Pressure Monitoring System Sensor (1.00
- Shop Supplies	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
	Accufit Beam	2.00
	Blade	1.00
	Washer Fluid Concentr	1.00
	Bulb	4.00
	Siren Amplifier	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
	Freight Charge	1.00
Hours 8.50	Labor: 510.00	Parts: 1,106.48
:		Total: 1,616.48

Workorder: 1506327 **Meter:** 57188 **In Date:** 06/24/2015 **Closed:** 06/30/2015
Problem: Light bar and PA system inop

- Inspect and diagnose light bar and Pa system inop.trace power and ground wiring under driver seat.connect and solder ground and power circuits and verify operation.retape wiring.	Parts List	Qty
- Shop Supplies	Vinyl Electrical Tape	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 3.52
:		Total: 123.52

Workorder: 1506842 **Meter:** 58009 **In Date:** 07/06/2015 **Closed:** 07/09/2015
Problem: service

- Tire Service 11260 park access rd, Boca - service			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1506843 **Meter:** 58009 **In Date:** 07/06/2015 **Closed:** 07/09/2015
Problem: Flat tire

- Tire Service 11260 Park Access Rd Boca - Flat tire			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508559 **Meter:** 63863 **In Date:** 08/26/2015 **Closed:** 09/16/2015
Problem: P.M. Service.Recall.

- Pm service.	Parts List	Qty
- Remove and install damage driver seat for repair.fabric torn.	5w20 Engine Oil	6.00
- Perform transmission flush.	Napagold Oil Filter	1.00
- Replace two tires.rotate and balance all four.	Used Fire X Refurbished	1.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Bulb	1.00
	Syn-atf Trans Fluid S	12.00
	P235 55r17 Fuel Max	2.00
	Seat R And R	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.50	Labor: 390.00	Parts: 797.34
:		Total: 1,187.34

Workorder: 1510314 **Meter:** 66376 **In Date:** 10/13/2015 **Closed:** 10/20/2015
Problem: Right headlight inop.

- Test and replace defective right headlamp bulb.	Parts List	Qty
	Halogen Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 11.85
:		Total: 41.85

Workorder: 1512620 **Meter:** 70795 **In Date:** 12/14/2015 **Closed:** 12/31/2015
Problem: Pm service.left headlamp inop.Check turnsignals.

- Pm service.	Parts List	Qty
- Replace failed left headlamp low beam bulb,left front park lamp bulb and tag lamp bulbs.	5w20 Engine Oil	6.00
- Diagnose clicking noise on turns.inspect and replace defective left front axle assembly.	Napagold Oil Filter	1.00
- Replace front brake pads and resurface front brake rotors.service calipers.flush and bleed brake system.test drive.	Accufit Beam	2.00
- Replace one tire.rotate and balance all four.	Blade	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Halogen Bulb	1.00
	Bulb	3.00
	Left Front Axle	1.00
	Fron Brake Pad	1.00
	Brk Fluid Dot 4-12oz	1.00
	Brake Cleaner	1.00
	P235 55r17 Fuel Max	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 9.50	Labor: 570.00	Parts: 502.96
:		Total: 1,072.96

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1602990 **Meter:** 76356 **In Date:** 03/22/2016 **Closed:** 03/30/2016
Problem: Pm service.Recall.

- Pm service.	Parts List	Qty
- Replace rear brake pads.resurface both rear brake rotors.service calipers.test drive.	5w20 Engine Oil	6.00
- Pressure test and inspect cooling system.flush and replace coolant.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Washer Fluid Concentr	1.00
- Transport vehicle to and from dealer for safety recall #14s21	Element	1.00
- Shop Supplies	Brake Pad	1.00
	Ford Red Antifreeze	2.00
	Shop Supplies	1.00
Hours 10.00	Labor: 600.00	Parts: 159.44
:		Total: 759.44

Workorder: 1604920 **Meter:** 79364 **In Date:** 05/11/2016 **Closed:** 05/24/2016
Problem: Tow in,no start.

- Test battery and charging system.replace bad battery and positive cable assemble.	Parts List	Qty
- Shop Supplies	Bxt96r 59	1.00
	Battery Cable	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 196.93
:		Total: 316.93

Workorder: 1605290 **Meter:** 79364 **In Date:** 05/11/2016 **Closed:** 05/23/2016
Problem: No start

- Tow From: South County Regional Park To: Lv shop			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1606780 **Meter:** 82867 **In Date:** 07/05/2016 **Closed:** 07/12/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	Washer Fluid Concentr	1.00
- Complete wheel alignment.test drive.	Accufit Beam	2.00
- Replace spark plugs.	Blade	1.00
- Service and clean throttle body and induction system.flush injectors.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	6.00
	235/55r17 Assurance	2.00
	Spark Plug	4.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.00	Labor: 600.00	Parts: 458.81
:		Total: 1,058.81

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1610036 **Meter:** 87874 **In Date:** 09/26/2016 **Closed:** 09/30/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Replace two tires, rotate and balance all four.	5w20 Engine Oil	6.00
- Replace noisy right front axle.	Napagold Oil Filter	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Accufit Beam	2.00
	Washer Fluid Concentr	1.00
	235/55r17 Assurance	2.00
	Right Front Axle Assembly	1.00
	Retainer	1.00
	Axel Nut	1.00
	Nut	1.00
	Bolt	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 6.25	Labor: 375.00	Parts: 711.81
:		Total: 1,086.81

Workorder: 1612739 **Meter:** 93096 **In Date:** 12/13/2016 **Closed:** 01/03/2017
Problem: P.M. service

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	5w20 Engine Oil	6.00
- Shop Supplies	Napagold Oil Filter	1.00
	Accufit Beam	2.00
	Accufit Rear	1.00
	Used Fire X Refurbished	1.00
	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 77.42
:		Total: 257.42

Workorder: 1700430 **Meter:** 94875 **In Date:** 01/13/2017 **Closed:** 01/23/2017
Problem: Right brake light inop.

- Replace right brake lamp bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.78
:		Total: 30.78

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1702075 **Meter:** 98969 **In Date:** 02/28/2017 **Closed:** 03/20/2017

Problem: P.M. service

- P.m. Service.	Parts List	Qty
- R&r driver seat for upholstery repairs.	Seat R And R	1.00
- Replace and balance four new tires.	Battery	1.00
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	6.00
- Complete wheel alignment.test drive.	Napagold Oil Filter	1.00
- Shop Supplies	Wiper Blade	2.00
	Washer Fluid Concentr	1.00
	Used Fire X Refurbished	1.00
	235/55r17 Assurance	4.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.50	Labor: 510.00	Parts: 1,155.12
:		Total: 1,665.12

Workorder: 1703294 **Meter:** 100271 **In Date:** 04/03/2017 **Closed:** 04/13/2017

Problem: A/C fan only works on high.

- Diagnose and replace defective blower resistor.	Parts List	Qty
- Shop Supplies	A/c Blower Regulator	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 36.88
:		Total: 96.88

Workorder: 1703854 **Meter:** 100603 **In Date:** 04/13/2017 **Closed:** 04/17/2017

Problem: Flat tire on Passenger Rear

- Tire Service Riverbend Park (left side) - Flat tire on Passenger Rear

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1704863 **Meter:** 102945 **In Date:** 05/16/2017 **Closed:** 05/22/2017

Problem: P.M. service and center console latch inop.

- P.m. service.	Parts List	Qty	
- Replace both catch and latch in center console lid.	Catch	1.00	
- Rotate and high speed balance all four tires .replace ten lug nuts on front.	Lug Nut	10.00	
- Shop Supplies	5w20 Engine Oil	6.00	
	Napagold Oil Filter	1.00	
	Accufit Beam	2.00	
	Wpr/blde	1.00	
	Latch	1.00	
	Shop Supplies	1.00	
Hours 3.50	Labor: 210.00	Parts: 208.72	Total: 418.72
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1707936 **Meter:** 108317 **In Date:** 08/14/2017 **Closed:** 08/16/2017

Problem: P.M. service.

- P.m. service.
- Replace two worn tires with new.rotate and balance four .
- Shop Supplies

Parts List	Qty
5w20 Engine Oil	6.00
Napagold Oil Filter	1.00
Washer Fluid Concentr	1.00
Wiper Blade	1.00
Wiper Blade	1.00
Used Fire X Refurbished	1.00
Napa Cabin Air Filter	1.00
Stg Wheel Cov - Ford	1.00
235/55r17 Assurance	2.00
Tire Pressure Monitoring System Sensor (2.00
Shop Supplies	1.00
Tire Disposal Fee	2.00

Hours 4.00 Labor: 240.00 Parts: 424.23 Total: 664.23
:

Workorder: 1708571 **Meter:** 109169 **In Date:** 08/30/2017 **Closed:** 08/31/2017

Problem: Left front tire going flat.

- Removed nail.repair and balance left front tire.
- Shop Supplies

Parts List	Qty
Shop Supplies	1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

Workorder: 1708749 **Meter:** 109726 **In Date:** 09/05/2017 **Closed:** 09/07/2017

Problem: Right low beam headlight inop.

- Test and replace right side low beam headlight bulb retest.

Parts List	Qty
Halogen Bulb	1.00

Hours 0.50 Labor: 30.00 Parts: 12.42 Total: 42.42
:

Workorder: 1710661 **Meter:** 110316 **In Date:** 10/02/2017 **Closed:** 10/27/2017

Problem: Damage to left front fender, left front door & mirror

- Damage to left front fender, left front door & mirror

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1801101 **Meter:** 110488 **In Date:** 01/30/2018 **Closed:** 02/01/2018

Problem: P.M. service and Light bar inop and tire light on.

- P.m. service.	Parts List	Qty
- Replace two faulty rear tag lamp bulb with new. Test and check light bar inop.found main fuse in cup hold .reinstall fuse and retest.	5w20 Engine Oil	6.00
	Napagold Oil Filter	1.00
- Repair both rear tires .rotate and balance all four .	Washer Fluid Concentr	1.00
- Shop Supplies	Bulb	2.00
	Wd40 Spr	1.00
	Shop Supplies	1.00
Hours 4.80	Labor: 288.00	Parts: 29.42
:		Total: 317.42

Workorder: 1803294 **Meter:** 110488 **In Date:** 03/29/2018 **Closed:** 03/29/2018

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			