

**Palm Beach County Fleet Management
Asset Maintenance History**

10169524 2008 FORD F350 Utility Truck, W/Walk-In Topper

Workorder: 748849 **Meter:** 0 **In Date:** 12/19/2007 **Closed:** 12/19/2007
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 832510 **Meter:** 28 **In Date:** 01/09/2008 **Closed:** 01/15/2008
Problem: NEEDS HITCH STEP,WATER IN UTILITY BED

- Install Hitch Step.drill Drain Holes In Utility Bed.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

6758 Hitch Mount Step 1.00

Hours 0.50 Labor: 30.00 Parts: 71.01 Total: 101.01
:

Workorder: 834579 **Meter:** 1058 **In Date:** 02/25/2008 **Closed:** 02/28/2008
Problem: IDLES TOO HIGH.

- Computer Diag,confirm Sys Not Going Into Regerearation Mode Refer To Dealer.

Parts List **Qty**

- To/fr Dealer For Moduel Reprogram

Shop Supplies 1.00

- Shop Supplies

Hours 2.40 Labor: 144.00 Parts: 2.00 Total: 146.00
:

Workorder: 837052 **Meter:** 1796 **In Date:** 04/16/2008 **Closed:** 05/08/2008
Problem: NEEDS FLOOR MAT

- Order And Install,floor Mats Removed Equipment Fr Cab And Prep For Dealer.

Parts List **Qty**

- To/front Dealer For Rubber Floormat Replacement.

Shop Supplies 1.00

Floor Mats 1.00

- Shop Supplies

Hours 2.40 Labor: 144.00 Parts: 57.44 Total: 201.44
:

Workorder: 840659 **Meter:** 3502 **In Date:** 06/27/2008 **Closed:** 06/30/2008
Problem: P.M SERVICE

- Pm Service

Parts List **Qty**

- Rotate And Hi Speed Balance All 6 Tires.remove Air Fr All Tires And Refill W/nitro Air.

Shop Supplies 1.00

7312 Oil Filterfrm Ch9549 Wix 57312 1.00

- Shop Supplies

Cs10263 Fuel Filter (use Cs10263a) 1.00

15/40 Oil 15.00

31-20 Wiper Blades 20" Blade 2.00

Hours 6.50 Labor: 390.00 Parts: 129.35 Total: 519.35
:

Workorder: 841543 **Meter:** 4351 **In Date:** 07/17/2008 **Closed:** 08/06/2008
Problem: VENT COVER ON UTILITY BODY MISSING

- Fabricate & Replace Broken Cargo Body Air Vent Dome.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

Roof Vent/fan 14x14 12v 1.00

Hours 2.00 Labor: 120.00 Parts: 91.93 Total: 211.93
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 844853	Meter: 6707	In Date: 09/30/2008	Closed: 10/02/2008
Problem: CHECK ENGINE LIGHT ON			
- Blow Out & Clean Debris Fr Radiator,inner Cooler,condencer, Oil Cooler Nad Trans Cooler.	Parts List		Qty
- Perform Computer Diagnostics,p2084 Egt Error.	Shop Supplies		1.00
- To/from Dealer For Failed Egt Sensor #2			
- Shop Supplies			
Hours 4.00	Labor: 240.00	Parts: 2.00	Total: 242.00
:			
Workorder: 845456	Meter: 6888	In Date: 10/09/2008	Closed: 10/14/2008
Problem: CHECK STROBES			
- L/rear Strobe Light Failed.r&r Strobe Light And Fabricate Wiring.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	6410a Strobe Lite Ecco		1.00
Hours 1.00	Labor: 60.00	Parts: 52.82	Total: 112.82
:			
Workorder: 845810	Meter: 7129	In Date: 10/17/2008	Closed: 10/21/2008
Problem: CHECK ENGINE LIGHT ON.			
- To/fr Dealer For Recall 08b07 Reprogram Pcm And Icm.	Parts List		Qty
Recall 08b06 Install Coolant Venturi Tee.	Shop Supplies		1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 846346	Meter: 7373	In Date: 10/30/2008	Closed: 10/30/2008
Problem: RIGHT REAR OUTER TIRE FLAT.			
- Repair Right Rear Outer Tire And High Speed Balance Same To Correct Problem.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 846858	Meter: 7890	In Date: 11/06/2008	Closed: 11/10/2008
Problem: VENT BROKEN			
- Fabricate & Replace Broken Cargo Body Air Vent Dome.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	Roof Vent		1.00
	66br Clear Silicone		2.00
Hours 2.50	Labor: 150.00	Parts: 114.93	Total: 264.93
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 932189 **Meter:** 9207 **In Date:** 01/02/2009 **Closed:** 01/08/2009
Problem: P.M. SERVICE.RECALL#08B06

- Pm Service	Parts List	Qty
- Shop Supplies	Pm-22-a Additive Diesel Fuel (m/craft)	1.00
	Shop Supplies	1.00
	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
Hours 4.00	Labor: 240.00	Parts: 232.24
:		Total: 472.24

Workorder: 936849 **Meter:** 12150 **In Date:** 04/22/2009 **Closed:** 04/24/2009
Problem: LEFT FRONT TIRE FLAT.

- Repair Left Front Tire Nitrogen Fill And Balance.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 937502 **Meter:** 12659 **In Date:** 05/07/2009 **Closed:** 05/11/2009
Problem: L/R OUTER TIRE FLAT

- Repair L/r Outer Tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 938713 **Meter:** 13949 **In Date:** 06/05/2009 **Closed:** 06/09/2009
Problem: PM SERVICE.

- Pm Service	Parts List	Qty
- Rotate And Hi Speed Balance All 6 Tires.nitro Fill To Specs.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
Hours 5.50	Labor: 330.00	Parts: 93.98
:		Total: 423.98

Workorder: 942192 **Meter:** 15701 **In Date:** 08/10/2009 **Closed:** 08/17/2009
Problem: R/F FLAT TIRE

- Forest Hill & Haverhill Frt Of Little Ceasars			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 942479	Meter: 15926	In Date: 08/25/2009	Closed: 08/27/2009
Problem: cargo vent cover broken			
- R&r cargo vent cover & fan assembly, rewire electric fan.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
	66br Clear Silicone		1.00
	Vent/fan Assy 14x14 12v Wvmf		1.00
Hours 2.00	Labor: 120.00	Parts: 112.63	Total: 232.63
:			

Workorder: 943491	Meter: 16176	In Date: 09/15/2009	Closed: 09/21/2009
Problem: L/R INNER TIRE HAS BOLT IN IT			
- N. Congress, Across From Cherry Rd			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 944914	Meter: 16871	In Date: 10/22/2009	Closed: 10/23/2009
Problem: Nail in L/F tire			
- Repair L/f tire.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

Workorder: 945775	Meter: 17202	In Date: 11/06/2009	Closed: 11/13/2009
Problem: Nail in L/R tire			
- Repair R/r outer tire.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

Workorder: 946704	Meter: 18053	In Date: 12/04/2009	Closed: 12/09/2009
Problem: P.M service.			
- P.m service.	Parts List		Qty
- Mount, balance & nitro fill six new tires.	Shop Supplies		1.00
- Test & replace R/s rear & L/s front strobe lamps on top of cargo topper.	7312 Oil Filterfrm Ch9549 Wix 57312		1.00
	Cs10263 Fuel Filter (use Cs10263a)		1.00
- Alignment.	Ca10270 Air Filter Mtc Fa1886 Wix 49886		1.00
- Shop Supplies	5441 Clear Gel Lube Gel Guard (mantek)		1.00
	Wd40 Spray Lube Stock# 405540002		1.00
	15/40 Oil		15.00
	Used Firex Refurbed Fire Extingshers		1.00
	31-20 Wiper Blades 20" Blade		2.00
	2015lpa Strobe Assy Amber (whelen)		2.00
	179636492 Lt245/75r17 Wrangler Sr-a E		6.00
	Tr416 Valve Stem		6.00
	Tire Disposal Fee		6.00
Hours 11.00	Labor: 660.00	Parts: 1,497.59	Total: 2,157.59
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 947035	Meter: 18297	In Date: 12/15/2009	Closed: 12/16/2009
Problem: No start, check batteries.			
- Test starting & charging system, charge & test each battery, both batteries failed load test, replace both batteries.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		Group 65 Battery (mtc Bxt-65-850)	2.00
Hours 1.50	Labor: 90.00	Parts: 259.49	Total: 349.49
:			
Workorder: 1000870	Meter: 19243	In Date: 01/22/2010	Closed: 01/26/2010
Problem: Rear cargo doors won't open.			
- Remove door handle from rear cargo door, repair lower latch & rod assembly, reinstall door handle		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1002989	Meter: 20514	In Date: 03/24/2010	Closed: 03/24/2010
Problem: Check strobes.			
- Test & replace R/f cargo mounted strobe lamp assembly, repair wiring to R/r strobe lamp.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		2015lpa Strobe Assy Amber (whelen)	1.00
Hours 1.50	Labor: 90.00	Parts: 100.10	Total: 190.10
:			
Workorder: 1003423	Meter: 20755	In Date: 04/02/2010	Closed: 04/07/2010
Problem: Lost fuel cap.			
- Replace missing fuel cap.		Parts List	Qty
		Fuel Cap / 8c3z9030b	1.00
Hours 0.30	Labor: 18.00	Parts: 26.96	Total: 44.96
:			
Workorder: 1003842	Meter: 21119	In Date: 04/14/2010	Closed: 04/21/2010
Problem: Cargo vent cover broken.			
- Replace broken cargo vent cover & rewire fan motor.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
		06133 3m Electric Tape Stock #832260101	1.00
		Vent Assy/fan 14x14 12 Volt	1.00
Hours 2.00	Labor: 120.00	Parts: 96.60	Total: 216.60
:			
Workorder: 1004182	Meter: 21328	In Date: 04/23/2010	Closed: 04/23/2010
Problem: A/C not blowing, clean Exhaust filter message.			
- Preform A/c inspection & service, clean out debris from radiator, condenser, inner cooler, trans cooler & pwst cooler. flush & clean evaporator core.		Parts List	Qty
- Perform engine diagnostics, add cetain booster & clean exhaust filter. vehicle idling too long causing multiple problems.		Shop Supplies	1.00
- Shop Supplies		Pm-22-a Additive Diesel Fuel (m/craft)	1.00
		6984 Evapor Cleaner Evaporator Cleaner	1.00
		R134a Refrigerant	1.00
Hours 7.00	Labor: 420.00	Parts: 22.66	Total: 442.66
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1006259 **Meter:** 22950 **In Date:** 06/14/2010 **Closed:** 06/14/2010
Problem: P.M. Service.

- P.m. Service	Parts List	Qty
- Replace and balance L/f tire.	Shop Supplies	1.00
- Shop Supplies	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Cs10263 Fuel Filter (use Cs10263a)	1.00
	15/40 Oil	15.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	1.00
	Tire Disposal Fee	1.00
Hours 5.00	Labor: 300.00	Parts: 297.73
:		Total: 597.73

Workorder: 1006721 **Meter:** 23365 **In Date:** 06/25/2010 **Closed:** 07/06/2010
Problem: Ac system blows warm air.

- Diagnose a/c not cold.leak test system.r/r dash board and evaporator module,and replace leaking evaporator.install new accumulator and orifice.evacuate and recharge system.	Parts List	Qty
- R/r trim panels and seat and cleandirt and grass clipping from cab.	Shop Supplies	1.00
- Shop Supplies	Orifice	1.00
	E8 A/c Oil R134a A/c Oil (tsi)	1.00
	R134a Refrigerant	2.00
	Evaporator	1.00
	Accumulator	1.00
	Antifreeze Ext/life All Makes (peak 407)	2.00
Hours 14.50	Labor: 870.00	Parts: 369.56
:		Total: 1,239.56

Workorder: 1007622 **Meter:** 23669 **In Date:** 07/20/2010 **Closed:** 07/21/2010
Problem: Right rear tires damage beyond repairs.

- Install one new tire right rear outer.repair one tire left rear outer,then balance both.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	1.00
	Tire Disposal Fee	1.00
Hours 2.00	Labor: 120.00	Parts: 188.69
:		Total: 308.69

Workorder: 1008251 **Meter:** 23848 **In Date:** 08/03/2010 **Closed:** 08/03/2010
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1008649 **Meter:** 24091 **In Date:** 08/11/2010 **Closed:** 08/20/2010
Problem: Check engine light on.

- Transport vehicle to and from dealer to replace failed blower switch,harness and torque converter clutch solnoid under factory warranty.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1009348	Meter: 24249	In Date: 08/27/2010	Closed: 08/30/2010
Problem: Left rear outter tire has nail in it.			
- Repair one tire and balance and remount on left rear outter.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1012375	Meter: 26263	In Date: 11/04/2010	Closed: 11/04/2010
Problem: Right front turn signal lamp out.			
- Replace right front t/s bulb.	Parts List		Qty
	3157 Tail Light Bulbs		1.00
Hours 0.50	Labor: 30.00	Parts: 1.19	Total: 31.19
:			
Workorder: 1012816	Meter: 26540	In Date: 11/17/2010	Closed: 11/17/2010
Problem: Left front tire has nail in it.			
- Repair flat and balance left front tire.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1013455	Meter: 26821	In Date: 12/01/2010	Closed: 12/08/2010
Problem: left rear outer flat			
- 6th ave s. east of congress n side of rd			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1013500	Meter: 26821	In Date: 12/08/2010	Closed: 12/08/2010
Problem: TIRES			
- 6 Ave East Of Congress			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1101418	Meter: 28240	In Date: 02/04/2011	Closed: 02/09/2011
Problem: Pm service.			
- Perform pm service.	Parts List		Qty
- Install one new tire.rotate and balance all six.	Pm-22-a Additive Diesel Fuel (m/craft)		1.00
- Shop Supplies	Shop Supplies		1.00
	Cs10263 Fuel Filter (use Cs10263a)		1.00
	7312 Oil Filterfrm Ch9549 Wix 57312		1.00
	Ca10270 Air Filter Mtc Fa1886 Wix 49886		1.00
	15/40 Oil		15.00
	31-20 Wiper Blades 20" Blade		2.00
	179636492 Lt245/75r17 Wrangler Sr-a E		1.00
	Tire Disposal Fee		1.00
Hours 6.25	Labor: 375.00	Parts: 324.90	Total: 699.90
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1104365 **Meter:** 30372 **In Date:** 04/22/2011 **Closed:** 04/28/2011

Problem: Chains for side bins and back doors broken also check turn signal lights

- Replace rear boor shocks and repair bracket on right front door shocks.	Parts List	Qty
	Shop Supplies	1.00
- Replace right front t/s bulb.	Door Props	2.00
- Shop Supplies	3157 Tail Light Bulbs	2.00
Hours 1.25	Labor: 75.00	Parts: 41.66
:		Total: 116.66

Workorder: 1105971 **Meter:** 31672 **In Date:** 06/06/2011 **Closed:** 06/06/2011

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1106723 **Meter:** 32431 **In Date:** 06/24/2011 **Closed:** 07/05/2011

Problem: back door hinges broken see notes.

- Perform pm service.	Parts List	Qty	
- Inspect and replace both failed rear axle seals and wheel bearings with new.	Shop Supplies	1.00	
	Rear Wheel Bearing Assy	1.00	
- Rotate and balance all six tires.	Rear Wheel Bearing Assy	1.00	
- Shop Supplies	Cs10263 Fuel Filter (use Cs10263a)	1.00	
	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	
	09997 Brake Clean	1.00	
	15/40 Oil	15.00	
	31-20 Wiper Blades 20" Blade	2.00	
	Used Firex Refurbed Fire Extingshers	1.00	
	Rear Axle Seals	1.00	
	Rear Axle Seals	1.00	
Hours 9.00	Labor: 540.00	Parts: 229.06	Total: 769.06
:			

Workorder: 1108553 **Meter:** 33563 **In Date:** 08/12/2011 **Closed:** 08/15/2011

Problem: Replace water cooler rack.

- Remove rusted out water cooler holder and replace with new.	Parts List	Qty	
	Shop Supplies	1.00	
- Shop Supplies	Keg Holder Water Coolers 450870003	1.00	
Hours 1.00	Labor: 60.00	Parts: 82.61	Total: 142.61
:			

Workorder: 1109679 **Meter:** 34588 **In Date:** 09/09/2011 **Closed:** 09/15/2011

Problem: Check backup alarm strobe lights and signal lights inop.

- Test and replace both failed rear strobe lights becon lamps with new.rewire and insulate both.	Parts List	Qty	
	Shop Supplies	1.00	
- Test and replace failed left front turn signal lamp bulb and head lamp bulb with new.	2015lpa Strobe Assy Amber (whelen)	2.00	
	3157 Tail Light Bulbs	2.00	
- Test and repair open power and ground circuit to back up alarm.	H6054 Sealed Beam	1.00	
- Shop Supplies			
Hours 3.25	Labor: 195.00	Parts: 213.49	Total: 408.49
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1110162 **Meter:** 34905 **In Date:** 09/23/2011 **Closed:** 09/28/2011
Problem: Right rear door strut damper broken.

- Inspect and replace failed strut damper for rear door with new.	Parts List	Qty
	Door Lift Support	1.00
Hours 0.50	Labor: 30.00	Parts: 18.74
:		Total: 48.74

Workorder: 1110574 **Meter:** 35065 **In Date:** 10/04/2011 **Closed:** 10/06/2011
Problem: Jump start at roads lot.

- Test starting and charging system.both batteries failed load test after recharge.replace both failed batteries with new.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Group 65 Battery (mtc Bxt-65-850)	2.00
Hours 2.00	Labor: 120.00	Parts: 259.49
:		Total: 379.49

Workorder: 1111130 **Meter:** 35388 **In Date:** 10/20/2011 **Closed:** 10/24/2011
Problem: Left front and left rear tires flat

- Repair two flat tires left front and left rear.nitrogen fill and balance both.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 2.00
:		Total: 122.00

Workorder: 1112765 **Meter:** 36863 **In Date:** 12/02/2011 **Closed:** 12/12/2011
Problem: Back door strut broken

- Fabricate and replace broken back door strut with new.	Parts List	Qty
	Lift Support	1.00
Hours 0.50	Labor: 30.00	Parts: 18.74
:		Total: 48.74

Workorder: 1200572 **Meter:** 37831 **In Date:** 01/18/2012 **Closed:** 01/24/2012
Problem: replace tire

- Replace L/r Tire			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1201199	Meter: 38283	In Date: 02/03/2012	Closed: 02/09/2012
Problem: Pm service.Air vent on roof and water cooler rack broken.			
- P.m. Service.	Parts List	Qty	
- Fabricate and replace broken roof vent.	Shop Supplies	1.00	
- Replace two tires,rotate and balance all six.	Upper Radiator Hose	1.00	
- Pressure and inspect cooling system.replace leaking upper radiator hose.flush and refill cooling system.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00	
- Complete wheel alignment.test drive.	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00	
- Shop Supplies	15/40 Oil	15.00	
	Keg Holder Water Coolers 450870003	1.00	
	31-20 Wiper Blades 20" Blade	2.00	
	66br Clear Silicone	1.00	
	Antifreeze Ext/life All Makes (peak 407)	1.00	
	179636492 Lt245/75r17 Wrangler Sr-a E	2.00	
	Tire Disposal Fee	2.00	
	Roof Vent/fan	1.00	
Hours 14.00	Labor: 840.00	Parts: 724.28	Total: 1,564.28
:			
Workorder: 1202023	Meter: 38890	In Date: 02/28/2012	Closed: 02/29/2012
Problem: Can not open rear doors on walk in topper.			
- remove rear cargo door handle and replace retainer clips.fabricate and repair locking rods.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1202961	Meter: 39741	In Date: 03/27/2012	Closed: 03/29/2012
Problem: Flat Tire			
- Flat repair			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1205771	Meter: 41693	In Date: 06/14/2012	Closed: 06/18/2012
Problem: Iri flat			
- Tire Service clintmoore west of lyons - Iri flat			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1205772	Meter: 41693	In Date: 06/14/2012	Closed: 06/18/2012
Problem: tires			
- Tire Service Clintmoore btwn Turnpike and Lyons rd - tires			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			
Workorder: 1205942	Meter: 42152	In Date: 06/22/2012	Closed: 06/28/2012
Problem: Check over for back window leaking.			
- Check for water leak at back window.r&r center brake light and reseal.	Parts List	Qty	
- Shop Supplies	Shop Supplies	1.00	
	66br Clear Silicone	2.00	
Hours 1.00	Labor: 60.00	Parts: 8.24	Total: 68.24
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1206138 **Meter:** 42261 **In Date:** 06/29/2012 **Closed:** 06/29/2012

Problem: Back doors latch jammed from equipments tossed from take off.

- Drill out rear door handle to open jammed rear doors.fabricate and repair rear door latch and linkages.fabricate and make up partician in topper to prevent equipment against back doors.	Parts List	Qty
	Shop Supplies	1.00
	Wd40 Spray Lube Stock# 405540002	1.00
- Shop Supplies		
Hours 2.50	Labor: 150.00	Parts: 8.86
:		Total: 158.86

Workorder: 1206717 **Meter:** 42779 **In Date:** 07/18/2012 **Closed:** 07/30/2012

Problem: White smoke from exhaust and check over rear doors.

- Perform pm service.	Parts List	Qty
- Test and replace failed ac blower resistor with new.	Shop Supplies	1.00
- Replace failed front becon strobe lamp assembly with new.test and replace failed left Led brake lamp and right side marker lamp with new.	7312 Oil Filterfrm Ch9549 Wix 57312	1.00
	Ca10270 Air Filter Mtc Fa1886 Wix 49886	1.00
- Install four new tires to wheels.nitrogen fill and balance all six tires	3963 Fuel Filter Frm Cs10263a Wix 33963	1.00
	15/40 Oil	15.00
- Computer diagnose for check engine light on.test and replace failed exhaust temperature sensors #2 and #3 with new.clear codes with scan tool and road test.	1066 White Lithium (crc 05037)	1.00
	5068 Penetrant Lube Pentron (mantek)	1.00
- Inspect and repair loose side door lock cylinder and hinges for utility body right side door.	D3tz2457b Brake Pedal Pad	1.00
	A/c Blower Resistor	1.00
- Shop Supplies	Used Firex Refurbed Fire Extingshers	1.00
	2015lpa Strobe Assy Amber (whelen)	1.00
	44202r Tail Light 4" Red 42 Led	1.00
	Exhaust Temperature Sensor	1.00
	Exhaust Temperature Sensor #2	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
Hours 12.50	Labor: 750.00	Parts: 1,214.52
:		Total: 1,964.52

Workorder: 1207817 **Meter:** 43230 **In Date:** 08/17/2012 **Closed:** 09/06/2012

Problem: Ac blows warm air and secure water cooler rack.

- Ac performance and leak test.recover freon and replace failed orifice tube filter/expansion valve with new.vacume and recharge system to specs.	Parts List	Qty
	Shop Supplies	1.00
- Replace failed water cooler rack with new.mount and secure to rear of vehicle.	R134a Refrigerant	2.00
	E8 A/c Oil R134a A/c Oil (tsi)	1.00
- Shop Supplies	Keg Holder Water Coolers 450870003	1.00
	Orfice Tube	1.00
Hours 3.75	Labor: 225.00	Parts: 104.58
:		Total: 329.58

Workorder: 1208526 **Meter:** 43431 **In Date:** 09/07/2012 **Closed:** 09/17/2012

Problem: Right side bend door will not stay shut.

- Repair and adjust right rear bin door lock striker.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1209386 **Meter:** 43649 **In Date:** 10/01/2012 **Closed:** 10/01/2012
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1209407 **Meter:** 44223 **In Date:** 10/02/2012 **Closed:** 10/17/2012
Problem: Strobe lamp on topper broken.

- Repair,secure and reseal broken left rear becon strobe lamp assembly.

Parts List

66br Clear Silicone Qty 1.00

- Shop Supplies

Shop Supplies Qty 1.00

Hours 1.00 Labor: 60.00 Parts: 5.48 Total: 65.48
:

Workorder: 1300444 **Meter:** 46704 **In Date:** 01/11/2013 **Closed:** 01/11/2013
Problem: tires

- Tire Service cong ave just stouth of lw rd - tires

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1300445 **Meter:** 46704 **In Date:** 01/10/2013 **Closed:** 01/11/2013
Problem: Flat tire on Driver Inside Rear

- Tire Service Congress Ave Just S of L.w. Rd south bound - Flat tire on Driver Inside Rear

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1300669 **Meter:** 46884 **In Date:** 01/17/2013 **Closed:** 01/29/2013
Problem: P.M. service and right rear top strobe broken and cargo door will not latch.

- P.m. Service.

Parts List

Qty

- Replace right strobe light on utility box top.replace rear marker light strip.

15-40 Oil Qty 15.00

Oil Filter Qty 1.00

- Flush and refill transmission system.

Fuel Filter Qty 1.00

- Remove left front door panel and replace broken check strap.fabricate and repair left rear door lock.

31-20 Wiper Blades 20 Qty 2.00

Mac Wite Lithium Gres Qty 1.00

- Repair left front tire,rotate and balance all six.

Floor Mat-2pc Rub Bk Qty 1.00

Wd40 Spray Lube Stock Qty 1.00

2015lpa Strobe Assy A Qty 1.00

Led M C Lamp Qty 1.00

Syn-atf Trans Fluid S Qty 20.00

Check Asy Qty 1.00

Led M C Lamp Qty 2.00

Shop Supplies Qty 1.00

Hours 12.00 Labor: 720.00 Parts: 522.68 Total: 1,242.68
:

Workorder: 1302605 **Meter:** 48026 **In Date:** 03/15/2013 **Closed:** 03/21/2013
Problem: Right front tire and right rear outer tire going flat.

- Repair and balance right front and right rear tires.

Parts List

Qty

- Shop Supplies

Shop Supplies Qty 1.00

Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1304401 **Meter:** 49154 **In Date:** 05/03/2013 **Closed:** 05/06/2013
Problem: Right front tire flat and check over hinge on back doors

- Repair flat left front tire.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1304893 **Meter:** 49625 **In Date:** 05/16/2013 **Closed:** 05/29/2013
Problem: Request step to go into back of walk in topper.

- Fabricate and replace broken roof vent on utility body.install hitch mounted step.	Parts List	Qty
- Shop Supplies	Hitch Step	1.00
	Fan Asym	1.00
	Silicone Clear Permatex	2.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 290.12
:		Total: 410.12

Workorder: 1306542 **Meter:** 50870 **In Date:** 06/28/2013 **Closed:** 07/17/2013
Problem: Ac inop.Pm service.

- P.m. Service.	Parts List	Qty
- A/c performance test.remove dashboard and replaced evaporator core,orifice tube and accumulator.vacuum and recharge system to specs.clean grass clippings and debri from cab.	15-40 Oil	15.00
	Napagold Oil Filter	1.00
	Napagold Fuel Filter	1.00
- Replace two roof clearance lamp bulbs and left front utility body bulb.	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
- Retorque hitch bolts.reposition rear fuel filler pipe,rubbing on body.	31-20 Wiper Blades 20	2.00
	Evapotator Core	1.00
- Rotate and balance all six tires.	R134a Lv Shop 1	2.00
- Shop Supplies	O Ring	3.00
	O-ring	3.00
	M C Lamp	1.00
	Miniature Bulb	2.00
	Peak Global	1.00
	Shop Supplies	1.00
Hours 19.50	Labor: 1,170.00	Parts: 435.71
:	0	Total: 1,605.71

Workorder: 1308087 **Meter:** 51958 **In Date:** 08/13/2013 **Closed:** 08/20/2013
Problem: Right front tire flat.

- Replace and balance right front tire.	Parts List	Qty
- Shop Supplies	179636492 Lt245-75r17	1.00
	Tr416 Valve Stem	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 250.17
:		Total: 310.17

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1310302 **Meter:** 53395 **In Date:** 10/11/2013 **Closed:** 10/22/2013
Problem: Left front turnsignal inop.

- Replace left signal light bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.25	Labor: 15.00	Parts: 0.99
:		Total: 15.99

Workorder: 1311124 **Meter:** 54161 **In Date:** 11/01/2013 **Closed:** 11/08/2013
Problem: Check becon strobelights on top of box damage.

- Fabricate and install new becon lamp strobe light assembly to left rear of box.repair wiring to right rear lamp and secure left front lamp.	Parts List	Qty
	Support	1.00
- Fabricate and replace broken right rear door strut/stop with new.	2015lpa Strobe Assy A	1.00
	Ptex Ultra Grey 3oz	1.00
- Shop Supplies	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 149.29
:		Total: 269.29

Workorder: 1400611 **Meter:** 56049 **In Date:** 01/17/2014 **Closed:** 01/31/2014
Problem: Pm service and batteries overheating.

- P.m. Service.	Parts List	Qty
- Replace and rewire left front strobe.replace right headlamp.	15-40 Oil	15.00
- Check batteries and charging system.replace both bad batteries.	Napagold Oil Filter	1.00
	Fuel Filter Ford Only	1.00
- Replace right rear door cable and prop.replace broken roof vent assemble.	Wiper Blade	2.00
	250adh12a Strobe Stro	1.00
- Replace four tires,rotate and balance all six.	Halogen Lamp	1.00
- Complete wheel alignment.test drive.	Battery	2.00
- Shop Supplies	Support	1.00
	179636492 Lt245-75r17	4.00
	Support	1.00
	Roof Vent	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 16.50	Labor: 990.00	Parts: 1,778.70
:		Total: 2,768.70

Workorder: 1401749 **Meter:** 56505 **In Date:** 02/24/2014 **Closed:** 02/27/2014
Problem: Weld rear door shock mount

- Weild door and install shock	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 2.00
:		Total: 182.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1404541	Meter: 58633	In Date: 05/08/2014	Closed: 05/14/2014
Problem: Cannot open rear doors for walk in topper.			
- Force entry into back doors.inspect and replace broken rod clips and adjust rods to open and close door locks.	Parts List		Qty
	Door Clip		1.00
- Shop Supplies	Ptex Superbond Sm		1.00
	Shop Supplies		1.00
Hours 1.50	Labor: 90.00	Parts: 8.71	Total: 98.71
:			
Workorder: 1404852	Meter: 58856	In Date: 05/19/2014	Closed: 05/21/2014
Problem: Vent on walk in broken and right front strobe inop.			
- Fabricate and replace damage ventilation Vent / fan assembly with new and secure wiring.	Parts List		Qty
	roofvent w/fan		1.00
- Test and replace failed right front becon strobe lamp assenby with new.fabricate and repair wiring.remove and reseal left front for water leak.	Clr Rtv Silcn Sealant		1.00
	2015lpa Strobe Assy A		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 3.50	Labor: 210.00	Parts: 230.14	Total: 440.14
:			
Workorder: 1405308	Meter: 59229	In Date: 05/30/2014	Closed: 06/06/2014
Problem: Vent fan in walk-in coming apart.			
- Fabricate and repair vent fan screen.			
Hours 0.50	Labor: 30.00	Parts: 0.00	Total: 30.00
:			
Workorder: 1405689	Meter: 59379	In Date: 06/10/2014	Closed: 06/12/2014
Problem: flat tire at road and bridge			
- Replace r/f tire moun balance w/nitro fill	Parts List		Qty
- Shop Supplies	179636492 Lt245-75r17		1.00
	Shop Supplies		1.00
	Tire Disposal Fee		1.00
Hours 1.00	Labor: 60.00	Parts: 247.77	Total: 307.77
:			
Workorder: 1406122	Meter: 59742	In Date: 06/20/2014	Closed: 06/25/2014
Problem: Left rear outside tire flat.			
- Repair both left rear tires flat.nitrogen fill and balance both.	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 2.00	Labor: 120.00	Parts: 2.00	Total: 122.00
:			
Workorder: 1406531	Meter: 59801	In Date: 07/02/2014	Closed: 07/09/2014
Problem: Door adjar light on.Turn signal light inop.Left center door lock on utility body loose.			
- Diagnose for door adjar warning light on.pinpoint test and replace failed driver door adjar switch with new.	Parts List		Qty
	Led Sup Mdl 44 42 Dio		1.00
- Test and replace failed left rear Led turnsignal lamp assembly with new.	Slip Plate Spray 12oz		1.00
	Switch Asy		1.00
- Fabricate,repair and secure loose center door lock assembly	Shop Supplies		1.00
- Shop Supplies			
Hours 2.00	Labor: 120.00	Parts: 85.43	Total: 205.43
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1409447 **Meter:** 61284 **In Date:** 09/19/2014 **Closed:** 09/26/2014
Problem: Pm service and check all lights.

- Pm service	Parts List	Qty
- Inspect and replace defective left front becon strobe lamp	15-40 Oil	15.00
- Replace two tires.rotate and balance all six.	Napagold Oil Filter	1.00
- Pressure test and inspect cooling system.replace leaking radiator and both lower radiator hoses.flush cooling system and refill coolant.	Fuel Filter Ford Only	1.00
- Inspect for fuel leak.drain and remove front fuel tank and repair for leak,then reinstall tank and refill fuel.	Used Fire X Refurbished	1.00
- Inspect and secure loose front bumper and bracket .	Wiper Blade	2.00
- Shop Supplies	Stg Wheel Cov - Ford	1.00
	Napagold Air Filter	1.00
	Strobe Lp Led	1.00
	179636492 Lt245-75r17	2.00
	Beacon Lp Amber Strobe	1.00
	Radiator	1.00
	lower hose	1.00
	Radiator Hose	1.00
	Coolant Ford Gold	3.00
	Ptex Gas Tank Repr Kt	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 16.80	Labor: 1,008.0	Parts: 2,132.55
:	0	Total: 3,140.55

Workorder: 1409917 **Meter:** 61510 **In Date:** 10/02/2014 **Closed:** 10/08/2014
Problem: Fuel cap missing

- Replace missing fuel cap on rear tank.	Parts List	Qty
	Fuel Cap Diesel	1.00
Hours 0.30	Labor: 18.00	Parts: 27.68
:		Total: 45.68

Workorder: 1411131 **Meter:** 62410 **In Date:** 11/05/2014 **Closed:** 12/04/2014
Problem: Replace rear step(push into hitch reciever.)

- Remove and replace damage step and mount into hitch receiver.	Parts List	Qty
- Shop Supplies	Hitch Step	1.00
	Shop Supplies	1.00
Hours 0.50	Labor: 30.00	Parts: 87.80
:		Total: 117.80

Workorder: 1412700 **Meter:** 63089 **In Date:** 12/19/2014 **Closed:** 12/29/2014
Problem: Roof vent on walk in came apart.

- Replace defective vent/fan assembly on top of walk in topper.fabricate and secure wiring for fan.	Parts List	Qty
- Shop Supplies	roofvent w/fan	1.00
	Clr Rtv Silcn Sealant	1.00
	Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 107.38
:		Total: 227.38

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1500415	Meter: 63424	In Date: 01/13/2015	Closed: 01/22/2015
Problem: Belt and tensioner broken.Windshield cracked.			
- Rerplace broken tensioner and serpentine belt.		Parts List	Qty
- Shop Supplies		Serpentine Belt	1.00
		Tensioner-heavy Duty	1.00
		Shop Supplies	1.00
Hours 3.50	Labor: 210.00	Parts: 139.78	Total: 349.78
:			

Workorder: 1500452	Meter: 63372	In Date: 01/13/2015	Closed: 01/27/2015
Problem: replace cracked windsheild			
- Set up windshield replacements reasset		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			

Workorder: 1501499	Meter: 64566	In Date: 02/10/2015	Closed: 03/20/2015
Problem: Left front turnsignal lamp inop.Pm service.			
- Test and replace defective left front turnsignal lamp bulb.replace defective tag lamp and licence plate bracket.		Parts List	Qty
- Replace defective left rear becon strobe lamp.fabricate wiring and reseal to roof.		Strobe	1.00
- Pm service.		Bulb	1.00
- Inspect and replace both upper and lower worn left and right side ball joints		15-40 Oil	15.00
- Replace front and rear brake pads and all four brake calipers.resurface all four brake rotors.bleed and flush hydraulic brake system.road test.		Napagold Oil Filter	1.00
- Rotate and balance all six tires.		Fuel Filter Ford Only	1.00
- Complete front end alignment and roadtest.		Wiper Blade	2.00
- Inspect and replace defective worn out left front frame to body mount/insulators.		Ball Joint	2.00
- Shop Supplies		Ball Joint	2.00
		Reman Brake Caliper	1.00
		Reman Brake Caliper	1.00
		Caliper w/ Hardware - Left Rear (eclipse	1.00
		Caliper w/ Hardware - Right Rear (eclips	1.00
		1401 Brake Fluid Bra	2.00
		Brake Cleaner	1.00
		License Bracket W/light	1.00
		Body Mount Kit	1.00
		Clr Rtv Silcn Sealant	1.00
		Shop Supplies	1.00
Hours 27.00	Labor: 1,620.00	Parts: 1,033.88	Total: 2,653.88
:	0		

Workorder: 1504141	Meter: 65359	In Date: 04/21/2015	Closed: 05/27/2015
Problem: Hitch reciever step.			
- Install hitch step.		Parts List	Qty
- Shop Supplies		Bully Hitch Step	1.00
		Shop Supplies	1.00
Hours 0.30	Labor: 18.00	Parts: 55.21	Total: 73.21
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1506163 **Meter:** 66133 **In Date:** 06/19/2015 **Closed:** 06/22/2015
Problem: Install second water cooler rack

- Replace left side water cooler rack and install second rack on right side.	Parts List	Qty
	Water Cooler Holder	2.00
- Shop Supplies	Clr Rtv Silcn Sealant	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 232.10
:		Total: 322.10

Workorder: 1507591 **Meter:** 67181 **In Date:** 07/30/2015 **Closed:** 08/18/2015
Problem: Check A/C warm in middle of day and check strobe lights.

- Diagnose a/c system,not cold.replace defective compressor,accumulator,orgice tube and schdrader valves.vacuum system and recharge to specs.clean condensor fins.	Parts List	Qty
	A/c Compressor	1.00
	Seal Kits	1.00
- Test and replace two strobe lamps.	Seal	1.00
- Shop Supplies	Rapid Seal Kit	1.00
	Ac Valve Core High	1.00
	A/c Service Port	1.00
	Strobe	2.00
	R134a Lv Shop 2	2.00
	Napagold Air Filter	1.00
	Accumulator	1.00
	Orifice Tube	1.00
	E8 A/c Oil Univ W Dye	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 1,102.16
:		Total: 1,642.16

Workorder: 1508798 **Meter:** 67630 **In Date:** 09/02/2015 **Closed:** 09/09/2015
Problem: Pm service.Right headlamp inop.Becon strobe lamp broken.

- Pm service.	Parts List	Qty
- Replace two defective tail lamps.broken right front becon strobe lamp assembly on top box and one defective right headlamp seal beam.	Strobe	1.00
	15-40 Oil	15.00
- Repair right rear outer tire.rotate and balance all six.	Napagold Oil Filter	1.00
- Shop Supplies	Fuel Filter Ford Only	1.00
	Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Halogen Lamp	1.00
	Strobe Lp Led	1.00
	Led Sup Mdl 44 42 Dio	2.00
	Seal Kit	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 734.93
:		Total: 1,274.93

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1509068 **Meter:** 67901 **In Date:** 09/10/2015 **Closed:** 09/29/2015

Problem: Air bag warning light on and chain for bin side lid.

- Computer diagnose air bag light on.code B1342 Perform pin point test and replace defective airbag module.perform Pmi on module.clear code,retest.p0703 Replace defective brake pressure switch.retest ok.	Parts List	Qty
	Restraint Control Mod	1.00
	Brake Pressure Switch	1.00
	Shop Supplies	1.00
- Fabricate and replace missing chain stop for left center bin lid.		
- Repair and balance right front tire.		
- Shop Supplies		

Hours 5.50 Labor: 330.00 Parts: 359.15 Total: 689.15

:

Workorder: 1600152 **Meter:** 69875 **In Date:** 01/06/2016 **Closed:** 01/26/2016

Problem: Towed in for no start.

- Charge batteries fully.test both batteries and charging system.replace both defective batteries.	Parts List	Qty
	Battery	2.00
- Replace fuel cap.	Fuel Cap Diesel	1.00
- Replace front saignal light bulb.	Bulb	1.00
- Shop Supplies	Shop Supplies	1.00

Hours 2.75 Labor: 165.00 Parts: 267.28 Total: 432.28

:

Workorder: 1600169 **Meter:** 69174 **In Date:** 01/06/2016 **Closed:** 01/06/2016

Problem: wont start, tried jumping still wont start. Hood up keys in it.

- Tow From: Roads parking lot To: vista

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00

:

Workorder: 1600963 **Meter:** 70258 **In Date:** 01/28/2016 **Closed:** 02/04/2016

Problem: Vent cover on top of walk in utility body broken.

- Replace broken roof vent fan assembly.	Parts List	Qty
	Vent Fan Assembly	1.00
- Shop Supplies	Clr Rtv Silcn Sealant	2.00
	Shop Supplies	1.00

Hours 2.50 Labor: 150.00 Parts: 113.71 Total: 263.71

:

Workorder: 1601654 **Meter:** 70824 **In Date:** 02/17/2016 **Closed:** 02/18/2016

Problem: Driver side low beam out.

- Replace droiver side headlamp.	Parts List	Qty
	Halogen Lamp	1.00

Hours 0.50 Labor: 30.00 Parts: 13.01 Total: 43.01

:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603485 **Meter:** 72012 **In Date:** 04/01/2016 **Closed:** 04/12/2016
Problem: Pm service.Whining noise from steering.

- P.m. Service.	Parts List	Qty
- Replace front shocks and bump stoppers.	Napagold Air Filter	1.00
- Diagnose whinning noise.replace leaking hydro-booster.flush and refill power steering system.	Fuel Filter Ford Only	1.00
- Replace four tires,rotate and balance all six.	Napagold Oil Filter	1.00
- Replace wiper nozzles and blades.	15-40 Oil	15.00
- Shop Supplies	bumper	2.00
	Gas Grande Fleet Shoc	2.00
	Brake Booster	1.00
	Syn-atf Trans Fluid S	4.00
	179636492 Lt245-75r17	4.00
	B Fluid Dot 3-32oz	1.00
	Washer Nozzle	2.00
	20" Wiper Blade	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 11.50	Labor: 690.00	Parts: 1,767.63
:		Total: 2,457.63

Workorder: 1604243 **Meter:** 72343 **In Date:** 04/22/2016 **Closed:** 04/29/2016
Problem: Driver seat belt will not cluck close.

- Replace seat belt buckles.	Parts List	Qty
- Shop Supplies	Seat Belt	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 233.80
:		Total: 293.80

Workorder: 1604932 **Meter:** 72717 **In Date:** 05/12/2016 **Closed:** 05/24/2016
Problem: Right front turn signal inop.

- Replace left front signal light bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.78
:		Total: 30.78

Workorder: 1606783 **Meter:** 73235 **In Date:** 06/30/2016 **Closed:** 07/05/2016
Problem: Winch out

- Tow From: Frt of Lion Country Safari			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1606919 **Meter:** 73365 **In Date:** 07/08/2016 **Closed:** 07/29/2016
Problem: Rear utility door lock inop and left side bin door stuck.

- Replace rear door and one side bin lock cylinder.	Parts List	Qty
- Shop Supplies	Lock Cylinder	2.00
	Shop Supplies	1.00
	Freight Charge	1.00
Hours 1.50	Labor: 90.00	Parts: 38.19
:		Total: 128.19

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1608580 **Meter:** 73833 **In Date:** 08/18/2016 **Closed:** 08/30/2016
Problem: A/C blows warm at times.

- Check a/c system.replace blower motor and resistor.replace condensor,accumulator anmd orifice tube.vacuum and recharge system to specs.
- Shop Supplies

Parts List	Qty
Fan Motor	1.00
A/c Condenser	1.00
Tube Filter	1.00
O-ring	3.00
Accumulator	1.00
Seal Kits	2.00
Blower Resistor	1.00
Seal	2.00
Shop Supplies	1.00

Hours 8.00 Labor: 480.00 Parts: 727.34 Total: 1,207.34
 :

Workorder: 1609430 **Meter:** 74409 **In Date:** 09/09/2016 **Closed:** 09/20/2016
Problem: Vent top blow off walk in.

- Replace and seal broken roof vent.install wiring.
- Shop Supplies

Parts List	Qty
Roof Vent	1.00
Clr Rtv Silcn Sealant	1.00
Shop Supplies	1.00

Hours 2.00 Labor: 120.00 Parts: 107.38 Total: 227.38
 :

Workorder: 1611976 **Meter:** 76192 **In Date:** 11/18/2016 **Closed:** 11/30/2016
Problem: P.M. service and replace drivers side cooler rack.

- P.m. Service.
- Replace worn out water pump drive belt.
- Replace rear suspension bump stops.
- Replace broken water cooler rack.
- Replace left front signal light bulb and right tail marker bulb.
- Rotate and balance six tires.
- Shop Supplies

Parts List	Qty
15-40 Oil	15.00
Napagold Oil Filter	1.00
Fuel Filter Ford Only	1.00
Napagold Air Filter	1.00
Mac Wite Lithium Gres	1.00
20" Wiper Blade	2.00
Pedal Pad	1.00
Mac Battery Protect	1.00
Used Fire X Refurbished	1.00
Serpentine Belt	1.00
Bumper	2.00
cooler wire rack	1.00
Bulb	1.00
4 Led S T T Lamp	2.00
Shop Supplies	1.00

Hours 10.00 Labor: 600.00 Parts: 490.46 Total: 1,090.46
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1612645	Meter: 76347	In Date: 12/09/2016	Closed: 12/12/2016
Problem: Build weed eater bracket			
- Fab weed eater rack		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 3.00	Labor: 180.00	Parts: 2.00	Total: 182.00
:			
Workorder: 1612825	Meter: 76520	In Date: 12/15/2016	Closed: 01/02/2017
Problem: Right front turn signal inop.			
- Replace right front signal light bulb.		Parts List	Qty
- Replace and rewire right front beacon lamp mounted on top of walk in topper.		Beacon	1.00
- Shop Supplies		Bulb	1.00
		Shop Supplies	1.00
Hours 2.00	Labor: 120.00	Parts: 179.81	Total: 299.81
:			
Workorder: 1700318	Meter: 76769	In Date: 01/11/2017	Closed: 01/23/2017
Problem: Left front turn signal inop.			
- Replace left front signal light bulb.		Parts List	Qty
		Bulb	1.00
		Light Socket	1.00
Hours 0.50	Labor: 30.00	Parts: 11.51	Total: 41.51
:			
Workorder: 1701594	Meter: 77209	In Date: 02/15/2017	Closed: 02/23/2017
Problem: Right rear beacon strobe inop.			
- Repair wiring for right frear beacon light.		Parts List	Qty
- Shop Supplies		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1702954	Meter: 77860	In Date: 03/23/2017	Closed: 04/04/2017
Problem: Replace hitch step .			
- Replace hitch mounted step.		Parts List	Qty
- Shop Supplies		Bully Hitch Step	1.00
		Shop Supplies	1.00
Hours 0.25	Labor: 15.00	Parts: 55.21	Total: 70.21
:			
Workorder: 1703834	Meter: 78609	In Date: 04/14/2017	Closed: 04/27/2017
Problem: Replace rusted cooler holder.			
- Fabricate and install cooler holder on right rear per costomer request.		Parts List	Qty
- Shop Supplies		Water Cooler Holder	1.00
		Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 104.26	Total: 164.26
:			
Workorder: 1703984	Meter: 78260	In Date: 04/13/2017	Closed: 04/20/2017
Problem: Winch Out			
- Tow From: On Jog rd Betwn Hood and Donald ross			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1704542 **Meter:** 79212 **In Date:** 05/05/2017 **Closed:** 05/11/2017

Problem: Left front strobe light inop.Rear marker light strip loose.Ddoor latch clip missing.

	Parts List	Qty
- Replace and rewire left front roof mounted strobe lamp.	Strobe	1.00
- Replace retainer clips for rear door latch rods.	Rod Clip	2.00
- Shop Supplies	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 262.10
:		Total: 352.10

Workorder: 1705639 **Meter:** 80242 **In Date:** 06/07/2017 **Closed:** 07/06/2017

Problem: P.M. Service.Battery light stays on.

	Parts List	Qty
- P.m. Service.	Cond/evap Cleaner 1gal	1.00
- Recharge batteries and test charging system.replace bad alternator.	License Bracket W/light	1.00
- Replace worn out rear cab mounts.	15-40 Oil	15.00
- Replace two tires,rotate and balance all six.	Napagold Oil Filter	1.00
- Replace rewar shocks.	Fuel Filter Ford Only	1.00
- Clean and flush evaporator coils to increase air flow.	Used Fire X Refurbished	1.00
- Shop Supplies	20" Wiper Blade	2.00
	Body Mount Kit	2.00
	179636492 Lt245-75r17	2.00
	Gas Grande Shock	2.00
	alternator	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 14.00	Labor: 840.00	Parts: 1,448.67
:		Total: 2,288.67

Workorder: 1706944 **Meter:** 80509 **In Date:** 07/14/2017 **Closed:** 07/20/2017

Problem: Check lights.

	Parts List	Qty
- Replace right front signal light bulb,two roof marker bulbs,left rear marker lamp and center rear marker strip.	Bulb	1.00
- Shop Supplies	Bulb	2.00
	Led Lamp	2.00
	M C Base Mount Kit	1.00
	Shop Supplies	1.00
Hours 1.50	Labor: 90.00	Parts: 51.40
:		Total: 141.40

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710359	Meter: 81556	In Date: 10/20/2017	Closed: 10/31/2017
Problem: Emergency beacon light out.			
- Inspect and replace defective right rear roof beacon strobe lamp with new.	Parts List		Qty
	Strobe Lp Led		1.00
- Load test both batteries. Recharge batteries but would not hold charge.replace both defective batteries with new.	Battery		2.00
	Strobe		1.00
- Diagnose fuel level sensor with scan tool for codes B1204 fuel sender short to ground. Self test and verified failed fuel sender.r&r primary front fuel tank and replace fuel level sensor with new.clear codes after passing retest.	Sender Assembly		1.00
	Fuel Tank Repair		1.00
- Shop Supplies	Shop Supplies		1.00
Hours 7.50	Labor: 450.00	Parts: 869.41	Total: 1,319.41
:			
Workorder: 1710983	Meter: 81616	In Date: 11/03/2017	Closed: 11/21/2017
Problem: Install 2 new water racks, Both walk in cab doors are jammed.			
- Install two new water cooler racks .force entry in rear doors .cut lower latch assembly due to objects jammed into latch.replace latches and adjust.	Parts List		Qty
	Rotary Latch		1.00
- Shop Supplies	Rotary Latch		1.00
	Water Keg Holder		2.00
	Clr Rtv Silcn Sealant		1.00
	Shop Supplies		1.00
Hours 3.00	Labor: 180.00	Parts: 253.37	Total: 433.37
:			
Workorder: 1711343	Meter: 81616	In Date: 11/16/2017	Closed: 11/28/2017
Problem: weld utility body door latch			
- We;ld Rear Door Latch	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.00	Labor: 60.00	Parts: 2.00	Total: 62.00
:			
Workorder: 1800093	Meter: 82188	In Date: 01/03/2018	Closed: 01/04/2018
Problem: Right front turn signal inop.			
- Test and replace right front turn signal bulb.retest.	Parts List		Qty
	Bulb		1.00
Hours 0.50	Labor: 30.00	Parts: 0.77	Total: 30.77
:			
Workorder: 1800782	Meter: 82417	In Date: 01/23/2018	Closed: 01/29/2018
Problem: Remove weed eater holder			
- remove bracket	Parts List		Qty
- Shop Supplies	Shop Supplies		1.00
Hours 1.50	Labor: 90.00	Parts: 2.00	Total: 92.00
:			
Workorder: 1804223	Meter: 82417	In Date: 04/24/2018	Closed: 04/24/2018
Problem: Transition Prep Charge			
- Transition Prep Charge			
Hours 2.00	Labor: 120.00	Parts: 0.00	Total: 120.00
:			