Palm Beach County Fleet Management Asset Maintenance History

10196255 2014 CLUB CAR CARRYALL 295 Utility Cart, All Terrain, 4X4, Diesel

	1408555 install hitch ex	Meter: xt.	1			In Date:	08/26/2014	Closed:	08/29/20	014
- parts only hi	tch				Parts Lis	st				Qty
- Shop Suppli					Ball Mou	int 3/4"				1.00
					Receiver	r Extension				1.00
					Pin W/cli	ip 5/8 For ⊢	litch			2.00
					Hitch Pir	n Lock				1.00
					Shop Su	pplies				1.00
	Hour :	rs 0.00		Labor:	0.00	Parts:	109.56	Total:	109.56	
Workorder:	1408851	Meter:	1			In Date:	09/03/2014	Closed:	09/03/20	014
Problem:	1061 - Pre De	ivery Insp	pection							
- Pre Delivery	Inspection									
	Hour :	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	1411713 install windsh	Meter: ield	114			In Date:	11/19/2014	Closed:	12/19/20	014
- Install winds	hield kit				Parts Lis	st				Qty
- First Service	9				Fold-dov	vn Windshie	eld Kit			1.00
- drive train flu	uid update				Napagol	d Oil Filter				1.00
- Shop Suppli	es				15-40 O	il				3.00
					Mobil 42	4 Fluid				3.00
					Shop Su	pplies				1.00
	Hour :	rs 4.50		Labor:	270.00	Parts:	264.55	Total:	534.55	
Workorder: Problem:	1511327 pm service	Meter:	661			In Date:	11/04/2015	Closed:	11/09/20	015
- Pm with driv	e train service				Parts Lis	st				Qty
- Replace I/tai	il lamp bulb				Napagol	d Air Filter				1.00
- Shop Suppli	es				Napagol	d Oil Filter				1.00
					Fuel Filte					1.00
					15-40 O					3.00
					Mobil 42	4 Fluid				4.00
					Bulb					1.00
					Shop Su	•••	70.00	- / I	400.00	1.00
	Hour :	rs 5.50		Labor:	330.00	Parts:	76.93	l otal:	406.93	
Workorder:	1511590 no start/ no po	Meter: ower	662			In Date:	11/12/2015	Closed:	11/18/20	015
Problem:	- Ck wont start. Ck electrical sys found main fuse blown,,				Parts Lis	st				Qty
- Ck wont star		L L L L L L								
- Ck wont star	and repaired s	hort in har	ness to alte	rnator	Shop Su	pplies				1.00

Palm Beach County Fleet Management Asset Maintenance History

Workorder: 160 Problem: nee	4664 ds 3 keys	Meter:	713			In Date:	05/03/2016	Closed:	05/24/20	016
- Secure keys for	dept				Parts Li	st				Qty
- Shop Supplies				Diesel Key Set					3.00	
					Shop Su	ipplies				1.00
	Hours	s 0.50		Labor:	30.00	Parts:	29.23	Total:	59.23	
Workorder: 161 Problem: pm/	0981 trans issue	Meter:	1340			In Date:	10/24/2016	Closed:	11/21/20	016
- Pm					Parts Li	st				Qty
- To hector turf for	rear end a	nd hub wa	arranty		Napago	d Air Filter				1.00
- Replace R/outer	Cv Boot				Napago	d Oil Filter				1.00
- Replace 4 tires					15-40 C	Dil				3.00
- Replace r/side ta	il lamp bulk	C			Mobil 42	4 Fluid				2.00
- Shop Supplies					L/f Outer Cv Boot					
					25 X 11	00 X 12 Tir	e Kenda			4.00
					Bulb					1.00
					Napa Fu	iel Filter				1.00
					Shop Su	ipplies				1.00
					Tire Dis	oosal Fee				4.00
	Hours :	9.00		Labor:	540.00	Parts:	1,078.68	Total:	1,618.68	3
Workorder: 161 Problem: star	2677 ting issues	Meter: / see note	1374 s			In Date:	12/12/2016	Closed:	12/14/20	016
- Test battery and	charging s	ys replace	battery		Parts Li	st				Qty
- R&r starter repla	ce worn so	lenoid cor	tacts in sta	rter	Battery					1.00
- Shop Supplies					Shop Su	pplies				1.00
	Hours	3.00		Labor:	180.00	Parts:	125.84	Total:	305.84	
Workorder: 170 Problem: nee	9912 ds 2 spare	Meter: keys	2128			In Date:	10/11/2017	Closed:	10/16/20	017
- Secure keys for	Dept				Parts Li	st				Qty
2	•				Diesel K					2.00
	Hours :	s 0.50		Labor:		•	18.15	Total:	48.15	

Palm Beach County Fleet Management Asset Maintenance History

Workorder: 1800267 Meter: 2256 Problem: pm/ will not move when put into gear			In Date:	01/08/2018	Closed:	02/06/2018		
- Pm		Parts Lis	st			Qt		
- Replace 4 tires		Bearings				1.0		
- Repalce frt and rear brake pads and rotors		Belt				1.		
- Replace rear hubs and bearings on both sides		Napa Qt	15w40		3.0			
- Ck Won't go into gear, replace broken drive belt		Napagolo	d Oil Filter		1			
- Shop Supplies		Napagolo	Air Filter		1.0			
		Napa Fue	el Filter			1.0		
		Mobil 424	1 Fluid			4.0		
		Glos Blk				1.0		
		25 X 11.0	00 X 12 Tir	e Kenda		2.0		
		Brake Ro	otor			4.0		
		295 Rear	Brake Pa	d Kit		2.0		
		Non-chlo	r Brake Clr		2.0			
		Bearings				1.0		
		Wheel Hu				2.0		
		25 X 11.00 X 12 Tire Kenda				2.0		
			eld For Axl		2.0			
		Shop Sup			1.0			
		Tire Disp				4.0		
Hours 14.00 :	Labor:	840.00	Parts:	1,918.42	Total:	2,758.42		
Workorder: 1803065 Meter: 2282 Problem: alternator smoking, wire popped off			In Date:	03/22/2018	Closed:	04/04/2018		
- check over cart. engine problems, not cost effective	Parts Lis	st		Q				
repair - Shop Supplies		Shop Sup	oplies			1.0		
Hours 1.00 :	Labor:	60.00	Parts:	2.00	Total:	62.00		
Workorder: 1804192 Meter: 2282			In Date:	04/23/2018	Closed:	04/23/2018		
Problem: Transition Prep Charge								
- Transition Prep Charge								
Hours 2.00	Labor:	120.00	Parts:	0.00	Total:	120.00		