Repair History

#19675



VehicleNun			del Yea	r Models	Assigned To:	CCW
428-38	428	-38 20	07	Crown Victoria	olivestri, Gino	CS428
Entry Date	WO#	Odomete	r Activi	ty Description	Details	Cost
2/23/16	26827	143,991	5K	Auto Gen 5K		\$9.30
10/31/15	25853	139,269	5K	Auto Gen 5K	Autogen LOF	\$9.30
7/10/15	24902	134,633	5K	Auto Gen 5K	Autogen LOF	\$9.30
3/13/15	24002	129,883	5K	Auto Gen 5K	5k service	\$15.28
10/31/14	22910	125,291	5K	Auto Gen 5K	5K Service	\$9.30
7/11/14	21939	121,337	5K	Auto Gen 5K	5k service	\$15.28
2/11/14	20764	115,987	5K	Auto Gen 5K		\$15.09
8/28/13	19427	111,279	5K	Auto Gen 5K	Autogen 5k SRS Light On	\$15.09
4/25/13	18105	107,454	5K	Auto Gen 5K	Autogen 5k Rear tires	\$200.57
12/26/12	17077	102,047	5K	Auto Gen 5K		\$15.09
8/28/12	16042	97,081	5K	Auto Gen 5K	5k cupholder in center ashtray broken.	\$189.21
5/16/12	15015	92,494	5K	Auto Gen 5K	Autogen 5k	\$15.09
2/2/12	14012	87,961	5K	Auto Gen 5K		\$25.75
9/19/11	12431	82,517	5K	Auto Gen 5K	Autogen 5k	\$40.80
6/27/11	11514	79,455	*		Tires worn, dead battery, power steering is hard	\$393.35
5/17/11	11093	78,411	5K	Auto Gen 5K	Autogen 5k	\$33.99
5/3/11	10934	74,822	6.0	To 18	Brake Light Switch	\$178.01
2/7/11	9865	73,259	5K	Auto Gen 5K	Autogen 5k	\$19.56
9/23/10	8436	69,063	5K	Auto Gen 5K	Autogen LOF, brake rotors, replace fuse for power supply in trunk, install power lead next to police radio	\$130.83
8/25/10	8202	67,617			Brakes make noise	\$115.15
7/15/10	7864	65,849		· · · · · · · · · · · · · · · · · · ·	Install additional lighting,	\$0.00
7/12/10	7843	65,825	S E	BV and an an an	Over Heats when vehicle is not moving: possible fan motor	\$384.89
6/1/10	7478	64,485	5K	Auto Gen 5K	Autogen LOF, wipers	\$32.99
2/11/10	6442	59,390	5K	Auto Gen 5K	Autogen LOF	\$27.87

VehicleNun	n ID	Model Year		Models	Assigned To:	CCW
Entry Date	WO#	Odometer	Activity	Description	Details	Cost
10/26/09	5513	55,025	5K	Auto Gen 5K	Autogen Lof, door lock inoperable pass side, rattling noise in door	\$27.87
9/14/09	5114	52,429	9		Brakes squeak and left turn signal 10-7	\$49.99
7/20/09	4736	50,129		Needs Tires and turn signal blinks too fast	Replace tires, uneven wear and poor ride. Check turn signals	\$332.58
7/8/09	4693	20,123			Maint Oil Change	\$27.87

\$2,339.40