

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V34167

In Date: 08/10/2010 Close Date:

08/27/2010

SRS warning on - unknown; went off w/key cycle cold

not getting back on.

1,285.00 Meter Reading:

Problem?

B inspection New vehicle prep R43

Task performed:	Parts	Quantity
B-Service 2. Mntd eqmpt in cab, pat compt, L-2 & L-3 compt.	101-124-000CRASH RESTRAINT STRAPS	1
	14-7014HGR-1 HELMET HOOK	4
3. Rem lights, SCBA holders, air horns, etc. for decal installation.	1878042C91FUEL FILTER 2008 HORTON	1
4. Reinstalled all previously rem parts/components;	5269LPVM-5 SM MOUNT	8
required by decal/striper.	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
5. R/R officers seat to go out to upholstery shop.	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
6. Change btrys arnd so neg term are facing out.	KD-UN-5-SFUSE 6-SF BRACKET	1
7. T-shoot SRS code & door open alarm; Horton warranty tech will rep on 8/24/10. ja	L PLACARDLARGE SIDE PLACARD	2
tech will report 6/24/10.	LPVM-7LG MOUNT	2
	S PLACARDFRONT AND BACK PLACARD	1
	UMVS162511STRAP	5
	UMVS254411STRAP 46 IN	1
Close Date: 09/07/2010 Problem? install striker gaurds on paitent doors R43		
Task performed:	Parts	Quantity
Install guards ovr Nader pines at rear entry doors. js	NO PARTS USED	
Workorder: V35056		
In Date: 09/20/2010 Meter Reading: 2,3°Close Date: 09/28/2010 Problem? on call srs warning on r43	17.00	
Task performed:	Parts	Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35051

In Date: 09/20/2010 Meter Reading:

Close Date: 10/20/2010

Problem?

Task performed:

repaired wheel on stretcher. jab

1. o2 alarm going off, check and repair broken wire at o2

2. stretcher lock inop. readjusted stretcher lock and

adjust o2 braket to fit bottle R43

Task perform	ned:			Parts	Quantity
Rem O2 bottl j	e from truck & b	rkt; readj brkt & reinstalled	d	NO PARTS USED	
Workorder:	V34599				
In Date: Close Date: Problem?	08/30/2010 10/21/2010	Meter Reading:	1,258	.00	
The new res	scue does not ha	ave a mic for the siren/pa	systen	n. R43	
Task perforn	ned:			Parts	Quantity
1. install mike	e clip and repair.	. jab		NO PARTS USED	
Workorder:	V34686				
In Date: Close Date: Problem?	09/02/2010 10/21/2010	Meter Reading:	1,258	.00	
The rear co		below the rear pt compars somthing wrong with the		doors keeps opening while the truck is driving down the ro. r43	oad causing
Task perform	ned:			Parts	Quantity
	r compartment d air leak, repaired	oor latch on I1 d small air leak on air tank	ζ.	NO PARTS USED	
Workorder:	V34687				
In Date: Close Date: Problem?	09/02/2010 10/21/2010	Meter Reading:	1,258		
The oxygen way and is		ver time the oxygen is tur	ned or	n showing low pressure in the system. The main oxygen is	open all the

Parts

NO PARTS USED

Quantity

2,317.00



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V35405

In Date: 10/04/2010

Close Date: 10/27/2010

Meter Reading: 3,317.00

Problem?

The rumbler on the driver side, bracket broke causing the rumbler to fall and break. The rumbler was found hanging by the wire ur the unit. The broken piece is in the office at sta 43.

Task performed: Parts Quantity

ontacted Hallmark for Warranty repair. j NO PARTS USED

Workorder: V35930

In Date: 10/26/2010 Meter Reading: 3,317.00

Close Date: 11/03/2010

Problem?

R43 low volt alarm

Task performed: Parts ____ Quantity

Call out - Low volt alarm btrys weak & actuater not charging; replc actuator & btrys; had to come to shop for

parts.

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

3

3

HP-31DBATTERY 950CCA HP-31D

Faulty btrys - replc; alt also faulty; repl alt which will be warranty ticket. j

Workorder: V35932

In Date: 10/26/2010 Meter Reading: 4,381.00

Close Date: 11/05/2010

Problem?

CHARGING SYSTEM 10-7 R43

Task performed: Parts Quantity

Low volt alarm sounding; charging sys diagnostics show 11.0 volts w/eng running; R/R alt & alt pulley; run eng & rechk volt; now at 14.0 volts; all ok.

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V36108

In Date: 11/02/2010 12/13/2010 Close Date:

Meter Reading:

4,778.00

Problem?

repair air leak r43

Task performed: **Parts** Quantity

NO PARTS USED

(1) TRAVELED TO STATION 43 TO REPAIR AIR LEAK ON R43. FOUND LEAK AND REPAIRED AT MAIN AIR

TANK.

(2) READJUSTED LATCH ON THE STRETCHER OF R43 DUE TO **BEING HARD** TO OPEN.

J.W.

Workorder: V36371

In Date: 11/11/2010

12/16/2010

5,245.00 Meter Reading:

Close Date: Problem?

> Green LED lamp on exterior indicator panel for shoreline charging is not lighting up. We know the cord works and breaker is not tripped... either the LED is burnt out or the truck is not charging off the shoreline?!?!? R43

> Task performed: Quantity

(1) TRAVELED TO ST43 TO CHECK OUT PROBLEM WITH SHORELINE CHARGING GREEN LED LIGHT FOR R43. REPLACED CHARGER LIGHT. OK.

J.W.

NO PARTS USED

Workorder: V35406

In Date: 10/04/2010 Meter Reading:

12/22/2010 Close Date:

Problem?

The air horn pedal on the dirvers side sticks causing the air horn to stay on until the air pressure runs out. R43

3,317.00

Task performed: Quantity **Parts**

(1) air horn sticks on causing horn to stay on until air pressure run out.

repaired air horn switch.ok.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder:	V35493
------------	--------

In Date: 10/07/2010 Close Date:

12/22/2010

Meter Reading: 3,317.00

Problem?

compartment 7 door latch working poorly. Activating alarm and opening on own. R43

Task performed:	Parts	Quantity
(1) TRAVELED TO ST43 TO CHECK OUT DOOR OF COMPARTMENT 7 ON R43 FOR ACTIVATING DOOR ALARM. REPAIRED THE REAR DOOR LATCH AND ADJUSTED THE DOOR. ALL TESTED OK. J.W.	NO PARTS USED	
Workorder: V37248		
In Date: 12/18/2010 Meter Reading: 7,41 Close Date: 01/11/2011 Problem?	1.00	
Rear "bench" and "cot" lights could not be controlled on the stuck on high)seems to be an intermittent problem??? R4	·	f they were
Task performed:	Parts	Quantity
Chkd opn of lights & tested ok. j	NO PARTS USED	
Workorder: V37247		

12/18/2010 In Date: Meter Reading: 7,411.00

Close Date: 02/07/2011

Problem?

O2 reads 0.0 psi in front cab, however gauge on feed line reads 2000 psi (front cab read out was just working prior to changing ou bottles... it read 567.4, then 506.7 after a few transports now won't register psi R43

Task performed:		Parts	Quantity
O2 alarm inop; replc alarm sensor & tested unit.	j	AST4000ASENSOR O2 REGULATOR	1
		MNT587148Z671 ALARM CARBON MONOXIDE	1



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V37704

In Date: 01/10/2011 Close Date:

02/22/2011

Meter Reading:

9,351.00

Problem?

C INSPECTION AND REPAIRS AS NEEDED R 43

Task performed:	Parts
(1) "C" INSPECTION AND NEEDED REPAIRS.	15W40BSYN OIL BULK QTS
(2) START TROUBLE SHOOT NO HIGH IDLE. HOOKED UP LAP TOP WITH ED FROM	1878042C91FUEL FILTER 2008 HORTON
INTERNATIONAL AND CHECKED OUT PROBLEM.	2506656C124316 WIX CAB A/C FILTER
SHOWED PROBLEM IS ON HORTON SIDE.	5774457744XD OIL FILTER
J.W.	

Workorder: V38471

In Date: 02/13/2011 Close Date:

02/24/2011

11,216.00 Meter Reading:

Problem?

The low pressure alarm for the tires in the cab keeps beeping the left rear tire sensor is missing. I checked all the tires and the sensors are all there. can you please have someone check this out. R43

Task performed:	Parts	Quantity
1. Reprogramed unit & tested.	NO PARTS USED	
2 Δ/C warm: tested & was cool at this time i		

12,026.00

Workorder: V38705

In Date: 02/22/2011

Close Date: 02/28/2011

Problem? siren quit working R43

Task performed:		Parts	Quantity
Siren head NG; R/R unit; tested ok.	j	295SLSA1SIREN	1

Workorder: V39702

04/05/2011 In Date: 15,098.00 Meter Reading:

05/05/2011 Close Date:

Problem?

Rescue 43 needs power steering fluid. We have none in the station

Meter Reading:

Task performed:		Parts	Quantity
Dropped off fluid & chkd for leaks.	j	L PLACARD INSERTLARGE PLACARD INSERT CARD	5



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V40486

In Date: 05/09/2011 Close Date:

05/16/2011

Meter Reading: 17,215.00

Problem?

Close Date:

Task performed:

08/05/2011

Contacted Horton for WARRANTY repair

rubber boot has a water leak between the cab and the box R 43

B INSPECTION AND REPAIRS AS NEEDED R 43

Task perforr	med:			Parts	Quantity
	polts; reset drive t A/C filters; R/F j	ers breakaway. R wiper blades; clnd pat	A/C	1501450007750USE 0775145 1878042C91FUEL FILTER 2008 HORTON 2506656C124316 WIX CAB A/C FILTER 5774457744XD OIL FILTER 91-22WIPER BLADE	3 1 1 1 2
Workorder: In Date: Close Date: Problem? A/C 10-7 Re	V40703 05/18/2011 05/25/2011 43	Meter Reading:	17,612	2.00	
Task perforr	med:			Parts	Quantity
R/R blower m R/side; replc		h of rescue; R/R dash p	anel	3674285C1BLOWER MOTOR	1
Workorder:	V40964				
In Date: Close Date: Problem? On R-43 in	05/30/2011 06/28/2011 the pt. compart	Meter Reading: ment, the hinge is broke	18,000 en to com	p. door above the bench seat and nearest the side door.	
Task perforr	med:			Parts	Quantity
reparied brok	en hindge ak			NO PARTS USED	
Workorder:	V42478				
In Date:	08/01/2011	Meter Reading:	22,071	.00	

Parts

NO PARTS USED

Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V42138

In Date: 07/20/2011

Close Date: 08/08/2011

Meter Reading: 21,420.00

Problem?

A/C MALFUCTION IN FRONT CAB. NO AIR WORKING AT ALL. R 43

Task performed:	Parts	Quantity
a/c blower inop in cab no codes found power at blower motor r&r motor test a/c performance all ok	3674285C1BLOWER MOTOR	1
Workorder: V42137		
In Date: 07/19/2011 Meter Reading: 2 Close Date: 08/26/2011 Problem? 2	1,420.00	
the tire pressure gauge will not stop going off. The gau oxygen low air pressure in the line alarm keeps going		isors are on the tires. The
Task performed:	Parts	Quantity
Rem tire sensors & installed new style. j	RWTG1234LED PRESSURE CAP	4
Workorder: V42892		
In Date: 08/18/2011 Meter Reading: 2 Close Date: 08/26/2011 Problem? Replace all tires on vehicle.	3,130.00	
Task performed:	Parts	Quantity
Replc all tires on veh - Boulevard j	NO PARTS USED	
Vendor? BOULEVARD		
Workorder: V43098		
In Date: 08/27/2011 Meter Reading: 2 Close Date: 08/31/2011 Problem? 2	3,737.00	
Rubber boot btwn cab and Pt compartment is leaking control panel not good R43	like a seive from the top whenever it rains. Water	then leaks onto the rear a
Task performed:	Parts	Quantity
contacted halmark run warranty repair	NO PARTS USED	



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43170

In Date: 08/30/2011

Close Date: 09/06/2011

Meter Reading:

23,737.00

Problem?

Repair cab a/c.

replaced latch

Task perfori	med:			Parts	Quantity
1. Dia A/C sys w/laptop; cleared codes; test drove unit; rechkd codes; fnd that thermistor was bad; vac sys; changed bad part; recharged; chk ok. j		091-3YWCOVER KUSSMAUL AUTO EJECT 3622764C32606229C92 THERMISTER			
Workorder:	V43067				
In Date: Close Date: Problem?	08/25/2011 09/19/2011	Meter Reading:	23,55	5.00	
	oreline plug brok	e off when flipped oper	n. Sta 43		
Task perfori	med:			Parts	Quantity
replaced cap	for 110 a/c			NO PARTS USED	
Workorder:	V43097				
In Date: Close Date: Problem?	08/27/2011 09/19/2011	Meter Reading:	23,73	7.00	
Cab A/C sta		air if truck is in park and and idling. R43	d idling. l	f truck and batteries are turned off then back on again, it	t blows cold
Task perfori	med:			Parts	Quantity
checked a/c	and checked ok			NO PARTS USED	
Workorder:	V43118				
In Date: Close Date: Problem?	08/29/2011 09/19/2011	Meter Reading:	23,73	7.00	
stretcher m	ount lock mecha	anism malfunction, Sta	43.		
Task perfori	med:			Parts	Quantity



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43545

In Date: 09/09/2011 Close Date:

09/21/2011

Meter Reading: 24,675.00

Problem?

C INSPECTION AND REPAIRS R 43

Task performed:	Parts	Quanti
·		
C INSPECTION	1501450007750USE 0775145	2
REAR END OIL LEVEL LOW NO EXTERNAL LEAK	15W40BSYN OIL BULK QTS	26
ADD 2 QTS REAR END OIL	1847727C1BELT	1
	1878042C91FUEL FILTER 2008 HORTON	1
PT. COMP. A/C FILTERS 2 REMOVED TO INSTALL	2506656C124316 WIX CAB A/C FILTER	1
NEW FILTERS	2507061C1PS RESV GASKET	1
PT. COMP. UV BULB BLOWN REMOVE TO INSTALL	388863HOSE KIT	2
NEW UV BULB	388863-1HTR HOSE SHUT VALVE NEW HORTONS	1
NEW OV BOLD	5-20PH1PGK4 CONNECTOR 120V 20A FEMALE	1
CAB REAR A/C FILTER SERVICE REMOVE AND	5774457744XD OIL FILTER	1
INSTALL NEW FILTER	607141-05USE 61H01 COPMPARTMENT LIGHT	1
WINDSHIELD WIPER BLADE SERVICE BUG	75W90GEAR OIL SYN QT	2
SOLVENT AND WATER TOP OFF	78R539018-2699 A/C FILTER	1
COLVENT / WE WATER FOR CIT	91-22WIPER BLADE	2
HEATER HOSE INSTALLED COOLANT SHUT OFF	GPX13ULTRA VIOLET LIGHT SHORT	1
VALVE A/C NOW BLOWING AT 26 DEGREES	K060705BELT HORTON	1
POWER STEERING FLUID AND FILTER SERVICE	VML/T1808D2503221C1 FILTER POWER STEERING	1
BATTERY LOW VOLTAGE AT IDEL 13 UVFOUND LOOSE GROUND AT BATTERY SWITCH AND CHASSIE SHUNT CLEAN AND SECURE FASTEN		

LOOSE GROUNDS A/C BELT SERVICE

ENGINE BELT SERVICE

PT. COMPT. OVERHEAD PADDING LOOSE SECURE LOOSE PADDING OVER BENCH SEAT TO UPPER **CABINET**

AIRHORN OUT OF TUNE ADJUST AIR HORN TONE

REMOVE -- TIRE PSI SYSTEM CHECK TIRES PSI AT 110 PSI AND INSTALL LED PRESSURE ---

QA TRUCK OK



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V43781

In Date: 09/20/2011 Close Date:

09/21/2011

Meter Reading:

24,596.00

Problem?

heard a pop, lost all power ,truck travels at 30 mph top speed.

Parts Task performed: Quantity

1. Mass air hose came loose; secure hose; chk for

thread code; test drive.

NO PARTS USED

2. Assist w/t-shooting.

Workorder: V43501

In Date: 09/07/2011

Meter Reading: 24,565.00

10/03/2011 Close Date:

Problem?

Hinge for storage compartment door, inside patient compartment, above bench seat is still broken r 43

Task performed: **Parts** Quantity

repaired hinge and tested NO PARTS USED

Workorder: V43552

In Date: 09/09/2011

Close Date: 10/04/2011

24,596.00 Meter Reading:

Problem?

Replace body mounts.

Task performed: Quantity

remove stair chair compartment to gain access to 2 rear body mounts jack up and seperate one side at a time and change mounts reassemble and torque all nut and

bolts, reinstall stair chair compartment

RWTG1234LED PRESSURE CAP

6

Workorder: V43625

09/13/2011 In Date: Meter Reading: 24,596.00

10/04/2011 Close Date:

Problem?

TORQUE ARM BUSHINGS 10-7 R 43

Task performed: **Parts** Quantity

REMOVE TORQUE AM FOR BUSHING REPLACEMENT, REMOVE SHOCK ABSORBERS, REMOVE SHOCK MOUNT, REMOVE LEVELING ROD, INSTALL TORQUE ARM, REASSEMBLE ALL PARTS TO SECURLY TORQUE ALL NUTS AND BOLTS



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44126

10/03/2011 In Date: Close Date:

10/05/2011

Meter Reading:

25,571.00

Problem?

locking mechanism for the stretcher, is not locking and is loose. R 43

tire sensors replaced removed system for tires an

installed new valve stems

T1				Posts	0
Task perfor	med:			Parts	Quantity
strecher lock	broken replace	strcher lock		0567042LONG STRECHER BAR	1
	arge replace the	ault 1548 for a/c ther ermostat charge and t		3622764C32606229C92 THERMISTER	2
Workorder:	V44044				
In Date: Close Date:	09/30/2011 10/06/2011	Meter Reading:	25,23	9.00	
Problem? A/C, interm	itant malfunctio	n. Same problem sub	mitted in I	BEM on the morning of the 28th. Sta 43.	
Task perfor	med:			Parts	Quantity
A/C repaired	on WO 44126	j		NO PARTS USED	
Workorder:	V43979				
In Date: Close Date: Problem?	09/28/2011 10/07/2011	Meter Reading:	25,09	0.00	
				is running for a while the a/c begins to blow warr Problem noticed 2230 hr, Sta 43.	n. If you turn the truck
Task perfor	med:			Parts	Quantity
repaired a/c	110 on cord tha	t was melted		RWTG1234LED PRESSURE CAP	4



12/17/2018

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44350

In Date: 10/12/2011 Close Date:

10/19/2011

Meter Reading:

Problem?

cab a/c blowing hot R 43

Cab a/C bio	WING HOUR 43			
Task perfor	med:		Parts	Quantity
CLEANED (COM BAD, F CLEANER, DRIER AND	CONNECTIONS RECOVER FRE COMPVAL	THE MISTER CODER, S, INSTALLED GAUGES, ON, REMOVED BELT, AIR VE, REPLACED COMP, E, FLUSHED, VAC AND CODES	3611894C9103-0805 A/C COMPRESSOR 4347 3660853C22512331C1 EXP VALVE NAV 3670134C1ACCUMULATOR ASSY INT.	1 1 1
	10/10/2011 10/21/2011 t compartment /	,	27.00 ugged in to the shoreline at the station. It sounds like t 43	the motor is not
Task perfor	med:		Parts	Quantity
repaired 110	a/c fans and te	sted	NO PARTS USED	
repaired side	door that was	nard to open		
Workorder:	V44382			
	10/14/2011 11/07/2011 ne problem with s not running pr		I into shoreline the pt compartment a/c blows but not c	old. It sounds as
Task perfor	med:		Parts	Quantity
-		FANS AND TESTED	NO PARTS USED	_
Workorder:	V44404			
In Date: Close Date:	10/15/2011 12/02/2011	Meter Reading:		

Problem?

R43 shoreline A/C blowing hot air. R43 taken in 2 days prior for same issue was thought to be fixed.

Task performed: REPLACED CONDENSOR FANS

NO PARTS USED

Quantity

Parts



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44997

11/06/2011 In Date:

Close Date: 12/02/2011

Problem?

Meter Reading:

Hindges is broken. Need s	screw for inside cabinet, v	vnere towels are kept. R43	
Task performed:		Parts	Quantity
replaced hinges		NO PARTS USED	
Workorder: V45027			
In Date: 11/07/2011 Close Date: 12/02/2011 Problem?	Meter Reading:		
The hinges on cabnet in the	ne pt compartment of R-4	3 broke off. The cabnet will not open or close. Sta	a 43.
Task performed:		Parts	Quantity
replaced hinge		NO PARTS USED	
Workorder: V45233			
In Date: 11/16/2011 Close Date: 12/02/2011 Problem?	Meter Reading:		
Right rear loading light bu	rned out. sta 43.		
Task performed:		Parts	Quantity
repaired ground wire		NO PARTS USED	
Workorder: V45559			
In Date: 12/01/2011 Close Date: 12/16/2011 Problem?	Meter Reading:		
Need Headlights. Sta 43			
Task performed:		Parts	Quantity
DROPPED OFF. HEADLIG	SHTS.	9007H9007 BULB ASSY	3

9007H9007 BULB ASSY



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V44366

In Date: 10/13/2011 Close Date:

01/03/2012

Meter Reading:

Problem?

Hinge on inside comartment door (above bench seat) is broken. Sta 43.

Task performed:	Parts	Quantity
repaired compartment door hinge	02841236CHROME HINGE HORTON	1
	HA24027HINGE EA	2

Workorder: V46168

In Date: 12/30/2011

01/04/2012 Close Date:

Meter Reading: 31,166.00

Problem?

R43 won't start

Task performed:	Parts	Quantity
TRUCK SLON CRANKING. LOAD EXTRA BATTERIES.	BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
FAILED LOAD TEST. REPLACE. CHECKED ACTIVE OUTPUT.	HP-31DBATTERY 950CCA HP-31D	3

Workorder: V45786

12/12/2011 In Date:

01/13/2012

Meter Reading:

29,940.00

Close Date: Problem?

back up light on rear light bar is 10-7 R43

Task performed:	Parts	Quantity
1. REPLACED REAR SCENE LIGHT.	10004858O2 SENSOR HORTON 0-3000	1

O2 SENSOR NOT WORKING - REPAIRED.

Workorder: V46072

In Date: 12/25/2011 30,314.00 Meter Reading:

Close Date: 01/13/2012

Problem?

the shoreline a/c blows warm air when pluged in. Sta 43

Task performed:	Parts		Quantity
Task performed:	Parts	C	auantity

1. REPAIRED 110-V A/C UNIT THAT WAS BLOWING

WARM.

NO PARTS USED

2. ADJUSTED REAR DOOR LATCH THAT WAS HARD

TO OPEN.



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V46271

In Date: 01/04/2012

Close Date: 01/13/2012

Meter Reading:

31,166.00

Problem?
No heat.

Task performed: Parts Quantity

TURN ON HEAT AND REPLACED VALVE. 10002298SOLENOID VAC A/C HEATER HORTON

1

Workorder: V46362

In Date: 01/06/2012 Close Date: 01/13/2012

01/06/2012 Meter Reading: 01/13/2012

31,166.00

Problem?

Coolant leak. Sta 43

Task performed: Parts Quantity

REPAIRED COLLANT LEAK. 2602872C91SURGE TANK 1

Workorder: V46371

In Date: 01/06/2012 Meter Reading: 31,166.00

Close Date: 01/13/2012

Problem?

The chrome cover that covers the lug nuts for the rear rim on the rescue was found missing. Can you pleases order us a new one

Thanks Lt J Garrow 43 c-shift

Task performed: Parts Quantity

TOOK OFF CROME COVERS.

NO PARTS USED

Workorder: V46447

In Date: 01/09/2012 Meter Reading: 31,893.00

Close Date: 01/23/2012

Problem?

the exhaust pipe is loose, Sta 43

Task performed: Parts Quantity

NO PARTS USED

1. REPAIRED GROUND LIGHTS AND MARKER

LIGHTS.

2. REPAIRED TWO GROUND LIGHTS THAT WERE

NOT WORKING.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V46584

01/15/2012 In Date: Close Date:

01/23/2012

Meter Reading: 32,348.00

Problem?

Engine coolant and power steering fluid are both below the add line and we have none at the station to fill them up. R43

Task performed: Quantity **Parts**

DROPPED OFF OIL AT STATION. **NO PARTS USED**



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

32,348.00

Parts

Workorder: V46674

In Date: 01/18/2012 Close Date: 01/31/2012

Meter Reading:

Problem?

B INSPECTION R 43

Task performed:

Quantity



PPORT

3 2 2

PROBLEM WITH UPDATE. WAIT FOR ED E. (RED LIGHT ON) REDO UPDATE STILL HAS ERROR INSTRUMENT CLUSTER NOT FOUND. OK PER ED E 19. REPLACE SCBA BRACKETS AND ADJUST FOR

20. ORDER MISSING O2 TRANSPUCER. FOUND OUT ONE WAS ORDERED FOR THIS VEHICLE AND SITTING IN TOMMY'S TRUCK. WILL GET FROM

21. INSTALL TRANSDUCER, SPLICE WIRING AND HEAT SHRINK CONNECTIONS. PROTECT WIRING AND TIE STRAP WIRES TO 02 LINE. 02 GAUGE READING CORRECTLY WITH TANK GAUGE BUT HAS

LIBRARY AND DUD FOR CALIBRATION INFO FOUND NO INFO. CALL HORTON SUPPORT FOUND 2ND TRANDSDUCER. DIAGNOSE NO POWER ON LINE

WARNING "O2 LINE LOW PRESSURE."

SCOTT BOTTLES.

TOMMY IN A.M. 1/27/12.



12/17/2018

Palm Beach County Fire Rescue **Fleet Maintenance Asset History** 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

O2. TRACE PROBLEM TO CPU PLUG TERMINAL. TERMINAL NOT LOCKED IN. INSTALL TERMINAL AND CHECK (OK).

22. DRIVE TO 43 PICK UP JEFF.

23. DIAGNOSE NUMEROUS AIR LEAKS.

24. REPAIR AIR LEAKS AT GOVONER FITTING, SEAT SUPPLY LINE AND TANK VALVE. INSTALL NEW FITTINGS ON ALL.

25. TRAVEL TO STA 43 AND DROP OFF RESCUE AND RETURN TO SHOP.

Workorder: V46889

01/27/2012 In Date: 32.602.00 Meter Reading:

02/03/2012 Close Date:

Problem?

the new scba bracket in the officers seat is broken. it appears to have a broken spring and will not lock or hold the air pack in the seat. R43

Task performed: **Parts** Quantity

NO PARTS USED

REPAIRED AIR BOTTLE HOLDER.

2. AIR LEAKS FOUND AND REPAIRED.

REPLACED LIGHT IN PT COMPT.

Workorder: V47034

02/02/2012 In Date: 33,140.00 Meter Reading:

02/03/2012 Close Date:

Problem?

SCBA bracket bottle stopper came off, Sta 43

Task performed: **Parts** Quantity

REMOVED BRACKET AND REPAIRED. NO PARTS USED

Workorder: V47239

In Date: 02/11/2012 33,946.00 Meter Reading:

Close Date: 03/06/2012

Problem?

the rear led red emergency light cover on the passenger side box is only held in with one screw and is about to fall off. Sta 43

Task performed: Quantity

REPAIRED LIGHT AND TESTED. NO PARTS USED



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V45887

12/15/2011 In Date:

Close Date: 03/12/2012

Meter Reading:

Task performed:

PRESSURE TESTED, FOUND NO LEAK AT THIS TIME

Workorder: V47509 In Date: 02/23/2012 Meter Reading: 34,753.00 Close Date: 03/13/2012 Problem? emgencey light oficer rear top loose. sta 43 Task performed: Parts Quant REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt cpmpartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. NO PARTS USED	Low coolant level below add level. Added approx	x 1 gallon of water to coolant resevoir. No leeks noted	d.
Workorder: V47509 In Date: 02/23/2012 Meter Reading: 34,753.00 Close Date: 03/13/2012 Problem? emgencey light oficer rear top loose. sta 43 Task performed: Parts Quant REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does now hen plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. NO PARTS USED Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Task performed:	Parts	Quantity
In Date: 02/23/2012 Meter Reading: 34,753.00 Problem? emgencey light officer rear top loose, sta 43 Task performed: Parts Quant REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. NO PARTS USED Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out		NO PARTS USED	
Close Date: 03/13/2012 Problem? emgencey light officer rear top loose, sta 43 Task performed: REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Workorder: V47509		
emgencey light oficer rear top loose. sta 43 Task performed: REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt cpmpartment is only held on by a screw and is falling off. The rear a/c does nowhen plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Close Date: 03/13/2012	34,753.00	
REPAIRED LIGHT THAT WAS HIT BY TREE. 6811813493LENS CLEAR 68-1181349-3 1 Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out			
Workorder: V47584 In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Task performed:	Parts	Quantity
In Date: 02/27/2012 Meter Reading: 34,936.00 Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt compartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	REPAIRED LIGHT THAT WAS HIT BY TREE.	6811813493LENS CLEAR 68-1181349-3	1
Close Date: 03/13/2012 Problem? The right rear red flashing light cover on the pt cpmpartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Workorder: V47584		
The right rear red flashing light cover on the pt cpmpartment is only held on by a screw and is falling off. The rear a/c does not when plugged into the shoreline. Sta 43 Task performed: Parts Quant 1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Close Date: 03/13/2012	34,936.00	
1. REPLACED LENS ON REAR OF TRUCK. 2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	The right rear red flashing light cover on the pt cp	ompartment is only held on by a screw and is falling	off. The rear a/c does not wo
2. CHECKED FOR COOLANT LEAK AND REPAIRED. Workorder: V47661 In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Task performed:	Parts	Quantity
In Date: 03/01/2012 Meter Reading: 35,253.00 Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out			
Close Date: 03/13/2012 Problem? Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Workorder: V47661		
Coolant level down approx. 1- 1.5 gal. of coolant. Per shop, water added and Tommy on his way down this a.m. to check out	Close Date: 03/13/2012	35,253.00	
	Coolant level down approx. 1- 1.5 gal. of coolant	. Per shop, water added and Tommy on his way dow	n this a.m. to check out the

Parts

NO PARTS USED

Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V47746

In Date: 03/05/2012

03/16/2012 Close Date:

Meter Reading:

35,473.00

Problem?

Coolant leak, low on coolant.

Task performed: **Parts** Quantity

PRESSURE TESTED NO LEAKS NO LEAK ON FLOOR. FOUND ONE SMALL HOSE CLAMP LEAKING

- REPAIRED AND TESTED.

NO PARTS USED

Workorder: V48166

In Date: 03/25/2012

Meter Reading: 04/16/2012 Close Date:

37,102.00

Problem?

The bracket that holds the airhorn in place on the drivers side has broken off.

Task performed: **Parts** Quantity

REPAIRED AIR HORN BRACKET. GRV1720244770R1 HORN SUPPORT BRKT 1

Workorder: V47922

03/13/2012 In Date:

Close Date: 05/14/2012 Meter Reading:

36,018.00

Problem?

paitient a/c 10-7 r 43

Task performed: **Parts** Quantity

INSTALLED NEW THERMASTATE. 32112THERMOSTAT HORTON RESCUES

Workorder: V48761

In Date: 04/19/2012 38,598.00 Meter Reading:

05/14/2012 Close Date:

Problem?

R43 very low coolant, and there is no back-up at the station.

Task performed: **Parts** Quantity

TOP OFF COOLANT AND REPAIRED LEAK. 502471801TRIGGER PARTNER SAW

FZ51368FEET RUBBER RAM-FAN

8

1



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V49427

In Date: 05/17/2012

05/17/2012 Close Date:

40,042.00 Meter Reading:

Problem?

on call check rear suspension R 43

Task performed: **Parts** Quantity

NO PARTS USED

OPERATOR COMPLAIN AIR SUSPENSION NOT WORKING - OPERATE AIR SUSPENSION WAS UNABLE TO GET SYSTEM TOFAIL UNIT IN SERVICE.

NO PROBLEM FOUND.

Workorder: V49220

In Date: 05/09/2012 Close Date:

05/25/2012

Problem?

a/c blowing warm R43

Task performed: Quantity **Parts**

39,640.00

REF. W.O. 49214. NO PARTS USED

Meter Reading:



12/17/2018

Palm Beach County Fire Rescue **Fleet Maintenance Asset History**

10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V49214

In Date: 05/09/2012

05/29/2012 Close Date:

Problem?

C INSPECTION R 43

39,640.00 Meter Reading:

Task performed:	Parts	Quantity
1. C-INSPECTION.	103385NDRAIN COCK	1
2. C-INSPECTION.	1501450007750USE 0775145	2
C-INSPECTION. SERVICE AIR DRYER.	1878042C91FUEL FILTER 2008 HORTON	1
5. ADJUST AIR BAGS.	211-2BULB	1
6. STRAIGHTEN AND ALIGN SQUAD SEAT LATCHES	2506656C124316 WIX CAB A/C FILTER	1
7. CHECK FOR COOLANT LEAKS. REPOSITION	46870AIR FILTER	1
HOSES ON EGR VALVE, TIGHTEN ALL HOSE CLAMPS.	5774457744XD OIL FILTER	1
8. CHECK A/C PULL DOWN SYSTEM FOUND 402		
LOW, CHECK FOR LEAK, TIGHTEN HIGH SIDE		
SCHRADER AND O-RING ON CONDENSER LEAKING.		
REPLACE O-RING.		

Workorder: V49677

SIDE STEP LIGHT.

In Date: 05/29/2012 Meter Reading: 40,677.00

CHECK FOR AIR LEAKS, REPLACE AUTO DRAIN

10. FIND GOOD USED TIRE IN BUILDING 3 MOUNT ON

11. REPLACE BULB IN ACTION LIGHT, REMOUND

06/01/2012 Close Date:

Problem?

12. QC.

CHECK REAR SUSPENSION R 43

ON TANK AND QUICK CONNECTS.

RIGHT FRONT OLD TIRE CUT.

Task performed: Quantity **Parts**

REAR SUSPENSION - CHECKED SUSPENSION AND OPERATION OF SUSPENSION, ALL TESTED OK.

NO PARTS USED

Workorder: V49922

In Date: 06/05/2012 Meter Reading: 41,311.00

06/08/2012 Close Date:

Problem?

automatic idle not working R 43

Task performed: **Parts** Quantity

1. NO PROBLEM WITH IDEL.

2. REPAIRED REAR DOOR THAT WAS HARD TO CLOSE.



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V49861

In Date: 06/04/2012

06/15/2012 Close Date:

Meter Reading:

40,677.00

Problem?

Rescue feels like its missing a cylinder/rough idle, and the read out on the dash says electrical fault

Task performed: **Parts** Quantity

CHECKED OUT ENGINE - FOUND UNIT RUNNING GOOD AT THIS TIME, JUST CAME BACK FROM A CALL - ROAD TESTED AND TESTED FINE/CHECKED OIL

NO PARTS USED

Workorder: V50091

06/12/2012 In Date: Meter Reading: 41,569.00

Close Date: 06/22/2012

Problem?

abs light on did not reset. elect fault in panel. R43

Task performed: **Parts** Quantity

ROAD TESTED FOUND NO LIGHT ON AND NO

CODES.

NO PARTS USED

V50201 Workorder:

06/18/2012 In Date: Meter Reading: 41,887.00

Close Date: 06/22/2012

Problem?

REPAIR AND REPLACE AIRBAGS ON REAR OF R43

Task performed: **Parts** Quantity

1. R&R BOTH REAR AIR BAGS, REPAIR LEAKS AT LEVELING VALVES ADJUST BAGS.

GUI1R11216GY1R11216 AIR BAG INT.

2

2. ASSIST IN AIR BAGS AND AIR LEAKS.

Workorder: V50191

06/18/2012 In Date: 41,887.00 Meter Reading:

06/25/2012 Close Date:

Problem?

ON CALL AIR LEAK R 43

Task performed: **Parts** Quantity

NO PARTS USED

ADJUSTED REAR LEAKING VALVES AND ROAD

TESTED ALL TESTED OK.

LEFT SIDE REAR AIR BAG WILL NEED TO BE

REPLACED.



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V50689

In Date: 07/09/2012

Close Date: 07/10/2012

Problem?

ON CALL A/C 10-7 R 43-

43.067.00 Meter Reading:

Task performed: **Parts** Quantity **PATIENT** COMPARTMENT A/C INOP/LINE 071601A07-0602A DRIER A/C 7118

BLOWN/REPAIRED A/C LINE AT SHOP NOT COOLING REPLACED ORING AND CLEANED CONDENSOR

STILLN OT COOLING PROERLY SWAPPED OUT.

Workorder: V50719

07/10/2012 In Date: Close Date:

07/12/2012

Meter Reading:

43,067.00

Problem?

REPAIR A/C R 43

Task perf	ormed:		

COMPARTMENT PATIENT A/C INOP/COMPRESSOR DEFECTIVE/REPLACED COMPRESSOR.

2. A-INSPECTION.

- 3. REAR BRAKES/WORN/REPLACE REAR BRAKES.
- REAR BRAKES/WORN/REPLACED 4. BRAKES.
- REPLACE REAR BRAKES/WORN/REPLACED REAR BRAKES.
- REPLACED ALL TIRES (6) /WORN/REPLACED ALL 6 TIRES.
- 7. REAR LOW TIRE PRESSURE LED INDICATORS ON OUTSIDE TIRES/NOT VISIBLE/INSTALLED VALVE **EXTEPERS** POINTED OUTSIDE AND REPLACED DEFECTIVE SENSOR.

Parts	Quantity
3757REAR DRUMS 3757X 3647X	2
559103-6537 MANIFOLD COMP 5779	1
577903-3673 COMP USE 5591 MANIFOLD	1
AMH-1AMH-1 VALVE EXTENSION	1
RWTG1234LED PRESSURE CAP	3
XK4034707OPMHD SHOF KIT 3/8 BEAM	2

Workorder: V50715

07/10/2012 In Date: Meter Reading: 43,067.00

Close Date: 07/17/2012

Problem?

B INSPECTION IOL CHANGE SERVICES

Task performed: **Parts** Quantity

B INSPECTION OIL CHANGE SERVICES NO PARTS USED

OIL CHANGE SERVICES Vendor?



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V50932

In Date: 07/17/2012 Close Date:

07/25/2012

Meter Reading:

43.067.00

Problem?

MAKE REPAIRS FROM B INSPECTION R 43

Task performed:

- HARD START ROUGH IDLE- ENGINE HARD STARTING AND IDLES ROUGH - CHECK OUT ENGINE CONNECT COMPUTER - FOUND LOW FUEL PRESSURE CODE - START ENGINE AND TAKE VEHICLE ON ROAD TEST TO CLEAR AIR FROM FUEL SYSTEM - WILL LET STAND TILL MORNING AND RETEST.
- 2. OIL LEAK -CHECK ENGINE FOR OIL OR FUEL LEAK AROUND INJECTOR PUMP - NO PROBLEM FOUND - WASH OFF FREON OIL THAT WAS LEFT FROM A PREVIOUS A/C LINE REPAIR.
- OIL LEAK -SLIGHT OIL SEAPAGE FROM P/STEERING RETURN LINE - WASH OFF OIL RESIDUE AND TIGHTEN CLAMP - RECHECK NOW OK.
- 4. AIR BAGS DON'T INFLATE REAR SUSPENSION -CHECK OUT PROBLEM - WORK REAR DOOR ACTIVATION SEVERAL TIMES - COULD NOT DUPLICATE PROBLEM ALL WORKS OK.
- 5. HEADLINER LOOSE CHECK OUT PROBLEM WITH HEADLINER AND FOUND NO PROBLEM.
- WIPER ARM ADJUSTMENT FOUND WIPER ARMS PIVOTS LOOSE IN COWLING - TIMING SET WRONG ON R/SIDE - RESET AND TIGHTEN PIVOTS.

Meter Reading:

Parts

Quantity

NO PARTS USED

Workorder: V51311

In Date: 08/02/2012

Close Date: 08/13/2012

Problem?

REPLACE ALL TIRES

Task performed:

Parts

43,812.00

Quantity

REPLACE ALL TIRES.

NO PARTS USED

BOULEVARD TIRE CENTE Vendor?



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51576

In Date: 08/13/2012

09/17/2012 **Close Date:**

Meter Reading:

windshield cracked passenger side, also left side, rear scene light out; R. rear tire stem has red flashing indicator R 43

Task performed: **Parts** Quantity 1. INSTALLED YELLOW HOOK AND REAR BARS. 1 100R4FOAM HOSE AS PER SAMPLE 2 6092036018J HOOK STRYKER

Workorder: V51935

In Date: 08/27/2012

Close Date: 10/01/2012

Problem?

Problem?

REAR PASSENGER A/C LEAKING WATER INSIDE TRUCK R 43

Meter Reading:

Task performed: Quantity **Parts**

FOUND WATER IN REAR FRM ROOF LEAKING

RESEALED ROOF.

NO PARTS USED

Workorder: V52667

In Date: 09/26/2012 Meter Reading:

10/16/2012 Close Date:

Problem?

fuel key on R43 needs to be replaced begining to break in half.

Task performed: Quantity **Parts**

AIR LEAK- READJUSTED AIR BAGS AND REPAIRED

ALL AIR LEAKS.

NO PARTS USED

Workorder: V52683

09/28/2012 In Date: Meter Reading: 47,306.00

10/16/2012 Close Date:

Problem?

water leaking in rear from a/c

Task performed: **Parts** Quantity

REPAIRED DRAIN TUBES AND TESTED UNIT.

READJUSTED REAR LEVING VALVES.



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53067

In Date: 10/14/2012

11/09/2012 **Close Date:**

Meter Reading:

Problem?

Driver side rear scene light is out R 43

Task performed: **Parts** Quantity REPLACED LIGHT. NO PARTS USED Workorder: V53276 10/24/2012 In Date: Meter Reading: 48,705.00 Close Date: 11/16/2012 Problem? A/C leaking in cab R43 Task performed: **Parts** Quantity REPAIRED DRAIN LINE IN REAR OF RESCUE. NO PARTS USED Workorder: V53434 10/31/2012 In Date: Meter Reading: 48,705.00 Close Date: 11/16/2012 Problem? Check engine for low coolant, pressure test R43 Task performed: **Parts** Quantity TRAVEL TO ST 43 FOUND MISSING RADIATOT CAP 1 F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT ON R43. Workorder: V53593 11/07/2012 In Date: Meter Reading:

11/30/2012 Close Date:

Problem?

Light box bulb not working r43

Task performed: **Parts** Quantity

REWIRED LIGHT BOXES. NO PARTS USED



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53982

In Date: 11/26/2012

Close Date: 12/26/2012

5,104.00

Meter Reading:

Problem?

the front seat scha cover that covers the airpack bracket to the rear of the seat has damaged snaps that needs to be replaced. Ry

the none se	at scha cover the	at covers the airpack bracket	to the real of the seat has damaged shaps that needs to be	replaced. IX
Task perfor	med:		Parts	Quantity
REPAIRED S BRACKET.	SEAT COVER A	ND ADJUSTED AIR PACK	NO PARTS USED	
Workorder:	V54359			
In Date: Close Date: Problem?	12/11/2012 01/03/2013	Meter Reading:		
R 43 will no	ot start			
Task perfor	med:		Parts	Quantity
REPLACED	OIL AND ROAD	TESTED.	NO PARTS USED	
Workorder:	V55203			_
In Date: Close Date: Problem? R-43 stuck	01/22/2013 01/23/2013 in mud on call	Meter Reading: 53,8	372.00	
Task perfor	med:		Parts	Quantity
	UD/WINCHED (TATION INSPEC	OUT OF MUD FOLLOWED TED OK.	NO PARTS USED	
Workorder:	V55787			
In Date: Close Date: Problem?	02/14/2013 03/05/2013	•	488.00	
•			I power at a stop sign and almost stalled. The rescue was puow the rescue runs fine. R-43	it in neutral a
Task perfor	med:		Parts	Quantity
CHECKED A	AND ROAD TES	STED AND UNIT TESTED	NO PARTS USED	



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V51697

08/18/2012 In Date: Close Date:

04/04/2013

Meter Reading:

Problem?

Driver side rear scene light is out R 43

		• "
Task performed: 1. REPAIRED SCENE LIGHT. 2. REAR A/C WARM CLEANED CONDENCER FANS AND TESTED.	Parts	
Workorder: V47816 In Date: 03/08/2012 Meter Reading: Close Date: 04/05/2013 Problem? light box needs new bulb, Sta 43		
Task performed:	Parts	Quantity
REPAIRED GROUND ON LIGHT BOXES.	NO PARTS USED	
Workorder: V56816		
In Date: 04/03/2013 Meter Reading: 58,72 Close Date: 04/05/2013 Problem? Check engine stalled out R-43	28.00	
Task performed:	Parts	Quantity
1. FOUND FUEL IN OIL CHECK COMPUTER CODES - DRAIN OIL AND REFILL. 2. CHECK COMPUTER CODES - ASSIST IN R&R OIL - CHECK OK.	NO PARTS USED	
Workorder: V46479		
In Date: 01/10/2012 Meter Reading: Close Date: 04/08/2013 Problem? (2) ground lights need replacing for drivers side, and the	exhaust pipe needs tightening, Sta 43	
Task performed:	Parts	Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53111

10/16/2012 In Date: Close Date:

04/08/2013

Meter Reading:

Problem?

passenger mirror bracket broken, driver side rear scene light out. r43

Task performed:	Parts	Quantity
	2506220C92LOOK DOWN MIRROR	1
	2507656C91FLIP OUT ARM R/H	1
	2509070C91MIRROR BRACKET UPPER R/H	1
	5-20PHBL5366C 20AMP PLUG	5
	78R539018-2699 A/C FILTER	3



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V54001

In Date: 11/26/2012 04/08/2013 Close Date:

Meter Reading:

48.435.00

Problem?

C INSPECTION R43

Task	perfor	rmed:
------	--------	-------

- replace battery's
- 3. replace wiper blades
- 4. service transmission
- 5. a/c vents for cab red dot a/c missing, replace vent
- 6. SCBA cover on officer seat broken, repair snaps and velcro cover to bracket
- 7. female seat blet bolt loose on floor, check all seat belt's for looseness found all were loose on floor, tighten
- 8. rear lite bar not comming on in primary or secondary mode, reprogram horton master console
- 9. replace 9 ground lites
- 10. replace a/c filters in cab
- 11. 110v outlets in pat. compt. inop, inverter inop, remove screen cover or inverter and test found plug's not tighten, tighten plugs and test, ok
- 12. replace bulb in lite above EMT work station in pat. compt.
- 13. remove and replace non skid tape on rear entry door
- 14. vehicle had air leak and bleed down over night, use soap and water to trace, found air leak at air horn fitting on foot valve, replace fitting, recheck found fittings on air tanks leaking, replace fittings and recheck, no air leaks found
- 15. low on coolant, top off and pressure check found hose clamps loose tighten clamps
- 16. I/side rumbler falling off of bracket, rescure rumble to bracket
- 17. I/side front brake chamber hoes fitting falling off, remove hose and tighten fitting reinstall brake hose
- 18. 110v a/c inop, check freon, was empty, refill and check for leaks, found clamp style fitting's on high side and low side hose's leaking, eveacute system and remove hoses, install new style clamp fittings, vacunm down systen and recharge, recheck for leaks, ok cools to 26deg.

Parts	Quantity
12854DOME LIGHT BULBS	2
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
29526898 29548988 TRANS FILTER ALLISON	1
5774457744XD OIL FILTER	1
607141-05USE 61H01 COPMPARTMENT LIGHT	9
72R31001720 DIFFUSER A/C 3.5 IN	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER	3
HP-31DBATTERY 950CCA HP-31D	3
TRANSYNDALLISON TRANS FLUID GAL	5



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V53016

10/11/2012 In Date:

04/09/2013 Close Date:

Problem?

REPAIR FLAT

Task performed: **Parts** Quantity

48,210.00

REPAIR FLAT NO PARTS USED

Meter Reading:

BOULEVARD TIRE CENTE Vendor?

Workorder: V56939

In Date: 04/10/2013 59,052.00 Meter Reading:

04/19/2013 Close Date:

Problem?

radiator reservoir is losing water every day. R-43

Task performed: **Parts** Quantity

REPAIRED ON W.O. 56925. NO PARTS USED



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V56925

In Date: 04/09/2013

04/22/2013 Close Date:

Problem?

B inspection R43

Meter Reading: 59.052.00

Task perform	ed	
--------------	----	--

- 1. B-INSPECTION.
- B-INSPECTION CONTINUED.
- R&R CAB AUX A/C FILTER AND REPLACE MISSING AIR DIFFUSER (FOUND ON CAB FLOOR)
- 4. R&R CAB A/C FILTER.
- 5. TORQUE BOLTS ON REAR MOST U-JOINT ON DRIVESHAFT.
- 6. ADJ ALL TIRE PRESSURES TO 110 PSI.
- 7. DIAGNOSE ALL COOLING SYSTEM LEAKS DRAIN COOLANT R&R HOSE BELOW TURBO. R&R ALL CONNECT HOSES ON ENGINE AND USE NEW CLAMPS.
- 8. CONTINUE ABOVE REPAIRS. PRESURRE TEST SYSTEM WITH AIR - OK. FILL COOLING SYSTEM PRESSURE TEST AGAIN. ROAD TEST VEHICLE AND RECHECK ALL HOSES FOR LEAKS AND TOP OFF COOLANT.
- 9. HOOK UP LAP TOP READ ALL ENGINE CODES CHECK I KNOW SYSTEM FOR CODE EXPLANATION. ERASE CODES ROAD TEST VEHICLE AND RECHECK TO SEE IF CODES RETURN - NO CODES RETURNEL 10. A. C. TRUCK.

Parts	Quantity
1873940C3RAD HOSE	2
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
ANTICOOLANT ANTIFREEZE GAL	8
FAA-8350-30UGSS1783UQ STRUT-LIFT	1

Quantity

Workorder: V57403

05/01/2013 In Date: Meter Reading: 60,105.00

Close Date: 05/02/2013

Problem?

INSTALL STRYKER STRETCHER R43

Task performed: **Parts**

1. CHANGED OUT STRETCHER FOR NEW STYLE STRYKER STRETCHER MOUNTED HOOK, MOUNTED MAGNETIC LOCK OUT ADHUSTED RELEASE POLE. 2. ASSIST IN STRECTHER SWAPT.



Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V57873

In Date: 05/21/2013

05/31/2013 Close Date:

Meter Reading:

61,098.00

Problem?

Roof leak R43

Task performed: **Parts** Quantity

1. RESEALED ROOF, THAT WAS LEAKING.

2. READJUSTED ALL AIR PACKS IN CAB.

NO PARTS USED

Workorder: V57955

In Date: 05/24/2013

Meter Reading:

Close Date: 06/07/2013

Problem?

Front AC is not blowing cold all of the time.

Task performed: Quantity **Parts**

1. CHECKED A/C AND IS RUNNING GOOD AT THIS

TIME.

NO PARTS USED

Workorder: V58253

In Date: 06/07/2013

Close Date:

06/12/2013

62,039.00 Meter Reading:

Problem?

rear tires need to be replaced down to wear bars, ruoghfidle when cold start.

Task performed: **Parts** Quantity

REAR TIRES NEED TO BE REPLACED DOWN TO WEAR BARS, ROUGH IDLE WHEN COLD START.

Vendor? BOULEVARD TIRE CENTE

216568BRIDGESTONE 255/70R22.5

Workorder: V58320

In Date: 06/11/2013 Meter Reading: 62,135.00

06/12/2013 Close Date:

Problem?

a/c cab is not working blowing hot air

	l ask performed:			Quantity
F	REPLACED A/C COMPRESSOR,	REPLACED	3611894C9103-0805 A/C COMPRESSOR 4347	1
_, ,	EXPANSION VALVE AND DRYER. SYSTEM AND RECHARGED.	VACUUMED	3660853C22512331C1 EXP VALVE NAV	1
	STSTEW AND RECHARGED.		3670134C1ACCUMULATOR ASSY INT.	1



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V59306

07/23/2013 In Date: Close Date:

07/30/2013

Meter Reading: 64,671.00

Problem?

Nail in front left tire, Leaking air R43

Task performed: **Parts** Quantity

NAIL IN FRONT LEFT TIRE, LEAKING AIR R43 NO PARTS USED

BOULEVARD TIRE CENTE Vendor?

Workorder: V59288

In Date: 07/23/2013

64,499.00 Meter Reading:

Close Date: 08/02/2013

Problem?

electrical outlet on left outerside hot to the touch when plugged in...

Task performed: **Parts** Quantity

NO PARTS USED

AIR LEAK AT REAR REPAIRED LEAK AT MAIN

TANK.

2. ADJUSTED REAR DOOR THAT WAS HARD TO CLOSE.

Workorder: V59591

08/05/2013 In Date: Meter Reading: 65,202.00

08/19/2013 Close Date:

Problem?

front drivers side headlight needs to be replaced

Task performed: **Parts** Quantity

REPLACED HEADLIGHT AND REPAIRED WIRE.

CLEANED A/C CONDENSER FANS AND TESTED

SYSTEM.

NO PARTS USED

Workorder: V59784

08/14/2013 In Date: 65,681.00 Meter Reading:

08/30/2013 Close Date:

Problem?

the rear shorline a/c compressor stopped working. E43

Task performed: **Parts** Quantity

REPAIRED 110 PLUG THAT WAS BAD AND NO PARTS USED

RETESTED.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60025

In Date: 08/25/2013

09/17/2013 Close Date:

Meter Reading:

Problem?

Shoreline AC not working properly. It is not cooling and keeps tripping the breaker R43.

Task performed: **Parts** Quantity

repaired on w/o#60413 **NO PARTS USED**

Meter Reading:

Workorder: V60210

09/01/2013 In Date:

Close Date: 09/17/2013

Problem? oil leak R43

Parts Quantity Task performed:

check on w/o#60413 NO PARTS USED



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60413

In Date: 09/10/2013 Close Date:

09/23/2013

Meter Reading:

67.412.00

Problem?

C inspeciton R43

- 1. C insp.
- 2. shore line keeps tripping breaker w/o#60025, found cond. fans not turning on, trace problem out to 110v/12v converter, replace converter, fans now work, also found cond. fans were replaced on a prior work order but never were, install updated cond. fans, run system all day. cooled down to 28 deg. and did not trip breaker
- 3. oil leak w/o#60210, clean engine check for leak, did not find any type of leak
- 4. r/side cab marker lite inop, replace bulb
- 5. truck was left outside in the rain, went to pull unit in bay found water on driver side floor, had safe-lit come to shop to check thought it was comming from windshield. we ran water on windshield, found water running down splash gaurd and running into foot brake rubber on fire wall, running into all air lines, seal all air lines and foot valve mounting
- 6. non skid tape comming off, replace non skid tape on rear entry and side door
- 7. repaice all 3 pat.compt a/c filters
- 8. during insp. found SRS system fault lite on in horton display in front and in pat. compt. called c/shop Steve R said to disconnect SRS system and had Scott Mcwhite call me to show me how to turn system off from both displays
- 9. replace cab red dot a/c filter
- 10. remove rear wheels, repalce rear brake shoes, brake harware and drums, reinstall wheels, adjust tire pressure on all tires, adjust brakes and road test, bring back into shop and recheck brake adjustment
- 11. service air dryer, dryer bolt was stripped, had to remove complete dryer assy. and use air chisel to remove bolt, reinstall dryer assy.
- 12. replace wiper blades,
- 13. service p/s
- 14. install N.Y hook brackets in o2 compt.

Parts	Quantity
065624AD-IP DRIER	1
109498BOLT KIT CARTRIDGE ADIP	1
15-40B15W40 MOTOR OIL NON SYN	30
1501450007750USE 0775145	3
1878042C91FUEL FILTER 2008 HORTON	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3757REAR DRUMS 3757X 3647X	2
50-2204FAN KIT DANHARD CONDENSER	1
5774457744XD OIL FILTER	1
72R31001720 DIFFUSER A/C 3.5 IN	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
K022105PURGE VALVE AD-IP-IS	1
PD9175DLS75 CONVERTOR 110V 75 AMP	1
VML/T1808D2503221C1 FILTER POWER STEERING	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60681

In Date: 09/23/2013

Close Date: 10/09/2013

Meter Reading:

161,405.00

Problem?

siren fell out of dashboard R43

Task performed: Parts ____ Quantity

SIREN INOP REMOVED SIREN AND INSTALLED NEW

ONE.

295SLSA1SIREN

1

Workorder: V60699

In Date: 09/23/2013

Meter Reading: 161,405.00

Close Date: 10/10/2013 **Problem?**

scene light cover on officer side missing.

Task performed: Parts Quantity

REMOVED BROKEN LIGHT AND REPLACED LENS.

Z8012062C-02LENS CLEAR 9 X 7 FLUTED

2

Workorder: V60789

In Date: 09/25/2013

Close Date: 10/10/2013

Problem?

SMALL PLACARD ON BACK OF R-43 THAT SHOWS "43" IS FADED AND UNREADABLE

Task performed: Parts Quantity

INSTALLED NEW NUMBER SIGN IN REAR OF

RESCUE.

S PLACARD INSERTFRONT AND BACK INSERT CARD

1

Workorder: V60912

In Date: 10/01/2013

10/21/2013

Meter Reading:

Meter Reading:

67,990.00

Close Date: Problem?

Shoreline cover is broken R43

Task performed: Parts Quantity

REMOVED SHORELINE COVER AND INSTALLED

NEW ONE AND ALSO REPAIRED PLUG.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V60967

In Date: 10/03/2013

10/21/2013 Close Date:

Meter Reading:

Meter Reading:

67,990.00

150,670.20

Problem?

the right front tire has a bald spot on it. The allignment of the truck may be off causing the uneven tire ware.

Task performed: **Parts** Quantity

CHECKED TIRES AND CHECKED OK. WIKLL MONITOR TIRES - NOT DOWN TO WARE BARS.

NO PARTS USED

Workorder: V61179

In Date: 10/11/2013

10/25/2013

Close Date: Problem?

shoreline not working

Task performed: Quantity **Parts**

- 1. A INSPECTION.
- UNIT LEANING LEFT. CHECK LEVELING VALVES. ADJUST NODS TO LEVEL UNIT.
- 3. HAND HELD SPOT LIGHT WIRE LOOSE SERVICE WIRE HARNESS TO UNDER DASH OFFICERS SIDE.
- 4. REMOVE METAL PLACARD HOLDERS CLEAN ADHESIVE OF SURFACE INSTALL NEW PLASTIC HOLDERS.
- PATIENT COMPART. A/C REGESTER VENT -DAMAGE - REMOVE AND INSTALL NEW VENT REGESTER FILTER ASSEMBLY.
- 6. L/R WINDOW MOLDING BROKEN REMOVE AND INSTALL NEW WINDOW MOLDING.
- 7. PATIENT COMP. TO CAB WINDOW MOLDING FALLING OFF CUT NEW WOOD FOR SUPPORT AND INSTALL ON FRAME, MOUNT MOLDING ONWOOD FRAME.
- PATIENT COMP. CELUMBE POST CUSHING FALLING OFF - REMOVE RETAP SCREW HOLES -REMOUNT AND SECURE.
- 9. REAR TIRES TO BE MONITORED AS PER S. REINES.
- 10. SHORELINE INOP REMOVED AND REPLACED 110 PLUG.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V61536

In Date: 10/25/2013

11/08/2013 Close Date:

Meter Reading:

passenger he	eadlight need	s replacement E43		
Task performe	ed:		Parts	Quantity
REPLACED HA	ARD LIGHT /	AND REPAIRED WIRES.	9007H9007 BULB ASSY	2
Workorder:	V61939			
	11/11/2013 11/14/2013	Meter Reading:		
the left side o		leaning 2 and 1/2 inches. The pain, we measured the truck and	machanic came out today and adjusted the air bag it has a 2 and a 1/2 inch lea	. The truck went back
Task performe	ed:		Parts	Quantity
1. REPLACED REAR AIR BAGS FOR INSPECTION			2505183C91LEVELING VALVE	2
OPERATION G	SOOD NOW.	S AND FRONT TIRES.	GUI1R11216GY1R11216 AIR BAG INT.	2
Workorder:	V61940			
	11/11/2013 11/14/2013	Meter Reading:		
the right front		n down and is bare on the end. ng the wear on the right front tir	the left front tire is fine. it appears the truck may be e.	e off allignment or
Task performe	ed:		Parts	Quantity
R&R BOTH FR	ONT TIRES		NO PARTS USED	
Workorder:	V61927			
In Date: 1	11/11/2013	Meter Reading:		

Close Date: 11/21/2013

Problem?

Resue is leaning to the left. It appears that the left airbag is blown. E43

Task performed: **Parts** Quantity

CHECKED FOR LEAKS FOUND NO LEAKS

READJUSTED AIR BAGS AND TESTED.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V62830

In Date: 12/19/2013 Close Date:

12/23/2013

Meter Reading:

Problem?

R43 stalled 4 times while idling at stop lights.

Task performed:

CK CODES- ICP TOO HIGH- FOUND FUEL IN OIL-REMOVE AIR CLEANER AIR TUBES, BREATHER AND EGR CROSS- OVER TUBE- CHK EGR COOLER FOR LEAK-CHK OK-CLEANED EGR REASSEMBLED ALL PARTS- R&R ENG OIL- RAN ENG- RUN TESTS- PASSED- COULD NOT REGEN-TEST DROVE- CHK OK.

Parts

Quantity

NO PARTS USED

Workorder: V62824

In Date: 12/18/2013

Close Date:

12/31/2013

73,031.00 Meter Reading:

Problem?

CHARGING SYSTEM 10-7 R43

Task performed:

REMOVED AND REPLACED ALTERNATOR AND TEST

Meter Reading:

SYSTEM.

Parts

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

Quantity 1

Workorder: V63000

In Date: 12/28/2013

Close Date: 01/02/2014

Problem?

While driving R43, the truck died three times, while on neutral and at redlight. Oil was checked and it was not overfill. radiant cook was not low. Pleas e come check asap, Thank you

Task performed:

1. TROUBLESHOOT SYSTEM- CHK CODES- ICP TO HIGH AT TIMES- REMOVED AIR CLEANER TUBES ICP VALVE COVER-R&R SENSOR-REASSEMBLED ALL PARTS- CODES ICP TO HIGH FOR SPECS- REPLACED ICP. REMOVED WASHER BOTTLE AND BRKT AIR GOV-LINES FUEL HARNESS AN DICP- REPLACED IPR- REASSEMBLED ALL PARTS- RAN- REPLACED COOLANT LEAK- TEST DROVE CHK OK.

CLEAN AND MOP FLOOR.

Parts

1875784C921875784C93 ICP SENSOR

1878629C94IPR VALVE

Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V63010

In Date: 12/29/2013 Close Date:

01/02/2014

Meter Reading:

Problem?

R-43 was involved in a minor accident with damage to the driver side running board and vehicle battery compartment. A mechanic needs to look at the damage to see if the rescue needs to be taken out of service.

Task performed: **Parts** Quantity

FOUND L STEP AND BATT BOX COVER DAMAGED

REPAIRED CHANGE CHK OK.

NO PARTS USED

Workorder: V63398

In Date: 01/14/2014 Close Date:

Meter Reading: 01/15/2014

Problem?

front cab a/c is not blowing/ seen by jerry at 39, needs filter and doors were blocked shut.... R43

Task performed: Quantity **Parts**

CHECK A/C IN CAB FOUND FILTER IS BAD AND NO AIR OUT VENTS, NEED DOOR PRESSURE WERE

LOW SO I ADDED FREON.

NO PARTS USED

Workorder: V63415

In Date: 01/15/2014

01/22/2014 Close Date:

Problem? Cab a/c inop

Task performed: **Parts** Quantity

74,893.00

TRY TO HOOK UP LAP TOP. DIAMOND LOGIC NOT CONNECTING, REMOVE BLEND DOOR MOTORS OR CHECK, REPLACE BAD MOTOR.

3542606C12611234C1 VENT ACTUATOR

Workorder: V63485

01/17/2014 In Date: 74,893.00 Meter Reading:

01/22/2014 Close Date:

Problem?

highwater problems

Task performed: Quantity **Parts**

CHECK ENGINE LIGHT ON, DRYED OUT NO PARTS USED

Meter Reading:

CONNECTORS.



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V63890

In Date: 01/31/2014 02/04/2014

Close Date:

Meter Reading:

76,068.00

Problem? repair flat

Task performed:

Parts

Quantity

REPAIR FLAT.

NO PARTS USED

BOULEVARD TIRE Vendor?

02/24/2014

Workorder: V64332

In Date: 02/19/2014

77,318.00 Meter Reading:

Close Date: **Problem?**

air leak

Task performed:

Parts Quantity

1. TRAVEL TO ST-43 CHECK AIR LEAK, PURGE AIR DRIER LEAKING REPLACE PURGE VALVE ON DRIER. REPLACE O-2 GOVERNOR AND REPLUMB UNIT TEST OK.

284358GOVERNOR D-2 800405PURGE VALVE KIT 1 1

Workorder: V63927

02/03/2014 In Date: 02/25/2014 Close Date:

Meter Reading:

76,131.00

Problem? low voltage

Task performed:

Parts

Quantity

REMOVED ALTERNATOR THAT WAS NOT CHARGING

AND INSTALLED NEW ONE.

A0014949PA4949PA/4962 320 AMP UPGRADE SADDLE MC

1

Workorder: V63337

01/13/2014 In Date:

03/20/2014

Meter Reading:

Close Date: **Problem?**

Front AC in cab not blowing properly.

Task performed:

Parts

Quantity

FRONT A/C PROBLEM REPAIRED ON W.O #63698.



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V61639

In Date: 10/30/2013

Close Date: 03/26/2014

Problem?

electrical button on stretcher not working. Plastic covering came off.

Meter Reading:

Meter Reading:

Meter Reading:

Task performed:

Parts _____ Quantity

NO PARTS USED

REPAIRED BY AL PACKER ON WORK ORDER

#62465.

Workorder: V65092

In Date: 03/21/2014

Close Date: 04/08/2014

Problem?

R-43 leaking oil.

Task performed: Parts Quantity

TRACED OIL LEAK OIL OUT. CLEANED MOTOR AND

WILL MONITOR OIL LEAK.

NO PARTS USED

Workorder: V64497

In Date: 02/24/2014

Close Date: 04/15/2014

Problem?

B inspection R43 OCS

Task performed: Parts Quantity

B inspection 1878042C91FUEL FILTER 2008 HORTON 1
filter change 1

78,357.00

Vendor? OCS 5774457744XD OIL FILTER

Workorder: V63993

In Date: 02/05/2014 Meter Reading:

Close Date: 04/21/2014

Problem?

one set of the electrical buttons for the operation of lifting pt. does not work.

Task performed: Parts Quantity



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History

10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V64053

In Date: 02/07/2014 Close Date:

04/22/2014

Meter Reading:

Meter Reading:

Problem?

upper lift button does not work and is becoming loose

Task performed: **Parts** Quantity

upper lift button does not work and is becoming loose.

Repairs complete.

NO PARTS USED

Workorder: V65509

04/07/2014 In Date: Close Date:

05/09/2014

Problem?

The map light in the cab broke off from the stand

Task performed:

- 1. INSTALL NEW MAP LIGHT AND TESTED.
- 2. ALC INOP- FOUND HIGH PRESSURE SWITCH BAD. REMOVED AND REPLACED.
- 3. MED DRAWER INOP- REPLACED SLIPING TRACKS.

Parts	Quantity
3546241C1SWITCH A/C PRESSURE INT.	1
HA24121HA24121 BRACKET-BALL MT	3
LF18TS-LEDMAP LIGHT LED 18 IN	1
LTC5993SSM1-63-8 LATCH STAINLESS	2
SLD5366HT4932-16 DRAWER SLIDE 16	1

Workorder: V66136

In Date: 05/01/2014

Close Date:

05/13/2014

Meter Reading: 82.200.00

Problem? cab a/c inop

Task performed:

DIAGNOSE CAB A/C. DISCHARGE SYSTEM. R&R COMPRESSOR EXP VALVE AND RECIEVER DRYER. CHECK SYSTEM FOR METAL. SYSTEM WAS OVERCHARGED BY 1 LB 80Z FREON COMPRESSOR FAILED.

Parts	Quantity
3611894C9103-0805 A/C COMPRESSOR 4347	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V66116

04/30/2014 In Date: Meter Reading:

05/22/2014 Close Date:

Problem?

front A/C suddenly blowing hot air

Task performed:	Parts	Quantity

TRACED OUT PROBLEM FOUND EXPANSION BLOCK NEEDS TO BE REPLACED SENT TO SHOP.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66648

05/21/2014 In Date: Close Date:

06/10/2014

Meter Reading:

Problem?

Task performed:

will replace all pack holder at shop

Drivers side rear tires nearing tread depth indicators; Passenger side rear tires at tread depth indicators

Task perfo	rmed:		Parts	Quantity
checked rear.	ar tires and will	need to replaced all four or	NO PARTS USED	
Workorder	: V66278			
In Date: Close Date: Problem? The open	05/06/2014 06/11/2014 door alarm not s	Meter Reading: sounding when in gear. The	reverse alarm not sounding while in reverse.	
Task perfo	rmed:		Parts	Quantity
-		and repaired back up alarm.	NO PARTS USED	
Workorder	: V66716			
In Date: Close Date: Problem? Replace r	05/24/2014 06/12/2014 ear tires	Meter Reading: 8	4,193.00	
Task perfo	rmed:		Parts	Quantity
Replace 4 r	ear tires.		NO PARTS USED	
Vendor?	ELPEX			
Workorder	: V66943			
In Date: Close Date: Problem?	06/03/2014 06/23/2014	Meter Reading:		
	nolding the scba ged the scba	is damaging the scba due t	o the scba being too low in the seat housing	and metal rubbing against me

Parts

NO PARTS USED

Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V66989

In Date: 06/05/2014 Close Date: 07/03/2014

Meter Reading:

Problem?

The airpack bracket lower arms current location leads to damage of the airpack air hose. Solutions might be to lower the bracket and leave the arms where they are or to raise the lower arms

Task performed: Parts Quantity

WILL HAVE ALL AIR PACKS AND BRACKETS REMOVED AT B-INSPECTION.



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

85,192.00

Parts

Workorder: V67097

06/09/2014 In Date: 07/08/2014 Close Date:

Meter Reading:

Problem?

C inspection R43

Task performed:

Quantity



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1. Replace all batteries. ALS Repair. Broken hold down.
2.Latch on one side of battery cover/step broken, others
very loose. Removed broken latch-Note: Parts dept. only
has black latches and broken one was chrome.
Disassemble both latches and used good pieces from
new latch to fix old latch and reinstall. Adjust all latches.
3.Replace wiper blades.

- 4. Battery slide tray is hard to open. Binding up. Wash and clean out debris from tracks. Relube and work tray back and forth until loose and free.
- 5. Service power steering
- 6. Fluid return hose from gear box to resevoir. Started leaking. Replace hose assembly.
- 7. Replace all patient area intake filters and cab rear a/c filter-Note: Many of the cage retaining screws stripped out. Replace all
- 8. Front tires has slight drift to the right. Set up front axle on stands and rotated front tires.
- 9. Repair eyelet on oxygen wrench cable and remounted on wall.
- 10. Removed front hubs from axle knock out seals and bearings. Washed out all grease from bearings and hubs. Reinstalled bearings and new seals. Reinstalled hubs on axle and installed new outer hub cap for oil fill. Filled hubs with gear oil.
- 11. 5 of the undertruck light brackets are very loose. Remove crews locked tight and reinstalled. Note: some screws are stripped out. Redrilled brakes and installed oversized screws.
- 12. Serviced air dryer.
- 13. Primary air tank keeps losing air. Spray tested all fittings associated with primary air tank, found two bushings on fittings bad. Replaced fittings and also found 3 small leaks in secondary air system that was pulling air out of primary tank. Repaired leaks.
- 14. A/C compressor wiring was rotten and casing was cracked. Ecposing inner wires. Evacuated system. Disconnect 110V wiring from electrical box. Removed compressor assembly from vehicle, on bench, disassembled wiring from top of the compressor (all soldered). On connectors, find new 12 gauge X 4 wire cable to make up new 90 degree connector and resolder to terminal on top of compressor. Reinstalled protection cover. Reinstalled compressor. Reconnected 110V wiring to electrical box. Vacummed system. Recharged system. Test run and now all is ok.
- 15. Unbolt compressor from its mounting and move to the side. The 6 mounting bolts holding the platform for compressor were way too long and rubbing into the wiring and housing. Replaced all bolts with shorter ones. Rebolted compressor to platform.
- 16. Replaced all engine drive belts. Found one tensioner for rear a/c compressor bad. Replaced tensioner.
- 17. Engine oil leaks severe. Oil dripping from front of

005024AD-IP DRIER	
0775145PANEL FILTER	3
1812348C1FUEL LINE SLEEVE INT	4
1821023C1LINE OIL FEED COMPRESSOR INT.	1
1836005C1GASKET HIGH PRESSURE PUMP MTG	1
1839415C91OIL PRESSURE SENSOR	1
1842122C1DRAIN PLUG	1
1847727C1BELT	1
1873906C1SEAL FUEL FILTER HSG	1
1878042C91FUEL FILTER 2008 HORTON	1
1878918C2EGR VALVE	1
1882259C931882259C94 HIGH PRESSURE OIL PUMP	1
1893940C911893940C93 OIL LINE HIGH PRESS PUMP	1
2506271C1DRAIN VALVE RADIATOR NAV	1
2506656C124316 WIX CAB A/C FILTER	1
2507061C1PS RESV GASKET	1
3533425C3FUEL LINE FITTING INT.	1
3591094C1FUEL FITTING	1
370001ASEAL 35066	2
38504TENSIONER HORTON ADD ON A/C	1
4307362R91KIT EGR COOLER COLD SIDE OLD 1876262C	1
46870AIR FILTER	1
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	3
CHR1612340-4024 HUB COVER - FRONT AXLE 2004 RESC	2
F6DZ-8100-A9C3Z8101B RADIATOR CAP 10238 STANT	1
HA49102C2-32-15 LATCH NON LOCKING	1
HP-31DBATTERY 950CCA HP-31D	3
K022105PURGE VALVE AD-IP-IS	1
K060705BELT HORTON	2
L2643655P/S HOSE 3/4	3
VML/T1808D2503221C1 FILTER POWER STEERING	1



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

12/17/2018

engine to off back of transmission. All on left side. First I competely washed off all oil to determine the location of oil leaks. The front leak was coming from bottom of high pressure pump for injection system. Midway back found 2 more leaks coming from oil pressure line from block to feed air compressor and also a pressure switch just in front of starter. Replaced high pressure pump, oiled feed line to air compressor and oiled pressure switch. Started engine and ran until running temperature. Shut down and rechecked. No leaks found.

18. Vehicle came in with coolant recovery bottle 3/4 empty. Check with Tommy to see if he was adding coolant. He said he wasn't but at the station was almost every shift. Removed EGR exhaust crossover pipe to check and coolant ran out. Pipe and EGR valve was soaked. Also checked intake throttle valve and it was caked heavly with wet mucky debris. Drained out all coolant and removed all components of the EGR system. Washed out debris from components that will be reused. Replaced both right and left side coolers. Replace all attaching hoses and clamps. Installed new EGR and intake throttle valves. Replaced broken radiator. Drained valve an refilled system. Road Test. Recheked and all is ok now.

Workorder: V67880

In Date: 07/13/2014

Close Date: 07/15/2014

Problem?

Cab A/C not working. Blows hot. R43

Task performed:

Checked out A/C inop. Replaced thermisters , compressors , dryer and expansion valve. Vacuumed and recharged. System is cabling normally.

Meter Reading:

Meter Reading:

Parts	Quantity
3611894C9103-0805 A/C COMPRESSOR 4347	1
3622764C32606229C92 THERMISTER	1
3660853C22512331C1 EXP VALVE NAV	1
3670134C1ACCUMULATOR ASSY INT.	1

Workorder: V68060

In Date: 07/21/2014

Close Date: 07/21/2014

Problem? cab a/c inop

Task performed:

went to sta, cab a/c not blowing cold, system seems to be oil loaded need to come to shop crew declined,will run that way till monday. **Parts**

85,923.00

Quantity



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V67923

In Date: 07/15/2014 Close Date: 07/25/2014

Meter Reading:

Problem?

LOOSE.

The side door to the patient compartment is stuck and will not open.

Task performed:

REPAIRED BOTH DOORS STRICKER THAT WERE

NO PARTS USED

Quantity

Workorder: V68302

In Date: 07/31/2014 Meter Reading: 86,585.00

Close Date: 08/01/2014

Problem? cab a/c inop

Task performed: Parts Quantity

Cleaned condensor fans and road tested, was cold after

cleaning.

NO PARTS USED

Workorder: V68126

In Date: 07/23/2014 Meter Reading:

Close Date: 08/05/2014

Problem?

shoreline for ac is not working R43

Task performed: Parts Quantity

ck 110v a/c and found unit working, NO PARTS USED

ck, all connections ok.

Workorder: V68340

In Date: 08/01/2014 Meter Reading: Close Date: 08/05/2014

Close Date: (Problem?

front cab A/C blowing hot air

Task performed: Parts Quantity

Cab AC inop, low charge. Recover EVAC and recharge. NO PARTS USED



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V68774

In Date: 08/18/2014 Close Date:

08/22/2014

Meter Reading:

Meter Reading:

Problem?

one of the extension cords are not working on the shoreline to the vehicle r43

Task performed: **Parts** Quantity TRACED OUT PROBLEM FOUND BREAKER BLOW IN NO PARTS USED STA.

Workorder: V68784

In Date: 08/19/2014

Close Date: 09/02/2014

Problem?

The front cab ac is not blowing cold air.

Task performed: **Parts** Quantity 1 R&R A/C COMPRESSOR PUMP DOWN AND CHARGE 3611894C9103-0805 A/C COMPRESSOR 4347 SYSTEM TESTED AND CK SYSTEM OK 1 3670134C1ACCUMULATOR ASSY INT.

Workorder: V69180

In Date: 09/04/2014 88,739.00 Meter Reading:

09/05/2014 Close Date:

Problem?

Engine low power/limping back to station

Task performed: **Parts** Quantity

Travel to station 43. Worked with Steve R. Connect laptop and checked vehicle. Forced DCF clean. Connect cooling fan solenoid back up. Test drive (ok) oil high in crankcase

NO PARTS USED

Workorder: V69182

09/04/2014 In Date: Meter Reading: 88,739.00

09/05/2014 Close Date:

Problem?

R43 malfunction after being on scene at a fire for a couple of hours. The dash lcd read stop engine, and it was stopped and reset. later a warning light stating exhaust temp and electrical fault also appeared.

Task performed: **Parts** Quantity

Found inactive level 1 and level 2 DPF codes. Ran

parked began and test drove. All ok at this time.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

12/17/2018

Workorder: V68490

In Date: 08/07/2014 **Close Date:**

09/15/2014

Meter Reading:

87,015.00

Problem?

scba clamps for rex

Task performed: **Parts** Quantity

work was completed by rex scba shop **FHLP-6TANK CLIP** 2

Workorder: V69915

In Date: 10/05/2014

Meter Reading: 91,071.00

Close Date: 10/29/2014

Problem?

Bolts on left side of hinged step have pulled the threads. Step is very loose.

Task performed: **Parts** Quantity

1. Removed broken bolts in step and installed all new

NO PARTS USED

- bolts. 2. Readjusted rear door latch that was hard to close.
- 3. Readjusted rear air bags and road tested.

Workorder: V70106

In Date: 10/13/2014 91,902.00 Meter Reading:

10/30/2014 Close Date:

Problem?

Oil level reads about 2.5-3 times as full as it should be.

Task performed: **Parts** Quantity

Remove and replace oil, replaced DPF- cleaned EOC Installed cleaned DPF and gaskets. Cleaned DPF codes , ran and checked ok.

1 2593986C1DPF GASKET 1 2593998C1DPF GASKET 1 **DPFCLEANED UNIT**

Workorder: V70713

In Date: 11/04/2014 Meter Reading:

Close Date: 11/12/2014

Problem?

the top buttons to raise and lower the carriage of the stretcher are not working. R43

Task performed: **Parts** Quantity

Repaired by EMSAR NO PARTS USED



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V69601

In Date: 09/23/2014

Close Date: 11/13/2014

Meter Reading: 90,087.00

Problem?

light cover for emergency lights (drivers side)

Task performed:PartsQuantityInstalled new light cover on rear of truck6811813493LENS CLEAR 68-1181349-31

Darte

Workorder: V70846

In Date: 11/12/2014 Meter Reading: 93,912.00

Close Date: 11/18/2014

Problem?

B inspection R43

- 1. "B" inspection
- 2. R/brakes
- 3. F/brakes-removed F/tires and drums inspected shoes and reassembled shoe could last unit next service.
- 4. Locate air leaks- R/R dump valve solonoid in frame rail and replace tee connector at air tanks.
- 5. Leveling valves-replace leveling valves due to leakage adjust height
- 6. Test drive truck and replace air filters(AC),refilters brakes and clean up bay and tools.
- 7. Q and A inspection

Parts	Quantity
0775145PANEL FILTER	2
1878042C91FUEL FILTER 2008 HORTON	1
2505183C91LEVELING VALVE	2
2505594C1SOL MANIFOLD	1
2506656C124316 WIX CAB A/C FILTER	1
2506712C91SOLENOID AIR DUMP INT	2
2506713C91AIR HORN SOL	1
3584247C1CHECK VALVE INT	1
3757REAR DRUMS 3757X 3647X	2
5774457744XD OIL FILTER	1
72R311018-2640 VENT A/C NEW # 1719	1
78R539018-2699 A/C FILTER	1
ALA00350-50 EXTENDED LIFE COOLANT GAL	1
GRV1720244770R1 HORN SUPPORT BRKT	1
HLD3999GSS1715UV 30LB STRUT GAS	2
S777COUPLING NIPPLE	1
XK4034707QPMHD SHOE KIT 3/8 BEAM	2

Quantity



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71167

In Date: 11/24/2014

Meter Reading:

Close Date: 12/03/2014

Problem? coolant leak

Coolant leak		
Task performed:	Parts	Quantity
Traced out problem with coolant leak-found bad water	1842665C93WATER PUMP DT570	1 6
pump-removed pump and installed new one refilled coolant and road tested.	ALA00350-50 EXTENDED LIFE COOLANT GAL	
Workorder: V71077		
In Date: 11/19/2014 Meter Reading: 93,9 Close Date: 12/12/2014 Problem?	12.00	
Replace front tires Used 2 from our stock		
Task performed:	Parts	Quantity
WORK REPAIRS AS REQUESTED.	216568BRIDGESTONE 255/70R22.5	2
Vendor? BLVD TIRE CENTER		
Workorder: V69568		
In Date: 09/21/2014 Meter Reading: Close Date: 12/22/2014 Problem?		
only the exit button transmits. the entrance button not ligh	nting up or transmitting. may need replacment	
Task performed:	Parts	Quantity
forwared to Build Maint	NO PARTS USED	
Workorder: V70003		
In Date: 10/08/2014 Meter Reading: Close Date: 12/29/2014 Problem?		
Rear folding step needs to be sercured. Bolts are coming	out.	
Task performed:	Parts	Quantity
Rear folding step needs to be secured WO#v69915 done	NO PARTS USED	

94,211.00



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V71806

In Date: 12/22/2014 Close Date: 12/29/2014

Problem?

check engine light

Meter Reading: 96,388.00

Task performed:	Parts	Quantity

Check engine light on, found low on coolant NO PARTS USED

Workorder: V71560

In Date: 12/10/2014 Meter Reading: 95,471.00

Close Date: 01/06/2015

Problem?

THE FUEL TANKS ARE NOT SWITCHING OVER ,WHEN THEY GET LOW.

Task performed: Parts Quantity

Traced out problem, found blown fuse-replaced fuse NO PARTS USED

Workorder: V71691

In Date: 12/16/2014 Meter Reading:

Close Date: 01/07/2015

Problem?

Roof mounted spotlight will turn on but will not articulate r43

Task performed: Parts Quantity

NO PARTS USED

Workorder: V71692

In Date: 12/16/2014 Meter Reading: 95,888.00

Close Date: 01/07/2015

Problem?

fuel is never used from the drivers side of the vehicle. fuel is only used from the passanger side. R43

Task performed: Parts Quantity

Repaired bad connection on relay for fuel tank

NO PARTS USED



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72424

In Date: 01/18/2015 Close Date:

02/05/2015

Meter Reading:

Meter Reading:

Meter Reading:

Problem?

Keeps saying compartment 7 is open and need to be closed. All compartments were throughly check to make sure they are secured. Unable to stop it from saying its open.

Task performed: **Parts** Quantity 1 1. Installed new compartment switch and tested. 03910030SWITCH COMPARTMENT DOORS 2. Performed park regen.

Workorder: V72463

In Date: 01/20/2015

02/05/2015

Close Date: Problem?

Scene light on the drivers side is secured with duct tape to the body of the rescue. Unknown if this is a known problem.

Task performed: Quantity **Parts** 2 Replaced lens on driver's side. 6811813493LENS CLEAR 68-1181349-3 2 Z8012062C-02LENS CLEAR 9 X 7 FLUTED

Workorder: V72467

In Date: 01/20/2015

02/05/2015 Close Date:

Problem?

Spotlight on top of the cab does not turn nor move up or down. The light itself turns on/off.

Task performed: Quantity **Parts** 1. Replaced controler on dash for spotlight. 2020-DDASH MOUNT REMOTE CONTROL Readjusted all air pack brackets.

Workorder: V72517

01/22/2015 In Date: Meter Reading:

02/05/2015 Close Date:

Problem?

air suspension (rear) is leaking air

Task performed: **Parts** Quantity 2 Check for air leaks. Found left air bag with hole in it. GUI1R11216GY1R11216 AIR BAG INT. Replace both air bags on rear of truck.



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V72044

In Date: 01/03/2015

Close Date: 02/06/2015

Meter Reading:

Problem?

Left upper cab red flasher light is loose, R43

Left upper cab red flasher light is loose. R45				
Task performed:	Parts Q			
Repaired right rear cab door handle.	NO PARTS USED			
Workorder: V72466				
In Date: 01/20/2015 Meter Reading: Close Date: 02/06/2015 Problem?				
Stretcher securing base loose on the floor				
Task performed:	Parts	Quantity		
Chcecked stretcher and tested ok. All was secure to floor.	NO PARTS USED			
Workorder: V72550				
In Date: 01/22/2015 Meter Reading: Close Date: 02/09/2015 Problem?				
A leak was fixed today at the shop in the rear air bag. No	w it sounds like there is a slow leak in the	e front airbag as well.		
Task performed:	Parts	Quantity		
Traced leaks and repaired.	NO PARTS USED			
Workorder: V72592				
In Date: 01/26/2015 Meter Reading: Close Date: 02/09/2015 Problem?				
LEFT HEADLIGHT IS OUT ON R43 :)				
Task performed:	Parts	Quantity		
R & R headlight.	NO PARTS USED			



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V73154

02/13/2015 In Date: Close Date:

02/26/2015

Meter Reading:

Problem?

Driver side head light out.

Task performed:	Parts	Quantity
R & R headlight.	9007H9007 BULB ASSY	1



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V73686

03/05/2015 In Date: **Close Date:** 03/20/2015

Problem?

C inspection R43

/leter	Reading:	102,044.00
--------	----------	------------

Task performed:	Parts	Quantity
i aon periorinea.	i di to	- Countries



12/17/2018

Palm Beach County Fire Rescue Fleet Maintenance Asset History 10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

1.	C-	Inspection.
----	----	-------------

- 2. C- Inspection.
- 3. R&R lens, R&R bulbs on 3 courtesy lights on 3 cab doors.
- 4. R&R 3 bulbs in barlight in patient arear.
- 5. R&R wiper blades.
- 6. Tighten all screws and pivot balls on compt L-2 doors.
- 7. Tighten all screws and pivot balls on compt L-3. One bracket all threads stripped and ruined.
- 8. Remove and redrill anchor plate for hold open air cylinder fabricate a steel plate for void for 4th hole and drill and tap new hole for # 3 screw.
- 9. Diagnose and repair UV light.
- 10. R&R 2 air springs on medical cabinet frame L/S rear in patient area.
- 11. Check air filter restriction gauge. R&R gauge and test ok.
- 12. R&R R/S rear scene light bulb. Wash reflector and lens. Bulb was fused into bulb socket.
- 13. R&R cab aux A/C filter. Found water build up caused by dirt, dust and sludge in drip pan area. Was drip pan area and clear drain hose that was partially blocked.
- 14. Checked with washer reservoir- broken. Check with parts dept- None in stock ordered.
- 15. Attaching hardware for air filter housing missing. Parts does not have these. Found metric shop harware to fit and installed.
- 16. Exhaust system loose. Check to find bad parts. R&R clamp between muffler and exhaust stack.
- 17. Finish exh. clamp replacement. R&R 2 heat shield mounting clamps. Get new metric S/S blots (4) and install heat, shield.
- 18. R&R 3 patient area A/C filters.
- 19. R&R driver's seat belt assy.
- 20. Repair rear entry doors. Can't open from inside. Remove door panel and window frame. R&R handle assy. Bend linkage rod , also bend tab on latch assy. R&R 2 nutserts.
- 21. Jack up veh. Remove front nut covers, lug nuts, wheels and drums. Remove linings. Install new linings.
- 22. Finish front brake job. Reinstall new drums, wheels and nut covers. Adjust brakes. Return boxed old linings to parts dept. Throw old drums and spring kits in metal dumpster.
- 23. R&R windsheild reservoir. Had R&R rumbler siren in order to do washer. In the way.
- 24. Repair eclec. connection at R/S front ground LT.
- 25. Find and repair leak on veh. R&R 2 fittings on air comp. governor.
- 26. R&R center console. O2 alarm missing off p/c board. Also access action area p/c board. Alarm also missing off board. No alarms in stock. Ordered.
- 27. R&R door panel. Lube all tracks- no good. R&R motor- no good. Put original motor back in . Ordered new

0775145PANEL FILTER	
1878042C91FUEL FILTER 2008 HORTON	1
194BULB	10
211-2BULB	3
2506656C124316 WIX CAB A/C FILTER	1
33961C35976 MUFFLER CLAMP	1
3555059C973555059C98 WASHER BOTTLE	1
3599692C1CLAMP EXH SHIELD	2
3711331C1SEAT BELT	1
3711355C91RECIEVER SEAT BELT BUCKLE WITH TETHEI	1
3753BRAKE DRUM RUMPER FRONT	2
5774457744XD OIL FILTER	1
78R539018-2699 A/C FILTER	1
91-22WIPER BLADE	2
GPX13ULTRA VIOLET LIGHT SHORT	1
H50SN12BULB	1
HLD3999GSS1715UV 30LB STRUT GAS	2
KSMA2124703QFRONTBRAKE KIT RUMPER AND 4DR RES	2



10182627

INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

regulator or assy. 28. Q/A

1. Repair A/C.

Workorder: V73334 02/22/2015 In Date: Meter Reading: 03/31/2015 Close Date: **Problem?** The rear scene light on the right side is out R43 Task performed: **Parts** Quantity 1. Repaired bad connection on light. NO PARTS USED Workorder: V73488 02/27/2015 In Date: Meter Reading: 04/28/2015 Close Date: **Problem?** both outside back tires need to be checked for wear. Task performed: Quantity **Parts** replaced rear tires NO PARTS USED Vendor? **BOULEVARD** Workorder: V74672 In Date: 04/15/2015 Meter Reading: **Close Date:** 05/05/2015 Problem? A/C in cab is not blowing. Task performed: **Parts** Quantity Finished in asset works NO PARTS USED Workorder: V74044 03/20/2015 In Date: 102,044.00 Meter Reading: Close Date: 05/22/2015 Problem? A/c inop Task performed: Quantity **Parts**

K060705BELT HORTON



INTERNATIONAL 4400 ADVANCED LIFE SUPPORT

Workorder: V74629

04/13/2015 In Date:

06/10/2015 Close Date:

Problem?

Meter Reading:

Front cab main AC cuts in and out while operating, the air is still cold that comes on when it is working. Rear cab AC works fine.

Task performed: Quantity **Parts** NO PARTS USED



Asset: (10182627) 2010 - INTERNATIONAL HORTON Advanced Life Support Vehicle

10182627

CSHOP-2015-1009

Comments: **CHECK BRAKES WONT START R43**

> Date Opened 6-4-2015 7-9-2015 Date Finished Meter 1 Reading: 106,679

TASKS PERFORMED

ENGINE COOLANT TEMPERATURE SE

CAP

PARK BRAKE AIR SYSTEM

DOOR

AIR CONDITIONING

CAP; 9C3Z8101B RADIATOR CAP 10238 STANT

2 BRAKE; REAR DRUMS 3757X 3647X

1 NUT; 13-3052 NUT

PARTS

2 BRAKE; HD SHOE KIT 3/8 BEAM

VALVE: PURGE VALVE AD-IP-IS

ACTUATOR: 2611234C1 VENT ACTUATOR

ASSEMBLY; ACCUMULATOR ASSY INT.

VALVE; SCHRADER VALVE INT.

NONSTOCK; FREIGHT CHARGE

VALVE; 8915 VALVE CORE A/C 3544706C1

COMPRESSOR: 03-0805 A/C COMPRESSOR

VALVE; 2512331C1 EXP VALVE NAV

LATCH; C2-32-15 LATCH NON LOCKING

CSHOP-2015-111

Date Opened 4-17-2015 Date Finished 4-27-2015 103,110 Meter 1 Reading:

TASKS PERFORMED

AIR CONDITIONING

NO PARTS USED

CSHOP-2015-1710

FRONT AC HOT R43 ALSO SHORE A/C INOP Comments:

> Date Opened 7-13-2015 Date Finished 7-21-2015 106,679 Meter 1 Reading:

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

AIR CONDITIONING

CSHOP-2015-1963

Comments: R43 RUBBER COVER OF THE CLOSED OPEN DOOR SENSOR US MISSING CAUSING THE DOOR ALARM AND THE

DOME LIGHT TO STAY ON

Date Opened 7-27-2015 8-2-2015 Date Finished Meter 1 Reading: 106,679

TASKS PERFORMED PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

DOOR LOCKS

CAB-INTERIOR ACCESSORIES

SWITCH; DOOR SWITCH

CSHOP-2015-2355

Comments: DIAMOND PLATE DRIVERS DOOR SEPARATING SHORELINE COVER BROKEN R43

Date Opened 8-17-2015 Date Finished 8-19-2015 Meter 1 Reading: 109,422

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

CSHOP-2015-2501

Comments: R43 AUTO EJECTS NOT WORKING

Date Opened 8-24-2015 Date Finished 9-2-2015 Meter 1 Reading: 109,422

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER AIR SYSTEM
AIR CONDITIONING

CSHOP-2015-2659

Comments: PM FOLLOW UPS TEMP GAGE READS 220 AND WARNING INTERMITTENT AIR HORN INOP R43 DRIVER SIDE

WINDOW STICKING - TOMMY, TRY SPRAYING TRACK WITH SILICONE IF TRACK NOT MESSED UP

Date Opened 9-2-2015 Date Finished 10-6-2015 Meter 1 Reading: 111,040

TASKS PERFORMED	Q	PARTS
SERPENTINE BELT OIL CHARGING SYSTEM TEMP GAUGE AIR CONDITIONING	1 1 1 1 1 1 1	PULLEY; IDLER PULLEY PULLEY; IDLER PULLEY BOLT COVER; IDLER DUST COVER BELT; BELT HORTON BELT; BELT PULLEY; PULLEY BUSHING COVER; COVER KUSSMAUL AUTO EJECT THERMOSTAT; 1842130C3 THERMOSTAT DT466

CSHOP-2015-2838

Comments: B-INSPECTION R43

Date Opened 9-10-2015 Date Finished 9-15-2015 Meter 1 Reading: 110,914

TASKS PERFORMED Q PARTS

PM SERVICE B

1 FILTER; 24316 WIX CAB A/C FILTER

1 FILTER: 57744XD OIL FILTER

1 FILTER; FUEL FILTER 2008 HORTON

CSHOP-2015-3004

Comments: R43 IS AT 31 AND WILL NOT START

Date Opened 9-21-2015 Date Finished 9-21-2015 Meter 1 Reading: 111,040

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

CRANKING SYSTEM

1 STARTER; 6808 38MT 12T STARTER

CSHOP-2015-3005

Comments: AIR LEAK R43

Date Opened 9-21-2015 Date Finished 9-21-2015 Meter 1 Reading: 111,040

TASKS PERFORMED

NO PARTS USED

AIR SYSTEM

CSHOP-2015-301

Comments: DOOR OPEN AUDIBLE WARNING INOP ONLY HAS VISUAL WARNING WICH IS NOT VISIBLE IN BRIGHT DAYLIGHT

R43

Date Opened 4-27-2015 Date Finished 6-18-2015 Meter 1 Reading: 106,635

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

GLASS

ALARM-BUZZER-WARNING LIGHT

1 BELT; BELT

AIR CONDITIONING

6 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

1

1 ALARM; O2 ALARM

BELT; BELT HORTON

CSHOP-2015-303

Comments: REAR FOLD UP BUMPER MISSING MOUNTING BOLTS R43

Date Opened 4-27-2015 Date Finished 4-27-2015 Meter 1 Reading: 103,200

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

STEPS

CSHOP-2015-3063

Comments: OIL LEAK R43

Date Opened 9-24-2015 Date Finished 9-28-2015 Meter 1 Reading: 111,040

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

AIR CONDITIONING

CSHOP-2015-3340

Comments: OIL LEAK RECHTIEN

Date Opened 10-9-2015 Date Finished 10-9-2015 Meter 1 Reading: 111,322

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2015-3435

Comments: R43 PATIENT AC

Date Opened 10-14-2015 Date Finished 10-16-2015 Meter 1 Reading: 111,645

TASKS PERFORMED Q PARTS

RADIATOR
HEADLIGHTS LOW BEAM

1 FITTING; 16-3409 A/C FITTING HIGH SIDE

AIR CONDITIONING

1 FITTING; 16-3408 A/C FITTING LOW SIDE

2 LIGHT; LOCK RING HEADLITE

2 VALVE; 8915 VALVE CORE A/C 3544706C1

Service Requests:

10/14/2015 A/C / 12: BROKEN / REPAIR

AC IN PATIENT COMPARTMENT NOT BLOWING COLD.

CSHOP-2015-3886

Comments: REAR STEP FALLING OFF UNIT R43

Date Opened 11-10-2015 Date Finished 11-10-2015 Meter 1 Reading: 113,284

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

STEPS

CSHOP-2015-4250

Comments: R43 FRONT TIRES

Date Opened 12-1-2015 Date Finished 12-1-2015 Meter 1 Reading: 114,400

TASKS PERFORMED NO PARTS USED

FRONT TIRES

VENDOR? EARL COLVARD BOULEVARD TIRE

CSHOP-2015-4357

Comments: R43

Date Opened 12-7-2015 Date Finished 12-8-2015 Meter 1 Reading: 115,017

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

1 BRAKE; BRAKE HOSE FR 262366-20

HOSES-LINES & FITTINGS (AIR &

Service Requests:

12/07/2015 BRAKES / 18: LEAKING / REPLACED R/F BRAKE HOSE.

AIR PRESSURE LEAK WHEN STEPPING ON BRAKE PEDAL.

CSHOP-2015-4494

Comments:

Date Opened 12-15-2015

Date Finished

12-16-2015

Meter 1 Reading:

115,557

TASKS PERFORMED

NO PARTS USED

AIR CONDITIONING

Service Requests: 12/15/2015

AIR RIDE / 19: LOOSE / REPAIR

R43 WAS EN ROUTE TO 31 FOR A MOVE UP.AFTER PULLING OUT ON TO MILITARY, THE LOW AIR ALARM WENT ON. PRIOR TO TURNING INTO ST31, THE ALARM SHUT OFF. THERE WAS NO ISSUES WITH THE BRAKES WHILE DRIVING

TO 31 FROM 43.

CSHOP-2015-4665

Comments: ON-CALL ENGINE SLOW TO START AND STAY RUNNING

Date Opened 12-28-2015 Date Finished 1-5-2016 Meter 1 Reading: 116,418

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

12/27/2015 ENGINE / 19: LOOSE / REPAIR

SLUGGISH TO START AFTER SITTING. WILL START AND STAY RUNNING.

CSHOP-2015-4678

Comments: ENGINE NOT STARTING

Date Opened 12-28-2015 Date Finished 1-4-2016 Meter 1 Reading: 116,353

TASKS PERFORMED Q PARTS

ENGINE AND ACCESSORIES

1 VALVE; VALVE COVER GASKET INT.

6 ADAPTER; INJ PUCK ADAPTER

1 FITTING; FUEL FITTING

1 SEAL; 1842626C96 OIL RAIL MANIFOLD SEALS

6 INJECTOR; 5010561R93 INJECTOR

1 SENSOR; 1875784C93 ICP SENSOR

1 PUMP; 1882259C94 HIGH PRESSURE OIL PUMP

CSHOP-2015-656

Comments: INVERTER NOT WORKING PROPERLY WHEN PLUGGED INTO SHORELINE STA,43 NOT IN STA, OUT ON CALL.

RETURN TO SHOP.

Date Opened 5-15-2015 Date Finished 6-3-2015 Meter 1 Reading: 106,635

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

CSHOP-2015-677

Comments: R43 OIL OVER FULL

Date Opened 5-18-2015 Date Finished 5-18-2015 Meter 1 Reading: 105,724

TASKS PERFORMED Q PARTS

OIL FILTER 1 FILTER: 57744XD OIL FILTER

30 MOTOR; 15W40 MOTOR OIL NON SYN

CSHOP-2015-926

Comments: R43 SHUT DOWN ON ROAD

Date Opened 6-1-2015 Date Finished 6-2-2015 Meter 1 Reading: 106,635

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

CSHOP-2016-1050

Comments: R43

Date Opened 3-4-2016 Date Finished 3-7-2016 Meter 1 Reading: 120,241

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER SAFTEY-EMERGENCY EQUIPMENT

Service Requests:

03/04/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

STRETCHER MOUNT BRACKET ON FLOOR OF PT COMPARTMENT IS LOOSE. ATTEMPTED TIGHTENING WITH NO

SUCCESS.

CSHOP-2016-1890

Comments: R43 BROKE DOWN AT COSTCO

Date Opened 4-21-2016 Date Finished 4-22-2016 Meter 1 Reading: 123,421

LOUD NOISE UNDER & SMOKE

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

1 FAN; FAN A/C COND 12IN 860026-2-W

A/C CONDENSER FAN

CSHOP-2016-1977

Comments: R43

Date Opened 4-26-2016 Date Finished 5-9-2016 Meter 1 Reading: 124,595

TASKS PERFORMED NO PARTS USED

ENGINE AND ACCESSORIES

Service Requests:

04/26/2016 OIL / 19: LOOSE / REPAIR

RESCUE IS LEAKING OIL (VERY SMALL AMOUNT). OIL LEVELS ARE GOOD

CSHOP-2016-20

Comments: R43 C INSPECTION - OIL JUST CHANGED FILTERS ONLY

Date Opened 1-4-2016 Date Finished 1-5-2016 Meter 1 Reading: 116,418

TASKS PERFORMED Q PARTS

PM SERVICE C RESCUE

1 FILTER; 24316 WIX CAB A/C FILTER

1 FILTER; 57744XD OIL FILTER

1 FILTER; FUEL FILTER 2008 HORTON

CSHOP-2016-2339

Date Opened 5-16-2016 Date Finished 5-25-2016 Meter 1 Reading: 125,515

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER

AIR CONDITIONING

CSHOP-2016-2583

Comments: R43
Date Opened 5-31-2016 Date Finished 9-7-2016 Meter 1 Reading: 131,602

TASKS PERFORMED Q PARTS

HOSE-LINES & FITTINGS
AIR CONDITIONING

1 BLOWER; BLOWER MTR. + SQU IRREL CAGE ASSY. 110

A/C

1 CHARGER; CONVERTOR 110V 80 AMP

1 MOTOR; USE 2284075 BLOWER MOTOR HORTON/MEDTEC

1 BLOWER; MOTOR BLOWER REAR CAB UNIT HORTON

3 A/C; FREON LB

Service Requests:

05/28/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

TRUCK IS NOT OUT OF SERVICE. WHEN PLUGGED IN TO THE SHORE LINE THE AC IS NOT COMING ON

06/15/2016 BODY / 12: BROKEN / REPAIR

HUB CAP IS OFF ON THE LT SIDE REAR. WE HAVE THE HUB CAP.

CSHOP-2016-2932

Date Opened 6-19-2016 Date Finished 7-17-2016 Meter 1 Reading: 128,732

TASKS PERFORMED Q PARTS

TRANSMISSION 1 NONSTOCK; PROGRAM FEE

1 NEWPART; MODULE TRANSMISSION CONTROL INT.

Service Requests:

06/19/2016 TRANSMISSION / 12: BROKEN / EXCHANGE - NEW

RESCUE WONT SHIFT WHEN DRIVING

CSHOP-2016-2987

Date Opened 6-21-2016 Date Finished 8-17-2016 Meter 1 Reading: 130,505

TASKS PERFORMED Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

CAB-INTERIOR ACCESSORIES AIR CONDITIONING

4 SWITCH; DOOR SWITCH

3 A/C; FREON LB

Service Requests:

06/21/2016 A/C / 18: LEAKING / REPAIR

AC DOES NOT WORK WHEN PLUGGED INTO SHORELINE. CREW PASS DOWN STATED THAT THE MECHANIC FIXED IT THE OTHER DAY. WE ARE STILL HAVING THE SAME ISSUE AS BEFORE- IT SOUNDS LIKE IT'S RUNNING WHEN IT IS

PLUGGED IN BUT THE AC IS NOT BLOWING

06/25/2016 ALARMS / 19: LOOSE / REPAIR

STATION 43 PASSENGER / REAR CAB DOOR. THE RUBBER COVERING 'DOOR OPEN' SENSOR SWITCH IS DAMAGED.

THE SWITCH DOES NOT FULLY DEPRESS WHEN DOOR IS CLOSED.

CSHOP-2016-3062

Comments: ON-CALL R43 COOLANT LEAK

Date Opened 6-27-2016 Date Finished 6-27-2016 Meter 1 Reading: 127,619

TASKS PERFORMED Q PARTS

EGR COOLER 2 HOSE: RAD HOSE

7 FLUID; 50-50 EXTENDED LIFE COOLANT GAL

CSHOP-2016-3096

Date Opened 6-27-2016 Date Finished 6-30-2016 Meter 1 Reading: 128,030

TASKS PERFORMED NO PARTS USED

CAB-INTERIOR ACCESSORIES

Service Requests:

06/27/2016 BODY / 19: LOOSE / REPAIR

ROOF LEAK IN BETWEEN THE CAB AND PT COMPARTMENT

CSHOP-2016-3208

Comments: R43 NO A/C

Date Opened 7-5-2016 Date Finished 7-5-2016 Meter 1 Reading: 128,045

TASKS PERFORMED	Q	PARTS

OIL
AIR CONDITIONING

26 MOTOR; 15W40 MOTOR OIL NON SYN
26 MOTOR; 15W40 MOTOR OIL NON SYN
4 ASSEMBLY: A COLUMN ATOR ASSEX INT

1 ASSEMBLY; ACCUMULATOR ASSY INT.

1 CAP; CAP A/C INTERNATIONAL

1 BELT; BELT TENSONER

1 TENSIONER; TENSIONER HORTON ADD ON A/C

2 A/C; FREON LB

1 CAP; CAP-BLUE R134 NEW #5574

2 CAP; CAP A/C INTERNATIONAL

1 VALVE; 2512331C1 EXP VALVE NAV1 COMPRESSOR; 03-0805 A/C COMPRESSOR

Service Requests:

07/05/2016 A/C / 12: BROKEN / EXCHANGE - NEW

THERE IS NO COOL OR COLD AIR AT ALL IN THE FRONT CAB. IT ACTUALLY BLOWS OUT WARM TO HOT AIR OUT. DID

MANY THINGS TO TROUBLESHOOT IT BUT NOTHING WORKED.

CSHOP-2016-39

Comments: PM FOLLOW UPS

DOOR WEATHER MOLDING

A/C FILTER SCREENS

CAB-INTERIOR ACCESSORIES

STEPS SEAT FRONT

Date Opened 1-5-2016 Date Finished 1-26-2016 Meter 1 Reading: 117,409

TASKS PERFORMED	Q	PARTS
A INSPECTION STRETCHER EQUIPMENT MOUNTING BRACKETS SIDE COMPARTMENT BODY DOOR PROP CYLINDER WIPER BLADES HOSE LOWER COOLING SYSTEM ENGINE AND ACCESSORIES LIGHTING SYSTEM BATTERY ALTERNATOR-GENERATOR WIRING TRANSMISSION WHEEL COVERS BRAKE INSPECTION REPAIR FROM PM - DECALS/CLEANLINESS AIR DRIER AIR SYSTEM	1 2 1 3 3 19 1 1 1 1 -1 2 1	HORTON; STREACHER HOLD DOWN WIPER; WIPER BLADE CAP; 9C3Z8101B RADIATOR CAP 10238 STANT BATTERY; BATTERY 950CCA HP-31D BATTERY; BATTERY EPA TAX \$1.50 PER BATTERY FLUID; ALLISON TRANS FLUID GAL FILTER; 29548988 TRANS FILTER ALLISON DRYER; AD-IP DRIER VALVE; PURGE VALVE AD-IP-IS VALVE; CAB AIR LEVEL VALVE INT VALVE; LEVELING VALVE VALVE; LEVELING VALVE NEWPART; HOLD DOWN REAR STEP FILTER; 18-2699 A/C FILTER

CSHOP-2016-4072

Date Opened 8-17-2016 Date Finished 8-20-2016 Meter 1 Reading: 130,686

TASKS PERFORMED NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

AIR CONDITIONING

CSHOP-2016-4371

Date Opened 9-7-2016 Date Finished 9-7-2016 Meter 1 Reading: 131,602

TASKS PERFORMED NO PARTS USED

DIAGNOSE ELECTRICAL CAB-INTERIOR ACCESSORIES

Service Requests:

09/04/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

THE MECHANISM TO HOLD THE STRETCHER IN PLACE NEEDS REPAIR,

CSHOP-2016-4424

Comments: CALL OUR R43 TIRE BRAKE ISSUE

Date Opened 9-10-2016 Date Finished 9-13-2016 Meter 1 Reading: 131,754

TASKS PERFORMED NO PARTS USED

BRAKES

CSHOP-2016-4440

PM SERVICE B

Date Opened 9-12-2016 Date Finished 9-12-2016 Meter 1 Reading: 131,829

TASKS PERFORMED Q PARTS

1 FILTER; 57744XD OIL FILTER

1 FILTER; 24316 WIX CAB A/C FILTER

30 FLUID; SYN OIL BULK QTS

1 FILTER; AIR FILTER

1 FILTER; FUEL FILTER 2008 HORTON

CSHOP-2016-4448

Date Opened 9-12-2016 Date Finished 9-15-2016 Meter 1 Reading: 131,838

TASKS PERFORMED Q PARTS

FUEL SYSTEM

LIGHTING SYSTEM

1 BULB; BULB

BULB; INTERIOR DOME BULB

BULB; INTERIOR DOME BULB

TIRE 1 BULB; BULB

BULB; BULB

BULB; BULB

DOOR PANEL

1 HORN; ELECTRIC HORN HI

CAB-INTERIOR ACCESSORIES
AIR CONDITIONING

1 HORN; ELECTRIC HORN LOW

1 BRAKE; BRK PEDAL PAD

1 LIGHT; LOUVER AC HORTON UV LIGHT

3 FILTER; PANEL FILTER

CSHOP-2016-4538

Date Opened 9-19-2016 Date Finished 9-19-2016 Meter 1 Reading: 132,169

TASKS PERFORMED NO PARTS USED

FRONT TIRES

VENDOR? DAN CALLAGHAN ENTERPRISES

CSHOP-2016-4897

Comments: R-43 TIMER LIGHTS NOT WORKING

Date Opened 10-13-2016 Date Finished 10-26-2016 Meter 1 Reading: 134,421

TASKS PERFORMED Q PARTS

LIGHTING SYSTEM
AIR CONDITIONING

3 LIGHT; DOME LED ROUND

Service Requests:

10/13/2016 LIGHTS / 19: LOOSE / REPAIR

VEHICLE LIGHTS NOT WORKING..... TIMER LIGHTS IN THE PT COMPARTMENT NOT COMING ON

10/25/2016 LIGHTS / 19: LOOSE / REPAIR

VEHICLE LIGHTS NOT WORKING.... ONLY HALF OF THE LIGHTS IN THE PT COMPARTMENT COME ON AND THEY ARE

EXTEREMLY DIM

10/25/2016 A/C / 19: LOOSE / REPAIR

A/C ISSUE... A/C IN FRONT CAB WORKS INTERMITTENTLY

CSHOP-2016-5310

Date Opened 11-14-2016 Date Finished 11-23-2016 Meter 1 Reading: 136,342

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

Service Requests:

11/13/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

DASHLIGHTS GOING ON AND OFF, CODE READING 2A 3 PIN FAIL

PM SERVICE C RESCUE

Date Opened 12-1-2016 Date Finisher	12-2	2-2016 Meter 1 Reading: 136,383	
TASKS PERFORMED	Q	PARTS	
DOOR PROP CYLINDER			
WIPER BLADES	3	STRUT; GSS6557UP STRUT-LIFT	
GOVERNOR	3	STRUT; GSS1783UQ STRUT-LIFT	
FAN CLUTCH	2	WIPER; WIPER BLADE	
COOLING SYSTEM	1	GOVERNOR; GOVERNOR D-2	
REPAIR FROM PM - REAR A/C	1	BELT; BELT	
REPAIR FROM PM - POWER STEERING	1	NEWPART; PULLEY FANHUB	
ALTERNATOR-GENERATOR	-1	BELT; BELT	
REPAIR FROM PM - REAR SUSPENSION	1	BELT; BELT	
REAR BRAKE DRUMS	10	FLUID; COOLANT ANTIFREEZE GAL	
BRAKE CHAMBER	1	VALVE; 1608 2 1/2 TON VALVE EXPANSION	
AIR DRIER	1	NEWPART; HOSE & FITTING	
AIR HORN	1	DRYER; 07-0602A DRIER A/C 7118	
A/C BELT REAR A/C	1	GASKET; PS RESV GASKET	
A/C FILTER SCREENS	2	FLUID; P/S FLUID	
AIR CONDITIONING	1	FILTER; 2503221C1 FILTER POWER STEERING	
	1	MOUNT; 4949PA/4962 320 AMP UPGRADE SADDLE MOUI	
	1	BELT; BELT HORTON	
	1	NEWPART; HOSE & FITTINGS CONNECTOR; RELAY CONNECTOR	
	2	BRAKE; GY1R11216 AIR BAG INT.	
	2	BRAKE; REAR DRUMS 3757X 3647X	
	2	BRAKE; HD SHOE KIT 3/8 BEAM	
	2	NEWPART; BRAKE CHAMBERS	
	2	BRAKES; CLEVIS KIT	
	1	DRYER; AD-IP DRIER	
	1	VALVE; PURGE VALVE AD-IP-IS	
	1	BRACKET; 244770R1 HORN SUPPORT BRKT	
	2	FILTER; PANEL FILTER	
	1	FILTER; 18-2699 A/C FILTER	
	1	BREAKER; BREAKER 30 AMP	
	1	CONNECTOR; RELAY CONNECTOR	
	1	BREAKER; THERMAL BREAKER 50 AMP	
CSHOP-2016-5635 Comments: C INSPECTION R43			
Date Opened 12-2-2016 Date Finisher	12-2	12-21-2016 Meter 1 Reading: 136,353	
TASKS PERFORMED	Q	PARTS	

FILTER; 57744XD OIL FILTER

FILTER; FUEL FILTER 2008 HORTON

CSHOP-2016-6083

Comments: R-43 FAULT CODE FOR MULTIPLEX

> Date Opened 12-29-2016 Date Finished 1-12-2017 Meter 1 Reading: 137,185

TASKS PERFORMED NO PARTS USED

INSTRUMENTS-GAUGES-WARNING &

Service Requests:

12/29/2016 SERVICE REQUEST / 19: LOOSE / REPAIR

IN THE MIDDLE OF THE CAB WHERE THE CONTROLS TO THE LIGHTS ARE THERE IS AN ERROR CODE READING "MOD

2A PIN 3 FAIL"

CSHOP-2016-636

R43 AIR LEAK Comments:

> Date Opened 2-9-2016 Date Finished 2-9-2016 Meter 1 Reading: 118,265

TASKS PERFORMED PARTS

TRAVEL TO BE CHARGED TO WORK ORDER BRAKE; GY1R11216 AIR BAG INT.

AIR SYSTEM

Service Requests:

02/09/2016 AIR RIDE / 18: LEAKING / EXCHANGE - NEW

AIR LEAK NEAR REAR SUSPENSION.

CSHOP-2016-719

Comments: R43

> Date Opened 2-16-2016 Date Finished 2-19-2016 Meter 1 Reading: 118,887

TASKS PERFORMED PARTS

TRAVEL TO BE CHARGED TO WORK ORDER

ENGINE AND ACCESSORIES

PUMP; 1893940C93 OIL LINE HIGH PRESS PUMP

Service Requests:

02/13/2016 A/C / 19: LOOSE / REPAIR

> THE FRONT AC IN THE CAB BLOWS INTERMITTENTLY. FOR EXAMPLE, WHEN GETTING BACK INTO THE RESCUE FROM PUBLIX THE FRONT AC WAS BLOWING. WHEN VEHICLE STARTED TO MOVE THE AC KICKED OFF THEN CAME BACK

ON. RESCUE STOPPED AT A STOP SIGN AND THE AC STOPPED. THE AC DID NOT START BLOWING AGAIN.

CSHOP-2017-1253

Date Opened 2-28-2017 Date Finished 3-1-2017 140,698 Meter 1 Reading:

TASKS PERFORMED **NO PARTS USED**

BODY EXTERIOR

Service Requests:

02/28/2017 BODY / 18: LEAKING / REPAIR

R43 LEAKING LARGE AMOUNTS OF WATER INTO CAB AND PATIENT COMPARTMENT AT OPENING BETWEEN RESCUE

CAB AND BOX.

CSHOP-2017-1343

Date Opened 3-6-2017 Date Finished 3-8-2017 Meter 1 Reading: 141,203

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM

Service Requests:

03/05/2017 RADIATOR / 18: LEAKING / REPAIR

> RADIATOR LEAKING AT A FAST RATE. WAS ONE OR TWO INCHES BELOW ADD LINE AT START OF SHIFT. PUT IN ENOUGH COOLANT TO BE JUST BELOW MAX LINE AND THE NEXT MORNING IT IS BACK TO ONE INCH BELOW ADD

LINE.

CSHOP-2017-1816

Date Opened 3-27-2017 Date Finished 4-19-2017 Meter 1 Reading: 143,655 Q

TASKS PERFORMED

FAULT CODE 9IP; BULB

ENGINE AND ACCESSORIES

9IP; OUTPUT MODULE HORTON LIGHTING SYSTEM

SWITCH; DOOR SWITCH REPAIR FROM PM - 110 A/C

LAMP; LAMP MARKER INT. DOOR PANEL

2 9XX; 134A 10194654

PARTS

9IP; LOUVER AC HORTON UV LIGHT

FILTER: 18-2699 A/C FILTER

INVERTER **STEERING**

BODY EXTERIOR DOOR PANEL GLOVE BOX

CAB-INTERIOR ACCESSORIES

A/C FILTER SCREENS

Service Requests:

OIL / 18: LEAKING / CLEAN ENGINE 03/24/2017

ENGINE IS LEAKING OIL.

CSHOP-2017-1918

Date Opened 3-31-2017 Date Finished 4-13-2017 143,602 Meter 1 Reading:

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

Service Requests:

03/31/2017 RADIATOR / 18: LEAKING / REPAIR

RADIATOR LEAKING, HAVING TO FREQUENTLY ADD COOLANT.

CSHOP-2017-2230

Date Opened 4-17-2017 4-19-2017 Date Finished Meter 1 Reading: 143,655

TASKS PERFORMED PARTS Q

PM SERVICE B 29 9OC: CONV 15W40

> FIL; NAPA GOLD FUEL FILTER 1 1 FIL; NAPA CABIN AIR FILTER

FIL; NAPAGOLD OIL FILTER

CSHOP-2017-25

Comments: R-43 AIR LEAK

Date Opened 1-3-2017 Date Finished 1-3-2017 Meter 1 Reading: 136,800

TASKS PERFORMED NO PARTS USED

AIR SYSTEM

CSHOP-2017-2738

Date Opened 5-9-2017 Date Finished 5-9-2017 Meter 1 Reading: 143,676

TASKS PERFORMED NO PARTS USED

COMMERCIAL WORK - OUTSIDE AGENCY

VENDOR? RECHTIEN INTERNATIONAL TRUCKS

CSHOP-2017-3338

Date Opened 6-6-2017 Date Finished 6-7-2017 Meter 1 Reading: 143,692

TASKS PERFORMED Q PARTS

ROOF 11 9IP; 10002439 WINDOW BELLOWS 6 IN

CSHOP-2017-3909

Date Opened 7-3-2017 Date Finished 7-5-2017 Meter 1 Reading: 143,699

TASKS PERFORMED Q PARTS

BATTERY
CHARGING SYSTEM
1 5EF; SWITCH
2 5EF; SWITCH

REPAIR FROM PM - REAR SUSPENSION

1 NONSTOCK; FREIGHT CHARGE

CSHOP-2017-41

Comments: R-43 OIL CHANGE

Date Opened 1-3-2017 Date Finished 1-5-2017 Meter 1 Reading: 136,894

TASKS PERFORMED Q PARTS

OIL 1 9IP; 9IP

LIGHTING SYSTEM

LIGHT BAR

Service Requests:

01/03/2017 OIL / 12: BROKEN / REPAIR

ENGINE OIL ABOVE MAX LEVEL ON R 43

01/03/2017 LIGHTS / 18: LEAKING / REPAIR

SCENE LIGHT ON BACK OF TRUCK ON THE DRIVERS SIDE NOT WORKING ON R 43

CSHOP-2017-4203

Comments: A/C NOT COOLING

> Date Opened 7-18-2017 7-20-2017 Date Finished Meter 1 Reading: 143,699

TASKS PERFORMED Q **PARTS**

BATTERY 3 1AD; BATTERY 31 SERIES AIR SYSTEM

AIR CONDITIONING

CSHOP-2017-476

R43 A/C ISSUE Comments:

> Date Opened 1-23-2017 Date Finished 2-10-2017 139,214 Meter 1 Reading:

TASKS PERFORMED NO PARTS USED

AIR CONDITIONING

Service Requests:

01/22/2017 A/C / 19: LOOSE / REPAIR

A/C ISSUE

CSHOP-2017-4971

AIR LEAKS NOTED Comments:

> Date Opened 8-24-2017 Date Finished 8-25-2017 143,873 Meter 1 Reading:

TASKS PERFORMED PARTS

AIR SYSTEM 2IH; VALVE PRESURE 1

CSHOP-2017-5071

Comments: R19

> Date Opened 8-29-2017 Date Finished 9-1-2017 144,173 Meter 1 Reading:

TASKS PERFORMED PARTS

TRAVEL TO BE CHARGED TO WORK ORDER STORAGE CABINET EMERGENCY VEH

CAB

SEAT FRONT

Service Requests:

08/28/2017 SERVICE REQUEST / 21: MISADJUSTED / REPAIR

SERVICE REQUEST DRIVER SEAT AIR SYSTEM DOES NOT WORK HOOKS TO HANG HEADSETS HEADSETS NOT

5SC; HELMET/HEADSET HOOK

WORKING LOCK IN CABINET FELL OUT

CSHOP-2017-5221

Comments: SR 20 AT STATION 19

Date Opened 9-6-2017 Date Finished 9-15-2017 Meter 1 Reading: 145,089

TASKS PERFORMED Q PARTS

COOLING SYSTEM 4 PAF; ANTIFRZ

Service Requests:

09/05/2017 A/C / 12: BROKEN / INSPECT

A/C ISSUE

CSHOP-2017-5277

Date Opened 9-11-2017 Date Finished 9-15-2017 Meter 1 Reading: 145,089

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

Service Requests:

09/11/2017 LIGHTS / 12: BROKEN / REPAIR

VEHICLE LIGHTS NOT WORKING, DRIVER SIDE GROUND HAZARD LIGHT BROKEN AND REMOVED, NEEDS

REPLACEMENT.

CSHOP-2017-5388

Comments: EGR SYSTEM POSSIBLE LEAK VERIFY GROUND LIGHT REPAIRED ROOFTOP A/C INOP

Date Opened 9-15-2017 Date Finished 11-17-2017 Meter 1 Reading: 149,942

TASKS PERFORMED Q PARTS

STORAGE CABINET EMERGENCY VEH

EGR COOLER

AIR CONDITIONING

1 2IH; KIT HOSE

1 2IH; INTAKE COOLER

4 2IH; EGR GASKET

1 2IH; EGR VALVE

1 2IH; EGR KIT

2 2IH; CLAMP

1 9AP; COMPRESSOR

3 8GR; FILTER

1 BK; TAPE

1 TEM; TAPE

-1 9IP; COMPRESSOR A/C 115V R22

1 9IP; COMPRESSOR A/C 115V R22

1 NONSTOCK; FREIGHT CHARGE

I TEM; PAG OIL

1 TEM; PAG OIL

CSHOP-2017-5610

Date Opened 9-27-2017 Date Finished 9-28-2017 Meter 1 Reading: 145,718

TASKS PERFORMED NO PARTS USED

COOLING SYSTEM

Service Requests:

09/27/2017 RADIATOR / 18: LEAKING / REPAIR

COOLANT SYSTEM VISUAL AND AUDIBLE ALARMS SOUNDING

CSHOP-2017-593

Comments: R43 A/C INTERMITTENT

Date Opened 1-26-2017 Date Finished 2-2-2017 Meter 1 Reading: 138,705

TASKS PERFORMED Q PARTS

BODY EXTERIOR
AIR CONDITIONING

1 2IH; 2IH

Service Requests:

01/26/2017 A/C / 18: LEAKING / REPAIR

A/C ISSUE- AC INTERMITTENT

CSHOP-2017-6108

Date Opened 10-23-2017 Date Finished 11-16-2017 Meter 1 Reading: 149,942

TASKS PERFORMED NO PARTS USED

AIR HORN

Service Requests:

10/23/2017 ALARMS / 18: LEAKING / ADJUST

ALARM SIGNALS/ AIR HORN NOT FUNCTIONING PROPERLY, DEPLETED AFTER 2 PUMPS

CSHOP-2017-6219

Date Opened 10-30-2017 Date Finished 11-16-2017 Meter 1 Reading: 149,942

TASKS PERFORMED Q PARTS

HEADLIGHTS LOW BEAM 1 AVB; CAPSULE

Service Requests:

10/29/2017 LIGHTS / 12: BROKEN / EXCHANGE - NEW

VEHICLE LIGHTS NOT WORKING OFFICERS HEADLIGHT OUT.

CSHOP-2017-6299

Date Opened 10-31-2017 Date Finished 11-16-2017 Meter 1 Reading: 149,942

TASKS PERFORMED Q PARTS

WIPER BLADES
AIR CONDITIONING

2 1AN; 22" WIPER BLADE

Service Requests:

10/31/2017 A/C / 18: LEAKING / EXCHANGE - REBUILT

A/C ISSUE PATIENT COMPARTMENT AC IS INOP. WARM AIR AND HISSING NOISE FROM UNDER CAPTAIN'S CHAIR.

CSHOP-2017-6730

Date Opened 11-22-2017 Date Finished 11-30-2017 Meter 1 Reading: 149,987

TASKS PERFORMED Q PARTS

STRETCHER 1 5SP; STRYKER RAIL ASSY

CSHOP-2017-6892

Comments: USE FOR PM FOLLOW UPS

Date Opened 12-3-2017 Date Finished 3-13-2018 Meter 1 Reading: 156,994

TASKS PERFORMED Q PARTS

STORAGE CABINET EMERGENCY VEH

STEP 1 9IP; 5632-14 DRAWER SLIDE 3 9ME; ZICO RATCHET STRAPS

REPAIR FROM PM - DRY AIR CLEANER

5 SML, 2100 NATOLLE STRAIGHT STR

PARK-CLEARANCE LIGHTS

1 SEF; HOLD DOWN REAR STEP

HEADLIGHTS LOW BEAM

-1
9IP; LATCH TRIGER W/O LOCK
9IP; LATCH TRIGER W/O LOCK

BRAKES

1 9IP; C2-32-15 LATCH NON LOCKING

REPAIR FROM PM - DECALS/CLEANLINESS

DOOR WEATHER MOLDING

TWD; REP/CART

DOOR LOCKS

1 TWD; PURGE VALVE ASSY KIT

2 MBI; GRIP/KIT

2 8GR; FILTER

Service Requests:

CABIN AIR FILTER

12/03/2017 TIRES / 44: WORN / INSPECT

BAD TIRES- THE LEFT SIDE FRONT TIRE HAS LOW THREAD AND NEEDS REPLACEMENT SOON. THE RIGHT SIDE IS

FINE.

CSHOP-2017-6969

Date Opened 12-6-2017 Date Finished 12-7-2017 Meter 1 Reading: 150,283

TASKS PERFORMED Q PARTS

PM SERVICE C RESCUE

1 FIL; NAPA GOLD FUEL FILTER

1 FIL; NAPAGOLD OIL FILTER

1 FIL; NAPA CABIN AIR FILTER

29 9OC; SYN 15W40

CSHOP-2017-888

Comments: R43

Date Opened 2-13-2017 Date

Date Finished

2-23-2017

Meter 1 Reading:

140,087

TASKS PERFORMED

NO PARTS USED

COOLING SYSTEM DIAGNOSE ELECTRICAL

Service Requests:

02/10/2017

SERVICE REQUEST / 18: LEAKING / REPAIR

R43 SHORELINE NOT CHARGING

CSHOP-2017-911

Date Opened 2-13-2017

Date Finished

2-14-2017

NO PARTS USED

Meter 1 Reading: 1

139,609

TASKS PERFORMED

TIRES & WHEELS

Service Requests:

02/13/2017

TIRES / 18: LEAKING / REPAIR

4 BAD TIRES

CSHOP-2018-1233

Date Opened 3-1-2018

Date Finished

3-2-2018

Meter 1 Reading:

155,862

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR?

DAN CALLAGHAN ENTERPRISES

Service Requests:

02/28/2018

TIRES / 18: LEAKING / EXCHANGE - NEW

DRIVER FRONT TIRE IS BALD AND WORSE ON INSIDE THREAD

CSHOP-2018-1285

Date Opened 3-2-2018

Date Finished

3-2-2018

Meter 1 Reading:

155,862

TASKS PERFORMED

NO PARTS USED

TIRE

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2018-2170

Date Opened 4-18-2018 Date Finished 4-19-2018 Meter 1 Reading: 157,498

TASKS PERFORMED PARTS

PM SERVICE B FIL; NAPAGOLD AIR FILTER

FIL; NAPA GOLD FUEL FILTER

FIL; NAPAGOLD OIL FILTER FIL; NAPA CABIN AIR FILTER

2IH; AIR FILTER -1

2IH; AIR FILTER

CSHOP-2018-2195

Comments: **USE FOR PM FOLLOW UPS**

> Date Opened 4-19-2018 Date Finished 5-24-2018 Meter 1 Reading: 157,500

REAR AC FILTER ,UV LT ,&LUVER ARE BAD

TASKS PERFORMED Q **PARTS**

SIDE COMPARTMENT BODY 2 5AH; GAS SPRING

KINGPIN 2IH; LIGHT DOME LIGHTS

2IH; LIGHT **TURN SIGNAL LIGHTS** 2IH; LAMP

PARK-CLEARANCE LIGHTS 2IH; HEADLAMP ASSY **BATTERY**

2IH; LIGHT **AUTO-EJECT**

2IH; HEADLAMP ASSY **BUMPER REAR**

2IH; LIGHT A/C FILTER SCREENS

5SC; AUTO EJECT KIT W/YELLOW CVR

5SC; AUTO EJECT KIT W/YELLOW CVR

9IP; LOUVER AC HORTON UV LIGHT

9IP; ULTRA VIOLET LIGHT SHORT

CSHOP-2018-266

SPARE RESCUE AT 41 Comments:

> Date Opened 1-11-2018 Date Finished 1-16-2018 151,369 Meter 1 Reading:

TASKS PERFORMED NO PARTS USED

AIR SYSTEM

Service Requests:

01/11/2018 SERVICE REQUEST / 18: LEAKING / REPAIR

AIR HORN IS WORKING INTERMITTENTLY.

CSHOP-2018-3013

Comments:

R36

Date Opened 5-31-2018 Date Finished

6-4-2018

Meter 1 Reading:

159,395

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER AIR CONDITIONING

Service Requests:

05/31/2018

A/C / 18: LEAKING / REPAIR

A/C ISSUE - FRONT CAB, MAIN A/C BLOWING WARM

CSHOP-2018-3187

Date Opened 6-7-2018

Date Finished

6-8-2018

Meter 1 Reading:

159,395

TASKS PERFORMED

STORAGE CABINET EMERGENCY VEH

PRE TRIP INSPECTION

WIPERS-WASHER

REPAIR FROM PM - O2 SYSTEM

LIGHTING SYSTEM

2 1AN; WIPER BLADE

PARTS

3 9ME; ZICO RATCHET STRAPS

2 9IP; BULB

CSHOP-2018-3482

Date Opened 6-21-2018

Date Finished

6-21-2018

Meter 1 Reading:

Meter 1 Reading:

160,114

TASKS PERFORMED

NO PARTS USED

TIRES ALL

VENDOR?

DAN CALLAGHAN ENTERPRISES

CSHOP-2018-3560

Date Opened 6-25-2018

Date Finished 6-27-2018

160,404

TASKS PERFORMED

PARTS Q

AIR CONDITIONING

2TK; BLOWER

TEM; NEW/CO

9XX; ACFREON10174676

1 **NBH**; SERPENTINEBELT

-1 SVP; COMPRSOR

SVP: COMPRSOR

Service Requests:

06/25/2018

A/C / 17: INSUFFICIENT LUBRICANT / REPAIR

PATIENT COMPARTMENT A/C FAILURE. BLOWING HOT AIR.

CSHOP-2018-4258

Comments: PAT A/C INOP AND LIGHTS OUT

Date Opened 7-30-2018 Date Finished 8-2-2018 Meter 1 Reading: 162,324

TASKS PERFORMED NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER DOME LIGHTS

AIR CONDITIONING

CSHOP-2018-5390

Date Opened 9-20-2018 Date Finished 10-18-2018 Meter 1 Reading: 162,324

TASKS PERFORMED Q PARTS

STRETCHER 2 5SP; POWER COMPATABILITY KIT

CSHOP-2018-848

Date Opened 2-8-2018 Date Finished 2-27-2018 Meter 1 Reading: 153,492

TASKS PERFORMED Q PARTS

HEADLIGHTS LOW BEAM 2 LMP; HALOGEN CAPSULE

RADIO-2016-655

Date Opened 10-24-2016 Date Finished 10-24-2016 Meter 1 Reading: 134,421

TASKS PERFORMED NO PARTS USED

RADIO

Service Requests:

10/24/2016 RADIO / /

R43 PM PAGER NOT WORKING

RADIO-2018-200

Comments: REMOVED 10188238, INSTALLED 10205588 INTO SR20 10182627

Date Opened 3-22-2018 Date Finished 3-22-2018 Meter 1 Reading: 0

TASKS PERFORMED NO PARTS USED

MOBILE RELATED

Service Requests:

03/22/2018 RADIO / /

REMOVE & INSTALL MOTOROLA MOBILE RADIO INTO SPARE RESCUE 20