

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

**Workorder:** 552621

**Problem:** P.M.

Meter Reading: 0	Labor	Parts	
In Date: 08/09/2005	Hours	Description	Quantity
- Replace Damaged Navigational Light And Repair Wiring	5.00	LITE 50-05011	-1.00
- Pm Hull		LITE 50-05011	1.00
- Pressure Clean Hull		LITE 50-05011	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	28.34	<b>Labor Charge:</b>	250.00

**Workorder:** 645255

**Problem:** PM SERVICE/STEERS STIFF AND STALLS WHEN COLD

Meter Reading: 0	Labor	Parts	
In Date: 09/08/2006	Hours	Description	Quantity
- Pm Hull	5.00	MARINE 24 BATTERY DEEP CYCLE (ACD M24MF)	1.00
- Replace Battery		SHOP SUPPLIES	1.00
- R&R Steering Cable & Lube			
- Pressure Clean Hull			
- Shop Supplies			
<b>Parts Charge:</b>	48.58	<b>Labor Charge:</b>	50.00

**Workorder:** 841111

**Problem:** CHANGE TRAILER HITCH TO 2 5/16"

Meter Reading: 0	Labor	Parts	
In Date: 07/09/2008	Hours	Description	Quantity
- Change Out 1 7/8 Hitch To 2 5/16 Hitch	4.50	HITCH COUPLER	1.00
- Replace Bow Stop		1/2X6X12 ALUM FLAT BAR	1.00
- Ck & Repair Tail Lights-Replace Both Led Tail Lights		BOW BLOCK STOP	1.00
Bulbs Burnt Out.		LH LED TAILLIGHT	1.00
- Ck & Repair Spare Tire		RH LED TAILLIGHT	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	211.81	<b>Labor Charge:</b>	60.00

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

**Workorder:** 932396

**Problem:** PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 01/06/2009	Hours	Description	Quantity
- Pm Hull	5.00	FUEL ADDITIVE	1.00
- Repair Migration Wire Harness And Replace Light Pole		LIGHT BASE ASSY	1.00
Plug Socket		SHOP SUPPLIES	1.00
- Clean Hull		MARINE 24 BATTERY DEEP CYCLE (ACD M24MF)	1.00
- Replace Battery Wont Hold A Load			
- Shop Supplies			
<b>Parts Charge:</b>	122.45	<b>Labor Charge:</b>	300.00

**Workorder:** 936624

**Problem:** STEERING LOCKED UP/BINDS

Meter Reading: 0	Labor	Parts	
In Date: 04/17/2009	Hours	Description	Quantity
- Replace Helm And Cable Assy, Clean Tilt Tube And Lube	3.00	NO FEED BACK STEERIN CABLE	1.00
- Shop Supplies		STEERING BRUSH TUBE	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	387.76	<b>Labor Charge:</b>	180.00

**Workorder:** 942603

**Problem:** REPAIR SNAP RING AT LOWER MOTOR MOUNT

Meter Reading: 0	Labor	Parts	
In Date: 08/27/2009	Hours	Description	Quantity
-			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00

**Workorder:** 1002784

**Problem:** pm

Meter Reading: 0	Labor	Parts	
In Date: 03/18/2010	Hours	Description	Quantity
- Pm Hull	3.70	RING FREE	1.00
- Replace Frt Hatch Cover Assy		SHOP SUPPLIES	1.00
- Replace Fire Ext.		FIRE EXTINGUISHER	1.00
- Replacement Leaning Post Cushion		HATCH COVER	1.00
- Shop Supplies			
<b>Parts Charge:</b>	208.95	<b>Labor Charge:</b>	222.00
		<b>Commercial Charge:</b>	201.76

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

**Workorder:** 1104677

**Problem:** pm service/ steering locks up

Meter Reading: 0	Labor	Parts	
In Date: 05/02/2011	Hours	Description	
Close Date: 05/25/2011		Quantity	
- Pm Service Hull	4.00	SHOP SUPPLIES	1.00
- R/R Steering Cable At Motor, Clean And Lube		FIRE EXTINGUISHER	1.00
- Clean Bilge Area And Outside Of Hull			
- Shop Supplies			
<b>Parts Charge:</b>	27.14	<b>Labor Charge:</b>	240.00

**Workorder:** 1205451

**Problem:** PM / see request

Meter Reading: 0	Labor	Parts	
In Date: 06/11/2012	Hours	Description	
Close Date: 06/29/2012		Quantity	
- Pm Hull	5.00	HATCH ASSY	1.00
- Repair Crackat Bottome Of Hull		SHOP SUPPLIES	1.00
- Make And Replace Hull Fla Vessel#S			
- Shop Supplies			
<b>Parts Charge:</b>	140.92	<b>Labor Charge:</b>	300.00

**Workorder:** 1303922

**Problem:** PM BOAT / Fire ex. needs remounted (see request)

Meter Reading: 0	Labor	Parts	
In Date: 04/22/2013	Hours	Description	
Close Date: 05/09/2013		Quantity	
- Pm	7.00	FUEL ADDITIVE	1.00
- Repair Hull Under Rub Rail After Removal Of Rub Rail		SHOP SUPPLIES	1.00
- Repalce And Relocate Fire Ext.		FR/EXTIN	1.00
- Shop Supplies			
<b>Parts Charge:</b>	66.28	<b>Labor Charge:</b>	420.00

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

**Workorder:** 1308440

**Problem:** replace rigging for new motor

Meter Reading: 0		Labor		Parts	
In Date: 08/21/2013	Close Date: 09/13/2013	Hours	Description		Quantity
-	Remove All Rigging And Replace Rigging To Accept New Motor	16.00	SHOP SUPPLIES		1.00
			RULE 500GPH BILGE PUMP		1.00
-	Make And Install New F'S		2" HOLE BLANK		2.00
-	Cut New Holes In Dash To Accept Rigging		KEY SWITCH		1.00
-	Replace Bilge Plugs Broken Exhaust Nipple		STEERING CABLE ASSY		2.00
-	Shop Supplies		FUEL FILTER ASSY		1.00
			5/16 FUEL HOSE		14.00
			TACHOMETER RIGGING KIT 2		1.00
			WIRING HARNESS		1.00
			RIGGING FLANGE - BLACK		1.00
			RIGGING TUBE		8.00
			BINNACLE REMOTE CNTRL ASSY		1.00
	<b>Parts Charge:</b> 1,668.35	<b>Labor Charge:</b>	960.00		

**Workorder:** 1401815

**Problem:** pm service

Meter Reading: 0		Labor		Parts	
In Date: 02/25/2014	Close Date: 03/14/2014	Hours	Description		Quantity
-	Hull Pm	2.00	SHOP SUPPLIES		1.00
-	Shop Supplies		FUEL ADDITIVE		1.00
	<b>Parts Charge:</b> 30.22	<b>Labor Charge:</b>	120.00		

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

Workorder: 1502468

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 03/10/2015	Hours	Description	Quantity
- Pm	5.50	SCREW	10.00
- Repair Numerous Corroded Connections Replace Ground		FUSE HOLDER	1.00
Lead To Switch , R/R Switch Repair Bow Light Mount		SHOP SUPPLIES	1.00
New Stern Light Base And Pole Install Pole Mounting		LED POLE LT W/BLK LK BASE	1.00
Hardware		ALL AROUND LIGHT W BASE	1.00
- Shop Supplies		RUBBER STORAGE CLIPS	1.00
		YAMAHA FUEL FILTER	1.00
		PUSH PULL SWITCH	1.00
		FUEL FILTER	1.00
		SCREW	25.00
		Freight Charge	1.00
<b>Parts Charge:</b>	144.31	<b>Labor Charge:</b>	330.00

Workorder: 1509984

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 10/01/2015	Hours	Description	Quantity
- Pm	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		YAMAHA FUEL FILTER	1.00
		FUEL ADDITIVE	2.00
<b>Parts Charge:</b>	48.41	<b>Labor Charge:</b>	120.00

Workorder: 1603669

Problem: hard to steer

Meter Reading: 0	Labor	Parts	
In Date: 04/07/2016	Hours	Description	Quantity
- Replace Steering Helm And Cable	5.50	BRAKE CLEANER	2.00
- Shop Supplies		MARINE BEARING GREASE	1.00
		SHOP SUPPLIES	1.00
		STEERING HELM W/CONTROL CABLE	1.00
<b>Parts Charge:</b>	404.52	<b>Labor Charge:</b>	330.00

1/3/2017  
4:39:12PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10125012 1999 RIVIERA FIBER CORPORATION OPEN FISHERMAN Boat, 16 Ft. Center Console

Workorder: 1610422

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/04/2016	Hours	Description	
- Transition Prep Charge	2.00		
Parts Charge: 0.00	Labor Charge: 0.00		

Total Parts Charges:	<b>3,538.04</b>	Total Labor Charges:	<b>3,882.00</b>	Total Comm. Charges:	<b>201.76</b>
----------------------	-----------------	----------------------	-----------------	----------------------	---------------