

1/6/2017  
5:14:25PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169554 2007 YAMAHA LF250TXR Boat Motor, 250 Hp, Outboard

**Workorder:** 739878

**Problem:** PRE-DELIVERY INSPECTION

<b>Meter Reading:</b> 0	<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 06/11/2007	<b>Hours</b>	<b>Description</b>
<b>Close Date:</b> 06/11/2007		<b>Quantity</b>
- Pre-Delivery Inspection	<b>4.00</b>	
<b>Parts Charge:</b> 0.00	<b>Labor Charge:</b> 220.00	

**Workorder:** 742062

**Problem:** 10 HOUR SERVICE

<b>Meter Reading:</b> 10	<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 07/26/2007	<b>Hours</b>	<b>Description</b>
<b>Close Date:</b> 07/31/2007		<b>Quantity</b>
- Perform 10 Hour Break In Service	<b>5.00</b>	1066 WHITE LITHIUM (CRC 05037) 1.00
- Travel To P/U Parts		SHOP SUPPLIES 1.00
- Lower Unit Service		69J-13440-00-00 OIL FILTER 1.00
- Shop Supplies		10W30 MOTOR OIL 6.00
<b>Parts Charge:</b> 57.49	<b>Labor Charge:</b> 110.00	

**Workorder:** 833792

**Problem:** SERVICE

<b>Meter Reading:</b> 60	<b>Labor</b>	<b>Parts</b>
<b>In Date:</b> 02/06/2008	<b>Hours</b>	<b>Description</b>
<b>Close Date:</b> 02/28/2008		<b>Quantity</b>
- Pm Outboard With R/R Lower Cowlings	<b>7.00</b>	10W30 MOTOR OIL 6.00
- Cooling Sys Service W/Replacement Of 2 Thermostats		SPARK PLUG 6.00
- Lower Unit Service		OIL FILTER ASSY 1.00
- Shop Supplies		WATER PUMP REPAIR KT 1.00
		FUEL FILTER 2.00
		SHOP SUPPLIES 1.00
		GEAR LUBE 1.00
		THERMOSTAT ASSY 2.00
		THERMOSTAT SEAL 2.00
<b>Parts Charge:</b> 441.02	<b>Labor Charge:</b> 120.00	

1/6/2017  
5:14:25PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169554 2007 YAMAHA LF250TXR Boat Motor, 250 Hp, Outboard

**Workorder:** 932795

**Problem:** PM ENGINE

<b>Meter Reading:</b> 60 <b>In Date:</b> 01/14/2009	<b>Close Date:</b> 02/12/2009	<b>Labor Hours</b>	<b>Description</b>	<b>Parts</b>	<b>Quantity</b>
- Pm Outboard		<b>6.00</b>	THERMOSTAT SEAL		2.00
- Cooling Sys Service			FUEL ADDITIVE		2.00
- Lower Unit Service			WATER PUMP KIT		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			10W30 MOTOR OIL		6.00
			SPARK PLUG		6.00
			FUEL FILTER ELEMENT		1.00
			OIL FILTER ASSY		1.00
			THERMOSTAT ASSY		2.00
	<b>Parts Charge:</b> 400.50	<b>Labor Charge:</b> 360.00			

**Workorder:** 946732

**Problem:** PM outboard

<b>Meter Reading:</b> 60 <b>In Date:</b> 12/07/2009	<b>Close Date:</b> 01/11/2010	<b>Labor Hours</b>	<b>Description</b>	<b>Parts</b>	<b>Quantity</b>
- Pm-Outboard		<b>8.00</b>	FUEL FILTER		1.00
- Cooling System Service			TRIM TAB		1.00
- Lower Unit Gear Lube Service			SHOP SUPPLIES		1.00
- Replace Engine Spacers Customer Parts			FUEL ADDITIVE		1.00
- Shop Supplies			COWLING TRIM SWITCH		1.00
			OIL FILTER		1.00
			SPARK PLUGS		6.00
			WATER PUMP REPAIR KIT		1.00
			10W30 MOTOR OIL		6.00
			THERMOSTAT ASSY		2.00
	<b>Parts Charge:</b> 468.05	<b>Labor Charge:</b> 960.00			

1/6/2017  
5:14:25PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169554 2007 YAMAHA LF250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1100732

Problem: pm service

Meter Reading: 419	Labor	Parts	
In Date: 01/19/2011	Hours	Description	Quantity
- Pm	7.00	FUEL FILTER	1.00
- Cooling Sys Service		YAMAHA GAR LUBE - GAL	1.00
- L/V Service		SPARK PLUGS	6.00
- Shop Supplies		WATER PUMP REPAIR KIT	1.00
		TRIM TAB	1.00
		10W30 MOTOR OIL	6.00
		OIL FILTER	1.00
		SHOP SUPPLIES	1.00
		ANODE	1.00
		THERMOSTATS	2.00
<b>Parts Charge:</b>	468.68	<b>Labor Charge:</b>	420.00

Workorder: 1201350

Problem: PM

Meter Reading: 574	Labor	Parts	
In Date: 02/09/2012	Hours	Description	Quantity
- Pm Outboard	9.00	TRIM SENDER	1.00
- Cooling Sys Service		10W30 MOTOR OIL	6.00
- Lower Gear Case Service		FUEL FILTER	1.00
- Replace Trim Sender		WATER PUMP REPAIR KIT	1.00
- Shop Supplies		THERMOSTAT SEAL	2.00
		OIL FILTER	1.00
		SPARK PLUGS	6.00
		THERMOSTAT	2.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	520.23	<b>Labor Charge:</b>	540.00

1/6/2017  
5:14:25PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169554 2007 YAMAHA LF250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1302189

Problem: pm/ cuts out WOT

Meter Reading: 822	Labor	Parts	
In Date: 03/04/2013	Hours	Description	Quantity
- Pm Outboard	10.00	FUEL FILTER ELEMENT	1.00
- Cooling Sys Service		10W30 MOTOR OIL	6.00
- Replace Timing Belt		OIL FILTER	1.00
- Conduct Compression Test On All Cyl.		SPARK PLUG	6.00
- Lower Gear Case Service		WATER PUMP REPAIR KIT	1.00
- Shop Supplies		THERMOSTAT ASSY	2.00
		GEAR LUBE GL	1.00
		THERMOSTAT SEAL	2.00
		SHOP SUPPLIES	1.00
		FUEL FILTER ASSY	1.00
		TIMING BELT	1.00
<b>Parts Charge:</b>	892.82	<b>Labor Charge:</b>	600.00

Workorder: 1404240

Problem: pm service

Meter Reading: 912	Labor	Parts	
In Date: 05/01/2014	Hours	Description	Quantity
- Pm Outboard	7.00	SPARK PLUG	6.00
- Cooling Sys Service W/Thermostat		THERMOSTAT ASSY	2.00
- Gear Case Service		WATER PUMP REPAIR KIT	1.00
- Shop Supplies		10W30 MOTOR OIL	6.00
		FUEL FILTER ELEMENT	1.00
		ANODE GROMMET	4.00
		YAMAHA GEAR LUBE QT	1.00
		POWERHEAD ANODE	4.00
		THERMOSTAT SEAL	2.00
		NAPA GOLD OIL FILTER	1.00
		ANODIC TRIM TAB	1.00
		SHOP SUPPLIES	1.00
		WHEEL BEARING GREASE	1.00
<b>Parts Charge:</b>	485.99	<b>Labor Charge:</b>	420.00

1/6/2017  
5:14:25PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169554 2007 YAMAHA LF250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1601378

Problem: pm service

Meter Reading: 912

In Date: 02/09/2016

Close Date: 02/12/2016

Labor

Hours

Description

Parts

Quantity

---

- Pm Service And Repairs Did By Outside Vendor

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **3,734.78**

Total Labor Charges: **3,750.00**

Total Comm. Charges: **0.00**