

1/6/2017
5:16:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169555 2007 YAMAHA F250TXR Boat Motor, 250 Hp, Outboard

Workorder: 739879

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 06/11/2007	Hours	Description	Quantity
- Pre-Delivery Inspection	4.00		
Parts Charge: 0.00	Labor Charge: 220.00		

Workorder: 742063

Problem: 10 HOUR SERVICE

Meter Reading: 10	Labor	Parts	
In Date: 07/26/2007	Hours	Description	Quantity
- Perform 10Hr Break In Service	5.00	10W30 MOTOR OIL	6.00
- Travel To P/R Parts		091343 CARB CLEANER	1.00
- Lower Unit Service		69J-13440-00-00 OIL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 57.50	Labor Charge: 110.00		

Workorder: 833793

Problem: SERVICE

Meter Reading: 60	Labor	Parts	
In Date: 02/06/2008	Hours	Description	Quantity
- Pm Outboard W/R/R Lower Cowlings	7.00	OIL FILTER ASSY	1.00
- Cooling Sys Service W/Replacement Of 2 Thermostats		FUEL ADDITIVE	2.00
- Lower Unit Service		WATER PUMP REPAIR KT	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		THERMOSTAT ASSY	2.00
		10W30 MOTOR OIL	6.00
		SPARK PLUG	6.00
		THERMOSTAT SEAL	2.00
		FUEL FILTER	2.00
Parts Charge: 430.11	Labor Charge: 120.00		

1/6/2017
5:16:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169555 2007 YAMAHA F250TXR Boat Motor, 250 Hp, Outboard

Workorder: 932796

Problem: PM ENGINE

Meter Reading: 60 In Date: 01/14/2009	Close Date: 02/19/2009	Labor Hours	Description	Parts	Quantity
- Outboard Pm Service		6.50	FUEL FILTER		1.00
- Cooling Sys Service			OIL FILTER		1.00
- Lower Unit Service			SPARK PLUG		6.00
- Shop Supplies			FUEL ADDITIVE		2.00
			WATER PUMP KIT		1.00
			THERMOSTAT ASSY		2.00
			10W30 MOTOR OIL		6.00
			SHOP SUPPLIES		1.00
			THERMOSTAT SEAL		2.00
Parts Charge:		400.50	Labor Charge:		390.00

Workorder: 946733

Problem: PM Outboard

Meter Reading: 60 In Date: 12/07/2009	Close Date: 01/11/2010	Labor Hours	Description	Parts	Quantity
- Pm Outboard		8.00	SHOP SUPPLIES		1.00
- Cooling System Service			TRIM TAB		1.00
- Lower Unit Gear Lube Service			FUEL ADDITIVE		1.00
- Replace Engine Space Kit (Customer Part)			WATER PUMP REPAIR KIT		1.00
- Shop Supplies			COWLING TRIM SWITCH		1.00
			10W30 MOTOR OIL		6.00
			THERMOSTAT ASSY		2.00
			OIL FILTER		1.00
			FUEL FILTER		1.00
			SPARK PLUGS		6.00
Parts Charge:		468.05	Labor Charge:		960.00

1/6/2017
5:16:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169555 2007 YAMAHA F250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1100733

Problem: pm service

Meter Reading: 420	Labor	Parts	
In Date: 01/19/2011	Hours	Description	Quantity
- Pm	7.00	SHOP SUPPLIES	1.00
- Cooling Sys Service		FUEL FILTER	1.00
- L/V Service		OIL FILTER	1.00
- Shop Supplies		THERMOSTAT ASSY	2.00
		WATER PUMP REPAIR KIT	1.00
		ANODE	1.00
		SPARK PLUGS	6.00
		YAMAHA GEAR LUBE - GAL	1.00
		TRIM TAB	1.00
		10W30 MOTOR OIL	6.00
Parts Charge:	468.68	Labor Charge:	420.00

Workorder: 1201351

Problem: PM

Meter Reading: 575	Labor	Parts	
In Date: 02/09/2012	Hours	Description	Quantity
- Pm Outboard	9.00	OIL FILTER	1.00
- Cooling Sys Service		THERMOSTAT	2.00
- Lower Unit Gear Case Service		SPARK PLUGS	6.00
- Replace Trim Sender		FUEL FILTER	1.00
- Shop Supplies		WATER PUMP REPAIR KIT	1.00
		THERMOSTAT SEAL	2.00
		10W30 MOTOR OIL	6.00
		SHOP SUPPLIES	1.00
		TRIM SENDER	1.00
Parts Charge:	520.23	Labor Charge:	540.00

1/6/2017
5:16:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169555 2007 YAMAHA F250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1302190

Problem: pm/ cuts out WOT

Meter Reading: 820	Labor	Parts	
In Date: 03/04/2013	Hours	Description	Quantity
- Pm Outboard	10.00	ANODE GROMMET	4.00
- Cooling Sys Service		FUEL FILTER ELEMENT	1.00
- Replace Timing Belt		10W30 MOTOR OIL	6.00
- Conduct Compression Test On All Cyl		OIL FILTER	1.00
- Lower Gear Case Service		SPARK PLUG	6.00
- Shop Supplies		WATER PUMP REPAIR KIT	1.00
		THERMOSTAT SEAL	2.00
		TIMING BELT	1.00
		THERMOSTAT ASSY	2.00
		FUEL FILTER ASSY	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	844.90	Labor Charge:	600.00

Workorder: 1404242

Problem: pm service

Meter Reading: 913	Labor	Parts	
In Date: 05/01/2014	Hours	Description	Quantity
- Pm Outboard	7.00	FUEL FILTER ELEMENT	1.00
- Cooling Sys Service		POWERHEAD ANODE	4.00
- Gear Case Service		ANODE GROMMET	4.00
- Shop Supplies		THERMOSTAT SEAL	2.00
		WHEEL BEARING GREASE	1.00
		ANODIC TRIM TAB	1.00
		10W30 MOTOR OIL	6.00
		NAPA GOLD OIL FILTER	1.00
		YAMAHA GEAR LUBE QT	1.00
		WATER PUMP REPAIR KIT	1.00
		SPARK PLUG	6.00
		THERMOSTAT ASSY	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	485.99	Labor Charge:	420.00

1/6/2017
5:16:16PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10169555 2007 YAMAHA F250TXR Boat Motor, 250 Hp, Outboard

Workorder: 1601379

Problem: pm service

Meter Reading: 913

In Date: 02/09/2016

Close Date: 02/12/2016

Labor
Hours

Description

Parts

Quantity

- Pm Service And Repairs Did By Outside Vendors

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: **3,675.96**

Total Labor Charges: **3,780.00**

Total Comm. Charges: **0.00**