

**Palm Beach County Fleet Management
Asset Maintenance History**

10174404 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 839098 **Meter:** 0 **In Date:** 05/29/2008 **Closed:** 05/29/2008
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 839219 **Meter:** 335 **In Date:** 05/30/2008 **Closed:** 06/05/2008
Problem: INSTALL LADDER RACK

- Fabricate & Install Ladder Rack

- Shop Supplies

Parts List **Qty**

Shop Supplies 1.00

Ladder Rack 1.00

Hours 4.00 Labor: 240.00 Parts: 347.60 Total: 587.60
:

Workorder: 934974 **Meter:** 6396 **In Date:** 03/10/2009 **Closed:** 03/16/2009
Problem: P.M. SERVICE.

- Pm Service

- Flush Contaminated Pwst System.

- Shop Supplies

Parts List **Qty**

Shop Supplies 1.00

Ca10262 Air Filter Mtc Fa1883 Wix 49883 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

Syn/atf Trans Fluid Synthetic 3.00

Syn/atf Trans Fluid Synthetic 3.00

Hours 3.75 Labor: 225.00 Parts: 57.45 Total: 282.45
:

Workorder: 944355 **Meter:** 9367 **In Date:** 10/08/2009 **Closed:** 10/16/2009
Problem: P.M. Service.

- P.m service.

- Rotate & balance all four tires

- Shop Supplies

Parts List **Qty**

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

G10166 Fuel Filter Mtc Fg1083 Wix 33243 1.00

5w20 Engine Oil 7.00

31-20 Wiper Blades 20" Blade 2.00

Used Firex Refurbed Fire Extingshers 1.00

Hours 3.75 Labor: 225.00 Parts: 58.31 Total: 283.31
:

Workorder: 1003475 **Meter:** 12904 **In Date:** 04/05/2010 **Closed:** 04/13/2010
Problem: P.M service, see note.

- P.m service.

- Shop Supplies

Parts List **Qty**

Shop Supplies 1.00

Big G Degreaser Stock# 485180002 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

31-20 Wiper Blades 20" Blade 2.00

Hours 2.75 Labor: 165.00 Parts: 33.58 Total: 198.58
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1006163 **Meter:** 14908 **In Date:** 06/10/2010 **Closed:** 07/09/2010
Problem: Install side boxes in nbed.

- Fabricate mounting and install two new side tool boxes in bed as per request. and secure.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
	Side Mount Box	2.00
Hours 1.50	Labor: 90.00	Parts: 596.00
:		Total: 686.00

Workorder: 1012859 **Meter:** 17215 **In Date:** 11/17/2010 **Closed:** 12/03/2010
Problem: Pm service also see notes check engine and tire pressure warning light.Engine misfires.

- Perform pm service.	Parts List	Qty
- Rotate and balance all four tires.	Shop Supplies	1.00
- Transport vehicle to and from dealer for replacing failed #7 ignition coil and spark plug with new under factory warranty.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	Ca10262 Air Filter Mtc Fa1883 Wix 49883	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	7090blk Frt Floor Mats (rubber Queen)	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.75	Labor: 345.00	Parts: 90.70
:		Total: 435.70

Workorder: 1013276 **Meter:** 17234 **In Date:** 12/02/2010 **Closed:** 12/06/2010
Problem: reflash canceiver spot #228

- Reflash Canceiver and Reprogram	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1103351 **Meter:** 19661 **In Date:** 03/29/2011 **Closed:** 03/29/2011
Problem: Right rear tire flat.

- Repair flat right rear tire.nitrogen fill and balance.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1105257 **Meter:** 20952 **In Date:** 05/17/2011 **Closed:** 05/26/2011
Problem: Pm service also see notes on tail gate and low tire light concern

- Perform pm service.	Parts List	Qty
- Test and replace failed ac blower motor resistor with new.clean debri from recirclation screen housing.	Shop Supplies	1.00
- Replace failed tailgate bushings with new.shim hinge and adjust to open and close.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Install four new tires.nitrogen fill and balance all.	G10166 Fuel Filter Mtc Fg1083 Wix 33243	1.00
- Perform wheel alignment complete.	5w20 Engine Oil	7.00
- Shop Supplies	A/c Blower Resistor	1.00
	Bushing	1.00
	Bushing	1.00
	31-20 Wiper Blades 20" Blade	2.00
	Used Firex Refurbed Fire Extingshers	1.00
	179636492 Lt245/75r17 Wrangler Sr-a E	4.00
	Tire Disposal Fee	4.00
	Tr416 Valve Stem	4.00
Hours 9.25	Labor: 555.00	Parts: 834.48
:		Total: 1,389.48

Workorder: 1112109 **Meter:** 24798 **In Date:** 11/10/2011 **Closed:** 11/22/2011
Problem: Pm service.

- Preform pm service.	Parts List	Qty
- Test starting and charging system.battery failed load test after recharge.replace failed battery with new.	Shop Supplies	1.00
- Repack and adjust both front wheel bearings.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Rotate and balance all four tires.	1066 White Lithium (crc 05037)	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
	Group 65 Battery (mtc Bxt-65-850)	1.00
Hours 5.75	Labor: 345.00	Parts: 165.30
:		Total: 510.30

Workorder: 1203465 **Meter:** 28104 **In Date:** 04/12/2012 **Closed:** 04/16/2012
Problem: Right rear tire going flat.

- Repair and balance right rear tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1204692 **Meter:** 29099 **In Date:** 05/17/2012 **Closed:** 05/24/2012
Problem: Pm service also check over all lights,see notes.

- Perform pm service.	Parts List	Qty
- Inspect and replace failed left rear turnsignal lamp bulb with new.	Shop Supplies	1.00
- Rotate and balance all four tires.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	3157 Tail Light Bulbs	1.00
Hours 4.25	Labor: 255.00	Parts: 38.72
:		Total: 293.72

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1208517 **Meter:** 31083 **In Date:** 09/07/2012 **Closed:** 09/07/2012
Problem: winch out

- Tow From: Melaluca and Firesky in Lake worth

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1211379 **Meter:** 33340 **In Date:** 11/26/2012 **Closed:** 12/19/2012
Problem: Pm service

- P.m. Service. **Parts List** **Qty**

- Replace cargo light bulb. 5w20 Engine Oil 6.00

- Rotate and balance all tires. 5w20 Engine Oil 1.00

- Shop Supplies Ph2 Oil Filter Lbf Ph 1.00

Ca10262 Air Filter Mt 1.00

Ford Fuel Filter 1.00

31-20 Wiper Blades 20 2.00

Shop Supplies 1.00

Hours 4.00 Labor: 240.00 Parts: 57.62 Total: 297.62
:

Workorder: 1211783 **Meter:** 32953 **In Date:** 12/05/2012 **Closed:** 12/05/2012
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1307269 **Meter:** 37351 **In Date:** 07/22/2013 **Closed:** 08/08/2013
Problem: P.M. service and check engine light on and right front window knob.

- Perform pm service. **Parts List** **Qty**

- Inspect and replace failed right window crank handle with new. 5w20 Engine Oil 7.00

Napagold Oil Filter 1.00

- Computer diagnose for airbag light on.test and replace failed passenger airbag on/off switch with new.clear codes with lds and road test. 31-20 Wiper Blades 20 2.00

Used Fire X Refurbished 1.00

- Rotate and balance all four tires. Handle 1.00

- Shop Supplies Switch Asy 1.00

Shop Supplies 1.00

Hours 6.75 Labor: 405.00 Parts: 155.98 Total: 560.98
:

Workorder: 1308982 **Meter:** 38306 **In Date:** 09/05/2013 **Closed:** 09/11/2013
Problem: Turn signal and brake lamps inop.

- Replace right rear signal light bulb. **Parts List** **Qty**

Bulb 2.00

Hours 0.25 Labor: 15.00 Parts: 1.98 Total: 16.98
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1400393 **Meter:** 41728 **In Date:** 01/13/2014 **Closed:** 02/27/2014
Problem: Pm service and no power on acceleration.

- P.m. Service.	Parts List	Qty
- Replace two tires,rotate and balance all four.	5w20 Engine Oil	7.00
- Replace both front bady to chassis insulators.	Napagold Oil Filter	1.00
- Check fuel pressure and volume..replace failed fuel pump module assemble and fuel pressure sensor.refill tank and test drive.	Wiper Blade	2.00
	Napagold Fuel Filter	1.00
- Shop Supplies	Washer FI	1.00
	179636492 Lt245-75r17	2.00
	fuel pump assembly	1.00
	fuel pump gasket	1.00
	Insulator	2.00
	Insualtor	2.00
	Bolt	2.00
	Plate	2.00
	Fuel Pump Drive Module	1.00
	Fuel Sensor	1.00
	Fuel Line Assmebly	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.75	Labor: 705.00	Parts: 2,028.83
:		Total: 2,733.83

Workorder: 1403977 **Meter:** 43455 **In Date:** 04/23/2014 **Closed:** 04/25/2014
Problem: SCREW IN R/REAR TIRE

- ck flat tire replace rr mount balance add n2	Parts List	Qty
- Shop Supplies	179636492 Lt245-75r17	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 1.00	Labor: 60.00	Parts: 247.77
:		Total: 307.77

Workorder: 1406137 **Meter:** 45728 **In Date:** 06/23/2014 **Closed:** 06/26/2014
Problem: Left head lamp inop.

- Remove left headlamp assembly.test and replace failed headlamp seal beam with new.	Parts List	Qty
	Halogen Lamp	1.00
Hours 0.50	Labor: 30.00	Parts: 9.87
:		Total: 39.87

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1411068 **Meter:** 49452 **In Date:** 11/05/2014 **Closed:** 12/04/2014
Problem: Pm service.Lifters noisy.Tow haul message on dash and lost power.

- Pm service.	Parts List	Qty
- Loadtest battery.check starting and charging system.replace defective battery.	5w20 Engine Oil	7.00
- Diagnose for engine noise and no power.remove right valve cover and replace broken rocker arm.scan test,no codes found.perform Kam reset.	Napagold Oil Filter	1.00
- Replace one tire.rotate and balance all four.	Used Fire X Refurbished	1.00
- Replace right headlamp seal beam due to moisture.	Wiper Blade	2.00
- Shop Supplies	Stg Wheel Cov - Ford	1.00
	Battery	1.00
	Rocker Arm	1.00
	179636492 Lt245-75r17	1.00
	Halogen Lamp	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	1.00
Hours 10.75	Labor: 645.00	Parts: 476.01
:		Total: 1,121.01

Workorder: 1506544 **Meter:** 51164 **In Date:** 06/30/2015 **Closed:** 07/15/2015
Problem: Pm service.Check battery and charging system.

- Pm service.	Parts List	Qty
- Check charging and electrical system.battery failed load test after recharge.replace defective battery.	5w20 Engine Oil	7.00
- Perform transmission service.replace filter.flush and replace fluid.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	Napagold Air Filter	1.00
- Shop Supplies	Napagold Fuel Filter	1.00
	Wiper Blade	2.00
	Battery	1.00
	Platinum Filter Kit	1.00
	Syn-atf Trans Fluid S	20.00
	Atp Filter	1.00
	Shop Supplies	1.00
Hours 7.25	Labor: 435.00	Parts: 342.91
:		Total: 777.91

Workorder: 1508810 **Meter:** 51282 **In Date:** 09/02/2015 **Closed:** 09/16/2015
Problem: Check engine light on.

- Computer diagnose for check engine light on.code P2272.replace defective rear oxygen sensor bank 2 sensor 2.clear code and retest.test drive.	Parts List	Qty
- Shop Supplies	Oxygen Sensor	1.00
	Shop Supplies	1.00
Hours 2.80	Labor: 168.00	Parts: 49.07
:		Total: 217.07

Workorder: 1512659 **Meter:** 53299 **In Date:** 12/15/2015 **Closed:** 12/15/2015
Problem: 2 - Key(s) issued

- 2 - Key(s) issued	Parts List	Qty
	Duplicate Vehicle Keys	2.00
Hours 0.60	Labor: 36.00	Parts: 6.00
:		Total: 42.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1603614 **Meter:** 56029 **In Date:** 04/06/2016 **Closed:** 04/19/2016
Problem: P.M. service.

- P.m. Service.	Parts List	Qty
- Pressure test and inspect cooling system.flush and refill system.	5w20 Engine Oil	7.00
- Replace front and rear bounce stops.replace leaking front shocks.	Napagold Oil Filter	1.00
- Replace all eight spark plugs.	Used Fire X Refurbished	1.00
- Flush injectors.service and clean throttle body and induction system.	22" Wiper Blade	2.00
- Replace left headlamp.	Peak Global bumper	2.00
- Rotate and balance all tires.	Gas Grande Fleet Shoc	2.00
- Shop Supplies	Real Suspension Bumpstops	2.00
	Spark Plug	8.00
	Intake Cleaner Kit	1.00
	Injector Cleaner	1.00
	Halogen Lamp	1.00
	Shop Supplies	1.00
Hours 14.25	Labor: 855.00	Parts: 458.45
:		Total: 1,313.45

Workorder: 1608925 **Meter:** 56340 **In Date:** 08/26/2016 **Closed:** 08/31/2016
Problem: Had to jump start in A/M.

- Test battery and charging system.replace bad battery.	Parts List	Qty
- Shop Supplies	Battery	1.00
	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 120.41
:		Total: 180.41

Workorder: 1611986 **Meter:** 56458 **In Date:** 11/21/2016 **Closed:** 11/30/2016
Problem: P.M. Service.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	Napagold Oil Filter	1.00
- Resurface front and rear brake rotors,replace pads abd calipers.flush and bleed system.	5w20 Engine Oil	7.00
- Shop Supplies	Washer Fluid Concentr	1.00
	22" Wiper Blade	2.00
	Pads	1.00
	Rear Pads	1.00
	Caliper w/ Hardware - Left Front (eclips	1.00
	Caliper w/ Hardware - Right Front (eclip	1.00
	Caliper w/ Hardware - Left Rear (eclipse	1.00
	Caliper w/ Hardware - Right Rear (eclips	1.00
	Non-chlor Brake Clnr	1.00
	B Fluid Dot 3-32oz	1.00
	Shop Supplies	1.00
Hours 11.75	Labor: 705.00	Parts: 505.81
:		Total: 1,210.81

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710736 **Meter:** 59102 **In Date:** 10/31/2017 **Closed:** 11/16/2017
Problem: P.M. service and rear brakes locked up and mount cooler holder.

- P.m. service.	Parts List	Qty
- Check and replace left headlight due to water intrusion.	5w20 Engine Oil	7.00
- Inspect and replace faulty trailer hitch connector,inop.install five gallon water cooler holder.	Napagold Oil Filter	1.00
	20" Wiper Blade	2.00
- Inspect all brakes.left rear caliper binding .r&i both rear calipers and service .replace both rear rotors,below spec..replace rear pads and flush and bleed brake system.road test.	Stg Wheel Cov - Ford	1.00
	Napagold Fuel Filter	1.00
	Used Fire X Refurbished	1.00
- Rotate and high speed balance all four wheels.nitro fill all.	trailer plug	1.00
- Shop Supplies	cooler wire rack	1.00
	Halogen Lamp	1.00
	Caliper w/ Hardware - Left Rear (eclipse	1.00
	Caliper w/ Hardware - Right Rear (eclips	1.00
	B Fluid Dot 3-32oz	1.00
	Non-chlor Brake Clnr	1.00
	Rear Pads	1.00
	Brake Rotor	2.00
	Ptex Thrd Lck Blue Lg	1.00
	Shop Supplies	1.00
Hours 10.25	Labor: 615.00	Parts: 626.00
:		Total: 1,241.00

Workorder: 1803915 **Meter:** 60288 **In Date:** 04/16/2018 **Closed:** 04/19/2018
Problem: Right brake light inop.

- Test and replace right brake light bulb .	Parts List	Qty
	Boxed Miniatures	1.00
Hours 0.50	Labor: 30.00	Parts: 0.77
:		Total: 30.77

Workorder: 1804832 **Meter:** 60428 **In Date:** 05/09/2018 **Closed:** 05/17/2018
Problem: P.M. service.

- P.m. service.	Parts List	Qty
- Test and replace third brake light bulb.	5w20 Engine Oil	7.00
- Replace two tires . Rotate and high speed balance all four tires.	Napagold Oil Filter	1.00
	20" Wiper Blade	2.00
- Complete front end alignment.	Used Fire X Refurbished	1.00
- Shop Supplies	Mac Wite Lithium Gres	1.00
	Napagold Air Filter	1.00
	Bulb	2.00
	Shop Supplies	1.00
	Lt245/75r17 Tires	2.00
Hours 7.75	Labor: 465.00	Parts: 358.06
:		Total: 823.06

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809770 **Meter:** 62478 **In Date:** 09/21/2018 **Closed:** 09/24/2018

Problem: Right rear brake light out.

- Test and replace left brake light bulb and socket .	Parts List	Qty
	Stp Trn TI Lgt Socket	1.00
	Boxed Miniatures	1.00
Hours 0.50	Labor: 30.00	Parts: 10.64
:		Total: 40.64

Workorder: 1810222 **Meter:** 62624 **In Date:** 10/02/2018 **Closed:** 10/04/2018

Problem: Brake light out, Drivers side.

- Test and replace left brake light bubl and socket .	Parts List	Qty
	Stp Trn TI Lgt Socket	1.00
	Boxed Miniatures	1.00
Hours 0.50	Labor: 33.50	Parts: 10.64
:		Total: 44.14

Workorder: 1812116 **Meter:** 63250 **In Date:** 11/28/2018 **Closed:** 11/28/2018

Problem: Transition Prep Charge

- Transition Prep Charge			
Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
:			