

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 238286

Problem: CHECK IN

Meter Reading: 46	Labor	Parts	
In Date: 04/10/2002	Hours	Description	Quantity
- Ck In	10.00	30055-20 CKT BREAKER 20 AMP	1.00
- Install Trailer Brake Control And Charge Wire.		S-12-10 10AMP CIRC BRKR	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		4047 BRAKE CONTROLLER (USE 5100)	1.00
Parts Charge:	84.01	Labor Charge:	500.00

Workorder: 239038

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 04/23/2002	Hours	Description	Quantity
- Pre-Delivery Inspection	8.00		
Parts Charge:	0.00	Labor Charge:	400.00

Workorder: 241382

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	
In Date: 05/31/2002	Hours	Description	Quantity
- Pre-Delivery Inspection	9.60		
- Make Duplicate Keys For New Vehicle			
Parts Charge:	0.00	Labor Charge:	480.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 243797

Problem: FAB HITCH

Meter Reading: 327 In Date: 07/11/2002	Close Date: 07/29/2002	Labor Hours	Description	Parts	Quantity
- Fab Hitch.		29.50	T-1 BLACK PAINT GLOSS		3.00
- Rewire Trailer Plugs & Rearlights			SOCKET 5418		1.00
- Repaired Wiring From Cab.					1.00
- Welding Supplies			TC101F CONNECTOR FEMALE (5404)		1.00
			HITCH 6063		1.00
			1/2X3X20 STEEL FLAT BAR		4.00
			06133 3M ELECTRIC TAPE STOCK #832260101		1.00
			1/2 4X8 SHEET STEEL		12.00
			BOLT 9S-1364		2.00
			PLUG 5416		1.00
	Parts Charge: 473.61	Labor Charge: 1,475.00			

Workorder: 246394

Problem: RAN OUT OF FUEL

Meter Reading: 723 In Date: 08/21/2002	Close Date: 08/28/2002	Labor Hours	Description	Parts	Quantity
- Filled With Fuel And Bleed Out Sys.		2.50	SHOP SUPPLIES		1.00
- Haverhill And Okeechobee.					
- Shop Supplies					
	Parts Charge: 2.00	Labor Charge: 125.00			

Workorder: 332264

Problem: PM SERVICE

Meter Reading: 2800 In Date: 01/03/2003	Close Date: 01/07/2003	Labor Hours	Description	Parts	Quantity
- Pm		7.50	15/40 OIL		30.00
- Repair Handle For Debris Tarp			L/F LFP3191 FRM PH49A WIX 51791 OIL FILTER		1.00
- Shop Supplies			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
			CA8193 AIR FILTER LBF LAF4498 WIX 46744		1.00
			SHOP SUPPLIES		1.00
	Parts Charge: 101.89	Labor Charge: 375.00			

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 332724 **Problem:** CHECK LIGHTS

Meter Reading: 2838	Labor	Parts	
In Date: 01/13/2003	Hours	Description	Quantity
- Trace Repair Wire Connections Replace Flasher	1.00	552 WAGNER FLASHER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 6.59	Labor Charge: 50.00		

Workorder: 334296 **Problem:** REPAIR DEBRIS TARP FRAME

Meter Reading: 3036	Labor	Parts	
In Date: 02/06/2003	Hours	Description	Quantity
- Rr Tarp Arm Frame Fabricate Measure For Attachment Holes	1.50	FREIGHT LEFT UPPER TARP BRKT 905	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge: 65.36	Labor Charge: 75.00		

Workorder: 339271 **Problem:** SISTERS TOWING & TRANSPORTATON 132065

Meter Reading: 0	Labor	Parts	
In Date: 04/25/2003	Hours	Description	Quantity
- Sisters Towing & Transportaton 132065 Tow From Purdy Lane And Jog Rd - Tow To Heavy Eqpt Shop			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 120.00	

Workorder: 339310 **Problem:** RAN OUT OF FUEL

Meter Reading: 3739	Labor	Parts	
In Date: 04/25/2003	Hours	Description	Quantity
- Bleed Fuel System . Ran Out Of Fuel.	4.00	SHOP SUPPLIES	1.00
- Take To Dealer For Fuel Sender.			
- Shop Supplies			
Parts Charge: 2.00	Labor Charge: 200.00		

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 339944

Problem: BAD FUEL SENDING UNIT-WARRANTY

Meter Reading: 3760		Labor		Parts	
In Date: 05/05/2003	Close Date: 05/07/2003	Hours	Description		Quantity
-	Transport From Freigh Liner Dealer To Sr Shop	2.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:		100.00

Workorder: 344053

Problem: SEBOK'S COLLISION CENTER 1437

Meter Reading: 0		Labor		Parts	
In Date: 07/14/2003	Close Date: 07/15/2003	Hours	Description		Quantity
-	Sebok'S Collision Center 1437				
Parts Charge:		0.00	Labor Charge:		0.00
			Commercial Charge:		4,296.02

Workorder: 345424

Problem: PM SERVICE

Meter Reading: 4158		Labor		Parts	
In Date: 08/05/2003	Close Date: 08/14/2003	Hours	Description		Quantity
-	Pm	10.00	31-24 WIPER BLADES 24" BLADE		2.00
-	R/R Seal		L/F LFP3191 FRM PH49A WIX 51791 OIL FILTER		1.00
-	Test Run		09997 BRAKE CLEAN		1.00
-	Shop Supplies		PIN.SEAL A1205P2590 R/FRT.AXLE BACK SIDE		1.00
			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
			AIR FILTER 46774		1.00
			SHOP SUPPLIES		1.00
			15/40 OIL		30.00
Parts Charge:		137.26	Labor Charge:		500.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 448574 **Problem:** REPAIR TARP ASSY

Meter Reading: 8282	Labor	Parts		
In Date: 06/21/2004	Hours	Description	Quantity	
- Repair Tarp Assy.Replace Crank Assy.	10.00	CRANK ASSY 441	1.00	
- Repair R.Door		SHOP SUPPLIES	1.00	
- Welding Supplies			1.00	
		1"X1"X24'BOX TUBING 1/8"WALL STEEL	14.00	
		#40 HALF LINK 40 O/L	6.00	
		G2013 BOWASSEMBLY #1344 & #1346 = G2013	1.00	
		#40 CHAIN 40RIV-I	20.00	
Parts Charge:	471.10	Labor Charge:	500.00	

Workorder: 449954 **Problem:** TIRESOLES OF BROWARD INC T070811

Meter Reading: 0	Labor	Parts		
In Date: 06/30/2004	Hours	Description	Quantity	
- Tiresoles Of Broward Inc T070811				
Parts Charge:	0.00	Labor Charge:	0.00	Commercial Charge: 18.00

Workorder: 451269 **Problem:** REPAIR THE LIGHTS

Meter Reading: 8758	Labor	Parts		
In Date: 07/19/2004	Hours	Description	Quantity	
- R&R Directional Switch.Replace 3 Bad Bulbs.Ck Wiring For Open Circuit,Repair.	3.50	SWTCH,DIR 6805450124	1.00	
- Shop Supplies		552 WAGNER FLASHER	1.00	
		SHOP SUPPLIES	1.00	
		9071 RED LENS TRUCK LIGHT GROTE 99164R	1.00	
Parts Charge:	140.48	Labor Charge:	175.00	

Workorder: 451320 **Problem:** CLEAN REAR RIMS FOR ELPEX TIRE REPAIR/REPLACEMENT

Meter Reading: 8758	Labor	Parts		
In Date: 07/20/2004	Hours	Description	Quantity	
- Clean Rear Rims	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	50.00	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 451760

Problem: TIRESOLES OF BROWARD INC T071304/T071274

Meter Reading: 0	Labor	Parts	Quantity
In Date: 07/19/2004	Hours	Description	
- Tiresoles Of Broward Inc T071304/T071274			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 248.52	

Workorder: 535029

Problem: PM SERVICE AND REPLACE MUD FLAPS

Meter Reading: 10946	Labor	Parts	Quantity
In Date: 02/01/2005	Hours	Description	
- Perform P M	12.00	15/40 OIL	30.00
- R & R Wiper Blades And Fire Ext		31-24 WIPER BLADES 24" BLADE	2.00
- R & R 2 Rear Mud Flaps		18410 PINTLE PIN	1.00
- R & R Two Batteries		HP31D BATTERY GROUP 31 STUD	2.00
- Freed Up Hitch Lock And Replaced Pin		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- R & R Body Up Switch		MUD FLAP 24X36 SPLASH GUARD (SPL4-3)	2.00
- Test Run		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Shop Supplies		B90 SWITCH BODY UP SWITCH	1.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		CA8193 AIR FILTER LBF LAF4498 WIX 46744	1.00
		SHOP SUPPLIES	1.00
Parts Charge: 321.67	Labor Charge: 600.00		

Workorder: 536625

Problem: TIRESOLES OF BROWARD INC T076986/T076868

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/07/2005	Hours	Description	
- Tiresoles Of Broward Inc T076986/T076868			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 960.48	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 540476

Problem: REPAIR THE TRAILER PLUG

Meter Reading: 10946	Labor	Parts	
In Date: 03/30/2005	Hours	Description	Quantity
- Installed New Tractor Plug	4.00	SHOP SUPPLIES	1.00
- Repaired Wiring To Body Up Light.		TC101F CONNECTOR FEMALE (5404)	1.00
- Code 23-12 Followed Chart & Scanner Cleaned & Repaired Connection At Selector.			
- Shop Supplies			
Parts Charge:	9.98	Labor Charge:	200.00

Workorder: 544696

Problem: TAIL GATE WON'T OPEN

Meter Reading: 12056	Labor	Parts	
In Date: 05/12/2005	Hours	Description	Quantity
- Lube Tail Gate Linkage Latch Arm On Driver'S Arm Bent	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 545955

Problem: MIRROR LOOSE ;BODY UP LIGHT NOT WORKING AND TAIL GATE LOCK

Meter Reading: 12416	Labor	Parts	
In Date: 05/26/2005	Hours	Description	Quantity
- Replace Switch For Bodyup Light	3.80	CYL, TAILGATE	1.00
- Replace Gate Actuator And Adjust			1.00
- Tighten Mirror Driver Side.		B90 SWITCH BODY UP SWITCH	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	400.21	Labor Charge:	190.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 560135

Problem: PM

Meter Reading: 15303 In Date: 12/29/2005	Close Date: 01/31/2006	Labor Hours	Description	Parts	Quantity
- Pm		26.00	STRIKER 680-723-01-0 3		1.00
- Left Frt Body Mount Bolt Missing Find Insulator And Install New Bolt			ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407) CAP,P/S FG/Q347367		3.00 1.00
- Pinion Seal Leaks Replace Seal Rear Driver			SP3971 MTRCRFT FW16 COOLANT ADDITIVE WIX24056		1.00
- Rf Door Opens While Driving Replace Striker And Latch.			SHOP SUPPLIES		1.00
- Cooling Sys Water Only Service Cooling Sys.			B90 SWITCH BODY UP SWITCH		1.00
- Power Steering Fill Cup Won'T Remove Break Off And Replace W/New			15/40 OIL PH49A OIL FILTER LBF LFP3191 WIX 51791		30.00 1.00
- Body Up Lite 10-7 Replace Switch			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
- 1St Stage Leaks At Gland Tighten Packing			31-24 WIPER BLADES 24" BLADE		2.00
- Ac Performance Ck.Temp And Pressure Rise W/Engine Fab Not Coupled Good On Road			USED FIREX REFURBED FIRE EXTINGSHERS BOLT 8F4225		1.00 1.00
- Find And Repair Body Marker Lite Intermittent Open Circuit.			85/140 GEAR OIL GEAR LUBE SEAL R A1-1205Z2730		4.00 1.00
- West Coast Mirror Head Broken Repl (Left)			LATCH 18-45484-001		1.00
- Road Test Ac Stay 35-40 Deg.			09997 BRAKE CLEAN		2.00
- Shop Supplies			97808 W/COAST MIRROR (RETRAC 610266)		1.00
	Parts Charge:	342.87	Labor Charge:	1,300.00	

Workorder: 636799

Problem: BODY UP LIGHT

Meter Reading: 16003 In Date: 04/04/2006	Close Date: 04/17/2006	Labor Hours	Description	Parts	Quantity
- Body Up Switch		0.50	B90 SWITCH BODY UP SWITCH		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
	Parts Charge:	44.71	Labor Charge:	25.00	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 737154

Problem: P.M./ A/C

Meter Reading: 17515 In Date: 04/13/2007	Close Date: 07/17/2007	Labor Hours	Description	Parts	Quantity
- Pm Complete		33.00	CA8193 AIR FILTER LBF LAF4498 WIX 46744		1.00
- Ac Not Working Troubleshoot Sys.Found Bad Expansion Valve And Dryer.Parts On Order.Readjust Heater Cable			31-24 WIPER BLADES 24" BLADE		2.00
- Replace Air In Tires With Nitrogen			15/40 OIL		30.00
- Hyd Oil Leak Form Pump Release Spool			R134A REFRIGERANT		3.00
- Box Tilt Limit Cable Rotted,Replaced New Cable And Adjusted			GREASE NLGI 2		1.00
- Hitch Pin			18410 PINTLE PIN		1.00
- To Elpex			AW68 HYDRO FLUID HYDRAULIC OIL 68		4.00
- Test Run			56521 THREAD SEALANT HI TEMP THREAD SEALANT		1.00
- Shop Supplies			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
			2851 5/16" CHAIN LINK 5/16" THREADED LINK		1.00
			ABPN83319614 DRIER		1.00
			SHOP SUPPLIES		1.00
			PH49A OIL FILTER LBF LFP3191 WIX 51791		1.00
			A22-45432001 VALVE		1.00
			3248112010 PUMP DUMP		1.00
	Parts Charge: 1,102.67	Labor Charge: 55.00			

Workorder: 740679

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0 In Date: 06/25/2007	Close Date: 06/27/2007	Labor Hours	Description	Parts	Quantity
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00		Commercial Charge: 1,857.14	

Workorder: 740680

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0 In Date: 06/25/2007	Close Date: 06/27/2007	Labor Hours	Description	Parts	Quantity
- Tiresoles Of Broward Inc					
	Parts Charge: 0.00	Labor Charge: 0.00		Commercial Charge: 144.00	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 842006 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts
In Date: 07/18/2008	Hours	Description
Close Date: 07/28/2008		Quantity
- Tiresoles Of Broward Inc		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 144.00

Workorder: 842639 **Problem:** GUARANTEED BUMPER & SUPPLIERS

Meter Reading: 0	Labor	Parts
In Date: 07/21/2008	Hours	Description
Close Date: 08/12/2008		Quantity
- Guaranteed Bumper & Suppliers		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 453.00

Workorder: 846679 **Problem:** REPAIR ALL LIGHTS

Meter Reading: 23568	Labor	Parts
In Date: 11/04/2008	Hours	Description
Close Date: 11/13/2008		Quantity
- Repair/Replace Lght For Truck Turn Signals.Repair Marker	3.50	10205R MARKER LIGHT 2.5" RED GROTE 45812
Lgtrepl/Repair Open In Line-Backup Lgt Out Repl		9-2951 BACKUP ALARM ECCO 575 GROTE 73120
Bulb,Repair Open Ground.		SHOP SUPPLIES
- Replace Back Alarm And Test.Ok		
- Shop Supplies		
Parts Charge: 49.43	Labor Charge: 60.00	

Workorder: 932704 **Problem:** HYD LEAK

Meter Reading: 23930	Labor	Parts
In Date: 01/13/2009	Hours	Description
Close Date: 01/30/2009		Quantity
- Diag. Hydraulic Leak.Determine Dump Cylinder	10.50	AW68 HYDRO FLUID HYDRAULIC OIL 68
Leaking.Remove Cylinder,Transfer All Fittings To New		TELESCOPIC HOIST 73-500-118 SN/965194
One.Re-Install Cyl & Bleed Air.Grease Al		AW68 HYDRO FLUID HYDRAULIC OIL 68
- Test Run		AW68 HYDRO FLUID HYDRAULIC OIL 68
- Shop Supplies		SHOP SUPPLIES
Parts Charge: 2,885.28	Labor Charge: 600.00	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 940330

Problem: P.M.

Meter Reading: 27050	Labor	Parts	
In Date: 07/06/2009	Hours	Quantity	
Close Date: 07/09/2009	Description		
- Pm Service	14.50	PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- Add Nitrogen To All Tires		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
- Replace The Marker Lights And Repair The Wireing		CUSTOM5LB BRACKET FIREX STOCK #340060300	1.00
- Pressure Wash The Engine To Locate Oil Leak And Repair		31-24 WIPER BLADES 24" BLADE	2.00
- Top Off Level And Check For Leaks		AIR FRESHENER	1.00
- Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		AW68 HYDRO FLUID HYDRAULIC OIL 68	10.00
		SHOP SUPPLIES	1.00
		09997 BRAKE CLEAN	2.00
		15/40 OIL	30.00
Parts Charge:	159.84	Labor Charge:	720.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1002831

Problem: P.M.

Meter Reading: 28811	Labor	Parts	Quantity
In Date: 03/19/2010	Hours	Description	
- Pm Service	46.50	26330 TAG LIGHT (TKR LITE)	1.00
- Add Nitogen To All Tires		43022 TAG BRACKET (GROTE)	1.00
- Repair Tail Lights		53640 TAIL LIGHT LED LEFT HAND (GROTE)	1.00
- Move Tag To Rear		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
- Service Trans And Replace Out Put Shaft Seal		PTO PUMP	1.00
- Replace Pto Pump		0311-963163 ARM KIT CONNECTION (AERO)	1.00
- Replace Hood Cables		3600A BRAKE DRUM	4.00
- Replace Tarp ,Frame And Chain Box		0311-963301 SWINGARM AERO TARP	2.00
- Replace Body Up Switch		4707 BRAKE SHOES W/HARDWARE (NEED CORE)	4.00
- Replace Rear Drums,Shoes And Hard Ware		TRANS SEAL	1.00
- Road Test		B90 SWITCH BODY UP SWITCH	1.00
- Fab Chain Box Brackets And Chain Guard		0311-962803 CRANK TARP (AERO)	1.00
- Shop Supplies		0715-619550 SPRING TORSION AERO TARP	2.00
- Shop Supplies		0311-863308 BUSHING INSERT AERO TARP	4.00
		SYN/ATF TRANS FLUID SYNTHETIC	19.00
		HOOD CABLE	2.00
		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
		TARP	1.00
		0720-603545 CHAIN TARP ASSY (AERO)	1.00
		0710-602174 BEARING FLANGE 2 BOLT	2.00
		0311-962801 HANDLE AERO TARP	1.00
		15/40 OIL	30.00
		0311-860908 MOUNTING BRACKET AERO TARP	2.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		80383R TAIL LIGHT (TKR LITE) DON'T REORDER	1.00
		29526898 TRANS FILTER FRM C9031 WIX 57740XE	1.00
		0311-860902 RING RETAINING AERO TARP	2.00
		31-24 WIPER BLADES 24" BLADE	2.00
		SHOP SUPPLIES	1.00
		0825-660852 SCREW AERO TARP	4.00
		AIR FRESHENER	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	2,927.58	Labor Charge:	2,790.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1010261

Problem: Belts

Meter Reading: 29770	Labor	Parts	
In Date: 09/20/2010	Hours	Description	Quantity
- Replace Belt And Tensioner	7.00	BELT TENSIONER	1.00
- Fm To Pinehurst And 10 Ave		FAN BELT	1.00
- To Atlantic Truck		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	314.09	Labor Charge:	270.00

Workorder: 1011152

Problem: oil leak

Meter Reading: 29978	Labor	Parts	
In Date: 10/08/2010	Hours	Description	Quantity
- Fm To C Rock Send To Shop	12.50	31-24 WIPER BLADES 24" BLADE	2.00
- Pm Service		15/40 OIL	30.00
- R&R Hyd Tank And Weld Cracks		AW68 HYDRO FLUID HYDRAULIC OIL 68	68.00
- Shop Supplies		SHOP SUPPLIES	1.00
		CA8193 AIR FILTER LBF LAF4498 WIX 46744	1.00
		PH49A OIL FILTER LBF LFP3191 WIX 51791	1.00
		1R0751 FUEL FILTER FRM P8264 WIX 33626	1.00
Parts Charge:	275.75	Labor Charge:	750.00

Workorder: 1105119

Problem: lights

Meter Reading: 30459	Labor	Parts	
In Date: 05/13/2011	Hours	Description	Quantity
- Repair Open In Stop Light	0.40		
Parts Charge:	0.00	Labor Charge:	24.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1107957

Problem: pm service

Meter Reading: 31494		Labor		Parts	
In Date: 07/29/2011	Close Date: 08/05/2011	Hours	Description		Quantity
- Pm Service		13.50	MOUNTED PINTLE HOOK		1.00
- Replace Rr Tail Light			GROUP 31 STUD BATTERY (ACD 31-900CT)		2.00
- Replace Trailer Hitch			D1925C HORN 12 VOLT A/F NOTE		1.00
- Replace Low Air Pressure Sensor			SHOP SUPPLIES		1.00
- Replace Batteries			15/40 OIL		30.00
- Replace Rs Tarp Arm Bushings			LOW AIR PRESSURE SWITCH		1.00
- Replace Horn			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
- Road Test			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Shop Supplies			31-24 WIPER BLADES 24" BLADE		2.00
			PH49A OIL FILTER LBF LFP3191 WIX 51791		1.00
			0311-860902 RING RETAINING AERO TARP		1.00
			53650 TAIL LIGHT LED TWO CONNECTOR (GROTE)		1.00
			0311-863308 BUSHING INSERT AERO TARP		2.00
Parts Charge:		874.21	Labor Charge:	810.00	

Workorder: 1201725

Problem: pm service and tires

Meter Reading: 33926		Labor		Parts	
In Date: 02/22/2012	Close Date: 03/09/2012	Hours	Description		Quantity
- Pm Service		10.50	SHOP SUPPLIES		1.00
- Replace High Pressure Oil Line With Updated Line			31-24 WIPER BLADES 24" BLADE		2.00
- Repair Tarp Crank			SYN/ATF TRANS FLUID SYNTHETIC		4.00
- Repair Wiring For Marker Lights			HIGH PRESSURE OIL LINE		1.00
- Replace All Ten Tires Boulevard			PH49A OIL FILTER LBF LFP3191 WIX 51791		1.00
- Shop Supplies			1R0751 FUEL FILTER FRM P8264 WIX 33626		1.00
			CA8193 AIR FILTER LBF LAF4498 WIX 46744		1.00
			15/40 OIL		30.00
			11R225RC TIRE RECAPPED		8.00
Parts Charge:		1,714.34	Labor Charge:	630.00	Commercial Charge: 1,552.16

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1204998

Problem: repair tarp,frame and hyds. for body are slow

Meter Reading: 34482	Labor	Parts	
In Date: 05/30/2012	Hours	Description	Quantity
- Replace Tarp Frame, Bushings And Gear Box	8.50	0311-863308 BUSHING INSERT AERO TARP	4.00
- Adjust Dump Controls And Repair Control Mounting Brackets		0311-963301 SWINGARM AERO TARP	2.00
		11/4X11/4X24 SQ TUBING .063 WALL ALUMINUM	8.00
- Shop Supplies		0311-962803 CRANK TARP (AERO)	1.00
		SHOP SUPPLIES	1.00
		0311-963163 ARM KIT CONNECTION (AERO)	1.00
Parts Charge:	597.44	Labor Charge:	510.00

Workorder: 1302495

Problem: pm service

Meter Reading: 37906	Labor	Parts	
In Date: 03/13/2013	Hours	Description	Quantity
- Pm Service	8.50	3006875 PIN ASSEMBLY	1.00
- Replace Brake Pedal Pad		SHOP SUPPLIES	1.00
- Road Test		15-40 OIL	30.00
- Replace Hitch Safety Pin		PH49A OIL FILTER LBF	1.00
- Shop Supplies		FUEL FILTER 1R0751	1.00
		31-24 WIPER BLADES 2	2.00
		NAPAGOLD AIR FILTER	1.00
		BRAKE PEDAL PAD	1.00
		USED FIREX REFURBED F	1.00
Parts Charge:	189.12	Labor Charge:	510.00

Workorder: 1305257

Problem: mirrors, tarp frame check brakes

Meter Reading: 38531	Labor	Parts	
In Date: 05/29/2013	Hours	Description	Quantity
- Repaired Mirrors	7.50	4645 TARP 7 5X18 FINI	1.00
- Replace Intire Tarp Assembly		SHOP SUPPLIES	1.00
- Checked Brakes And Brake Wirring		BUSHING	4.00
- Shop Supplies		TARP BAR	1.00
		SPRING	2.00
		SWING ARM	2.00
		CONNECT ARM KIT	1.00
Parts Charge:	522.77	Labor Charge:	450.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1306185

Problem: Tarp

Meter Reading: 38715	Labor	Parts	
In Date: 06/20/2013	Hours	Description	
Close Date: 07/01/2013		Quantity	
- Adjust Tarp And Mirrors	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1310832

Problem: bed will not lower

Meter Reading: 39018	Labor	Parts	
In Date: 10/29/2013	Hours	Description	
Close Date: 01/10/2014		Quantity	
- Lower Bed	19.00	PUMP REBUILD	1.00
- Fm To C Roc And Fm To 45 Dump		SHOP SUPPLIES	1.00
- R&R Hyd Pump And Bleed System		AW68 HYDRO FLUID HYDR	8.00
- Shop Supplies			
Parts Charge:	554.90	Labor Charge:	1,140.00

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1400962

Problem: replace mirrors

Meter Reading: 39339 In Date: 01/29/2014	Close Date: 03/07/2014	Labor Hours	Description	Parts	Quantity
- Exstend Mirrors		20.70	NAPAGOLD FUEL FILTER		1.00
- P.M.			NAPAGOLD OIL FILTER		1.00
- Replace Hose And Dryer Recharge Ac			15-40 OIL		30.00
- Repair Coolent Leaks R&R Sight Glass And Cap			NAPAGOLD AIR FILTER		1.00
- R&R Air Dryer Assembly			A/C HOSE ASSEMBLY		1.00
- Repair Body Up Switch			MIRROR		2.00
- Test Drive			BINARY SWITCH		1.00
- Shop Supplies			RADIATOR CAP		1.00
			1CART PALLADIUM 2 GRS		1.00
			Freight Charge		1.00
			SHOP SUPPLIES		1.00
			R134A FREON		3.00
			SIGHT GLASS		1.00
			Freight Charge		1.00
			HOSE MAKE UP		1.00
			31-24 WIPER BLADES 2		2.00
			RECEICER DRIER		1.00
			Freight Charge		1.00
			AIR DRYER		1.00
			WASHER FL		1.00
			BODY UP SWITCH		1.00
	Parts Charge:	1,073.91	Labor Charge:	1,242.00	

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1408925

Problem: pm

Meter Reading: 40897		Labor		Parts	
In Date: 09/04/2014	Close Date: 09/09/2014	Hours	Description	Quantity	
- Pm		12.50	BUSHING		4.00
- R&R Marker Light			TARP BAR		1.00
- Replace Tarp Arms, Cross Bar, Bushings, And Tarp			TARP 7.5 X 18 IN		1.00
- Hitch Pin			SHOP SUPPLIES		1.00
- Test Run			15-40 OIL		30.00
- Shop Supplies			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
			WASHER FL		1.00
			SWING ARM		2.00
			SPRING		2.00
			3006875 PIN ASSEMBLY		1.00
			LED M C LAMP		1.00
			LED M C ADAPER PLUG		1.00
			CONNECT ARM KIT		1.00
			31-24 WIPER BLADES 2		2.00
			NAPAGOLD AIR FILTER		1.00
Parts Charge:		705.65	Labor Charge:	750.00	

Workorder: 1408987

Problem: replace four rear recaps

Meter Reading: 40886		Labor		Parts	
In Date: 09/08/2014	Close Date: 09/11/2014	Hours	Description	Quantity	
- Replace Rear Caps			TIRE DISPOSAL FEE		4.00
- Shop Supplies			11R225RC TIRE RECAPPED		4.00
			SHOP SUPPLIES		1.00
Parts Charge:		746.47	Labor Charge:	0.00	Commercial Charge: 226.40

Workorder: 1411833

Problem: Replace LFO Tire

Meter Reading: 41677		Labor		Parts	
In Date: 11/21/2014	Close Date: 12/01/2014	Hours	Description	Quantity	
- Replace Tire					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 502.60

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1501328		Problem: 4 - Key(s) issued		
Meter Reading: 42124		Labor	Parts	
In Date: 02/04/2015	Close Date: 02/04/2015	Hours	Description	Quantity
- 4 - Key(S) Issued		1.20	DUPLICATE VEHICLE KEYS	4.00
	Parts Charge: 12.00	Labor Charge:	72.00	

Workorder: 1503206		Problem: PM		
Meter Reading: 42522		Labor	Parts	
In Date: 03/27/2015	Close Date: 04/09/2015	Hours	Description	Quantity
- Pm		16.50	BRAKE CLEANER	2.00
- Replace Hitch Pin			3006875 PIN ASSEMBLY	1.00
- Service Air Dryer			USED FIRE X REFURBISHED	1.00
- Repair Lights			CARTRIDGE AD9	1.00
- R&R All Faded Stickers			GROUP 31 STUD DELCO	2.00
- Charge Ac			R134A FREON	2.00
- Replace Battery			TURN LAMP LED	1.00
- Rood Test			LED M C LAMP	1.00
- Shop Supplies			LED M C ADAPER PLUG	1.00
			NAPAGOLD OIL FILTER	1.00
			31-24 WIPER BLADES 2	2.00
			15-40 OIL	30.00
			NAPAGOLD AIR FILTER	1.00
			SHOP SUPPLIES	1.00
			NAPAGOLD FUEL FILTER	1.00
			WASHER FL	1.00
	Parts Charge: 624.17	Labor Charge:	990.00	

Workorder: 1509869		Problem: RRI tire repair		
Meter Reading: 46008		Labor	Parts	
In Date: 09/29/2015	Close Date: 09/29/2015	Hours	Description	Quantity
- Tire Repair Rri				
	Parts Charge: 0.00	Labor Charge:	0.00	Commercial Charge: 73.81

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1511303

Problem: Bed stuck in air

Meter Reading: 46680		Labor		Parts	
In Date: 11/04/2015	Close Date: 11/30/2015	Hours	Description	Quantity	
- Lower Bed		20.00	AW68 HYDRO FLUID HYDR		60.00
- To Croc			PUMP		1.00
- Replace Hydraulic Pump			SHOP SUPPLIES		1.00
- To Mako			Freight Charge		1.00
- Add Oil			HOSE CLAMP		4.00
- Shop Supplies			HYDRAULIC HOSE		54.00
Parts Charge: 1,122.83		Labor Charge: 1,200.00			

Workorder: 1512551

Problem: Weld up bed

Meter Reading: 46680		Labor		Parts	
In Date: 12/11/2015	Close Date: 02/09/2016	Hours	Description	Quantity	
- Repair Cracks In Bed					
Parts Charge: 0.00		Labor Charge: 0.00		Commercial Charge: 8,166.00	

Workorder: 1601299

Problem: PM

Meter Reading: 46715		Labor		Parts	
In Date: 02/05/2016	Close Date: 03/14/2016	Hours	Description	Quantity	
- Pm		17.50	NAPAGOLD OIL FILTER		1.00
- Replace 2 Marker Lights And Rewire			GROMMET		2.00
- Road Test			AW68 HYDRO FLUID HYDR		70.00
- Remove Tank And Patch Repair. Test For Leaks			WIPER BLADE		2.00
- Shop Supplies			JB WELD KWIK WELD		1.00
			15-40 OIL		30.00
			LED M C LAMP		2.00
			24 175 UVB CABLE TIE		1.00
			LED M C ADAPER PLUG		2.00
			AW68 HYDRO FLUID HYDR		60.00
			NAPAGOLD AIR FILTER		1.00
			SHOP SUPPLIES		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 490.04		Labor Charge: 1,050.00			

1/3/2017
2:53:00PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10139486 2002 FREIGHTLINER FL80 Dump Truck, Tandem, 12 Yard

Workorder: 1601621	Problem: RFIO				
Meter Reading: 46680		Labor		Parts	
In Date: 02/16/2016	Close Date: 02/19/2016	Hours	Description		Quantity
<hr/>					
- Rfio Tire					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 1,003.38		
Workorder: 1610453	Problem: 4 rear tires				
Meter Reading: 48156		Labor		Parts	
In Date: 10/11/2016	Close Date: 10/17/2016	Hours	Description		Quantity
<hr/>					
- 4 Rear Tires					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 1,988.80		
Workorder: 1611629	Problem: Transition Prep Charge				
Meter Reading: 48156		Labor		Parts	
In Date: 11/14/2016	Close Date: 11/14/2016	Hours	Description		Quantity
<hr/>					
- Transition Prep Charge		2.00			
	Parts Charge: 0.00	Labor Charge: 120.00			
Total Parts Charges:	22,399.25	Total Labor Charges:	22,313.00	Total Comm. Charges:	22,876.84