

**Palm Beach County Fleet Management
Asset Maintenance History**

10175100 2009 FORD F350 Utility Body, 1 Ton, W/Med. Duty Crane

Workorder: 936830 **Meter:** 0 **In Date:** 04/22/2009 **Closed:** 04/22/2009
Problem: PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 4.00 Labor: 240.00 Parts: 0.00 Total: 240.00
:

Workorder: 937481 **Meter:** 39 **In Date:** 05/06/2009 **Closed:** 05/18/2009
Problem: INSTALL COMPRESSOR

- Fab Platform Stand For Air Compressor & Mount To Truck.mount Air Compressor.mount Diesel Fuel Tank To Truck W/bolt.fab Safety Strap

Parts List **Qty**

Shop Supplies 1.00

1/8 4x8 Sheet Steel 1.00

- Hydraulic Tk Leaking At All Fittings.suck Fuel Out.remv Fitt& Hoses.reseal.instl Fittings Test For Leaks.add 45qts Fluid To Proper Level.

1/4x4x12 Alum Plate 5052 8.00

1/4 4x8 Sheet Steel 6.00

- Relocate & Raise Llight Bar On Truck.fabricate 2 Brackets & Weld To Headache Bar.drill Holes & Mount.extend Wieing Thru Body.

3"x3"x20' Alum Angle Architectual 1/4" Thick 6.00

1"x24' Square Alum Tube With Radius 1/8 Wall 6.00

- Wash Hydraulic Fluid From Bed Of Truck With Big G On Wash Rack.

Square Tube Aluminum 3.00

Aw68 Hydro Fluid Hydraulic Oil 68 45.00

- Shop Supplies

30055-20 Ckt Breaker 20 Amp 1.00

30055-20 Ckt Breaker 20 Amp -1.00

30055-30 30amp Circuit Breaker 1.00

30055-30 30amp Circuit Breaker 1.00

66br Clear Silicone 1.00

Hours 26.00 Labor: 1,560.0 Parts: 298.68 Total: 1,858.68
:

Workorder: 938019 **Meter:** 424 **In Date:** 05/20/2009 **Closed:** 06/05/2009
Problem: INSTALL CUSTOMERS COMP STAND,CRANE LEAKING

- Fabricate And Install Customer Computer Stand & Wire Harness

Parts List **Qty**

Shop Supplies 1.00

- Cut Key

- Transport Vehicle To Fab Shon For Crane Warranty Repair.

- Shop Supplies

Hours 6.50 Labor: 390.00 Parts: 2.00 Total: 392.00
:

Workorder: 940759 **Meter:** 1579 **In Date:** 07/15/2009 **Closed:** 07/16/2009
Problem: cover for hydraulic tank leaking

- Replace missing hyd tank cap.

Parts List **Qty**

- Shop Supplies

Shop Supplies 1.00

35610001 Cap/screen Hyd Tank Bucket Truck 1.00

Hours 0.50 Labor: 30.00 Parts: 83.93 Total: 113.93
:

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|--|--|----------------------------|---------------------------|
| Workorder: 941527 | Meter: 2128 | In Date: 08/03/2009 | Closed: 08/04/2009 |
| Problem: Remove bolt and install hitch pin. | | | |
| - Remove bolt from trailer receiver & install correct hitch pin. | Parts List | | Qty |
| - Shop Supplies | Shop Supplies | | 1.00 |
| | 2560 Hitch Pin/clip | | 1.00 |
| Hours 0.25 | Labor: 15.00 | Parts: 3.52 | Total: 18.52 |
| : | | | |
| Workorder: 942796 | Meter: 3285 | In Date: 09/01/2009 | Closed: 09/01/2009 |
| Problem: crane stuck in the air | | | |
| - Travel to royal palm | Parts List | | Qty |
| - Bypassed switch to lower boom | Shop Supplies | | 1.00 |
| - Shop Supplies | | | |
| Hours 2.50 | Labor: 150.00 | Parts: 2.00 | Total: 152.00 |
| : | | | |
| Workorder: 943030 | Meter: 3718 | In Date: 09/08/2009 | Closed: 09/21/2009 |
| Problem: P.M service, check cran operation. | | | |
| - P.m service. | Parts List | | Qty |
| - Inspect & service crane, flush contaminated fluid, R&r | Shop Supplies | | 1.00 |
| leaking hyd hose from pump to crane & send out for repairs, | Hydraulic Filter | | 1.00 |
| - Rewire crane power to upfitter switches. Fabricate & refit | 7312 Oil Filterfrm Ch9549 Wix 57312 | | 1.00 |
| hyd line off Pto pump away from trans shift lever, reinstall | Cs10263 Fuel Filter (use Cs10263a) | | 1.00 |
| shift cable retaining clip correctly. Protect hyd hoses @ | Aw68 Hydro Fluid Hydraulic Oil 68 | | 44.00 |
| outriggers. | Aw68 Hydro Fluid Hydraulic Oil 68 | | 9.00 |
| - Nitro fill all six tires. | 15/40 Oil | | 15.00 |
| - Alignment, install camber/caster bushing in R/f to correct | Camber Kit | | 1.00 |
| caster. | Camber Kit | | 1.00 |
| - Shop Supplies | | | |
| Hours 18.00 | Labor: 1,080.00 | Parts: 277.15 | Total: 1,357.15 |
| : | 0 | | |
| Workorder: 1000759 | Meter: 6379 | In Date: 01/20/2010 | Closed: 01/26/2010 |
| Problem: Crane not working. | | | |
| - Inspect crane, remove Pto pump & install 45 fitting on | Parts List | | Qty |
| pressure side of pump, secure hose over rear axle. Test & | Shop Supplies | | 1.00 |
| replace pressure sensor & switch on crane, adjust & set | 51551 Hydraulic Filter | | 1.00 |
| pressure regulator. | 17002 Switch Anti-two Block | | 1.00 |
| - Shop Supplies | 31498 L/sense Switch 2550 3660 (liftmoore) | | 1.00 |
| Hours 4.00 | Labor: 240.00 | Parts: 383.24 | Total: 623.24 |
| : | | | |
| Workorder: 1001263 | Meter: 6648 | In Date: 02/03/2010 | Closed: 02/04/2010 |
| Problem: Hyd leak. | | | |
| - Replace blown hyd hose from flow control valve to out | Parts List | | Qty |
| rigger control valve. | Shop Supplies | | 1.00 |
| - To/from hyd shop to make up new hose. | | | |
| - Shop Supplies | | | |
| Hours 2.50 | Labor: 150.00 | Parts: 2.00 | Total: 152.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1002809 **Meter:** 7956 **In Date:** 03/18/2010 **Closed:** 03/31/2010
Problem: P.M service. Install customers vise, check trailer plug.

| | | |
|-----------------------------------|--------------------------------------|---------------|
| - P.m service. | Parts List | Qty |
| - Inspect & service crane. | Shop Supplies | 1.00 |
| - Test & rewire trailer plug. | 51551 Hydraulic Filter | 1.00 |
| - Redrill & mount customers vice. | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Shop Supplies | Cs10263 Fuel Filter (use Cs10263a) | 1.00 |
| | 15/40 Oil | 15.00 |
| | Aw68 Hydro Fluid Hydraulic Oil 68 | 8.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| | 31-20 Wiper Blades 20" Blade | 2.00 |
| Hours 7.20 | Labor: 432.00 | Parts: 135.78 |
| : | | Total: 567.78 |

Workorder: 1010058 **Meter:** 13318 **In Date:** 09/14/2010 **Closed:** 09/23/2010
Problem: Pm service,also see notes on tires and brakes.

| | | |
|--|---|-----------------|
| - Perform pm service. | Parts List | Qty |
| - Install four new tires and balance all six. | Shop Supplies | 1.00 |
| - Inspect and service power crane.fabricate and replace leaking hydralric filter housing with new and top off fluid. | 51551 Hydraulic Filter | 1.00 |
| - Shop Supplies | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| | Cs10263 Fuel Filter (use Cs10263a) | 1.00 |
| | Ca10270 Air Filter Mtc Fa1886 Wix 49886 | 1.00 |
| | Aw68 Hydro Fluid Hydraulic Oil 68 | 4.00 |
| | 15/40 Oil | 15.00 |
| | 50002 Filter Adapter (cimtek) | 1.00 |
| | 31-20 Wiper Blades 20" Blade | 2.00 |
| | 179636492 Lt245/75r17 Wrangler Sr-a E | 4.00 |
| | Tr416 Valve Stem | 4.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 8.50 | Labor: 510.00 | Parts: 915.35 |
| : | | Total: 1,425.35 |

Workorder: 1010428 **Meter:** 13318 **In Date:** 09/22/2010 **Closed:** 09/23/2010
Problem: flash canceiver in spot# 210

| | | |
|---------------------|-------------------|--------------|
| - Reflash Canceiver | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1012998 **Meter:** 15126 **In Date:** 11/23/2010 **Closed:** 12/03/2010
Problem: Crane very noisy.

| | | |
|--|-------------------|---------------|
| - Inspect crane for noises and oil leak.dismantle trunnion and gear box.fabricate,extract and replace broken slew motor to bracket mounting bolts with new and reseal. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1101029 **Meter:** 16431 **In Date:** 01/27/2011 **Closed:** 02/17/2011
Problem: Service light on.

- Computer diagnose for warning light concern.road test and follow procedure for exhaust regeneration to complete.clear codes with scan tool. **Parts List** **Qty**
Shop Supplies 1.00
- Shop Supplies
Hours 2.00 Labor: 120.00 Parts: 2.00 Total: 122.00
:

Workorder: 1104219 **Meter:** 18120 **In Date:** 04/19/2011 **Closed:** 04/20/2011
Problem: Crane leaking oil

- Inspect and secure Leaking union for hydraulic oil line and top off fluid. **Parts List** **Qty**
Shop Supplies 1.00
- Shop Supplies Aw68 Hydro Fluid Hydraulic Oil 68 6.00
Hours 1.00 Labor: 60.00 Parts: 16.25 Total: 76.25
:

Workorder: 1104584 **Meter:** 18661 **In Date:** 04/28/2011 **Closed:** 05/13/2011
Problem: Pm service,check tires and see notes on air comperssor.

- Perform pm service. **Parts List** **Qty**
- Install two newt tires to the front wheels.nitrogen fill and balance all six. Shop Supplies 1.00
7312 Oil Filterfrm Ch9549 Wix 57312 1.00
- Inspect and service power crane. Cs10263 Fuel Filter (use Cs10263a) 1.00
- Test and repair failed ground circuit to clearance lamp bar. 51551 Hydraulic Filter 1.00
- Perform wheel alignment complete. Aw68 Hydro Fluid Hydraulic Oil 68 4.00
- Shop Supplies 15/40 Oil 15.00
31-20 Wiper Blades 20" Blade 2.00
7090blk Frt Floor Mats (rubber Queen) 1.00
Used Firex Refurbed Fire Extingshers 1.00
179636492 Lt245/75r17 Wrangler Sr-a E 2.00
Tire Disposal Fee 2.00
18410 Pintle Pin 1.00
Hours 10.75 Labor: 645.00 Parts: 552.50 Total: 1,197.50
:

Workorder: 1107081 **Meter:** 20411 **In Date:** 07/05/2011 **Closed:** 07/05/2011
Problem: No start

- From: 12500 40th street-sw corner of 40th and 120 ave n
Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1107097 **Meter:** 20440 **In Date:** 07/05/2011 **Closed:** 07/08/2011
Problem: Has to jump start in the am

- Test starting and charging system.batteries failed load test after recharge.replace both failed batteries with new. **Parts List** **Qty**
Shop Supplies 1.00
- Shop Supplies Group 65 Battery (mtc Bxt-65-850) 2.00
Hours 2.00 Labor: 120.00 Parts: 259.49 Total: 379.49
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1110300 **Meter:** 22783 **In Date:** 09/27/2011 **Closed:** 09/28/2011
Problem: Right rear outside tire is flat.

| | | |
|---|-------------------|--------------|
| - Repair flat right rear outside tire.nitrogen fill and balance same. | Parts List | Qty |
| | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1112002 **Meter:** 23825 **In Date:** 11/08/2011 **Closed:** 11/21/2011
Problem: P.m. service.

| | | |
|--|---|---------------|
| - Perform pm service. | Parts List | Qty |
| - Inspect and service hydraulic crane. | Shop Supplies | 1.00 |
| - Inspect and repair failed ground circuit to right side Led marker lamp.test and replace failed licence plate and dome lamp bulbs with new. | 8c3z9a343a Seal Kit Fuel Filter (ford) | 1.00 |
| | 51551 Hydraulic Filter | 1.00 |
| - Rotate and balance all six tires. | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Shop Supplies | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| | 15/40 Oil | 15.00 |
| | Aw68 Hydro Fluid Hydraulic Oil 68 | 3.00 |
| | 31-20 Wiper Blades 20" Blade | 2.00 |
| | 18410 Pintle Pin | 1.00 |
| Hours 7.50 | Labor: 450.00 | Parts: 154.46 |
| : | | Total: 604.46 |

Workorder: 1112457 **Meter:** 23825 **In Date:** 11/22/2011 **Closed:** 11/22/2011
Problem: FUEL LOCK

- From: 12500 40th Street North, Loxatchee To: He Shop

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1112461 **Meter:** 23863 **In Date:** 11/23/2011 **Closed:** 11/29/2011
Problem: Towed in with fuel leak.

| | | | |
|--|--|---------------|---------------|
| - Diagnose for fuel leak.test and replace failed fuel conditioning module seals with new and bleed fuel lines. | Parts List | Qty | |
| | Shop Supplies | 1.00 | |
| - Diagnose crane inop.test and replace failed boom cylinder pressure transducer with new . | 8c3z9a343a Seal Kit Fuel Filter (ford) | 1.00 | |
| - Shop Supplies | 31498 L/sense Switch 2550 3660 (liftmoore) | 1.00 | |
| Hours 2.75 | Labor: 165.00 | Parts: 290.72 | Total: 455.72 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1205508 **Meter:** 28857 **In Date:** 06/12/2012 **Closed:** 07/11/2012
Problem: P.M. service.

| | Parts List | Qty |
|---|--|-----------------|
| - P.m. Service. | | |
| - Replaceleft front and left rear marker light. | Shop Supplies | 1.00 |
| - Pressure test and inspect cooling system.replace leaking upper radiator hose.refill cooling system. | 7312 Oil Filterfrm Ch9549 Wix 57312 | 1.00 |
| - Inspect and service crane.replace leaking swivel fitting and leaking hose.refill system. | 3963 Fuel Filter Frm Cs10263a Wix 33963 | 1.00 |
| - Rotate and balance all six tires. | 51551 Hydraulic Filter | 1.00 |
| - Shop Supplies | Aw68 Hydro Fluid Hydraulic Oil 68 | 3.00 |
| | 15/40 Oil | 15.00 |
| | Used Firex Refurbed Fire Extingshers | 1.00 |
| | 31-20 Wiper Blades 20" Blade | 2.00 |
| | 19006y Marker Light 4" Rect Yellow Led | 1.00 |
| | 19006r Marker Light 4" Rectangular Red Led | 1.00 |
| | Upper Radiator Hose | 1.00 |
| | Hydraulic Swivel | 1.00 |
| Hours 12.50 | Labor: 750.00 | Parts: 273.11 |
| : | | Total: 1,023.11 |

Workorder: 1208332 **Meter:** 30877 **In Date:** 09/04/2012 **Closed:** 09/20/2012
Problem: Crane inop.Lighter socket has no power.

| | Parts List | Qty |
|--|--|---------------|
| - Diagnose crane inop.test and replace defective pressure transducer.retest operation. | Shop Supplies | 1.00 |
| - Check inop power outlet.test and replace blown fuses. | 06133 3m Electric Tape Stock #832260101 | 1.00 |
| - Shop Supplies | 31498 L/sense Switch 2550 3660 (liftmoore) | 1.00 |
| | 15319476 Fuse 20 Amp Gmc | 2.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 268.52 |
| : | | Total: 448.52 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1302269 **Meter:** 35517 **In Date:** 03/06/2013 **Closed:** 03/28/2013
Problem: P.M. Service.Check engine light on.

| | | |
|---|-----------------------|-----------------|
| - Perform pm service. | Parts List | Qty |
| - Dismantle light bar to acess and replace failed right alley lamp with new.fabricate and repair failed rear clearance lamp and right rear tail lamp circuits.install missing pintle pin. | 15-40 Oil | 15.00 |
| - Install four new tires.nitrogen fill and balance all six. | Napagold Oil Filter | 1.00 |
| - Inspect ane replace failed serpentine belt and tensioner with new. | Napagold Fuel Filter | 1.00 |
| - Remove front fuel tank and replace failed fuel module gasket with new. | 31-20 Wiper Blades 20 | 2.00 |
| - Perform crane service complete. Remove crane Pto unit to acess and repair hydraulic oil leak.inspect and secure leaking swivel fittings under crane. | Brake Cleaner | 1.00 |
| - Computer diagnose for check engine light on.perform update software asper Tsb#12-7-7.reprogram pcm,tcm and instrument cluster. | Fxalf1 Alley Light Le | 1.00 |
| - Shop Supplies | 18410 Pintle Pin | 1.00 |
| | 179636492 Lt245-75r17 | 4.00 |
| | Tr416 Valve Stem | 4.00 |
| | A/c Belt | 1.00 |
| | Belt Tensioner | 1.00 |
| | Seal | 1.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | Adapter | 1.00 |
| | Aw68 Hydro Fluid Hydr | 17.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 4.00 |
| Hours 18.50 | Labor: 1,110.0 | Parts: 1,377.48 |
| : | 0 | Total: 2,487.48 |

Workorder: 1303376 **Meter:** 35989 **In Date:** 04/08/2013 **Closed:** 05/02/2013
Problem: Licence plate fell off.

| | | |
|---|-----------------------|--------------|
| - Fabricate and install new licence plate bracket.install new tag lamp assembly and secure licence plate. | Parts List | Qty |
| - Shop Supplies | License Plate Brkt | 1.00 |
| | 26330 Tag Light Tkr L | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 1.25 | Labor: 75.00 | Parts: 11.20 |
| : | | Total: 86.20 |

Workorder: 1305245 **Meter:** 37404 **In Date:** 05/29/2013 **Closed:** 07/30/2013
Problem: Crane inop.

| | | |
|--|-----------------------|-----------------|
| - Diagnose crane inop.test and replace failed boom hydraulic pressure transducer with new.also replace damage pendant/control cable with new asper operator request.due to normal wear and tear. | Parts List | Qty |
| - Prssure test and inspect cooling system.test and replace failed radiator assembly with new.reverse flush and renew engine coolant. | Radiator | 1.00 |
| - Shop Supplies | Peak Global | 3.00 |
| | Liftmoore Control | 1.00 |
| | Vinyl Electrical Tape | 1.00 |
| | Fmx-30 Fuse | 1.00 |
| | 33167 Pressure Switch | 1.00 |
| | Shop Supplies | 1.00 |
| | Freight Charge | 1.00 |
| Hours 7.50 | Labor: 450.00 | Parts: 2,117.24 |
| : | | Total: 2,567.24 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1312352 **Meter:** 40540 **In Date:** 12/11/2013 **Closed:** 12/30/2013

Problem: Pm service and right side outrigger hydraulic actuator falling.

| | | |
|--|-------------------------|-----------------|
| - Perform pm service. | Parts List | Qty |
| - Inspect and service hydraulic crane.replace filter with new.repair oil leak at valve block and by pass block. | 15-40 Oil | 15.00 |
| - Remove failed right side outrigger hydraulic actuator.sent out for over haul and reinstall after rebuild. | Napagold Oil Filter | 1.00 |
| - Pressure test and inspect cooling system.replace both failed lower radiator hoses with new,reverse flush and renew engine coolant. | Fuel Filter Ford Only | 1.00 |
| - Inspect and service auxiliary fuel tank. | Napagold Air Filter | 1.00 |
| - Install two new tires to the front wheels. Nitrogen fill and balance all six tires. | Wiper Blade | 2.00 |
| - Replace missing hitch pindel pin with new. | Used Fire X Refurbished | 1.00 |
| - Perform wheel alignment complete. | Brake Cleaner | 1.00 |
| - Shop Supplies | Washer FI | 1.00 |
| | Mac Wite Lithium Gres | 1.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | Aw68 Hydro Fluid Hydr | 8.00 |
| | lower hose | 1.00 |
| | Radiator Hose | 1.00 |
| | Coolant Ford Gold | 3.00 |
| | Napagold Fuel Filter | 1.00 |
| | 179636492 Lt245-75r17 | 2.00 |
| | Tr416 Valve Stem | 2.00 |
| | Pintle Pin W/chain | 1.00 |
| | Cylinder Repair | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 17.25 | Labor: 1,035.0 | Parts: 1,254.36 |
| : | 0 | Total: 2,289.36 |

Workorder: 1400431 **Meter:** 41028 **In Date:** 01/14/2014 **Closed:** 02/28/2014

Problem: Check crane and right rear outter tire going flat.

| | | |
|--|----------------------|-----------------|
| - Inspect and replace failed valve body solenoid coil with new and repair wiring.diagnose crane for no boom rotation.inspect and replace failed worm pinnion and bearing housing with new. | Parts List | Qty |
| - Use of acetelane torch and straighten bent right rear shock mount bracket with new. | Duplomatic Valve | 1.00 |
| - Pressure test cooling system for water leak.repair Egr cooler hose leak at clamp. | Nut Retainer | 1.00 |
| - Shop Supplies | Bearing Holder Motor | 1.00 |
| | 5068 Penetrating Oil | 1.00 |
| | Shop Supplies | 1.00 |
| | Freight Charge | 1.00 |
| | Freight Charge | 1.00 |
| Hours 5.50 | Labor: 330.00 | Parts: 841.35 |
| : | | Total: 1,171.35 |

Workorder: 1402198 **Meter:** 41028 **In Date:** 03/05/2014 **Closed:** 03/05/2014

Problem: leaking Fluid ?

| | | | | |
|---|------------|-------------|-------------|-------------|
| - Tow From: 12500 40th street North, Royal Palm beach To: Lv shop | Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| | : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

| | | | |
|--|-------------------------------|----------------------------|---------------------------|
| Workorder: 1402205 | Meter: 41251 | In Date: 03/05/2014 | Closed: 03/18/2014 |
| Problem: Towed in for coolant leak. | | | |
| - Pressure test and inspect cooling system.replace defective hose clamp.top off system. | Parts List | | Qty |
| | Peak Global | | 2.00 |
| - Shop Supplies | Shop Supplies | | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 37.46 | Total: 97.46 |
| : | | | |
| Workorder: 1403108 | Meter: 41251 | In Date: 03/18/2014 | Closed: 03/31/2014 |
| Problem: damage to frt bumper & grille | | | |
| - damage to frt bumper & grille | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |
| Workorder: 1403410 | Meter: 41742 | In Date: 04/08/2014 | Closed: 05/20/2014 |
| Problem: Check engine light and no power. | | | |
| - Transport vehicle to dealer for check engine light.(high pressure fuel pump). Dealer replaced worn out body mounts (non warranty). | Parts List | | Qty |
| | Shop Supplies | | 1.00 |
| - Shop Supplies | | | |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 | Total: 122.00 |
| : | | | |
| Workorder: 1406896 | Meter: 42962 | In Date: 07/14/2014 | Closed: 07/28/2014 |
| Problem: Pm service and has to jump start. | | | |
| - P.m. Service. | Parts List | | Qty |
| - Test batteries and charging system.replace both bad batteries. | 15-40 Oil | | 15.00 |
| | Fuel Filter Ford Only | | 1.00 |
| - Inspect and service crane. | Napagold Oil Filter | | 1.00 |
| - Inspect and service aux. fuel system.fabricate and install piping and fuel filter housing.install new filter. | Wiper Blade | | 2.00 |
| | Used Fire X Refurbished | | 1.00 |
| - Replace left headlamp. | Mac Wite Lithium Gres | | 1.00 |
| - Repair left rear tire,rotate and balance all six. | Battery | | 2.00 |
| - Shop Supplies | Napa Hydraulic Filtr | | 1.00 |
| | Napagold Fuel Filter | | 1.00 |
| | Halogen Lamp | | 1.00 |
| | Pintle Pin W/chain | | 1.00 |
| | Adapter | | 1.00 |
| | Aw68 Hydro Fluid Hydr | | 6.00 |
| | Shop Supplies | | 1.00 |
| | 3/4x4 Nipple Galv. (various) | | 1.00 |
| | 3/4 90d Elbow Galv. (various) | | 1.00 |
| Hours 13.00 | Labor: 780.00 | Parts: 457.97 | Total: 1,237.97 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1412125 **Meter:** 44275 **In Date:** 12/03/2014 **Closed:** 12/09/2014
Problem: Towed in for no start.

- Recharge both batteries fully.test each battery and charging system.replace one defective battery on driver side due to a bad cell..install steering wheel cover.(warranty battery)
- Shop Supplies

| | Parts List | Qty |
|------------|----------------------|---------------|
| | Battery | 1.00 |
| | Stg Wheel Cov - Ford | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 140.36 |
| : | | Total: 200.36 |

Workorder: 1412192 **Meter:** 44131 **In Date:** 12/03/2014 **Closed:** 12/04/2014
Problem: no start/ batteries

- Tow From: 12500 40th st north lox To: vista

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1412801 **Meter:** 44583 **In Date:** 12/24/2014 **Closed:** 12/31/2014
Problem: Towed in for no start.

- Recharge both batteries and test charging system.draw from computer killing battery.
- Shop Supplies

| | Parts List | Qty |
|------------|-------------------|--------------|
| | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1412825 **Meter:** 44370 **In Date:** 12/22/2014 **Closed:** 12/29/2014
Problem: wont start

- Tow From: 12500 40th st N, royal palm To: vista

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1505276 **Meter:** 48686 **In Date:** 05/26/2015 **Closed:** 06/18/2015
Problem: Pm service.Install vice.Left outrigger cylinder sticking.Install nozzle for transfer tank pump.

- Pm service.
- Inspect and service Aps auxiliary fuel system.replace broken pump nozzle and extension hose.
- Inspect and replace both front shocks (leaking)
- Check and diagnose right front body amber marker light out.replace complete assembly.
- Fabricate rear bumper pedestal necessary to mount vise.
- Inspect and service hoisting devices crane.
- Inspect and remove both hydraulic outrigger leaking-binding-for repairs.reinstall after repairs.
- Rotate and balance all six wheels.
- Shop Supplies

| | Parts List | Qty |
|-------------|-----------------------|-----------------|
| | 15-40 Oil | 15.00 |
| | Napagold Oil Filter | 1.00 |
| | Wiper Blade | 2.00 |
| | Washer Fluid Concentr | 1.00 |
| | Fuel Filter Ford Only | 1.00 |
| | Napagold Fuel Filter | 1.00 |
| | Gas Grande Fleet Shoc | 2.00 |
| | M C Base Mount Kit | 1.00 |
| | Pintle Pin W/chain | 1.00 |
| | Vise | 1.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | Inv506737 | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 13.50 | Labor: 810.00 | Parts: 582.38 |
| : | | Total: 1,392.38 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1511589 **Meter:** 52896 **In Date:** 11/12/2015 **Closed:** 11/13/2015
Problem: Broken key side bin lock cylinder.

| | | |
|---|-------------------|--------------|
| - Remove bin side door lock cylinder.fabricate and remove broken key from cylinder. | Parts List | Qty |
| | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 1.00 | Labor: 60.00 | Parts: 2.00 |
| : | | Total: 62.00 |

Workorder: 1600336 **Meter:** 54292 **In Date:** 01/11/2016 **Closed:** 01/28/2016
Problem: Pm service.Replace crane cable with longer cable.

| | | |
|--|-------------------------|-----------------|
| - Pm service. | Parts List | Qty |
| - Ccheck and replace two defective center tail light assemblies. | 15-40 Oil | 15.00 |
| | Napagold Oil Filter | 1.00 |
| - Inspect and service auxiliary fuel tank. | Fuel Filter Ford Only | 1.00 |
| - Perform transmission fluid flush and refill. | Used Fire X Refurbished | 1.00 |
| - Replace and balance all six tires. | 20" Wiper Blade | 2.00 |
| - Inspect and service crane.replace crane cable. | Led M C Lamp | 2.00 |
| - Check and replace broken right side rear view mirror. | Napagold Fuel Filter | 1.00 |
| - Complete front end alignment. | Syn-atf Trans Fluid S | 20.00 |
| - Shop Supplies | 179636492 Lt245-75r17 | 6.00 |
| | Tr416 Valve Stem | 6.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | Crane Cable Fabrication | 1.00 |
| | Washer Nozzle | 1.00 |
| | Mirror Assembly | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 6.00 |
| Hours 15.50 | Labor: 930.00 | Parts: 2,222.80 |
| : | | Total: 3,152.80 |

Workorder: 1601422 **Meter:** 54522 **In Date:** 02/10/2016 **Closed:** 02/18/2016
Problem: Gas cap broken.

| | | |
|-----------------------------------|-------------------|--------------|
| - Replace broken fuel filler cap. | Parts List | Qty |
| | Fuel Cap | 1.00 |
| Hours 0.30 | Labor: 18.00 | Parts: 20.04 |
| : | | Total: 38.04 |

Workorder: 1603775 **Meter:** 56442 **In Date:** 04/11/2016 **Closed:** 04/22/2016
Problem: Crane leaking and left front seat belt buckle and right rearhas large cut in it.

| | | |
|--|-------------------|---------------|
| - Replace driver seat belt buckle. | Parts List | Qty |
| - Clean and check hydraulic fitting on crane.remove fittings and reseal.top off fluid. | Seat Belt Buckde | 1.00 |
| | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 3.00 | Labor: 180.00 | Parts: 260.80 |
| : | | Total: 440.80 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1604410 **Meter:** 57062 **In Date:** 04/27/2016 **Closed:** 05/05/2016
Problem: Crane controller inop on winch switch.

| | | |
|--|-------------------------------|--------------|
| - Test and repair inop crane controller. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 1.00 | Labor: 60.00 Parts: 2.00 | Total: 62.00 |
| : | | |

Workorder: 1605256 **Meter:** 57431 **In Date:** 05/20/2016 **Closed:** 05/31/2016
Problem: Hydraulic oil leaking from crane. Replace fuel cap and hydraulic tank cap.

| | | |
|---|----------------------------------|---------------|
| - Replace hydraulic oil tank cap. diagnose hydraulic fluid leaks on crane. remove and reseal pressure lines. clean fluid from crane and truck bed. check and varify crane oiperation. | Parts List | Qty |
| - Replace aux. fuel tank cap. | Hydraulic Cap W Screen | 1.00 |
| - Shop Supplies | Cap | 1.00 |
| | Hydrolic Line | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 5.25 | Labor: 315.00 Parts: 173.41 | Total: 488.41 |
| : | | |

Workorder: 1605742 **Meter:** 57485 **In Date:** 06/03/2016 **Closed:** 06/17/2016
Problem: hitch

| | | |
|---------------------|---------------------------------|---------------|
| - Order hitch parts | Parts List | Qty |
| - Shop Supplies | pintle mount | 1.00 |
| | Pintle Hook With Ball | 1.00 |
| | mounting kit | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 0.50 | Labor: 30.00 Parts: 222.92 | Total: 252.92 |
| : | | |

Workorder: 1606752 **Meter:** 58469 **In Date:** 07/01/2016 **Closed:** 07/05/2016
Problem: Rear Pass outside tire flat, hood up parked in yard, driver waiting

- Tire Service 12500 40th st Loxahatchee N Region Pump Station - Rear Pass outside tire flat, hood up parked in yard, driver waiting

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1606753 **Meter:** 58469 **In Date:** 07/01/2016 **Closed:** 07/05/2016
Problem: Service

- Tire Service 12500 40th street - Service

| | | | |
|------------|-------------|-------------|-------------|
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1607982 **Meter:** 60606 **In Date:** 08/03/2016 **Closed:** 09/12/2016
Problem: P.M. Service.Tow in,no brakes.

| | | |
|--|-----------------------|-----------------|
| - P.m. Service. | Parts List | Qty |
| - Replace and resurface front and rear brake rotors.replace pads and calipers.diagnose Abs light.replace left front wheel speed sensor.flush and bleed brake system. | Napagold Oil Filter | 1.00 |
| | 15-40 Oil | 15.00 |
| - Inspect and service crane. | Napagold Air Filter | 1.00 |
| - Repair one tire,rotate and balance all six. | 20" Wiper Blade | 2.00 |
| - Inspect and service aux. fuel system. | Washer Fluid Concentr | 1.00 |
| - Replace right side upper and lower ball joints. | Slip Plate Spray 12oz | 1.00 |
| - Install adjustable cam bushings.complete wheel alignment.test drive. | B Fluid Dot 3-32oz | 2.00 |
| - Replace tag light assemble.replace right marker lamp. | Brake Cleaner | 1.00 |
| - Shop Supplies | Napa Hydraulic Filtr | 1.00 |
| | Napagold Fuel Filter | 1.00 |
| | M C Base Mount Kit | 1.00 |
| | License Lamp | 1.00 |
| | Fuel Filter Ford Only | 1.00 |
| | Reman Brake Caliper | 1.00 |
| | Reman Brake Caliper | 1.00 |
| | Reman Brake Caliper | 1.00 |
| | Reman Brake Caliper | 1.00 |
| | Sensor Asy | 1.00 |
| | Upper Ball Joint | 1.00 |
| | Lower Ball Joint | 1.00 |
| | Brake Pads | 1.00 |
| | Brake Pad | 1.00 |
| | Brake Rotor-dih | 2.00 |
| | Napa Oil Seal | 2.00 |
| | Bolt | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 27.00 | Labor: 1,620.0 | Parts: 1,001.93 |
| : | 0 | Total: 2,621.93 |

Workorder: 1607998 **Meter:** 59544 **In Date:** 08/03/2016 **Closed:** 08/03/2016
Problem: No Brakes/PM Service

- Tow From: 12500 40th Street North, Royal Palm Beach
To: Lv Shop

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
:

Workorder: 1610447 **Meter:** 61831 **In Date:** 10/11/2016 **Closed:** 10/25/2016
Problem: Check engine light on.

| | | |
|---|-------------------|---------------|
| - Diagnose check engine light.replace exhaust back pressure sensor.clear code.perform forced regen. | Parts List | Qty |
| | Sensor Assembly | 1.00 |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 3.00 | Labor: 180.00 | Parts: 103.03 |
| : | | Total: 283.03 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1700053 **Meter:** 63590 **In Date:** 01/03/2017 **Closed:** 01/03/2017
Problem: FFlat tire on R/P/O

- Tire Service 12500 40th street North - Flat tire on R/p/o

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

Workorder: 1701073 **Meter:** 64665 **In Date:** 02/01/2017 **Closed:** 02/16/2017
Problem: P.M. service.

- P.m. Service.

Parts List **Qty**

- Diagnose and replace defective blower resistor. 15-40 Oil 15.00

- Inspect and service aux fuel system. Napagold Oil Filter 1.00

- Replace two tires,rotate and balance all six. Fuel Filter Ford Only 1.00

- Replace missing front suspension bump stops. 20" Wiper Blade 2.00

- Replace rear bump stops. Washer Fluid Concentr 1.00

- Replace rear marker lamp. Used Fire X Refurbished 1.00

- Replace pintle pin.repair vise.retorque exhaust bolts at Blower Resistor 1.00

flange to correct leak. Napagold Fuel Filter 1.00

- Inspect and service creane. 179636492 Lt245-75r17 2.00

- Replace left cam adjuster and lube and free right bumper 2.00

side.complete wheel alignment.test drive. Real Suspension Bumpstops 2.00

- Shop Supplies Mount 1.00

Led M C Lamp 1.00

Pintle Pin W/clip 1.00

Napagold Fuel Filter 1.00

Caster-camber Bushing 1.00

Shop Supplies 1.00

Tire Disposal Fee 2.00

Hours 15.50 Labor: 930.00 Parts: 858.06 Total: 1,788.06
 :

Workorder: 1704024 **Meter:** 66484 **In Date:** 04/21/2017 **Closed:** 04/28/2017
Problem: Crane switches broken.

- Replace two switches on crane remote.tightened bolts for remote plug on crane retest(parts no charge.)

Parts List **Qty**

Shop Supplies 1.00

- Shop Supplies

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
 :

Workorder: 1705605 **Meter:** 67617 **In Date:** 06/02/2017 **Closed:** 06/06/2017
Problem: accident

- Tow From: okeechobee/wildcat way To: vista

Hours 0.00 Labor: 0.00 Parts: 0.00 Total: 0.00
 :

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1706378 **Meter:** 67743 **In Date:** 06/28/2017 **Closed:** 07/20/2017

Problem: Check vehicle after body repairs(front end collision.)

| | | |
|---|-------------------|---------------|
| - Inspect vehicle from front end damage repair.tighten air cleaner.replace right front side marker lamp bulb. | Parts List | Qty |
| | Bulb | 1.00 |
| - Check front end alignment, made minor adjustments. | Shop Supplies | 1.00 |
| - r/r cross over exhaust pipe replacement. | | |
| - Shop Supplies | | |
| Hours 3.50 | Labor: 210.00 | Parts: 2.41 |
| : | | Total: 212.41 |

Workorder: 1706557 **Meter:** 67617 **In Date:** 06/07/2017 **Closed:** 07/03/2017

Problem: Damage to hood, grille, bumper, coolers, condenser, right front fender & possible under hood

| | | | |
|--|-------------|-------------|-------------|
| - Damage to hood, grille, bumper, coolers, condenser, right front fender & possible under hood | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1708747 **Meter:** 69748 **In Date:** 09/05/2017 **Closed:** 10/24/2017

Problem: P.M. service and truck overheats and AUX fuel tank leaking.

| | | |
|---|---------------------------|-----------------|
| - P.m. Service. | Parts List | Qty |
| - Inspect and service crane. | 15-40 Oil | 15.00 |
| - Replace two tires,rotate and balance all six. | Napagold Oil Filter | 1.00 |
| - Replace left tail lamp.replace right side rear marker light..replace left spot lamp in light bar. | Fuel Filter Ford Only | 1.00 |
| | Napagold Air Filter | 1.00 |
| - Replace leaking aux. fuel tank.rewire transfer pump. | Used Fire X Refurbished | 1.00 |
| - Shop Supplies | 20" Wiper Blade | 2.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | 179636492 Lt245-75r17 | 2.00 |
| | M C Base Mount Kit | 1.00 |
| | Led Sup Mdl 44 42 Dio | 2.00 |
| | Stg Wheel Cov - Ford | 1.00 |
| | Aw68 Hydro Fluid Hydr | 11.00 |
| | Bar Light Bulb | 1.00 |
| | Delta Transfer Tank 96gal | 1.00 |
| | Napagold Fuel Filter | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 15.50 | Labor: 930.00 | Parts: 1,450.25 |
| : | | Total: 2,380.25 |

Workorder: 1708990 **Meter:** 69361 **In Date:** 09/19/2017 **Closed:** 09/20/2017

Problem: needs handle for crane boom

| | | |
|---|-------------------|---------------|
| - Fab and install boom-release handle for crane | Parts List | Qty |
| - Remove problem canceiver issue fuel card | Shop Supplies | 1.00 |
| - Shop Supplies | | |
| Hours 3.00 | Labor: 180.00 | Parts: 2.00 |
| : | | Total: 182.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1710831 **Meter:** 69777 **In Date:** 11/01/2017 **Closed:** 11/16/2017
Problem: No crank and left side bin door stricker missing.

| | | | |
|--|---|--|-----------------|
| <ul style="list-style-type: none"> - Charge batteries fully .test batteries and charging system.r&r defective batteries that failed load test. - Replace right headlight sealed beam bulb. - A/c performance test ,leak test .recover feon .r&r leaking condensor,accumulator,orifice tube and high side line from condensor to compressor.evacuate and fully charge system to spec.retest. - Repair left front utility bin door stricker and adjust. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Battery Halogen Lamp Accumulator Line Asy Seal Tube Filter A/c Condenser Seal Kits Freon Lv Shop 2 E8 A/c Oil Univ W Dye Shop Supplies | <p>Qty</p> <ul style="list-style-type: none"> 2.00 1.00 1.00 1.00 4.00 1.00 1.00 2.00 1.00 1.00 | |
| Hours 9.00 : | Labor: 540.00 | Parts: 981.59 | Total: 1,521.59 |

Workorder: 1711753 **Meter:** 70113 **In Date:** 11/29/2017 **Closed:** 11/30/2017
Problem: Inner, rear, passenger flat

| | | | | |
|--|-----------------|-------------|-------------|-------------|
| <ul style="list-style-type: none"> - Tire Service Nroc, 12500 40th st N - Inner, rear, passenger flat | Hours 0.00 : | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
|--|-----------------|-------------|-------------|-------------|

Workorder: 1802065 **Meter:** 72734 **In Date:** 02/23/2018 **Closed:** 03/06/2018
Problem: Right rear hub missing studs and lug nuts.

| | | | |
|--|---|--|---------------|
| <ul style="list-style-type: none"> - Remove right rear wheels and tires.remove and replace all eight wheel studs and nuts and wheels .swap tires to different wheels.torque wheel lugs and check all wheels. - Shop Supplies | <p>Parts List</p> <ul style="list-style-type: none"> Bolt Wheel Nut Tr416 Valve Stem Shop Supplies | <p>Qty</p> <ul style="list-style-type: none"> 8.00 8.00 2.00 1.00 | |
| Hours 3.50 : | Labor: 210.00 | Parts: 123.38 | Total: 333.38 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1803483 **Meter:** 73602 **In Date:** 04/03/2018 **Closed:** 04/11/2018
Problem: P.M. service and noise from rear when braking.

| | | |
|---|-----------------------|-----------------|
| - P.m. service. | Parts List | Qty |
| - Inspect and service auxilary fuel tank. | Aw68 Hydro Fluid Hydr | 6.00 |
| - Inspect and service hydraulic crane. | Napagold Oil Filter | 1.00 |
| - Check brake noise .replace missing caliper bracket bolts and retorque all four bracket bolts .test drive. | 15-40 Oil | 15.00 |
| - Replace damaged transmission pan and gasket .replace filter and refill transmission . | 20" Wiper Blade | 2.00 |
| - Repair left rear outter tire .rotate and balance all six tires..nitrofill. | Led Lamp | 1.00 |
| - Shop Supplies | Fuel Filter Ford Only | 1.00 |
| | Napagold Fuel Filter | 1.00 |
| | Napa Hydraulic Filtr | 1.00 |
| | Slip Plate Spray 12oz | 1.00 |
| | Syn-atf Trans Fluid S | 8.00 |
| | Bolt | 2.00 |
| | Pan Asy | 1.00 |
| | Trans Filter | 1.00 |
| | Trans Pan Gasket | 1.00 |
| | Shop Supplies | 1.00 |
| Hours 10.80 | Labor: 648.00 | Parts: 451.51 |
| : | | Total: 1,099.51 |

Workorder: 1805441 **Meter:** 75091 **In Date:** 05/29/2018 **Closed:** 06/07/2018
Problem: Towed in for no start, check engine light on and white smoke.

| | | |
|--|-----------------------|---------------|
| - Diagnose check engine light . codes P242e and P200f .perform pinpoint test . Replace all three Egt sensors and retap thrid sensors mount . Clear codes and retest. | Parts List | Qty |
| - Check transmission fluid level .test drive and recheck .add one and half quarts fluid . | exhaust sensor | 3.00 |
| - Shop Supplies | Syn-atf Trans Fluid S | 2.00 |
| | Shop Supplies | 1.00 |
| Hours 2.50 | Labor: 150.00 | Parts: 293.09 |
| : | | Total: 443.09 |

Workorder: 1805598 **Meter:** 74794 **In Date:** 05/11/2018 **Closed:** 06/01/2018
Problem: No Start

| | | | |
|---|-------------|-------------|-------------|
| - Tow From: Sr 7 N of Okeechobee Blvd To: Lv shop | | | |
| Hours 0.00 | Labor: 0.00 | Parts: 0.00 | Total: 0.00 |
| : | | | |

Workorder: 1807145 **Meter:** 75750 **In Date:** 07/13/2018 **Closed:** 07/19/2018
Problem: Crane stop working, cable tangled up.

| | | |
|--|-------------------|---------------|
| - Diagnose crane inop. Repair wire in crane pendent. Operate crane .remove birdcaged wire rope and reinstall and respool. Test operation of crane. | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 120.00 | Parts: 2.00 |
| : | | Total: 122.00 |

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1810068 **Meter:** 78186 **In Date:** 09/28/2018 **Closed:** 10/17/2018
Problem: PM Service

| | | |
|--|--------------------------|-----------------|
| - P.m. service. | Parts List | Qty |
| - Inspect and service auxillary fuel system . | Napagold Oil Filter | 1.00 |
| - Inspect and service crane . | 15-40 Oil | 15.00 |
| - Test and replace left side amber marker light and both reverse lamps . | Fuel Filter Ford Only | 1.00 |
| - Replace leaking hydro booster . Bleed and fill power steering fluid . | Used Fire X Refurbished | 1.00 |
| - Replace left front upper and lower ball joints. Repack wheel bearings and replace seal . | Washer Fluid Concentr | 1.00 |
| - Replace two worn tires . Rotate and balance all six tires. | 22" Wiper Blade | 2.00 |
| - Complete front end alignment and road test. | Napagold Fuel Filter | 1.00 |
| - Replace front asset number . | Napa Hydraulic Filtr | 1.00 |
| - Shop Supplies | Aw68 Hydro Fluid Hydr | 4.00 |
| | Led Back-up Lamp Sys | 2.00 |
| | M C Base Mount Kit | 1.00 |
| | Brake Booster | 1.00 |
| | Non-chlor Brake Clnr | 1.00 |
| | Syn-atf Trans Fluid S | 2.00 |
| | Lower Ball Joint | 1.00 |
| | Upper Ball Joint | 1.00 |
| | Tr416 Valve Stem | 2.00 |
| | 179636492 Lt245-75r17 | 2.00 |
| | Wheel Seal - Front Wheel | 1.00 |
| | Shop Supplies | 1.00 |
| | Tire Disposal Fee | 2.00 |
| Hours 18.90 | Labor: 1,266.3 | Parts: 1,451.20 |
| : | 0 | Total: 2,717.50 |

Workorder: 1901354 **Meter:** 80695 **In Date:** 02/04/2019 **Closed:** 02/08/2019
Problem: remove saddle tank and generator as per customer

| | | |
|--|-------------------|---------------|
| - Remove compressor and saddle tank per dept request | Parts List | Qty |
| - Shop Supplies | Shop Supplies | 1.00 |
| Hours 2.00 | Labor: 134.00 | Parts: 3.00 |
| : | | Total: 137.00 |

Workorder: 1901402 **Meter:** 80695 **In Date:** 02/05/2019 **Closed:** 02/05/2019
Problem: Transition Prep Charge

| | | |
|--------------------------|---------------|---------------|
| - Transition Prep Charge | | |
| Hours 2.00 | Labor: 134.00 | Parts: 0.00 |
| : | | Total: 134.00 |