10179135 2009 FORD E350 Van, 1 Ton, Cargo

			3133 20	00.0.12	_000	11, 1 1011, 0	ai go			
Workorder: Problem:	940067 Pre Delivery I	Meter: Inspection	0			In Date:	07/02/2009	Closed:	07/02/20	009
- Pre Delivery	Inspection									
	Hou :	rs 2.00		Labor:	120.00	Parts:	0.00	Total:	120.00	
Workorder: Problem:	944551 right rear tire	Meter: flat	2292			In Date:	10/14/2009	Closed:	10/15/20	009
- Repair R/r ti	re.				Parts Li	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	946537 Nail in R/F tire	<b>Meter:</b> e	3237			In Date:	12/01/2009	Closed:	12/02/20	009
- Repair R/f tii	e.				Parts Li	ist				Qty
- Shop Suppli	es				Shop St	upplies				1.00
	Hou :	rs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	947116 P.M service.	Meter:	3496			In Date:	12/16/2009	Closed:	12/31/20	009
- P.m. Service	)				Parts Li	ist				Qty
- Rotate and b	alance all tire	S.			Shop St	upplies				1.00
- Shop Suppli	es				1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
					Ca8039	Air Filter Lb	of Af1615 Wix	46418		1.00
					5w20 Er	ngine Oil				7.00
					31-20 W	/iper Blades	20" Blade			2.00
	Hou :	rs 5.00		Labor:	300.00	Parts:	33.71	Total:	333.71	
Workorder: Problem:	1005748 P.M service.	Meter:	6879			In Date:	06/02/2010	Closed:	06/08/20	010
- Perform pm	service.				Parts Li	ist				Qty
- Brake pedal					Shop St	upplies				1.00
rotors,repack v	_		d lube caliper	slides.	1372 O	il Filter Frm	Ph2 Wix 513	372		1.00
- Rotate and b		S.			5w20 Er	ngine Oil				7.00
- Shop Suppli	es				Used Fi	rex Refurbe	d Fire Extings	hers		1.00
					31-20 W	/iper Blades	20" Blade			2.00
					D3tz245	7b Brake P	edal Pad			1.00
	Hou	rs 8.00		Labor:	480.00	Parts:	49.82	Total:	529.82	

Workorder: Problem:	1013619 Pm service.	Meter:	11939			In Date:	12/10/2010	Closed:	12/16/20	010
- P.mn. Servi	ce				Parts Lis	t				Qty
- Rotate and I	palance tires.				Shop Sup	plies				1.00
- Shop Suppli	es						Ph2 Wix 513	372		1.00
					5w20 Eng	gine Oil				7.00
					-		20" Blade			2.00
	Hou	urs 5.00		Labor:	300.00	Parts:		Total:	327.31	
Workorder: Problem:	1013820 flash canceiv	Meter: ver spot 227	11949		]	In Date:	12/16/2010	Closed:	12/22/20	010
- Reflash can	ceiver and rep	program			Parts Lis	t				Qty
- Shop Suppli	es				Shop Sup	plies				1.00
	Ηοι :	urs 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
Workorder: Problem:	1101037 Left rear tire	Meter: flat.	12919		!	In Date:	01/27/2011	Closed:	01/28/20	011
- Repair and I	oalance left re	ear tire.			Parts Lis	t				Qty
- Shop Suppli					Shop Sup					1.00
		urs 1.00		Labor:		Parts:	2.00	Total:	62.00	
Workorder: Problem:	1106829 Pm service.	Meter:	16151		ļ	In Date:	06/28/2011	Closed:	07/06/20	011
- Perform pm	service.				Parts Lis	t				Qty
- Fabricate ar	nd replace fail	ed hitch pin	del pin with r	new.	Shop Sup	plies				1.00
- Rotate and I	palance all for	ur tires.	-		1372 Oil	Filter Frm	Ph2 Wix 513	372		1.00
- Shop Suppli	es				Ca8039 A	Air Filter Lb	of Af1615 Wix	46418		1.00
					5w20 Eng	gine Oil				7.00
					Used Fire	x Refurbe	d Fire Extings	hers		1.00
					31-20 Wip	oer Blades	20" Blade			2.00
					18410 Pir	ntle Pin				1.00
	Hou :	urs 5.50		Labor:	330.00	Parts:	53.71	Total:	383.71	
Workorder: Problem:	1201208 Pm service.	Meter:	20814		[	In Date:	02/06/2012	Closed:	02/24/20	012
- P.m. Service	Э.				Parts Lis	t				Qty
- Rotate and I		es.			Shop Sup					1.00
- Complete w	heel alignmer	nt.				•	Ph2 Wix 513	372		1.00
- Shop Suppli	_				5w20 Eng					7.00
,,-					_		20" Blade			2.00
							d Fire Extings	hers		1.00
	Hou :	urs 7.50		Labor:	450.00		45.57		495.57	- <del>-</del>

- Shop Supplies	Workorder: Problem:	1205009 Left rear tir	Meter: e going flat.	22954			In Date:	05/30/2012	Closed:	06/04/20	012
Hours 1.00	- Repair and I	oalance righ	t rear tire.			Parts Li	st				Qty
Workorder:   1207785   Meter:   24812   In Date:   08/16/2012   Closed:   08/29/2012	- Shop Suppli	es				Shop Su	upplies				1.00
Problem: Pm service.  - P.m. Service Resurface front and rear brake rotors, replace rear pads. service and lube calipers. flush and bleed system and test drive Clean and lube sliding door tracks.adjust hinges and latch. Rotate and balance all tires Shop Supplies - Shop Supplies - Clean and lube sliding door tracks.adjust hinges and latch. Rotate and balance all tires Shop Supplies - Shop Supplies - Ca8039 Air Filter Lbf Af1615 Wix 46418 - 1.00 - Rotate and balance all tires Shop Supplies - Shop Supplies - Fisce Fold Brake Fluid Brake Fluid - Sw20 Engine Oil - Wd40 Spray Lube Stock# 405540002 - 31-20 Wiper Blades 20" Blade - F75z6730ba Drain Plug - 1.00 - Parts: 104.82 - Total: 839.82 - Total: 839.82  Workorder: 1302261 - P.m. Service P.m. Service P.m. Service Replace and balance four new tires Test battery and charging system.recharge and retest battery, fail load test.replace defective battery Shop Supplies - Shop Supplies - Traff6 Valve Stem - Shop Supplies - 1.00 - Total Stem - And Stem Stem Stem Stem - Replace Stem - Repl		H(	ours 1.00		Labor:	60.00	Parts:	2.00	Total:	62.00	
- Resurface front and rear brake rotors, replace rear pads. service and lube calipers. flush and bleed system and test drive.  - Clean and lube sliding door tracks. adjust hinges and latch Rotate and balance all tires Shop Supplies  - Shop Supplies  - Shop Supplies  - Rotate and balance all tires Shop Supplies  - Clean and lube sliding door tracks. adjust hinges and latch Rotate and balance all tires Shop Supplies  - Rotate and balance all tires Shop Supplies  - Shop Supplies				24812			In Date:	08/16/2012	Closed:	08/29/20	012
Dadds.service and lube calipers.flush and bleed system and test drive.	- P.m. Service	€.				Parts Li	st				Qty
test drive Clean and lube sliding door tracks.adjust hinges and latch Rotate and balance all tires Shop Supplies - Sh	- Resurface fr	ont and rea	r brake rotors	,replace rear		Shop St	upplies				1.00
- Clean and lube sliding door tracks.adjust hinges and latch Rotate and balance all tires Shop Supplies - Ca8039 Air Filter Lbf Af1615 Wix 46418 - Mkd1329 Rear Pads - 1.0 - Mkd1329 Rear Pads - 1.0 - Sw20 Engine Oil - Wd40 Spray Lube Stock# 405540002 - 31-20 Wiper Blades 20" Blade - F75z6730ba Drain Plug - Total: 839.82 - Total		and lube cali	pers.flush an	d bleed syster	m and	1372 O	372		1.00		
Rotate and balance all tires.		لم ممالمالم ممار		livet bisess on	مامدما ام	Ca8039	Air Filter L	of Af1615 Wix	46418		1.00
- Shop Supplies    1401   Brake Fluid Brake Fluid   2.0		_		ijust ninges an	id laten.	Mkd132		1.00			
Workorder: 1302261   Meter: 29738   In Date: 03/06/2013   Closed: 03/18/2013			ires.			1401 Brake Fluid Brake Fluid					2.00
31-20 Wiper Blades 20" Blade   2.00   F75z6730ba Drain Plug   1.00   1.00   F75z6730ba Drain Plug   1.00   1.00   F75z6730ba Drain Plug   1.00   1.00   F75z6730ba Drain Plug   1.00   F	- Shop Suppli	es				5w20 Engine Oil					7.00
Hours 12.25						Wd40 Spray Lube Stock# 405540002					1.00
Hours 12.25   Labor: 735.00   Parts: 104.82   Total: 839.82						31-20 W	/iper Blades	20" Blade			2.00
:  Workorder: 1302261 Meter: 29738 In Date: 03/06/2013 Closed: 03/18/2013  Problem: P.M. Service.  - P.m. Service.  - Replace and balance four new tires.  - Test battery and charging system.recharge and retest battery,fail load test.replace defective battery.  - Shop Supplies    In Date: 03/06/2013 Closed: 03/18/2013						F75z673	30ba Drain	Plug			1.00
Problem: P.M. Service.  - P.m. Service.  - Replace and balance four new tires.  - Test battery and charging system.recharge and retest battery, fail load test.replace defective battery.  - Shop Supplies  Parts List  5w20 Engine Oil  1372 Oil Filter  1.00  Used Firex Refurbed F  179747492 Lt245-75r16  Battery 65  Tr416 Valve Stem  Shop Supplies  1.00  Shop Supplies		H(	ours 12.25		Labor:	735.00	Parts:	104.82	Total:	839.82	
- Replace and balance four new tires.  - Test battery and charging system.recharge and retest battery, fail load test.replace defective battery.  - Shop Supplies  5w20 Engine Oil 7.00 1372 Oil Filter 1.00 1.00 179747492 Lt245-75r16 1.00 179747492 Lt245-75r16 1.00 17416 Valve Stem 1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.0				29738			In Date:	03/06/2013	Closed:	03/18/20	013
- Test battery and charging system.recharge and retest battery, fail load test.replace defective battery Shop Supplies  1372 Oil Filter  Used Firex Refurbed F  1.00	- P.m. Service	Э.				Parts Li	st				Qty
battery,fail load test.replace defective battery.  - Shop Supplies  179747492 Lt245-75r16  Battery 65  Tr416 Valve Stem  Shop Supplies  1.00  Shop Supplies  1.00	- Replace and	d balance fo	ur new tires.			5w20 Er	ngine Oil				7.00
- Shop Supplies 179747492 Lt245-75r16 4.0  Battery 65 1.0  Tr416 Valve Stem 4.0  Shop Supplies 1.0					est	1372 Oi	l Filter				1.00
Battery 65 1.0  Tr416 Valve Stem 4.0  Shop Supplies 1.0	-	-	e defective b	attery.		Used Fi	rex Refurbe	d F			1.00
Tr416 Valve Stem 4.00 Shop Supplies 1.00	- Shop Suppli	es				179747	192 Lt245-7	5r16			4.00
Shop Supplies 1.0						Battery	65				1.00
· ··						Tr416 V	alve Stem				4.00
Tire Disposal Fee 4.0						Shop St	upplies				1.00
						Tire Dis	posal Fee				4.00

Labor: 345.00

Parts: 1,056.19

Total: 1,401.19

Hours 5.75

Problem:	1309597 Pm service	Meter:	35859		lı	n Date:	09/23/2013	Closed:	10/16/2013	
- P.m. Service	<b>)</b> .				Parts List				Qty	
- R&r driver se	eat and send o	ut for upho	olstery repairs.		5w20 Engi	ne Oil			7.00	
- Replace one	tire,rotate and	d balance a	all four.		Napagold Oil Filter					
- Shop Supplie	es				Napagold	Air Filter			1.00	
					31-20 Wip	er Blades	s 20		2.00	
					Pedal Pad				1.00	
					179747492	2 Lt245-7	5r16		1.00	
					Caliper Ha	rdware			1.00	
					Seat R An	d R			1.00	
					Shop Supp	olies			1.00	
					Tire Dispo	sal Fee			1.00	
	Hour	rs 6.50		Labor:	390.00	Parts:	572.71	Total:	962.71	
Workorder: Problem:	1402849 Pm service.	Meter:	40044		lı	n Date:	03/25/2014	Closed:	04/21/2014	
- Perform pm	service.				Parts List				Qty	
	ront brake pad				5w20 Engine Oil 7.0					
	ush brake fluid		d bleed hydrau	ulic	Napagold	Oil Filter			1.00	
•	an tool and ro				Wiper Blad	de			2.00	
	ed driver door v eat trim panel w				Used Fire	X Refurb	ished		1.00	
cargo door sil			p.a.co .aca	9	Brake Pad	S			1.00	
- Repair flat rig	ght rear tire.nit	rogen fill a	nd balance all	l four.	Brake Clea	aner			1.00	
	ailer lights inop			railer	Weatherst	ripping			1.00	
harness socke	t with new.ther	n insulate a	and secure.		Hardware	Kit			2.00	
- Shop Supplie	es				Cover				1.00	
					Plate				1.00	
					Rivet				8.00	
					Trailer Cor	nn Socke	t		1.00	
					Shop Supp				1.00	
	Hour	rs 13.25		Labor:	795.00		480.80	Total:	1,275.80	
Workorder: Problem:	: 1409426 Pm service	Meter:	43827		lı	n Date:	09/19/2014	Closed:	09/30/2014	
		Meter:	43827		lı Parts List		09/19/2014	Closed:		
<b>Problem:</b> - Pm service.	Pm service		43827		Parts List		09/19/2014	Closed:	09/30/2014 <b>Qty</b> 7.00	
Problem: - Pm service Inspect,and	Pm service flush transmiss	sion fluid.	43827		Parts List 5w20 Engi	ne Oil	09/19/2014	Closed:	<b>Qty</b> 7.00	
Problem: - Pm service Inspect, and to	Pm service flush transmiss palance all four	sion fluid.	43827		Parts List 5w20 Engi Napagold	ne Oil Oil Filter	09/19/2014	Closed:	<b>Qty</b> 7.00 1.00	
Problem: - Pm service Inspect,and	Pm service flush transmiss palance all four	sion fluid.	43827		Parts List 5w20 Engi Napagold Wiper Blace	ne Oil Oil Filter de		Closed:	<b>Qty</b> 7.00 1.00 2.00	
Problem: - Pm service Inspect, and to	Pm service flush transmiss palance all four	sion fluid.	43827		Parts List 5w20 Engi Napagold Wiper Blac Washer Fl	ne Oil Oil Filter de uid Conc	entr	Closed:	<b>Qty</b> 7.00 1.00 2.00 1.00	
Problem: - Pm service Inspect, and to	Pm service flush transmiss palance all four	sion fluid.	43827		Parts List 5w20 Engi Napagold Wiper Blace	ne Oil Oil Filter de uid Conca ans Fluid	entr	Closed:	<b>Qty</b> 7.00 1.00 2.00	

Workorder:	1412318	Meter:	46867			In Date:	12/04/2014	Closed:	12/09/2014
Problem:	Flat tire on	P/R							
- Tire Service	Mlk and Ave	e P (parks Ma	aint) - Flat tire	e on P/r					
	Ho	ours 0.00		Labor:	0.00	Parts:	0.00	Total:	0.00
Workorder:	1502559	Meter:	49200			In Date:	03/11/2015	Closed:	03/31/2015
Problem:	Pm service	.Trailer brake	controller in	op.					
- Pm service.					Parts L	ist			Qty
- Pressure te		ct cooling sys	tem.flush an	d refill	5w20 E	ngine Oil			7.00
engine coolan					Napago	old Oil Filter			1.00
- R&i damage			•	•		old Air Filter			1.00
<ul> <li>Test and replacement</li> <li>fabricate wirin</li> </ul>		trailer brake	controller an	iu	Wiper B				2.00
- Rotate and		Mac Ba	1.00						
- Shop Suppl		Pedal P	1.00						
,,,					Peak G				2.00
						ire X Refurbi	shed		1.00
					Brake (				1.00
					Seat R	-			1.00
					Shop S				1.00
	Ho	ours 9.25		Labor:	555.00	Parts:	539.36	Total:	1,094.36
Workorder: Problem:	1506311 Check traile	Meter: er plug outlet.	51842			In Date:	06/23/2015	Closed:	06/25/2015
Problem: - Diagnose tra	Check traile	er plug outlet		ectrical	Parts L		06/23/2015	Closed:	06/25/2015 <b>Qty</b>
Problem: - Diagnose tracconnector and	Check traile ailer connect d rewire.retes	er plug outlet		ectrical				Closed:	
Problem: - Diagnose tra	Check traile ailer connect d rewire.retes	er plug outlet		ectrical		ist Conn Socke		Closed:	Qty
Problem: - Diagnose tracconnector and	Check traile ailer connect d rewire.retes ies	er plug outlet		ectrical Labor:	Female Shop S	<b>ist</b> Conn Socke upplies			<b>Qty</b> 1.00
Problem: - Diagnose tracconnector and	Check traile ailer connect d rewire.retes ies	er plug outlet. or .r&r dama st.			Female Shop S	<b>ist</b> Conn Socke upplies	et		<b>Qty</b> 1.00 1.00
Problem: - Diagnose traconnector and - Shop Suppl	Check traile ailer connect d rewire.retes ies Ho :	er plug outlet. or .r&r damaget. ours 1.25  Meter:	ge six pin ele		Female Shop S	<b>ist</b> Conn Socke upplies Parts:	et 13.12	Total:	<b>Qty</b> 1.00 1.00 88.12
Problem: - Diagnose traconnector and - Shop Suppl	Check trailed ailer connect of rewire.retesties  Hotel: 1509621 Pm service	er plug outlet. or .r&r damaget. ours 1.25  Meter:	ge six pin ele		Female Shop S	ist Conn Socke upplies Parts: In Date:	et 13.12	Total:	<b>Qty</b> 1.00 1.00 88.12
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem:	Check trailed ailer connected rewire.retesties  Hotel: 1509621 Pm service	er plug outlet. or .r&r damaget. ours 1.25  Meter:	ge six pin ele		Female Shop Si 75.00	ist Conn Socke upplies Parts: In Date:	et 13.12	Total:	Qty 1.00 1.00 88.12 10/13/2015
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace right	Check trailed ailer connected rewire.retesties  Hotel: 1509621 Pm service  of tires.rotate and front camb	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Female Shop Si 75.00 Parts L 5w20 E	ist Conn Socke upplies Parts: In Date:	et 13.12	Total:	Qty 1.00 1.00 88.12 10/13/2015 Qty
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace rigit complete from	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Female Shop Si 75.00 Parts L 5w20 E	ist Conn Socke upplies Parts: In Date: ist ngine Oil	et 13.12	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace right	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Female Shop Si 75.00 Parts L 5w20 E Napago Wiper B Lt245 7	ist Conn Socke upplies Parts: In Date: ist ngine Oil old Oil Filter Blade 5r16	et 13.12	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00 1.00
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace rigit complete from	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Parts L 5w20 E Napago Wiper B Lt245 73	ist Conn Socke upplies Parts: In Date:  ist ngine Oil old Oil Filter Blade 5r16 /alve Stem	et 13.12 09/23/2015	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00 1.00 2.00 2.00 2.00
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace rigit complete from	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Parts L 5w20 E Napago Wiper B Lt245 75 Tr416 V Caster-	ist Conn Socke upplies Parts: In Date: ist ngine Oil old Oil Filter Blade 5r16 /alve Stem camber Bus	et 13.12 09/23/2015	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00 1.00 2.00 2.00 2.00 1.00
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace rigit complete from	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Parts L 5w20 E Napago Wiper B Lt245 73	ist Conn Socke upplies Parts: In Date: ist ngine Oil old Oil Filter Blade 5r16 /alve Stem camber Bus	et 13.12 09/23/2015	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00 1.00 2.00 2.00 2.00 1.00 1.00 1.00
Problem: - Diagnose traconnector and - Shop Suppl  Workorder: Problem: - Pm service Replace two - Replace right	Check trailed ailer connected rewire.retesties  Hotel 1509621 Pm service of tires.rotate that front camb tend alignments.	er plug outlet. or .r&r damaget. ours 1.25  Meter: and balance per/caster adj	ge six pin ele 54569 all four.	Labor:	Parts L 5w20 E Napago Wiper B Lt245 7: Tr416 V Caster-c Shop Si	ist Conn Socke upplies Parts: In Date: ist ngine Oil old Oil Filter Blade 5r16 /alve Stem camber Bus	et 13.12 09/23/2015	Total:	Qty 1.00 1.00 88.12  10/13/2015  Qty 7.00 1.00 2.00 2.00 2.00 1.00

Workorder: 160 Problem: P.N	03721 M. service.	Meter:	60196			In Date:	04/08/2016	Closed:	04/19/2	016
- P.m. Service.					Parts Lis	st				Qty
- Test battery and	I charging s	ystem.rep	lace bad batt	ery.	5w20 En	gine Oil				7.00
- Replace two tire		-		•	Napagolo		1.00			
- Resurface rear l					22" Wiper Blade					2.00
pads.service and	adjuste rear	brakes.fl	ush and bleed	d system.	Battery		1.00			
- Pressure test ar	nd inspect c	ooling sys	tem.flush and	d refill	Lt245 75r16					2.00
system.					Semi Los	ded Calipe	er			1.00
- Shop Supplies					Semi Loa	aded Calipe	er			1.00
					B Fluid D	ot 3-32oz				1.00
					Brake Cl	eaner				2.00
					Peak Glo	bal				2.00
					Tr416 Va	lve Stem				2.00
					Disc Pad					1.00
					Drain Plu	g				1.00
					Shop Sup	oplies				1.00
					Tire Disp	osal Fee				2.00
	Hours :	s 13.00		Labor:	780.00	Parts:	865.17	Total:	1,645.1	7
Workorder: 160 Problem: Rig	06420 ght brake lig	Meter: ht inop	62537			In Date:	06/23/2016	Closed:	06/29/2	016
- Replace right br	ake lamp bi	ulb.			Parts Lis	st				Qty
					Bulb					1.00
	Hours	s 0.50		Labor:	30.00	Parts:	0.78	Total:	30.78	
	09520	Meter:	65512			In Date:	09/13/2016	Closed:	09/27/2	016
Problem: P.N	M. Service.									
- P.m. Service.					Parts Lis	st				Qty
- Replace center	brake lamp	bulbs.			5w20 En	gine Oil				7.00
- Inspect and serv	ice rear dif	ferential.			Napagolo	d Oil Filter				1.00
- Rotate and bala	nce all tires									1.00
				20" Wipe	r Blade				2.00	
<ul> <li>Shop Supplies</li> </ul>										
- Shop Supplies					Washer F	Fluid Conce	entr			1.00
- Shop Supplies					Washer F Pedal Pa	Fluid Conce	entr			1.00 1.00
- Shop Supplies					Pedal Pa	Fluid Conce				
- Shop Supplies					Pedal Pa	Fluid Conce d				1.00
- Shop Supplies					Pedal Pa Used Fire Rpl Bulb	Fluid Conce d	ished			1.00 1.00
- Shop Supplies					Pedal Pa Used Fire Rpl Bulb	Fluid Conco d e X Refurbi Ford Axle L	ished			1.00 1.00 1.00
- Shop Supplies					Pedal Pa Used Fire Rpl Bulb 75w140 I Friction M	Fluid Conco d e X Refurbi Ford Axle L	ished Lube			1.00 1.00 1.00 3.00
- Shop Supplies					Pedal Pa Used Fire Rpl Bulb 75w140 I Friction M	Fluid Conco d e X Refurbi Ford Axle L Modifier a Grey 3oz	ished Lube			1.00 1.00 1.00 3.00 2.00

Workorder: 170 Problem: P.M	1814 I. service ar	<b>Meter:</b> nd A/C far	70875 n inop.		lr	n Date:	02/21/2017	Closed:	03/16/2017
- P.m. Service.					Parts List				Qt
- Diagnose and rep	place a/c bl	ower resi	stor.replace	burnt	V Belt				1.0
connector.					5w20 Engi	7.0			
- Replace and rew		•	lug.		Napagold (		1.0		
- Tune-up.replace					Cover				1.0
<ul> <li>Service and clear injectors.</li> </ul>	n throttle bo	ody and in	nduction syst	tem.flush	20" Wiper I	Blade			2.0
- Replace serpenti	ine belt.				Blower Mo	tor Resis	tor		1.0
- Rotate and balan					trailer plug				1.0
- Shop Supplies					Spark Plug				8.0
					Intake Clea				1.0
					Injector Cle				1.0
					Connector		Resistor		1.0
	Houre	14.75		Labor	Shop Supp 885.00		294.95	Total	1.0
	:	14.75		Labor.	005.00	raits.	294.90	TOtal.	1,179.95
Workorder: 170 Problem: Left	4430 brake light	Meter: inop.	72132		lr	n Date:	05/02/2017	Closed:	05/11/2017
- Replace left brak	e lamp bulb	Э.			Parts List				Qt
·	·				Bulb				1.0
	Hours	0.50		Labor:	30.00	Parts:	0.78	Total:	30.78
Workorder: 170 Problem: P.M	9478 I. service.	Meter:	77240		lr	n Date:	09/28/2017	Closed:	10/17/2017
Problem: P.M		Meter:	77240		Ir Parts List		09/28/2017	Closed:	10/17/2017 <b>Qt</b>
<b>Problem:</b> P.M - P.m. service.	I. service.			02272 ,02			09/28/2017	Closed:	
Problem: P.M - P.m. service Engine light on.c sensor lean.check	I. service. omputer dia circuit for sl	agnoise co	ode P2098,p ound and	•	Parts List	ne Oil	09/28/2017	Closed:	Qt
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new	I. service. omputer dia circuit for sl	agnoise co	ode P2098,p ound and	•	Parts List 5w20 Engi	ne Oil Oil Filter	09/28/2017	Closed:	<b>Qt</b> 7.0
Problem: P.M - P.m. service Engine light on.c sensor lean.check voltage,ok.r&i new test Inspect and repla	I. service.  omputer dia circuit for sl O2 sensor ace two wor	agnoise co hort to gro .clear coo	ode P2098,p ound and des and rete	st .road	Parts List 5w20 Engil Napagold (	ne Oil Oil Filter Blade		Closed:	<b>Qt</b> 7.0 1.0
Problem: P.M - P.m. service Engine light on.c sensor lean.check voltage,ok.r&i new test Inspect and repla	I. service.  omputer dia circuit for sl O2 sensor ace two wor	agnoise co hort to gro .clear coo	ode P2098,p ound and des and rete	st .road	Parts List 5w20 Engil Napagold 0 20" Wiper	ne Oil Oil Filter Blade uid Conc	entr	Closed:	<b>Qt</b> 7.0 1.0 2.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and repla speed balance all f - Inspect and repla	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra	agnoise con hort to ground to continue on tires on an introfill al	ode P2098,p ound and des and rete front .rotate I . sure and rep	st .road	Parts List 5w20 Engin Napagold ( 20" Wiper I Washer Flu	ne Oil Oil Filter Blade uid Conc X Refurb	entr ished	Closed:	Qt 7.0 1.0 2.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and repla speed balance all f - Inspect and repla rear rotors.service	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engil Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degil O2/ Senso	ne Oil Oil Filter Blade uid Conc X Refurb reaser 1	entr ished	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new rest Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engin Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1	ne Oil Oil Filter Blade uid Conc X Refurb reaser 1	entr ished	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new rest Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engin Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad	ne Oil Oil Filter Blade uid Conc X Refurb reaser 1 r 6	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new rest Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engin Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I	ne Oil Oil Filter Blade uid Conc X Refurb reaser 1 r 6	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new rest Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold ( 20" Wiper I Washer Flu Used Fire ( Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 r 6 Brake Cli	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check roltage,ok.r&i new est Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Rote	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 or 6 Brake Cli	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0 1.0 2.0 2.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold ( 20" Wiper I Washer Flo Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Roto Wheel Nut	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 or 6 Brake Cli	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 2.0 1.0 1.0 2.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and repla speed balance all f - Inspect and repla rear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Rote Wheel Nut Sensor	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 or 6 Brake Clo	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 2.0 1.0 1.0 2.0 1.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and replaspeed balance all for any replacement of the rear rotors.service	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold (20" Wiper I Washer Flo Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Roto Wheel Nut Sensor Caliper Ha	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 r 6 Brake Clo	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0 2.0 1.0 2.0 2.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and replayspeed balance all for linspect and replayers rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor ace two wor our wheels. ace rear bra rear caliper	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both	Parts List 5w20 Engir Napagold (20" Wiper I Washer Flu Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Rote Wheel Nut Sensor Caliper Ha Shop Supp	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 6 Brake Clo or	entr ished Gal	Closed:	Qt 7.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0 2.0 1.0 2.0 1.0
Problem: P.M - P.m. service Engine light on.c. sensor lean.check voltage,ok.r&i new test Inspect and replaspeed balance all f - Inspect and replarear rotors.service stuck.replace pads	I. service.  omputer dia circuit for sl O2 sensor  ace two wor our wheels. ace rear bra rear caliper and bleed	agnoise con hort to ground to clear coordinates on the contraction of	ode P2098,p ound and des and rete front .rotate I . sure and rep nd bushings	st .road e and high place both st.	Parts List 5w20 Engir Napagold (20" Wiper I Washer Flo Used Fire 2 Big G Degr O2/ Senso Lt245 75r1 Disc Pad Non-chlor I brake fluid Brake Roto Wheel Nut Sensor Caliper Ha	ne Oil Oil Filter Blade uid Conco X Refurb reaser 1 r 6 Brake Clo or rdware olies sal Fee	entr ished Gal		Qt 7.0 1.0 2.0 1.0 1.0 1.0 1.0 1.0 2.0 1.0 1.0 1.0 2.0 1.0 2.0 1.0 2.0 2.0

Workorder: Problem:	1803143 PM Service	Meter:	81786			In Date:	03/26/2018	Closed:	04/04/2018
- P.m. service	ı <u>.</u>				Parts Lis	st			Qty
- Computer di	agnoise engine	light ,cod	e P0442 and F	2272.	5w20 En	gine Oil			7.00
	test .r&r defect				Napagolo	d Oil Filter			1.00
	o oxygen sens on . Clear code			touna	22" Wiper Blade				2.00
- Rotate and I	fill all.	Washer Fluid Concentr				1.00			
- Shop Suppli					Purge Va	alve			1.00
Chop Gappii					Shop Su	pplies			1.00
	Hour	s 7.80		Labor:	468.00	Parts:	96.01	Total:	564.01
	1803660 ABS light on.	Meter:	81789		Dania Lia	In Date:	04/06/2018	Closed:	04/10/2018
	agnoise Abs lic &i defective Ho				Parts Lis	Qty			
	pinpoint test .r&i defective Hcu and Abs module .reprogram module and clear codes. Test drive.								•
module and ci			modulo mopre	Jyram	brake flui				2.00
- Shop Suppli	ear codes. Tes		medale nepre	ogram	Non-chlo	r Brake Clr			2.00 1.00
	ear codes. Tes		modulo nopre	ogram	Non-chlo Abs Hydi	r Brake Clr raulic Modu			2.00 1.00 1.00
	ear codes. Tes		medale nepr	ogram	Non-chlo Abs Hydi Abs Con	or Brake Clr raulic Modu trol			2.00 1.00 1.00 1.00
	ear codes. Tes es	t drive.	modale mopile		Non-chlo Abs Hydr Abs Con Shop Su	or Brake Clr raulic Modu trol pplies	ıle		2.00 1.00 1.00 1.00
	ear codes. Tes es		medale mep.		Non-chlo Abs Hydi Abs Con	or Brake Clr raulic Modu trol pplies		Total:	2.00 1.00 1.00 1.00
- Shop Suppli	ear codes. Tes es	t drive. s 3.80  Meter:	86496		Non-chlo Abs Hydr Abs Con Shop Su 228.00	or Brake Clr raulic Modu trol pplies	ıle	Total:	2.00 1.00 1.00 1.00
- Shop Suppli Workorder: Problem:	ear codes. Tes es Hour : 1809187	s 3.80  Meter: es	86496	Labor:	Non-chlo Abs Hydr Abs Con Shop Su 228.00	or Brake Clr raulic Modu trol pplies Parts:	1,289.80		2.00 1.00 1.00 1.00 1.00 1,517.80

Workorder: 1809189 Meter: 86707 Problem: P.M. service and towed in for no brakes.	In Date: 09/06/2018 Clos	sed: 09/24/2018
- P.m. service.	Parts List	Qty
- Replace two worn tires . Rotate and high speed balance all	Napagold Oil Filter	1.00
four tires. Nitrofill all .	5w20 Engine Oil	7.00
- Inspect brakes . Replace front and rear rotors and brake pads . Replace rear calipers and service front calipers . Flush	20" Wiper Blade	2.00
and bleed brake system . Road test.	Washer Fluid Concentr	1.00
- Test and replace high mounted brake light bulb.	Lt245 75r16	2.00
- Test and replace radio assembly . Retest.	Brake Rotor	2.00
- Shop Supplies	Disc Pad	1.00
	Brake Rotor Hub	2.00
	Disc Pad	1.00
	Non-chlor Brake Clnr	1.00
	B Fluid Dot 3-32oz	2.00
	Used Fire X Refurbished	1.00
	Napa Oil Seal	2.00
	Retainer	1.00
	Brake Caliper	1.00
	Brake Caliper	1.00
	Boxed Capsules	1.00
	Radio Assy	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 15.30 Labor:	918.00 Parts: 1,368.81	Total: 2,286.81
Workorder: 1902781 Meter: 93000 Problem: Transition Prep Charge	In Date: 03/13/2019 Clos	sed: 03/13/2019
- Transition Prep Charge		
Hours 2.00 Labor:	134.00 Parts: 0.00	Total: 134.00