

**Palm Beach County Fleet Management
Asset Maintenance History**

10179138 2009 FORD E350 Van, 1 Ton, Cargo

Workorder: 940249 **Meter:** 332 **In Date:** 07/02/2009 **Closed:** 07/02/2009
Problem: Pre Delivery Inspection

- Pre Delivery Inspection

Hours 2.00 Labor: 120.00 Parts: 0.00 Total: 120.00
:

Workorder: 946856 **Meter:** 2542 **In Date:** 12/09/2009 **Closed:** 12/22/2009
Problem: P.M service

- P.m service.

- Test & replace dome light bulb.

- Shop Supplies

Parts List Qty

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

31-20 Wiper Blades 20" Blade 2.00

Hours 4.50 Labor: 270.00 Parts: 27.71 Total: 297.71
:

Workorder: 1006023 **Meter:** 2750 **In Date:** 06/08/2010 **Closed:** 06/14/2010
Problem: P.M. Service.

- Perform pm service.

- Shop Supplies

Parts List Qty

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

5w20 Engine Oil 7.00

Wd40 Spray Lube Stock# 405540002 1.00

31-20 Wiper Blades 20" Blade 2.00

Used Firex Refurbed Fire Extingshers 1.00

Hours 4.00 Labor: 240.00 Parts: 46.39 Total: 286.39
:

Workorder: 1100799 **Meter:** 6761 **In Date:** 01/20/2011 **Closed:** 01/28/2011
Problem: Pm service,also see notes passenger door lock and ac concern.

- P.m. Service.

- R&r passenger door panel and replace broken retainer clip on latch rod.

- Rotate and balance all tires.

- Shop Supplies

Parts List Qty

Shop Supplies 1.00

1372 Oil Filter Frm Ph2 Wix 51372 1.00

Ca8039 Air Filter Lbf Af1615 Wix 46418 1.00

5w20 Engine Oil 7.00

Retainer 1.00

Used Firex Refurbed Fire Extingshers 1.00

31-20 Wiper Blades 20" Blade 2.00

Hours 6.00 Labor: 360.00 Parts: 51.21 Total: 411.21
:

Workorder: 1101005 **Meter:** 6761 **In Date:** 01/26/2011 **Closed:** 01/27/2011
Problem: reflash canceiver spot 221

- Reflash Canceiver and Reprogram

- Shop Supplies

Parts List Qty

Shop Supplies 1.00

Hours 1.00 Labor: 60.00 Parts: 2.00 Total: 62.00
:

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1107440 **Meter:** 11529 **In Date:** 07/15/2011 **Closed:** 08/08/2011

Problem: Pm service and blower second speed inop.

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	Shop Supplies	1.00
- Transport vehicle to dealer for a/c control warranty.	1372 Oil Filter Frm Ph2 Wix 51372	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 7.00	Labor: 420.00	Parts: 31.33
:		Total: 451.33

Workorder: 1201036 **Meter:** 15657 **In Date:** 01/31/2012 **Closed:** 02/14/2012

Problem: Pm service

- Perform pm service.	Parts List	Qty
- Rotate and balance all four tires.	Shop Supplies	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	Ca8039 Air Filter Lbf Af1615 Wix 46418	1.00
	5w20 Engine Oil	7.00
	Used Firex Refurbed Fire Extingshers	1.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.00	Labor: 300.00	Parts: 57.68
:		Total: 357.68

Workorder: 1207206 **Meter:** 20020 **In Date:** 08/01/2012 **Closed:** 08/09/2012

Problem: P.M. service and repair damage to front bumper.

- Perform pm service.	Parts List	Qty
- Rotate and balance all four tires.	Shop Supplies	1.00
- Shop Supplies	1372 Oil Filter Frm Ph2 Wix 51372	1.00
	5w20 Engine Oil	7.00
	31-20 Wiper Blades 20" Blade	2.00
Hours 5.00	Labor: 300.00	Parts: 32.06
:		Total: 332.06

Workorder: 1208089 **Meter:** 20020 **In Date:** 08/10/2012 **Closed:** 08/27/2012

Problem: damage to frt bumper

- damage to frt bumper			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1300016 **Meter:** 23683 **In Date:** 01/02/2013 **Closed:** 01/02/2013

Problem: Tires

- Tire Service 6401 Indiantown Rd - Tires			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1301116 **Meter:** 24543 **In Date:** 01/31/2013 **Closed:** 02/20/2013
Problem: Pm service.Flat tire and tire pressure warning light on dash.

- P.m. Service.	Parts List	Qty
- Replace and balance four new tires.	5w20 Engine Oil	7.00
- Install camber/caster bushings on both sides.perform complete alignment and test drive.	Filter	1.00
- Shop Supplies	Ca8039 Air Filter Lbf	1.00
	Used Firex Refurbed F	1.00
	179747492 Lt245-75r16	4.00
	Tr416 Valve Stem	4.00
	Caster-camber Bushing	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 8.25	Labor: 495.00	Parts: 999.07
:		Total: 1,494.07

Workorder: 1308230 **Meter:** 29210 **In Date:** 08/15/2013 **Closed:** 09/05/2013
Problem: Pm service.Check blower motor speeds inop and low tire pressure warning light on.

- Perform pm service.	Parts List	Qty
- Test and replace failed blower resistor with new.	5w20 Engine Oil	7.00
- Test starting and charging system.battery failed loadtest after recharge.replace failed battery with new.	Napagold Oil Filter	1.00
- Rotate and balance all four tires.	31-20 Wiper Blades 20	2.00
- Shop Supplies	Blower Motor Resistor	1.00
	Battery	1.00
	Napagold Oil Filter	1.00
	Shop Supplies	1.00
Hours 7.00	Labor: 420.00	Parts: 177.73
:		Total: 597.73

Workorder: 1401341 **Meter:** 34136 **In Date:** 02/10/2014 **Closed:** 02/25/2014
Problem: Pm service

- P.m. Service.	Parts List	Qty
- Rotate and balance all tires.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	Wiper Blade	2.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 32.38
:		Total: 332.38

Workorder: 1401764 **Meter:** 34204 **In Date:** 02/24/2014 **Closed:** 02/28/2014
Problem: Right rear tire flat.

- Repair flat right rear tire.nitrogen fill and balance same.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1407885 **Meter:** 38554 **In Date:** 08/11/2014 **Closed:** 08/22/2014
Problem: Pm service and ac air flow moves from vent to defrost on acceleration

- Pm service.	Parts List	Qty
- Diagnose for dome light on all the time.test and replace back door pin switch.	A/c Valve	1.00
- Diagnose for ac air flow changes to defrost on acceleration.replace and relocate vacume canister,check valve and hose.	Vacuum Reservoir	1.00
- Rotate and balance all four tires.	Napagold Oil Filter	1.00
- Shop Supplies	5w20 Engine Oil	7.00
	Napagold Air Filter	1.00
	Used Fire X Refurbished	1.00
	Switch Asy	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 101.81
:		Total: 641.81

Workorder: 1412455 **Meter:** 40953 **In Date:** 12/12/2014 **Closed:** 12/16/2014
Problem: Right rear tire flat.

- Repair flat and balance right rear tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

Workorder: 1412920 **Meter:** 41535 **In Date:** 12/31/2014 **Closed:** 01/06/2015
Problem: Left tail lamp inop

- Test and replace defective left brake lamp bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75
:		Total: 30.75

Workorder: 1501674 **Meter:** 43063 **In Date:** 02/17/2015 **Closed:** 02/27/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace and balance all four tires.	5w20 Engine Oil	7.00
- Flush and refill transmission fluid.	Napagold Oil Filter	1.00
- Complete front end alignment.	Wiper Blade	2.00
- Shop Supplies	Washer Fluid Concentr	1.00
	Lt245 75r16	4.00
	Tr416 Valve Stem	4.00
	Syn-atf Trans Fluid S	12.00
	Shop Supplies	1.00
	Tire Disposal Fee	4.00
Hours 10.00	Labor: 600.00	Parts: 1,021.65
:		Total: 1,621.65

Workorder: 1505881 **Meter:** 46593 **In Date:** 06/12/2015 **Closed:** 06/16/2015
Problem: Right rear tire flat.

- Repair and balance right rear tire.	Parts List	Qty
- Shop Supplies	Shop Supplies	1.00
Hours 1.00	Labor: 60.00	Parts: 2.00
:		Total: 62.00

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1508231 **Meter:** 48182 **In Date:** 08/17/2015 **Closed:** 08/31/2015
Problem: Pm service.

- Pm service.	Parts List	Qty
- Replace front brake pads and resurface front rotors.clean and repack front wheel bearings.lube calipers.flush and bleed brake system.test drive.	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
	Wiper Blade	2.00
- Rotate and balance all four tires.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Bulb	2.00
	Napa Oil Seal	2.00
	B Fluid Dot 3-32oz	1.00
	Brake Cleaner	1.00
	Kit Brak	1.00
	Shop Supplies	1.00
Hours 9.00	Labor: 540.00	Parts: 169.85
:		Total: 709.85

Workorder: 1511739 **Meter:** 49926 **In Date:** 11/17/2015 **Closed:** 11/23/2015
Problem: Right tail lamp inop.

- Test and replace defective right brake lamp bulb.	Parts List	Qty
	Bulb	1.00
Hours 0.50	Labor: 30.00	Parts: 0.75
:		Total: 30.75

Workorder: 1601810 **Meter:** 52805 **In Date:** 02/22/2016 **Closed:** 03/07/2016
Problem: P.M. service and left front door will not open from outside.

- Pm service.	Parts List	Qty
- Check battery and charging system.battery failed loadtest after recharge.replace defective battery.	5w20 Engine Oil	7.00
	Napagold Oil Filter	1.00
- Perform engine coolant flush and refill.	20" Wiper Blade	2.00
- Resurface both rear brake rotors.replace rear brake pads and calipers.flush and bleed brake system.test drive.	Napagold Air Filter	1.00
	Battery	1.00
- Check and replace defective left front door lock assembly by removing door panel	Peak Global	2.00
	B Fluid Dot 3-32oz	1.00
- Repair left front tire.rotate and balance all four.	Semi Loaded Caliper	1.00
- Shop Supplies	Semi Losded Caliper	1.00
	Brake Pads Rear	1.00
	Drain Plug	1.00
	Latch Assy	1.00
	Shop Supplies	1.00
Hours 14.50	Labor: 870.00	Parts: 554.90
:		Total: 1,424.90

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1609508 **Meter:** 57413 **In Date:** 09/13/2016 **Closed:** 09/27/2016

Problem: P.M. service and check engine light and tire pressure light on.

- P.m. Service.	Parts List	Qty
- Diagnose check engine light/.p2270.replace bank 1 sensor 1 oxygen sensor.clear codes.	5w20 Engine Oil	7.00
- Replace center brake lamp bulbs.	Napagold Oil Filter	1.00
- Inspect and service rear differential.	Washer Fluid Concentr	1.00
- Replace two tires,rotate and balance all four.	20" Wiper Blade	2.00
- Shop Supplies	Rpl Bulb	1.00
	75w140 Ford Axle Lube	3.00
	Friction Modifier	2.00
	Ptex Ultra Grey 3oz	1.00
	744395900 245-75r16	2.00
	O2 Sensor	1.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 10.00	Labor: 600.00	Parts: 581.90
:		Total: 1,181.90

Workorder: 1610353 **Meter:** 57861 **In Date:** 10/03/2016 **Closed:** 10/14/2016

Problem: Check engine light and running rough.

- Diagnose check engine light.p0305,p0316.replace spark plugs nad #5 coil.clear codes.	Parts List	Qty
- Sservice and clean throttle body and induction system.flush injectors.	Ford Ignition Coil	1.00
- Shop Supplies	Spark Plugs	8.00
	Injector Cleaner	1.00
	Intake Cleaner Kit	1.00
	Clean-r-carb 20oz	1.00
	Shop Supplies	1.00
Hours 6.00	Labor: 360.00	Parts: 186.04
:		Total: 546.04

Workorder: 1702346 **Meter:** 58882 **In Date:** 03/08/2017 **Closed:** 03/27/2017

Problem: P.M. service and dead battery.

- P.m. Service.	Parts List	Qty
- Test battery and charging system.replace bad battery.	5w20 Engine Oil	7.00
- Replace alternator,belt tensioner and serpentine belt.	Napagold Oil Filter	1.00
- Replace center brake lamp.	20" Wiper Blade	2.00
- Rotate and balance tires.	Washer Fluid Concentr	1.00
- Shop Supplies	Used Fire X Refurbished Battery	1.00
	Alternator Motorcraft	1.00
	Lamp Assembly	1.00
	Cover	1.00
	V Belt	1.00
	Shop Supplies	1.00
Hours 8.50	Labor: 510.00	Parts: 657.89
:		Total: 1,167.89

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1708042 **Meter:** 62257 **In Date:** 08/16/2017 **Closed:** 08/24/2017

Problem: P.M. service and rear cargo door inop and install cone rack on front.

- P.m. service.	Parts List	Qty
- Replace failed rear cargo door latch and install front safety cone rack.	Door Remote	1.00
- Repair right front tire .rotate and high speed balance all four tires.	5w20 Engine Oil	7.00
- Shop Supplies	Napagold Oil Filter	1.00
	20" Wiper Blade	2.00
	Used Fire X Refurbished	1.00
	Cone Holder	1.00
	Shop Supplies	1.00
Hours 8.00	Labor: 480.00	Parts: 169.72
:		Total: 649.72

Workorder: 1712364 **Meter:** 65053 **In Date:** 12/15/2017 **Closed:** 12/30/2017

Problem: Check engine light and noise in rear of vehicle and detail.

- Diagnose check engine light with scan tool code P0150 and P0130 Perform pinpoint test on circuits and replace both failed oxygen sensors with new .reprogram Pcm to latest calibration and clear codes.	Parts List	Qty
- Load test battery and recharge due to low voltage.replace failed battery due to bad cell with new.	Sensor	2.00
- Test drive and inspect rear differential fluid.could not duplicate rear end noise at this time.	Battery	1.00
- Shop Supplies	O2/ Sensor	2.00
	Shop Supplies	1.00
Hours 5.00	Labor: 300.00	Parts: 518.96
:		Total: 818.96

Workorder: 1712773 **Meter:** 64930 **In Date:** 12/29/2017 **Closed:** 12/29/2017

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

Workorder: 1800365 **Meter:** 65367 **In Date:** 01/10/2018 **Closed:** 01/16/2018

Problem: Parts credit

- Over charge credit.			
Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
:			

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1803133 **Meter:** 66933 **In Date:** 03/26/2018 **Closed:** 04/04/2018
Problem: PM Service, ABS light-grinding noise, Detail.

- P.m. service.	Parts List	Qty
- Service rear differential. Drain and reseal cover and refill.	5w20 Engine Oil	7.00
- Replace two tires and rotate and balance all four tires	Napagold Oil Filter	1.00
.nitrogen fill tires.	Washer Fluid Concentr	1.00
- Computer diagnose Abs light,code C1693.replace Hcu and	20" Wiper Blade	2.00
Abs module .flush and bleed brake system with scan	75w140 Ford Axle Lube	1.00
tool.clear codes and retest.	Friction Modifier	2.00
- Shop Supplies	Gear Oil Rtv	1.00
	Non-chlor Brake Clnr	4.00
	744395900 245-75r16	2.00
	brake fluid	4.00
	Abs Control	1.00
	Abs Hydraulic Module	1.00
	Non-chlor Brake Clnr	2.00
	brake fluid	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 11.00	Labor: 660.00	Parts: 1,811.51
:		Total: 2,471.51

Workorder: 1803459 **Meter:** 66755 **In Date:** 04/02/2018 **Closed:** 04/02/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1806322 **Meter:** 69258 **In Date:** 06/20/2018 **Closed:** 06/27/2018
Problem: Rear inside door will not open.

- Replace and adjust left rear cargo door latches .retest.	Parts List	Qty
- Shop Supplies	Door Latch W/cable	1.00
	Door Handle W/cable	1.00
	Shop Supplies	1.00
Hours 1.25	Labor: 75.00	Parts: 170.54
:		Total: 245.54

**Palm Beach County Fleet Management
Asset Maintenance History**

Workorder: 1809438 **Meter:** 71650 **In Date:** 09/13/2018 **Closed:** 09/27/2018
Problem: P.M. service and detail.

- P.m. service.	Parts List	Qty
- Replace two tires . Rotate and high speed balance all four tires.	Napagold Oil Filter	1.00
	5w20 Engine Oil	7.00
- Perform front end alignment and road test.	20" Wiper Blade	2.00
- Shop Supplies	Used Fire X Refurbished	1.00
	Mac Wite Lithium Gres	1.00
	Tr416 Valve Stem	2.00
	744395900 245-75r16	2.00
	Cover	2.00
	Shop Supplies	1.00
	Tire Disposal Fee	2.00
Hours 8.50	Labor: 510.00	Parts: 595.17
:		Total: 1,105.17

Workorder: 1809919 **Meter:** 71459 **In Date:** 09/25/2018 **Closed:** 09/25/2018
Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

- 1 - Detail Vehicle Wash Ticket(s) Issued	Hours 0.00	Labor: 0.00	Parts: 0.00	Total: 0.00
	:			

Workorder: 1902099 **Meter:** 75968 **In Date:** 02/26/2019 **Closed:** 02/26/2019
Problem: Transition Prep Charge

- Transition Prep Charge	Hours 2.00	Labor: 134.00	Parts: 0.00	Total: 134.00
	:			