

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 745790

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0		Labor	Parts	
In Date: 10/17/2007	Close Date: 10/17/2007	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
Parts Charge:	0.00	Labor Charge:	120.00	

Workorder: 746828

Problem: INSTALL TOOL BOX

Meter Reading: 303		Labor	Parts	
In Date: 11/06/2007	Close Date: 11/07/2007	Hours	Description	Quantity
- Install Toolbox In Back Of Bed.		1.00	TBSD72LP TOOL BOX (UNITED WELDING)	1.00
- Shop Supplies			SHOP SUPPLIES	1.00
Parts Charge:	429.20	Labor Charge:	60.00	

Workorder: 838238

Problem: P.M.SERVICE

Meter Reading: 4221		Labor	Parts	
In Date: 05/08/2008	Close Date: 05/15/2008	Hours	Description	Quantity
- Pm Service		2.75	SHOP SUPPLIES	1.00
- Shop Supplies			5W20 ENGINE OIL	7.00
			OIL FILTER	1.00
Parts Charge:	38.85	Labor Charge:	165.00	

Workorder: 841435

Problem: INSTALL AUX FUEL TANK

Meter Reading: 5582		Labor	Parts	
In Date: 07/16/2008	Close Date: 07/18/2008	Hours	Description	Quantity
- Install Aux Fuel Tank & Wire Power For Pump; Mount Toolbox; Fill Tank & Test For Leaks; Test Drive; Replace Fuel Nozzle		14.00	09997 BRAKE CLEAN	1.00
			SHOP SUPPLIES	1.00
			504303-05 REBUILT DON'T REORDER	1.00
- Chip, Scrape & Clean Rust From Fuel Tank; Apply Rust Converter				
- Fabricate Extra Long Bolts For Mounting Toolbox				
- Shop Supplies				
Parts Charge:	77.84	Labor Charge:	75.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 844328

Problem: INSTALL LADDER RACK.

Meter Reading: 6707		Labor		Parts	
In Date: 09/17/2008	Close Date: 09/24/2008	Hours	Description		Quantity
- Fabricate & Install Ladder Rack.Removed&Reinstall		7.00	SHOP SUPPLIES		1.00
Auxiliary Fuel Tank & Toolbox To Access And Install			LADDER RACK		1.00
Ladder Rack.					
- Shop Supplies					
Parts Charge: 334.40		Labor Charge: 420.00			

Workorder: 848108

Problem: PM SERVICE

Meter Reading: 8623		Labor		Parts	
In Date: 12/11/2008	Close Date: 12/19/2008	Hours	Description		Quantity
- Pm Service		5.25	1066 WHITE LITHIUM (CRC 05037)		1.00
- Service Fuel Tank & Pump; R&R Fuel Filter; Ck & Secure			CA10262 AIR FILTER MTC FA1883 WIX 49883		-1.00
Boltson Box & Tank; Service & Adjust Ladder Rack			NB-19 WIPER BLADES 19" ANCO 31-19		2.00
- Shop Supplies			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
			G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
			5W20 ENGINE OIL		7.00
			SHOP SUPPLIES		1.00
Parts Charge: 91.96		Labor Charge: 150.00			

Workorder: 940762

Problem: P.M.SERVICE

Meter Reading: 12918		Labor		Parts	
In Date: 07/15/2009	Close Date: 07/20/2009	Hours	Description		Quantity
- P.M.Service		5.00	SHOP SUPPLIES		1.00
- Service F/Tank&Pump. R/R Fuel Filter,Repair Handle			1372 OIL FILTER FRM PH2 WIX 51372		1.00
Sticking			5W20 ENGINE OIL		7.00
- Install No Smoking Decals			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
- Shop Supplies					
Parts Charge: 42.29		Labor Charge: 300.00			

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 943220

Problem: Accident

Meter Reading: 14090

In Date: 09/14/2009

Close Date: 09/14/2009

Labor

Hours

Description

Parts

Quantity

- From: 7550 Glen Devon Lane (Glen Eagles Point) To:
Accident Line

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 114.00

Workorder: 943843

Problem: damage to lft rear fender, hitch, bumper & possible frame

Meter Reading: 14090

In Date: 09/16/2009

Close Date: 09/29/2009

Labor

Hours

Description

Parts

Quantity

- Damage To Lft Rear Fender, Hitch, Bumper & Possible
Frame

Parts Charge: 0.00

Labor Charge: 0.00

Commercial Charge: 2,187.00

Workorder: 1000319

Problem: P.M.SERVICE

Meter Reading: 16611

In Date: 01/07/2010

Close Date: 01/08/2010

Labor

Hours

Description

Parts

Quantity

- P. M. **6.75** 1372 OIL FILTER FRM PH2 WIX 51372 1.00
- Verify Vehicle Needs Four Tires. Mount, Balance, Add 75 G10166 FUEL FILTER MTC FG1083 WIX 33243 1.00
- Pounds Of N2. 5W20 ENGINE OIL 8.00
- Service Fuel System, R/R Fuel Filter. NB-19 WIPER BLADES 19" ANCO 31-19 2.00
- Service Lube & Adjust Ladder Rack. USED FIREX REFURBED FIRE EXTINGUISHERS 1.00
- Shop Supplies 179636492 LT245/75R17 WRANGLER SR-A E 4.00
- TIRE DISPOSAL FEE 4.00
- 1259 HYDR FILTER LBF FRM P1653A WIX 51259 1.00
- 1066 WHITE LITHIUM (CRC 05037) 1.00
- SHOP SUPPLIES 1.00

Parts Charge: 839.17

Labor Charge: 405.00

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1000692

Problem: WONT START

Meter Reading: 16811

In Date: 01/19/2010

Close Date: 01/26/2010

Labor

Hours

Description

Parts

Quantity

- | | | | |
|---|-------------|---------------|------|
| - Transport & Pick Up Vehicle At Dealer For Battery Warranty. | 2.00 | SHOP SUPPLIES | 1.00 |
| - Shop Supplies | | | |

Parts Charge:	2.00	Labor Charge:	60.00
----------------------	------	----------------------	-------

Workorder: 1006144

Problem: P.M.SERVICE/SEE NOTE

Meter Reading: 20018

In Date: 06/09/2010

Close Date: 06/22/2010

Labor

Hours

Description

Parts

Quantity

- | | | | |
|--|-------------|---|------|
| - P. M. Service. | 7.25 | CA10262 AIR FILTER MTC FA1883 WIX 49883 | 1.00 |
| - Replace 3Rd Brake Light Bulb. Replace Right Tag Light Assembly (Damaged). | | 1259 HYDR FILTER LBF FRM P1653A WIX 51259 | 1.00 |
| - Service Aux Fuel Tank. | | SHOP SUPPLIES | 1.00 |
| - C/S: Trailer Lights Not Working. Perform Pinpoint Test, Found Corroded Wires. Repair Wires & Replace Trailer Female Connector. | | TAG LIGHT ASSY | 1.00 |
| - Install "How'S My Driving" Decal. | | 5404 FEMALE CONNECTOR | 1.00 |
| - Shop Supplies | | G10166 FUEL FILTER MTC FG1083 WIX 33243 | 1.00 |
| | | 1372 OIL FILTER FRM PH2 WIX 51372 | 1.00 |
| | | 5W20 ENGINE OIL | 8.00 |

Parts Charge:	88.72	Labor Charge:	435.00
----------------------	-------	----------------------	--------

Workorder: 1013506

Problem: LOW TIRE PRESSURE LIGHT ON

Meter Reading: 23912

In Date: 12/08/2010

Close Date: 12/14/2010

Labor

Hours

Description

Parts

Quantity

- | | | | |
|--|-------------|--|--|
| - C/C: Tpms On. Check All Tires For Damage, Correct Nitrogen Levels. | 0.50 | | |
|--|-------------|--|--|

Parts Charge:	0.00	Labor Charge:	30.00
----------------------	------	----------------------	-------

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1013745

Problem: P.M.SERVICE

Meter Reading: 24042		Labor		Parts	
In Date: 12/14/2010	Close Date: 12/22/2010	Hours	Description		Quantity
-	P. M. Service.	5.25	5W20 ENGINE OIL		7.00
-	Service Aux Fuel Tank.		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Install "How'S My Driving" Decal.		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Service Ladder Rack.		5W20 ENGINE OIL		1.00
-	R&R Lr Reverse Light Bulb.		NB-19 WIPER BLADES 19" ANCO 31-19		2.00
-	Shop Supplies		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		70.02	Labor Charge:	315.00	

Workorder: 1106108

Problem: P. M., Tool box lock broken & driver's seat is ripped

Meter Reading: 25904		Labor		Parts	
In Date: 06/09/2011	Close Date: 06/30/2011	Hours	Description		Quantity
-	P. M. Service.	7.75	5W20 ENGINE OIL		8.00
-	Service Aux Fuel Tank.		CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Commercial Repair Only.		1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
-	Service Ladder Rack.		G10166 FUEL FILTER MTC FG1083 WIX 33243		1.00
-	Remove Seat & Send Out For Repair.		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Transport & Pick Up Seat At Central Auto Trim For		1372 OIL FILTER FRM PH2 WIX 51372		1.00
-	Repair.		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		71.71	Labor Charge:	465.00	Commercial Charge: 207.17

Workorder: 1108842

Problem: Passenger brake light out

Meter Reading: 26598		Labor		Parts	
In Date: 08/22/2011	Close Date: 08/26/2011	Hours	Description		Quantity
-	R&R Bulb.	0.50	3157 TAIL LIGHT BULBS		1.00
Parts Charge:		0.83	Labor Charge:	30.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1110083

Problem: Driver's side brake light out

Meter Reading: 26961

Labor

Parts

In Date: 09/21/2011

Close Date: 09/26/2011

Hours

Description

Quantity

- R&R Bulb.	0.50	3157 TAIL LIGHT BULBS	1.00
Parts Charge:	0.83	Labor Charge:	30.00

Workorder: 1200191

Problem: Air pressure gauge on

Meter Reading: 28808

Labor

Parts

In Date: 01/06/2012

Close Date: 01/12/2012

Hours

Description

Quantity

- C/C: Air Light On. Correct All N2 Levels. Inspect Tires For Damage. Clear Tpms Light.	0.50		
Parts Charge:	0.00	Labor Charge:	30.00

Workorder: 1200412

Problem: P.M. Service, & A/C control only works on level 3

Meter Reading: 28901

Labor

Parts

In Date: 01/12/2012

Close Date: 01/27/2012

Hours

Description

Quantity

- P. M. Service.	6.75	5W20 ENGINE OIL	8.00
- Service Aux Fuel Tank.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- C/S: A/C Only Works On High Speed. Perform Pinpoint		SHOP SUPPLIES	1.00
Test & Found Bad Blower Resistor. Replace A/C Blower		1259 HYDR FILTER LBF FRM P1653A WIX 51259	1.00
Motor Resistor.		NB-19 WIPER BLADES 19" ANCO 31-19	2.00
- Replace Right Rear Reverse Light Bulb.		A/C BLOWER RESISTER	1.00
- Install "How'S My Driving" Decal.			
- Shop Supplies			
Parts Charge:	72.07	Labor Charge:	405.00

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1201590

Problem: CHECK ENGINE LIGHT ON .

Meter Reading: 29310	Labor	Parts		
In Date: 02/16/2012	Hours	Description	Quantity	
<hr/>				
- C/S: Ck Engine Light Is On. Verify, Scan & Found Code # P0171, P0301, P0316, Perform Pinpoint Test & Found Water In Spark Plug Hole. Remove, Clean Plugs & Wires.	5.50	SHOP SUPPLIES	1.00	
- Clear Codes & Test Drive 64 Miles.				
- Shop Supplies				
Parts Charge:	2.00	Labor Charge:	330.00	

Workorder: 1206038

Problem: driver side brake light is out

Meter Reading: 32166	Labor	Parts		
In Date: 06/27/2012	Hours	Description	Quantity	
<hr/>				
- Rr Tail Light Bulb	0.50	3157 TAIL LIGHT BULBS	1.00	
Parts Charge:	0.65	Labor Charge:	30.00	

Workorder: 1206096

Problem: ck engine light come on

Meter Reading: 32187	Labor	Parts		
In Date: 06/28/2012	Hours	Description	Quantity	
<hr/>				
- Clean Battery Tray Terminals Ck Charging System And Repalce Bad Battery Aces Code Hcoop Dtc Code 841 54H	2.75	GROUP 65 BATTERY (MTC BXT-65-850)	1.00	
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00	
		SHOP SUPPLIES	1.00	
- Ck Engine Light In On Scan For Codes Po191 Perform Pinpoint Test And Was Unable To Duplicate Problem At This Time Replace Fuel Filter Clear Codes And Test Drive				
- Shop Supplies				
Parts Charge:	134.93	Labor Charge:	165.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1206424

Problem: P.M.SERVICE

Meter Reading: 32196		Labor		Parts	
In Date: 07/10/2012	Close Date: 07/11/2012	Hours	Description		Quantity
- Pm		5.50	5W20 ENGINE OIL		8.00
- Service Aux. Fuel Tank			NB-19 WIPER BLADES 19" ANCO 31-19		2.00
- Repalce Both Rear Tires And Rotate To The Front			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Install Hows My Driving Decal No Smoking And No Idling			1259 HYDR FILTER LBF FRM P1653A WIX 51259		1.00
Decal			179636492 LT245/75R17 WRANGLER SR-A E		2.00
- Shop Supplies			TIRE DISPOSAL FEE		2.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 479.73		Labor Charge: 330.00			

Workorder: 1210101

Problem: driver side turn signal is burned out

Meter Reading: 35504		Labor		Parts	
In Date: 10/22/2012	Close Date: 10/29/2012	Hours	Description		Quantity
- Rr Bulb		0.50	3157 TAIL LIGHT BULBS		1.00
Parts Charge: 1.64		Labor Charge: 30.00			

Workorder: 1211296

Problem: REAR PASSENGER BRAKE LIGHT INOP.

Meter Reading: 35986		Labor		Parts	
In Date: 11/21/2012	Close Date: 11/26/2012	Hours	Description		Quantity
- Repair And Clean R Rear Brake Light Wiring Connection		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge: 2.00		Labor Charge: 60.00			

Workorder: 1301278

Problem: driver rear tire has nail , low pressure sensor on

Meter Reading: 37394		Labor		Parts	
In Date: 02/05/2013	Close Date: 02/12/2013	Hours	Description		Quantity
- Ck Nail In Tires Replace Two Rear Tires Rotate To Front		1.50	SHOP SUPPLIES		1.00
Mount Balance Add N2			179636492 LT245-75R17		2.00
- Shop Supplies			TIRE DISPOSAL FEE		2.00
Parts Charge: 492.05		Labor Charge: 90.00			

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1303158

Problem: pm, stalling out

Meter Reading: 39103		Labor		Parts	Quantity
In Date: 04/01/2013	Close Date: 04/18/2013	Hours	Description		
-	Pm	6.00	SHOP SUPPLIES		1.00
-	Ck Vehicle Stalled Out Ck And Scan For Code Found		NAPAGOLD AIR FILTER		1.00
	Code Po300, P0191 Ck Fuel System Pressure And		NAPA QUART 5W20		8.00
	Replace Fuel Filter		NAPAGOLD OIL FILTER		1.00
-	50 Miles Test Drive Was Unable To Verify Driver Concern		WIPER BLADE		2.00
	Of Stalling		FORD FUEL FILTER		1.00
-	Shop Supplies				
Parts Charge:		63.69	Labor Charge:	360.00	

Workorder: 1303862

Problem: CHECK ENGINE LIGHT STAYS ON/ NO POWER

Meter Reading: 39196		Labor		Parts	Quantity
In Date: 04/18/2013	Close Date: 04/26/2013	Hours	Description		
-	Ck Vehicle Have No Power Scan Found Code #P017A,	5.25	FUEL PUMP W/SENDER		1.00
	P0191 Perform Pinpoint Test And Found Bad Fuel Pump		SHOP SUPPLIES		1.00
	Replace Fuel Pump And Clear Codes				
-	Test Drive Vehicle 100 Miles To Verify No More				
	Performance Problem At This Time				
-	Shop Supplies				
Parts Charge:		520.88	Labor Charge:	315.00	

Workorder: 1304802

Problem: miss firing again

Meter Reading: 39395		Labor		Parts	Quantity
In Date: 05/14/2013	Close Date: 05/17/2013	Hours	Description		
-	Ck Misfire Scan Test Post Perform Coimpression Test	11.00	COIL ASSEMBLY		8.00
	Drive For Engine Misfire Replace All Spark Plugs Coil		SPARK PLUG		8.00
	Pack Clean Dthrottle Body Clean Injector And Test Drive		SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		735.68	Labor Charge:	660.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1308039 **Problem:** REAR RIGHT SIDE TURN SIGNAL INOP, REPLACE PINTAL PIN BROKEN

Meter Reading: 40961		Labor		Parts	
In Date: 08/12/2013	Close Date: 08/16/2013	Hours	Description		Quantity
-	Pintle Pin	0.75	BULB		1.00
-	Rr Right Rear Brake Light Bulb		PINTLE PIN W/CHAIN		1.00
Parts Charge: 3.60		Labor Charge: 45.00			

Workorder: 1309194 **Problem:** replace left tail light

Meter Reading: 41831		Labor		Parts	
In Date: 09/10/2013	Close Date: 09/12/2013	Hours	Description		Quantity
-	Ck Lr Rtail Light Out Replace Lr Tail Light Bulb Test All Lights	0.50	BULB		1.00
Parts Charge: 0.99		Labor Charge: 30.00			

Workorder: 1309232 **Problem:** instdall pintal pin

Meter Reading: 41999		Labor		Parts	
In Date: 09/11/2013	Close Date: 09/18/2013	Hours	Description		Quantity
-	Replace Pintle Pin	0.25	PINTLE PIN W/CHAIN		1.00
Parts Charge: 2.61		Labor Charge: 15.00			

Workorder: 1309879 **Problem:** R/REAR TAIL LIGHT INOP.

Meter Reading: 42315		Labor		Parts	
In Date: 09/30/2013	Close Date: 10/04/2013	Hours	Description		Quantity
-	Repair Rr Tail Light	0.50	BULB		1.00
Parts Charge: 0.99		Labor Charge: 30.00			

Workorder: 1405775 **Problem:** 2 - Key(s) issued

Meter Reading: 44849		Labor		Parts	
In Date: 06/12/2014	Close Date: 06/12/2014	Hours	Description		Quantity
-	2 - Key(S) Issued	0.40	DUPLICATE VEHICLE KEYS		2.00
Parts Charge: 6.00		Labor Charge: 36.00			

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1406804

Problem: pm, strobe light ck out

Meter Reading: 45448		Labor		Parts	
In Date: 07/10/2014	Close Date: 07/22/2014	Hours	Description		Quantity
- Pm		5.75	NAPA QUART 5W20		8.00
- Install And Wire Strobe Light			NAPAGOLD OIL FILTER		1.00
- Shop Supplies			USED FIRE X REFURBISHED		1.00
			STROBE LP LED		1.00
			CLR RTV SILCN SEALANT		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 181.74		Labor Charge:	345.00		

Workorder: 1410680

Problem: pm

Meter Reading: 49703		Labor		Parts	
In Date: 10/24/2014	Close Date: 10/30/2014	Hours	Description		Quantity
- Pm		4.50	NAPA QUART 5W20		8.00
- Repair Both Front Head Lights			NAPAGOLD OIL FILTER		1.00
- Install Hows My Driving Decal			WIPER BLADE		2.00
- Shop Supplies			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD AIR FILTER		1.00
			WASHER FL		1.00
			SHOP SUPPLIES		1.00
			MAC WITE LITHIUM GRES		1.00
			HALOGEN LAMP		2.00
Parts Charge: 93.07		Labor Charge:	270.00		

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1412450

Problem: CHECK ENGINE LIGHT STAYS ON

Meter Reading: 50877		Labor		Parts	Quantity
In Date: 12/12/2014	Close Date: 12/29/2014	Hours	Description		
-	Ck Engine Lifht Is On Scan Found Code Po420 Perform Pinpoint Test Found Bad Catalist Sent To Dealer For Warranty	4.25	BLOWER MOTOR RESISTOR SHOP SUPPLIES		1.00 1.00
-	Transport To Pick Up At Dealer For Warranty Repair Defective Cat Converter				
-	Ac Blower Not Working On Speed 1 & 2 Perform Pinpoint Test And Found Bad Blower Resestor Replace Ac Blower Resistor				
-	Shop Supplies				
Parts Charge:		21.41	Labor Charge:	255.00	

Workorder: 1501054

Problem: brake light and blinker out drivers side rear

Meter Reading: 52630		Labor		Parts	Quantity
In Date: 01/29/2015	Close Date: 01/30/2015	Hours	Description		
-	Ck Tail Light Out Rpair Left Rear Tail Light	0.50	BULB		1.00
Parts Charge:		0.75	Labor Charge:	30.00	

Workorder: 1502810

Problem: pm, ladder racks

Meter Reading: 54790		Labor		Parts	Quantity
In Date: 03/18/2015	Close Date: 03/27/2015	Hours	Description		
-	Pm	7.75	NAPA QUART 5W20		8.00
-	Install Ladder Rack		NAPAGOLD OIL FILTER		1.00
-	Repair 3Rd Brake Light Repair Roof Top Strobe Light		LADDER RACK		1.00
-	Shop Supplies		WASHER FL		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		598.31	Labor Charge:	465.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1504486		Problem: r/rear brake light inop.			
Meter Reading: 55828		Labor		Parts	
In Date: 05/01/2015		Close Date: 05/07/2015			
		Hours		Description	
				Quantity	
- Repair Left Rear Barke Light		0.50	BULB		1.00
Parts Charge:		0.75	Labor Charge:	30.00	
Workorder: 1504686		Problem: screw in pass front tire			
Meter Reading: 56329		Labor		Parts	
In Date: 05/08/2015		Close Date: 05/12/2015			
		Hours		Description	
				Quantity	
- Repair Right Front Tire		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	
Workorder: 1505238		Problem: brake light out drivrs side rear			
Meter Reading: 57472		Labor		Parts	
In Date: 05/26/2015		Close Date: 05/29/2015			
		Hours		Description	
				Quantity	
- Repair Left Rear Brake Light		0.50	BULB		1.00
Parts Charge:		0.75	Labor Charge:	30.00	
Workorder: 1506674		Problem: screw in dirver side front tire			
Meter Reading: 58398		Labor		Parts	
In Date: 07/02/2015		Close Date: 07/08/2015			
		Hours		Description	
				Quantity	
- Repair Left Front Tire		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	
Workorder: 1507268		Problem: driver side rear tail light out			
Meter Reading: 58972		Labor		Parts	
In Date: 07/21/2015		Close Date: 07/30/2015			
		Hours		Description	
				Quantity	
- Repair Left Rear Tail Light		0.50	BULB		1.00
Parts Charge:		0.75	Labor Charge:	30.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1508550

Problem: pm, bad battery

Meter Reading: 60236		Labor		Parts	Quantity
In Date: 08/26/2015	Close Date: 09/14/2015	Hours	Description		
-	Pm	6.00	179636492 LT245-75R17		2.00
-	CI Slow Start Recharge Test Battery Bad		SHOP SUPPLIES		1.00
-	Svc Ladder Rack		TIRE DISPOSAL FEE		2.00
-	Verify Needs Two Tires Mount Balnace Add N2 Replaced		BATTERY		1.00
-	2 Tires		WD40 16OZ		1.00
-	Shop Supplies		NAPA QUART 5W20		8.00
			NAPAGOLD FUEL FILTER		1.00
			NAPAGOLD OIL FILTER		1.00
			WIPER BLADE		2.00
Parts Charge:		701.36	Labor Charge:	360.00	

Workorder: 1512627

Problem: dead battery towed in

Meter Reading: 64618		Labor		Parts	Quantity
In Date: 12/15/2015	Close Date: 12/29/2015	Hours	Description		
-	Ck And Replace Starter	1.50	STARTER		1.00
-	Shop Supplies		SHOP SUPPLIES		1.00
			starter		1.00
Parts Charge:		377.21	Labor Charge:	90.00	

Workorder: 1512755

Problem: dead battery

Meter Reading: 64153		Labor		Parts	Quantity
In Date: 12/14/2015	Close Date: 12/17/2015	Hours	Description		
-	Tow From: Stone Bridge Cc To: Sr Delray				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 96.00

Workorder: 1600638

Problem: brake light out

Meter Reading: 65290		Labor		Parts	Quantity
In Date: 01/20/2016	Close Date: 01/22/2016	Hours	Description		
-	Repair Right Rear Brake Light	0.50	BULB		1.00
Parts Charge:		0.78	Labor Charge:	30.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1601095		Problem: drivers side break light out			
Meter Reading: 66137		Labor		Parts	
In Date: 02/01/2016	Close Date: 02/04/2016	Hours	Description	Quantity	
- Repired Left Rear Brake Light		0.50	BULB	1.00	
Parts Charge:		0.78	Labor Charge:	30.00	
Workorder: 1602071		Problem: Install computer stand.			
Meter Reading: 67027		Labor		Parts	
In Date: 02/29/2016	Close Date: 03/02/2016	Hours	Description	Quantity	
- Assemble And Install Computer Stand.		2.00	SHOP SUPPLIES	1.00	
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	120.00	
Workorder: 1602509		Problem: PM			
Meter Reading: 67295		Labor		Parts	
In Date: 03/09/2016	Close Date: 03/14/2016	Hours	Description	Quantity	
- Pm		5.25	TIRE DISPOSAL FEE	2.00	
- Verify Needs Two Tires Rr Tires Rotate To Front Balance			SHOP SUPPLIES	1.00	
Correct All N2 Reset Tpms			NAPA QUART 5W20	8.00	
- Svc Ladder Rack K Re Svc Tool Box And Rack			179636492 LT245-75R17	2.00	
- Shop Supplies			NAPAGOLD OIL FILTER	1.00	
Parts Charge:		542.64	Labor Charge:	315.00	
Workorder: 1604196		Problem: Driver side tail lamp inop.			
Meter Reading: 68595		Labor		Parts	
In Date: 04/21/2016	Close Date: 04/26/2016	Hours	Description	Quantity	
- Test And Replace Defective Left Tail Lamp Bulb.		0.50	BULB	1.00	
Parts Charge:		0.78	Labor Charge:	30.00	

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1605213

Problem: Right rear turnsignal light inop.

Meter Reading: 69932		Labor		Parts	
In Date: 05/19/2016	Close Date: 05/25/2016	Hours	Description		Quantity
- Test And Replace Defective Right Rear Turnsignal Lamp Bulb		0.50	BULB		1.00
Parts Charge: 0.78		Labor Charge:	30.00		

Workorder: 1607562

Problem: Left side tail light out.

Meter Reading: 71826		Labor		Parts	
In Date: 07/25/2016	Close Date: 07/28/2016	Hours	Description		Quantity
- Replace Left Rear Tail Light Bulb.		0.25	BULB		1.00
Parts Charge: 0.78		Labor Charge:	15.00		

Workorder: 1608390

Problem: Pm service and check tail lights.

Meter Reading: 72558		Labor		Parts	
In Date: 08/15/2016	Close Date: 08/17/2016	Hours	Description		Quantity
- P.M.Service.		15.50	BULB		2.00
- C/C Tail Lights. Replace Two Tail Light			NAPA QUART 5W20		8.00
Sockets,&Bulbs.R/R Cargo Light Bulb.			NAPAGOLD OIL FILTER		1.00
- Replace W/Washer Nozzles,Service Ladder Rack& Tool			USED FIRE X REFURBISHED		1.00
Box.			WASHER FLUID CONCENTR		1.00
- Rotate & Balance All Tires.			STP TRN TL LGT SOCKET		2.00
- Verify Needs Front&Rear Brake Pads. Turn All			BULB		1.00
Rotors,Service All Calipers,R/R Front &Rear Brake			PADS		1.00
Pads.Test Drive.			SHOP SUPPLIES		1.00
- Shop Supplies			WIPER BLADE ANCO		2.00
			REAR PADS		1.00
			WASHER NOZZLE		2.00
			NAPAGOLD AIR FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
Parts Charge: 254.03		Labor Charge:	930.00		

1/3/2017
12:28:11PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10170994 2008 FORD F250 Pickup, 3/4 Ton, W/Tow Pkg

Workorder: 1610900

Problem: Transition Prep Charge

Meter Reading: 74054

Labor

Parts

In Date: 10/21/2016

Close Date: 10/21/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 120.00

Total Parts Charges: 7,390.00

Total Labor Charges: 9,666.00

Total Comm. Charges: 2,604.17