

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 746393                      **Problem:** PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/29/2007	Hours	Description	
- Pre-Delivery Inspection	<b>2.00</b>		
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	120.00

**Workorder:** 747145                      **Problem:** 001 KEY ISSUED OUT      11/08/07

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/08/2007	Hours	Description	
- 001 Key Issued Out	<b>0.20</b>	DUPLICATE VEHICLE KEYS	1.00
<b>Parts Charge:</b>	3.00	<b>Labor Charge:</b>	0.00

**Workorder:** 833846                      **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 01/28/2008	Hours	Description	
- Tiresoles Of Broward Inc			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	60.00

**Workorder:** 835423                      **Problem:** P.M SERVICE

Meter Reading: 5000	Labor	Parts	Quantity
In Date: 03/12/2008	Hours	Description	
- Pm Service	<b>3.75</b>	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And High Speed Balance All 4 Tires.Nitro Fill Tires.		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
- Shop Supplies		AIR FILTER	1.00
		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	53.51	<b>Labor Charge:</b>	60.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 836109

**Problem:** INSTALL CUSTOMERS COMPUTER STAND

<b>Meter Reading:</b> 5291	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 03/27/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Fabricate & Install Computer Stand,Fabricate Route & Install Laptop Wiring To Engine Compartment.	<b>4.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	240.00

**Workorder:** 837355

**Problem:** FLOOR MAT WRINKLED

<b>Meter Reading:</b> 5436	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 04/22/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Remove & Replace Computer Stand & Fire Extinguisher Bracket So That Dealer Can Replace Floor Carpet Under Warranty.	<b>3.40</b>	SHOP SUPPLIES	1.00
- To/From Dealer For Warrenty Floor Mat.			
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	42.00

**Workorder:** 841112

**Problem:** POLISH FRT FENDER TO REMOVE SCRATCH & REPLACE LEFTMIRROR

<b>Meter Reading:</b> 7377	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/09/2008	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
<hr/>			
- Replace Left Mirror	<b>2.50</b>	SHOP SUPPLIES	1.00
- Polish Frt Fender Remove Scratch		LH MIRROR ASSY	1.00
- Shop Supplies			
<b>Parts Charge:</b>	129.05	<b>Labor Charge:</b>	60.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 846611

**Problem:** P.M SERVICE

Meter Reading: 10018	Labor	Parts	
In Date: 11/03/2008	Hours	Description	Quantity
- Pm Service	3.75	5W20 ENGINE OIL	7.00
- Rotate & High Speed Balance All 4 Tires.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Shop Supplies		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
		SHOP SUPPLIES	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
<b>Parts Charge:</b>	79.61	<b>Labor Charge:</b>	60.00

**Workorder:** 937876

**Problem:** P.M SERVICE,CHECK LIGHT BAR SWITCH

Meter Reading: 14900	Labor	Parts	
In Date: 05/18/2009	Hours	Description	Quantity
- Pm Service	8.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Mount And Balance 4 New Tires. Nitro Fill Tires.		5W20 ENGINE OIL	7.00
- Test And Replace Toggle Switch For Beacon Strobe Light.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Complete Front End Alignment.Test Drive.		TIRE DISPOSAL FEE	4.00
- Shop Supplies		TR416 VALVE STEM	4.00
		LT24575/R17 TIRE	4.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b>	396.33	<b>Labor Charge:</b>	495.00

**Workorder:** 938378

**Problem:** INSTALL STEPS.

Meter Reading: 14914	Labor	Parts	
In Date: 05/29/2009	Hours	Description	Quantity
- Install New Step On Left And Right Side Of Vehicle.Fabricatebrackets.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies		SUPER HOOP STEP SET	1.00
<b>Parts Charge:</b>	194.00	<b>Labor Charge:</b>	120.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 943292

**Problem:** Slow cranking, had to jump start

Meter Reading: 17983	Labor	Parts	
In Date: 09/16/2009	Hours	Description	Quantity
- Test Starting & Charging System, Charge & Test Battery, Failed Load Test, R&R Battery.	1.00	SHOP SUPPLIES	1.00
- Shop Supplies		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
<b>Parts Charge:</b> 127.44		<b>Labor Charge:</b> 60.00	

**Workorder:** 945024

**Problem:** P.M. Service.

Meter Reading: 18844	Labor	Parts	
In Date: 10/26/2009	Hours	Description	Quantity
- P.M Service.	5.25	7039D SPOT MIRROR VELVAC 723060	2.00
- Mount Two Spot Mirrors.		USED FIREX REFURBED FIRE EXTINGSHERS	1.00
- Repair R/F Tire, Rotate & Balance All Four Tires.		FLOOR MAT SET	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		5W20 ENGINE OIL	7.00
		31-20 WIPER BLADES 20" BLADE	2.00
<b>Parts Charge:</b> 121.76		<b>Labor Charge:</b> 315.00	

**Workorder:** 1005099

**Problem:** P.M service.

Meter Reading: 23835	Labor	Parts	
In Date: 05/17/2010	Hours	Description	Quantity
- P.M Service.	2.75	5W20 ENGINE OIL	7.00
- Shop Supplies		1372 OIL FILTER FRM PH2 WIX 51372	1.00
		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 17.61		<b>Labor Charge:</b> 165.00	

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1006463                      **Problem:** Check power steering fluid condition.

Meter Reading: 24806	Labor	Parts	
In Date: 06/18/2010	Hours	Description	Quantity
- Power Steering Fluid Contaminated Due To Water Ingestion. Power Flush System Multiple Times. Remove And Clean Reservoir And Cooler Then Renew Fluid.	3.00	SYN/ATF TRANS FLUID SYNTHETIC	8.00
- Shop Supplies		SHOP SUPPLIES	1.00
<b>Parts Charge:</b> 41.22		<b>Labor Charge:</b> 180.00	

**Workorder:** 1013236                      **Problem:** P.M. service.

Meter Reading: 28885	Labor	Parts	
In Date: 12/01/2010	Hours	Description	Quantity
- Perform Pm Service.	7.25	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Install Four New Tires. Nitrogen Fill And Balance All Four.		CA10262 AIR FILTER MTC FA1883 WIX 49883	1.00
- Perform Wheel Alignment Complete.		USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
		SHOP SUPPLIES	1.00
		179636492 LT245/75R17 WRANGLER SR-A E	4.00
		TIRE DISPOSAL FEE	4.00
		31-20 WIPER BLADES 20" BLADE	2.00
		G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00
<b>Parts Charge:</b> 798.51		<b>Labor Charge:</b> 435.00	

**Workorder:** 1105917                      **Problem:** Pm service and see notes on tires.

Meter Reading: 33092	Labor	Parts	
In Date: 06/03/2011	Hours	Description	Quantity
- Perform Pm Service.	3.75	1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Rotate And Balance All Four Tires.		WD40 SPRAY LUBE STOCK# 405540002	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		31-20 WIPER BLADES 20" BLADE	2.00
		USED FIREX REFURBED FIRE EXTINGUISHERS	1.00
		5W20 ENGINE OIL	7.00
<b>Parts Charge:</b> 51.61		<b>Labor Charge:</b> 225.00	

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1110873

**Problem:** Install tool box/fuel tank combo(supplied by costomer).Left rear has nail.

Meter Reading: 36082	Labor	Parts	
In Date: 10/12/2011	Hours	Description	Quantity
- Fabricate And Install Combination Fuel Tank/Tool Box In Bed Of Truck.Install New Fuel Transfer Pump And Fabricate Elbows For Plumbing And Filter.Fabricate And Install Wiring Harness To Operate Pump.	7.00	GROUP 65 BATTERY (MTC BXT-65-850) SHOP SUPPLIES 80865 FUSEHOLDER IMPERIAL 80865 3/4 90D ELBOW GALV. (VARIOUS)	1.00 1.00 1.00 1.00
- Test Starting And Charging System.Battery Failed Loadtest After Recharge.Replace Failed Battery With New.		3/4X3 NIPPLE GALV. (VARIOUS) TOGGLE SWITCH	1.00 1.00
- Repair Flat Right Rear Tire.Nitrogen Fill And Balance Same.			
- Shop Supplies			
<b>Parts Charge:</b>	148.38	<b>Labor Charge:</b>	420.00

**Workorder:** 1113021

**Problem:** Pm service and see notes on hose extension.

Meter Reading: 38197	Labor	Parts	
In Date: 12/09/2011	Hours	Description	Quantity
- Perform Pm Service.	5.75	SHOP SUPPLIES	1.00
- Perform Auxiliary Fuel Tank Service.Fabricate And Install Customer Supplied Extension Fuel Hose And Secure.		31-20 WIPER BLADES 20" BLADE 5W20 ENGINE OIL	2.00 7.00
- Rotate And Balance All Four Tires.		1372 OIL FILTER FRM PH2 WIX 51372	1.00
- Shop Supplies		70236 FUEL FILTER 10 MICRON BIODIESEL 3/4 PIPE COUPLING (VARIOUS) D3TZ2457B BRAKE PEDAL PAD G10166 FUEL FILTER MTC FG1083 WIX 33243	1.00 1.00 1.00 1.00
<b>Parts Charge:</b>	76.77	<b>Labor Charge:</b>	345.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1204785

**Problem:** P.M. service and towed in right front tire flat.

<b>Meter Reading: 45332</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 05/22/2012</b>	<b>Close Date: 05/31/2012</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Perform Pm Service.	<b>8.25</b>	CA10262 AIR FILTER MTC FA1883 WIX 49883		1.00
-	Perform Auxiliary Fuel Tank Service And Replace Fuel Filter.		24006 FUEL FILTER DIESEL AND GAS		1.00
-	Install Two New Tires To The Front Wheels.Nitrogen Fill And Balance All Four.		179636492 LT245/75R17 WRANGLER SR-A E		2.00
-	Perform Wheel Alignment Complete.		TIRE DISPOSAL FEE		2.00
-	Shop Supplies		5W20 ENGINE OIL		7.00
			1372 OIL FILTER FRM PH2 WIX 51372		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			SHOP SUPPLIES		1.00
<b>Parts Charge:</b>		431.24	<b>Labor Charge:</b>		495.00

**Workorder:** 1204972

**Problem:** Flat tire

<b>Meter Reading: 45175</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 05/22/2012</b>	<b>Close Date: 05/30/2012</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Tow From: Royal Palm Beach, 340 Crestwood Circle To: Vista Center				
<b>Parts Charge:</b>		0.00	<b>Labor Charge:</b>		0.00
			<b>Commercial Charge:</b>		104.15

**Workorder:** 1206729

**Problem:** Right brake lamp inop.

<b>Meter Reading: 47095</b>		<b>Labor</b>		<b>Parts</b>	
<b>In Date: 07/19/2012</b>	<b>Close Date: 07/19/2012</b>	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>	
-	Test And Replace Two Failed Tail Lamp Bulbs With New.	<b>0.50</b>	3157 TAIL LIGHT BULBS		2.00
<b>Parts Charge:</b>		1.20	<b>Labor Charge:</b>		30.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1209511                      **Problem:** Pm service.Request for installing light bar insde of rear windshield.

Meter Reading: 51552	Labor	Parts	
In Date: 10/04/2012	Hours	Description	Quantity
- P.M. Service.	<b>13.75</b>	LIGHT BAR	1.00
- Flush And Refill Transmission System		5W20 ENGINE OIL	7.00
- Inspect And Service Aux. Fuel System.		G10166 FUEL FILTER MT	1.00
- Replace Two Tires,Rotate And Balance All Four.		179636492 LT245-75R17	2.00
- Install Traffic Advisor Light Bar In Rear Window.Fabricate		31-20 WIPER BLADES 20	2.00
Mounting Brackets And Wiring.		TR416 VALVE STEM	2.00
- Diagnose Check Engine Light.Replace Failed Oxygen		SYN-ATF TRANS FLUID S	18.00
Senor,Bank #1,Sensor#2.Clear Codes.		80865 FUSEHOLDER IMPE	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
		PH2 OIL FILTER LBF PH	1.00
		24006 FUEL FILTER	1.00
		OXYGEN SENSOR	1.00
<b>Parts Charge:</b>	1,802.04	<b>Labor Charge:</b>	825.00

**Workorder:** 1303088                      **Problem:** Pm service.

Meter Reading: 57118	Labor	Parts	
In Date: 03/29/2013	Hours	Description	Quantity
- Perform Pm Service.Replace Wheel Center Cap.	<b>5.75</b>	31-20 WIPER BLADES 20	2.00
- Inspect And Service Auxiliary Fuel Tank And Replace Fuel		1372 OIL FILTER	1.00
Filter.		WHEEL COVER	1.00
- Repair Flat Right Rear Tire.Nitrogen Fill And Balance All		SHOP SUPPLIES	1.00
Four.		FUEL FILTER	1.00
- Shop Supplies		5W20 ENGINE OIL	7.00
<b>Parts Charge:</b>	114.66	<b>Labor Charge:</b>	345.00

**Workorder:** 1305884                      **Problem:** Repair left front tire.

Meter Reading: 59459	Labor	Parts	
In Date: 06/13/2013	Hours	Description	Quantity
- Repair And Balance Left Front Tire.	<b>1.00</b>	SHOP SUPPLIES	1.00
- Shop Supplies			
<b>Parts Charge:</b>	2.00	<b>Labor Charge:</b>	60.00



1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1307272

**Problem:** Wiper blades seperated.

<b>Meter Reading:</b> 62330	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 07/22/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Inspect And Replace Both Failed Wiper Blades With New.	<b>0.30</b>	31-20 WIPER BLADES 20	2.00
<b>Parts Charge:</b> 11.01	<b>Labor Charge:</b> 18.00		

**Workorder:** 1308628

**Problem:** P.M. service and tailgate protector missing.

<b>Meter Reading:</b> 64052	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 08/27/2013	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- Perform Pm Service.	<b>5.25</b>	SHOP SUPPLIES	1.00
- Inspect And Service Auxiliary Fuel Tank And Install New Filter.		ANTENNA	1.00
		5W20 ENGINE OIL	7.00
- Inspect And Replace Failed Tailgate Cap And Antenna Mask With New.		NAPAGOLD OIL FILTER	1.00
		USED FIRE X REFURBISHED	1.00
- Rotate And Balance All Four Tires.		31-20 WIPER BLADES 20	2.00
- Shop Supplies		NAPAGOLD FUEL FILTER	1.00
		MOULDING	1.00
<b>Parts Charge:</b> 174.14	<b>Labor Charge:</b> 315.00		

**Workorder:** 1401163

**Problem:** Pm service and has to jump start .

<b>Meter Reading:</b> 69137	<b>Labor</b>	<b>Parts</b>	
<b>In Date:</b> 02/04/2014	<b>Hours</b>	<b>Description</b>	<b>Quantity</b>
- P.M. Service.	<b>15.75</b>	PADS	1.00
- Inspect And Service Aux. Fuel System.		2232 BRAKE FLUID QUAR	1.00
- Replace Two Tires,Rotate And Balance All Four.		BRAKE CLEANER	1.00
- Test Battery And Charging System.Replace Defective Battery.		5W20 ENGINE OIL	7.00
		BATTERY 65	1.00
- Resurface Front And Rear Brake Rotors,Replace Front And Rear Brake Pads.Service And Lubecalipers.Flush And Bleed System And Test Drive.		NAPAGOLD FUEL FILTER	1.00
		BRAKE PAD	1.00
		NAPAGOLD FUEL FILTER	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
		WIPER BLADE	2.00
		179636492 LT245-75R17	2.00
		NAPAGOLD OIL FILTER	1.00
		TIRE DISPOSAL FEE	2.00
<b>Parts Charge:</b> 709.49	<b>Labor Charge:</b> 945.00		

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

<b>Workorder:</b> 1401769		<b>Problem:</b> Right rear tire flat.			
<b>Meter Reading:</b> 69244		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 02/24/2014	<b>Close Date:</b> 02/27/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Repair And Balance Right Rear Tire.	<b>1.00</b>	SHOP SUPPLIES		1.00
-	Shop Supplies				
	<b>Parts Charge:</b> 2.00		<b>Labor Charge:</b> 60.00		
<b>Workorder:</b> 1405273		<b>Problem:</b> Left rear turn signal inop.			
<b>Meter Reading:</b> 73831		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 05/30/2014	<b>Close Date:</b> 06/04/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Replace Left Rear Signal Light Bulb.	<b>0.50</b>	BULB		1.00
	<b>Parts Charge:</b> 0.99		<b>Labor Charge:</b> 30.00		
<b>Workorder:</b> 1406308		<b>Problem:</b> rear turn signal out right side			
<b>Meter Reading:</b> 75930		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 06/26/2014	<b>Close Date:</b> 07/07/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Repair Right Rear Turn Signal	<b>0.50</b>	BULB		1.00
	<b>Parts Charge:</b> 0.99		<b>Labor Charge:</b> 30.00		
<b>Workorder:</b> 1408131		<b>Problem:</b> Pm service and headlamps not bright enough at night.			
<b>Meter Reading:</b> 78140		<b>Labor</b>		<b>Parts</b>	
<b>In Date:</b> 08/15/2014	<b>Close Date:</b> 08/28/2014	<b>Hours</b>	<b>Description</b>		<b>Quantity</b>
<hr/>					
-	Pm Service.	<b>7.75</b>	CAP		1.00
-	Service Auxiliary Fuel Tank And Replace Filter.		SHOP SUPPLIES		1.00
-	Replace Both Headlamp Seal Beams Due To Corroded Reflectors,		PEAK GLOBAL		2.00
-	Pressure Test And Service Cooling System.Flush And Renew Coolant.		HALOGEN LAMP		2.00
-	Rotate And Balance All Four Tires.		5W20 ENGINE OIL		7.00
-	Shop Supplies		WIPER BLADE		2.00
			NAPAGOLD AIR FILTER		1.00
			FLOOR MAT-2PC RUB BK		1.00
			NAPAGOLD OIL FILTER		1.00
			NAPAGOLD FUEL FILTER		1.00
	<b>Parts Charge:</b> 167.09		<b>Labor Charge:</b> 465.00		

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1409451                      **Problem:** damage to rgt rear fender

Meter Reading: 78180	Labor	Parts	
In Date: 08/25/2014	Hours	Description	Quantity
- Damage To Rgt Rear Fender			
<b>Parts Charge:</b>	0.00	<b>Labor Charge:</b>	0.00
		<b>Commercial Charge:</b>	375.00

**Workorder:** 1500548                      **Problem:** Rear right turnsignal lamp inop.

Meter Reading: 80243	Labor	Parts	
In Date: 01/15/2015	Hours	Description	Quantity
- Test And Replace Defective Right Rear Turnsignal Lamp Bulb.			
<b>Parts Charge:</b>	0.75	<b>Labor Charge:</b>	30.00
	0.50	BULB	1.00

**Workorder:** 1501613                      **Problem:** P.M. Service.

Meter Reading: 80894	Labor	Parts	
In Date: 02/12/2015	Hours	Description	Quantity
- Pm Service.			
	18.75	WIPER BLADE	2.00
- Inspect And Service Auxiliary Fuel Tank.			
		KA8A THROTTLE BODY- U	2.00
- Perform Major Tune Up And Replace All Eight Spark Plugs And One Ignition Coil.Had To Fabricate And Extract Three Broken Sparkplugs Clear Codes With Scan Tool And Road Test.			
		5W20 ENGINE OIL	7.00
		CLR RTV SILCN SEALANT	1.00
		NAPAGOLD FUEL FILTER	1.00
		RESTRAINT CONTROL MOD	1.00
- Inspect And Replace Defective Becon Lamp And Toggle Switch.			
		COIL ASSEMBLY	1.00
		SHOP SUPPLIES	1.00
- Rotate And Balance All Four Tires.			
		NAPAGOLD OIL FILTER	1.00
- Perform Induction Service And Clean Trottle Body.Perform Injectors Flushed.			
		TOGGLE SWITCH	1.00
		5068 PENTRATING OIL	1.00
		STROBE	1.00
- Computer Diagnose For Airbag Light On.Code B1342 Pinpoint Test And Replace Defective Restraint Control Module.Clear Code With Scan Tool Anr Retest.			
		SPARK PLUG	8.00
		408 FUEL INJECTION CL	1.00
- Shop Supplies			
<b>Parts Charge:</b>	814.86	<b>Labor Charge:</b>	1,125.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1504134

**Problem:** Truck runs rough and check engine light on.

Meter Reading: 82671	Labor	Parts
In Date: 04/21/2015	Hours	Description
Close Date: 04/30/2015	Quantity	
- Computer Diagnose Check Engine Light On And Runs	2.00	SHOP SUPPLIES
Rough.Code P0302.Test And Replace Defective #2		COIL ASSEMBLY
Ignition Coil..Clear Codes And Test Drive.		
- Shop Supplies		
<b>Parts Charge:</b>	77.90	<b>Labor Charge:</b> 120.00

**Workorder:** 1508315

**Problem:** Pm service.Right rear tire flat.

Meter Reading: 87505	Labor	Parts
In Date: 08/19/2015	Hours	Description
Close Date: 09/11/2015	Quantity	
- P.M. Service.	14.75	BULB
- Inspect And Service Aux. Fuel System.Replace Hose		STG WHEEL COV - FORD
Nozzle.		FLOOR MAT-2PC RUB BK
- Replace Two Tires,Rotate And Balance All Four.		NAPAGOLD FUEL FILTER
- Check And Replace All Six Cab Mounts/Insulators.		179636492 LT245-75R17
- Complete Wheel Alignment.Test Drive.		TR416 VALVE STEM
- Shop Supplies		INSULATOR
		INSUALTOR
		INSULATOR
		SHOP SUPPLIES
		MANUAL NOZZLE
		INSULATOR
		TIRE DISPOSAL FEE
		BOLT
		NAPAGOLD OIL FILTER
		WIPER BLADE
		NAPAGOLD AIR FILTER
		5W20 ENGINE OIL
		BODY MOUNT KIT
<b>Parts Charge:</b>	1,199.89	<b>Labor Charge:</b> 885.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1509544

**Problem:** Ac blows warm air.

Meter Reading: 88138	Labor	Parts	
In Date: 09/22/2015	Hours	Description	Quantity
- Ac Performance Test For Ac Blows Warm Air.Evacuate System.Replace Defective Ac Compressor,Accumulator And Orifice Tube.Flush System.Vacume And Recharge System To Specs.	<b>6.00</b>	FLUSH SOLVENT	1.00
		SHOP SUPPLIES	1.00
		ACCUMULATOR	1.00
		NEW COMPRESSOR	1.00
- Shop Supplies		ORIFICE TUBE	1.00
		R134A LV SHOP 1	2.00
		AC VALVE CORE HIGH	1.00
		E8 A/C OIL UNIV W DYE	1.00
		SEAL KIT	1.00
<b>Parts Charge:</b>	514.40	<b>Labor Charge:</b>	360.00

**Workorder:** 1510199

**Problem:** Right tail lamp inop.

Meter Reading: 88722	Labor	Parts	
In Date: 10/07/2015	Hours	Description	Quantity
- Test And Replace Defective Right Tail Lamp Bulb.	<b>0.50</b>	BULB	1.00
<b>Parts Charge:</b>	0.75	<b>Labor Charge:</b>	30.00

**Workorder:** 1512915

**Problem:** R/REAR SIGNAL LIGHT INOP

Meter Reading: 91641	Labor	Parts	
In Date: 12/22/2015	Hours	Description	Quantity
- Replace Right Rear Signal Light	<b>0.50</b>	BULB	1.00
<b>Parts Charge:</b>	0.75	<b>Labor Charge:</b>	30.00

1/3/2017  
12:29:15PM

## Palm Beach County Fleet Management Asset Maintenance History

Asset: 10171051 2008 FORD F250 Pickup, 3/4 Ton, 4X4, W/Tow Pkg

**Workorder:** 1604559

**Problem:** P.M. Service.

Meter Reading: 96277 In Date: 04/29/2016	Close Date: 05/11/2016	Labor Hours	Description	Parts	Quantity
- P.M. Service.		<b>9.50</b>	5W20 ENGINE OIL		7.00
- Inspect And Service Aux. Fuel Sysytem.			PEDAL PAD		1.00
- Test Battery And Charging System.Replace Bad Alternato And Serpentine Belt.			NAPAGOLD FUEL FILTER		1.00
			ALTERNATOR		1.00
- Replace Tewo Tires,Roatae And Balance All Four.			BELT		1.00
- R&R Drive Shaft And Clean And Lube Slip Yoke To			BULB		1.00
Correct Clunking At Stops And Take-Off.			TR416 VALVE STEM		2.00
- Shop Supplies			20" WIPER BLADE		2.00
			179636492 LT245-75R17		2.00
			NAPAGOLD OIL FILTER		1.00
			SHOP SUPPLIES		1.00
			TIRE DISPOSAL FEE		2.00
	<b>Parts Charge: 846.37</b>	<b>Labor Charge: 570.00</b>			

**Workorder:** 1610877

**Problem:** Transition Prep Charge

Meter Reading: 100954 In Date: 10/21/2016	Close Date: 10/21/2016	Labor Hours	Description	Parts	Quantity
- Transition Prep Charge		<b>2.00</b>			
	<b>Parts Charge: 0.00</b>	<b>Labor Charge: 0.00</b>			

Total Parts Charges:	<b>9,115.32</b>	Total Labor Charges:	<b>10,110.00</b>	Total Comm. Charges:	<b>539.15</b>
----------------------	-----------------	----------------------	------------------	----------------------	---------------