

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 842470

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0		Labor	Parts	
In Date: 08/06/2008	Close Date: 08/06/2008	Hours	Description	Quantity
- Pre-Delivery Inspection		4.00		
	Parts Charge: 0.00	Labor Charge: 240.00		

Workorder: 842788

Problem: INSTALL CUSTOMERS WIRE HARNESS FOR COMPUTER

Meter Reading: 114		Labor	Parts	
In Date: 08/13/2008	Close Date: 08/14/2008	Hours	Description	Quantity
- Fabricate And Install Wiring Harness For Computer Stand.		1.50	SHOP SUPPLIES	1.00
- Shop Supplies				
	Parts Charge: 2.00	Labor Charge: 90.00		

Workorder: 933255

Problem: P.M SERVICE,RECALL #08B07

Meter Reading: 5953		Labor	Parts	
In Date: 01/28/2009	Close Date: 02/06/2009	Hours	Description	Quantity
- Pm Service		9.00	15/40 OIL	15.00
- Right Alley Lamp Inop.Disassemble Light Bar To Diag			CS10263 FUEL FILTER (USE CS10263A)	1.00
Circuit.Repl Bulb,Pins Broken.Reassemble.Repair Ground			SHOP SUPPLIES	1.00
For Tag Lamp.			7312 OIL FILTERFRM CH9549 WIX 57312	1.00
- Rotate & Hi Speed Balance 6 Tires.Fill W/Nitrogen.			17189E BULB (MR11/12V 35)	1.00
- To/Fr Dealer For Recall #08B07				
- Shop Supplies				
	Parts Charge: 133.51	Labor Charge: 480.00		

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 943535

Problem: P.M service

Meter Reading: 14342		Labor		Parts	
In Date: 09/22/2009	Close Date: 09/30/2009	Hours	Description		Quantity
- P.M. Service.		7.00	TIRE DISPOSAL FEE		2.00
- Replace Spot Light Bulb In R/S Of Light Bar.			17189E BULB (MR11/12V 35)		1.00
- Replace Three Tires.Balnce And Nitro Fill All Six Tires.			SHOP SUPPLIES		1.00
- Shop Supplies			179636492 LT245/75R17 WRANGLER SR-A E		2.00
			LT245/75R17 TIRE		1.00
			15/40 OIL		15.00
			CS10263 FUEL FILTER (USE CS10263A)		1.00
			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
Parts Charge:		711.44	Labor Charge:	420.00	

Workorder: 943913

Problem: Floor mat torn and hydro booster leaking.

Meter Reading: 14342		Labor		Parts	
In Date: 09/30/2009	Close Date: 10/15/2009	Hours	Description		Quantity
- Remove Radios, Comp Stand & Misc Cab Items For		3.50	SHOP SUPPLIES		1.00
Dealer To Replace Floor Mat.			FLOOR MATS(SET)		1.00
- To/From Dealer For Warrenty Floor Mat & Hydro Booster.					
- Shop Supplies					
Parts Charge:		61.99	Labor Charge:	150.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1003706

Problem: Pm service also see notes on raising hitch ball

Meter Reading: 20686		Labor		Parts	
In Date: 04/09/2010	Close Date: 04/20/2010	Hours	Description		Quantity
- P.M Service.		6.00	31-20 WIPER BLADES 20" BLADE		2.00
- Mount Balance & Nitro Fill Two New Tires.			RT SIDE STEP / AC3Z16450AA		1.00
- Replace Damaged Right Side Step Rail.			TIRE DISPOSAL FEE		3.00
- Shop Supplies			179636492 LT245/75R17 WRANGLER SR-A E		3.00
			18410 PINTLE PIN		1.00
			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			15/40 OIL		15.00
			CS10263 FUEL FILTER (USE CS10263A)		1.00
			SHOP SUPPLIES		1.00
Parts Charge:		997.60	Labor Charge:	360.00	

Workorder: 1009344

Problem: P.M. service and canceiver.

Meter Reading: 25746		Labor		Parts	
In Date: 08/27/2010	Close Date: 09/09/2010	Hours	Description		Quantity
- P.M. Service.		9.00	FXAM1 LIGHT SOCKET ASSY (WHELEN)		1.00
- A/C Blower Not Working On All Speeds.Check Resistor.Replace Defective Blower Resistor.			26330 TAG LIGHT (TKR LITE)		1.00
			15/40 OIL		15.00
- Batteries Low On Charge.Recharge Both Batteries And Retest,Fail Load Test.Replace Both Batteries.			7312 OIL FILTERFRM CH9549 WIX 57312		1.00
			USED FIREX REFURBED FIRE EXTINGSHERS		1.00
- Replace Tag Lamp Assemble.Diassemble Light Bar And Replace Both Alley Lamps.			66997 COMBO VISE (RIGID F-60)		1.00
			GROUP 65 BATTERY (MTC BXT-65-850)		2.00
- Replace Broken Vise.			A/C BLOWER RESISTOR		1.00
- Shop Supplies			SHOP SUPPLIES		1.00
			CA10270 AIR FILTER MTC FA1886 WIX 49886		1.00
			31-20 WIPER BLADES 20" BLADE		2.00
			17189E BULB (MR11/12V 35)		1.00
			CS10263 FUEL FILTER (USE CS10263A)		1.00
Parts Charge:		906.54	Labor Charge:	540.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1009740

Problem: flash canceiver-spot # 228

Meter Reading: 25706	Labor	Parts		
In Date: 09/03/2010	Hours	Description	Quantity	
- Flash Canceiver	1.00	SHOP SUPPLIES	1.00	
- Shop Supplies				
Parts Charge: 2.00		Labor Charge: 60.00		

Workorder: 1013905

Problem: Pm service also see notes on tali gate and fuel cap problem.

Meter Reading: 31021	Labor	Parts		
In Date: 12/17/2010	Hours	Description	Quantity	
- P.M. Service.	7.00	LIGHT BAR LAMP BULB	1.00	
- Replace Tag Lamp Bulb And One Bulb In Light Bar.		SHOP SUPPLIES	1.00	
- Replace Cigar Lighter Fuse.		15319476 FUSE 20 AMP GMC	1.00	
- Rotate And Balance All Six Tires.		FUEL CAP GREEN	1.00	
- Adjust Tailgate Latch.		CS10263 FUEL FILTER (USE CS10263A)	1.00	
- Shop Supplies		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
		15/40 OIL	15.00	
		FUEL CAP GREEN	1.00	
Parts Charge: 146.56		Labor Charge: 420.00		

Workorder: 1103886

Problem: R/R/O FLAT TIRE

Meter Reading: 34789	Labor	Parts		
In Date: 03/30/2011	Hours	Description	Quantity	
- Intersection Of Sem Pratt And Sycamore				
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 172.58	

Workorder: 1103890

Problem: service

Meter Reading: 34789	Labor	Parts		
In Date: 04/06/2011	Hours	Description	Quantity	
- Seminole Pratt And Sycamore				
Parts Charge: 0.00		Labor Charge: 0.00	Commercial Charge: 54.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1105916

Problem: Pm service.

Meter Reading: 37141		Labor		Parts	
In Date: 06/03/2011	Close Date: 06/15/2011	Hours	Description	Quantity	
-	Perform Pm Service.	12.25	15/40 OIL	15.00	
-	Test And Replace Failed Right Front Marker Lamp Bulb With New.		7312 OIL FILTERFRM CH9549 WIX 57312	1.00	
			PM-22-A ADDITIVE DIESEL FUEL (M/CRAFT)	1.00	
-	Diagnose For Loud Noise On Acceleration.Inspect And Replace Failed Serpentine Belt Idler Pulley Assembly With New.		L0135-063 LUBRIPLATE CHAIN&CABLE LUBE,03050CRC	1.00	
			WD40 SPRAY LUBE STOCK# 405540002	1.00	
			TIRE DISPOSAL FEE	1.00	
-	Install One New Tire To Right Rear Wheel..Nitrogen Fill And Balance All Six.		179636492 LT245/75R17 WRANGLER SR-A E	1.00	
			19006Y MARKER LIGHT 4" RECT YELLOW LED	1.00	
-	Pressure Test And Inspect Cooling System.Replace Failed Upper Radiator Hose Assembly With New.Reverse Flush And Renew Coolant.		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)	2.00	
			CS10263 FUEL FILTER (USE CS10263A)	1.00	
-	Shop Supplies		SHOP SUPPLIES	1.00	
			UPPER RADIATOR HOSE	1.00	
			IDLER PULLEY	1.00	
Parts Charge:		437.98	Labor Charge:	735.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1112956

Problem: Pm service.Serpentine belt,wiper blades and switch.Request for detail vehicle.

Meter Reading: 45582		Labor		Parts	
In Date: 12/08/2011	Close Date: 01/03/2012	Hours	Description		Quantity
-	P.M. Service.	22.75	7312 OIL FILTERFRM CH9549 WIX 57312		1.00
-	Prssure Test Cooling System,Coolant Leak At Lower		USED FIREX REFURBED FIRE EXTINGSHERS		1.00
-	Radiator Hoses.Drain System And Replace Both Lower		31-20 WIPER BLADES 20" BLADE		2.00
-	Hoses.Flush And Refill System.		15/40 OIL		15.00
-	Both Batteries Leaking Acid From Caps,Also Failed Load		TENSIONER		1.00
-	Test.Replace Both Defective Batteries And Test Charging		ANTIFREEZE EXT/LIFE ALL MAKES (PEAK 407)		1.00
-	System.		TIRE DISPOSAL FEE		4.00
-	Wipers Does Not Function Sometimes,Perform Pinpoint		17189E BULB (MR11/12V 35)		1.00
-	Test On Wiper Switch.Replace Defective Multi-Function		3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
-	Switch.Replace Alley Light Bulbs In Lightbar.		LOWER RADIATOR HOSE		1.00
-	Replace Leaking Power Steering Pump,Flush And Bleed		GROUP 65 BATTERY (MTC BXT-65-850)		2.00
-	System.Replace Front Suspension Bump Stoppers.		17189E BULB (MR11/12V 35)		1.00
-	Replace Four Tires,Rotate And Balance All Six.		26330 TAG LIGHT (TKR LITE)		1.00
-	Replace Broken Belt Tensioner And Serpentine Belt.		05074 SILICONE SPRAY		1.00
-	Shop Supplies		FAN BELT		1.00
			POWER STEERING PUMP		1.00
			179636492 LT245/75R17 WRANGLER SR-A E		4.00
			SHOP SUPPLIES		1.00
			FRONT JOUNCE BUMPER STOPS		2.00
			TUBE ELBOW BAND CLAMP COOLER		1.00
			LOWER RADIATOR HOSE		1.00
			SYN/ATF TRANS FLUID SYNTHETIC		2.00
			MULTIFUNCTION SWITCH		1.00
Parts Charge:		1,687.81	Labor Charge:	1,365.00	

Workorder: 1112966

Problem: Power Steering and brakes not working

Meter Reading: 45184		Labor		Parts	
In Date: 12/08/2011	Close Date: 12/08/2011	Hours	Description		Quantity
-	Tow From: Lake Worth Rd And Turnpike To: Lv Shop				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 134.77

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1113422

Problem: 1 - Detail Vehicle Wash Ticket(s) Issued

Meter Reading: 45184		Labor		Parts	
In Date: 12/27/2011	Close Date: 12/27/2011	Hours	Description	Quantity	
- 1 - Detail Vehicle Wash Ticket(S) Issued					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 97.92

Workorder: 1113436

Problem: RF FLAT

Meter Reading: 45184		Labor		Parts	
In Date: 07/29/2011	Close Date: 12/27/2011	Hours	Description	Quantity	
- Tire Service 12500 40 St Loxahat		-			
Rf Flat					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 44.70

Workorder: 1113438

Problem: Tires

Meter Reading: 45184		Labor		Parts	
In Date: 07/29/2011	Close Date: 12/27/2011	Hours	Description	Quantity	
- Tire Service 12500 40Th Street, Loxahatchee					
- Tires					
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 194.98

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1203549

Problem: P.M. service and A/C not cold and check engine light on.

Meter Reading: 50839		Labor		Parts	
In Date: 04/16/2012	Close Date: 06/11/2012	Hours	Description		Quantity
-	P.M. Service.	21.25	R134A REFRIGERANT		2.00
-	Replace Missing Pintle Pin.		D3TZ2457B BRAKE PEDAL PAD		1.00
-	Replace One Tire,Rotate And Balance All Six.		ORIFICE		1.00
-	Check A/C System,Not Cold.Charge And Leak Test		E8 A/C OIL R134A A/C OIL (TSI)		1.00
	System,Leaking Evaporator.R&R Dash Assemble And		7312 OIL FILTERFRM CH9549 WIX 57312		1.00
	Replace Evaporator,Orfice Tube And		18410 PINTLE PIN		1.00
	Accumulator.Evacuate And Recharge System.		A/C EVAPORATOR CORE		1.00
-	Repair Ground Wire To Center Brake Light.Replace One		3963 FUEL FILTER FRM CS10263A WIX 33963		1.00
	Marker Light Bulb And Dome Light Bulb.		TIRE DISPOSAL FEE		1.00
-	Transport Vehicle To Dealer For Check Engine		31-20 WIPER BLADES 20" BLADE		2.00
	Light,P0088,High Pressure Fuel Pump.		SHOP SUPPLIES		1.00
-	Shop Supplies		179636492 LT245/75R17 WRANGLER SR-A E		1.00
			15/40 OIL		15.00
Parts Charge:		548.90	Labor Charge:	1,275.00	

Workorder: 1206055

Problem: All power point fuses open.

Meter Reading: 51869		Labor		Parts	
In Date: 06/27/2012	Close Date: 06/28/2012	Hours	Description		Quantity
-	Test For Short Circuit.Faulty 18 Volt Dewalt Charger.Test	1.00	SHOP SUPPLIES		1.00
	And Replace Three Open 20 Amp Circuit Breakers For		15319476 FUSE 20 AMP GMC		3.00
	Power Outlets And Cigarette Lighter With New.				
-	Shop Supplies				
Parts Charge:		14.56	Labor Charge:	60.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1210110

Problem: P.M. service and mount water tank on right rear rack.

Meter Reading: 56427		Labor		Parts	
In Date: 10/22/2012	Close Date: 12/03/2012	Hours	Description		Quantity
-	Perform Pm Service.	10.55	exhaust sensor		3.00
-	Install One New Tire To The Left Front Wheel.Nitrogen Fill		STEERING WHEEL COVER		1.00
	And Balance All Six.		Turn signal switch		1.00
-	Computer Diagnose For Check Engine Light On.Test And		CH9549 OIL FILTER MTC		1.00
	Replace Three Failed Exhaust Temperature Sensors With		CA10270 AIR FILTER MT		1.00
	New.Clear Codes With Scan Tool And Road Test.		SHOP SUPPLIES		1.00
-	Fabricate And Install New Steering Wheel Cover With		15-40 OIL		15.00
	Heat Gun To Protect Steering Wheel.		OIL FILTER		1.00
-	Inspect And Repair Failed Marker Lamp Harness With		FUEL FILTER		1.00
	New Connector.		179636492 LT245-75R17		1.00
-	Shop Supplies		USED FIREX REFURBED F		1.00
Parts Charge:		661.47	Labor Charge:	633.00	

Workorder: 1211306

Problem: mount water tank

Meter Reading: 56426		Labor		Parts	
In Date: 11/21/2012	Close Date: 12/04/2012	Hours	Description		Quantity
-	Mount Water Tank To Utility Body	2.50	SHOP SUPPLIES		1.00
-	Shop Supplies		RATCHET TIE DOWN		1.00
			1/4X2X4X20 ALUM ANGLE 6063		10.00
			1/2X6X12 ALUM FLAT BAR		10.00
Parts Charge:		178.60	Labor Charge:	150.00	

Workorder: 1301525

Problem: Right front going flat.

Meter Reading: 60974		Labor		Parts	
In Date: 02/12/2013	Close Date: 02/20/2013	Hours	Description		Quantity
-	Repair And Balance Right Front Tire.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies				
Parts Charge:		2.00	Labor Charge:	60.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1302082

Problem: Pm service.

Meter Reading: 61731		Labor		Parts	Quantity
In Date: 02/28/2013	Close Date: 03/12/2013	Hours	Description		
-	P.M. Service.	8.00	SHOP SUPPLIES		1.00
-	Replace Left Alley Light On Lightbar.		15-40 OIL		15.00
-	Pressure Test And Inspect Cooling System.Retorque		NAPAGOLD OIL FILTER		1.00
	Hose Clamps.Flush And Refill Cooling System.		FUEL FILTER		1.00
-	Rotate And Balance All Six Tires.		17189E BULB MR11-12V		1.00
-	Shop Supplies		31-20 WIPER BLADES 20		2.00
			VC7B COOLANT MOTORCRA		2.00
			46-0763846-13 SOCKET		1.00
Parts Charge:		182.16	Labor Charge:	480.00	

Workorder: 1302629

Problem: Left front tire has sidewall damage.

Meter Reading: 62521		Labor		Parts	Quantity
In Date: 03/18/2013	Close Date: 03/21/2013	Hours	Description		
-	Replace And Balance Left Front Tire.	1.00	SHOP SUPPLIES		1.00
-	Shop Supplies		TIRE DISPOSAL FEE		1.00
			179636492 LT245-75R17		1.00
Parts Charge:		247.03	Labor Charge:	60.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1307084

Problem: Pm service.Driver window,Ac and light bar inop.

Meter Reading: 66824		Labor	Parts	
In Date: 07/16/2013	Close Date: 08/06/2013	Hours	Description	Quantity
-	P.M Service.	14.00	15-40 OIL	15.00
-	Resurface Rear Brake Rotors,Replace Rear Pads.Service		NAPAGOLD OIL FILTER	1.00
	And Lube Calipers.Flush And Bleed System And Test		NAPAGOLD FUEL FILTER	1.00
	Drive.		31-20 WIPER BLADES 20	2.00
-	Replace Driver Window Run.Replace Broken Cup Holder.		USED FIRE X REFURBISHED	1.00
-	Test And Replace Inop Lightbar Control Box.Replace		BRAKE PADS	1.00
	Work Lamp Bulb In Light Bar.		BRAKE CLEANER	2.00
-	Rotate And Balance All Six Tires.		PCC6RFL SWITCH BOX WH	1.00
-	Shop Supplies		HOLDER	1.00
			SHOP SUPPLIES	1.00
			LAMP	1.00
			LF WINDOW TRUCK RUN	1.00
Parts Charge:		728.32	Labor Charge:	840.00

Workorder: 1307847

Problem: 1 - Wash ticket(s) issued

Meter Reading: 66526		Labor		Parts	Quantity
In Date: 08/06/2013	Close Date: 08/06/2013	Hours	Description		
-	1 - Wash Ticket(S) Issued				
Parts Charge:		0.00	Labor Charge:	0.00	Commercial Charge: 9.73

Workorder: 1310479

Problem: Towed in for no crank.

Meter Reading: 66885		Labor		Parts	Quantity
In Date: 10/17/2013	Close Date: 10/30/2013	Hours	Description		
-	Test Batteries.Replace Bad Batteries And Test Charging	3.50	weatherstrip		1.00
-	System,Good.		SPACER		1.00
-	Repair Circuit To Light Bar.Install New Fuse Holder.R&R		SHOP SUPPLIES		1.00
-	Left Door Panel And Repair Inner Window Belt Moulding.		BATTERY		2.00
-	Shop Supplies		FUSE HOLDER		1.00
Parts Charge:		294.35	Labor Charge:	210.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1310485

Problem: no start

Meter Reading: 66836	Labor	Parts
In Date: 10/17/2013	Hours	Description
Close Date: 10/18/2013		Quantity
- Tow From: 8100 Forest Hill Blvd To: Lv Shop		
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 134.77

Workorder: 1403107

Problem: P.m. service and light bar inop and A/C blows warm and left front window off track.

Meter Reading: 68554	Labor	Parts
In Date: 03/31/2014	Hours	Description
Close Date: 04/15/2014		Quantity
- Perform Pm Service.	17.00	FUSE HOLDER 1.00
- Diagnose Light Bar Inop. And Replace Failed Fusable Link		E8 A/C OIL UNIV W DYE 1.00
And Holder With New.Test And Replace Failed Rear Led		LED SUP MDL 44 42 DIO 1.00
Lamp With New.Test And Replace Failed Amber Marker		LINE ASY 1.00
Lamp On Body With New.		TR416 VALVE STEM 2.00
- Remove Driver Door Trim.Inspect And Replace Failed		R134A LV SHOP 1 2.00
Window Regulator Assembly With New.Inspect And		REGULATOR 1.00
Replace Both Failed Windshield Washer Nozzles With		SEAL 2.00
New.Install New Front Gas Tank Cap.		A/C HOSE 1.00
- Ac Performance And Leak Test.Recover Freon.Replace		LED M C LAMP 1.00
Failed Ac Accumulator,Liquid Line And High Pressure		15-40 OIL 15.00
Lines From Condenser To Compressor With New.Vacume		FUEL CAP DIESEL 1.00
And Recharge System To Specs.Then Retest.		FUEL FILTER FORD ONLY 1.00
- Install Two New Tires To The Front Wheels.Nitrogen Fill		NAPAGOLD AIR FILTER 1.00
And Balance All Six.		TIRE DISPOSAL FEE 2.00
- Perform Wheel Alignment Complete.		WIPER BLADE 2.00
- Shop Supplies		SHOP SUPPLIES 1.00
		179636492 LT245-75R17 2.00
		NAPAGOLD OIL FILTER 1.00
		ORIFICE TUBE 10.00
		ACCUMULATOR 1.00
		WASHER NOZZLE 2.00
Parts Charge: 1,277.48	Labor Charge: 1,020.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management
Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1407769

Problem: Install ladder

Meter Reading: 70757	Labor	Parts	
In Date: 08/06/2014	Hours	Description	Quantity
- Mount Ladder Rack On Left Rear Side Of Truck.	5.00	SHOP SUPPLIES	1.00
- Inspect And Replace Ac Blower Resistor.		LADDER RACK	1.00
- Shop Supplies		BLOWER MOTOR RESISTOR	1.00
Parts Charge:	631.91	Labor Charge:	300.00

Workorder: 1408254

Problem: Install Air Compressor

Meter Reading: 70748	Labor	Parts	
In Date: 08/20/2014	Hours	Description	Quantity
- Prep And Installed Compressor	3.50	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	210.00

Workorder: 1411010

Problem: P.M. Service.

Meter Reading: 71321	Labor	Parts	
In Date: 11/03/2014	Hours	Description	Quantity
- Pm Service.	6.00	15-40 OIL	15.00
- Test And Replace Defective Clearance Lamp Bulb On Cab		FUEL FILTER FORD ONLY	1.00
Roof.		SHOP SUPPLIES	1.00
- Rotate And Balance All Six Tires.		WIPER BLADE	2.00
- Shop Supplies		BULB	1.00
		8C3Z9A343A SEAL KIT	1.00
		NAPAGOLD OIL FILTER	1.00
		USED FIRE X REFURBISHED	1.00
Parts Charge:	216.64	Labor Charge:	360.00

Workorder: 1500335

Problem: One fuel cap missing.

Meter Reading: 71379	Labor	Parts	
In Date: 01/09/2015	Hours	Description	Quantity
- Replace Missing Fuel Cap And Secure.	0.25	FUEL CAP	1.00
Parts Charge:	20.04	Labor Charge:	15.00

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1502141

Problem: Driver window inop.Wiper blades.

Meter Reading: 71952		Labor		Parts	Quantity
In Date: 02/27/2015	Close Date: 03/09/2015	Hours	Description		
- Remove Driver Door Trim To Inspect And Adjust Window Runner And Regulator To Secure Glass.Replace Both Front Wiper Blades.		1.00	WIPER BLADE		2.00
- Shop Supplies			SHOP SUPPLIES		1.00
Parts Charge:		11.00	Labor Charge:	60.00	

Workorder: 1502363

Problem: wont fuel

Meter Reading: 71952		Labor		Parts	Quantity
In Date: 03/05/2015	Close Date: 03/06/2015	Hours	Description		
- Test And Remove Canceiver Issue Fuel Card		1.00	SHOP SUPPLIES		1.00
- Shop Supplies					
Parts Charge:		2.00	Labor Charge:	60.00	

Workorder: 1504522

Problem: Pm service.

Meter Reading: 72065		Labor		Parts	Quantity
In Date: 05/04/2015	Close Date: 05/12/2015	Hours	Description		
- Pm Service.		9.00	NAPAGOLD OIL FILTER		1.00
- Replace Broken Hitch Pintle Pin And Chain.			15-40 OIL		15.00
- Replace Two Tires.Rotate And Balance All Six.			WASHER FLUID CONCENTR		1.00
- Replace Two Defective Front Frame Rail To Radiator			WIPER BLADE		2.00
Support Body Mount/Insulators.			FUEL FILTER FORD ONLY		1.00
- Shop Supplies			BULB		1.00
			TR416 VALVE STEM		2.00
			TIRE DISPOSAL FEE		2.00
			SHOP SUPPLIES		1.00
			179636492 LT245-75R17		2.00
			PINTLE PIN W/CHAIN		1.00
			BODY MOUNT KIT		2.00
Parts Charge:		820.36	Labor Charge:	540.00	

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1511738

Problem: Pm service.Ac not cold.

Meter Reading: 72911		Labor		Parts	
In Date: 11/17/2015	Close Date: 11/24/2015	Hours	Description		Quantity
- Pm Service.		10.00	WIPER BLADE		2.00
- Ac Performance Test.Install Gauges.Check Low			WASHER FLUID CONCENTR		1.00
Pressure..Partial Charge And Test For Leaks.Evacuate			MAC WITE LITHIUM GRES		1.00
System.Replace Defective Orifice Tube And			ACCUMULATOR		1.00
Accumulator.Replace Manifold Line Gaskets To			TUBE FILTER		1.00
Compressor.Vacu			SEAL		2.00
- Rotate And Balance All Six Wheels.			SEAL KITS		1.00
- Shop Supplies			R134A LV SHOP 1		2.00
			NAPAGOLD OIL FILTER		1.00
			15-40 OIL		15.00
			FUEL FILTER FORD ONLY		1.00
			SHOP SUPPLIES		1.00
Parts Charge: 381.00		Labor Charge: 600.00			

Workorder: 1605284

Problem: P.M. Service.Fuel switch on dash is loose.

Meter Reading: 73992		Labor		Parts	
In Date: 05/23/2016	Close Date: 06/09/2016	Hours	Description		Quantity
- P.M. Service.		15.00	FUEL FILTER FORD ONLY		1.00
- Test Batteries And Charging System.Replace Both Bad			NAPAGOLD OIL FILTER		1.00
Batteries.			LAMP		1.00
- Replace One Signal Lamp Bulb,One Tag Lamp And Inop			20" WIPER BLADE		2.00
Strobe Light Bulb.Replace Broken Fuel Tank Switch.			BATTERY		2.00
- Replace Four Rear Body To Frame Mounts And Left Rear			SHOP SUPPLIES		1.00
Bounce Stop.			BODY MOUNT KIT		4.00
- Rotate And Balance All Tires.			15-40 OIL		15.00
- Shop Supplies			BULB		1.00
			LED M C LAMP		1.00
			BEZEL		1.00
			USED FIRE X REFURBISHED		1.00
			BUMPER		1.00
			LAMP KIT		1.00
Parts Charge: 1,080.16		Labor Charge: 900.00			

1/3/2017
12:34:13PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10174459 2008 FORD F350 Utility Body, 1 Ton

Workorder: 1611067

Problem: Transition Prep Charge

Meter Reading: 76056

Labor

Parts

In Date: 10/26/2016

Close Date: 10/26/2016

Hours

Description

Quantity

- Transition Prep Charge

2.00

Parts Charge: 0.00

Labor Charge: 0.00

Total Parts Charges: 12,387.41

Total Labor Charges: 12,693.00

Total Comm. Charges: 843.45