



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V547

In Date: 11/14/2005
Close Date: 11/15/2005

Meter Reading: 42,191.00

Problem?
HEADLIGHT OUT R15

Task performed:

Parts	Quantity
H6054USE CV TYPE SEALED BEAM	6

Workorder: V855

In Date: 12/08/2005
Close Date: 12/12/2005

Meter Reading:

Problem?
BATTERY ON/OFF SWITCH HEATS UP R-15

Task performed:

Parts	Quantity
51-30219-1045 MASTER SWITCH 175 AMP	1

Workorder: V673

In Date: 11/23/2005
Close Date: 12/19/2005

Meter Reading:

Problem?
WINDSHIELD WASHER RESERVOIR LEAKING R-15

Task performed:

Parts	Quantity
22-40867-000RESERVOIR	1
A2254926000WASHER PUMP W/GROMMET	1

Workorder: V1502

In Date: 02/14/2006
Close Date: 03/02/2006

Meter Reading:

Problem?
INSIDE DOOR HANDLE INOP, L/SIDE HEADLIGHT INOP, R-15

Task performed:

Parts	Quantity
NO PARTS USED	



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V1642

In Date: 02/27/2006

Meter Reading:

Close Date: 03/27/2006

Problem?

BIO-HAZARD DOOR BROKEN, R-15

Task performed:

Parts

Quantity

DOOR1LEXAN 15 X 9 MEDIC MASTER F

1

DOOR2LEXAN 14.5 X 8.5

2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2177

In Date: 04/10/2006

Meter Reading:

Close Date: 04/19/2006

Problem?

B INSPECTION R-15

Task performed:

See B Inspection pre-printed form

<u>Parts</u>	<u>Quantity</u>
0106837849C8COMP LIGHT WHITE LED 200	1
032-0116549297 BATTERY INDICATOR	1
071601A07-0602A DRIER A/C 7118	1
161657700065489 SHOCK REAR NEW RESCUE	2
194BULB	2
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
91513AMBER LENS	2
9451BELT	1
9485BELT	1
A0631087000CABLE BATT. POS.	1
A0631088000CABLE BATT. NEG.	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
CA8193AIR FILTER 46744 WIX	1
EXO3AH00015SPLUG RAD. DRAIN	1
HLD374211 IN HOLD-OPEN 30LB	1
HP-31DBATTERY 950CCA HP-31D	4
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V2236

In Date: 04/17/2006

Meter Reading:

Close Date: 04/24/2006

Problem?

FIRE EXTINGUISHER BRACKET IN CAB BROKEN, R-15

Task performed:

Parts

Quantity

818818 BRACKET EXTINGUISHER

1

Workorder: V2309

In Date: 04/20/2006

Meter Reading:

Close Date: 04/28/2006

Problem?

R/REAR BACK LIGHTS INOP, R-15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V3652

In Date: 07/26/2006

Meter Reading:

Close Date: 08/04/2006

Problem?

Moving piece of rear bumper broken off. R15

Task performed:

Parts

Quantity

68118313250OBSOLETE REPLACE UNIT LENS RED 97 E S

2

W000349RUNNING BOARD

1

Workorder: V3788

In Date: 08/04/2006

Meter Reading:

Close Date: 08/08/2006

Problem?

2 LIGHTS OUT IN ROOF OF THE BACK OF RESCUE ALSO THE FAN BELT IS SQUEALING R15

Task performed:

Parts

Quantity

322502BULB PATIENT GH22

3

H27SN12BULB

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V3789

In Date: 08/04/2006

Meter Reading:

Close Date: 08/11/2006

Problem?

LATCH ON DRAWER IN BACK OF RESCUE IS BROKEN AND THE STAY CLOSED R15

Task performed:

Parts

Quantity

LTC5993SSM1-63-8 LATCH STAINLESS

1

Workorder: V3973

In Date: 08/17/2006

Meter Reading:

Close Date: 08/21/2006

Problem?

SEARCH LIGHT ON ROOF OF CAB DOES NOT ROTATE. R15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V4068

In Date: 08/22/2006

Meter Reading:

Close Date: 08/25/2006

Problem?

the belt is still squeeking R15

Task performed:

Parts

Quantity

39437933943793 LINK ADJ A/C COMP

1

3945207BOLT ADJ A/C COMP

1

Workorder: V4234

In Date: 09/04/2006

Meter Reading: 40,310.00

Close Date: 09/07/2006

Problem?

HOSE ON AIR COMPRESSOR BROKEN, R-15

Task performed:

Parts

Quantity

3944427INTAKE HOSE NEW #3949710

2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V4370

In Date: 09/11/2006
Close Date: 09/21/2006

Meter Reading: 40,310.00

Problem?

REPAIR A/C SR3 AT 14

Task performed:

1. WENT TO STN 15 TO INSTALL A/C CLUTCH. A/C CLUTCH INSTALLED A/C OPERATING PROPERLY.
2. REAR COMPARTMENT DOOR HANDLE WILL NOT SHUT. DOOR HANDLE REPLACED.

Parts

Quantity

279LSS1250D-RING HANDLE W/LOCK 101280008

1

Workorder: V4554

In Date: 09/22/2006
Close Date: 10/03/2006

Meter Reading:

Problem?

Red emer. light cover off, and bulb is cracked. Wire waste container bracket inside rear door broke at weld. Plastic door over wast bin on bench seat broken.

Task performed:

1. TRAVELED TO STN 15 FOUND LIGHT COVER OFF AND BULB CRACKED. REPLACE BULB, REATTACH COVER.

Parts

Quantity

68118313250OBSOLETE REPLACE UNIT LENS RED 97 E S

1

TURBO5TUBE - STROBE

1

Workorder: V4675

In Date: 10/02/2006
Close Date: 10/12/2006

Meter Reading:

Problem?

Change driver side head light no spares in the station. BATT 1 SPARE AT 15

Task performed:

1. TRAVLED TO STN 15. GIVE HEAD LIGHTS TO DRIVER.

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

3

Workorder: V5571

In Date: 11/28/2006
Close Date: 11/29/2006

Meter Reading: 52,518.00

Problem?

ON CALL CHARGING SYSTEM 10-7 R15

Task performed:

1. repair wiring on charging system

Parts

Quantity

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6314

In Date: 01/17/2007

Meter Reading: 53,792.00

Close Date: 01/23/2007

Problem?

B Inspection and all needed repairs R15

Task performed:

1. PERFORM PM- B.
2. REMOVE BOTH FRT SEATS FOR REPAIR.
3. R/R OIL PAN TO REPLACE LEAKY GASKET.
4. REPLACE LEFT REAR MUD FLAP.
5. REPLACE COVER FOR 110V A/C OUTLET.
6. REPLACED WIPER BLADES.
7. REPLACED RIGHT FRT. T/S SIDE MAKER LENS.
8. REMOUNT O2 WRENCH INSIDE COMPARTMENT.
9. REPLACED BEZEL ON BOTH PT COMPARTMENT ENTRY DOORS.
10. REPLACE LEFT REAR COMP DOOR HOLD OPEN
11. REPLACED BOTH CAB DOOR TRIMS.
12. REPLACED DRIVER DOOR WEATER STRIP.
13. INSTALL MISSING AIR HORN MOUNTING BRACKET FOR RIGHT AIR HORN.
14. REPLACE SHOCKS ON SQUAD BENCH.
15. REPLACE SHOCKS ON A/C DOOR IN PT COMP.
16. REPLACED 2 HIGH BEAM BULBS IN PT. COMP.
17. ADJUSTED IR BAG TO LEVEL REAR OF TRUCK.
18. REPAIR BIO DOOR IN PT COMP AND INSTALL NEW HANDEL.
19. REPLACE 6 TIRES.
20. REPLACE BELTS.

Parts

Quantity

091-3YWCOVER KUSSMAUL AUTO EJECT	1
322502BULB PATIENT GH22	2
3920773WASHER DRAIN PLUG	1
3959052PAN GASKET B ENGINE	1
52-24WIPER BLADES ANCO 24	2
6806970098SEAL DOOR	1
91513AMBER LENS	1
9451BELT	1
9485BELT	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
B2420LP-SMUD FLAP 24 X 24	1
CA8193AIR FILTER 46744 WIX	1
GRV1720244770R1 HORN SUPPORT BRKT	1
HLD374211 IN HOLD-OPEN 30LB	1
HLD3999GSS1715UV 30LB STRUT GAS	4
HND5941USE HAN-1L METAL LATCH INTERIOR LOCKING	2
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
S3225PFUEL FILTER 33630 LFF5849	1
SWT1277EL57755 SWITCH DOOR 2PCS	1
UNT7744USE PINK A/C FILTER MEDIC MASTER	1

Workorder: V6320

In Date: 01/17/2007

Meter Reading: 53,792.00

Close Date: 01/23/2007

Problem?

repair seats central auto trim r15

Task performed:

1. SENT UNIT FOR SEAT REPAIRS TO CENTRAL AUTO.

Parts

Quantity

NO PARTS USED

Vendor? CENTRAL AUTO TRIM C



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6257

In Date: 01/12/2007

Meter Reading: 4,251.00

Close Date: 01/24/2007

Problem?

A/C in cab of R15 not working

Task performed:

Parts

Quantity

6805450828PLUG A/C BLR

1

ABPN8332229011-3050 SWITCH BLOWER

2

Workorder: V6321

In Date: 01/17/2007

Meter Reading: 53,792.00

Close Date: 01/30/2007

Problem?

replace tires at callaghan ent r15

Task performed:

Parts

Quantity

1. UNIT SENT TO CALLAGHAN TIRE FOR 6 NEW TIRES PRICE \$218.32 EACH.

NO PARTS USED

2. 5 FLA STATE NEW TIRE FEE \$ 1.00 EACH X 6.

3. SCRAP TIRE FEE MEDIUM TRUCK TIRE SFM \$7.00 EACH X 6.

4. VALVE STEM MEDIUM TRUCK VSM \$4.00 EACH X 6.

5. DISMOUNT & MOUNT - 245/70R19.5 MTD/R \$18.00 EACH X 6.

6. EQUAL BALANCE MTEQ \$17.50 EACH X 6.

7. TOTAL 1594.92.

Vendor? CALLAGHAN TIRE

Workorder: V6789

In Date: 02/15/2007

Meter Reading: 4,323.00

Close Date: 03/02/2007

Problem?

Latch on rear patient door needs adjustment, door is hard to open and close.R15

Task performed:

Parts

Quantity

Take rear door apart & adjusted rods; test ok

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V6899

In Date: 02/22/2007
Close Date: 03/02/2007

Meter Reading: 4,335.00

Problem?

pastic cover over speedometer stained from foam hand cleaner while cleaning hands. minor stain, you can still see guages. r15

Task performed:

Installed new cover; test ok

Parts

Quantity

2332920005SMASK LENS W/RST BUTTON VDO

1

Workorder: V7588

In Date: 04/09/2007
Close Date: 04/11/2007

Meter Reading: 4,486.40

Problem?

guage broken on main o2, needs replacement. R15

Task performed:

Drive to station. R&R gauge on O2 and test for leak

Parts

Quantity

MG-C23SPMGC23 GAUGE

1

Workorder: V7782

In Date: 04/18/2007
Close Date: 04/23/2007

Meter Reading: 56,946.00

Problem?

CHECK FRONT END R15

Task performed:

Check front end; tow; need to be adjusted. Ed. E will get it done.

Parts

Quantity

5648056480 PLUG-POWER/ACCESS.

1

LTC5993SSM1-63-8 LATCH STAINLESS

3

Workorder: V7834

In Date: 04/20/2007
Close Date: 04/23/2007

Meter Reading: 4,513.00

Problem?

Need 2 drawer pulls for pt compartment; Overhead light in pt comp nearest jump seat - hi beam is out; Engine coolant is low. R15 will stop at shop while returning from El Pex Fri 4-20. Thanks RLt G. Denison

Task performed:

Replaced all (5) drawer pull handles & compt strikers.
Replaced (1) patient compt high beam light bulb.
Pressure check cooling system.

Parts

Quantity

322502BULB PATIENT GH22

1

LTC5993SSM1-63-8 LATCH STAINLESS

5



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V7785

In Date: 04/18/2007
Close Date: 04/30/2007

Meter Reading: 56,946.00

Problem?

front end alignment r15 tiresoles

Task performed:

Elpex - front end alignment/tire balance

Parts

NO PARTS USED

Quantity

Vendor? ELPEX

Workorder: V7926

In Date: 04/25/2007
Close Date: 04/30/2007

Meter Reading: 57,181.00

Problem?

balance front tires

Task performed:

Elpex - alignment & tire balance

Parts

NO PARTS USED

Quantity

Vendor? ELPEX

Workorder: V8066

In Date: 05/03/2007
Close Date: 05/08/2007

Meter Reading: 57,245.00

Problem?

door alarm stays on R15

Task performed:

Replace middle left sendr; test ok.

Parts

SWT7970DOOR MAGNETIC SWITCH

Quantity

1

Workorder: V8210

In Date: 05/11/2007
Close Date: 05/15/2007

Meter Reading: 57,587.00

Problem?

Rear doors hard to open R15

Task performed:

Adjusted rod in rear door; test ok.

Parts

NO PARTS USED

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8340

In Date: 05/21/2007
Close Date: 06/11/2007

Meter Reading: 57,918.00

Problem?

on call door ajar lt on r15

Task performed:

Parts

Quantity

1. Travel to station 15, repair battery switch & bend bracket for clearance, at home. Recheck Q-15 OK re-connect door alarm buzzer

NO PARTS USED

Workorder: V8468

In Date: 05/29/2007
Close Date: 06/11/2007

Meter Reading: 58,199.00

Problem?

repair fuel system cummins se power r15

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? POWER SOUTH

Workorder: V8467

In Date: 05/29/2007
Close Date: 06/13/2007

Meter Reading: 58,199.00

Problem?

tow unit from sta 15 to cummins se power r15

Task performed:

Parts

Quantity

NO PARTS USED

Vendor? SISTERS TOWING

Workorder: V8484

In Date: 05/30/2007
Close Date: 06/13/2007

Meter Reading: 58,199.00

Problem?

R51 BROKE DOWN US 1 AND UNIVERSAL

Task performed:

Parts

Quantity

1. Drive to site, NP44 inop, tow to Sta, will repair at cummins

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V8587

In Date: 06/04/2007
Close Date: 06/20/2007

Meter Reading: 58,199.00

Problem?

repair air leaks

Task performed:

1. Drive to station, R/R parking brake test Ok

Parts

Quantity

276567XVALVE DASH PP1

1

KN20901KN20901 KNOB PARKING BRAK

1

Workorder: V8688

In Date: 06/08/2007
Close Date: 06/26/2007

Meter Reading: 4,615.00

Problem?

voltmeter is intermittently going to the all fail mode R-15

Task performed:

1. Disconnect beacon on truck

Parts

Quantity

NO PARTS USED

Workorder: V8667

In Date: 06/08/2007
Close Date: 07/02/2007

Meter Reading: 4,615.00

Problem?

air leak in vehicle system. Mike Lehan was here on June 5 and replaced emergency brake button but it is still leaking down and needs time to build up on startup. r15

Task performed:

1. Drive to Stn; fix coolant leak head on compressor; sent to shop
2. Chkd air leak on compressor; fnd only leak wire line charged; chk w/Ehrke; advsd ok; rep (2) other air leaks & sent to Stn

Parts

Quantity

EL360081760611 SOLENOID AIR HORN

1

Workorder: V8980

In Date: 06/23/2007
Close Date: 07/03/2007

Meter Reading: 58,751.00

Problem?

A/C is not cold; Light in cab is out. R15

Task performed:

Drive to stn; replc seat belt, lights and A/C low on freon; tighten fitting; all test ok

Parts

Quantity

1156BULB

10



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V9134

In Date: 07/04/2007

Meter Reading: 58,972.00

Close Date: 07/06/2007

Problem?

"Door Open" light remains on constantly. R15

Task performed:

1. Drive to sta, replace batt charge indicator, replace batt open stw hook up light and buzzer for door open test OK

Parts

032-0116549297 BATTERY INDICATOR

M4099BUZZER 52-400

SWT54912SWITCH DOOR LGHT

Quantity

1

1

1

Workorder: V9152

In Date: 07/05/2007

Meter Reading: 4,659.60

Close Date: 07/06/2007

Problem?

R15 Shore line inop.

Task performed:

1. See wo# 9134

Parts

NO PARTS USED

Quantity

Workorder: V9444

In Date: 07/20/2007

Meter Reading:

Close Date: 07/27/2007

Problem?

pt compartment a/c does not work on shore line, also does not cool below 85 while truck is running. r15

Task performed:

Drive to stn; 100 sys low on freon & fan bad; chk oil leak; fnd fitting loose; replc fan; test ok; 12V back sys belts loose & freon low; tighten belt

Parts

60027FAN A/C COND 12IN 860026-2-W

X2232548SWITCH

Quantity

1

1

Drive to stn; master cyl sender inop; replc sender; test ok

Workorder: V9612

In Date: 07/29/2007

Meter Reading:

Close Date: 08/13/2007

Problem?

Please forward 2 headlight sealed bulbs to station 15. we need to replace one and have a spare. Thank you

Task performed:

drive to station r/r head lights. testes ok

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V10124

In Date: 08/25/2007

Meter Reading: 60,051.00

Close Date: 09/05/2007

Problem?

patient compartment A/C needs service, not blowing cold enough intermittently R15

Task performed:

Parts

Quantity

1. Drive to Stn15; chk A/C; fnd 110 AC compressor is leaking & R134 compressor; valve going bad
2. Drove to Stn15 - chk valve
3. R/R (4) bulbs on cab marker light

NO PARTS USED

Workorder: V10551

In Date: 09/19/2007

Meter Reading: 137,258.00

Close Date: 09/24/2007

Problem?

Frame rail repair- grind and weld cracks- install fishplate R15 (Warranty)

Task performed:

Parts

Quantity

- 1 complete feild service campain sf350 frame support plate and weld cracks

25-SF350-000L-SERT REINFORCEMENT

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V10354

In Date: 09/10/2007

Meter Reading: 60,051.00

Close Date: 09/28/2007

Problem?

B INSPECTION AND REPAIRS AS NEEDED R15

Task performed:

1. "B" INSPECTION
2. R/R REAR BRAKES
3. R/R BRAKE BOOSTER, RESEAL MOTOR UNIT
4. R/R AIR BAG VALVES AND ADJUST
5. R/R PLASTIC DOOR MOLDING, REINSTALL DOOR PANEL
6. R/R WHITE C&R STROBE IN FRONT LIGHT BAR, REMOVED ALL LIGHTS FRONT SIDE, REINSTALL
7. CHECK OUT REAR 110 A/C UNIT, CHECK UNIT FOR LEAKS, TOP OFF FREON, CHECK OUT CM-1000 PANEL, FOUND BLOWER MOTOR INOP, CHECK OUT RESISTOR BLOCK, REPLACE, PUT UNIT BACK TOGETHER, RETEST
8. CHECK OUT REAR 134-A UNIT, CHECK FOR LEAKS, FREON O.K. R/R DRYER AND H-BLOCK VAC SYSTEM, RETEST O.K. PUT UNIT BACK TOGETHER.
9. REPAIR GAUGES AND REPLACE BATTERY
10. R/R COMPARTMENT LIGHT REPAIRSTEP LIGHT SOCKET, R/R CAB LIGHT BULB.
11. SERVICE AIR DRYER, R/R UNIT AND REBUILD
12. SERVICE TRANSMISSION AND REAR
13. PULL RADIO, CLEAN OFF GLASS WITH RAZOR BLADE AND BUFF OUT
14. GO TO GRANGER FOR SUPPLIES, ORDER NOT READY GET HALF WILL GO BACK TOMM.
15. R/R AIR SEAT VALVE, REPLACE LINES, R/R WIPPER BLADES, R/R DOOR SHOCKS ON PATIENT COMPARTMENT DOORS, TIGHTEN U-BOLTS, TIGHTEN P/S HOSE.
16. DR. APPT AND PICK-UP PARTS FROM GRANGER.

Parts

Quantity

Parts	Quantity
02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
071601A07-0602A DRIER A/C 7118	1
12-3022A1608 2 1/2 TON VALVE EXPANSION	1
161657700065489 SHOCK REAR NEW RESCUE	2
29526898 29548988 TRANS FILTER ALLISON	1
2FC00ZCR4 IN ROUND LED	1
322502BULB PATIENT GH22	1
52-24WIPER BLADES ANCO 24	2
91823SWITCH SWT5499 MED MASTER	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
ABPN83321070RESISTOR BLOWER	1
ACX-84534LUG NUT COVER PK10	2
ASL-2770932O-RING POWER BOOSTER	4
BOS62221360026222207-001 W AIR SEAT	1
CA8193AIR FILTER 46744 WIX	1
H5010BOLT	1
HLD3999GSS1715UV 30LB STRUT GAS	6
KN33002DRYER-AIR BRAKES SYSTEM	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	1
MTR3030VM-100 VOLT METER	2
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
S4640024430VALVE LEVELIN	2
S775COUPLER	3
S777COUPLING NIPPLE	2
UNT7744USE PINK A/C FILTER MEDIC MASTER	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V11294

In Date: 10/29/2007

Meter Reading: 61,367.00

Close Date: 11/05/2007

Problem?

ON CALL R15 WONT START

Task performed:

Drive to scene where R15 is dead; R/R batteries; cln all connections; dte btrys; chk chrgng voltage-ok

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

4

HP-31DBATTERY 950CCA HP-31D

4

Workorder: V11418

In Date: 11/04/2007

Meter Reading: 4,880.00

Close Date: 11/21/2007

Problem?

NO BLOWER IN FRONT CAB; WENT ON A CALL IN MIDDLE OF THE NIGHT AND DIDN'T HAVE A BLOWER IN THE FRONT CAB; A/C NOT RUNNING R15

Task performed:

drive to strn; R/R A/C swtch; test ok. j

Parts

Quantity

ABPN8332229011-3050 SWITCH BLOWER

1

Workorder: V12037

In Date: 12/12/2007

Meter Reading: 63,004.00

Close Date: 01/02/2008

Problem?

front strobe light and front left light on light bar top of truck 10-7 rescue 15.

Task performed:

1. Travel to 15.
2. Diss. front light bar to gain access to middle rotator and unjam to rotate.

Parts

Quantity

NO PARTS USED

Workorder: V12799

In Date: 01/24/2008

Meter Reading: 6,434.14

Close Date: 01/28/2008

Problem?

repair stretcher r15

Task performed:

repair stretcher - Medco Equimt j

Parts

Quantity

NO PARTS USED

Vendor? MEDCO(EMSAR)



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V12850

In Date: 01/26/2008
Close Date: 01/30/2008

Meter Reading: 6,434.00

Problem?

air leak in or around air horn connection on r 15

Task performed:

Air leak fnd; pin on brake valve stuck & air horn valve leaking; rep park brake valve & replc air horn valve;
J

Parts	Quantity
EL360081760611 SOLENOID AIR HORN	1

Workorder: V12594

In Date: 01/15/2008
Close Date: 02/01/2008

Meter Reading: 5,031.70

Problem?

two ceiling lights in pt compartment not working. r15

Task performed:

1. Drove to Stn15
2. Replc (2) bulbs in pat compt j

Parts	Quantity
322502BULB PATIENT GH22	2
921LIGHT BULB	2

Workorder: V12829

In Date: 01/25/2008
Close Date: 02/05/2008

Meter Reading: 6,434.00

Problem?

MAP LIGHT INOP, O2 LEAK, R-15

Task performed:

1. Drive to Station, installed new map light, found leak in pt coompartent, tighten fitting, test ok

Parts	Quantity
LF18TS-LEDMAP LIGHT LED 18 IN	1

Workorder: V12863

In Date: 01/28/2008
Close Date: 02/06/2008

Meter Reading: 6,434.00

Problem?

AIR LEAKS R15

Task performed:

1. Drive to station, gov leak, r/r gov, still leaks, remove pack, found line leak, repaired, test OK.

Parts	Quantity
284358GOVERNOR D-2	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V13371

In Date: 02/20/2008
Close Date: 02/25/2008

Meter Reading: 5,140.00

Problem?

passenger front headlight out r15

Task performed:

1. Drive to station, installed head light, test OK

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V14147

In Date: 03/28/2008
Close Date: 05/01/2008

Meter Reading: 67,053.00

Problem?

b inspection and repairs as needed r15

Task performed:

1. B Inspection
2. R/R Horn mount on left front
3. R/R High-Low lights in rear
4. R/R Cylinder head, gasket leak
5. Check air leak in truck, tighten lines
6. Check leak in 02 system, line leaking. Retap all lines in panel

Parts

05-17223-000CAP RADIATOR 10 LB
 15W40BSYN OIL BULK QTS
 322502BULB PATIENT GH22
 3286278WATER PUMP ISB
 3905351SEAL GROMMET
 3940386SEAL ISC WATER PUMP
 3963983WASHER SEAL ISB
 4090035HEAD GASKET SET ISB
 9451BELT
 9485BELT
 AS79934ACT AREA LIGHT
 GRV1720244770R1 HORN SUPPORT BRKT
 K080733BELT
 L1261F33585XE FUEL FILTER WIX
 PH8942FILTER OIL 57182 LFP3729
 S1003-A3103015 SEAL
 S3225PFUEL FILTER 33630 LFF5849

Quantity

1
16
1
1
1
1
1
1
1
1
1
1
1
1
1
4
1

Workorder: V16187

In Date: 07/07/2008
Close Date: 07/07/2008

Meter Reading: 70,329.00

Problem?

ON CALL R15 OIL CAP MISSING

Task performed:

1. replaced missing oil cap

Parts

39377593937759 OIL CAP

Quantity

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V15895

In Date: 06/22/2008
Close Date: 07/08/2008

Meter Reading: 5,439.10

Problem?

R-15 Check Engine light went on while we were transporting a pt to the hospital. Our driver pulled over and shut down the truck. After restarting, we have not had the light go on again.

Task performed:

Drive to Stn; 115 code; replc sender for cam; road test ok. j

Parts

40020664921601 SENSOR CRANK POSITION

Quantity

1

Workorder: V15902

In Date: 06/23/2008
Close Date: 07/10/2008

Meter Reading: 5,439.10

Problem?

during rain, water leaks into cab from the overhead amp/volt meter read out. R15

Task performed:

Drive to Stn; seal roof; test w/hose; no leaks. j

Parts

NO PARTS USED

Quantity

Workorder: V16580

In Date: 07/25/2008
Close Date: 08/01/2008

Meter Reading: 5,496.00

Problem?

headlight out r15

Task performed:

1. drive to station. r/r head lite .tested all ok

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1

Workorder: V16787

In Date: 08/03/2008
Close Date: 08/08/2008

Meter Reading: 5,526.00

Problem?

Right front turn signal not working. R-15

Task performed:

R/R bulb - test ok. j

Parts

NO PARTS USED

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V17075

In Date: 08/15/2008

Meter Reading: 5,552.20

Close Date: 08/21/2008

Problem?

parking brake knob loose on dash board. r15

Task performed:

Parts

Quantity

1. drive to station tighten up parking brake test ok

NO PARTS USED

Workorder: V17269

In Date: 08/23/2008

Meter Reading: 71,861.00

Close Date: 09/22/2008

Problem?

right side seam light cover missing.light 10-7.(PASSANGER SIDE) R 15

Task performed:

Parts

Quantity

Drive to Stn; installed lense. test ok. j

68118354250900 SERIES RED LENS

1

Workorder: V18491

In Date: 10/21/2008

Meter Reading: 5,603.60

Close Date: 10/29/2008

Problem?

exterior door handle right side of pt. comp. broken. unable to open door from exterior. not fixable. please replace. r15

Task performed:

Parts

Quantity

Drive to Stn; installed door handle & holdopen; test ok. j

HLD39917DC23-5011 50 # HOLD-OPEN RESCUE

1

HND5948TM22676-02 HANDLE DOOR ENTRY

1

Workorder: V18994

In Date: 11/11/2008

Meter Reading: 74,332.50

Close Date: 11/19/2008

Problem?

Belts squeal; Overhead light in patient compartment is out; Onboard O2 hoseline slow leak between bottle and pt compartment connection. R15

Task performed:

Parts

Quantity

Drive to Stn; adj belts & rep air leak at bottle. j

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19039

In Date: 11/13/2008

Meter Reading: 74,403.00

Close Date: 11/25/2008

Problem?

C INSPECTION AND REPAIRS AS NEEDED R15

Task performed:

Parts

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

C-Inspection.	05-17223-000CAP RADIATOR 10 LB	1
2. Test btrys; cln term/cables; rep brkn wire term; repositioned cables to term post.	15W40BSYN OIL BULK QTS	16
3. Replcd alt belt tensioner.	16-15762-00016-19471-000 AIR BAG	2
4. Dia cab door light inop; fnd bad door swtch.	322502BULB PATIENT GH22	2
5. R/R wheels for tire replacement.	39768315259022 GROOVED TENSIONER OLD#3936213	1
6. Replace frt A/C compressor; drain/add adequate oil; evac/change freon; adj belt tension.	4020362171 GRO LAMP DOME 4 IN	1
7. Svc rear axle.	52-24WIPER BLADES ANCO 24	2
8. Svc P/S.	532703-0602 COMPRESSOR U4735 4471	1
9. Dia no press for window squirters; fnd cracked fitting; replcd fitting & adj nozzles.	58ELTUBE58L4TUBE STROBE/REFLECTOR ASSY. 58E	1
10. Tighten loose rear pat compt latch screws; R-3 striker; R-2 holdopen bolts & L4 pin.	60027FAN A/C COND 12IN 860026-2-W	1
11. C-Inspection; lube door latches/hinges; replcd wiper blades.	91822OBSOLETE USE SERV TKS SWITCH - DOOR	1
12. Replcd L-F grille strobe; drill holes/install.	B2420LP-SMUD FLAP 24 X 24	1
13. Rebuild air dryer & purge valve.	BOS62221360026222207-001 W AIR SEAT	1
14. Replcd missing L-rear mud flap; drill/cut to size.	CA8193AIR FILTER 46744 WIX	1
15. Dia/rep R/F cab door light; no grnd; chk wiring; R/R switch.	HLD3999GSS1715UV 30LB STRUT GAS	2
16. R/R lens; R/R bulbs & high beam pat ceiling lights.	L1261F33585XE FUEL FILTER WIX	1
17. R/R (2) bench seat air lift cyl in pat comp.	MK184HDBRAKE PADS	2
18. R/R compt L-3 door holdopen asy.	P128013T-BOLT AIR FILTER	1
19. Tighten bolts on compt door holdopen R-2.	PH8942FILTER OIL 57182 LFP3729	1
20. R/R compt L-1 light asy.	S3225PFUEL FILTER 33630 LFF5849	1
21. R/R R/Rear top marker light asy.	SPR-W58-1TEE PLASTIC	1
22. Torque rear u-bolts.	V122XRCAN USE 46892-5 MARKER LIGHT	1
23. Replc frt/rear brake pads.	VML-S1414FILTER P/S	1
24. Press chk cooling sys; fnd leak at upper rad hose & heater hose; tightened clamps; fnd bent rad cap; replc cap; protect rad hose in saddle w/rubber mat & tie strap.	VML-T1264GASKET P/S COVER	1
25. Replcd stripped out air cleaner stud.	VML-T1279WASHER P/S	1
26. Cln shop & work area.		
27. Reposition trans cooler lines rubbing radiator tank.		
28. Dia no wigwags; chk switch(ok); chkd relay-ok; chkd flasher-ok; trace wires; fnd cut wire; rep wire.		
29. Replcd seat swtch drivers side; splice air lines.		
30. Chkd computer codes; fnd code 434 inactive; unable to erase due to software; chkd trans/ABS codes.		
31. Connect 02 bottle & chk for leaks; fnd leak behind actionary panel @ hose clamp; tighten hose clamp & recheck ok.		
32. Chk veh air leak; fnd loose fitting at air tank & air bags cracked & leaking; tightened line; replcd air bags & adj ride height.		
33. Dia leak in P/S sys; fnd bad fitting; replcd fitting & tightened line.		
34. Dia 110V A/C problem; fnd bad condensor fan & low freon; replcd fan; splice wires & sec heat shrink; change freon & chkd ok.		
35. Adj air horns.		



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V19142

In Date: 11/18/2008
Close Date: 12/09/2008

Meter Reading: 74,403.00

Problem?

replace tires at shop r15

Task performed:

Replace tires at shop R15 - Callaghan j

Parts

NO PARTS USED

Quantity

Vendor? CALLAGHAN

Workorder: V19516

In Date: 12/04/2008
Close Date: 12/16/2008

Meter Reading: 74,868.00

Problem?

repair fuel leak r15

Task performed:

Drive to Stn; fuel filter housing leak; get part installed new; bleed fuel sys; start; test drive ok. j

Parts

FS1269FUEL FILTER COMPLETE

Quantity

1

Workorder: V19973

In Date: 12/26/2008
Close Date: 01/06/2009

Meter Reading: 5,603.80

Problem?

Yellow parking brake knob has come off. Brake is still functional. R15

Task performed:

Drive to Stn15; replc parking brake knob. j

Parts

KN20901KN20901 KNOB PARKING BRAK

Quantity

1

Workorder: V19986

In Date: 12/27/2008
Close Date: 01/06/2009

Meter Reading: 75,840.00

Problem?

PASSENGER SIDE HEADLAMP IS OUT ON NORMAL BEAM. BOTH LAMPS ARE ON WHEN SWITCHED TO HIGH BEAM. R1

Task performed:

Drive to Stn15; R/R right front headlight. j

Parts

H6054USE CV TYPE SEALED BEAM

Quantity

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V20419

In Date: 01/16/2009
Close Date: 02/04/2009

Meter Reading: 5,603.80

Problem?

driver side rear door that holds backboards opened while driving .top latch holding door broken. R-15

Task performed:

1- Drive to station installed and adjust striker. test ok.

Parts

HLD374211 IN HOLD-OPEN 30LB

Quantity

1

Workorder: V20590

In Date: 01/26/2009
Close Date: 02/11/2009

Meter Reading: 76,320.30

Problem?

SLOW START, R-15

Task performed:

1- Found battery charger nor work. trip braker in A/C compartmen.

Parts

NO PARTS USED

Quantity

Workorder: V20966

In Date: 02/09/2009
Close Date: 02/23/2009

Meter Reading: 5,603.80

Problem?

New batteries installed last week, R-15 still difficult to start.

Task performed:

drive to Stn; replc starter; test ok. j

Parts

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

Quantity

1

Workorder: V21063

In Date: 02/12/2009
Close Date: 02/23/2009

Meter Reading: 5,603.80

Problem?

The "Check Engine" light came on after the new starter was installed. After truck was shut off and re-started, the light did not come on for remainder of shift. R15

Task performed:

Driv e to stn; hookup laptop 434 code; clear code; talk w/driver about. j

Parts

NO PARTS USED

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21141

In Date: 02/17/2009

Meter Reading: 77,788.20

Close Date: 02/23/2009

Problem?

ON CALL R15 CHECK ENG LT ON

Task performed:

Parts

Quantity

Drive to Stn15; hookup laptop 0434 code; no worry erased codes; tape up hanging wire in eng compt; also phone time & wait time on WPB Stn5 dead btrys.
j

NO PARTS USED

Workorder: V16966

In Date: 08/11/2008

Meter Reading: 5,552.20

Close Date: 03/02/2009

Problem?

replace left rear mud flap r15

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V17476

In Date: 09/03/2008

Meter Reading:

Close Date: 03/02/2009

Problem?

Red battery indicator light is on, amps read neg. L rear clearance light is out; Rear mobile radio speaker has high - pitched whinin; noise while vehicle is running. r15

Task performed:

Parts

Quantity

4864JBRALTERNATOR 270 A

1

4867JB320 UPGRADE ALTERNATOR

1

Workorder: V20780

In Date: 02/02/2009

Meter Reading: 5,603.80

Close Date: 03/06/2009

Problem?

Truck is increasingly difficult to start, possible bad batteries or alternator. R-15

Task performed:

Parts

Quantity

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

4

HP-31DBATTERY 950CCA HP-31D

4



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V21329

In Date: 02/25/2009

Meter Reading: 5,603.80

Close Date: 03/06/2009

Problem?

Right front head light out. Replaced with spare. Need a new spare head light for ST 15.

Task performed:

Drop off bulb at stn. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23201

In Date: 05/11/2009

Meter Reading: 80,731.90

Close Date: 05/21/2009

Problem?

B INSPECTION AND REPAIRS AS NEEDED R15

Task performed:

Parts

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

1. Rep marker light on R-side cab-hood marker.	1500900017000USE 9 X 14 FILTER	1
2. REp marker lights on R-side of box.	22-49905-000CABLE HEATER	1
3. Tightened panels in R-1 compt	322502BULB PATIENT GH22	1
4. Rep L-3 compt door hinge.	370047ASEAL 34387	2
5. Resecured air swtch for drivers seat.	52-24WIPER BLADES ANCO 24	2
6. Tighten lock on door of pat comp; replcd plastic covr over lock.	680-10LAMERICAN FLAG W UV CLEAR LEFT	1
7. Dropped off R30 at Stn30 & went to carwash place with PO to PU coupons.	680-10RAMERICAN FLAG W UV CLEAR RIGHT	1
8. C/O Focus for rip; fnd tire flat w/nail; took tire off to have replcd; prepared Malibu instead. j	6806970098SEAL DOOR	1
9. Road test & B-Inspection	921LIGHT BULB	1
10. B-I nspection	A1834388003MOLD R/H	1
11. Pat compt A/C coil clogged; cln coil w/coil cleaning solvent.	D6176M121-83014 ROTORS RESCUE	2
12. Pat compt A/C filter damaged/dirty; rem/install new air filter.	E-2436R002436 GASKET-REAR AXLE	2
13. Change windshield wiper blades & fill washer fluid bottle; add bug solvent to water.	L1261F33585XE FUEL FILTER WIX	1
14. rem damage pass window molding & install new molding.	MK184HDBRAKE PADS	1
15. Pass/driver doo weather strip torn; rem/install new weather strips.	PH8942FILTER OIL 57182 LFP3729	1
16. Pass door hinge hard to swing open; rem door panel/lube pivoting arm; reassemble.	S3225PFUEL FILTER 33630 LFF5849	1
17. Flag faded & frnt hood decal stripping; rem faded flag; install new flags; rem hood decal; cln area & polish.	SWT54914SW ROCKER SPST ON/OFF AMBER	1
18. Rar wheel seal leak; diss wheel hub, brakes & rem rotor; need new rotor, pads & seal; cln up parts & frame, diff of excessive oil spill; reassemble w/new parts & fill diff.		
19. Dia 110 A/C sys failure; low on freon; unable to locate leak; vac sys for overnight pressure lost test.		
20. Loose door lock & door panels; sec all loose items on unit.		
21. Electrical interuptting power lost; dia fault; fnd loose grnd to pat compt electrical boards; cln/sec loose grnd; sec all loose cablings.		
22. 110 A/C freezing up at expansion valve; recover frec		
23. Heater control cable brkn; diss dash board to rem/replc cable; reassemble dash board.		
24. L-4 compt light bulb out; cables torn out; rewire/install new bulb pat compt hi/lo bulb out; rem/install new bulbs.		
25. Install eng cover (hood); fire rescue lettering;		
26. Chk 110 A/C sys for contamination, lines; cln/chk expansion valve for dirt; reconnect/vac sys for 1.5 hr; chk for leak; no leak; charge sys; unit rns, then shuts down.		
27. Dia 12V side of 110V A/c; fnd blown fuse; replc fuse 30 AMP; sys working normal; temp 14 degrees. j		



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23605

In Date: 05/28/2009

Meter Reading: 81,422.00

Close Date: 06/01/2009

Problem?

ON CALL R15 WONT START

Task performed:

Drive to Stn; fnd truck unplugged outside; made up cord to plug in outside; replc starter relay & had "check engine light" on.

Fnd preheat to intake on plug; plug in; cIn all codes. j

Parts

Quantity

ESX120105112STARTER RELAY ESX-120-105112

1

Workorder: V23694

In Date: 06/01/2009

Meter Reading: 81,422.00

Close Date: 06/16/2009

Problem?

on call batterys dead r15

Task performed:

Call out to Stn15; no start; C/O truck; btry not plugged in outside; resete brakes in back; charging ok. Chk all btry in truck; all tested good. j

Parts

Quantity

NO PARTS USED

Workorder: V23930

In Date: 06/09/2009

Meter Reading: 5,603.80

Close Date: 06/18/2009

Problem?

R-15 vehicle has no dampening (shock absorbtion) for pt compartment during transport. Minor road imperfections are greatly magnified causing extremely rough transports for patients.

Task performed:

Go to Stn15; Chk clara nce in rear; readj both ride height valves & road test. j

Parts

Quantity

NO PARTS USED

Workorder: V23723

In Date: 06/01/2009

Meter Reading: 81,422.00

Close Date: 06/22/2009

Problem?

INTERMITTENT NO START R15

Task performed:

1. Ck for not starting; ck starter solenoid; ck ok; ck grnd at sol; fnd/tightened btry grnd at frame & frame to eng grnd; starter/sol has been replcd; cld not get trk to not start; ck shoreline for charging & charging sys; ck lk.
2. Left headlight out; R/R headlight; ck ok. j

Parts

Quantity

H6054USE CV TYPE SEALED BEAM

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V23765

In Date: 06/02/2009

Meter Reading: 5,603.80

Close Date: 06/24/2009

Problem?

UNIT STILL DIFFICULT TO START; "CHECK ENGINE" LIGHT ON AFTER STARTING.r15

Task performed:

1. Rem dash panel; ck connections at ign swtch; ck ok; rem btry cables; R/R starter; cnd connections; reinstalled btry; ck opn; ck ok.

2. Fnd right rear axle wheel seal leaking; rem wheel covers, wheels, brake caliper, axle, brgs & hub; R/R wheel seal; cnd rotor, hub & wheel; reassemble all parts.

Parts

Quantity

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

1

370047ASEAL 34387

1

Workorder: V24584

In Date: 07/06/2009

Meter Reading: 5,603.80

Close Date: 07/16/2009

Problem?

A/C in PT compartment is not blowing cold air r15

Task performed:

drive to Stn; wire bad for hi-press; press bad; rework; test. j

Parts

Quantity

NO PARTS USED

Workorder: V24626

In Date: 07/07/2009

Meter Reading: 5,603.80

Close Date: 07/16/2009

Problem?

several lights in patient compartment not working on high r15

Task performed:

drive to Stn; replcd (3) light; test ok. j

Parts

Quantity

322502BULB PATIENT GH22

3

Workorder: V24830

In Date: 07/16/2009

Meter Reading: 83,545.90

Close Date: 07/24/2009

Problem?

front a/c blowing warm. r15

Task performed:

T-shoot A/C sys; replc trinary swtch; send to shop for swapout. j

Parts

Quantity

471R755011-2624 TRINARY SWITCH A/C 1560

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V25162

In Date: 07/30/2009

Meter Reading: 83,899.40

Close Date: 08/05/2009

Problem?

BELT SQUEALING, 110V A/C INOP, R-15

Task performed:

Parts

Quantity

drive to Stn; tighten belts; test ok. j

NO PARTS USED

Workorder: V27146

In Date: 10/24/2009

Meter Reading: 5,603.80

Close Date: 11/05/2009

Problem?

Patient compartment A/C from shore power does not work. (15 amp fuse wil not reset). r15

Task performed:

Parts

Quantity

Drive to Stn; fnd 110 A/C board bad; need updated board; talk w/Ed about it; will repair at shop. j

NO PARTS USED

Workorder: V27440

In Date: 11/05/2009

Meter Reading: 87,163.60

Close Date: 11/17/2009

Problem?

A inspection and repairs

Task performed:

Parts

Quantity

- A-Service
- 2. Install tap on side step; slip tag left/right frnt doors.
- 3. Drill/rivet panel on left side loose.
- 4. R/R both frnt shocks on truck; chk & set toe in on frnt wheels. j

6803230300 65482 SHOCK FRONT ENGINE

2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28004

In Date: 11/30/2009

Meter Reading: 87,163.60

Close Date: 01/05/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED SR 11

Task performed:

- 1. C-Inspection - Road Test; Chk alt/starter for performance units working good; no stored ECU, Wabco or Allison codes fnd.\
- 2. Rem jump seat for reupholstery.
- 3. Air dryer svc.
- 4. Dia 110V sys failure; rep 110V sys; rem board & rewire new revised board.
- 5. Rem fuel cap; cln/paint yellow.
- 6. Replc windshield wiper blades & add bug solvent to reservoir.
- 7. Driver window molding brkn; rem/install new molding.
- 8. Rear pat entrance door lock loose; sec door locking asy.
- 9. Driver seat air switch loose; reroute air lines & sec air valve swtch asy.
- 10. Hood support cables fraying; rem/install new support cables.
- 11. Svc eng/A/C belts; also install new tensioner.
- 12. Install cln A/C vent filter.
- 13. Pat entrance no-skid damage; rem/install new section of no-skid on steps.
- 14. Pat compt A/C coil clogged; cln coil.
- 15. CO2 monitor loose & hanging; sec monitor.
- 16. Pat comp corner padding loose; sec hold down straps to wall & install molding.
- 17. Sec loose cables in eng compt.
- 18. O2 leak; locate leak behind A/A drop down panel at connections; sec loose fitting.
- 19. Dia wigwag failure.
- 20. Complete dia of wigwag failure & rep fault; fnd relay 23 to relay 24; jumper wire loose on contact pin; sec pin to holder.
- 21. P/S booster has oil arnd base; cln surface; operate unit to find source of leak; no leak vissable at this time.
- 22. P/S pump only; cln aera; operate unit; fnd fitting at press side leaking; tighten hose fitting.
- 23. 110 converter tripping GFI brkr; converter inop; rem/install new converter; operate sys.
- 24. Install reupholstered jump seat. j

Parts

Quantity

1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	24
3945207BOLT ADJ A/C COMP	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
91-22WIPER BLADE	2
9451BELT	1
9485BELT	1
A1712756000HOOD CABLE	2
A1834388002MOLD L/H	1
CA8193AIR FILTER 46744 WIX	1
CM110VCONTROL BOARD OLD REV-3	1
L1261F33585XE FUEL FILTER WIX	1
PD9180CONVERTOR 110V 80 AMP	1
PH8942FILTER OIL 57182 LFP3729	1
QO120GFIGFI CIRCUIT BREAKER 20 AMP	2
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V28072

In Date: 12/02/2009
Close Date: 01/15/2010

Meter Reading: 87,163.60

Problem?

repair seat SR11 (outside agency-central auto trim)

Task performed:

Rep seat SR11 - Central Auto j

Parts

NO PARTS USED

Quantity

Vendor? CENTRAL AUTO

Workorder: V28803

In Date: 01/04/2010
Close Date: 01/26/2010

Meter Reading: 87,163.60

Problem?

won't start in yard, was plugged in SR11

Task performed:

1. Jump start unit.
2. Test channing sys; btry test; alt test; starter test; chk for loose connection; all sys operating normal.
3. Jump start; chk sys; passed alt, starter & btry test; chk 110; fnd auto-eject tripping 110 sys; was not plugged all the way in; chk sys four hours later; good. j

Parts

NO PARTS USED

Quantity

Workorder: V29905

In Date: 02/11/2010
Close Date: 03/18/2010

Meter Reading: 88,447.10

Problem?

A inspection and repairs

Task performed:

1. Replc left rear marker t-signa.
2. Replc L-3 support brkts X 2.
3. Replc bulb in frnt light bar.
4. Rep fuel cell cvr step. j

Parts

40202RT/L#40202R RED TAIL LIGHT
H35SN12BULB
HLD44614446 1/4 LATCH

Quantity

1
1
2

Workorder: V29402

In Date: 01/25/2010
Close Date: 03/19/2010

Meter Reading: 5,603.80

Problem?

Passenger side head light out R41

Task performed:

Replcd headlight & rep headlight holder. j

Parts

NO PARTS USED

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V29673

In Date: 02/03/2010

Meter Reading: 5,603.80

Close Date: 03/19/2010

Problem?

wig wag lights not working r41

Task performed:

Rep wig-wag that had bad grd. j

Parts

NO PARTS USED

Quantity

Workorder: V31832

In Date: 04/27/2010

Meter Reading: 89,993.60

Close Date: 05/06/2010

Problem?

A inspection R37

Task performed:

- A-Inspection
- 2. Replace marker lite bulbs X 3.
- 3. Replc action area lite bulbs. j

Parts

1895BULB

Quantity

2

Workorder: V32951

In Date: 06/16/2010

Meter Reading: 89,993.60

Close Date: 06/22/2010

Problem?

2 patient compt. overhead light out, o2 compt. light out

Task performed:

- 1/ (2) pat compt dome lights inop; install new bulbs.
- 2. O2 light inop; installed new bulb. j

Parts

322502BULB PATIENT GH22

4020362171 GRO LAMP DOME 4 IN

Quantity

2

1

Workorder: V32825

In Date: 06/11/2010

Meter Reading: 89,993.60

Close Date: 06/25/2010

Problem?

A inspection (from 24)

Task performed:

- A-Inspection
- 2. Replc btrys.
- 3. Replc marker bulb & lens
- 4. Replc windshield washer pump. j

Parts

91513AMBER LENS

A2254926000WASHER PUMP W/GROMMET

BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF

HP-31DBATTERY 950CCA HP-31D

Quantity

1

1

4

4



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V33398

In Date: 07/07/2010
Close Date: 07/30/2010

Meter Reading: 90,251.00

Problem?

shoreline charging system not working. no A/C in back. R52

Task performed:

Breaker tripped. ja

Parts

NO PARTS USED

Quantity

Workorder: V33830

In Date: 07/27/2010
Close Date: 08/04/2010

Meter Reading: 90,821.00

Problem?

A inspection R15

Task performed:

A-Inspection ja

Parts

NO PARTS USED

Quantity

Workorder: V34300

In Date: 08/16/2010
Close Date: 08/27/2010

Meter Reading: 90,821.00

Problem?

A inspection and repairs (from 34)

Task performed:

A-Inspection
2. Rep door support L3. ja

Parts

4020362171 GRO LAMP DOME 4 IN
HLD44614446 1/4 LATCH

Quantity

1
1

Workorder: V34849

In Date: 09/09/2010
Close Date: 09/27/2010

Meter Reading: 91,661.00

Problem?

ALL STROBE LIGHTS INOP, R-53

Task performed:

1. Travel to Walmart on SR441; chk strobe lights; replc load manager; rep bad grd wires on pull down compt in pat compt; travel back to south shop.
2. Went to 53; all strobes inop; strobe packs powered no output; suspect faulty packs; went to 42 for parts; Ed. O. came with to assist; fnd faulty load manager & grd wires in pull down electrical panel; took Ed back to stn.
j

Parts

EL30213091-32 LOAD MANAGER

Quantity

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34852

In Date: 09/09/2010

Meter Reading: 91,661.00

Close Date: 09/28/2010

Problem?

shore line was pulled apart, from ceiling and unit connection. possible that ejector did not function. found this way at the beginning of "B" shift, not sure when problem occurred. R53

Task performed:

Went to 53; fnd auto-eject inop; rem panel; R/R auto-eject; ck opn; ck ok. j

Parts

Quantity

0915520120AUTO EJECT 20 AERO OTL3925

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V34921

In Date: 09/13/2010

Meter Reading: 92,290.00

Close Date: 10/18/2010

Problem?

B INSPECTION AND REPAIRS AS NEEDED SR11

Task performed:

Parts

Quantity



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

B-Inspection

2. Eng wld not start during B-Inspection; chk codes; lift pump NG; wld not run; replc fuel lift pump to finish B-Inspection.

2. Replc auto-eject on 110V sys.

4. R/rear backup light inop; diss light fixture; replc inset bulb & rep socket; reassemble.

5. R-1 compt light inop; replc light asy in R-1 compt.

6. Replc wiper blades.

7. Replc pat area bench seat hold open pistons; first rep mnts in seat; screws stripped out & mnt brkts loose.

8. Rep drivers seat air valve; hanging on floor; reattach to seat frame.

9. Replc pat area A/C air intake filter.

10. Frnt light bar lenses very dull; acquire (5) new lenses; measure & cut to fit; install.

11. (4) frnt hood emerg light lenses dull; with buffer & liquid doe the same to rear light bar lenses.

12. (3) pat area slide draws brkn; acquire (3) sets of draw slides; install new slides; NOTE: new style slides diff than original; redrill/reposition to mk work.

13. Severe oil leaking on L/side fire wall; wash off entire area & chk for locn of leak; fnd power brake booster & emerg motor for booster leaking; rem booster & motor asy frm veh; diss/chk mntng tee plate betwn both warped; replc booster, motor & teel plae; assem new components on bench & install in veh.

13a. Replc drivers side seat belt; order R/side; install right side seat belt.

14. Veh leaning to L/side; seems like right air bag is at 80% inflation & L/side at 20% inflation; readj length of cntrl arms to be equal & at proper length; adj height leveling valves to proper height; NOTE: right air bag doesn't sit properly under veh frame to suspension component arm; this was shown to shop supt M. Lehan & was his decision to monitor to see if any problems start to occur; conclusiong is no rep to be done at this time.

15. Replc both frnt tires; use older marked tires under Bldg 3 as per M. Lehan.

16. Pat A/C condenser fans inop; chk power to fans - NG; trace back to output power - ok; fnd wires to fans cut; resplice wiring & rechk; now all good.

17. Pat area A/C evap fans growling(vary load); evac freon frm sys; disconnect all elect/A/C hoses frm evap asy; rem entire asy frm veh & diss on bench to install new blower motor asy; NOTE: this is a newere style blower asy & some mod needed & wiring harnesses needed to be made; reassemble/reinstall in veh.

18. A/C sys blowing warm; C/O press & fnd compressor-NG; replc complete compressor asy under veh; NOTE: a special lo-side hose fitting had to be made to connect diff style compressor connectoers; also replc dryer/expansion valve; vac/recharge sys; C/O entirre sys

040444-01EXPANSION VALVE R-22	1
071601A07-0602A DRIER A/C 7118	1
1501450007750USE 0775145	1
15W40BSYN OIL BULK QTS	16
16-31438915 VALVE CORE A/C 3544706C1	2
1661657C1RELAY	1
2587324C1LEVEL SENSOR	1
3963983WASHER SEAL ISB	3
39901054943048 FUEL PUMP ISB	1
4020362171 GRO LAMP DOME 4 IN	1
52-24WIPER BLADES ANCO 24	2
68116169650CLENS RED SUPER ADV. PLUS LT. BAR 68-1	5
ASL3369972HYDRO-BOOST	1
CA8193AIR FILTER 46744 WIX	1
H27SN12BULB	1
HLD3999GSS1715UV 30LB STRUT GAS	2
IMMF13225BELT SEAT PASS. IMMF11852 OLD #	3
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
S3225PFUEL FILTER 33630 LFF5849	1
SLD5366HT4932-16 DRAWER SLIDE 16	6
UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 110 A/	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

to mk sure sys turned off/on automaticaly w/temp setting.

19. Brake sys/parking brake dash indicator on continuously; isolate sys that causes this light to come on; find manual in library & study diff sys assoc to this light one-by-one; narrow down to one problem; replc low sensor indicator in master cy; road test. j

Workorder: V34765

In Date: 09/06/2010 Meter Reading: 91,661.00
Close Date: 10/20/2010

Problem?

the emergency lights of pt compartment (all 4) dont work R53

Task performed:

Rep bad connection. j

Parts

NO PARTS USED

Quantity

Workorder: V38292

In Date: 02/07/2011 Meter Reading: 93,095.00
Close Date: 02/15/2011

Problem?

A inspection

Task performed:

A-Inspection
2. Pat A/C warm; sys has no charge; vac/leak test; held vac; cld not find leaks; charged sys & ran performance test.
3. Replc (2) burnt out strobes; other (2) not getting power; t-shoot; find bad strobe pack; R/R pack.
4. Rear inner left tire low; fnd valve stem core leaking; R/R core & fill tire; chk for leaks. j

Parts

01-0285809-00C REFURB ONLY POWER SUPPLY KKKEPS
02036317300STROBE LINEAR REFLECTOR 6ELTUBE
TURBO5TUBE - STROBE

Quantity

1
2
2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V38607

In Date: 02/18/2011

Meter Reading: 93,097.00

Close Date: 03/07/2011

Problem?

A INSPECTION SR11

Task performed:

- Perform A-Svc
- 2. replcd cab roof marker light bulb.
- 3. Replcd entire light asy on R/frt upper body.
- 4. Replcd wiper blades.
- 5. Replcd right side t-signal side marker lens - cracked.
- 6. Replcd driver/pass side non-skid on cab steps - worn.
- 7. Replcd left headlight.
- 8. C/O stretcher mnt & ordered parts; recvd parts & installed. j

Parts

Quantity

0200271ANTLER BAR	1
194BULB	1
52-24WIPER BLADES ANCO 24	2
91513AMBER LENS	1
V122XARESCUES MARKER LIGHT	1

Workorder: V39164

In Date: 03/14/2011

Meter Reading: 92,945.00

Close Date: 05/17/2011

Problem?

A INSPECTION

Task performed:

- A-Inspection
- 2. Put back tires & brake pad; looks good; rotor looks good.
- 3. Recover rear A/C sys; it only had 4 oz os filled sys to find leak; fnd leak at hi-press switch; rem switch to chk fitting; fittings were good; R/R switch chargswitch charge sys; no leaks fnd; sys cooled good.
- 4. Cln sand out of compt. j

Parts

Quantity

FTT53931491 SW PRESS. HI SIDE NC OPEN-350 CLOSE-2	1
---	---

Workorder: V39805

In Date: 04/08/2011

Meter Reading: 93,103.00

Close Date: 05/17/2011

Problem?

battery charger malfunction-dead in yard

Task performed:

- Jump truck; pull in shop; charge & chk btrys; chk shoreline; reset brkr; chk charging; ok. j
- Chk btry charger; it was charging 14.2V; thats good. j

Parts

Quantity

NO PARTS USED	
---------------	--



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V41171

In Date: 06/07/2011

Meter Reading: 93,740.00

Close Date: 06/17/2011

Problem?

Repair light bar, air vent.

Task performed:

Rem L/S outer lens; straighten light bar frame; install new lens & marker light; R/R air vent asy. j

Parts

Quantity

1895BULB	1
68118132150CLENS RED MAR.LIGHT SUPER ADV.LT.BA	1
68118206050BEND CAP RED SUPER ADV.PLUS LT.BAR	1

Workorder: V41252

In Date: 06/10/2011

Meter Reading: 93,902.00

Close Date: 06/28/2011

Problem?

C INSPECTION AND REPAIRS SR 11

Task performed:

1. C-Inspection
2. Load test btrys - failed test; rem/install (4) new btrys.
3. Rear end svc.
4. Frnt/rear brake pads; rem/inspect rotor & caliper valve extensions shafing; rem/install (2) new outer valve.
5. Air dryer svc.
6. Rear wheel cvr loose; replc msng hold down screws.
7. Retorque frnt/rear u-bolts.
8. Trans svc.
9. Coolant sys svc; replc fail rad cap.
10. P/S sys svc.
11. Windshield wiper blade & fluid svc; add bug solvent.
12. Officers seat window molding brkn; rem/install new molding.
13. 110 A/C 10-7; dia fault; brkr tripping, chk shoreliine ckt, converter; rem freon; none in unit; reassem; fnd compressor dry; rem, install new compressor; add oil as per mfr recomendation; change sys 2.5 lbs & operate.
14. Hoses along frame rail unsecure; securely fasten loose hoses along frame rail.
15. Bench seat back rest off; securely fasten back rest cushion.
16. A/C belt svc.
17. Eng serpentine belt svc & tensioner.
18. Compt door panels screw loose; secure all loose panel screws.
19. Quality check. j

Parts

Quantity

05-17223-000CAP RADIATOR 10 LB	2
071601A07-0602A DRIER A/C 7118	1
29526898 29548988 TRANS FILTER ALLISON	1
39768315259022 GROOVED TENSIONER OLD#3936213	1
52-24WIPER BLADES ANCO 24	2
8201L17-3428 ESTER OIL E7	1
91-22WIPER BLADE	2
9451BELT	1
9485BELT	1
A1834388003MOLD R/H	1
BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTEF	4
HP-31DBATTERY 950CCA HP-31D	4
K080733BELT	1
L1261F33585XE FUEL FILTER WIX	1
MK184HDBRAKE PADS	2
PH8942FILTER OIL 57182 LFP3729	1
RKB5513COMPRESSOR A/C 115V R22	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
VML-S1414FILTER P/S	1
VML-T1264GASKET P/S COVER	1
WHL9291VALVE EXT. KIT	2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V40020

In Date: 04/20/2011
Close Date: 08/02/2011

Meter Reading: 92,945.00

Problem?

need suction hose

Task performed:

needed parts only

Parts

Quantity

NO PARTS USED

Workorder: V40344

In Date: 05/02/2011
Close Date: 08/03/2011

Meter Reading: 92,945.00

Problem?

REPLACE TIRES SR11

Task performed:

Replc tires SR11 - Boulevard j

Parts

Quantity

NO PARTS USED

Vendor? BOULEVARD

Workorder: V43120

In Date: 08/29/2011
Close Date: 08/30/2011

Meter Reading: 93,913.00

Problem?

A/C not cooling.

Task performed:

had rescue come to st 25 found a/c level low filled system ck ok

Parts

Quantity

NO PARTS USED

Workorder: V43537

In Date: 09/09/2011
Close Date: 09/21/2011

Meter Reading: 94,861.00

Problem?

A inspection.

Task performed:

a inspection

tighten and adjust all patient comp door latches

redrill and tap l3 comp door hinge mounts stripped out

check and charge cab and pt. a/c

Parts

Quantity

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V44052

In Date: 09/30/2011
Close Date: 10/03/2011

Meter Reading: 94,924.60

Problem?

A inspection.

Task performed:

A-Inspection j

Parts

Quantity

NO PARTS USED

Workorder: V44502

In Date: 10/19/2011
Close Date: 10/19/2011

Meter Reading: 95,676.00

Problem?

A inspection.

Task performed:

A INSPECTION

Parts

Quantity

A1818557002HANDLE-WINDOW

1

REMOVE R/S DOOR PANEL AND REPAIR WINDOW
REGULATOR AND INSTALL WINDOW CRANK
HANDLE

Workorder: V44597

In Date: 10/21/2011
Close Date: 10/28/2011

Meter Reading: 95,358.70

Problem?

patinet compartment a/c making noise

Task performed:

found pat. a/c blowers making noise, removed --chute,
wires and blower case, r&r blower assembly, reassemble
unit wire and --up, ran and ck operation ck ok

Parts

Quantity

52-624SWITCH DOOR

5

UNT1400BLOWER MTR. + SQU IRREL CAGE ASSY. 110 A/

1

round door panel lights out, repaired wires ck ok

ck door alarm going off, round switches corroded, r&r
switched ck ok



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V45363

In Date: 11/22/2011

Meter Reading: 96,518.00

Close Date: 12/02/2011

Problem?

A inspection.

Task performed:

A INSPECTION

REMOVE R REAR HUB CAP CHECK TIRE PRESSURE AND SECURE LOOSE HUB CAP

REPALCE L MARKER BULB

REPLACE PATIENT STEP LIGHT

ADD P/S FLUID, CLEAN RESEVOIR

DIAGNOSE FRT LIGHT BAR STROBE OUT REMOVE LENSES AND TEST STROBE FOUND BAD STROBE REPALCED STROBE

REBUILD AIR HORNS AND ADJ FOR SOUND QUALITY REE UP FROZEN AIR HORN HOUSING THREADS

Parts

Quantity

02036317300STROBE LINEAR REFLECTOR 6ELTUBE

1

1094KIT-AIR HORN-GROVER

2

Workorder: V45149

In Date: 11/14/2011

Meter Reading: 96,437.00

Close Date: 02/02/2012

Problem?

A INSPECTION SR11

Task performed:

A-Inspection. j

Parts

Quantity

NO PARTS USED



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47050

In Date: 02/02/2012
Close Date: 02/08/2012

Meter Reading: 96,096.30

Problem?

B inspection

Task performed:

1. B-INSPECTION.
2. ADJUST AIR HORNS.
3. TIGHTEN ALL GRAB HANDLES.
4. CHECK FOR COOLANT LEAKS, TIGHTEN ALL HOSE CLAMPS, R&R BOTH HEATER CONTROL SHUT OFF VALVES.
5. R&R CITY HORNS.
6. ADJUST A/C BELTS.
7. TIGHTEN ALL DOOR HOLD OPEN BRACKETS.
8. Q & A.

Parts	Quantity
71847062455 VALVE HEATER	2
A0631117000HORN HIGH NEW # 06-52125-039	1
A0631117003HORN LOW NEW #06-52125-041	1

Workorder: V47488

In Date: 02/22/2012
Close Date: 02/27/2012

Meter Reading: 96,686.40

Problem?

passanger side rear outside tire is flat

Task performed:

PASSANGER SIDE REEAR OUTSIDE TIRE IS FLAT.

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE CENTE

Workorder: V47635

In Date: 02/29/2012
Close Date: 03/07/2012

Meter Reading: 96,686.40

Problem?

R451 (Spare Truce) has a flat tire. Rear right outside tire asst#10136378

Task performed:

R451 (SPARE TRUCE) HAS A FLAT TIRE. REAR RIGHT OUTSIDE TIRE ASST#10136378.

Parts	Quantity
NO PARTS USED	

Vendor? BOULEVARD TIRE CENTE



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V43718

In Date: 09/16/2011

Meter Reading: 94,822.00

Close Date: 03/09/2012

Problem?

A-Inspection from 81. Check noise coming from wheels.

Task performed:

Parts

Quantity

NO PARTS USED

Workorder: V47704

In Date: 03/02/2012

Meter Reading: 96,686.40

Close Date: 03/16/2012

Problem?

rear exterior door handle broken. unable to open the door from the outside. To get the stretcher in and out must go through the side door to open from the interior. Sta 45

Task performed:

Parts

Quantity

REPLACED DOOR HANDLE.

HND5948TM22676-02 HANDLE DOOR ENTRY

1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V47835

In Date: 03/09/2012

Meter Reading: 97,356.50

Close Date: 03/28/2012

Problem?

A inspection.

Task performed:

1. A-INSPECTION.
2. REAR TIRES OVER INFLATED - BRING TIRE PRESSURES DOWN TO MANUFACTORY SPECS 110 PS.
3. DIAGNOSING PATIENT COMPT. A/C FAILURE. AIR COMPRESSOR MALFUNCTION, HIGH SIDE CHARGING PORT CRIMP LEAKING, CONDENSOR CONNECTION LEAKING, CHANGE O-RINGS, REPLACE HOSE AND CHANGING PONT PIPING, INSTALL NEW COMPRESSOR. VACCUME AND CHARGE UNIT.
4. SMOKING EXHAUST AT ACCEPTABLE LEVEL AS PER S. REINES, FOREMAN.
5. CHECK BRAKE ADJUSTMENT AND PADS SYSTEM WITHIN SPECS.
6. DRIVER SEAT AIR SWITCH BROKEN - REMOVE AND INSTALL NEW SWITCH.
7. POWER STEERING RESOVOIR GASKET LEAKING - REMOVE CLEAN AND PROPERLY SEAT GASKET AND SECURE.
8. GRILL MOUNT STROBES UNSECURE AND DAMAGE - REMOVE INSTALL AND REWIRE UP DATED STROBE LIGHTS ASSEMBLY.
9. PATIENT COMPARTMENT DRAW SLIDERS BROKEN - REMOVES SLIDERS AND INSTALL NEW SLIDERS.
10. PATIENT COMP BENCH SEAT STRUT WEAK - REPOSITION BENCH SEAT STRUT MOUNT AND SECURE.
11. REAR TIRES TREAD WORN - REMOVE TIRES INSTALL NEW TIRES, REMOVE WHEEL COVERS AS PER E.E AND S.R. FOREMAN, CLEAN TIRE RIMS.
12. WINDSHIELD SPRAY NOZZLES CLOG AND NEED ADJUSTING - REMOVE CLEAN NOZZLE PORTS, INSTALL AND ADJUST SPRAY DIRECTION.

Parts

Quantity

404584HOSE AND FITTING ASSY.	1
4511S08-6932BS 90 DEGREE FEMALE W/SERVICE PORT	1
4579S08-3422BS SPLICE	1
508RED58EC20RU STROBE-RED SURFACE MOUNT	2
532703-0602 COMPRESSOR U4735 4471	1
AMH-1AMH-1 VALVE EXTENSION	1
BOS62221360026222207-001 W AIR SEAT	1
SLD5366HT4932-16 DRAWER SLIDE 16	2



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V48485

In Date: 04/06/2012
Close Date: 04/17/2012

Meter Reading: 98,185.80

Problem?

A inspection.

Task performed:

1. A-INSPECTION.
2. FOUND L TURN MARKER OUT - R&R BULB, FOUND LEFT TOP FRONT STROBE OUT - REP BULB - FOUND LEFT CENTER REAR LIGHT BAR SCENE LIGHT OUT - REMOVED LENSES.
3. FOUND REAR SCENE LIGHT OUT - R&R BUILB - REINSTALLED REAR LIGHT BAR LENSES - FOUND LEFT BRAKE LIGHT OUT - R&R BULB - CHECK ALL LIGHTS CHECK OK.
4. FOUND RT NADER PIN COVER DAMAGED - REMOVED AND REPAIRED CHECK OK - FOUND RR TIRE PSI 86 SPRAYED AND REPAIRED LEAK CK. OK

Parts	Quantity
194BULB	2
H50SN12BULB	1
STOPSN12BULB STOP/TAIL LIGHT	1
TURBO5TUBE - STROBE	1

Workorder: V49222

In Date: 05/09/2012
Close Date: 05/17/2012

Meter Reading:

Problem?

the parking brake light does not turn off andparking brake noise will not stop. sr at 44

Task performed:

1. travel to sta-44, check brake lite on dash not going out, check brake fluid, found half empty, check brakes found l/rear brake lines with rub holes in them. have vehicle towed to s/shop for repairs, travel back to s/shop
2. remove and order brake lines, replace l/side rear brake lines that were leaking, r/side brake lines were on back order, also they were not leaking. bleed front and rear brakes, road test. ok

Parts	Quantity
12-15026-000BRAKE HOSE ASSY	1
372000082CHROME MARKER LIGHT MOUNT	1
372000083GASKET MOUNTING	1
372000084MARKER LIGHT	1
372000085HARNES FOR MARKER LIGHT	1
6804200148BRK HOSE FRONT L+R RESCUE	1
6804200448BRAKE LINE REAR AXLE	1
6804200748HOSE BRAKE REAR R/H	1
6804201048HOSE ASY REAR BRAKE L/H	1
NI PLATEMARKER LIGHT MOUNTING PLATE	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V50317

In Date: 06/22/2012
Close Date: 07/13/2012

Meter Reading: 100,177.50

Problem?

R500 has spare truck 10136378.. -6 E-lights are out -main o2 cylinder not reading inside pt compartment, its blank -need 1-2 qt of oil

Task performed:

1. REPLACED STROBE PACK FOR LIGHTS.
2. TOP OFF WITH OIL.
3. REWIRED O2 SENSOR AND TESTED AND CALABRATED.

Parts

Quantity

NO PARTS USED

Workorder: V50871

In Date: 07/16/2012
Close Date: 08/06/2012

Meter Reading: 100,675.90

Problem?

Driver side, front side emergency flasher out. R400

Task performed:

- REPAIRED LIGHT THAT HAD BAD CONNECTION.

Parts

Quantity

NO PARTS USED

Workorder: V51773

In Date: 08/21/2012
Close Date: 08/21/2012

Meter Reading: 101,507.90

Problem?

l/side, r/side, of pat box lites inop, R-451

Task performed:

1. check l/side, r/side, strobe lites inop, also found strobe lites in front lite bar inop, check bulbs, check wiring, found strobe pack n/g, remove suction motor, air pack brackets to be able to lower mesh covering strobe packs, replace strobe pack all lites now work ok,

Parts

Quantity

01-0285809-00C REFURB ONLY POWER SUPPLY KKKEPS	1
TURBO5TUBE - STROBE	3



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V52457

In Date: 09/17/2012

Meter Reading: 101,781.90

Close Date: 11/06/2012

Problem?

C INSPECTION SR 11

Task performed:

1. R&R REPOSITION STRUTS ON A/C ACCESS DOOR IN PATIENT AREA.
2. UV LIGHT IN PATIENT AREA A/C.
3. CONT DIAGNOSIS AND REPAIR OF AMBER STROBE IN CENTER OF REAR LIGHT BAR.
4. REPAIR ON BOARD BATT CHARGER.
5. R&R BATT CHARGER STARTS PANEL AT SHEERLINE.
6. 110V A/C NOT WORKING. DIAGNOSE AND REPAIR.
7. INSP PLAY AT STEERING COLUM U JOINT.
8. CHK ALT. 14. 2 VOLT AT ALT 13.95 AT BATTS.
9. C INSP
10. CHANGE ALL BATTS.
11. DIAGNOSE AND REPAIR R/S TOP FRT MED BOX 5 STROBE.
12. DIAGNOSE AMBER STROBE LT.
13. R&R WIPER BLADES.
14. R&R CAB ROOF MARKER LT BULB.
15. R&R MARKER, LT BULB IN REAR TOP MARKER LT.
16. R&R AIR PISTON STROUTS FOR BENCH SEAT IN MED AREA.
17. SERVICE AIR DRYER.
18. DIAGNOSE PATIENT A/C DISCH EVACUATE AND RECHARGE SYST.
19. DASH BOARD A/C CONTROLS R&R ALL DASH PANELS ADJ ALL HVAC CABLES.

Parts

Quantity

02036320700LINEAR STROBE MOD.6E EXTR. MOUNT	1
032-0116549297 BATTERY INDICATOR	1
05-17223-000CAP RADIATOR 10 LB	1
1501450007750USE 0775145	1
1895BULB	1
194BULB	1
52-24WIPER BLADES ANCO 24	2
6808310398SEAL AIR DUCT	1
CA8193AIR FILTER 46744 WIX	1
HLD3999GSS1715UV 30LB STRUT GAS	2
L1261F33585XE FUEL FILTER WIX	1
PH8942FILTER OIL 57182 LFP3729	1
RN60JDRYER KIT	1
S3225PFUEL FILTER 33630 LFF5849	1
TURBO5TUBE - STROBE	1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V55379

In Date: 01/29/2013

Meter Reading: 101,781.90

Close Date: 02/07/2013

Problem?

prep for special events

Task performed:

1. SWAPPED OUT CAB SEATS WITH TRUCK THAT WAS GOING TO SURPLUS (10136368) TO GET RESCUE READY TO BECOME SPECIAL EVENTS RESCUE.
2. SWAPPED OVER CHROME HUB CAPS (REAR) FROM SURPLUS TRUCK (10136364) ALONG WITH VALVE STEM HOSE EXTENSION KIT WITH STANDS.
3. REPLACED DRIVER'S SIDE SOT MIRROR. (RUSTED SOLID.)
4. REPLACED DRIVER'S OUTER DOOR CAP LATCH. ALSO WHILE DOOR PANEL WAS OFF LUBED WINDOW REG AND REPLACED DOOR TRIM. (BROKEN)
5. REPLACED PASSENGER CAB DOOR LATCH/HANDLE (OUTSIDE). WILE DOOR PANEL WAS OFF LUBED WINDOWS. REG. AND SECURED DOOR LIGHT. (FALLING OUT).
6. FABBED NEW CABLE FOR O2 WRENCH AND NEW VELCRO.
7. REDUCED STROBE LIGHT ASSEMBLY ON RIGHT SIDE OF HOOD.

Parts

Quantity

02-0383470-CROBSOLETE LENS RED/CLEAR	2
6807600070HANDLE DOOR EXT L/H	1
6807600170HANDLE DOOR EXT. R/H	1
980-412173 MIRROR 8 IN	1
A1834388002MOLD L/H	1
A1834388003MOLD R/H	1
ACX-84534LUG NUT COVER PK10	20

Workorder: V56285

In Date: 03/09/2013

Meter Reading: 101,799.00

Close Date: 03/14/2013

Problem?

buzzer wont stop while vehicle is running. Driver side right round rear view mirror fell off while driving. Unable to retrieve.

Task performed:

ROAD TESTED TRUCK ONLY BUZZER I CAN HEAR IN O2 ALARM NORMAL.

Parts

Quantity

980-412173 MIRROR 8 IN	1
------------------------	---



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V59208

In Date: 08/07/2013
Close Date: 08/19/2013

Meter Reading: 102,723.00

Problem?

B inspection OCS SER 2

Task performed:

change oil and filters

Parts

NO PARTS USED

Quantity

Vendor? OCS

Workorder: V68229

In Date: 07/28/2014
Close Date: 08/18/2014

Meter Reading: 103,153.00

Problem?

front A/C blowing hot

Task performed:

Travel to 25. Recharged A/C and tested ok.

Parts

NO PARTS USED

Quantity

Workorder: V70328

In Date: 10/21/2014
Close Date: 11/05/2014

Meter Reading: 103,153.00

Problem?

C inspection SER2

Task performed:

1. "C" inspection
2. Battery fail carbon test-Remove 4 batter install 4 new batter.
3. Oil seepage through exhust manifold and head-Notified E.Ehrke, told to let it go for now.
4. Patient A/C inop-Found low on freon-Pressure switch leaking, rmeove switch, section of hose , dryer and H-block, clean e-core and reassemble. Charge with freeon, opsmate, cooling to 34 F.
5. Front bumper-brake away bolts missing. Install new water pin cover plate and install.
6. Water pin cover broken-Remove piece-tap new water pin cover plate and install.
7. Cab roof liner wet-Water intrusion-Seal, marker light base, antener and spot light base.
8. Q.C inspection

Parts

- 05-17223-000CAP RADIATOR 10 LB
- 071601A07-0602A DRIER A/C 7118
- 12-3022A1608 2 1/2 TON VALVE EXPANSION
- 23-12080-150BOLT BUMPER
- 484773HOSE &FITTING
- BATTERY EPA TAXBATTERY EPA TAX \$1.50 PER BATTER
- CA8193AIR FILTER 46744 WIX
- HP-31DBATTERY 950CCA HP-31D
- L1261F33585XE FUEL FILTER WIX
- PH8942FILTER OIL 57182 LFP3729
- S3225PFUEL FILTER 33630 LFF5849

Quantity

- 1
- 1
- 2
- 4
- 1
- 4
- 1
- 4
- 1
- 1
- 1



5/8/2019

Palm Beach County Fire Rescue

Fleet Maintenance Asset History

10136378

FL60 ADVANCED LIFE SUPPORT VEHICLE

Workorder: V69861

In Date: 10/02/2014

Meter Reading: 103,153.00

Close Date: 12/05/2014

Problem?

No start SE rescue @25

Task performed:

Parts

Quantity

Checked all 3 special event rescues all start and run fine

NO PARTS USED

Workorder: V73270

In Date: 02/19/2015

Meter Reading: 103,452.00

Close Date: 02/24/2015

Problem?

INTERMITTANT NO START BAD STARTER.

Task performed:

Parts

Quantity

Travel to stadium jumping and replaced starter and solenoid on fire wall. Tested - ok.

11132766583 STARTER 28MT 5.9 10 TOOTH 10465043

1

ESX120105112STARTER RELAY ESX-120-105112

1

Workorder: V73997

In Date: 03/18/2015

Meter Reading:

Close Date: 05/12/2015

Problem?

back door not opening SER AT 25

Task performed:

Parts

Quantity

1. Travel to 25. Checked back doors. Working fine, no problem found.

NO PARTS USED



Palm Beach County Fire Rescue Fleet Maintenance Asset History

Asset: (10136378) 2001 - AMERICAN LAFRAN FL60 Advanced Life Support Vehicle

10136378

CSHOP-2015-1337

Comments: **SPEC EVENTS RESCUE AT 25 WILL NOT START**

Date Opened 6-23-2015 Date Finished 6-23-2015 Meter 1 Reading: 103,452

TASKS PERFORMED

NO PARTS USED

BATTERY

CSHOP-2015-1930

Comments: **FRONT AC NOT COOLING SE RESCUE @25**

Date Opened 7-23-2015 Date Finished 7-24-2015 Meter 1 Reading: 103,452

TASKS PERFORMED

NO PARTS USED

TRAVEL TO BE CHARGED TO WORK ORDER
AIR CONDITIONING

CSHOP-2016-2848

Date Opened 6-14-2016 Date Finished 9-14-2016 Meter 1 Reading: 104,491

TASKS PERFORMED

Q PARTS

RADIATOR	1	RADIATOR; F10 RESCUE C RADIATOR
OIL PAN-GASKET	1	GASKET; THERMASTATE-GASKET ISL 4936026
ELECTRICAL	1	LIGHT; LIGHT ASSY. TURN SIGNAL
REAR AXLE	10	GEAR; GEAR OIL SYN QT
STEERING	2	GASKET; R002436 GASKET-REAR AXLE
AIR SYSTEM	1	BRAKE; BRAKE PADS
CAB-INTERIOR ACCESSORIES	2	SEAL; SEAL 34387
AIR CONDITIONING	1	CHASSIS; DRAG LINK RESCUE
	1	SENSOR; 91-8301 85 PSI CLOSED 67 OPEN PREEURE
		PROT
	1	VALVE; 12-0615A VALVE EXPANSION FTRLNR 1606
	1	HOSE; A2241332084 HOSE A/C LOW
	-30	A/C; FREON LB
	5	A/C; FREON LB
	30	A/C; FREON LB
	1	DRYER; 07-0610A DRYER
	1	NEWPART; A/C HOSE
	1	NEWPART; CONDENSOR

Service Requests:

06/14/2016 A/C / 18: LEAKING / PREFORMED A/C PERFORMANCE AND LEAK TESTS. FOUND SYSTEM CHARC
FRONT AC NOT WORKING

Asset Work Order History 10136378

CSHOP-2016-2903

Comments: **C INSPECTION**

Date Opened 6-16-2016

Date Finished

6-27-2016

Meter 1 Reading:

104,382

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

1 FILTER; FUEL FILTER 33630 LFF5849
1 FILTER; 33585XE FUEL FILTER WIX
1 FILTER; FILTER OIL 57182 LFP3729

VENDOR? H2 FIRE SERVICES

CSHOP-2016-5298

Comments: **UNIT NOT STARTING**

Date Opened 11-13-2016

Date Finished

11-24-2016

Meter 1 Reading:

104,863

TASKS PERFORMED

NO PARTS USED

BATTERY

CSHOP-2016-5709

Date Opened 12-7-2016

Date Finished

12-12-2016

Meter 1 Reading:

104,863

TASKS PERFORMED

Q PARTS

DIAGNOSE ELECTRICAL

2 WIPER; WIPER BLADES ANCO 24
1 STARTER; 6583 STARTER 28MT 5.9 10 TOOTH 10465043
1 RELAY; STARTER RELAY ESX-120-105112

CSHOP-2017-2340

Comments: **USE A FORM**

Date Opened 4-20-2017

Date Finished

7-24-2017

Meter 1 Reading:

105,138

TASKS PERFORMED

NO PARTS USED

PM SERVICE B

CSHOP-2017-4304

Date Opened 7-24-2017

Date Finished

7-25-2017

Meter 1 Reading:

105,138

TASKS PERFORMED

Q PARTS

DOOR LATCH
BATTERY

2 9IP; M1-63-8 LATCH STAINLESS
4 1AD; BATTERY 31 SERIES

Asset Work Order History 10136378

CSHOP-2018-5891

Date Opened 10-17-2018 Date Finished 10-17-2018 Meter 1 Reading: 106,062

TASKS PERFORMED

Q PARTS

PM SERVICE C RESCUE

4 CRC; CLEANRCARB 200Z
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD FUEL FILTER
1 FIL; NAPAGOLD OIL FILTER
20 4PC; 15W40 PREMIUM BLUE OIL

CSHOP-2018-5903

Date Opened 10-17-2018 Date Finished 10-19-2018 Meter 1 Reading: 106,062

TASKS PERFORMED

Q PARTS

WIPER BLADES
PARK-CLEARANCE LIGHTS
AIR BAG SYSTEM
STROBE LIGHTS
AIR HORN
MIRRORS
DRYER-ACCUMULATOR
AIR CONDITIONING

2 1AN; WIPER BLADES
1 NCB; SUPER K WASH CONCNRTR
1 2FL; WASHER PUMP FRIGHTLINER
2 LIT; LED M C LAMP
10 9IP; BULB
4 LMP; LAMP
2 2DD; AIR BAG
1 1WL; LINEAR STROBE
1 1WL; 508 STROBE
1 9AP; HORNBLASTER SOLENOID
1 9IP; DRYER KIT
3 9XX; AC FREON 10199801

CSHOP-2018-691

Date Opened 2-1-2018 Date Finished 2-12-2018 Meter 1 Reading: 105,138

TASKS PERFORMED

Q PARTS

TRAVEL TO BE CHARGED TO WORK ORDER
SHORELINE CHRAGER

1 NONSTOCK; FREIGHT CHARGE
1 9AP; BATTERY TENDER 12V

Service Requests:

02/01/2018 STARTER / 38: SHORTED / EXCHANGE - NEW
VEHICLE WILL NOT START. I RAN THIS TRUCK ABOUT 2 WEEKS AGO AND IT HAS BEEN PLUGED IN SINCE. THE LIGHT IS ON THAT IT IS CHARGING BUT IT SEEMS NOT TO BE. ALSO THE 110 PLUGS IN THE BACK DONT SEEM TO BE WORKING ETHER.

CSHOP-2019-1589

Comments: **TROUBLE STOPPING**

Date Opened 3-26-2019 Date Finished 4-1-2019 Meter 1 Reading: 106,414

TASKS PERFORMED

NO PARTS USED

BRAKES