

1/3/2017
3:30:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161695 2005 ESSICK EM90SH8 Mortar Mixer, Trailer Mntd

Workorder: 551935	Problem: PRE-DELIVERY INSPECTION			
Meter Reading: 0	Labor	Parts		
In Date: 08/02/2005	Close Date: 08/02/2005	Hours	Description	Quantity
- Pre-Delivery Inspection		2.00		
Parts Charge:	0.00	Labor Charge:	100.00	

Workorder: 648844	Problem: PM SERVICE			
Meter Reading: 0	Labor	Parts		
In Date: 11/17/2006	Close Date: 11/28/2006	Hours	Description	Quantity
- Pm Mixer		6.50	SHOP SUPPLIES	1.00
- Pm Trailer			46760 SEAL	2.00
- Test Run			BPR6ES SPARK PLUG 7131	1.00
- Shop Supplies			10W30 MOTOR OIL	2.00
Parts Charge:	12.68	Labor Charge:	27.50	

Workorder: 746817	Problem: WONT START			
Meter Reading: 0	Labor	Parts		
In Date: 11/06/2007	Close Date: 11/15/2007	Hours	Description	Quantity
- Bad Fuel Drain Tank & Clean		5.50	HOOD LATCH KITS 42410	2.00
- R/R Carb Clean & Adj			SHOP SUPPLIES	1.00
- Replace Hood Latch				
- Repair Pull Start				
- Test Run				
- Shop Supplies				
Parts Charge:	34.97	Labor Charge:	30.00	

Workorder: 842607	Problem: PM MORTER MIXER AND TRAILER			
Meter Reading: 0	Labor	Parts		
In Date: 08/11/2008	Close Date: 08/14/2008	Hours	Description	Quantity
- Pm Mixer		7.00	SHOP SUPPLIES	1.00
- Service Trailer Section			HOOD LATCHES	2.00
- Replaced Rubber Hood Latches				
- Shop Supplies				
Parts Charge:	19.82	Labor Charge:	60.00	

1/3/2017
3:30:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161695 2005 ESSICK EM90SH8 Mortar Mixer, Trailer Mntd

Workorder: 942397

Problem: PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 08/21/2009	Hours	Description	Quantity
- Pm Servie	8.00	10W30 MOTOR OIL	1.00
- Replaced Left Rear Tail Bulb		BPR6ES SPARK PLUG 7131	1.00
- Service Trailer		46760 SEAL	2.00
- Replaced Trailer Plug		SHOP SUPPLIES	1.00
- Shop Supplies		755-5046 MALE CONNECTOR	1.00
Parts Charge:	20.10	Labor Charge:	480.00

Workorder: 942892

Problem: TRAILER PLUG TO SHORT/ ORDER FUEL CAP

Meter Reading: 0	Labor	Parts	
In Date: 09/03/2009	Hours	Description	Quantity
- New Fuel Cap Order Cap	2.50	HOOD STRAP	1.00
- Makes New Trailer Plug Repalce Bulb		8616-100 TRAILER WIRE 6 WIRE 14 GAUGE	5.00
- Repalce Rubber Hood Stamp		FUEL CAP	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	34.97	Labor Charge:	150.00

Workorder: 1004298

Problem: chain hooks

Meter Reading: 0	Labor	Parts	
In Date: 04/27/2010	Hours	Description	Quantity
- Install Safety Hooks, Shorten Safety Chain To Proper Length	1.00	2848 S HOOK	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	5.23	Labor Charge:	60.00

Workorder: 1004684

Problem: no start

Meter Reading: 0	Labor	Parts	
In Date: 05/05/2010	Hours	Description	Quantity
- Ck Oil Level, All Wiring, Fuel Sys. Safety Switch	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

1/3/2017
3:30:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161695 2005 ESSICK EM90SH8 Mortar Mixer, Trailer Mntd

Workorder: 1010446

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 09/22/2010	Hours	Description	Quantity
- Service Mixer	8.50	SHOP SUPPLIES	1.00
- Repair Lights		46760 SEAL	2.00
- Service Trailer		17210ZE2505 AIR FILTER HONDA 746096	1.00
- R/R Pull Start And Install New Pull Cord		BPR6ES SPARK PLUG 7131	1.00
- Shop Supplies		10W30 MOTOR OIL	1.00
Parts Charge:	29.20	Labor Charge:	510.00

Workorder: 1103068

Problem: pull cord

Meter Reading: 0	Labor	Parts	
In Date: 03/22/2011	Hours	Description	Quantity
- Repair Pull Start	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1103429

Problem: rubber paddles/ weld cage/ pin for safety latch

Meter Reading: 0	Labor	Parts	
In Date: 03/30/2011	Hours	Description	Quantity
- Replaced Pin For Latch And Fabricate Teather Cable For Pin	5.50	FREIGHT	1.00
		RUBBER BLADE KIT	1.00
- Replace All Rubber Blades And Adjusted-Inside Of Mixer Loaded With Concrete, Adjusted Paddles As Best As Possible		SHOP SUPPLIES	1.00
- R&R Case To Straighten And Weld Cage			
- Shop Supplies			
Parts Charge:	99.63	Labor Charge:	330.00

1/3/2017
3:30:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161695 2005 ESSICK EM90SH8 Mortar Mixer, Trailer Mntd

Workorder: 1111807

Problem: PM

Meter Reading: 0	Labor	Parts	
In Date: 11/02/2011	Hours	Description	Quantity
- Pm Service	8.50	SHOP SUPPLIES	1.00
- Trailer Service		SAE 30W OIL	1.00
- Fix Broken Safety Shut Off Switch Tune Up		PB-16 PBBLASTER	1.00
- Replace Two Rear Light Bulbs		09997 BRAKE CLEAN	1.00
- New Male Trailer Plug		755-5046 MALE CONNECTOR	1.00
- Shop Supplies		46760 SEAL	2.00
		BPR5ES SPARK PLUG 7734	1.00
Parts Charge:	27.32	Labor Charge:	510.00

Workorder: 1303605

Problem: PM

Meter Reading: 0	Labor	Parts	
In Date: 04/12/2013	Hours	Description	Quantity
- Pm Service	8.00	SPARK PLUG	1.00
- Ign Service		NAPA HEAVY DUTY 30QT	1.00
- Service Trailer		SHOP SUPPLIES	1.00
- R&R Carb Clean And Adjust		46760 SEAL	2.00
- Shop Supplies			
Parts Charge:	12.89	Labor Charge:	480.00

Workorder: 1404018

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 04/24/2014	Hours	Description	Quantity
- Perform Pm Service	8.00	NAPA HEAVY DUTY 30QT	1.00
- Service Trailer		SPARK PLUG	1.00
- Ign Tune Up		GREASE NLGI 2	1.00
- Clean Carb And Fuel Tank Add Fresh Fuel W/ Additive		SEAL 1.250 1.979 .250	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	20.25	Labor Charge:	480.00

1/3/2017
3:30:19PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10161695 2005 ESSICK EM90SH8 Mortar Mixer, Trailer Mntd

Workorder: 1504484

Problem: pm service

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/01/2015	Hours	Description	Quantity
- Pm	11.00	NAPA HEAVY DUTY 30QT	1.00
- Service Trailer		NAPAGOLD AIR FILTER	1.00
- Replace Safety Shut Of Switch And Rewire		SPARK PLUG	1.00
- Tun Up Ign Sys Service Free Up Cylinder		TRAILER CONN PLUG	1.00
- Replace Male Trailer Plug And Replace Bulb In Tail Markers		BULB	2.00
- Flush Fuel Sys And Add Fuel Replace Fuel Lines		STARTRON 8OZ FUEL TRT	1.00
- Clean Out Carb And And Adust		BRAKE CLEANER	1.00
- Shop Supplies		SWITCH	1.00
		46760 SEAL	2.00
		SHOP SUPPLIES	1.00
Parts Charge:	59.62	Labor Charge:	660.00

Workorder: 1605014

Problem: pm service

Meter Reading: 0	Labor	Parts	Quantity
In Date: 05/13/2016	Hours	Description	Quantity
- Pm	5.00	TAPPERED BEARING SET	2.00
- Service Trailer		SEAL 1.250 1.979 .250	2.00
- Shop Supplies		NAPA HEAVY DUTY 30QT	1.00
		SHOP SUPPLIES	1.00
Parts Charge:	28.64	Labor Charge:	300.00

Workorder: 1607554

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	Quantity
In Date: 07/22/2016	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **409.32** Total Labor Charges: **4,297.50** Total Comm. Charges: **0.00**