

1/3/2017
3:40:14PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10110795 1996 JOHN DEERE 800 POUND Trailer, Utility

Workorder: 333388

Problem: PM SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 01/24/2003	Hours	Description	
- Pm	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	50.00

Workorder: 744455

Problem: P.M.SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 09/20/2007	Hours	Description	
- Pm Service	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	55.00

Workorder: 846773

Problem: P.M.SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/05/2008	Hours	Description	
- Pm Service	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 945970

Problem: P. M. SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 11/13/2009	Hours	Description	
- P.M. Unit Is Un-Safe To Operate. Tom Dillenger Was Advised & Acknowledged.	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	240.00

1/3/2017
3:40:14PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10110795 1996 JOHN DEERE 800 POUND Trailer, Utility

Workorder: 1013465

Problem: P.M.SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 12/07/2010	Hours	Description	
- P. M. Service. Equipment Not Safe To Operate.	2.50	SHOP SUPPLIES	1.00
- Plug Two Holes In Tires. Correct Nitro Levels.			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	150.00

Workorder: 1113488

Problem: P. M. SERVICE

Meter Reading: 0	Labor	Parts	Quantity
In Date: 12/28/2011	Hours	Description	
- P. M. Service.	3.50	1066 WHITE LITHIUM (CRC 05037)	1.00
- Verify, Needs Two Tires, Dry Rotted. Replace Tires, Add N2.		TIRE DISPOSAL FEE	2.00
		20-10.00-8 CARLISLE TURF MASTER	2.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	240.43	Labor Charge:	210.00

Workorder: 1206786

Problem: pm

Meter Reading: 0	Labor	Parts	Quantity
In Date: 07/20/2012	Hours	Description	
- Pm	2.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	120.00

Workorder: 1307669

Problem: pm

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/01/2013	Hours	Description	
- Pm	3.00	SHOP SUPPLIES	1.00
- Repair Two Tires Repair Multiple Holes Add N2		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	4.00	Labor Charge:	180.00

1/3/2017
3:40:14PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10110795 1996 JOHN DEERE 800 POUND Trailer, Utility

Workorder: 1407614

Problem: pm, needs tires new bearings

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/01/2014	Hours	Description	
- Ck Pm Tires Bearings Etc Verify Not Cost Effective To Repair As Per Mr Mike Edwards Eq Needs Tires Bearings Axle Shaft Etc	1.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	60.00

Workorder: 1607234

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	Quantity
In Date: 07/15/2016	Hours	Description	
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges: **258.43** Total Labor Charges: **1,125.00** Total Comm. Charges: **0.00**