

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 448056

Problem: TRANSPORT AND SET UP FOR TRAILER TO BE WEIGHED

Meter Reading: 0	Labor	Parts	Quantity
In Date: 06/16/2004	Hours	Description	Quantity
- Transport And Set Up To Be Weighed	0.50		1.00
- Weigh Slip			
Parts Charge: 7.75	Labor Charge: 25.00		

Workorder: 448121

Problem: PRE-DELIVERY INSPECTION

Meter Reading: 0	Labor	Parts	Quantity
In Date: 06/17/2004	Hours	Description	Quantity
- Pre-Delivery Inspection	2.00		
Parts Charge: 0.00	Labor Charge: 100.00		

Workorder: 451422

Problem: TAG

Meter Reading: 0	Labor	Parts	Quantity
In Date: 07/20/2004	Hours	Description	Quantity
- Tag Charge		TAG CHARGE	1.00
Parts Charge: 51.85	Labor Charge: 0.00		

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 545982

Problem: NEEDS HYD POWER TO RUN TILT BED

Meter Reading: 0		Labor	Parts	
In Date: 05/26/2005	Close Date: 08/08/2005	Hours	Description	Quantity
- Engineer And Fabricate Hydraulic Lift, For Tilt Trailer		18.00	SYN/ATF TRANS FLUID SYNTHETIC	16.00
- Shop Supplies			84-9288 GROTE BATTERY HOLD DOWN	1.00
			65-72 BATTERY GROUP GROUP 65	1.00
			TC101M/5403 TRAILER PLUG MALE TRAILER PLUG,11-604	1.00
			84-9287 GROTE 8" BATTERY J-BOLT	1.00
			2067-6-6S 3/8 FITTING	1.00
			02-173728 COUNTER BALANCE VLVE	1.00
			GC80000C08D020DAA123 A120A1H POWER UNIT	1.00
			HOSE FITTINGS	1.00
			CABLE LUGS 84-9432	1.00
			8-149 IN-LINE FUSEHOLDER 30 AMP	1.00
			2067-6-6S	3.00
			SW33 SWITCH	1.00
			TC101F CONNECTOR FEMALE (5404)	1.00
			SHOP SUPPLIES	1.00
			770-1734 TAPE	1.00
	Parts Charge: 1,608.60	Labor Charge: 900.00		

Workorder: 551261

Problem: CHECK LIGHTS

Meter Reading: 0		Labor	Parts	
In Date: 07/26/2005	Close Date: 07/28/2005	Hours	Description	Quantity
- Replace L/F Tail Lamp		0.50	60283R LAMP	1.00
	Parts Charge: 10.04	Labor Charge: 25.00		

Workorder: 636134

Problem: CHECK TRAILER LIGHTS

Meter Reading: 0		Labor	Parts	
In Date: 03/22/2006	Close Date: 03/27/2006	Hours	Description	Quantity
- Repaor Trailer Wiring		1.50	SHOP SUPPLIES	1.00
- Shop Supplies			GRO 52892-5 TAIL LAMP	2.00
	Parts Charge: 23.66	Labor Charge: 75.00		

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 741103

Problem: P.M.SERVICE/L/SIDE TIRES FLAT

Meter Reading: 0	Labor	Parts	
In Date: 07/09/2007	Hours	Description	Quantity
- Pm Service	7.00	SHOP SUPPLIES	1.00
- Repair 3 Tires		GROUP 65 BATTERY (MTC BXT-65-850)	1.00
- Charge & Test Battery; Replace Battery			
- Shop Supplies			
Parts Charge:	126.18	Labor Charge:	41.25

Workorder: 742746

Problem: L/FRONT TIRE FLAT.

Meter Reading: 0	Labor	Parts	
In Date: 08/13/2007	Hours	Description	Quantity
- Do Water Leak Test On L/F Tire; Leaking From Rim;	1.25	SHOP SUPPLIES	1.00
- Clean Off Rust, Clean Tire & Remount			
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	68.75

Workorder: 742880

Problem: REPAIR THE LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 08/20/2007	Hours	Description	Quantity
- R&R Light & Repaired Wiring	2.00	SHOP SUPPLIES	1.00
- Replace Trailer Plug.		755-5046 MALE CONNECTOR	1.00
- Shop Supplies		60202R TAIL LIGHT RED OVAL DON'T REORDER	1.00
Parts Charge:	15.18	Labor Charge:	55.00

Workorder: 748665

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	
In Date: 12/11/2007	Hours	Description	Quantity
- Tiresoles Of Broward Inc			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	200.68

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 748666 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 12/11/2007	Hours	Description	
- Tiresoles Of Broward Inc			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 54.00	

Workorder: 833874 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/05/2008	Hours	Description	
- Tiresoles Of Broward Inc			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 54.00	

Workorder: 833875 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 02/05/2008	Hours	Description	
- Tiresoles Of Broward Inc			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 200.68	

Workorder: 836824 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/01/2008	Hours	Description	
- Tiresoles Of Broward Inc			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 399.82	

Workorder: 836825 **Problem:** TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 04/01/2008	Hours	Description	
- Tiresoles Of Broward Inc			
Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 108.00	

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 845429

Problem: REPAIR TRAILER

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/08/2008	Hours	Description	Quantity
- Pm Service	8.00	60202R TAIL LIGHT RED OVAL DON'T REORDER	1.00
- Repair Rear Drop Down Bumper		SHOP SUPPLIES	1.00
- Repair Lights			
- Fill Tires With Nitrogen			
- Shop Supplies			
Parts Charge:	7.81	Labor Charge:	60.00

Workorder: 846213

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/17/2008	Hours	Description	Quantity
- Tiresoles Of Broward Inc			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	802.70

Workorder: 846214

Problem: TIRESOLES OF BROWARD INC

Meter Reading: 0	Labor	Parts	Quantity
In Date: 10/17/2008	Hours	Description	Quantity
- Tiresoles Of Broward Inc			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	144.00

Workorder: 1008627

Problem: pm service

Meter Reading: 0	Labor	Parts	Quantity
In Date: 08/10/2010	Hours	Description	Quantity
- Pm Service	7.10	SHOP SUPPLIES	1.00
- Test And Clean Battery		755-5046 MALE CONNECTOR	1.00
- Test And Repair Electrical Connections For Tilt Bed		L427 KENDALL HIGH TEMP USE #252-7867	1.00
- Replace Trailer Plug And Repair Wiring		42385 SEAL	4.00
- Shop Supplies			
Parts Charge:	25.36	Labor Charge:	426.00

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Workorder: 1012889	Problem: Tires				
Meter Reading: 0		Labor		Parts	
In Date: 08/18/2010	Close Date: 11/18/2010	Hours	Description		Quantity
<hr/>					
- 8100 Forest Hill Blve					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 141.65		

Workorder: 1012890	Problem: service				
Meter Reading: 0		Labor		Parts	
In Date: 08/18/2010	Close Date: 11/18/2010	Hours	Description		Quantity
<hr/>					
- 8100 Forst Hill Blvd					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 60.00		

Workorder: 1101169	Problem: Flat				
Meter Reading: 0		Labor		Parts	
In Date: 01/31/2011	Close Date: 02/01/2011	Hours	Description		Quantity
<hr/>					
- Flat Tire Repair Boulevard					
	Parts Charge: 0.00	Labor Charge: 0.00	Commercial Charge: 67.50		

Workorder: 1203772	Problem: pm service				
Meter Reading: 0		Labor		Parts	
In Date: 04/20/2012	Close Date: 05/23/2012	Hours	Description		Quantity
<hr/>					
- Pm Service		22.00	5/16-18X3 DECK SCREWS T/C TORX M/S BLK		200.00
- Redeck Trailer			2"X8"X16 PT BOARD		10.00
- Shop Supplies			SHOP SUPPLIES		1.00
			2"X6"X16' PT BOARD		6.00
			PB-16 PBBLASTER		2.00
	Parts Charge: 353.94	Labor Charge: 1,320.00			

Workorder: 1612472	Problem: Transition Prep Charge				
Meter Reading: 0		Labor		Parts	
In Date: 12/06/2016	Close Date: 12/06/2016	Hours	Description		Quantity
<hr/>					
- Transition Prep Charge		2.00			
	Parts Charge: 0.00	Labor Charge: 0.00			

1/3/2017
3:47:35PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: 10155305 2004 BETTER BUILT TRAILERS PH2922FB14KE Trailer, 7 Ton, Tilt Bed

Total Parts Charges: **2,232.37**

Total Labor Charges: **3,096.00**

Total Comm. Charges: **2,233.03**