

1/3/2017
3:49:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: Z203724 2004 EMERSON LT510SPC Trailer W/Ramp

Workorder: 643606

Problem: JACK STAND PROBLEMS

Meter Reading: 0	Labor	Parts	
In Date: 08/08/2006	Hours	Description	Quantity
- Pm Single Axle Trailer	4.00	58856 SEAL	2.00
- Repair Tongue Jack Stand		SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	3.78	Labor Charge:	50.00

Workorder: 734810

Problem: REPAIR TRAILER JACK,PM SERVICE

Meter Reading: 0	Labor	Parts	
In Date: 02/27/2007	Hours	Description	Quantity
- Pm Service	5.50	30881 JACK	1.00
- Replace Tounge Jack		58856 SEAL	2.00
- Repair Lights And Replace Lens		2640 LH TAIL LIGHT GROTE# 52312	1.00
- Shop Supplies		SHOP SUPPLIES	1.00
Parts Charge:	18.03	Labor Charge:	82.50

Workorder: 835567

Problem: P.M.

Meter Reading: 0	Labor	Parts	
In Date: 03/14/2008	Hours	Description	Quantity
- Pm Single Axle Trailer	5.50	58856 SEAL	2.00
- Repair Both Tail Lights & Repair Shorted Wiring		SHOP SUPPLIES	1.00
- Make & Apply Asset			
- Shop Supplies			
Parts Charge:	4.09	Labor Charge:	60.00

Workorder: 847430

Problem: CHECK TRAILER/SAFETY INSPECTION,PM SERVICE NOT DUE

Meter Reading: 0	Labor	Parts	
In Date: 11/24/2008	Hours	Description	Quantity
- Pm Service	5.50	58856 SEAL	2.00
- Replace Left And Right Bearing And Races		SHOP SUPPLIES	1.00
- Repair Ground Bad Connection To Lr Tail Lamp		SET 4 BEARING SET TIMKEN L44649/L44610	2.00
- Shop Supplies		SET 17 BEARING SET TIMKIN L68149/L68111	2.00
Parts Charge:	66.87	Labor Charge:	30.00

1/3/2017
3:49:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: Z203724 2004 EMERSON LT510SPC Trailer W/Ramp

Workorder: 946407

Problem: PM Trailer

Meter Reading: 0	Labor	Parts	
In Date: 11/30/2009	Hours	Description	Quantity
- Pm Service	5.00	SET 17 BEARING SET TIMKIN L68149/L68111	2.00
- New Right And Left Inner And Outer Wheel Bearings		SET 4 BEARING SET TIMKEN L44649/L44610	2.00
- New Grease Caps		58856 SEAL	2.00
- Shop Supplies		09997 BRAKE CLEAN	1.00
		SHOP SUPPLIES	1.00
		81733 GREASE CAP	2.00
Parts Charge:	87.53	Labor Charge:	600.00

Workorder: 1013067

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 11/29/2010	Hours	Description	Quantity
- Pm	3.00	SHOP SUPPLIES	1.00
- Shop Supplies			
Parts Charge:	2.00	Labor Charge:	180.00

Workorder: 1102957

Problem: left tail light bracket/ check coupler

Meter Reading: 0	Labor	Parts	
In Date: 03/18/2011	Hours	Description	Quantity
- Secure Coupler	4.50	SHOP SUPPLIES	1.00
- Tr To Van Linda		A-FRAME COUPLER	1.00
- Fab And Braze New L/R Tail Light Bracket On Trailer			
- Replace Trailer Hitch			
- Shop Supplies			
Parts Charge:	22.75	Labor Charge:	270.00
		Commercial Charge:	303.00

Workorder: 1103795

Problem: REPAIR LIGHTS

Meter Reading: 0	Labor	Parts	
In Date: 04/07/2011	Hours	Description	Quantity
- Replace L/R Tail/Stop Lamp	0.50	2808 TAIL LIGHT LED LEFT HAND (EXPEDITER)	1.00
Parts Charge:	16.48	Labor Charge:	30.00

1/3/2017
3:49:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: Z203724 2004 EMERSON LT510SPC Trailer W/Ramp

Workorder: 1112404 **Problem:** pm service

Meter Reading: 0	Labor	Parts	
In Date: 11/22/2011	Hours	Description	Quantity
- Pm Service	4.00	SHOP SUPPLIES	1.00
- R/R R/R Tail/Stop Lamp And Repair Harness		58856 SEAL	2.00
- Shop Supplies		2809 TAIL LIGHT LED RIGHT HAND (EXPEDITER)	1.00
Parts Charge:	25.24	Labor Charge:	240.00

Workorder: 1302942 **Problem:** pm service

Meter Reading: 0	Labor	Parts	
In Date: 03/26/2013	Hours	Description	Quantity
- Pm Trailer	4.50	TIRE DISPOSAL FEE	2.00
- Replace 2 Tires		T-1 BLACK PAINT GLOSS	1.00
- Shop Supplies		81733 GREASE CAP	2.00
		SHOP SUPPLIES	1.00
		762176400 205-75R14	2.00
Parts Charge:	188.74	Labor Charge:	270.00

Workorder: 1402512 **Problem:** pm/ chain pin

Meter Reading: 0	Labor	Parts	
In Date: 03/14/2014	Hours	Description	Quantity
- Pm	4.50	SHOP SUPPLIES	1.00
- Replace Chian Pin		PINTLE PIN W/CHAIN	1.00
- Tire Repair Right Side			
- Shop Supplies			
Parts Charge:	4.61	Labor Charge:	270.00

Workorder: 1402917 **Problem:** tailgate repair

Meter Reading: 0	Labor	Parts	
In Date: 03/26/2014	Hours	Description	Quantity
- Commercial Tail Gate Repair			
Parts Charge:	0.00	Labor Charge:	0.00
		Commercial Charge:	374.40

1/3/2017
3:49:36PM

Palm Beach County Fleet Management Asset Maintenance History

Asset: Z203724 2004 EMERSON LT510SPC Trailer W/Ramp

Workorder: 1503220

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 03/27/2015	Hours	Description	Quantity
- Pm	3.00	BRAKE CLEANER	1.00
- Shop Supplies		SEAL 1.719 2.561 .500	2.00
		SHOP SUPPLIES	1.00
		WD40 16OZ	1.00
		MAC WITE LITHIUM GRES	1.00
Parts Charge:	25.51	Labor Charge:	180.00

Workorder: 1604541

Problem: pm service

Meter Reading: 0	Labor	Parts	
In Date: 04/29/2016	Hours	Description	Quantity
- Pm	3.50	SHOP SUPPLIES	1.00
- Repair Ground Connection At R/Tail Lamp		SEAL 1.719 2.561 .500	2.00
- Shop Supplies			
Parts Charge:	4.19	Labor Charge:	210.00

Workorder: 1611717

Problem: Transition Prep Charge

Meter Reading: 0	Labor	Parts	
In Date: 11/15/2016	Hours	Description	Quantity
- Transition Prep Charge	2.00		
Parts Charge:	0.00	Labor Charge:	0.00

Total Parts Charges:	469.82	Total Labor Charges:	2,472.50	Total Comm. Charges:	677.40
----------------------	---------------	----------------------	-----------------	----------------------	---------------