

**Palm Beach County Fleet Management  
Asset Maintenance History**

**10179173 2009 TORO GRNDMASTER 7200 Mower, 72", Ztr, Side Discharge**

**Workorder:** 939308      **Meter:** 0      **In Date:** 06/22/2009      **Closed:** 06/22/2009  
**Problem:** PRE-DELIVERY INSPECTION

- Pre-delivery Inspection

Hours 2.00      Labor: 120.00      Parts: 0.00      Total: 120.00  
:

**Workorder:** 1006246      **Meter:** 168      **In Date:** 06/11/2010      **Closed:** 06/28/2010  
**Problem:** P. M. SERVICE

- P. M. Service.  
- Replace rear deck wheels.  
- Shop Supplies

| <b>Parts List</b>                       | <b>Qty</b> |
|---|------------|
| Shop Supplies                           | 1.00       |
| P8043 Fuel Filter Lbf Lff8062 Wix 33472 | 1.00       |
| 6438 Air Filterfrm Ca9550 Wix 46438     | 1.00       |
| Oil Filter                              | 1.00       |
| 15/40 Oil                               | 4.00       |
| Roller Scalp Anti                       | 2.00       |
| Tube Spacers                            | 2.00       |
| Tube Spanners                           | 2.00       |
| Screw Hh                                | 2.00       |
| Lock Nuts                               | 2.00       |

Hours 5.00      Labor: 300.00      Parts: 106.37      Total: 406.37  
:

**Workorder:** 1105906      **Meter:** 339      **In Date:** 06/03/2011      **Closed:** 06/10/2011  
**Problem:** Fix rear left, tire losing air

- Repair left rear tire.  
- Shop Supplies

| <b>Parts List</b> | <b>Qty</b> |
|-------------------|------------|
| Shop Supplies     | 1.00       |

Hours 1.00      Labor: 60.00      Parts: 2.00      Total: 62.00  
:

**Workorder:** 1107890      **Meter:** 382      **In Date:** 07/27/2011      **Closed:** 08/05/2011  
**Problem:** P. M. Service.

- P. M. Service.  
- Service hydraulic system. Inspect lines & hoses. Tighten all fittings.  
- Wash equipment for service & repairs.  
- Verify both fuel tanks empty, add 5 gals of diesel to test drive & prime fuel filter.  
- Shop Supplies

| <b>Parts List</b>                       | <b>Qty</b> |
|---|------------|
| Shop Supplies                           | 1.00       |
| Oil Filter                              | 1.00       |
| 6438 Air Filterfrm Ca9550 Wix 46438     | 1.00       |
| P8043 Fuel Filter Lbf Lff8062 Wix 33472 | 1.00       |
| 15/40 Oil                               | 4.00       |
| Aw68 Hydro Fluid Hydraulic Oil 68       | 1.00       |

Hours 7.00      Labor: 420.00      Parts: 41.64      Total: 461.64  
:

**Workorder:** 1205128      **Meter:** 548      **In Date:** 06/01/2012      **Closed:** 06/12/2012  
**Problem:** WONT START,MISSING CAP R/FRONT WHEEL.

- ck won't start verify blown fuse replace with 20a fuse test drive  
- verify bad battery test battery bad replace battery with battery  
- Shop Supplies

| <b>Parts List</b>           | <b>Qty</b> |
|-----------------------------|------------|
| Shop Supplies               | 1.00       |
| Group 26 Battery (acd 26ps) | 1.00       |

Hours 2.75      Labor: 165.00      Parts: 78.50      Total: 243.50  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1209438      **Meter:** 643      **In Date:** 10/02/2012      **Closed:** 10/29/2012  
**Problem:** pm, cover missing nut tie down

|  | <b>Parts List</b>     | <b>Qty</b>    |
|--|-----------------------|---------------|
| - pm   |                       |               |
| - svc hyd sys inspect lines                        | Ph6607 Oil Filter Lbf | 1.00          |
| - svc sheilds install nuts                         | Ca9550 Air Filter Lbf | 1.00          |
| - wash eq clean dirt grass debris out off radiator | P8043 Fuel Filter Lbf | 1.00          |
| - Shop Supplies                                    | 15w40 Bulk South Reg  | 4.00          |
|  | Filter                | 1.00          |
|  | Knob                  | 2.00          |
|  | Nut Retainer          | 2.00          |
|  | Shop Supplies         | 1.00          |
| Hours 7.00   | Labor: 420.00         | Parts: 112.96 |
| :  |                       | Total: 532.96 |

**Workorder:** 1300567      **Meter:** 673      **In Date:** 01/15/2013      **Closed:** 01/18/2013  
**Problem:** tire leaking

|   | <b>Parts List</b> | <b>Qty</b>   |
|---|-------------------|--------------|
| - ck flat tire dismount plug and rr valve stem lr tire add n2 |                   |              |
| - Shop Supplies   | Shop Supplies     | 1.00         |
| Hours 1.00  | Labor: 60.00      | Parts: 2.00  |
| :   |                   | Total: 62.00 |

**Workorder:** 1309431      **Meter:** 809      **In Date:** 09/17/2013      **Closed:** 10/23/2013  
**Problem:** replace belts, propel blades one missing , replace both frot tires, wing nuts missing front top deck

|   | <b>Parts List</b>       | <b>Qty</b>    |
|---|-------------------------|---------------|
| - ck belts pulley chains etc replace both deck belts repair linkage and chains replace anti scalp wheel | V-belt                  | 1.00          |
| - ck front tires dismount can mount by hand replace valve stems clean bead add n2 grease bearings       | V-belt                  | 1.00          |
| - Shop Supplies   | Clevis Adjust           | 1.00          |
|   | Knob                    | 1.00          |
|   | Grease Cap              | 2.00          |
|   | Flange Nut Ni           | 1.00          |
|   | Screw                   | 1.00          |
|   | Tube-spanner            | 1.00          |
|   | Roller Scalp            | 1.00          |
|   | Tube Spacer             | 1.00          |
|   | 15-600-6 Nhs Str Rib 04 | 2.00          |
|   | Shop Supplies           | 1.00          |
|   | Tire Disposal Fee       | 2.00          |
| Hours 6.00  | Labor: 360.00           | Parts: 336.50 |
| :   |                         | Total: 696.50 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1312475      **Meter:** 840      **In Date:** 12/16/2013      **Closed:** 12/26/2013  
**Problem:** pm, belt on deck wont stay on

|  | <b>Parts List</b>    | <b>Qty</b>                       |
|--|----------------------|----------------------------------|
| - pm   |                      |                                  |
| - svc hyd sys inspect lines and hoses correct fluid level            | Napagold Air Filter  | 1.00                             |
| - ck belt wont stay on replace idler pulley belt pto switch test now | Napagold Fuel Filter | 1.00                             |
|  | Napagold Oil Filter  | 1.00                             |
| - wash eq  | 15w40 Bulk South Reg | 4.00                             |
| - Shop Supplies  | V-belt               | 1.00                             |
|  | Idler Pulley         | 1.00                             |
|  | Screw                | 1.00                             |
|  | Nut                  | 1.00                             |
|  | Pto Switch           | 1.00                             |
|  | Shop Supplies        | 1.00                             |
| Hours 10.00  | Labor: 600.00        | Parts: 262.84      Total: 862.84 |
| :  |                      |                                  |

**Workorder:** 1400051      **Meter:** 842      **In Date:** 01/02/2014      **Closed:** 01/16/2014  
**Problem:** deck belt keeps slipping off

|   | <b>Parts List</b>      | <b>Qty</b>                       |
|---|------------------------|----------------------------------|
| - ck deck belt slips off  |                        |                                  |
| verify bushingd bad on gear box rr bolts bushings replace air filter cap test mow | Gearbox Bracket Rh     | 1.00                             |
|   | Flange Nut Ni          | 3.00                             |
| - Shop Supplies   | Bolt                   | 3.00                             |
|   | Washer                 | 3.00                             |
|   | Rubber Mount           | 3.00                             |
|   | Gearbox Bracket Lh     | 1.00                             |
|   | Air Cleaner Cover Assy | 1.00                             |
|   | Shop Supplies          | 1.00                             |
| Hours 4.00  | Labor: 240.00          | Parts: 241.72      Total: 481.72 |
| :   |                        |                                  |

**Workorder:** 1401753      **Meter:** 856      **In Date:** 02/24/2014      **Closed:** 03/11/2014  
**Problem:** replace deck belt front, replace side flap

|   | <b>Parts List</b>     | <b>Qty</b>                       |
|---|-----------------------|----------------------------------|
| - ck belt and chute replace deck elt and discharge chute test mow | V-belt                | 1.00                             |
| - Shop Supplies   | Rubber Deflector Assy | 1.00                             |
|   | Shop Supplies         | 1.00                             |
| Hours 3.00  | Labor: 180.00         | Parts: 224.98      Total: 404.98 |
| :   |                       |                                  |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1501194      **Meter:** 1025      **In Date:** 02/02/2015      **Closed:** 02/24/2015  
**Problem:** pm

|   |                         |               |
|---|-------------------------|---------------|
| - pm  | <b>Parts List</b>       | <b>Qty</b>    |
| - inspect hyd sys lines and hoses correct filluid level rr hyd filter | Napagold Air Filter     | 1.00          |
| - wasg eq   | Napagold Fuel Filter    | 1.00          |
| - ck and replace rr right deck belt                                   | Oil Filter No Supercede | 1.00          |
| - replace ignition key  | 15w40 Bulk South Reg    | 3.00          |
| - Shop Supplies   | Napa Hydraulic Filtr    | 1.00          |
|   | V-belt                  | 1.00          |
|   | Ignition Key            | 1.00          |
|   | Shop Supplies           | 1.00          |
| Hours 7.25  | Labor: 435.00           | Parts: 132.71 |
| :   |                         | Total: 567.71 |

**Workorder:** 1502593      **Meter:** 1025      **In Date:** 03/12/2015      **Closed:** 03/27/2015  
**Problem:** belt keeps pulling off

|  |                     |               |
|--|---------------------|---------------|
| - ck blet fall off verify bad bushing and brackets on gear box replace bushing and brackets test mos | <b>Parts List</b>   | <b>Qty</b>    |
| - Shop Supplies  | Bracket Gear Box Rh | 1.00          |
|  | Bracket Bear Box Lh | 1.00          |
|  | Rubber Mount        | 3.00          |
|  | Bolt                | 3.00          |
|  | Shop Supplies       | 1.00          |
| Hours 2.00   | Labor: 120.00       | Parts: 154.88 |
| :  |                     | Total: 274.88 |

**Workorder:** 1508366      **Meter:** 1100      **In Date:** 08/20/2015      **Closed:** 08/28/2015  
**Problem:** pto not coming on, battery weak, small roller tires on deck, air filter cover replace flap on deck n

|  |                        |                 |
|--|------------------------|-----------------|
| - ck battery weak test battery bad ck charging sys   | <b>Parts List</b>      | <b>Qty</b>      |
| - pto chute wheels etc repair pto replace chute anti wheels air filter and cover replace drive shaft | Group 26 Delco         | 1.00            |
| - wash eq  | Pto Switch             | 1.00            |
| - Shop Supplies  | Air Cleaner Cover Assy | 1.00            |
|  | Napagold Air Filter    | 1.00            |
|  | Deflector              | 1.00            |
|  | Driveshaft             | 1.00            |
|  | Nut                    | 1.00            |
|  | Spacer-roller          | 1.00            |
|  | Roller,deck            | 1.00            |
|  | Bolt                   | 1.00            |
|  | Flange Nut Ni          | 4.00            |
|  | Screw                  | 2.00            |
|  | Tube-spanner           | 2.00            |
|  | Roller Scalp           | 2.00            |
|  | Tube Spacer            | 2.00            |
|  | Shop Supplies          | 1.00            |
| Hours 6.75   | Labor: 405.00          | Parts: 1,110.79 |
| :  |                        | Total: 1,515.79 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1511695      **Meter:** 1144      **In Date:** 11/16/2015      **Closed:** 12/09/2015  
**Problem:** PTO IS NOT WORKING

|  |                                 |                    |
|--|---------------------------------|--------------------|
| - ck pto wont engage trouble spool electrical sys found bad<br>clow controller replace controller test mow | <b>Parts List</b><br>Controller | <b>Qty</b><br>1.00 |
| - verify missing grease caps replace two caps lub all ppulley<br>grease fittings etc                       | Grease Cap                      | 2.00               |
| - wash eq  | Shop Supplies                   | 1.00               |
| - Shop Supplies  | Freight Charge                  | 1.00               |
| Hours 5.50   | Labor: 330.00                   | Parts: 314.87      |
| :  |                                 | Total: 644.87      |

**Workorder:** 1602090      **Meter:** 1171      **In Date:** 02/29/2016      **Closed:** 04/14/2016  
**Problem:** pm, wont start wont turn over when key is turned on

|  |                         |                 |
|--|-------------------------|-----------------|
| - Pm service.  | <b>Parts List</b>       | <b>Qty</b>      |
| - Replace two tires.mount and add N2                                     | Napagold Air Filter     | 1.00            |
| - Replace air filter cover,vaccator bracket etc.                         | Napagold Fuel Filter    | 1.00            |
| - Replace multiple hardware,anti scalp wheels,etc.                       | Napagold Oil Filter     | 1.00            |
| - C/c wont start.verify bad safety switches on brake and shift<br>lever. | 15w40 Bulk South Reg    | 4.00            |
| - Shop Supplies  | 24-1200-12b Turf M Carl | 2.00            |
|  | Air Cleaner Cover Assy  | 1.00            |
|  | Valve-actuator          | 1.00            |
|  | Flange Nut Ni           | 2.00            |
|  | Screw                   | 2.00            |
|  | Tube-spanner            | 2.00            |
|  | Nipple Pipi             | 1.00            |
|  | Serv Indicator          | 1.00            |
|  | Bracket Air Cleaner     | 1.00            |
|  | Harness Wire Seat       | 1.00            |
|  | Roller Scalp            | 2.00            |
|  | Tube Spacer             | 2.00            |
|  | Switch                  | 1.00            |
|  | Bail Switch             | 1.00            |
|  | Shop Supplies           | 1.00            |
|  | Tire Disposal Fee       | 2.00            |
|  | Freight Charge          | 1.00            |
| Hours 11.00  | Labor: 660.00           | Parts: 780.30   |
| :  |                         | Total: 1,440.30 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1608551      **Meter:** 1171      **In Date:** 08/17/2016      **Closed:** 09/26/2016  
**Problem:** Replace front rollers.Blade wont engage.

|   |                     |                 |
|---|---------------------|-----------------|
| - C/c rollers.replace front rollers& anti-scalp wheels.grease all pulleys and fittings.unseize tensioner.test mow.repair wiring on Pto. | <b>Parts List</b>   | <b>Qty</b>      |
|   | Roller              | 1.00            |
|   | Shaft,roller        | 1.00            |
| - Blades wont stay engage.replace Pto electric solenoid and test mow.   | Flange Nut Ni       | 2.00            |
|   | Screw               | 2.00            |
| - Shop Supplies   | Tube-spanner        | 2.00            |
|   | Roller Scalp        | 2.00            |
|   | Tube Spacer         | 2.00            |
|   | Solenoid Assy       | 1.00            |
|   | Solenoid Vlave Assy | 1.00            |
|   | Shop Supplies       | 1.00            |
|   | Freight Charge      | 1.00            |
| Hours 6.00  | Labor: 360.00       | Parts: 741.07   |
| :   |                     | Total: 1,101.07 |

**Workorder:** 1610995      **Meter:** 1261      **In Date:** 10/25/2016      **Closed:** 11/14/2016  
**Problem:** PTO intermittently on and off.

|   |                     |               |
|---|---------------------|---------------|
| - C/c Pto inop.replace control module.test mow. | <b>Parts List</b>   | <b>Qty</b>    |
|   | Control Module Assy | 1.00          |
| - Shop Supplies                                 | Shop Supplies       | 1.00          |
| Hours 2.00                                      | Labor: 120.00       | Parts: 397.75 |
| :   |                     | Total: 517.75 |

**Workorder:** 1611772      **Meter:** 1262      **In Date:** 11/16/2016      **Closed:** 11/29/2016  
**Problem:** pto wont stay engaged

|  |                     |               |
|--|---------------------|---------------|
| - Replace 4 safety switches repair wiring and Connectors | <b>Parts List</b>   | <b>Qty</b>    |
|  | Napa Antifreeze Gal | 2.00          |
| - Ck overheating, pressure test and flush cooling sys    | Switch              | 2.00          |
|  | Bail Switch         | 1.00          |
| - Shop Supplies  | Harness Wire Seat   | 1.00          |
|  | Switch              | 1.00          |
|  | Shop Supplies       | 1.00          |
| Hours 4.00   | Labor: 240.00       | Parts: 288.50 |
| :  |                     | Total: 528.50 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1706599      **Meter:** 1360      **In Date:** 07/05/2017      **Closed:** 07/31/2017

**Problem:** Pm Service.Replace chute.Replace all deck wheels.

|   |   |  |
|---|---|--|
| <ul style="list-style-type: none"> <li>- Pm Service.</li> <li>- Replace front tires.hand mount and add N2</li> <li>- C/c Chute,deck,wheels,etc..replace gear box bushings,grummets,all anti scalp wheels and test mow.</li> <li>- Service hyd.system.replace filter.inspect all.correct fluid level.</li> <li>- Wash equipment.</li> <li>- Shop Supplies</li> </ul> | <p><b>Parts List</b></p> <ul style="list-style-type: none"> <li>Napagold Air Filter</li> <li>Napagold Fuel Filter</li> <li>Napagold Oil Filter</li> <li>15w40 Bulk South Reg</li> <li>Bolt</li> <li>Rubber Mount</li> <li>Flange Nut Ni</li> <li>Shaft,roller</li> <li>Screw</li> <li>Tube-spanner</li> <li>Roller Scalp</li> <li>Tube Spacer</li> <li>Napa Hydraulic Filtr</li> <li>Aw68 Bulk Sr</li> <li>Tire</li> <li>Grommet</li> <li>Washer</li> <li>Deflector</li> <li>Plate-roller</li> <li>Plate Roller</li> <li>Roller</li> <li>Locknut</li> <li>323-11 Screw Toro</li> <li>Shop Supplies</li> </ul> | <p><b>Qty</b></p> <ul style="list-style-type: none"> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>4.00</li> <li>3.00</li> <li>3.00</li> <li>5.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>2.00</li> <li>2.00</li> <li>1.00</li> <li>2.00</li> <li>2.00</li> <li>4.00</li> <li>3.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>1.00</li> <li>6.00</li> <li>6.00</li> <li>1.00</li> </ul> |
|---|---|--|

Hours 12.25      Labor: 735.00      Parts: 598.72      Total: 1,333.72  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1708357      **Meter:** 1383      **In Date:** 08/24/2017      **Closed:** 09/21/2017  
**Problem:** new blade belt

- Verify needs multiple repairs.replace L/h spindle  
assm,scalp wheels and rollers.gear box  
brackets,bushings,etc..lube all.test drive.
- C/c Belts.replace two deck belts.
- Shop Supplies

| <b>Parts List</b>  | <b>Qty</b> |
|--------------------|------------|
| High Spindle Assy  | 1.00       |
| Anti-scalp Cup     | 3.00       |
| Gearbox Bracket Rh | 1.00       |
| Gearbox Bracket Lh | 1.00       |
| Washer             | 3.00       |
| Cotter Pin         | 2.00       |
| Screw              | 8.00       |
| Rotary Blade       | 3.00       |
| Rubber Mount       | 3.00       |
| Flange Nut Ni      | 13.00      |
| Bolt               | 3.00       |
| Deck Roller        | 2.00       |
| Shaft              | 2.00       |
| Screw              | 2.00       |
| Tube-spanner       | 2.00       |
| Roller Scalp       | 2.00       |
| Tube Spacer        | 2.00       |
| V-belt             | 1.00       |
| V-belt             | 1.00       |
| Shop Supplies      | 1.00       |

Hours 7.75      Labor: 465.00      Parts: 1,208.33      Total: 1,673.33  
:

**Workorder:** 1803373      **Meter:** 1466      **In Date:** 03/30/2018      **Closed:** 04/12/2018  
**Problem:** Bad battery.Also wont start intermittently.

- C/c Dead batterytest battery bad.replace battery check  
charging system.
- C/c intermittent starting issues,replace blown fuse.clean  
multiple connections.replace R/h neutral safety switch.
- Replace all rollers clean deck.lube tensioners and all lube  
points
- Replace two front tires mount and add N2
- Shop Supplies

| <b>Parts List</b> | <b>Qty</b> |
|-------------------|------------|
| Flange Nut Ni     | 2.00       |
| Screw             | 2.00       |
| Tube-spanner      | 2.00       |
| Roller Scalp      | 2.00       |
| Tube Spacer       | 2.00       |
| Battery           | 1.00       |
| Nut               | 1.00       |
| Spacer-roller     | 1.00       |
| Roller,deck       | 1.00       |
| Bolt              | 1.00       |
| Roller            | 1.00       |
| Tire              | 2.00       |
| Switch            | 1.00       |
| Atc-10 Fuse Pac   | 1.00       |
| Shop Supplies     | 1.00       |

Hours 5.50      Labor: 330.00      Parts: 443.69      Total: 773.69  
:

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1803975      **Meter:** 1467      **In Date:** 04/17/2018      **Closed:** 05/14/2018  
**Problem:** Check blades.Change belts.Adjust deck.Off left side

|  |                   |                 |
|--|-------------------|-----------------|
| - C/c belts,blades Etc..replace both belts.all adjust linkages<br>R/h spindle and idler armand pulley.grease all and test mow. | <b>Parts List</b> | <b>Qty</b>      |
| - Wash equipment.  | Dispenser Unit    | 1.00            |
| - Shop Supplies  | V-belt            | 1.00            |
|  | V-belt            | 1.00            |
|  | Nozzle            | 1.00            |
|  | Pulley            | 1.00            |
|  | Snao Ring         | 1.00            |
|  | Idler Arm Assy    | 1.00            |
|  | Spindle Assy      | 1.00            |
|  | Shop Supplies     | 1.00            |
|  | Freight Charge    | 1.00            |
| Hours 5.75   | Labor: 345.00     | Parts: 1,006.39 |
| :  |                   | Total: 1,351.39 |

**Workorder:** 1806916      **Meter:** 1503      **In Date:** 07/06/2018      **Closed:** 07/23/2018  
**Problem:** P.M.SERVICE,NEW DECK WHEELS

|  |                      |               |
|--|----------------------|---------------|
| - Pm Service.  | <b>Parts List</b>    | <b>Qty</b>    |
| - Replace rear anti scalp wheels.repair bracket on gear box. | Napagold Air Filter  | 1.00          |
| - Service Hyd system.  | Napagold Fuel Filter | 1.00          |
| - Wash equipment.  | 15w40 Bulk South Reg | 4.00          |
| - Shop Supplies  | Napagold Oil Filter  | 1.00          |
|  | Tube Spacer          | 2.00          |
|  | Roller Scalp         | 2.00          |
|  | Tube-spanner         | 2.00          |
|  | Screw                | 2.00          |
|  | Flange Nut Ni        | 2.00          |
|  | Shop Supplies        | 1.00          |
| Hours 8.00   | Labor: 480.00        | Parts: 112.94 |
| :  |                      | Total: 592.94 |

**Palm Beach County Fleet Management  
Asset Maintenance History**

**Workorder:** 1909024      **Meter:** 1723      **In Date:** 08/28/2019      **Closed:** 09/30/2019  
**Problem:** P.M.SERVICE,NEEDS BELT,IGN.KEY,TIRES, DECK WHEELS.

|   | <b>Parts List</b>    | <b>Qty</b> |
|---|----------------------|------------|
| - Pm Service.   |                      |            |
| - Replace front tires.mount.add N2.                         | Napagold Air Filter  | 1.00       |
| - Service hyd.system.                                       | Napagold Fuel Filter | 1.00       |
| - C/c Belt,deck,wheels etc...replace wheels,belt,driveshaft | 15w40 Bulk South Reg | 4.00       |
| asm.gear box bushings.clean rust from components,free       | Napagold Oil Filter  | 1.00       |
| tensioners,lube all,test mow.                               | Napa Hydraulic Filtr | 1.00       |
| - C/c Ignition.replace ignition switch with key.            | Tube Spacer          | 2.00       |
| - Shop Supplies   | Roller Scalp         | 2.00       |
|   | Flange Nut Ni        | 3.00       |
|   | Rubber Mount         | 3.00       |
|   | V-belt               | 1.00       |
|   | Driveshaft           | 1.00       |
|   | Tube-spanner         | 2.00       |
|   | Screw                | 2.00       |
|   | Washer               | 3.00       |
|   | Bolt                 | 3.00       |
|   | Gearbox Bracket Rh   | 1.00       |
|   | Gearbox Bracket Lh   | 1.00       |
|   | Key Switch Assy      | 1.00       |
|   | 15x6.00-6            | 2.00       |
|   | Ignition Key         | 1.00       |
|   | Plate Roller         | 1.00       |
|   | Shop Supplies        | 1.00       |
|   | Freight Charge       | 1.00       |
|   | Freight Charge       | 1.00       |

Hours 12.50      Labor: 837.50      Parts: 1,540.22      Total: 2,377.72  
:

**Workorder:** 1912642      **Meter:** 1723      **In Date:** 12/10/2019      **Closed:** 12/10/2019  
**Problem:** Transition Prep Charge

|                          |            |               |                                |
|--------------------------|------------|---------------|--------------------------------|
| - Transition Prep Charge |            |               |                                |
|                          | Hours 2.00 | Labor: 146.00 | Parts: 0.00      Total: 146.00 |
|                          | :          |               |                                |